Chart no. 5023

5023 - Cape Harrison to / à Nunaksaluk Island - New Edition - 30-APR-2004 - NAD 1983

09-DEC-2022 LNM/D. 01-OCT-2021

Add light Fl 5s37m5M 55°19′04.6″N 059°38′31.9″W
(See Chart 1, P1)
This notice affects Electronic Navigational Chart: CA276322 *(N2022248) LL(321.058) DFO(6310435-02)*

09-DEC-2022 LNM/D. 01-OCT-2021

Amend Fl 3s54m6M to read Fl 5s54m5M against light 55°49′28.0″N 059°54′07.4″W
(See Chart 1, P16)
This notice affects Electronic Navigational Chart: CA276652, CA376368 *(N2022249) LL(322.2) DFO(6310436-01)*

01-OCT-2021 LNM/D. 16-APR-2021

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 160 metres 55°25′10.2″N 058°49′04.8″W
(See Chart No. 1, L25) *DFO(6309506-01)*
This notice affects Electronic Navigational Chart: CA276322

16-APR-2021 LNM/D. 17-NOV-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 160 metres 55°25′10.0″N 058°49′05.0″W
(See Chart No. 1, L25) *DFO(6309396-01)*
This notice affects Electronic Navigational Chart: CA276322

17-NOV-2017 LNM/D. 31-MAR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 9 metres 55°36′18.2″N 057°45′01.2″W
(See Chart No. 1, L25) *DFO(6308129-01)*

31-MAR-2017 LNM/D. 02-DEC-2016

Replace depth of 5 metres with depth of 9 metres 55°36′18.2″N 057°44′55.6″W
(See Chart No. 1, L25)
DFO(6307869-01)

02-DEC-2016 LNM/D. 09-AUG-2013

Add subsurface Ocean Data Acquisition system (ODAS/SADO) with known depth of 5 fathoms 55°36′18.2″N 057°44′55.6″W
(See Chart No. 1, L25) *DFO(6307699-02)*

Chart no. 5023

09-AUG-2013 LNM/D. 21-OCT-2011

Reposition Adjoining Chart/Carte adjacente 8047 from centre to 57º 25′ 00″W of the north border
See Chart No 1 A20

DFO(6306447-01)

09-AUG-2013 LNM/D. 21-OCT-2011

Add Adjoining Chart/Carte adjacente 5024 northern border of chart at 59º05′00″W
(See Chart No. 1, A20)

DFO(6306447-02)

21-OCT-2011 LNM/D. 18-FEB-2011

Delete depth of 37 metres 54°53′02.5″N 057°51′07.2″W
(See Chart No. 1, I10)

DFO(6305746-02)

21-OCT-2011 LNM/D. 18-FEB-2011

Add depth of 2 metres, 5 decimetres 54°51′51.9″N 057°57′43.7″W
(See Chart No. 1, I10)

DFO(6305746-03)

21-OCT-2011 LNM/D. 18-FEB-2011

Add depth of 14 metres, 8 decimetres 54°53′03.4″N 057°51′20.5″W
(See Chart No. 1, I10)

DFO(6305746-04)

18-FEB-2011 LNM/D. 20-MAR-2009

Add depth of 103 metres, over artificial feature 55°24′43.1″N 058°03′54.5″W
(See Chart No 1 Ka)
The mooring is temporary. The proposed date of removal is November 2011. *DFO(6305212-01)*

18-FEB-2011 LNM/D. 20-MAR-2009

Add depth of 103 metres, over artificial feature 55°24′13.9″N 058°03′40.1″W
(See Chart No 1 Ka)
The mooring is temporary. The proposed date of removal is November 2011. *DFO(6305212-02)*

18-FEB-2011 LNM/D. 20-MAR-2009

Chart no. 5023

Add depth of 93 metres, over artificial feature 55°24′30.4″N 058°03′49.8″W
(See Chart No 1 Ka)
The mooring is temporary. The proposed date of removal is November 2011. *DFO(6305212-03)*

20-MAR-2009 LNM/D. 15-SEP-2006

(T)Add subsurface mooring at a depth of 104 metres 55°24′43.1″N 058°03′54.9″W
The mooring is temporary and will be removed by July 2009 (contact Murray Scotney, Bedford Institute of Oceanography, 902-426-3495). *DFO(6304262-01)*
The mooring has been removed. Notice 20-March-2009(T), DFO (6304262-01) is now cancelled.
Cancelled on 04-SEP-09

20-MAR-2009 LNM/D. 15-SEP-2006

(T)Add subsurface mooring at a depth of 104 metres 55°24′13.9″N 058°03′40.1″W
The mooring is temporary and will be removed by July 2009 (contact Murray Scotney, Bedford Institute of Oceanography, 902-426-3495). *DFO(6304262-02)*
The mooring has been removed. Notice 20-March-2009(T), DFO (6304262-02) is now cancelled.
Cancelled on 04-SEP-09

20-MAR-2009 LNM/D. 15-SEP-2006

(T)Add subsurface mooring at a depth of 94 metres 55°24′30.0″N 058°03′51.8″W
The mooring is temporary and will be removed by July 2009 (contact Murray Scotney, Bedford Institute of Oceanography, 902-426-3495). *DFO(6304262-03)*
The mooring has been removed. Notice 20-March-2009(T), DFO (6304262-03) is now cancelled.
Cancelled on 04-SEP-09

15-SEP-2006 LNM/D. 08-OCT-2004

Amend ″NH5″ to read ″NQ1″ against green port hand lighted pillar buoy FlG 54°59′55.9″N 058°30′48.7″W

(N2006064) LL(319.12) DFO(6302952-01)

08-OCT-2004

Amend ″Fl 5m 7M″ to read ″FlR 5m 7M″ against light 55°16′49.2″N 059°30′13.1″W

(N2004166) LL(321.05) DFO(6301943-01)

Chart no. 5023