Chart no. 5048

5048 - Cape Harrigan to / aux Kidlit Islands - New Edition - 25-DEC-2015 - NAD 1983

09-OCT-2020 LNM/D. 10-JUL-2020

Amend Fl 4s8m7M to read Fl 3s8m7M against light 55°57′28.8″N 060°24′43.3″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276652, CA376368 *(N2020086) LL(323.3) DFO(6309180-01)*

10-JUL-2020 LNM/D. 01-MAR-2019

Amend FI 3s8m7M to read FI 4s8m7M against light 55°57′28.7″N 060°24′43.5″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276652, CA376368 *(N2020042) LL(323.3) DFO(6309009-01)*

01-MAR-2019 LNM/D. 15-JUL-2016

Add depth of 24.9 metres 55°51′52.4″N 060°10′52.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376368 *DFO(6308567-01)*

15-JUL-2016 LNM/D. 01-JUL-2016

Amend ′Route Usually Followed/Route normalement naviguée′ to read ′Alternate Route / Route alternative′ 56°05′30.0″N 060°46′18.0″W
DFO(6307640-01)

01-JUL-2016

Amend ′Alternate Route / Route alternative′ to read ′Route Usually Followed/Route normalement naviguée′ 56°05′51.0″N 060°44′31.2″W
This notice affects Electronic Navigational Chart: CA376049 *DFO(6307551-02)*

01-JUL-2016

Amend ′Route Usually Followed / Route normalement naviguée′ to read ′Alternate Route/Route alternative′ 56°04′33.3″N 060°50′04.2″W
This notice affects Electronic Navigational Chart: CA376049 *DFO(6307551-06)*