Chart no. 7573

7573 - M'Clintock Channel, Larsen Sound and/et Franklin Strait - New Chart - 25-FEB-2000 - NAD 1983

31-OCT-2025 LNM/D. 25-OCT-2024

Delete depth of 42 metres 71°21′05.5″N 096°54′46.6″W
(See Chart 1, I10)
DFO(6605564-01)

31-OCT-2025 LNM/D. 25-OCT-2024

Add obstruction with known depth of 6.4 metres Rep (2025) 71°21′03.7″N 096°53′52.6″W
(See Chart 1, K41)
DFO(6605564-02)

31-OCT-2025 LNM/D. 25-OCT-2024

Add obstruction with known depth of 21.7 metres Rep (2025) 71°20′38.2″N 096°55′33.9″W
(See Chart 1, K41)
DFO(6605564-03)

25-OCT-2024 LNM/D. 17-NOV-2023

Add depth of 8.9 metres Rep (2024) 72°38′03.9″N 095°26′54.2″W
(See Chart 1, I10)
DFO(6605355-01)

17-NOV-2023 LNM/D. 06-SEP-2019

Add obstruction with known depth of 8.9 metres 70°36′14.0″N 096°06′34.9″W
(See Chart 1, K41)
This notice affects Electronic Navigational Chart: CA273329 *DFO(6605164-01)*

06-SEP-2019 LNM/D. 16-DEC-2016

Add obstruction, depth unknown, Rep (2019) 69°55′03.7″N 096°25′04.0″W
(See Chart No. 1, K40)
DFO(6604551-01)

16-DEC-2016 LNM/D. 11-OCT-2013

Add depth of 26.4 metres, Rep (2016) 71°45′16.2″N 096°34′14.4″W
(See Chart No. 1, I10, I3.2)
This notice affects Electronic Navigational Chart: CA273329 *DFO(6604245-01)*

11-OCT-2013 LNM/D. 11-JAN-2013

Chart no. 7573

Add depth of 20.2 metres, ″Rep (2009)″ 71°21′16.8″N 096°53′25.6″W
(See Chart No. 1, I10,I3.2)
This notice affects Electronic Navigational Chart: CA273329 *DFO(6603918-01)*

11-OCT-2013 LNM/D. 11-JAN-2013

Delete depth of 46 metres 71°19′41.0″N 096°40′42.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA273329 *DFO(6603918-02)*

11-OCT-2013 LNM/D. 11-JAN-2013

Add underwater rock of unknown depth, dangerous to surface navigation, ″Rep (2011)″ 71°19′39.7″N 096°41′01.9″W
(See Chart No. 1, K13, I3.2) *DFO(6603918-03)*

This notice affects Electronic Navigational Chart: CA273329

11-JAN-2013 LNM/D. 20-JAN-2012

Delete depth of 20 metres 71°43′54.0″N 095°41′04.0″W
(See Chart No. 1, I10)
DFO(6603839-01)

11-JAN-2013 LNM/D. 20-JAN-2012

Add sounding of 2.2 metres, Rep [2012] 71°43′56.4″N 095°41′18.0″W
(See Chart No.1, I3.2)
DFO(6603839-02)

20-JAN-2012 LNM/D. 23-JUL-2010

Add depth of 22.2 metres 71°46′01.3″N 096°33′07.3″W
(See Chart No. 1, I10)
DFO(6603748-01)

23-JUL-2010 LNM/D. 01-MAY-2009

Add recommended main two way track joining 69°34′00.0″N 095°12′00.0″W
(See Chart No. 1, M4) 69°35′00.0″N 095°14′48.0″W
69°40′00.0″N 095°26′21.0″W
69°41′00.0″N 095°35′33.0″W
and 69°46′10.8″N 096°10′00.0″W

DFO(6603604-01)

Chart no. 7573

01-MAY-2009 LNM/D. 02-JAN-2009

Reposition red beacon and radar reflector from 69°35′42.0″N 095°26′30.0″W
(See Chart No.1, Q81 and S4) to 69°35′20.9″N 095°25′45.8″W

(A2009002) DFO(6603370-01)

This notice affects Electronic Navigational Chart: CA273329

02-JAN-2009 LNM/D. 07-JUL-2006

Add sounding of 1.9m, Rep (2005) 71°43′36.6″N 095°31′19.2″W
(See Chart No.1, I3.2 and K1)

DFO(6603266-01)

This notice affects Electronic Navigational Chart: CA273329

07-JUL-2006

Add rock which covers and uncovers with drying height of 0.8 metres 71°51′09.9″N 095°31′03.1″W

DFO(6602650-01)

This notice affects Electronic Navigational Chart: CA273329