Chart no. 8015

8015 - Funk Island and Approaches / et les approches - New Edition - 16-NOV-2001 - NAD 1983

06-OCT-2023 LNM/D. 29-APR-2022

Amend Fl 3s23m5M to read Fl 5s23m5M against light 49°15′23.3″N 053°25′46.3″W
(See Chart 1, P16)
This notice affects Electronic Navigational Chart: CA276092, CA376371 *(N2023102) LL(408) DFO(6310851-01)*

29-APR-2022 LNM/D. 07-MAY-2021

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 9 meters 50°24′40.0″N 049°11′45.3″W
(See Chart No. 1, L25) *DFO(6310061-01)*

29-APR-2022 LNM/D. 07-MAY-2021

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 9 meters 50°45′30.8″N 052°19′49.1″W
(See Chart No. 1, L25) *DFO(6310062-01)*

07-MAY-2021 LNM/D. 02-DEC-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 1095 meters 49°45′57.7″N 049°38′22.9″W
(See Chart No. 1, L25) *DFO(6309410-01)*

02-DEC-2016 LNM/D. 19-AUG-2016

Add subsurface Ocean Data Acquisition system (ODAS/SADO) with known depth of 9 metres 50°45′30.8″N 052°19′49.1″W
(See Chart No. 1, L25) *DFO(6307699-01)*
This notice affects Electronic Navigational Chart: CA176030

02-DEC-2016 LNM/D. 19-AUG-2016

Add subsurface Ocean Data Acquisition system (ODAS/SADO) with known depth of 9 metres 50°24′40.0″N 049°11′45.3″W
(See Chart No. 1, L25) *DFO(6307699-07)*
This notice affects Electronic Navigational Chart: CA176030

19-AUG-2016 LNM/D. 19-JUN-2015

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 45 metres (See Chart No. 1, L25) 50°16′42.0″N 051°50′42.0″W
This notice affects Electronic Navigational Chart: CA176030 *DFO(6307641-02)*

Chart no. 8015

19-JUN-2015 LNM/D. 16-JAN-2015

Add subsurface Ocean Data Acquisition system (ODAS) with known depth of 45 metres (See Chart No. 1, L25) 50°16′42.0″N 051°50′42.0″W
This notice affects Electronic Navigational Chart: CA176030 *DFO(6307140-02)*

16-JAN-2015 LNM/D. 06-SEP-2013

Delete legend Fog Sig against light (See Chart No. 1, R1) 49°10′28.1″N 053°22′03.3″W
This notice affects Electronic Navigational Chart: CA276092, CA376371, CA576373 *(N2014066) LL(406) DFO(6306986-01)*

06-SEP-2013 LNM/D. 06-MAR-2009

Add obstruction with known depth of 315 metres (See Chart No. 1, K41) 49°22′33.0″N 050°59′17.4″W
This notice affects Electronic Navigational Chart: CA276092 *DFO(6306428-01)*

06-SEP-2013 LNM/D. 06-MAR-2009

Add obstruction with known depth of 318 metres (See Chart No. 1, K41) 49°23′53.4″N 050°53′50.4″W
This notice affects Electronic Navigational Chart: CA276092 *DFO(6306428-02)*

06-SEP-2013 LNM/D. 06-MAR-2009

Add obstruction with known depth of 311 metres (See Chart No. 1, K41) 49°25′35.4″N 050°48′40.2″W
DFO(6306428-03)

06-SEP-2013 LNM/D. 06-MAR-2009

Add obstruction with known depth of 311 metres (See Chart No. 1, K41) 49°26′56.4″N 050°43′24.0″W
DFO(6306428-04)

06-SEP-2013 LNM/D. 06-MAR-2009

Add obstruction with known depth of 311 metres (See Chart No. 1, K41) 49°28′52.2″N 050°38′18.6″W
DFO(6306428-05)

06-SEP-2013 LNM/D. 06-MAR-2009

Chart no. 8015

Add obstruction with known depth of 311 metres 49°30′46.8″N 050°33′15.6″W
(See Chart No. 1, K41)

DFO(6306428-06)

06-SEP-2013 LNM/D. 06-MAR-2009

Add obstruction with known depth of 311 metres 49°32′43.2″N 050°28′14.4″W
(See Chart No. 1, K41)

DFO(6306428-07)

06-SEP-2013 LNM/D. 06-MAR-2009

Add obstruction with known depth of 311 metres 49°34′41.4″N 050°23′24.0″W
(See Chart No. 1, K41)

DFO(6306428-08)

06-MAR-2009 LNM/D. 26-OCT-2007

Add submarine cable joining 50°51′59.6″N 049°43′10.1″W
(See Chart No 1 L30.1) 50°49′05.6″N 049°46′07.8″W
49°35′30.9″N 051°22′13.3″W
and 48°41′59.6″N 052°30′06.5″W

DFO(6304223-01)

26-OCT-2007 LNM/D. 13-OCT-2006

Amend note Adjoining Chart/Carte adjacente 4520 to read Adjoining Chart/Carte adjacente 4001 upper west border

DFO(6303536-05)

26-OCT-2007 LNM/D. 13-OCT-2006

Amend note Adjoining Chart/Carte adjacente 4017 to read Adjoining Chart/Carte adjacente 4820 lower west border

DFO(6303536-17)

13-OCT-2006 LNM/D. 02-SEP-2005

Amend legend ′Iso 5s 21m 14M′ to read ′Fl 5s 21m 16M′ against the light 49°03′42.0″N 053°33′03.2″W

LL(430) DFO(6303071-01)

02-SEP-2005 LNM/D. 30-JUL-2004

Chart no. 8015

Add non-dangerous wreck 49°45′57.0″N 053°08′51.0″W

DFO(6302412-01)

30-JUL-2004 LNM/D. 21-OCT-1994

Delete red, green and red starboard bifurcation pillar light buoy Fl(2+1)R, WHIS 49°14′58.0″N 053°22′06.0″W

(N2004064) LL(409) DFO(6301534-01)

This notice affects Electronic Navigational Chart: CA376371

30-JUL-2004 LNM/D. 21-OCT-1994

Add black and yellow North cardinal pillar light buoy Q 49°14′58.0″N 053°22′07.0″W

(N2004064) LL(409) DFO(6301534-02)

This notice affects Electronic Navigational Chart: CA376371