



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2207

2207 - Bay of Islands to/à Benjamin Islands (2207-1) - Sheet/Feuille 1 - New Chart - 27-JUL-2001 - NAD 1983

11-DEC-2020

LNМ/D. 19-MAY-2017

Delete depth of 28.9 metres 46°03'31.0"N 082°12'38.0"W
(See Chart No. 1, I10)

DFO(6604710-01)

11-DEC-2020

LNМ/D. 19-MAY-2017

Add wreck "Wk" with known depth of 11.9 metres, Rep (2020)
(See Chart No. 1, K26)

46°03'32.0"N 082°12'39.1"W

DFO(6604710-02)

This notice affects Electronic Navigational Chart: CA473288,
CA573280

30-SEP-2016

LNМ/D. 26-SEP-2014

Reposition starboard hand daybeacon
(See Chart No. 1, Qt)

from 46°07'00.1"N 082°12'14.7"W
to 46°07'00.6"N 082°12'24.3"W

This notice affects Electronic Navigational Chart:
CA473251

(D2016006) DFO(6604221-01)

23-JUL-2004

LNМ/D. 09-JUL-2004

Replace starboard hand pillar light buoy Fl R, marked J72,
with starboard hand spar light buoy Fl R, marked
J72

46°03'25.5"N 082°13'25.2"W

(D2004058) LL(1014) DFO(6601958-01)

23-JUL-2004

LNМ/D. 09-JUL-2004

Replace starboard hand pillar light buoy Fl R, marked
JD14, with starboard hand spar light buoy Fl
R, marked JD14

45°59'42.1"N 082°19'02.7"W

(D2004059) LL(1015.500) DFO(6601958-02)

15-MAR-2002

LNМ/D. 08-MAR-2002

Replace depth of 0.2 m with depth of 4.5 m 46°06'05.7"N 082°15'40.4"W

DFO(6600138-01)

08-MAR-2002



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2207

Replace drying height of 0.3m with depth of 0.3m over crib 46°02'37.9"N 081°58'46.1"W

DFO(6600125-01)

2207 - Little Current to/à Clapperton Island (2207-2) - Sheet/Feuille 1 - New Chart - 27-JUL-2001 - NAD 1983

01-SEP-2023

LNМ/D. 06-JAN-2023

Add subsurface Ocean Data Acquisition system (ODAS) with known depth of 2 metres (See Chart 1, L25)

45°52'28.0"N 082°08'59.5"W

DFO(6605118-01)

26-DEC-2008

LNМ/D. 12-DEC-2008

Amend legend F G 12m to read F G 9m against light

45°58'04.1"N 081°54'23.8"W

(D2008040) LL(997) DFO(6603345-01)

This notice affects Electronic Navigational Chart:
CA573307

23-JUL-2004

LNМ/D. 09-JUL-2004

Replace starboard hand pillar light buoy Fl R, marked JD14, with starboard hand spar light buoy Fl R, marked JD14

45°59'42.1"N 082°19'02.7"W

(D2004059) LL(1015.500) DFO(6601958-02)

09-JUL-2004

LNМ/D. 09-JAN-2004

Replace red starboard hand pillar light buoy QR, marked J24, with red starboard hand spar light buoy QR, marked J24

45°58'12.6"N 081°53'34.9"W

(D2004054) LL(999) DFO(6601954-01)

09-JUL-2004

LNМ/D. 09-JAN-2004

Replace red starboard hand pillar light buoy Fl R, marked J66, with red starboard hand spar light buoy Fl R, marked J66

45°58'55.3"N 082°05'00.7"W

(D2004057) LL(1010) DFO(6601957-01)

08-MAR-2002



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2207

Delete drying height of 4.3m. Depth of 4.3m over an artificial feature 45°54'49.6"N 082°16'14.5"W
remains against the crib.

DFO(6600127-01)

2207 - Bay of Islands (2207-3) - Sheet/Feuille 2 - New Chart - 27-JUL-2001 - NAD 1983

06-JAN-2023

LNM/D. 22-APR-2022

Delete starboard hand daybeacon 46°04'16.5"N 081°48'19.4"W
(See Chart 1, Qp)

(D2022067) DFO(6605000-01)

06-JAN-2023

LNM/D. 22-APR-2022

Add red starboard hand spar buoy, marked UY2/2 (See Chart 1, Qb) 46°04'17.6"N 081°48'17.9"W

(D2022068) DFO(6605001-01)

31-MAR-2006

LNM/D. 01-APR-2005

Reposition green port hand spar buoy, marked UA7 from 46°04'25.2"N 081°49'11.0"W
to 46°04'22.7"N 081°49'16.4"W

(D2006002) DFO(6602644-01)

14-JUN-2002

LNM/D. 15-MAR-2002

Add red, starboard hand spar buoy, marked UT10 46°05'36.2"N 081°45'12.3"W

DFO(6600177-01)

14-JUN-2002

LNM/D. 15-MAR-2002

Add green, port hand spar buoy, marked UT5 46°04'38.2"N 081°46'48.8"W

DFO(6600177-02)

15-MAR-2002

LNM/D. 08-MAR-2002

Delete depth of 0.1m 46°05'41.2"N 081°50'38.1"W

DFO(6600131-01)

15-MAR-2002

LNM/D. 08-MAR-2002



Chart no. 2207

Add drying height of 0.1m 46°05'41.2"N 081°50'38.1"W

DFO(6600131-02)

2207 - Little Current (2207-4) - Sheet/Feuille 2 - New Chart - 27-JUL-2001 - NAD 1983

22-APR-2022

LNM/D. 11-DEC-2020

Add crib with depth of 5.5 metres
(See Chart No. 1, Fb,Ka)

45°59'26.3"N 081°56'58.9"W

This notice affects Electronic Navigational Chart: CA573307

DFO(6604844-01)

22-APR-2022

LNM/D. 11-DEC-2020

Add crib with depth of 6.7 metres
(See Chart No. 1, Fb,Ka)

45°59'25.3"N 081°57'02.5"W

This notice affects Electronic Navigational Chart: CA573307

DFO(6604844-02)

22-APR-2022

LNM/D. 11-DEC-2020

Add depth of 5.8 metres
(See Chart No. 1, I10)

45°58'52.9"N 081°55'19.3"W

This notice affects Electronic Navigational Chart: CA573307

DFO(6604844-03)

19-MAY-2017

LNM/D. 30-SEP-2016

Add submarine power cable
(See Chart No. 1, L31.1)

joining 45°58'35.0"N 081°54'11.8"W
45°58'37.6"N 081°54'09.9"W

This notice affects Electronic Navigational Chart:
CA473229, CA573307

45°58'39.4"N 081°54'10.4"W
and 45°58'50.1"N 081°54'09.5"W

DFO(6604265-01)

26-SEP-2014

LNM/D. 26-DEC-2008

Reposition red starboard hand spar buoy, marked J32
(See Chart No. 1, Qf)

from 45°58'41.7"N 081°54'10.1"W
to 45°58'41.2"N 081°54'09.2"W

This notice affects Electronic Navigational Chart:
CA473229, CA573307

(D2014013) DFO(6604014-01)

26-DEC-2008

LNM/D. 12-DEC-2008



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2207

Amend legend F G 12m to read F G 9m against light

45°58'04.1"N 081°54'23.8"W

(D2008040) LL(997) DFO(6603345-01)

This notice affects Electronic Navigational Chart:
CA573307

26-DEC-2008

LNМ/D. 12-DEC-2008

Amend legend F R 9m to read F R 7m against light

45°58'51.3"N 081°54'24.1"W

(D2008041) LL(1001) DFO(6603346-01)

This notice affects Electronic Navigational Chart:
CA573307

26-DEC-2008

LNМ/D. 12-DEC-2008

Amend legend F R 14m to read F R 11m against light

45°58'57.5"N 081°54'31.9"W

(D2008042) LL(1002) DFO(6603347-01)

This notice affects Electronic Navigational Chart:
CA573307

12-DEC-2008

LNМ/D. 01-DEC-2006

Replace red starboard hand conical buoy, marked J46 with red
starboard hand spar buoy, marked J46

45°59'01.0"N 081°55'31.6"W

DFO(6603335-01)

This notice affects Electronic Navigational Chart: CA473229,
CA573307

01-DEC-2006

LNМ/D. 31-MAR-2006

Delete green port hand spar buoy, marked J43

45°58'59.0"N 081°55'38.5"W

(D2006064) DFO(6602844-01)

This notice affects Electronic Navigational Chart: CA473229,
CA573307

01-APR-2005

LNМ/D. 23-JUL-2004

Replace port hand can buoy, marked J45, with port hand spar buoy,
marked J45

45°59'05.7"N 081°55'37.9"W

(D2004182) DFO(6602286-01)

This notice affects Electronic Navigational Chart:
CA473229



Chart no. 2207

09-JUL-2004

Replace red starboard hand pillar light buoy QR, marked J24, with red starboard hand spar light buoy QR, marked J24

LNМ/D. 09-JAN-2004
45°58'12.6"N 081°53'34.9"W
(D2004054) LL(999) DFO(6601954-01)

09-JUL-2004

Replace green port hand pillar light buoy QG, marked J31, with green port hand spar light buoy QG, marked J31

LNМ/D. 09-JAN-2004
45°58'40.1"N 081°54'17.8"W
(D2004055) LL(1000) DFO(6601955-01)

09-JUL-2004

Replace red starboard hand pillar light buoy Fl R, marked J56, with red starboard hand spar light buoy Fl R, marked J56

LNМ/D. 09-JAN-2004
45°59'33.5"N 081°56'44.6"W
(D2004056) LL(1007) DFO(6601956-01)

09-JAN-2004

Delete red, starboard hand conical buoy, marked J28

LNМ/D. 16-MAY-2003
45°58'33.0"N 081°53'58.0"W
(D2003156) DFO(6601124-01)

09-JAN-2004

Add red, starboard hand spar buoy, marked J28

LNМ/D. 16-MAY-2003
45°58'33.7"N 081°53'58.3"W
(D2003156) DFO(6601124-02)

16-MAY-2003

Delete red, starboard hand conical buoy, marked J54

LNМ/D. 14-JUN-2002
45°59'29.5"N 081°56'31.2"W
(D2003015) DFO(6600809-01)

This notice affects Electronic Navigational Chart: CA473229

16-MAY-2003

Add red, starboard hand spar buoy, marked J54

LNМ/D. 14-JUN-2002
45°59'29.5"N 081°56'31.2"W
(D2003015) DFO(6600809-02)

This notice affects Electronic Navigational Chart: CA473229



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2207

16-MAY-2003

LNM/D. 14-JUN-2002

Delete red, starboard hand conical buoy, marked J60 45°59'32.6"N 081°57'06.7"W

(D2003017) DFO(6600810-01)

16-MAY-2003

LNM/D. 14-JUN-2002

Add red, starboard hand spar buoy, marked J60 45°59'32.6"N 081°57'06.7"W

(D2003017) DFO(6600810-02)