



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2225

2225 - Approaches to/Approches à Parry Sound - New Edition - 08-MAR-1991 - NAD 1927

01-JUL-2016

LNМ/D. 02-JAN-2015

Amend light characteristics Fl 7s 62ft 17M to read Fl 10s
62ft 11M against light
(See Chart No. 1, P16)

45°21'36.0"N 080°24'29.0"W

(D2016003) LL(906) DFO(6604213-02)

This notice affects Electronic Navigational Chart:
CA573283

02-JAN-2015

LNМ/D. 06-JUN-2008

Amend note Adjoining Chart/Carte adjacente 2242 to read Adjoining Chart/Carte adjacente 2224
(See Chart No. 1, A20)

in East border at 45°20'20"W

DFO(6604080-01)

06-JUN-2008

LNМ/D. 02-MAY-2008

Amend legend F G 40 ft to read F G 38 ft against light

45°22'15.0"N 080°19'19.5"W

(D2008017) LL(909) DFO(6603206-01)

02-MAY-2008

LNМ/D. 23-NOV-2007

Amend legend F G 49ft to read F G 57ft against light

45°22'25.1"N 080°18'40.6"W

(D2008016) LL(910) DFO(6603192-01)

This notice affects Electronic Navigational Chart:
CA573283

23-NOV-2007

LNМ/D. 04-AUG-2006

Add recommended track
(See Chart No. 1, M4)

joining 45°21'34.0"N 080°22'06.0"W
45°21'50.0"N 080°22'29.0"W
45°23'03.0"N 080°23'45.5"W
and 45°23'30.0"N 080°24'04.0"W

This notice affects Electronic Navigational Chart:
CA573283

DFO(6603021-01)

04-AUG-2006

LNМ/D. 02-SEP-2005



Chart no. 2225

Add submarine power cable

This notice affects Electronic Navigational Chart:
CA373311, CA573284

joining 45°19'07.2"N 080°13'22.0"W
45°19'01.8"N 080°13'26.0"W
45°18'47.2"N 080°14'09.0"W
45°18'46.7"N 080°14'16.5"W
45°18'47.9"N 080°14'17.0"W
45°18'49.5"N 080°14'19.5"W
45°18'48.8"N 080°14'51.0"W
45°18'45.4"N 080°15'11.0"W
45°18'39.5"N 080°15'29.0"W
45°18'41.0"N 080°15'43.0"W
45°18'42.0"N 080°15'45.0"W
45°18'36.5"N 080°15'50.0"W
45°18'31.4"N 080°15'57.5"W
45°18'29.0"N 080°16'06.0"W
45°18'27.0"N 080°16'25.5"W
45°18'20.0"N 080°16'38.0"W
45°18'16.0"N 080°16'43.5"W
45°18'19.0"N 080°16'44.0"W
45°18'26.0"N 080°16'48.5"W
45°18'30.0"N 080°16'55.5"W
and 45°18'32.0"N 080°17'06.0"W

DFO(6602738-01)

02-SEP-2005

Amend note Adjoining Chart/Carte adjacente 2284 to read
Adjoining Chart/Carte adjacente 2242

LNM/D. 03-JUN-2005
in South border at 80° 23' 06"W

DFO(6602475-01)

02-SEP-2005

Amend note Adjoining Chart/Carte adjacente 2284 to read
Adjoining Chart/Carte adjacente 2242

LNM/D. 03-JUN-2005
in South border at 80° 14' 30"W

DFO(6602475-02)

02-SEP-2005

Amend note Adjoining Chart/Carte adjacente 2284 to read Adjoining
Chart/Carte adjacente 2242

LNM/D. 03-JUN-2005
in East border at 45° 20' 24"N

DFO(6602475-03)

02-SEP-2005

Amend note Adjoining Chart/Carte adjacente 2284 to read
Adjoining Chart/Carte adjacente 2242

LNM/D. 03-JUN-2005
in North border at 80° 25' 00"W

DFO(6602475-04)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2225

02-SEP-2005

LNM/D. 03-JUN-2005

Amend note Adjoining Chart/Carte adjacente 2284 to read Adjoining in West border at 45° 21' 00"N
Chart/Carte adjacente 2242

DFO(6602475-05)

03-JUN-2005

LNM/D. 08-APR-2005

Delete radar transponder beacon Racon against light

45°21'36.0"N 080°24'29.0"W

(D2005031) LL(906) DFO(6602356-01)

This notice affects Electronic Navigational Chart:
CA273097, CA573283

08-APR-2005

LNM/D. 11-MAR-2005

Delete legend Tr Aband (35ft) against tower 45°19'53.5"N 080°15'30.5"W

DFO(6602292-03)

08-APR-2005

LNM/D. 11-MAR-2005

Add legend Tr (35ft) against tower 45°19'53.5"N 080°15'30.5"W

DFO(6602292-04)

11-MAR-2005

LNM/D. 28-JAN-2005

Amend legend 131½° to read 132° 45°20'58.0"N 080°20'12.0"W

LL(917/918) DFO(6602262-01)

11-MAR-2005

LNM/D. 28-JAN-2005

Amend legend Fl 7s 66ft 17M to read Fl 7s 62ft 17M against light 45°21'36.0"N 080°24'29.0"W

LL(906) DFO(6602263-01)

This notice affects Electronic Navigational Chart: CA273097

28-JAN-2005

LNM/D. 26-OCT-2001

Replace red starboard hand conical buoy, marked P20 with red
starboard hand spar buoy, marked P20

45°20'15.0"N 080°19'29.0"W

(D2004140) DFO(6602157-01)

This notice affects Electronic Navigational Chart:
CA573283



Chart no. 2225

26-OCT-2001 LNM/D. 09-MAR-2001

Add port daybeacon 45°20'25.5"N 080°17'33.0"W

DFO(6601703-02)

09-MAR-2001

LNM/D. 23-JUN-2000

Add red starboard hand spar buoy marked PP4

45°22'35.1"N 080°23'05.0"W

(CCG-D01-010) LL(8759.02) DFO(6601417-01)

09-MAR-2001

LNM/D. 23-JUN-2000

Add green port hand spar buoy marked PP5

45°22'28.4"N 080°23'23.3"W

(CCG-D01-011) LL(8759.03) DFO(6601418-01)

23-JUN-2000

LNM/D. 16-JUN-2000

(T)Add red starboard hand spar buoy, marked PP4

45°22'35.4"N 080°23'40.5"W

Temporary action dated 23-JUN-2000, is now *(CCG-D00-071) LL(8759.02) DFO(6601129-01)*
a permanent action. Refer to the chart action
to that effect in this publication.

Cancelled on 30-JAN-01

16-JUN-2000

LNM/D. 09-JUN-2000

(T)Add green, port hand, spar buoy, marked PP5

45°22'28.7"N 080°23'22.8"W

Temporary action dated 16-JUN-2000, is now *(CCG-D00-073) LL(8759.03) DFO(6601131-01)*
a permanent action. Refer to the chart action
to that effect in this publication.

Cancelled on 09-MAR-01

09-JUN-2000

LNM/D. 31-DEC-1999

Delete depth of 12ft 45°16'20.0"N 080°13'51.7"W

DFO(6600560-01)