



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2241

2241 - Waubaushene - New Chart - 30-JUL-1999 - NAD 1983

15-DEC-2000 LNM/D. 04-AUG-2000

Affix patch 44°46'18.0"N 079°42'30.0"W

DFO(6500392-01)

[PDF](#)

04-MAY-2001

LNM/D. 15-DEC-2000

Add green port hand spar buoy marked MC41 44°45'39.8"N 079°42'31.7"W

(CCG-D01-027) DFO(6601468-01)

2241 - Port Severn to/à Christian Island - New Chart - 30-JUL-1999 - NAD 1983

30-NOV-2012

LNM/D. 26-DEC-2008

Add crib with known depth of 0.6, Rep (2000) 44°46'13.0"N 079°56'35.0"W
(See Chart No. 1, Fb, Ka)

DFO(6500444-01)

This NTM cancels 6600441
Cancelled on

30-NOV-2012

LNM/D. 26-DEC-2008

Add crib with known depth of 0.3, Rep (2000) 44°46'17.5"N 079°56'55.0"W
(See Chart No. 1, Fb, Ka)

DFO(6500444-02)

This NTM cancels 6600441
Cancelled on

28-APR-2000

(P)Add Notice 28-APR-200, add crib with known depth of "0.6m" 44°46'13.0"N 079°56'35.0"W

With this notification, notice 28 APR 2000 is now cancelled.

See reference 6500444-1, appearing in this edition

DFO(6600441-01)

This NTM canceled by 6500444

Cancelled on 30-NOV-12

28-APR-2000

(P)Add Notice 28-APR-2000, add crib with known depth of "0.3 m" 44°46'17.5"N 079°56'55.0"W

This NTM canceled by 6500444

DFO(6600441-02)

Cancelled on 30-NOV-12



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2241

28-FEB-2003

LNM/D. 06-JUL-2001

Amend FR to read Oc(3) R 10s against light

44°48'29.4"N 079°52'29.7"W

(D2002051) LL(878) DFO(6600710-01)

20-JUN-2003

LNM/D. 28-FEB-2003

Add green, port hand spar buoy, marked MN3

44°51'27.2"N 079°51'11.4"W

(D2003045) DFO(6600867-01)

10-OCT-2003

LNM/D. 03-OCT-2003

Add red, starboard hand spar buoy, marked MK2/2

44°50'39.8"N 079°50'24.0"W

(D2003073) DFO(6600976-01)

03-OCT-2003

LNM/D. 20-JUN-2003

Add red, starboard hand spar buoy, marked MH2/2

44°53'18.8"N 079°54'04.2"W

(D2003074) DFO(6600977-01)

31-OCT-2003

LNM/D. 10-OCT-2003

Delete red and white, fairway pillar light buoy, Mo (A),
marked MK

44°50'23.2"N 079°50'50.4"W

(D2003118) LL(895) DFO(6601018-01)

31-OCT-2003

LNM/D. 10-OCT-2003

Add red and white, fairway spar light buoy, Mo (A), marked MK

44°50'23.0"N 079°50'51.0"W

DFO(6601018-02)

09-JAN-2004

LNM/D. 31-OCT-2003

Delete red starboard hand pillar light buoy FIR, marked
MM4

44°46'31.8"N 079°48'06.1"W

(D2003117) LL(883) DFO(6601021-01)

09-JAN-2004

LNM/D. 31-OCT-2003



Chart no. 2241

Add red starboard hand spar light buoy FIR, marked MM4 44°46'31.5"N 079°48'06.2"W
(D2003117) LL(883) DFO(6601021-02)

04-AUG-2000 LNM/D. 28-APR-2000
Add breakwater joining 44°48'58.3"N 079°50'50.9"W
44°48'57.5"N 079°50'48.9"W
and 44°48'55.8"N 079°50'47.7"W
DFO(6601168-01)

06-FEB-2004 LNM/D. 09-JAN-2004
Add green, port hand spar buoy, marked MP5 44°46'54.2"N 079°43'40.4"W
(D2003170) DFO(6601298-01)

27-FEB-2004 LNM/D. 06-FEB-2004
Amend F 20m to read Fl 20m against light 44°47'11.9"N 080°09'21.8"W
(D2003172) LL(857.5) DFO(6601300-01)

04-MAY-2001 LNM/D. 15-DEC-2000
Replace red starboard hand spar buoy marked GB6 44°59'38.7"N 080°05'02.3"W
with yellow, black, yellow, West cardinal pillar
light buoy, Q(9) 15s, marked MC (CCG-D01-030) LL(902.4) DFO(6601470-01)

04-MAY-2001 LNM/D. 15-DEC-2000
Replace green light, port hand pillar buoy FIG marked 44°51'43.2"N 079°50'56.4"W
MN5, with green light, port hand spar buoy FIG
marked MN5 (D2001035) LL(895.5) DFO(6601475-02)

06-JUL-2001 LNM/D. 04-MAY-2001
Delete submarine cable between 44°45'42.0"N 079°46'24.0"W
and 44°46'03.5"N 079°47'00.0"W
DFO(6601516-01)



Chart no. 2241

06-JUL-2001

LNM/D. 04-MAY-2001

Add submarine cable between 44°45'43.0"N 079°46'19.0"W
and 44°46'04.5"N 079°47'01.0"W

DFO(6601516-02)

09-APR-2004

LNM/D. 27-FEB-2004

Replace green port hand pillar light buoy Fl G, marked MV1
with green port hand spar light buoy Fl G, marked
MV1

44°45'12.5"N 079°47'12.0"W

(D2003179) LL(884) DFO(6601832-01)

25-JUN-2004

LNM/D. 09-APR-2004

Add depth of 0.2m

44°58'12.6"N 080°03'54.7"W

DFO(6601927-01)

This notice affects Electronic Navigational Chart: CA273097

25-JUN-2004

LNM/D. 09-APR-2004

Delete depth of 2.8m 44°57'08.6"N 080°03'54.9"W

DFO(6601927-02)

25-JUN-2004

LNM/D. 09-APR-2004

Add depth of 2.1m

44°57'09.4"N 080°03'52.1"W

DFO(6601927-03)

This notice affects Electronic Navigational Chart: CA273097

25-JUN-2004

LNM/D. 09-APR-2004

Delete depth of 4.6 metres

44°57'29.2"N 080°00'40.3"W

DFO(6601927-04)

This notice affects Electronic Navigational Chart: CA273097

25-JUN-2004

LNM/D. 09-APR-2004

Add depth of 4.4 metres

44°57'26.2"N 080°00'40.1"W

DFO(6601927-05)

This notice affects Electronic Navigational Chart: CA273097



Chart no. 2241

16-JUL-2004

Replace green port hand pillar light buoy Fl G, marked M13, with green port hand spar light buoy Fl G, marked M13

LNМ/D. 09-JUL-2004
44°49'14.9"N 079°52'28.2"W
(D2004037) LL(863) DFO(6601936-01)

This notice affects Electronic Navigational Chart: CA473297

16-JUL-2004

Replace red starboard hand pillar light buoy Fl R, marked M12, with red starboard hand spar light buoy Fl R, marked M12

LNМ/D. 09-JUL-2004
44°50'22.7"N 079°53'38.3"W
(D2004036) LL(862.000) DFO(6601936-02)

This notice affects Electronic Navigational Chart: CA473297

16-JUL-2004

Replace red starboard hand pillar light buoy Fl R, marked M6, with red starboard hand spar light buoy Fl R, marked M6

LNМ/D. 09-JUL-2004
44°52'26.7"N 079°57'04.8"W
(D2004035) LL(860.000) DFO(6601936-03)

This notice affects Electronic Navigational Chart: CA473297

16-JUL-2004

Replace green port hand pillar light buoy Fl G, marked M3, with green port hand spar light buoy Fl G, marked M3

LNМ/D. 09-JUL-2004
44°52'25.0"N 080°01'26.9"W
(D2004034) LL(858.000) DFO(6601936-04)

This notice affects Electronic Navigational Chart: CA473297

09-JUL-2004

Replace red starboard hand pillar light buoy Fl R, marked M20, with red starboard hand spar light buoy Fl R, marked M20

LNМ/D. 25-JUN-2004
44°45'57.0"N 079°52'44.0"W
(D2004038) LL(870) DFO(6601937-01)



Chart no. 2241

27-MAY-2005

Amend note Adjoining Chart/Carte adjacente 2289 to read
Adjoining Chart/Carte adjacente 2242

LNМ/D. 16-JUL-2004

in north border at 80° 07' 30" W

DFO(6602361-02)

27-MAY-2005

Amend note Adjoining Chart/Carte adjacente 2289 to read
Adjoining Chart/Carte adjacente 2242

LNМ/D. 16-JUL-2004

in west border at 44° 57' 30" N

DFO(6602361-03)

18-NOV-2005

Replace yellow, black and yellow West cardinal lighted
pillar buoy Q(9) 15s, marked MC with a yellow,
black and yellow West cardinal lighted spar buoy (D2005059) LL(902.4) DFO(6602541-01)
Q(9) 15s, marked MC

LNМ/D. 27-MAY-2005

44°59'38.7"N 080°05'02.3"W

03-FEB-2006

Amend legend Fl 5s 18m 21M to read Fl 10s 18m against
light

LNМ/D. 18-NOV-2005

44°54'56.6"N 080°09'52.3"W

(D2005087) LL(857) DFO(6602602-01)

31-AUG-2007

Delete private white and orange hazard spar buoy
(See Chart No. 1 Qs)

LNМ/D. 03-FEB-2006

44°45'23.8"N 079°51'54.9"W

DFO(6603002-01)

This notice affects Electronic Navigational Chart: CA473297

31-AUG-2007

Delete submerged pipeline, PWI
(See Chart No. 1 Lb)

LNМ/D. 03-FEB-2006

between 44°45'19.0"N 079°52'05.0"W
and 44°45'22.5"N 079°51'56.0"W

DFO(6603002-02)

This notice affects Electronic Navigational Chart:
CA473297

12-DEC-2008

LNМ/D. 31-AUG-2007



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2241

Replace rear range/leading light F 27m with rear
range/leading beacon
(See Chart No. 1, P20.2 and Q120)

44°52'37.0"N 079°52'30.0"W

(D2008032) LL(865) DFO(6603317-01)

This notice affects Electronic Navigational Chart:
CA473297

26-DEC-2008

Amend legend F 12m to read Iso against light

LNМ/D. 12-DEC-2008

44°52'36.0"N 079°53'04.4"W

(D2008046) LL(864) DFO(6603351-01)

This notice affects Electronic Navigational Chart:
CA473297

13-JUL-2018

Add underwater rock of unknown depth, dangerous to surface
navigation, Rep (2018)
(See Chart No. 1, K13)

LNМ/D. 30-NOV-2012

44°45'20.4"N 079°47'48.0"W

DFO(6604426-01)

This notice affects Electronic Navigational Chart: CA473271

31-JUL-2020

Amend FG 53m to read FG 46m against light

LNМ/D. 13-JUL-2018

44°45'22.2"N 079°49'45.7"W

(D2018015) LL(867) DFO(6604650-01)