



Chart no. 2268

2268 - Blind River - New Edition - 31-MAR-1989 - NAD 1927

13-APR-2007

LNМ/D. 16-JUL-2004

Replace green, red and green port bifurcation can buoy, marked UN
with green, red and green port bifurcation spar buoy, marked
UN

46°10'31.2"N 082°57'54.8"W

DFO(6602879-01)

13-APR-2007

LNМ/D. 16-JUL-2004

Replace green port hand can buoy, marked UP3 with green port hand
spar buoy, marked UP3

46°10'21.0"N 082°57'55.0"W

DFO(6602879-02)

13-APR-2007

LNМ/D. 16-JUL-2004

Replace red starboard hand conical buoy, marked UP4 with red
starboard hand spar buoy, marked UP4

46°10'20.9"N 082°57'50.0"W

DFO(6602879-03)

13-APR-2007

LNМ/D. 16-JUL-2004

Delete sounding of 2 ft 46°10'47.0"N 082°57'02.0"W

DFO(6602880-01)

13-APR-2007

LNМ/D. 16-JUL-2004

Add sounding of 1ft with bottom quality of Bo 46°10'47.1"N 082°57'01.6"W

DFO(6602880-02)

13-APR-2007

LNМ/D. 16-JUL-2004

Delete tower, Tr 46°10'40.0"N 082°58'56.5"W

DFO(6602880-03)

13-APR-2007

LNМ/D. 16-JUL-2004

Delete tower, Tr 46°10'37.0"N 082°58'55.0"W

DFO(6602880-04)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2268

27-FEB-2004

LNM/D. 13-JUN-2003

Replace green port hand pillar light buoy FlG, marked UP9
with green port hand spar light buoy FlG, marked
UP9

46°10'51.0"N 082°57'29.0"W

(D2003154) LL(1031) DFO(6601122-01)

2268 - Boyd Island to/à Spanish River - New Edition - 31-MAR-1989 - NAD 1927

30-DEC-2022

LNM/D. 25-MAR-2022

Add red starboard hand spar buoy, marked U14 (See Chart 1, Qb)

46°10'28.4"N 082°22'42.8"W

(D2022055) DFO(6604976-01)

25-MAR-2022

LNM/D. 05-NOV-2021

Delete starboard hand daybeacon
(See Chart No. 1, Qt)

46°10'28.7"N 082°22'42.3"W

This notice affects Electronic Navigational Chart: CA473251 *(D2022004) DFO(6604836-01)*

05-NOV-2021

LNM/D. 12-APR-2013

Delete depth of 46 feet

46°06'46.8"N 082°20'37.9"W

(See Chart No. 1, I10)

DFO(6604786-02)

05-NOV-2021

LNM/D. 12-APR-2013

Delete legend Rep (2011) against crib 46°10'42.7"N 082°23'07.7"W

DFO(6604786-06)

05-NOV-2021

LNM/D. 12-APR-2013

Delete depth of 10 feet

46°09'56.6"N 082°22'26.6"W

(See Chart No. 1, I10)

DFO(6604786-07)

05-NOV-2021

LNM/D. 12-APR-2013

Add obstruction with known depth of 1 foot

46°09'52.8"N 082°22'34.5"W

(See Chart No. 1, K41)

This notice affects Electronic Navigational Chart: CA473251

DFO(6604786-11)



Chart no. 2268

- 05-NOV-2021** LNM/D. 12-APR-2013
Add obstruction with known depth of 24 feet 46°06'48.2"N 082°20'36.5"W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA473251 *DFO(6604786-12)*
- 05-NOV-2021** LNM/D. 12-APR-2013
Add obstruction with known depth of 32 feet 46°06'59.6"N 082°20'28.1"W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA473251 *DFO(6604786-14)*
- 05-NOV-2021** LNM/D. 12-APR-2013
Add obstruction with known depth of 2 feet 46°10'12.5"N 082°22'46.7"W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA473251 *DFO(6604786-15)*
- 05-NOV-2021** LNM/D. 12-APR-2013
Add legend Ru against crib 46°10'44.2"N 082°23'03.3"W
(See Chart No. 1, F33)
This notice affects Electronic Navigational Chart: CA473251 *DFO(6604786-16)*
- 05-NOV-2021** LNM/D. 12-APR-2013
Add depth of 4 feet over crib 46°10'44.2"N 082°23'03.3"W
(See Chart No. 1, Ka, Ib)
This notice affects Electronic Navigational Chart: CA473251 *DFO(6604786-17)*
- 05-NOV-2021** LNM/D. 12-APR-2013
Add obstruction with known depth of 48 feet 46°08'32.6"N 082°21'24.4"W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA473251 *DFO(6604786-18)*
- 12-APR-2013** LNM/D. 17-AUG-2007
Add crib which covers and uncovers Rep (2011) 46°10'44.2"N 082°23'03.3"W
(See Chart No. 1, Fb)
This notice affects Electronic Navigational Chart: CA473251 *DFO(6603861-01)*
- 17-AUG-2007** LNM/D. 13-APR-2007



Chart no. 2268

Add breakwater joining 46°11'02.3"N 082°21'44.5"W
46°10'59.0"N 082°21'44.0"W
and 46°10'58.8"N 082°21'41.8"W

DFO(6602509-01)

17-AUG-2007 LNM/D. 13-APR-2007

Add breakwater between 46°10'59.5"N 082°21'40.0"W
and 46°11'00.0"N 082°21'33.0"W

DFO(6602509-02)

17-AUG-2007 LNM/D. 13-APR-2007

Delete shoreline and legend Ru. between 46°11'03.8"N 082°21'31.0"W
and 46°11'02.0"N 082°21'16.7"W

DFO(6602509-03)

17-AUG-2007 LNM/D. 13-APR-2007

Add shoreline joining 46°11'03.8"N 082°21'31.0"W
46°11'03.0"N 082°21'30.5"W
46°11'00.1"N 082°21'32.0"W
46°11'00.5"N 082°21'30.5"W
46°11'02.5"N 082°21'29.0"W
46°11'03.5"N 082°21'27.5"W
46°11'04.3"N 082°21'25.0"W
46°11'03.5"N 082°21'22.0"W
46°11'02.7"N 082°21'22.0"W
46°11'02.2"N 082°21'21.0"W
46°11'02.0"N 082°21'19.0"W
and 46°11'02.0"N 082°21'16.7"W

DFO(6602509-04)

17-AUG-2007 LNM/D. 13-APR-2007

Add private light FG 46°10'58.8"N 082°21'41.8"W

DFO(6602509-05)

This notice affects Electronic Navigational Chart: CA473251

17-AUG-2007 LNM/D. 13-APR-2007



Chart no. 2268

Delete crib with drying height of 0m 46°11'01.6"N 082°21'28.5"W

DFO(6602509-06)

17-AUG-2007 LNM/D. 13-APR-2007

Delete crib 46°11'00.0"N 082°21'28.0"W

DFO(6602509-07)

16-JUL-2004

Delete red starboard hand pillar light buoy Fl R, marked
UV2

LNM/D. 27-FEB-2004

46°10'52.8"N 082°22'15.0"W

(D2004073) LL(1013.3) DFO(6601987-01)

16-JUL-2004

Add red starboard hand spar light buoy Fl R, marked
UV2

LNM/D. 27-FEB-2004

46°10'51.4"N 082°22'28.0"W

(D2004073) LL(1013.300) DFO(6601987-02)

16-JUL-2004

Delete green port hand spar buoy, marked UV1 46°10'54.8"N 082°22'10.0"W

LNM/D. 27-FEB-2004

(D2004074) DFO(6601987-03)

16-JUL-2004

Add green port hand spar buoy, marked UV1/1 46°10'55.4"N 082°22'10.7"W

LNM/D. 27-FEB-2004

(D2004075) DFO(6601987-04)

16-JUL-2004

Add red starboard hand spar buoy, marked UV2/2 46°10'54.9"N 082°22'10.0"W

LNM/D. 27-FEB-2004

(D2004076) DFO(6601987-05)

16-JUL-2004

LNM/D. 27-FEB-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2268

Reposition red starboard hand spar buoy, marked UV4 from 46°10'55.0"N 082°21'50.0"W
to 46°10'57.7"N 082°21'41.7"W

(D2004078) DFO(6601987-06)

16-JUL-2004

LNM/D. 27-FEB-2004

Delete port hand daybeacon

46°10'28.0"N 082°22'28.0"W

A rock with elevation 7 feet remains in this location.

(D2004079) DFO(6601987-07)

16-JUL-2004

LNM/D. 27-FEB-2004

Add starboard hand daybeacon 46°10'28.5"N 082°22'42.5"W

(D2004080) DFO(6601987-08)

16-JUL-2004

LNM/D. 27-FEB-2004

Add green port hand spar buoy, marked UV1 46°10'51.8"N 082°22'28.5"W

(D2004074) DFO(6601987-09)

13-JUN-2003

LNM/D. 03-SEP-1999

Add rock with known depth of 6 ft, with legend Repd 1990

46°07'07.5"N 082°20'10.5"W

With this notification, Notice 380(P)/91 is cancelled. See
reference DFO 6000743 appearing in this edition.

DFO(6600859-01)

2268 - Little Detroit - New Edition - 31-MAR-1989 - NAD 1927

05-NOV-2021

LNM/D. 12-APR-2013

Delete depth of 47 feet 46°08'56.6"N 082°22'26.6"W
(See Chart No. 1, I10)

DFO(6604786-08)

05-NOV-2021

LNM/D. 12-APR-2013

Delete depth of 20 feet 46°08'54.5"N 082°22'22.6"W
(See Chart No. 1, I10)

DFO(6604786-09)

05-NOV-2021

LNM/D. 12-APR-2013



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2268

Add obstruction with known depth of 22 feet
(See Chart No. 1, K41)

46°08'56.8"N 082°22'26.4"W

This notice affects Electronic Navigational Chart: CA473251

DFO(6604786-19)

05-NOV-2021

LN/D. 12-APR-2013

Add obstruction with known depth of 14 feet
(See Chart No. 1, K41)

46°08'54.5"N 082°22'22.6"W

This notice affects Electronic Navigational Chart: CA473251

DFO(6604786-20)