



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2282

2282 - Lion's Head Harbour - New Edition - 07-JUN-1996 - NAD 1983

06-JAN-2023

LNМ/D. 24-SEP-2021

Add red starboard hand lighted spar buoy Fl R, marked
TV2

44°59'23.9"N 081°14'51.5"W

(See Chart 1, Qb)

(D2022070) LL(825.2) DFO(6605009-01)

This notice affects Electronic Navigational Chart:
CA373286

24-SEP-2021

LNМ/D. 28-AUG-2020

Reposition light, marked Iso

from 44°59'26.0"N 081°14'53.3"W

(See Chart No. 1, P1)

to 44°59'25.9"N 081°14'53.6"W

This notice affects Electronic Navigational
Chart: CA373286

(D2021013) LL(825) DFO(6604749-01)

12-DEC-2008

LNМ/D. 04-JAN-2008

Amend legend Iso R to read Iso against light

44°59'26.0"N 081°14'53.2"W

(See Chart No. 1, P16)

(D2008031) LL(825) DFO(6603329-01)

This notice affects Electronic Navigational Chart:
CA373286

28-FEB-2003

LNМ/D. 03-JAN-2003

Reposition light Iso R

from 44°59'24.5"N 081°14'51.9"W

to 44°59'26.0"N 081°14'53.2"W

(D2002055) LL(825) DFO(6600714-01)

2282 - Owen Sound to/à Cabot Head - New Edition - 07-JUN-1996 - NAD 1983

28-JUL-2023

LNМ/D. 06-JAN-2023

Add subsurface Ocean Data Acquisition system (ODAS) with known
depth of 2 metres (See Chart 1, L25)

45°02'29.6"N 081°02'30.5"W

This notice affects Electronic Navigational Chart: CA273097,
CA373286

DFO(6605081-01)

24-SEP-2021

LNМ/D. 28-AUG-2020



Chart no. 2282

Reposition light, marked Iso
(See Chart No. 1, P1)
This notice affects Electronic Navigational
Chart: CA373286

from 44°59'24.5"N 081°14'50.9"W
to 44°59'25.9"N 081°14'53.6"W

(D2021013) LL(825) DFO(6604749-01)

28-AUG-2020

Amend Fl 10s 24m 9M to read Fl 10s 25m 10M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA273097, CA373281

LNM/D. 14-FEB-2014
45°14'42.8"N 081°17'31.1"W

(D2020010) LL(826) DFO(6604651-01)

14-FEB-2014

Replace dangerous underwater rock of 2 metres or less with rock
awash (See Chart No. 1, K13, K12)

LNM/D. 03-DEC-2010
44°53'50.5"N 081°03'50.0"W

DFO(6603950-02)

03-DEC-2010

Amend Iso R to read Fl R 5s against light
(See Chart No. 1, P16)

LNM/D. 12-DEC-2008
44°45'00.2"N 081°08'07.9"W

(D2010011) LL(830) DFO(6603645-01)

This notice affects Electronic Navigational Chart:
CA373287

12-DEC-2008

Amend legend Iso R to read Iso against light
(See Chart No. 1, P16)

LNM/D. 04-JAN-2008
44°59'24.5"N 081°14'52.0"W

(D2008031) LL(825) DFO(6603329-01)

This notice affects Electronic Navigational Chart:
CA373286

04-JAN-2008

Delete yellow cautionary spar buoy, marked TMAA
(See Chart No. 1, Qm)

LNM/D. 23-NOV-2007
44°43'01.5"N 080°46'11.7"W

(D2007016) DFO(6603034-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

LNM/D. 23-NOV-2007



Chart no. 2282

Delete yellow cautionary spar buoy, marked TMA
(See Chart No.1, Qm)

44°43'16.7"N 080°46'13.4"W

(D2007017) DFO(6603035-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

LNМ/D. 23-NOV-2007

Delete yellow cautionary spar buoy, marked TMB
(See Chart No. 1, Qm)

44°43'39.1"N 080°46'15.5"W

(D2007018) DFO(6603036-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

LNМ/D. 23-NOV-2007

Delete yellow cautionary spar buoy, marked TMC
(See Chart No.1, Qm)

44°44'12.8"N 080°46'18.8"W

(D2007020) DFO(6603037-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

LNМ/D. 23-NOV-2007

Replace yellow cautionary lighted spar buoy Fl Y, marked
TMD with yellow cautionary lighted spar buoy Fl
Y, marked TMA
(See Chart No. 1, Qm)

44°44'40.2"N 080°46'21.4"W

(D2007021) LL(839.3) DFO(6603038-01)

This notice affects Electronic Navigational Chart:
CA373287

04-JAN-2008

LNМ/D. 23-NOV-2007

Delete yellow cautionary spar buoy, marked TME
(See Chart No.1, Qm)

44°44'40.2"N 080°45'36.4"W

(D2007022) DFO(6603039-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

LNМ/D. 23-NOV-2007



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2282

Delete yellow cautionary spar buoy, marked TMF
(See Chart No.1, Qm)

44°44'40.2"N 080°44'50.3"W

(D2007023) DFO(6603040-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

Replace yellow cautionary spar buoy, marked TMG with yellow
cautionary spar buoy, marked TMB
(See Chart No. 1, Qm)

LNМ/D. 23-NOV-2007

44°44'40.2"N 080°44'04.9"W

(D2007024) DFO(6603041-01)

This notice affects Electronic Navigational Chart:
CA373287

04-JAN-2008

Delete yellow cautionary spar buoy, marked TMH
(See Chart No.1, Qm)

LNМ/D. 23-NOV-2007

44°44'40.2"N 080°43'22.4"W

(D2007025) DFO(6603042-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

Delete yellow cautionary spar buoy, marked TMI
(See Chart No. 1, Qm)

LNМ/D. 23-NOV-2007

44°44'39.8"N 080°42'34.9"W

(D2007026) DFO(6603043-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

Replace yellow cautionary spar buoy, marked TMJ with yellow
cautionary lighted spar buoy Fl Y, marked TMC
(See Chart No. 1, Qm)

LNМ/D. 23-NOV-2007

44°44'40.2"N 080°41'49.6"W

(D2007027) DFO(6603044-01)

This notice affects Electronic Navigational Chart:
CA373287



Chart no. 2282

04-JAN-2008

Delete yellow cautionary lighted spar buoy Fl Y, marked
TMK
(See Chart No. 1, Qm)

LNМ/D. 23-NOV-2007
44°44'40.2"N 080°41'03.8"W
(D2007028) LL(839.4) DFO(6603045-01)

This notice affects Electronic Navigational Chart:
CA373287

04-JAN-2008

Delete yellow cautionary spar buoy, marked TML
(See Chart No. 1, Qm)

LNМ/D. 23-NOV-2007
44°44'40.2"N 080°40'18.1"W
(D2007030) DFO(6603046-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

Replace yellow cautionary spar buoy, marked TMM with yellow
cautionary spar buoy, marked TMD
(See Chart No. 1, Qm)

LNМ/D. 23-NOV-2007
44°44'40.2"N 080°39'31.7"W
(D2007031) DFO(6603047-01)

This notice affects Electronic Navigational Chart:
CA373287

04-JAN-2008

Delete yellow cautionary spar buoy, marked TMN
(See Chart No. 1, Qm)

LNМ/D. 23-NOV-2007
44°44'35.5"N 080°38'47.8"W
(D2007032) DFO(6603048-01)

This notice affects Electronic Navigational Chart: CA373287

04-JAN-2008

Delete yellow cautionary spar buoy, marked TMO
(See Chart No. 1, Qm)

LNМ/D. 23-NOV-2007
44°44'29.8"N 080°37'59.5"W
(D2007033) DFO(6603049-01)

This notice affects Electronic Navigational Chart: CA373287



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2282

23-NOV-2007

Replace green port hand lighted pillar buoy Fl G, marked T5 with green port hand lighted spar buoy Fl G, marked T5
(See Chart No. 1, Qg)

LNМ/D. 25-MAY-2007

45°03'31.1"N 081°01'44.5"W

(D2007015) LL(827) DFO(6603020-01)

This notice affects Electronic Navigational Chart:
CA373286

23-NOV-2007

Delete Adjoining Chart/Carte adjacente 2284 in top right border of chart at 45° 18' 00" N

LNМ/D. 25-MAY-2007

DFO(6603024-01)

25-MAY-2007

Add tower with elevation of (107)m, RLts
(See Chart No. 1, E20)

LNМ/D. 13-APR-2007

44°57'29.4"N 080°57'53.3"W

DFO(6602909-01)

This notice affects Electronic Navigational Chart: CA373287

25-MAY-2007

Add tower with elevation of (134)m, WLts
(See Chart No. 1, E20)

LNМ/D. 13-APR-2007

44°35'00.8"N 080°54'47.0"W

DFO(6602909-03)

This notice affects Electronic Navigational Chart: CA373287

13-APR-2007

Amend Fl (2) 5s 19m 24M to read Iso against light.

LNМ/D. 28-JAN-2005

44°57'21.3"N 080°57'38.1"W

(D2006090) LL(828) DFO(6602900-01)

This notice affects Electronic Navigational Chart:
CA273097, CA373287

28-JAN-2005

LNМ/D. 19-NOV-2004



Chart no. 2282

Amend legend Fl 15s 24m 14M to read Fl 10s 24m 9M
against light

45°14'42.8"N 081°17'31.1"W

(D2004067) LL(826) DFO(6602139-01)

This notice affects Electronic Navigational Chart:
CA273097, CA373281

19-NOV-2004

Add yellow cautionary spar buoy, marked TMA
With this notification, a (P) portion of Notice 07-SEP-2001 is
cancelled. See reference DFO 6601627-01 appearing in this
edition.

LNМ/D. 06-FEB-2004

44°43'16.7"N 080°46'13.4"W

DFO(6602080-01)

19-NOV-2004

Add yellow cautionary spar buoy, marked TMC
With this notification, a (P) portion of Notice 07-SEP-2001 is
cancelled. See reference DFO 6601628-01 appearing in this
edition.

LNМ/D. 06-FEB-2004

44°44'12.8"N 080°46'18.8"W

DFO(6602080-02)

19-NOV-2004

Add yellow cautionary spar buoy, marked TME
With this notification, a (P) portion of Notice 07-SEP-2001 is
cancelled. See reference DFO 6601629-01 appearing in this
edition.

LNМ/D. 06-FEB-2004

44°44'40.2"N 080°45'36.4"W

DFO(6602080-03)

19-NOV-2004

Add yellow cautionary spar buoy, marked TMF
With this notification, a (P) portion of Notice 07-SEP-2001 is
cancelled. See reference DFO 6601630-01 appearing in this
edition.

LNМ/D. 06-FEB-2004

44°44'40.2"N 080°44'50.3"W

DFO(6602080-04)

19-NOV-2004

Add yellow cautionary spar buoy, marked TMG
With this notification, a (P) portion of Notice 07-SEP-2001 is
cancelled. See reference DFO 6601631-01 appearing in this
edition.

LNМ/D. 06-FEB-2004

44°44'40.2"N 080°44'04.9"W

DFO(6602080-05)

19-NOV-2004

LNМ/D. 06-FEB-2004



Chart no. 2282

Add yellow cautionary spar buoy, marked TMB With this notification, a (P) portion of Notice 07-SEP-2001 is cancelled. See reference DFO 6601633-01 appearing in this edition.	44°43'39.1"N 080°46'15.5"W <i>DFO(6602080-06)</i>
19-NOV-2004 Add yellow cautionary spar buoy, marked TMH With this notification, a (P) portion of Notice 07-SEP-2001 is cancelled. See reference DFO 6601634-01 appearing in this edition.	LNМ/D. 06-FEB-2004 44°44'40.2"N 080°43'22.4"W <i>DFO(6602080-07)</i>
19-NOV-2004 Add yellow cautionary spar buoy, marked TMI With this notification, a (P) portion of Notice 07-SEP-2001 is cancelled. See reference DFO 6601635-01 appearing in this edition.	LNМ/D. 06-FEB-2004 44°44'39.8"N 080°42'34.9"W <i>DFO(6602080-08)</i>
19-NOV-2004 Add yellow cautionary spar buoy, marked TMJ With this notification, a (P) portion of Notice 07-SEP-2001 is cancelled. See reference DFO 6601636-01 appearing in this edition.	LNМ/D. 06-FEB-2004 44°44'40.2"N 080°41'49.6"W <i>DFO(6602080-09)</i>
19-NOV-2004 Add yellow cautionary spar buoy, marked TML With this notification, a (P) portion of Notice 07-SEP-2001 is cancelled. See reference DFO 6601637-01 appearing in this edition.	LNМ/D. 06-FEB-2004 44°44'40.2"N 080°40'18.1"W <i>DFO(6602080-10)</i>
19-NOV-2004 Add yellow cautionary spar buoy, marked TMM With this notification, a (P) portion of Notice 07-SEP-2001 is cancelled. See reference DFO 6601638-01 appearing in this edition.	LNМ/D. 06-FEB-2004 44°44'40.2"N 080°39'31.7"W <i>DFO(6602080-11)</i>
19-NOV-2004 Add yellow cautionary spar buoy, marked TMN With this notification, a (P) portion of Notice 07-SEP-2001 is cancelled. See reference DFO 6601639-01 appearing in this edition.	LNМ/D. 06-FEB-2004 44°44'35.5"N 080°38'47.8"W <i>DFO(6602080-12)</i>



Chart no. 2282

19-NOV-2004

Add yellow cautionary spar buoy, marked TMO
With this notification, a (P) portion of Notice 07-SEP-2001 is
cancelled. See reference DFO 6601640-01 appearing in this
edition.

LNM/D. 06-FEB-2004
44°44'29.8"N 080°37'59.5"W
DFO(6602080-13)

06-FEB-2004

Replace green port hand pillar light buoy FIG, marked T9
with green port hand spar light buoy FIG, marked
T9

LNM/D. 28-FEB-2003
44°37'01.4"N 080°55'07.4"W
(D2003134) LL(834) DFO(6601073-01)

03-JAN-2003

Add yellow cautionary spar buoy, marked TMAA
44°43'01.5"N 080°46'11.7"W
(D2002027) DFO(6600587-01)

LNM/D. 21-DEC-2001

21-DEC-2001

Reposition green port hand pillar light buoy FIG, marked T5

LNM/D. 14-DEC-2001
from 45°03'28.0"N 081°01'40.0"W
to 45°03'31.1"N 081°01'44.5"W

(D2001150) LL(827) DFO(6600018-01)

14-DEC-2001

Add yellow ODAS/SADO light buoy, Fl (5) Y, marked
45143

LNM/D. 07-SEP-2001
44°56'42.0"N 080°37'36.0"W
(D2001139) LL(832.5) DFO(6600006-01)

07-SEP-2001

(P)Add yellow cautionary spar buoy, marked "TMA"

LNM/D. 01-JUN-2001
44°43'16.7"N 080°46'13.4"W

This portion of Notice 07-SEP-2001 is cancelled by a new
permanent notice. See reference DFO 6602080-01
appearing in this edition.
Cancelled on 26-NOV-04

(D2001-056) DFO(6601627-01)

07-SEP-2001

LNM/D. 01-JUN-2001



Chart no. 2282

(P)Add yellow cautionary spar buoy, marked "TMC"

44°44'12.8"N 080°46'18.8"W

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-02 appearing in this edition.
Cancelled on 26-NOV-04

(D2001-058) DFO(6601628-01)

07-SEP-2001

LNМ/D. 01-JUN-2001

(P)Add yellow cautionary spar buoy, marked "TME"

44°44'40.2"N 080°45'36.4"W

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-03 appearing in this edition.
Cancelled on 26-NOV-04

(D2001-060) DFO(6601629-01)

07-SEP-2001

LNМ/D. 01-JUN-2001

(P)Add yellow cautionary spar buoy, marked "TMF"

44°44'40.2"N 080°44'50.3"W

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-04 appearing in this edition.
Cancelled on 26-NOV-04

(D2001-061) DFO(6601630-01)

07-SEP-2001

LNМ/D. 01-JUN-2001

(P)Add yellow cautionary spar buoy, marked "TMG"

44°44'40.2"N 080°44'04.9"W

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-05 appearing in this edition.
Cancelled on 26-NOV-04

(D2001-062) DFO(6601631-01)

07-SEP-2001

LNМ/D. 01-JUN-2001

(P)Add yellow cautionary spar buoy, marked "TMB"

44°43'39.1"N 080°46'15.5"W

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080 appearing in this edition.
Cancelled on 26-NOV-04

(D2001-057) DFO(6601633-01)

07-SEP-2001

LNМ/D. 01-JUN-2001



Chart no. 2282

(P)Add yellow cautionary spar buoy, marked "TMH"

44°44'40.2"N 080°43'22.4"W

(D2001-063) DFO(6601634-01)

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-07 appearing in this edition.
Cancelled on 26-NOV-04

07-SEP-2001

LN/D. 01-JUN-2001

(P)Add yellow cautionary spar buoy, marked "TMI"

44°44'39.8"N 080°42'34.9"W

(D2001-064) DFO(6601635-01)

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-08 appearing in this edition.
Cancelled on 26-NOV-04

07-SEP-2001

LN/D. 01-JUN-2001

(P)Add yellow cautionary spar buoy, marked "TMJ"

44°44'40.2"N 080°41'49.6"W

(D2001-065) DFO(6601636-01)

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080 appearing in this edition.
Cancelled on 26-NOV-04

07-SEP-2001

LN/D. 01-JUN-2001

(P)Add yellow cautionary spar buoy, marked "TML"

44°44'40.2"N 080°40'18.1"W

(D2001-067) DFO(6601637-01)

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-10 appearing in this edition.
Cancelled on 26-NOV-04

07-SEP-2001

LN/D. 01-JUN-2001

(P)Add yellow cautionary spar buoy, marked "TMM"

44°44'40.2"N 080°39'31.7"W

(D2001-068) DFO(6601638-01)

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-11 appearing in this edition.
Cancelled on 26-NOV-04



Chart no. 2282

07-SEP-2001

(P)Add yellow cautionary spar buoy, marked "TMN"

LNМ/D. 01-JUN-2001

44°44'35.5"N 080°38'47.8"W

(D2001-069) DFO(6601639-01)

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-12 appearing in this edition.
Cancelled on 26-NOV-04

07-SEP-2001

(P)Add yellow cautionary spar buoy, marked "TMO"

LNМ/D. 01-JUN-2001

44°44'29.8"N 080°37'59.5"W

(D2001-070) DFO(6601640-01)

This portion of Notice 07-SEP-2001 is cancelled by a new permanent notice. See reference DFO 6602080-13 appearing in this edition.
Cancelled on 26-NOV-04

07-SEP-2001

Add yellow cautionary spar light buoy, Fl Y, marked "TMD"

LNМ/D. 01-JUN-2001

44°44'40.2"N 080°46'21.4"W

(D2001-085) LL(839.3) DFO(6601648-01)

07-SEP-2001

Add yellow cautionary spar light buoy, Fl Y, marked "TMK"

LNМ/D. 01-JUN-2001

44°44'40.2"N 080°41'03.8"W

(D2001-086) LL(839.4) DFO(6601649-01)

01-JUN-2001

Amend Iso G to read Iso G (Priv) against light

LNМ/D. 06-APR-2001

44°47'37.0"N 080°56'51.5"W

(D2001042) LL(831) DFO(6601496-01)

06-APR-2001

Amend FR to read FR (Priv) against light

LNМ/D. 27-OCT-2000

44°46'47.0"N 081°07'22.2"W

(CCG-D01-024) LL(829) DFO(6601435-01)

27-OCT-2000

LNМ/D. 14-JUL-2000



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2282

Add See Inset Chart 2283/Voir cartouche carte 2283 44°44'44.0"N 081°07'42.0"W

DFO(6500373-01)

27-OCT-2000

LNМ/D. 14-JUL-2000

Add See Inset Chart 2283/Voir cartouche carte 2283 44°36'42.0"N 080°55'50.0"W

DFO(6500373-02)

14-JUL-2000

LNМ/D. 12-NOV-1999

Delete legend "Chart/Carte 2213" 44°36'42.0"N 080°55'50.0"W

DFO(6601157-10)

14-JUL-2000

LNМ/D. 12-NOV-1999

Delete legend "Chart/Carte 2212" 44°45'12.0"N 081°07'30.0"W

DFO(6601157-11)

14-JUL-2000

LNМ/D. 12-NOV-1999

Add legend "Chart/Carte 2283" 45°12'00.0"N 080°45'30.0"W

DFO(6601157-12)

14-JUL-2000

LNМ/D. 12-NOV-1999

Amend legend "Adjoining Chart/Carte 2201" to read "Adjoining Chart/Carte 2283" in the east corner

DFO(6601157-14)

2282 - Wingfield Basin - New Edition - 07-JUN-1996 - NAD 1983

28-AUG-2020

LNМ/D. 14-FEB-2014

Amend Fl 10s 24m 9M to read Fl 10s 25m 10M against light
(See Chart No. 1, P16)

45°14'42.8"N 081°17'31.1"W

This notice affects Electronic Navigational Chart: (D2020010) LL(826) DFO(6604651-01)
CA273097, CA373281

28-JAN-2005

LNМ/D. 19-NOV-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2282

Amend legend Fl 15s 24m 14M to read Fl 10s 24m 9M
against light

45°14'42.8"N 081°17'31.1"W

(D2004067) LL(826) DFO(6602139-01)

This notice affects Electronic Navigational Chart:
CA273097, CA373281