



Chart no. 2293

2293 - Continuation A - New Edition - 30-MAR-2001 - NAD 1983

05-JUL-2002 LNM/D. 21-DEC-2001

Delete beacon, Priv 45°46'00.2"N 080°34'27.2"W

DFO(6600195-01)

05-JUL-2002 LNM/D. 21-DEC-2001

Delete beacon, Priv 45°46'00.2"N 080°34'30.0"W

DFO(6600195-02)

14-DEC-2001

Add radio tower R Lts with elevation of 160 feet 45°45'54.4"N 080°33'56.3"W

DFO(6601751-01)

2293 - Byng Inlet and Approaches / et les approches - New Edition - 30-MAR-2001 - NAD 1983

21-DEC-2001

Replace red, starboard hand conical buoy, marked H6 with red,
starboard hand spar buoy, marked H6

LNM/D. 14-DEC-2001

45°44'20.0"N 080°42'26.0"W

(D2001147) DFO(6600010-01)

31-OCT-2003

Amend Fl 5sec 52ft 16M to read Oc 10sec 52ft against light

LNM/D. 05-JUL-2002

45°44'40.0"N 080°39'32.7"W

(D2003114) LL(954) DFO(6601015-01)

31-OCT-2003

Add rock with known depth of 2 feet 45°45'46.1"N 080°37'56.7"W

LNM/D. 05-JUL-2002

DFO(6601038-01)

09-JAN-2004

LNM/D. 31-OCT-2003



Chart no. 2293

Reposition red, starboard hand spar buoy, marked H6 from 45°44'20.0"N 080°42'26.0"W
to 45°44'20.5"N 080°42'28.0"W

(D2003138) DFO(6601077-01)

09-JAN-2004

LNM/D. 31-OCT-2003

Amend Fl G to read QG against buoy H13

45°44'39.1"N 080°40'43.7"W

(D2003141) LL(955) DFO(6601081-01)

20-FEB-2004

LNM/D. 09-JAN-2004

(T)Add red, starboard hand spar buoy, marked H26/2

45°45'46.3"N 080°37'57.4"W

(D2003169T) DFO(6601297-01)

Notice 20-FEB-2004(T) is cancelled. See reference
DFO(6602835) appearing in this edition.
Cancelled on 01-DEC-06

03-SEP-2004

LNM/D. 20-FEB-2004

Replace red starboard hand pillar light buoy Fl R, marked
HH2, with red starboard hand spar light buoy Fl R,
marked HH2

45°43'58.2"N 080°44'39.9"W

(D2004040) LL(953) DFO(6601939-01)

This notice affects Electronic Navigational Chart:
CA273097

03-SEP-2004

LNM/D. 20-FEB-2004

Replace green port hand pillar light buoy QG, marked
H13, with green port hand spar light buoy QG,
marked H13

45°44'39.1"N 080°40'42.8"W

(D2004041) LL(955.000) DFO(6601939-02)

03-SEP-2004

LNM/D. 20-FEB-2004

Replace red starboard hand pillar light buoy Fl R,
marked H12, with red starboard hand spar
light buoy Fl R, marked H12

45°44'33.8"N 080°40'52.1"W

(D2004042) LL(955.200) DFO(6601939-03)

03-SEP-2004

LNM/D. 20-FEB-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2293

Replace green port hand pillar light buoy QG, marked
H19, with green port hand spar light buoy QG,
marked H19 45°45'00.1"N 080°39'27.1"W
(D2004043) LL(956.000) DFO(6601939-04)

03-SEP-2004

Replace green port hand pillar light buoy Fl G, marked
H21, with green port hand spar light buoy Fl
G, marked H21 LNM/D. 20-FEB-2004
45°45'14.0"N 080°38'59.5"W
(D2004044) LL(958.400) DFO(6601939-05)

15-JUL-2005

Amend legend FG 54ft to read 2 FG (vert) against light LNM/D. 03-SEP-2004
45°45'55.7"N 080°37'43.9"W
LL(960) DFO(6602372-01)

15-JUL-2005

Amend legend FG 35ft to read FG against light LNM/D. 03-SEP-2004
45°45'52.2"N 080°37'50.2"W
LL(959) DFO(6602372-02)

01-DEC-2006

Add red starboard hand spar buoy, marked H26/2 LNM/D. 15-JUL-2005
45°45'46.3"N 080°37'57.4"W
With this notification, Notice 20-Feb-2004 (T) is cancelled. See
reference DFO(6601297-01) appearing in this edition. *(D2006083) DFO(6602835-01)*

This notice affects Electronic Navigational Chart: CA573231

02-MAY-2008

Amend legend F R 64ft to read F R 57ft against light LNM/D. 01-DEC-2006
45°45'11.4"N 080°38'20.3"W
(D2008018) LL(958) DFO(6603193-01)

This notice affects Electronic Navigational Chart:
CA373052, CA573231

29-AUG-2008

Amend legend FR 26ft to read FR 27ft against light LNM/D. 02-MAY-2008
45°46'03.5"N 080°36'58.5"W
DFO(6603237-01)

This notice affects Electronic Navigational Chart: CA573231



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2293

29-AUG-2008

Amend legend FR 35ft to read FR 43ft against light

LNМ/D. 02-MAY-2008

45°46'04.5"N 080°36'53.0"W

DFO(6603237-02)

This notice affects Electronic Navigational Chart: CA573231

21-AUG-2009

Amend legend F R 43ft to read F R 42ft against light

LNМ/D. 29-AUG-2008

45°46'04.3"N 080°36'53.0"W

LL(962) DFO(6603426-01)

This notice affects Electronic Navigational Chart: CA573231

21-AUG-2009

Amend legend F R 27ft to read F R 26ft against light

LNМ/D. 29-AUG-2008

45°46'03.2"N 080°36'58.8"W

LL(961) DFO(6603426-02)

This notice affects Electronic Navigational Chart: CA573231

05-MAR-2010

Add Rescue Station
(See Chart No. 1, T12)

LNМ/D. 21-AUG-2009

45°44'41.6"N 080°39'33.4"W

DFO(6603571-01)

This notice affects Electronic Navigational Chart: CA573231

07-JUN-2013

Add sounding of 5 feet, Rep (2012)
(See Chart No. 1, I10 & I3.2)

LNМ/D. 05-MAR-2010

45°46'00.5"N 080°38'54.6"W

DFO(6603870-01)

This notice affects Electronic Navigational Chart: CA573231