



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2301

2301 - Passage Island to/à Thunder Bay - New Edition - 22-FEB-1991 - US Standard Datum

09-FEB-2024

LNM/D. 22-DEC-2023

Amend Fl to read Fl (priv) against light
(See Chart 1, P65)

48°26'09.5"N 088°28'49.7"W

This notice affects Electronic Navigational Chart: (D2023038) LL(1127) DFO(6605208-01)
CA373070

22-DEC-2023

LNM/D. 17-NOV-2023

Add depth of 3¾ fathoms
(See Chart 1, I10)

48°09'54.5"N 089°13'40.4"W

This notice affects Electronic Navigational Chart: CA373486 DFO(6605175-01)

22-DEC-2023

LNM/D. 17-NOV-2023

Add depth of 4¾ fathoms
(See Chart 1, I10)

48°12'31.9"N 089°10'59.3"W

This notice affects Electronic Navigational Chart: CA373486 DFO(6605175-02)

22-DEC-2023

LNM/D. 17-NOV-2023

Delete sounding of 5 fathoms Rep (2013)
(See Chart 1, I10)

48°11'23.8"N 089°07'11.7"W

This notice affects Electronic Navigational Chart: CA373486 DFO(6605175-03)

22-DEC-2023

LNM/D. 17-NOV-2023

Add depth of 4¾ fathoms
(See Chart 1, I10)

48°11'23.3"N 089°06'50.4"W

This notice affects Electronic Navigational Chart: CA373486 DFO(6605175-04)

22-DEC-2023

LNM/D. 17-NOV-2023

Delete depth of 8 fathoms
(See Chart 1, I10)

48°12'44.1"N 089°12'26.2"W

This notice affects Electronic Navigational Chart: CA373486 DFO(6605175-05)

22-DEC-2023

LNM/D. 17-NOV-2023

Add depth of 6 fathoms
(See Chart 1, I10)

48°12'42.0"N 089°12'25.5"W

This notice affects Electronic Navigational Chart: CA373486 DFO(6605175-06)



Chart no. 2301

22-DEC-2023

LNM/D. 17-NOV-2023

Delete depth of 2 fathoms
(See Chart 1, I10)

48°08'01.8"N 089°14'41.5"W

This notice affects Electronic Navigational Chart: CA373486

DFO(6605175-07)

22-DEC-2023

LNM/D. 17-NOV-2023

Add depth of 1¾ fathoms
(See Chart 1, I10)

48°08'04.2"N 089°14'39.5"W

This notice affects Electronic Navigational Chart: CA373486

DFO(6605175-08)

22-DEC-2023

LNM/D. 17-NOV-2023

Delete depth of 5 fathoms
(See Chart 1, I10)

48°08'00.8"N 089°14'56.2"W

This notice affects Electronic Navigational Chart: CA373486

DFO(6605175-09)

22-DEC-2023

LNM/D. 17-NOV-2023

Add depth of 4½ fathoms
(See Chart 1, I10)

48°08'02.6"N 089°14'53.4"W

This notice affects Electronic Navigational Chart: CA373486

DFO(6605175-10)

17-NOV-2023

LNM/D. 25-AUG-2023

Delete depth of 1¾ fathoms 48°31'35.3"N 088°55'12.0"W
(See Chart 1, I10)

DFO(6605165-01)

17-NOV-2023

LNM/D. 25-AUG-2023

Add depth of ½ fathoms 48°31'37.7"N 088°55'12.6"W
(See Chart 1, I10)

DFO(6605165-02)

25-AUG-2023

LNM/D. 11-AUG-2023

Delete depth of 22 fathoms
(See Chart 1, I10)

48°10'55.1"N 089°12'03.8"W

This notice affects Electronic Navigational Chart: CA373486

DFO(6605124-01)

25-AUG-2023

LNM/D. 11-AUG-2023



Chart no. 2301

- Add depth of 7¼ fathoms 48°10'51.0"N 089°12'02.8"W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373486 *DFO(6605124-02)*
- 11-AUG-2023** LNM/D. 25-DEC-2020
Delete chimney with elevation of 650 feet, Q 48°21'31.5"N 089°13'16.1"W
(See Chart 1, E22)
This notice affects Electronic Navigational Chart: CA573253 *DFO(6605114-01)*
- 25-DEC-2020** LNM/D. 15-MAY-2020
Delete red starboard hand conical buoy 48°11'10.7"N 088°27'20.1"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA373070 *DFO(6604691-01)*
- 15-MAY-2020** LNM/D. 14-APR-2017
Add obstruction with known depth of 3 fathoms 48°20'52.7"N 088°36'35.9"W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA373070 *DFO(6604617-01)*
- 14-APR-2017** LNM/D. 28-JUN-2013
Delete depth of 4 1/2 fathoms 48°21'31.5"N 089°07'38.4"W
(See Chart No. 1, I10)
DFO(6604287-07)
- 14-APR-2017** LNM/D. 28-JUN-2013
Add depth of 2¾ fathoms 48°21'33.9"N 089°07'37.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA373070, *DFO(6604287-10)*
CA573253
- 14-APR-2017** LNM/D. 28-JUN-2013
Add depth of 2¾ fathoms 48°20'45.4"N 089°11'37.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA373070, *DFO(6604287-12)*
CA573253
- 28-JUN-2013** LNM/D. 24-MAR-2006



Chart no. 2301

Add rock with known depth of 5 Fathoms Rep (2013), dangerous to surface navigation
(See Chart No. 1, K14.2 & I3.2)
This notice affects Electronic Navigational Chart: CA373070

48°11'24.6"N 089°06'57.0"W
DFO(6603883-03)

24-MAR-2006

Amend legend Fl 5s 138ft 16M to read Fl 10s 141ft against light

LNМ/D. 17-JUN-2005
48°22'10.8"N 089°07'13.4"W
(D2005102) LL(1133) DFO(6602613-01)

This notice affects Electronic Navigational Chart:
CA173289, CA573253

17-JUN-2005

Replace black, red and black isolated danger conical buoy, marked D with black, red and black isolated danger can buoy, marked D

LNМ/D. 18-MAR-2005
48°11'13.0"N 088°24'18.0"W
LL(16825) DFO(6602363-01)

17-JUN-2005

Replace black, red and black isolated danger pillar buoy, marked D with black, red and black isolated danger can buoy, marked D

LNМ/D. 18-MAR-2005
48°11'13.0"N 088°24'18.0"W
LL(16825) DFO(6602363-02)

18-MAR-2005

Amend legend Fl 10s 82ft 15M to read Fl 10s 82ft 9M against light

LNМ/D. 28-JAN-2005
48°20'24.0"N 088°38'54.0"W
(D2004158) LL(1128) DFO(6602267-01)

This notice affects Electronic Navigational Chart:
CA173289

28-JAN-2005

Amend light Fl 5s 114ft 16M to read Fl 5s 114ft 9M

LNМ/D. 24-DEC-2004
48°17'33.0"N 088°52'26.0"W
(D2004-029) LL(1129) DFO(6602137-02)

This notice affects Electronic Navigational Chart:
CA173289

24-DEC-2004

LNМ/D. 16-JAN-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2301

Amend legend Fl 20s 81ft 16M to read Fl 10s 81ft 9M
against light

48°14'07.0"N 089°00'27.0"W

(D2004022) LL(1130) DFO(6602132-01)

This notice affects Electronic Navigational Chart:
CA173289

16-JAN-2004

LNМ/D. 24-JAN-2003

Replace red starboard hand spar buoy marked A2 with red
starboard hand spar light buoy, Fl R, marked A2

48°17'54.8"N 088°59'11.4"W

(D2003142) LL(1132) DFO(6601082-01)

24-JAN-2003

LNМ/D. 25-MAY-2001

Delete red, green, red, starboard bifurcation spar buoy, marked T

48°31'37.0"N 088°52'49.0"W

(D2002029) DFO(6600589-01)

24-JAN-2003

LNМ/D. 25-MAY-2001

Add black, red, black, isolated danger spar buoy, marked T

48°31'37.0"N 088°52'49.0"W

(D2002-029) DFO(6600589-02)

24-JAN-2003

LNМ/D. 25-MAY-2001

Delete red, green, red, starboard bifurcation conical buoy

48°11'13.0"N 088°24'18.0"W

DFO(6600616-01)

24-JAN-2003

LNМ/D. 25-MAY-2001

Add black, red, black, isolated danger conical buoy, marked D
This buoy is not fitted with topmarks.

48°11'13.0"N 088°24'18.0"W

DFO(6600616-02)

25-MAY-2001

LNМ/D. 14-JUL-2000

Affix patch

48°07'00.0"N 088°42'00.0"W

DFO(6500416-01)

[PDF](#)

14-JUL-2000

LNМ/D. 17-DEC-1999



Chart no. 2301

Delete red, starboard hand, spar buoy

48°06'50.0"N 088°41'10.0"W

(NGA:NM 4/00 FOR CHART 14976) DFO(6601152-01)

14-JUL-2000

LNМ/D. 17-DEC-1999

Add red, starboard hand, conical buoy

48°06'50.0"N 088°41'10.0"W

(NGA:NM 4/00 FOR CHART 14976) DFO(6601152-02)

14-JUL-2000

LNМ/D. 17-DEC-1999

Delete green, port hand, spar buoy

48°06'55.0"N 088°41'04.0"W

LL(VOL. 7, 16810) DFO(6601152-03)

14-JUL-2000

LNМ/D. 17-DEC-1999

Add green, port hand, can buoy

48°06'55.0"N 088°41'04.0"W

LL(VOL. 7, 16810) DFO(6601152-04)