



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3053

3053 - Chase to/à Anglemont - Sheet/Feuille 1 - New Chart - 11-APR-1986 - NAD 1927

05-JUL-2024

LNM/D. 03-NOV-2023

Delete starboard hand daybeacon 50°49'38.5"N 119°41'52.9"W
(See Chart 1, Qp)

DFO(6204968-01)

29-NOV-2019

LNM/D. 17-NOV-2017

Reposition green port hand spar buoy from 50°49'47.3"N 119°41'42.0"W
(See Chart No. 1, Qg) to 50°49'42.4"N 119°41'45.7"W

(P2019106) DFO(6204157-01)

29-NOV-2019

LNM/D. 17-NOV-2017

Reposition green port hand spar buoy from 50°49'52.2"N 119°41'33.2"W
(See Chart No. 1, Qg) to 50°49'54.0"N 119°41'26.7"W

DFO(6204157-02)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete marina 50°57'24.0"N 119°06'05.0"W
(See Chart No. 1, U1.1)

DFO(6202180-04)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete marina 50°54'46.0"N 119°25'50.0"W
(See Chart No. 1, U1.1)

DFO(6202180-06)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete marina 50°53'11.0"N 119°23'12.0"W
(See Chart No. 1, U1.1)

DFO(6202180-07)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete marina 50°54'13.0"N 119°22'23.0"W
(See Chart No. 1, U1.1)

DFO(6202180-08)



Chart no. 3053

05-FEB-2010

LNM/D. 04-DEC-2009

Delete marina 50°55'31.0"N 119°18'48.0"W
(See Chart No. 1, U1.1)

DFO(6202180-09)

05-JUN-2009

LNM/D. 26-OCT-2007

Add submarine cable between 50°55'08.3"N 119°20'43.8"W
(See Chart No. 1, L30.1) and 50°56'28.3"N 119°20'48.8"W

DFO(6202060-01)

26-OCT-2007

LNM/D. 04-MAR-2005

Amend E15 to read E37 against buoy 50°51'52.5"N 119°36'16.8"W

LL(5683) DFO(6201761-02)

04-MAR-2005

LNM/D. 19-JAN-2001

Add submarine cable area joining 50°52'51.9"N 119°28'14.0"W
50°53'00.0"N 119°28'22.5"W
50°53'52.1"N 119°27'58.0"W
and 50°53'56.8"N 119°27'43.0"W

DFO(6201216-01)

04-MAR-2005

LNM/D. 19-JAN-2001

Add submarine cable area joining 50°52'52.0"N 119°28'12.0"W
50°52'54.5"N 119°28'06.0"W
50°53'52.1"N 119°27'38.0"W
and 50°53'56.8"N 119°27'43.0"W

DFO(6201216-02)

3053 - Little River - Sheet/Feuille 1 - New Chart - 11-APR-1986 - NAD 1927

26-OCT-2007

LNM/D. 04-MAR-2005

Amend E15 to read E37 against buoy 50°51'52.5"N 119°36'16.8"W

LL(5683) DFO(6201761-02)



Chart no. 3053

3053 - Cinnemousun Narrows - Sheet/Feuille 2 - New Chart - 11-APR-1986 - NAD 1927

05-FEB-2010

LNM/D. 04-DEC-2009

Delete orange and white mooring spherical buoy 51°00'03.2"N 119°00'23.1"W
(See Chart No.1, Q40)

DFO(6202181-01)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete orange and white mooring spherical buoy 50°59'47.4"N 119°00'33.9"W
(See Chart No.1, Q40)

DFO(6202181-02)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete orange and white mooring spherical buoy 50°59'48.5"N 119°00'35.9"W
(See Chart No.1, Q40)

DFO(6202181-03)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete orange and white mooring spherical buoy 50°59'54.8"N 119°00'44.1"W
(See Chart No.1, Q40)

DFO(6202181-04)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete orange and white mooring spherical buoy 50°59'56.4"N 119°00'47.9"W
(See Chart No.1, Q40)

DFO(6202181-05)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete orange and white mooring spherical buoy 50°59'59.1"N 119°00'51.8"W
(See Chart No.1, Q40)

DFO(6202181-06)

19-JAN-2001

LNM/D. 08-NOV-1996



Chart no. 3053

(P)Add 3 barges

50°59'44.3"N 119°00'15.5"W

A store doing business on these barges is located on the South side of the Eastern approach to Cinnemousun Narrows, from June until September. This information will be incorporated in the next New Edition.

DFO(6200974-01)

with this notification, preliminary action dated 19-JAN-2001 is cancelled.

Cancelled on 07-DEC-12

3053 - Salmon Arm to/à Seymour Arm - Sheet/Feuille 2 - New Chart - 11-APR-1986 - NAD 1927

05-FEB-2010

LNM/D. 04-DEC-2009

Delete marina 50°51'15.0"N 119°04'46.0"W
(See Chart No. 1, U1.1)

DFO(6202180-02)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete marina 50°43'16.0"N 119°01'53.0"W
(See Chart No. 1, U1.1)

DFO(6202180-03)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete marina 50°57'24.0"N 119°06'05.0"W
(See Chart No. 1, U1.1)

DFO(6202180-04)

05-FEB-2010

LNM/D. 04-DEC-2009

Add marina 51°14'19.0"N 118°56'05.0"W
(See Chart No. 1, U1.1)

DFO(6202180-05)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete orange and white mooring spherical buoy 51°04'38.9"N 118°53'50.0"W
(See Chart No.1, Q40)

DFO(6202181-07)

05-FEB-2010

LNM/D. 04-DEC-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3053

Delete orange and white mooring spherical buoy 51°04'53.9"N 118°53'47.5"W
(See Chart No.1, Q40)

DFO(6202181-08)

05-FEB-2010

LNM/D. 04-DEC-2009

Delete orange and white mooring spherical buoy 51°05'04.5"N 118°53'45.0"W
(See Chart No.1, Q40)

DFO(6202181-09)

26-OCT-2007

LNM/D. 04-MAR-2005

Reposition red starboard hand spar buoy, marked E22 from 50°48'57.5"N 118°59'17.0"W
(See Chart No. 1 Qf) to 50°48'54.1"N 118°59'15.6"W

LL(5694) DFO(6201761-03)

3053 - Continuation A - Sheet/Feuille 2 - New Chart - 11-APR-1986 - NAD 1927

03-NOV-2023

LNM/D. 29-NOV-2019

Delete starboard hand daybeacon 50°46'38.5"N 119°19'18.0"W
(See Chart 1, Qp)

(P2023046) DFO(6204765-01)

17-NOV-2017

LNM/D. 02-JUL-2010

Reposition green port hand pillar buoy, marked E25 from 50°43'16.3"N 119°17'38.8"W
(See Chart No. 1, Qg) to 50°43'10.8"N 119°17'32.8"W

(P2017054) DFO(6203568-01)

17-NOV-2017

LNM/D. 02-JUL-2010

Reposition red starboard hand lighted spar buoy Fl R,
marked E26
(See Chart No. 1, Qf)

from 50°43'15.0"N 119°17'43.2"W
to 50°43'08.9"N 119°17'37.9"W

(P2017058) LL(43.5) DFO(6203569-01)

02-JUL-2010

LNM/D. 05-FEB-2010

Affix patch 50°42'42.0"N 119°17'54.0"W

DFO(6202271-01)

[PDF](#)



Chart no. 3053

05-FEB-2010

LNМ/D. 04-DEC-2009

Delete marina 50°43'49.0"N 119°18'31.0"W
(See Chart No. 1, U1.1)

DFO(6202180-01)

04-DEC-2009

LNМ/D. 05-JUN-2009

Delete starboard hand daybeacon 50°42'26.0"N 119°17'02.0"W
(See Chart No. 1, Qt)

(P2009110) DFO(6202164-01)

05-JUN-2009

LNМ/D. 26-OCT-2007

Delete green port hand can buoy, marked E1 50°44'06.0"N 119°17'26.0"W
(See Chart No. 1, Qg)

DFO(6202061-01)

05-JUN-2009

LNМ/D. 26-OCT-2007

Add light Iso Y 2s 6m 50°42'26.0"N 119°16'53.0"W
(See Chart No. 1, P20.2)

DFO(6202062-01)

05-JUN-2009

LNМ/D. 26-OCT-2007

Add light Iso Y 1½s 3m 50°42'33.0"N 119°16'58.0"W
(See Chart No. 1, P20.2)

DFO(6202062-02)

05-JUN-2009

LNМ/D. 26-OCT-2007

Add leading line between 50°42'26.0"N 119°16'53.0"W
(See Chart No. 1, P20.2) and 50°43'46.0"N 119°18'01.0"W

DFO(6202062-03)

05-JUN-2009

LNМ/D. 26-OCT-2007

Add legend 151° 50°43'33.0"N 119°17'54.0"W
(See Chart No. 1, P20.2)

DFO(6202062-04)

05-JUN-2009

LNМ/D. 26-OCT-2007



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3053

Reposition green port hand pillar buoy, marked E25 from 50°43'16.5"N 119°17'38.8"W
(See Chart No. 1, Qg) to 50°43'16.5"N 119°17'32.0"W

DFO(6202062-05)

05-JUN-2009

LNM/D. 26-OCT-2007

Add port hand daybeacon 50°42'40.0"N 119°17'06.0"W
(See Chart No. 1, Qt)

DFO(6202062-06)

26-OCT-2007

LNM/D. 04-MAR-2005

Add green port hand pillar buoy, marked E25
(See Chart No. 1 Qg)

50°43'16.5"N 119°17'38.8"W

(P2007086) LL(5687) DFO(6201761-01)