



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3440

3440 - Race Rocks to/à D'Arcy Island - New Edition - 01-JUL-2005 - NAD 1983

03-NOV-2023

LNМ/D. 23-JUN-2023

Delete obstruction with known depth of 55 metres
(See Chart 1, K41)

48°24'04.2"N 123°24'32.3"W

This notice affects Electronic Navigational Chart: CA470075,
CA570562

DFO(6204813-01)

23-JUN-2023

LNМ/D. 16-JUN-2023

Delete harbour limit and legend ESQUIMALT
(See Chart 1, N49)

between 48°25'22.5"N 123°25'09.0"W

and 48°25'22.5"N 123°27'58.0"W

This notice affects Electronic Navigational Chart:
CA470075, CA570138

DFO(6204773-05)

23-JUN-2023

LNМ/D. 16-JUN-2023

Add harbour limit between 48°25'18.1"N 123°25'11.7"W
(See Chart 1, N49) and 48°23'10.2"N 123°25'11.7"W

DFO(6204773-06)

23-JUN-2023

LNМ/D. 16-JUN-2023

Add harbour limit and legend ESQUIMALT
(See Chart 1, N49)

between 48°23'10.2"N 123°25'11.7"W

and 48°22'58.0"N 123°28'59.0"W

This notice affects Electronic Navigational Chart:
CA470075

DFO(6204773-07)

23-JUN-2023

LNМ/D. 16-JUN-2023

Delete harbour limit
(See Chart 1, N49)

between 48°23'40.0"N 123°18'18.5"W

and 48°23'03.0"N 123°28'47.5"W

This notice affects Electronic Navigational Chart:
CA470075

DFO(6204773-08)

23-JUN-2023

LNМ/D. 16-JUN-2023

Delete VICTORIA

48°23'34.5"N 123°20'19.8"W

This notice affects Electronic Navigational Chart: CA470075

DFO(6204773-09)

23-JUN-2023

LNМ/D. 16-JUN-2023



Chart no. 3440

- Delete VICTORIA 48°23'15.9"N 123°25'41.5"W
This notice affects Electronic Navigational Chart: CA470075 *DFO(6204773-10)*
- 16-JUN-2023** LNM/D. 14-APR-2023
Delete submarine cable joining 48°24'53.9"N 123°23'02.0"W
(See Chart 1, L30.1) 48°24'46.4"N 123°23'06.3"W
This notice affects Electronic Navigational Chart: 48°24'38.8"N 123°23'02.2"W
CA470075, CA570562 and 48°24'23.4"N 123°23'16.3"W
DFO(6204772-01)
- 16-JUN-2023** LNM/D. 14-APR-2023
Delete cable sign 48°24'54.8"N 123°23'02.3"W
(See Chart 1, Q123)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6204772-02)*
- 14-APR-2023** LNM/D. 28-OCT-2022
Add lighted offshore ODAS/SADO platform Fl(5) Y(Priv) 48°23'38.1"N 123°18'30.7"W
(See Chart 1, P2)
This notice affects Electronic Navigational Chart: CA470075, *DFO(6204733-01)*
CA570214
- 28-OCT-2022** LNM/D. 22-APR-2022
Delete depth of 3 metres 48°33'34.6"N 123°16'29.3"W
(See Chart 1, I10) *DFO(6204656-18)*
- 28-OCT-2022** LNM/D. 22-APR-2022
Add depth of 1.0 metre 48°33'35.1"N 123°16'28.0"W
(See Chart 1, I10) *DFO(6204656-19)*
- 28-OCT-2022** LNM/D. 22-APR-2022
Add rock which covers and uncovers with drying height of 0.6 metre 48°33'36.8"N 123°16'34.8"W
(See Chart 1, K11) *DFO(6204656-20)*
- 28-OCT-2022** LNM/D. 22-APR-2022



Chart no. 3440

Add rock which covers and uncovers with drying height of 0.1 metre 48°33'50.7"N 123°15'51.4"W
(See Chart 1, K11)

DFO(6204656-21)

28-OCT-2022

LNМ/D. 22-APR-2022

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 228 metres (See Chart 1, L25)

48°29'45.1"N 123°11'30.3"W

DFO(6204660-05)

22-APR-2022

LNМ/D. 16-APR-2021

Delete ANCHORAGE PROHIBITED MOUILLANGE INTERDIT
This notice affects Electronic Navigational Chart: CA470075

48°23'54.5"N 123°23'17.6"W

DFO(6204592-03)

22-APR-2022

LNМ/D. 16-APR-2021

Delete anchoring prohibited area
(See Chart No. 1, N20)

between 48°23'03.0"N 123°28'47.0"W
and 48°23'40.0"N 123°18'17.0"W

This notice affects Electronic Navigational Chart:
CA470075

DFO(6204592-04)

16-APR-2021

LNМ/D. 18-SEP-2020

Add foul ground (See Chart No. 1, K31)
This notice affects Electronic Navigational Chart: CA470075,
CA570138

48°26'41.5"N 123°26'23.7"W

DFO(6204435-01)

16-APR-2021

LNМ/D. 18-SEP-2020

Add foul ground (See Chart No. 1, K31)
This notice affects Electronic Navigational Chart: CA470075,
CA570138

48°26'58.1"N 123°26'51.0"W

DFO(6204435-02)

18-SEP-2020

LNМ/D. 27-MAR-2020

Add outfall pipe (See Chart No. 1, L41.1)
This notice affects Electronic Navigational Chart:
CA470075, CA570562

joining 48°25'09.7"N 123°23'50.0"W
48°25'06.4"N 123°23'49.7"W
and 48°24'14.7"N 123°24'26.1"W

DFO(6204366-01)

27-MAR-2020

LNМ/D. 16-AUG-2019



Chart no. 3440

Reposition yellow ODAS/SADO lighted super-buoy Fl(4)
Y 20s, marked 46088
(See Chart No. 1, Q58)

from 48°19'53.0"N 123°10'22.0"W
to 48°19'56.3"N 123°10'44.1"W

(USCG:District 13 50/19) DFO(6204260-01)

16-AUG-2019

LNM/D. 21-DEC-2018

Amend F Y 11m to read F G 11m against light
(See Chart No. 1, P20.2)

48°26'33.7"N 123°26'19.1"W

This notice affects Electronic Navigational Chart:
CA470075, CA570138

(P2019070) LL(200) DFO(6204071-01)

16-AUG-2019

LNM/D. 21-DEC-2018

Amend F Y 6m to read F G 6m against light
(See Chart No. 1, P20.2)

48°26'30.9"N 123°26'20.2"W

This notice affects Electronic Navigational Chart:
CA470075, CA570138

(P2019071) LL(199) DFO(6204071-02)

16-AUG-2019

LNM/D. 21-DEC-2018

Replace bearing of 015° with 014°
(See Chart No. 1, M1)

48°25'33.5"N 123°26'47.0"W

This notice affects Electronic Navigational Chart:
CA470075

(P2019070) LL(200) DFO(6204071-07)

16-AUG-2019

LNM/D. 21-DEC-2018

Replace bearing of 195° with 194°
(See Chart No. 1, M1)

48°26'21.0"N 123°26'27.0"W

This notice affects Electronic Navigational Chart:
CA470075

(P2019070) LL(200) DFO(6204071-08)

21-DEC-2018

LNM/D. 20-JUL-2018

Amend Victoria TIDAL INFORMATION/RENSEIGNEMENTS SUR LES
MARÉES HHW/PMS 3.4 to read 3.1

48°28'20.5"N 123°36'39.0"W

DFO(6203939-01)

20-JUL-2018

LNM/D. 22-JUN-2018

Delete green port hand lighted pillar buoy Fl G, marked V17
(See Chart No. 1, Qg)

48°25'49.8"N 123°26'39.2"W

This notice affects Electronic Navigational Chart:
CA470075, CA570138

(P2018066) LL(198) DFO(6203795-01)



Chart no. 3440

20-JUL-2018

Add green port hand lighted pillar buoy Fl G, marked V17
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA470075, CA570138

LNМ/D. 22-JUN-2018
48°25'50.1"N 123°26'42.5"W
(P2018066) LL(198) DFO(6203795-02)

20-JUL-2018

Delete depth of 3.1 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075

LNМ/D. 22-JUN-2018
48°25'50.3"N 123°26'44.1"W
DFO(6203795-03)

22-JUN-2018

Amend existing outfall to extend 485 metres further.
This notice affects Electronic Navigational Chart:
CA470075, CA570214

LNМ/D. 11-MAY-2018
between 48°23'54.2"N 123°20'48.2"W
and 48°23'38.8"N 123°20'45.7"W
DFO(6203792-01)

11-MAY-2018

Delete breakwater
(See Chart No. 1, F4.1)
This notice affects Electronic Navigational Chart:
CA470075, CA570562

LNМ/D. 30-MAR-2018
between 48°24'52.0"N 123°23'13.4"W
and 48°24'51.0"N 123°23'12.5"W
DFO(6203756-01)

30-MAR-2018

Reposition yellow ODAS/SADO lighted super-buoy Fl Y, marked
46088
(See Chart No. 1, Q58)

LNМ/D. 02-MAR-2018
from 48°20'01.5"N 123°09'52.6"W
to 48°19'53.1"N 123°10'22.6"W
DFO(6203692-01)

30-MAR-2018

Amend yellow ODAS/SADO lighted super-buoy Fl Y, marked 46088 to
read yellow ODAS/SADO lighted super-buoy Fl (4) Y 20s,
marked 46088
(See Chart No. 1, Q58)

LNМ/D. 02-MAR-2018
48°19'53.1"N 123°10'22.6"W
DFO(6203692-02)

02-MAR-2018

LNМ/D. 31-MAR-2017



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3440

Delete anchoring prohibited area
(See Chart No. 1, N20)

between 48°25'58.1"N 123°26'18.8"W
and 48°26'27.9"N 123°26'11.7"W

This notice affects Electronic Navigational Chart:
CA470075, CA570138

DFO(6203638-01)

02-MAR-2018

LN/D. 31-MAR-2017

Delete anchoring prohibited area
(See Chart No. 1, N20)

between 48°25'57.9"N 123°26'20.0"W
and 48°26'13.5"N 123°26'50.0"W

This notice affects Electronic Navigational Chart:
CA470075, CA570138

DFO(6203638-02)

02-MAR-2018

LN/D. 31-MAR-2017

Add anchoring prohibited area
(See Chart No. 1, N20)

between 48°26'53.5"N 123°27'01.8"W
and 48°26'52.1"N 123°25'58.0"W

This notice affects Electronic Navigational Chart:
CA470075, CA570138

DFO(6203638-03)

02-MAR-2018

LN/D. 31-MAR-2017

Amend Spoil Ground symbol to abandoned Spoil ground symbol
(See Chart No. 1, N62.2)

48°22'17.0"N 123°21'52.0"W

This notice affects Electronic Navigational Chart: CA470075

DFO(6203641-01)

31-MAR-2017

LN/D. 03-MAR-2017

Add floating breakwater, Bkw
(See Chart No. 1, F4.1)

between 48°26'16.6"N 123°26'46.9"W
and 48°26'19.7"N 123°26'43.2"W

This notice affects Electronic Navigational Chart:
CA470075, CA570138

DFO(6203460-01)

03-MAR-2017

LN/D. 18-SEP-2015

Delete port hand daybeacon
(See Chart No. 1, Qt)

48°25'28.6"N 123°17'22.4"W

This notice affects Electronic Navigational Chart: CA470075, (P2017003) DFO(6203452-01)
CA570214

03-MAR-2017

LN/D. 18-SEP-2015



Chart no. 3440

Add black and yellow North cardinal pillar buoy, marked VJ
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA470075, CA570214
48°25'30.6"N 123°17'23.4"W
(P2017002) DFO(6203452-02)

18-SEP-2015
Add depth of 13.7 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075, CA570214
LNМ/D. 19-JUN-2015
48°25'44.4"N 123°13'13.4"W
DFO(6203086-01)

18-SEP-2015
Delete depth of 15.5 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075
LNМ/D. 19-JUN-2015
48°25'43.0"N 123°13'11.0"W
DFO(6203086-02)

19-JUN-2015
Replace VESSEL TRAFFIC SYSTEM SERVICES DU TRAFIC
MARITIME
3rd paragraph note with
LNМ/D. 03-OCT-2014
48°25'52.0"N 123°36'00.0"W
DFO(6203038-07)

Limits of the Victoria or Seattle Vessel Traffic Services Zones.
Applicable vessels must participate fully on the appropriate
sector frequency reporting at all calling-in points and upon
entering or leaving these zones.

Limites des Zones de services du trafic maritime de Victoria
ou de Seattle. Les navires concernés doivent être à l'écoute
de la fréquence de secteur approprié et doivent envoyer
un compte rendu à chaque point d'appel radio, ainsi qu'à
l'entrée et à la sortie de ces zones.

This notice affects Electronic Navigational Chart: CA470075

03-OCT-2014
Add depth of 1.5 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370367
LNМ/D. 12-SEP-2014
48°27'53.5"N 123°02'58.5"W
DFO(6202905-01)

12-SEP-2014
LNМ/D. 27-JUN-2014



Chart no. 3440

- Delete radio mast 48°23'17.0"N 123°29'29.0"W
(See Chart No. 1, E28)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202898-03)*
- 12-SEP-2014** LNM/D. 27-JUN-2014
Delete radio mast marked RLts 48°23'10.5"N 123°29'31.0"W
(See Chart No. 1, E28,P61.1)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202898-04)*
- 27-JUN-2014** LNM/D. 13-JUN-2014
Delete fishing prohibited area joining 48°25'02.0"N 123°27'32.0"W
(See Chart No. 1, N21) 48°24'57.0"N 123°27'17.0"W
This notice affects Electronic Navigational Chart: 48°24'50.0"N 123°27'22.0"W
CA470075 48°24'54.0"N 123°27'37.0"W
and 48°25'02.0"N 123°27'32.0"W
DFO(6202866-01)
- 27-JUN-2014** LNM/D. 13-JUN-2014
Add fishing prohibited area joining 48°24'41.8"N 123°27'03.8"W
(See Chart No. 1, N21) 48°24'38.4"N 123°26'47.6"W
48°24'30.3"N 123°26'51.7"W
This notice affects Electronic Navigational Chart: 48°24'33.9"N 123°27'07.8"W
CA470075 and 48°24'41.8"N 123°27'03.8"W
DFO(6202866-02)
- 27-JUN-2014** LNM/D. 13-JUN-2014
Add submarine cable joining 48°25'54.5"N 123°26'18.5"W
(See Chart No. 1, L30.1) 48°25'52.5"N 123°26'27.5"W
This notice affects Electronic Navigational Chart: 48°25'48.0"N 123°26'30.0"W
CA470075 48°25'01.5"N 123°26'49.5"W
and 48°24'39.0"N 123°26'59.5"W
DFO(6202866-03)
- 27-JUN-2014** LNM/D. 13-JUN-2014
Delete anchor berth, marked E 48°24'43.0"N 123°26'41.0"W
(See Chart No. 1, N11.1)
DFO(6202866-04)
This notice affects Electronic Navigational Chart: CA470075



Chart no. 3440

13-JUN-2014 LNM/D. 30-MAY-2014

Delete depth of 31 metres 48°18'31.0"N 123°04'05.0"W
(See Chart No. 1, I10)

DFO(6202846-01)

13-JUN-2014 LNM/D. 30-MAY-2014

Add depth of 23.5 metres 48°18'26.5"N 123°04'13.5"W
(See Chart No. 1, I10)

DFO(6202846-02)

13-JUN-2014 LNM/D. 30-MAY-2014

Add depth of 25.5 metres 48°18'40.0"N 123°04'00.0"W
(See Chart No. 1, I10)

DFO(6202846-03)

13-JUN-2014 LNM/D. 30-MAY-2014

Delete depth of 29.3 metres 48°18'46.0"N 123°04'01.0"W
(See Chart No. 1, I10)

DFO(6202846-04)

13-JUN-2014 LNM/D. 30-MAY-2014

Delete depth of 25.6 metres 48°19'23.5"N 123°03'36.0"W
(See Chart No. 1, I10)

DFO(6202846-05)

13-JUN-2014 LNM/D. 30-MAY-2014

Add depth of 21.5 metres 48°19'30.5"N 123°03'28.0"W
(See Chart No. 1, I10)

DFO(6202846-06)

13-JUN-2014 LNM/D. 30-MAY-2014

Add depth of 16.2 metres 48°19'51.0"N 123°03'08.0"W
(See Chart No. 1, I10)

DFO(6202846-07)

30-MAY-2014

LNM/D. 11-OCT-2013



Chart no. 3440

Delete Custom Office (See Chart No. 1, F61) This notice affects Electronic Navigational Chart: CA470075	48°25'29.0"N 123°22'07.0"W <i>DFO(6202835-05)</i>
30-MAY-2014 Add Custom Office (See Chart No. 1, F61) This notice affects Electronic Navigational Chart: CA470075	LNM/D. 11-OCT-2013 48°25'17.0"N 123°22'47.0"W <i>DFO(6202835-06)</i>
11-OCT-2013 Add obstruction, least depth known 113 metres (See Chart No. 1 K41) This notice affects Electronic Navigational Chart: CA470075	LNM/D. 15-FEB-2013 48°18'00.6"N 123°23'44.5"W <i>DFO(6202740-01)</i>
11-OCT-2013 Add obstruction, least depth known 55 metres (See Chart No. 1, K41) This notice affects Electronic Navigational Chart: CA470075	LNM/D. 15-FEB-2013 48°24'04.2"N 123°24'32.3"W <i>DFO(6202740-02)</i>
15-FEB-2013 Delete depth of 10.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470075	LNM/D. 30-NOV-2012 48°26'45.4"N 123°15'57.0"W <i>DFO(6202678-13)</i>
15-FEB-2013 Delete depth of 11 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470075	LNM/D. 30-NOV-2012 48°25'42.2"N 123°15'18.4"W <i>DFO(6202678-14)</i>
15-FEB-2013 Delete depth of 5.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470075	LNM/D. 30-NOV-2012 48°25'43.4"N 123°17'30.2"W <i>DFO(6202678-15)</i>
15-FEB-2013 Add depth of 4.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA470075, CA570214	LNM/D. 30-NOV-2012 48°27'01.5"N 123°17'00.2"W <i>DFO(6202678-16)</i>



Chart no. 3440

15-FEB-2013

Add depth of 8 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

LNМ/D. 30-NOV-2012

48°26'44.4"N 123°15'54.1"W

DFO(6202678-17)

15-FEB-2013

Add depth of 7.6 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

LNМ/D. 30-NOV-2012

48°25'43.4"N 123°15'19.8"W

DFO(6202678-18)

15-FEB-2013

Add depth of 2.9 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

LNМ/D. 30-NOV-2012

48°25'42.5"N 123°17'29.7"W

DFO(6202678-19)

15-FEB-2013

Add depth of 2.8 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

LNМ/D. 30-NOV-2012

48°25'15.3"N 123°17'21.1"W

DFO(6202678-20)

30-NOV-2012

Reposition yellow ODAS/SADO lighted buoy Fl Y, marked 46088 from 48°20'00.0"N 123°10'00.0"W
(See Chart No. 1, Q58) to 48°20'01.4"N 123°09'52.6"W

LNМ/D. 31-AUG-2012

(NOS:46088) DFO(6202639-01)

31-AUG-2012

Add wreck, least depth known of 5.3 metres

(See Chart No. 1, K26)

LNМ/D. 15-JUN-2012

48°18'42.5"N 123°32'30.5"W

DFO(6202588-01)

This notice affects Electronic Navigational Chart: CA470075,
CA570101

15-JUN-2012

LNМ/D. 08-JUN-2012



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3440

Delete depth of 5.5 metres
(See Chart No. 1, I10)

48°24'12.6"N 123°17'06.8"W

DFO(6202566-01)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

15-JUN-2012

Add depth of 4.7 metres
(See Chart No. 1, I10)

LNМ/D. 08-JUN-2012

48°24'12.5"N 123°17'06.2"W

DFO(6202566-02)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

15-JUN-2012

Add depth of 5.9 metres
(See Chart No. 1, I10)

LNМ/D. 08-JUN-2012

48°25'03.7"N 123°14'03.7"W

DFO(6202566-06)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

08-JUN-2012

Delete black, red and black isolated danger lighted pillar buoy Fl(2)
5s, marked DH
(See Chart No. 1, Q130.4)

LNМ/D. 10-JUN-2011

48°21'05.6"N 123°02'45.7"W

LL(16361) DFO(6202564-01)

10-JUN-2011

Add submarine pipeline
(See Chart No. 1, L41.1)

LNМ/D. 20-MAR-2009

joining 48°21'37.4"N 123°32'09.3"W
48°21'37.4"N 123°32'07.5"W
and 48°21'31.6"N 123°31'53.6"W

This notice affects Electronic Navigational Chart:
CA470075, CA570101

DFO(6202435-01)

10-JUN-2011

LNМ/D. 20-MAR-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3440

Add pipeline sign
(See Chart No. 1, Qu)

48°21'37.4"N 123°32'10.2"W

DFO(6202435-02)

This notice affects Electronic Navigational Chart: CA470075,
CA570101

20-MAR-2009

Replace bifurcation daybeacon with port hand daybeacon
(See Chart No. 1, Qt)

LNМ/D. 23-NOV-2007

48°25'27.7"N 123°17'39.6"W

(P2009022) DFO(6202011-01)

This notice affects Electronic Navigational Chart:
CA470075, CA570214

23-NOV-2007

Delete depth of 3.7 metres
(See Chart No. 1, I10)

LNМ/D. 19-JAN-2007

48°25'15.4"N 123°23'21.3"W

DFO(6201780-01)

This notice affects Electronic Navigational Chart: CA470075

23-NOV-2007

Add depth of 7.6 metres
(See Chart No. 1, I10)

LNМ/D. 19-JAN-2007

48°25'16.2"N 123°23'20.3"W

DFO(6201780-02)

This notice affects Electronic Navigational Chart: CA470075

19-JAN-2007

Delete depth of 7 metres
(see Chart No. 1 I10)

LNМ/D. 05-JAN-2007

48°18'05.2"N 123°32'01.4"W

DFO(6201642-01)

This notice affects Electronic Navigational Chart: CA470075,
CA570101

19-JAN-2007

LNМ/D. 05-JAN-2007



Chart no. 3440

Add obstruction with known depth of 5 metres
(see Chart No. 1 K41)

48°18'06.4"N 123°32'02.1"W

DFO(6201642-02)

This notice affects Electronic Navigational Chart: CA470075,
CA570101

19-JAN-2007

LN/D. 05-JAN-2007

Add submarine cable
(see Chart No. 1 L30.1)

joining 48°18'06.4"N 123°32'02.1"W
48°18'03.6"N 123°31'53.4"W
48°17'58.9"N 123°31'51.9"W
and 48°17'55.0"N 123°31'53.7"W

This notice affects Electronic Navigational Chart:
CA470075, CA570101

DFO(6201642-03)

05-JAN-2007

LN/D. 15-DEC-2006

Delete depth of 11 metres

48°33'05.9"N 123°14'56.8"W

DFO(6201636-01)

This notice affects Electronic Navigational Chart: CA470366

05-JAN-2007

LN/D. 15-DEC-2006

Add depth of 5.5 metres

48°33'03.7"N 123°14'57.2"W

DFO(6201636-02)

This notice affects Electronic Navigational Chart: CA470366

05-JAN-2007

LN/D. 15-DEC-2006

Add depth of 9.8 metres

48°33'16.6"N 123°19'59.0"W

DFO(6201636-03)

This notice affects Electronic Navigational Chart: CA370367,
CA470366

15-DEC-2006

Delete yellow cautionary spherical buoy, marked NAVY
(see Chart No. 1 Q22)

48°23'36.0"N 123°28'36.0"W

DFO(6201578-01)

This notice affects Electronic Navigational Chart: CA470075



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3440