



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3461

3461 - Juan de Fuca Strait, Eastern Portion/Partie Est - New Edition - 01-JUL-2005 - NAD 1983

15-SEP-2023

LNM/D. 30-JUN-2023

Delete harbour limit and legend ESQUIMALT between 48°25'22.5"N 123°25'08.4"W
(See Chart 1, N49) and 48°25'22.5"N 123°27'57.4"W

DFO(6204801-01)

15-SEP-2023

LNM/D. 30-JUN-2023

Delete harbour limit and legend VICTORIA between 48°23'41.1"N 123°18'16.4"W
(See Chart 1, N49) and 48°23'05.6"N 123°28'50.2"W

This notice affects Electronic Navigational Chart:
CA570101, CA570214

DFO(6204801-02)

15-SEP-2023

LNM/D. 30-JUN-2023

Add harbour limit and legend ESQUIMALT joining 48°23'02.3"N 123°28'46.4"W
(See Chart 1, N49) 48°23'12.6"N 123°25'12.6"W
and 48°25'19.3"N 123°25'11.0"W

DFO(6204801-03)

30-JUN-2023

LNM/D. 16-JUN-2023

Amend light Al RW 5s 16m 15M to read Al WR 10s 16m 15M 48°08'38.5"N 122°45'17.0"W
(See Chart No. 1, P1)

DFO(6204780-01)

16-JUN-2023

LNM/D. 05-MAY-2023

Delete submarine cable joining 48°24'50.9"N 123°23'06.9"W
(See Chart 1, L30.1) 48°24'35.0"N 123°23'04.1"W
This notice affects Electronic Navigational Chart: and 48°24'23.4"N 123°23'16.2"W
CA470075, CA570562

DFO(6204772-01)

05-MAY-2023

LNM/D. 14-OCT-2022

Delete aero light 48°05'33.0"N 122°55'49.2"W
(See Chart 1, P60)

DFO(6204736-01)

14-OCT-2022

LNM/D. 22-APR-2022



Chart no. 3461

Amend Oc 9m9M to read Fl 6s9m7M against light 48°06'05.8"N 122°41'16.6"W
(See Chart 1, P1)

DFO(6204634-02)

14-OCT-2022

LNM/D. 22-APR-2022

Delete legend Racon against lighted
yellow pillar buoy Fl Y 2.5s
marked SA

48°11'27.4"N 122°49'47.6"W

(USCG:USCG LNM District 13 - 21/22) DFO(6204649-01)

22-APR-2022

LNM/D. 14-JAN-2022

Delete ANCHORAGE PROHIBITED 48°24'01.3"N 123°23'19.7"W
MOUILLANGE INTERDIT

DFO(6204592-01)

22-APR-2022

LNM/D. 14-JAN-2022

Delete limit of restricted area between 48°23'03.0"N 123°28'47.0"W
(See Chart No. 1, 2.1) and 48°23'40.0"N 123°18'17.0"W

DFO(6204592-05)

14-JAN-2022

LNM/D. 04-JUN-2021

Add AIS 48°22'01.5"N 123°02'11.2"W
(See Chart No. 1, S17.2)

DFO(6204523-01)

14-JAN-2022

LNM/D. 04-JUN-2021

Add AIS 48°19'45.3"N 122°58'38.2"W
(See Chart No. 1, S17.2)

DFO(6204523-03)

14-JAN-2022

LNM/D. 04-JUN-2021

Add yellow ODAS/SADO lighted spherical buoy Fl (5) Y 20s, marked
46267
(See Chart No. 1, Q58)

48°10'23.5"N 123°36'18.8"W

DFO(6204524-01)

04-JUN-2021

LNM/D. 18-SEP-2020

Add yellow ODAS/SADO lighted buoy Fl (5) Y 20s, marked Priv (See
Chart No. 1, Q58)

48°20'59.3"N 123°43'50.9"W

DFO(6204448-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3461

18-SEP-2020

Add outfall pipe (See Chart No. 1, L41.1)
This notice affects Electronic Navigational Chart:
CA470075, CA570562

LNLM/D. 24-JUL-2020
joining 48°25'09.7"N 123°23'50.0"W
48°25'05.1"N 123°23'50.8"W
and 48°24'15.0"N 123°24'26.0"W

DFO(6204366-01)

24-JUL-2020

Add yellow ODAS/SADO lighted spherical buoy Fl (5) Y 20s, marked
Priv
(See Chart No. 1, Q58)

LNLM/D. 27-MAR-2020
48°10'21.3"N 123°26'25.8"W

DFO(6204345-01)

27-MAR-2020

Reposition yellow ODAS/SADO lighted super-buoy Fl(4)
Y 20s, marked 46088
(See Chart No. 1, Q58)

LNLM/D. 21-DEC-2018
from 48°19'53.0"N 123°10'22.0"W
to 48°19'56.3"N 123°10'44.1"W

(USCG:District 13 50/19) DFO(6204260-01)

21-DEC-2018

Amend Victoria TIDAL INFORMATION/RENSEIGNEMENTS SUR LES
MARÉES HHW/PMS 3.4 to read 3.1

LNLM/D. 22-JUN-2018
47°58'14.5"N 123°42'02.0"W

DFO(6203939-01)

22-JUN-2018

Amend existing outfall to extend 485 metres further.
This notice affects Electronic Navigational Chart:
CA470075, CA570214

LNLM/D. 30-MAR-2018
between 48°23'54.2"N 123°20'48.2"W
and 48°23'38.8"N 123°20'45.7"W

DFO(6203792-01)

30-MAR-2018

Reposition yellow ODAS/SADO lighted super-buoy Fl Y, marked
46088
(See Chart No. 1, Q58)

LNLM/D. 02-MAR-2018
from 48°19'20.0"N 123°09'59.3"W
to 48°19'53.1"N 123°10'22.6"W

DFO(6203692-01)

30-MAR-2018

Amend yellow ODAS/SADO lighted super-buoy Fl Y, marked 46088 to
read yellow ODAS/SADO lighted super-buoy Fl(4) Y 20s,
marked 46088
(See Chart No. 1, Q58)

LNLM/D. 02-MAR-2018
48°19'53.1"N 123°10'22.6"W

DFO(6203692-02)



Chart no. 3461

02-MAR-2018

LNМ/D. 23-FEB-2018

Amend Spoil Ground symbol to abandoned Spoil ground symbol
(See Chart No. 1, N62.2)

48°22'21.5"N 123°21'46.0"W

This notice affects Electronic Navigational Chart: CA470075

DFO(6203641-01)

23-FEB-2018

LNМ/D. 05-MAY-2017

Amend yellow lighted pillar buoy Fl Y, marked PA to read yellow
lighted pillar buoy Fl Y 2.5s, marked PA

48°12'54.0"N 123°28'41.1"W

(See Chart No. 1, Q61)

LL(187.5) DFO(6203628-01)

23-FEB-2018

LNМ/D. 05-MAY-2017

Amend yellow lighted pillar buoy Fl Y, marked R to read yellow
lighted pillar buoy Fl Y 2.5s, marked R

48°16'25.3"N 123°06'34.6"W

(See Chart No. 1, Q61)

LL(187.0) DFO(6203628-02)

23-FEB-2018

LNМ/D. 05-MAY-2017

Amend yellow lighted pillar buoy Fl Y, with RACON, marked RA to
read yellow lighted pillar buoy Fl Y 2.5s, with RACON, marked
RA

48°19'45.4"N 122°58'38.6"W

(See Chart No. 1, Q61)

DFO(6203628-03)

23-FEB-2018

LNМ/D. 05-MAY-2017

Amend yellow lighted pillar buoy Fl Y, marked S to read yellow lighted
pillar buoy Fl Y 2.5s, marked S

48°12'21.3"N 123°06'34.6"W

(See Chart No. 1, Q61)

DFO(6203628-04)

23-FEB-2018

LNМ/D. 05-MAY-2017

Amend yellow lighted pillar buoy Fl Y, marked SC to read yellow
lighted pillar buoy Fl Y 2.5s, marked SC

48°01'51.2"N 122°38'09.0"W

(See Chart No. 1, Q61)

DFO(6203628-05)

23-FEB-2018

LNМ/D. 05-MAY-2017

Amend yellow lighted pillar buoy Fl Y, marked SD to read yellow
lighted pillar buoy Fl Y 2.5s, marked SD

47°57'53.5"N 122°34'46.5"W

(See Chart No. 1, Q61)

DFO(6203628-06)

23-FEB-2018

LNМ/D. 05-MAY-2017



Chart no. 3461

Amend green port hand lighted pillar buoy Fl G, with RACON, marked 48°22'01.4"N 123°02'11.2"W
1 to read green port hand lighted pillar buoy Fl G 6s, with
RACON, marked 1 *DFO(6203628-07)*
(See Chart No. 1, Qg)

23-FEB-2018

Amend red starboard hand lighted pillar buoy Fl R, with BELL, LNM/D. 05-MAY-2017
48°24'41.0"N 122°46'23.7"W
marked 2 to read red starboard hand lighted pillar buoy Fl R
2.5s, with BELL, marked 2 *DFO(6203628-08)*
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA370368

23-FEB-2018

Amend green port hand lighted pillar buoy Fl G, marked 3 to read LNM/D. 05-MAY-2017
48°27'01.6"N 122°47'30.9"W
green port hand lighted pillar buoy Fl G 2.5s, marked 3
(See Chart No. 1, Qg) *DFO(6203628-09)*
This notice affects Electronic Navigational Chart: CA370368

23-FEB-2018

Amend red starboard hand lighted pillar buoy Fl R, marked 2 to read LNM/D. 05-MAY-2017
48°08'20.5"N 123°23'57.8"W
red starboard hand lighted pillar buoy Fl R 2.5s, marked 2
(See Chart No. 1, Qf) *LL(190.2) DFO(6203628-10)*

05-MAY-2017

Delete light Fl 8m5M LNM/D. 18-NOV-2016
48°19'26.0"N 122°49'09.0"W
(See Chart No. 1, P1)
(P2017024) LL(218.8) DFO(6203488-01)

18-NOV-2016

Amend red, green and red starboard bifurcation lighted pillar buoy LNM/D. 05-AUG-2016
48°24'03.3"N 122°42'57.7"W
marked, Fl (2+1) R to read Fl (2+1) R 6s
(See Chart No. 1, Q23, Qi) *DFO(6203404-01)*
This notice affects Electronic Navigational Chart: CA370368

05-AUG-2016

Add Automatic Identification System Transmitter to yellow pillar LNM/D. 06-MAY-2016
48°11'27.3"N 122°49'47.6"W
buoy, marked SA Fl Y
(See Chart No. 1, S17.2) *DFO(6203315-01)*



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3461

05-AUG-2016

LNМ/D. 06-MAY-2016

Amend yellow pillar buoy, marked SA Fl Y to read yellow pillar buoy, marked SA Fl Y 2½s
(See Chart No. 1, Q23)

DFO(6203315-02)

06-MAY-2016

LNМ/D. 08-APR-2016

Add light Fl R, marked 5m4M 48°05'03.7"N 123°01'48.6"W
(See Chart No. 1, P1)

DFO(6203259-01)

08-APR-2016

LNМ/D. 19-JUN-2015

Delete light marked Fl 10s 30m 18M 48°19'06.5"N 122°50'37.7"W
(See Chart No. 1, P1)

DFO(6203253-01)

08-APR-2016

LNМ/D. 19-JUN-2015

Add light marked Fl 10s 17m 14M 48°19'14.4"N 122°49'51.5"W
(See Chart No. 1, P1)

DFO(6203253-03)

19-JUN-2015

LNМ/D. 16-JAN-2015

Replace VESSEL TRAFFIC SYSTEM SERVICES DU TRAFIC
MARITIME
3rd paragraph note with

48°00'13.0"N 123°20'00.0"W

DFO(6203038-04)

Limits of the Victoria or Seattle Vessel Traffic Services Zones.
Applicable vessels must participate fully on the appropriate
sector frequency reporting at all calling-in points and upon
entering or leaving these zones.

Limites des Zones de services du trafic maritime de Victoria
ou de Seattle. Les navires concernés doivent être à l'écoute
de la fréquence de secteur approprié et doivent envoyer
un compte rendu à chaque point d'appel radio, ainsi qu'à
l'entrée et à la sortie de ces zones.

16-JAN-2015

LNМ/D. 03-OCT-2014

Add depth of 4.9 metres 48°06'39.0"N 122°53'10.5"W
(See Chart No. 1, I10)

DFO(6202942-01)



Chart no. 3461

16-JAN-2015 LNM/D. 03-OCT-2014
Add depth of 3.7 metres 48°06'47.0"N 122°52'50.0"W
(See Chart No. 1, I10)
DFO(6202942-02)

16-JAN-2015 LNM/D. 03-OCT-2014
Add depth of 6.7 metres 48°05'54.5"N 122°58'41.0"W
(See Chart No. 1, I10)
DFO(6202942-03)

16-JAN-2015 LNM/D. 03-OCT-2014
Add depth of 6.7 metres 48°08'55.0"N 122°56'37.0"W
(See Chart No. 1, I10)
DFO(6202942-04)

16-JAN-2015 LNM/D. 03-OCT-2014
Add depth of 7.6 metres 48°09'07.0"N 122°56'05.0"W
(See Chart No. 1, I10)
DFO(6202942-05)

03-OCT-2014 LNM/D. 12-SEP-2014
Add depth of 1.5 metres 48°27'53.5"N 123°02'58.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370367 *DFO(6202905-01)*

12-SEP-2014 LNM/D. 27-JUN-2014
Delete radio mast marked RLts 48°23'15.5"N 123°29'28.5"W
(See Chart No. 1, E28,P61.1)
DFO(6202898-01)

12-SEP-2014 LNM/D. 27-JUN-2014
Delete radio mast marked RLts 48°23'11.0"N 123°29'30.0"W
(See Chart No. 1, E28,P61.1)
DFO(6202898-02)

27-JUN-2014 LNM/D. 13-JUN-2014



Chart no. 3461

Add submarine cable joining 48°25'54.0"N 123°26'20.0"W
(See Chart No. 1, L30.1) 48°25'52.0"N 123°26'27.0"W
and 48°24'39.0"N 123°26'59.0"W

DFO(6202866-10)

13-JUN-2014 LNM/D. 25-APR-2014

Add depth of 23.5 metres 48°18'26.5"N 123°04'13.5"W
(See Chart No. 1, I10)

DFO(6202846-02)

13-JUN-2014 LNM/D. 25-APR-2014

Add depth of 25.5 metres 48°18'40.0"N 123°04'00.0"W
(See Chart No. 1, I10)

DFO(6202846-03)

13-JUN-2014 LNM/D. 25-APR-2014

Add depth of 16.2 metres 48°19'51.0"N 123°03'08.0"W
(See Chart No. 1, I10)

DFO(6202846-07)

13-JUN-2014 LNM/D. 25-APR-2014

Delete depth of 29 metres 48°18'46.0"N 123°04'02.0"W
(See Chart No. 1, I10)

DFO(6202846-08)

13-JUN-2014 LNM/D. 25-APR-2014

Delete depth of 20.1 metres 48°19'57.0"N 123°03'08.0"W
(See Chart No. 1, I10)

DFO(6202846-09)

25-APR-2014 LNM/D. 30-AUG-2013

Amend Fl 7m6M to read Fl 8m5M against light 48°19'27.0"N 122°49'09.5"W
(See Chart No. 1, P10.4)

DFO(6202829-01)

30-AUG-2013

LNM/D. 31-MAY-2013



Chart no. 3461

Amend Fl 6s 17m 9M to read Fl 6s 17m 7M against light 48°28'40.6"N 122°42'48.8"W
This notice affects Electronic Navigational Chart: CA370368

DFO(6202730-01)

31-MAY-2013

LNM/D. 24-MAY-2013

Replace out of position green port hand can buoy, marked 3 with out of position green port hand lighted pillar buoy Fl G, marked 3 (See Chart No. 1, Qa, Qg) 48°27'00.0"N 122°47'30.0"W

DFO(6202696-01)

This notice affects Electronic Navigational Chart: CA370368

24-MAY-2013

LNM/D. 21-DEC-2012

Delete firing practice area joining 48°10'49.0"N 123°45'34.7"W
(See Chart No. 1, N30) 48°10'30.0"N 123°42'06.0"W
48°14'38.0"N 123°42'06.0"W
48°15'16.0"N 123°45'34.7"W
and 48°10'49.0"N 123°45'34.7"W

DFO(6202695-02)

24-MAY-2013

LNM/D. 21-DEC-2012

Delete note 48°12'24.0"N 123°43'48.0"W

US NAVY EXERCISE AREA 2 *DFO(6202695-04)*
ZONE D'EXERCICES 2 DU "US NAVY"

21-DEC-2012

LNM/D. 09-NOV-2012

Delete firing practice area joining 48°17'24.2"N 122°45'11.9"W
(See Chart No. 1, N30) 48°20'00.0"N 122°44'00.0"W
and 48°18'43.0"N 122°42'41.0"W

DFO(6202670-01)

21-DEC-2012

LNM/D. 09-NOV-2012

Add firing practice area joining 48°17'24.2"N 122°45'11.9"W
(See Chart No. 1, N30) 48°19'59.9"N 122°44'12.1"W
and 48°19'21.4"N 122°42'10.4"W

DFO(6202670-02)

09-NOV-2012

LNM/D. 31-AUG-2012



Chart no. 3461

Delete spoil ground 48°09'00.7"N 123°23'59.2"W
(See Chart No. 1, N62.1)

DFO(6202629-01)

09-NOV-2012

LNM/D. 31-AUG-2012

Delete spoil ground joining 48°08'07.6"N 123°28'02.7"W
(See Chart No. 1, N62.1) 48°08'15.6"N 123°28'06.4"W
48°08'31.2"N 123°27'23.6"W
48°08'39.7"N 123°26'36.0"W
and 48°08'28.9"N 123°26'34.1"W

DFO(6202629-02)

31-AUG-2012

LNM/D. 15-JUN-2012

Delete black, red and black isolated danger lighted pillar buoy Fl(2)
5s, marked BR
(See Chart No. 1, Q130.4)

48°29'36.5"N 122°44'56.5"W

DFO(6202589-01)

This notice affects Electronic Navigational Chart: CA370368

15-JUN-2012

LNM/D. 08-JUN-2012

Delete depth of 5.5 metres
(See Chart No. 1, I10)

48°24'12.6"N 123°17'06.8"W

DFO(6202566-01)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

15-JUN-2012

LNM/D. 08-JUN-2012

Add depth of 4.7 metres
(See Chart No. 1, I10)

48°24'12.5"N 123°17'06.2"W

DFO(6202566-02)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

08-JUN-2012

LNM/D. 16-MAR-2012

Delete black, red and black isolated danger lighted pillar buoy Fl(2)
5s, marked DH
(See Chart No. 1, Q130.4)

48°21'05.6"N 123°02'45.7"W

LL(16361) DFO(6202564-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3461

16-MAR-2012

LNМ/D. 16-DEC-2011

Delete green port hand can buoy, marked 1 48°15'31.8"N 122°50'12.1"W
(See Chart No. 1, Qg)

DFO(6202549-01)

16-MAR-2012

LNМ/D. 16-DEC-2011

Delete BELL against light 48°14'48.8"N 122°50'02.7"W
(See Chart No. 1, R14)

DFO(6202549-02)

16-MAR-2012

LNМ/D. 16-DEC-2011

Amend aid ID 3 to read 1 against light 48°14'48.8"N 122°50'02.7"W

DFO(6202549-03)

16-MAR-2012

LNМ/D. 16-DEC-2011

Reposition green port hand lighted pillar buoy Fl G, marked 1 from 48°14'48.8"N 122°50'02.7"W
(See Chart No. 1, Qg) to 48°15'23.7"N 122°49'56.2"W

DFO(6202549-04)

16-DEC-2011

LNМ/D. 24-JUN-2011

Add black, red and black isolated danger lighted pillar buoy Fl(2) 5s, 48°29'36.5"N 122°44'56.5"W
marked BR
(See Chart No. 1, Q130.4)

LL(19397) DFO(6202529-01)

This notice affects Electronic Navigational Chart: CA370368

24-JUN-2011

LNМ/D. 07-JAN-2011

Reposition red starboard hand bell buoy, BELL
(See Chart No. 1, Qc, R21)

from 48°10'19.3"N 123°43'26.6"W
to 48°10'19.6"N 123°43'34.6"W

(USCG:USLNM13) DFO(6202441-01)

This notice affects Electronic Navigational Chart:
CA370141

07-JAN-2011

LNМ/D. 24-DEC-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3461

Delete light Q G(Priv)
(See Chart No. 1, P1)

48°09'20.3"N 122°40'22.6"W

DFO(6202385-01)

This notice affects Electronic Navigational Chart: CA370141

07-JAN-2011

Add light Fl G(Priv)
(See Chart No. 1, P1)

LNМ/D. 24-DEC-2010

48°09'24.0"N 122°40'18.0"W

DFO(6202385-02)

This notice affects Electronic Navigational Chart: CA370141

24-DEC-2010

Delete GONG against buoy marked 4
(See Chart No. 1, R16)

LNМ/D. 15-OCT-2010

48°26'50.3"N 122°42'24.9"W

DFO(6202381-01)

This notice affects Electronic Navigational Chart: CA370368

15-OCT-2010

Amend Fl 5s 32m 18M to read Fl 5s 32m 13M against light

LNМ/D. 01-OCT-2010

48°13'28.8"N 122°46'09.9"W

LL(217.5) DFO(6202350-01)

This notice affects Electronic Navigational Chart: CA370141

01-OCT-2010

Add non-dangerous wreck, depth unknown, marked PA
(See Chart No. 1, K29 and W)

LNМ/D. 04-DEC-2009

48°26'19.7"N 123°00'11.3"W

DFO(6202346-01)

This notice affects Electronic Navigational Chart: CA370367

04-DEC-2009

Amend Fl 2½s 8m 11M to read Fl 2½s 8m 7M against
light

LNМ/D. 30-OCT-2009

48°01'50.5"N 122°36'25.4"W

(USCG:USLNM13 43/09) DFO(6202165-01)

This notice affects Electronic Navigational
Chart: CA370141



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3461

30-OCT-2009

Add depth of 6.4 metres with bottom quality of R
(See Chart No. 1, I10 and J9.1)

LN/D. 29-MAY-2009

48°18'52.0"N 122°53'01.8"W

(USCG:USLNM13 39/09) DFO(6202155-01)

This notice affects Electronic Navigational Chart:
CA370141

29-MAY-2009

Delete green port hand buoy, marked 1
(See Chart No. 1, Qg)

LN/D. 22-MAY-2009

48°06'52.3"N 122°57'54.1"W

(USCG:USLNM 13 16/09) DFO(6202054-01)

This notice affects Electronic Navigational
Chart: CA370141

22-MAY-2009

Delete BELL against buoy marked 2
(See Chart No. 1, R14)

LN/D. 17-APR-2009

48°11'32.3"N 123°05'40.6"W

(USCG:USLNM13 15/09) DFO(6202050-01)

This notice affects Electronic Navigational
Chart: CA370141

17-APR-2009

Delete radar transponder beacon against buoy marked
R
(See Chart No. 1, S3.6)

LN/D. 07-MAR-2008

48°16'25.3"N 123°06'34.6"W

(USCG:USLNM13 10/09) DFO(6202027-01)

This notice affects Electronic Navigational
Chart: CA370141

07-MAR-2008

Delete FogSig(2)30s against light
(See Chart No. 1, R20)

LN/D. 25-JAN-2008

48°06'05.8"N 122°41'16.5"W

(USCG:USLNM13 05/08) DFO(6201813-01)

This notice affects Electronic Navigational
Chart: CA370141



Chart no. 3461

25-JAN-2008

Delete radar transponder beacon against buoy marked
S
(See Chart No. 1, S3.6)

LNМ/D. 28-DEC-2007

48°12'21.3"N 123°06'34.6"W

(USCG:USLNM13 51/07) DFO(6201798-01)

This notice affects Electronic Navigational
Chart: CA370141

28-DEC-2007

Add radar transponder beacon against buoy marked VF
(See Chart No. 1, S3.6)

LNМ/D. 11-MAY-2007

48°14'04.4"N 123°31'58.7"W

(P2007106) LL(189.5) DFO(6201797-01)

This notice affects Electronic Navigational Chart:
CA370141

11-MAY-2007

Amend Al Oc W & Fl R 20s 16m 15M to read Al RW 5s
16m 15M

LNМ/D. 28-JUL-2006

48°08'39.0"N 122°45'17.2"W

(USCG:USLNM13 14/07) DFO(6201673-01)

This notice affects Electronic Navigational
Chart: CA370141

28-JUL-2006

Add depth of 7.3 metres
(see Chart No. 1 I10)

LNМ/D. 14-JUL-2006

48°18'35.2"N 122°52'16.3"W

(USCG:USLNM13 25/06) DFO(6201489-01)

This notice affects Electronic Navigational Chart:
CA370141

14-JUL-2006

Delete FogSig30s

LNМ/D. 31-MAR-2006

48°08'39.0"N 122°45'17.2"W

(USCG:USLNM13 23/06) DFO(6201479-01)

This notice affects Electronic Navigational
Chart: CA370141

31-MAR-2006

LNМ/D. 05-AUG-2005



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3461

Amend Fl 15s 30m 21M to read Fl 10s 30m 18M

48°19'06.4"N 122°50'37.7"W

(USCG:USLNM 07/06) DFO(6201388-01)

This notice affects Electronic Navigational Chart:
CA370141

05-AUG-2005

Delete FogSig(2)20s

48°07'02.0"N 122°44'57.2"W

(USCG:USCG13 07/05) DFO(6201247-01)

05-AUG-2005

Amend Iso R to read Fl R 2½s 11m 5M

48°07'02.0"N 122°44'57.2"W

(USCG:USCG13 07/05) DFO(6201247-02)

05-AUG-2005

Delete FogSig30s

48°10'54.3"N 123°06'36.9"W

(USCG:USLNM13 18/05) DFO(6201254-01)

05-AUG-2005

Delete FogSig30s

48°13'28.8"N 122°46'09.9"W

(P2005048) LL(217.5) DFO(6201260-01)