



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3462

3462 - Juan de Fuca Strait to/à Strait of Georgia - New Edition - 01-JUL-2005 - NAD 1983

29-NOV-2024

LNМ/D. 20-SEP-2024

Amend light Fl R to read Fl(2+1)R 6s
(See Chart 1, P1)

48°39'17.8"N 123°19'23.9"W

(P2024045) LL(225.4) DFO(6204984-01)

20-SEP-2024

LNМ/D. 16-AUG-2024

Reposition red starboard hand lighted pillar buoy QR,
marked V30
(See Chart 1, Qb)

from 48°31'54.6"N 123°19'44.5"W
to 48°31'54.3"N 123°19'47.6"W

(P2024032) LL(222.8) DFO(6204967-01)

16-AUG-2024

LNМ/D. 24-MAY-2024

Reposition green, red and green port bifurcation lighted pillar
buoy Fl (2+1) G
(See Chart 1, Qf)
This notice affects Electronic Navigational Chart:
CA370766

from 48°38'15.8"N 123°10'58.2"W
to 48°38'18.2"N 123°11'01.2"W

DFO(6204997-01)

24-MAY-2024

LNМ/D. 17-MAY-2024

Delete radar reflector
(See Chart 1, S4)

48°50'33.1"N 123°25'10.5"W

This notice affects Electronic Navigational Chart:
CA570239

(P2023102) LL(259) DFO(6204865-01)

24-MAY-2024

LNМ/D. 17-MAY-2024

Amend Q R to read Fl R against light
(See Chart 1, P16)

48°52'17.3"N 123°23'30.3"W

This notice affects Electronic Navigational Chart:
CA570008

(P2023107) LL(269) DFO(6204866-01)

24-MAY-2024

LNМ/D. 17-MAY-2024

Add radar reflector
(See Chart 1, S4)

48°52'17.3"N 123°23'30.3"W

This notice affects Electronic Navigational Chart: CA570008

DFO(6204866-02)

17-MAY-2024

LNМ/D. 12-APR-2024



Chart no. 3462

Delete radar reflector 48°50'13.1"N 123°27'11.5"W
(See Chart 1, S4)
This notice affects Electronic Navigational Chart: *(P2023103) LL(261) DFO(6204863-01)*
CA570239

17-MAY-2024 LNM/D. 12-APR-2024
Delete radar reflector 48°50'59.8"N 123°24'18.8"W
(See Chart 1, S4)
This notice affects Electronic Navigational Chart: *(P2023106) LL(268) DFO(6204864-01)*
CA570239

12-APR-2024 LNM/D. 16-FEB-2024
Delete radar reflector 48°39'18.0"N 123°19'24.0"W
(See Chart 1, S4)
(P2023114) LL(225.4) DFO(6204845-01)

12-APR-2024 LNM/D. 16-FEB-2024
Add radar reflector 48°42'36.9"N 123°25'54.8"W
(See Chart 1, S4)
(P2023099) LL(248.3) DFO(6204867-01)

12-APR-2024 LNM/D. 16-FEB-2024
Add radar reflector 48°41'14.5"N 123°29'21.9"W
(See Chart 1, S4)
DFO(6204872-02)

12-APR-2024 LNM/D. 16-FEB-2024
Delete radar reflector 48°43'33.5"N 123°23'12.9"W
(See Chart 1, S4)
(P2023096) LL(241) DFO(6204875-01)

12-APR-2024 LNM/D. 16-FEB-2024
Delete radar transponder beacon 48°40'33.7"N 122°42'48.4"W
(See Chart 1, S3.1)
DFO(6204915-01)

12-APR-2024 LNM/D. 16-FEB-2024



Chart no. 3462

Delete black spherical topmarks against buoy 48°32'56.4"N 122°59'22.3"W
(See Chart 1, Q9)

DFO(6204922-01)

12-APR-2024

LNM/D. 16-FEB-2024

Delete radar transponder beacon against buoy 48°45'18.5"N 122°46'30.5"W
(See Chart 1, S3.1)

DFO(6204922-03)

16-FEB-2024

LNM/D. 02-FEB-2024

Delete radar reflector
(See Chart 1, S4)

48°48'07.0"N 123°22'55.4"W

This notice affects Electronic Navigational Chart:
CA370367, CA470003, CA570239

(P2023077) LL(258) DFO(6204805-01)

02-FEB-2024

LNM/D. 15-SEP-2023

Delete pontoon
(See Chart 1, F16)

between 48°44'50.5"N 123°13'40.0"W
and 48°44'51.7"N 123°13'43.4"W

This notice affects Electronic Navigational Chart:
CA370367, CA570186

DFO(6204849-01)

02-FEB-2024

LNM/D. 15-SEP-2023

Add pontoon
(See Chart 1, F16)

between 48°44'52.2"N 123°13'41.0"W
and 48°44'50.9"N 123°13'41.8"W

This notice affects Electronic Navigational Chart:
CA370367, CA570186

DFO(6204849-03)

15-SEP-2023

LNM/D. 16-JUN-2023

Delete harbour limit and legend ESQUIMALT between 48°25'22.5"N 123°25'08.4"W
(See Chart 1, N49) and 48°25'22.5"N 123°27'57.4"W

DFO(6204801-01)

15-SEP-2023

LNM/D. 16-JUN-2023

Delete harbour limit and legend VICTORIA
(See Chart 1, N49)

between 48°23'41.1"N 123°18'16.4"W
and 48°23'03.5"N 123°28'46.7"W

This notice affects Electronic Navigational Chart:
CA570101, CA570214

DFO(6204801-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3462

15-SEP-2023

LNM/D. 16-JUN-2023

Add harbour limit and legend ESQUIMALT joining 48°23'02.3"N 123°28'46.4"W
(See Chart 1, N49)

48°23'12.6"N 123°25'12.6"W
and 48°25'19.3"N 123°25'11.0"W

DFO(6204801-03)

16-JUN-2023

LNM/D. 19-AUG-2022

Delete submarine cable
(See Chart 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470075, CA570562

joining 48°24'51.6"N 123°23'07.1"W
48°24'36.1"N 123°23'03.7"W
and 48°24'24.1"N 123°23'15.7"W

DFO(6204772-01)

19-AUG-2022

LNM/D. 22-APR-2022

Delete topmark
(See Chart No. 1, Q9)
This notice affects Electronic Navigational Chart:
CA370367

48°45'53.4"N 123°00'52.7"W

LL(US19815) DFO(6204626-01)

22-APR-2022

LNM/D. 14-JAN-2022

Delete ANCHORAGE PROHIBITED 48°24'01.3"N 123°23'19.7"W
MOUILLANGE INTERDIT

DFO(6204592-01)

22-APR-2022

LNM/D. 14-JAN-2022

Delete limit of restricted area between 48°23'03.0"N 123°28'47.0"W
(See Chart No. 1, 2.1) and 48°23'40.0"N 123°18'17.0"W

DFO(6204592-05)

14-JAN-2022

LNM/D. 09-OCT-2020

Add AIS
(See Chart No. 1, S17.2)
This notice affects Electronic Navigational Chart: CA370368

48°40'33.7"N 122°42'48.2"W

DFO(6204523-02)

09-OCT-2020

LNM/D. 18-SEP-2020



Chart no. 3462

Add submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:
CA370367

joining 48°46'46.4"N 123°03'31.7"W
48°46'44.5"N 123°03'29.9"W
48°46'39.9"N 123°03'19.3"W
48°46'35.3"N 123°03'12.5"W
48°46'22.3"N 123°03'19.9"W
48°46'01.5"N 123°03'30.0"W
48°45'52.2"N 123°03'33.0"W
48°45'40.3"N 123°03'39.9"W
and 48°45'33.4"N 123°03'51.8"W

DFO(6204378-01)

18-SEP-2020

Add outfall pipe (See Chart No. 1, L41.1)

This notice affects Electronic Navigational Chart:
CA470075, CA570562

LNM/D. 31-JUL-2020

joining 48°25'09.7"N 123°23'50.0"W
48°25'05.1"N 123°23'50.8"W
and 48°24'15.0"N 123°24'26.0"W

DFO(6204366-01)

31-JUL-2020

Delete spoil ground

(See Chart No. 1, N62.1)

This notice affects Electronic Navigational Chart: CA370367,
CA470003, CA570567

LNM/D. 29-MAY-2020

48°41'00.0"N 123°16'29.0"W

DFO(6204210-01)

29-MAY-2020

Delete submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:
CA370367, CA470003

LNM/D. 10-JAN-2020

joining 48°39'13.6"N 123°27'12.1"W
48°39'14.4"N 123°27'19.0"W
48°39'04.5"N 123°28'53.2"W
48°39'04.6"N 123°29'10.9"W
48°37'47.0"N 123°29'17.0"W
and 48°37'20.2"N 123°29'56.0"W

DFO(6204300-01)

29-MAY-2020

Add submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:
CA370367, CA470003

LNM/D. 10-JAN-2020

joining 48°39'05.9"N 123°26'57.3"W
48°39'07.2"N 123°27'25.8"W
48°39'03.2"N 123°29'12.1"W
48°37'47.7"N 123°29'20.6"W
48°37'30.7"N 123°30'10.1"W
and 48°37'20.2"N 123°29'56.0"W

DFO(6204300-02)



Chart no. 3462

10-JAN-2020

Reposition circular aeromarine radiobeacon
(See Chart No. 1, Si)

This notice affects Electronic Navigational Chart:
CA370145, CA470005

LNM/D. 21-DEC-2018

from 48°52'24.0"N 123°17'29.0"W
to 48°52'26.0"N 123°17'24.0"W

(P2019127) LL(275) DFO(6204190-01)

21-DEC-2018

Amend Victoria TIDAL INFORMATION/RENSEIGNEMENTS
SUR LES MARÉES HHW/PMS 3.4 to read 3.1

LNM/D. 16-NOV-2018

outside east border at 48-45-09.0N

DFO(6203939-01)

16-NOV-2018

Amend Fl (2+1) G 6s6m6M to read Fl(2+1) G 6s7m11M
against light

(See Chart No.1, P1)

This notice affects Electronic Navigational Chart:
CA370367, CA470003

LNM/D. 19-OCT-2018

48°41'05.2"N 123°17'37.3"W

(P2018131) LL(254.3) DFO(6203916-01)

19-OCT-2018

Add rock which covers and uncovers with drying height of 0.7 metres
(See Chart No. 1, K11)

This notice affects Electronic Navigational Chart: CA370145,
CA470005

LNM/D. 22-JUN-2018

48°52'41.8"N 123°27'41.5"W

DFO(6203880-02)

22-JUN-2018

Amend existing outfall to extend 485 metres further.

This notice affects Electronic Navigational Chart:
CA470075, CA570214

LNM/D. 02-MAR-2018

between 48°23'54.2"N 123°20'48.2"W
and 48°23'38.8"N 123°20'45.7"W

DFO(6203792-01)

22-JUN-2018

Add outfall pipe (See Chart No. 1, L41.1)

This notice affects Electronic Navigational Chart:
CA370145, CA470005

LNM/D. 02-MAR-2018

between 48°54'38.1"N 123°31'27.8"W
and 48°54'45.2"N 123°31'22.9"W

DFO(6203792-02)

02-MAR-2018

Amend Spoil Ground symbol to abandoned Spoil ground symbol
(See Chart No. 1, N62.2)

This notice affects Electronic Navigational Chart: CA470075

LNM/D. 23-FEB-2018

48°22'37.0"N 123°21'54.0"W

DFO(6203641-01)



Chart no. 3462

23-FEB-2018

Amend red starboard hand lighted pillar buoy Fl R, with BELL, marked 2 to read red starboard hand lighted pillar buoy Fl R 2.5s, with BELL, marked 2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA370368

LNМ/D. 16-FEB-2018
48°24'38.0"N 122°46'22.0"W
DFO(6203628-08)

23-FEB-2018

Amend green port hand lighted pillar buoy Fl G, marked 3 to read green port hand lighted pillar buoy Fl G 2.5s, marked 3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA370368

LNМ/D. 16-FEB-2018
48°27'01.6"N 122°47'30.9"W
DFO(6203628-09)

23-FEB-2018

Add light Fl G
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA370368

LNМ/D. 16-FEB-2018
48°32'06.3"N 122°57'52.5"W
DFO(6203630-01)

23-FEB-2018

Add black, red and black isolated danger lighted pillar buoy Fl(2) 5s, marked DR
(See Chart No. 1, Q130.4)
This notice affects Electronic Navigational Chart: CA370368

LNМ/D. 16-FEB-2018
48°32'56.4"N 122°59'22.3"W
DFO(6203630-02)

23-FEB-2018

Amend Fl to read Fl 2.5s against light 48°37'59.6"N 122°37'21.7"W
(See Chart No. 1, P1)

LNМ/D. 16-FEB-2018
DFO(6203630-03)

23-FEB-2018

Amend red starboard hand lighted pillar buoy Fl R, marked 4 to read red starboard hand lighted pillar buoy Fl R 2.5s, marked 4
(See Chart No. 1, Qf)

LNМ/D. 16-FEB-2018
48°38'20.0"N 122°40'03.0"W
DFO(6203630-04)

23-FEB-2018

Amend red starboard hand lighted pillar buoy Fl R, with BELL, marked 14, to read red starboard hand lighted pillar buoy Fl R 6s with BELL, marked 14
(See Chart No. 1, Qf)

LNМ/D. 16-FEB-2018
48°37'27.2"N 122°43'46.8"W
DFO(6203630-05)



Chart no. 3462

- 23-FEB-2018** LNM/D. 16-FEB-2018
Amend yellow lighted pillar buoy Fl Y, with RACON, marked CA to 48°45'18.3"N 122°46'30.7"W
read yellow lighted pillar buoy Fl Y 2.5s, with RACON, marked
CA *DFO(6203630-06)*
(See Chart No. 1, Q61)
- 23-FEB-2018** LNM/D. 16-FEB-2018
Amend red, green and red starboard hand bifurcation lighted pillar 48°45'14.0"N 122°43'27.6"W
buoy Fl(2+1) R to read red, green and red starboard hand
bifurcation lighted pillar buoy Fl(2+1) R 6s *DFO(6203630-07)*
(See Chart No. 1, Qi)
- 23-FEB-2018** LNM/D. 16-FEB-2018
Amend red, green and red starboard hand bifurcation lighted pillar 48°47'03.8"N 122°48'58.1"W
buoy Fl(2+1) R, with BELL, marked B to read red, green and
red starboard hand bifurcation lighted pillar buoy Fl(2+1) R *DFO(6203630-08)*
6s, with BELL, marked B
(See Chart No. 1, Qi)
- 23-FEB-2018** LNM/D. 16-FEB-2018
Add light Fl G 48°36'58.2"N 123°10'12.9"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA370367 *DFO(6203630-09)*
- 23-FEB-2018** LNM/D. 16-FEB-2018
Delete depth of 16.5 metres 48°38'15.5"N 122°40'03.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6203630-10)*
- 23-FEB-2018** LNM/D. 16-FEB-2018
Delete lighted offshore platform Fl(5)Y, marked Priv 48°38'57.0"N 123°28'32.5"W
(See Chart No. 1, P2)
This notice affects Electronic Navigational Chart: CA370367, *DFO(6203631-01)*
CA470003
- 16-FEB-2018** LNM/D. 18-AUG-2017



Chart no. 3462

Delete yellow ODAS/SADO lighted can buoy Fl (5) Y, 48°38'56.5"N 123°29'41.5"W
marked 46134
(See Chart No. 1, Q58) (P2017099) LL(251.3) DFO(6203614-01)
This notice affects Electronic Navigational Chart:
CA370367, CA470003

18-AUG-2017 LNM/D. 28-JUL-2017
Delete underwater rock of unknown depth, dangerous to surface 48°50'07.8"N 123°14'29.7"W
navigation
(See Chart No. 1, K13) DFO(6203532-14)

This notice affects Electronic Navigational Chart: CA370145,
CA470005, CA570186

18-AUG-2017 LNM/D. 28-JUL-2017
Add rock which covers and uncovers with drying height of 0.3 metres 48°50'07.8"N 123°14'29.2"W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA370145, DFO(6203532-15)
CA470005, CA570186

28-JUL-2017 LNM/D. 28-APR-2017
Replace black dot printing error with rock that covers and uncovers 48°37'12.9"N 123°02'34.1"W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA370367 DFO(6203511-02)

28-APR-2017 LNM/D. 18-NOV-2016
Amend Fl 11m 7M to read Fl 11m 6M against light 48°31'28.5"N 122°47'18.6"W
(See Chart No. 1,P1)
This notice affects Electronic Navigational Chart: CA370368 DFO(6203474-01)

18-NOV-2016 LNM/D. 10-JUN-2016
Amend red, green and red starboard bifurcation lighted pillar buoy 48°24'03.3"N 122°42'57.7"W
marked, Fl (2+1) R to read Fl (2+1) R 6s
(See Chart No. 1,Q23, Qi) DFO(6203404-01)
This notice affects Electronic Navigational Chart: CA370368

10-JUN-2016 LNM/D. 06-NOV-2015
Delete beacon marked Danger Reef 48°45'39.5"N 122°52'34.0"W
(See Chart No. 1, Q80)
This notice affects Electronic Navigational Chart: CA370368 DFO(6203281-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3462

10-JUN-2016

Add light marked Fl 2.5s 4m 4M
(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: CA370368

LNМ/D. 06-NOV-2015

48°45'39.4"N 122°52'34.2"W

DFO(6203281-02)

06-NOV-2015

Add submarine pipeline
(See Chart No. 1, L41.1)

This notice affects Electronic Navigational Chart:
CA370368

LNМ/D. 16-OCT-2015

between 48°43'05.4"N 122°54'38.3"W
and 48°42'50.6"N 122°54'38.8"W

DFO(6203122-01)

16-OCT-2015

Delete out of position white and orange cylindrical hazard buoy
(See Chart No. 1, Qs,a)

This notice affects Electronic Navigational Chart: CA370368

LNМ/D. 02-OCT-2015

48°45'37.4"N 122°52'34.2"W

DFO(6203111-01)

02-OCT-2015

Delete depth of 4.3 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370367,
CA470005

LNМ/D. 07-AUG-2015

48°49'29.0"N 123°17'50.0"W

DFO(6203093-03)

02-OCT-2015

Add depth of 3.6 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA370367,
CA470005

LNМ/D. 07-AUG-2015

48°49'29.1"N 123°17'49.7"W

DFO(6203093-04)

07-AUG-2015

Amend Fl GW 6m 7M to read Fl GW 7m 7M against light
(See Chart No. 1, 40.1)

This notice affects Electronic Navigational Chart:
CA370367, CA470003

LNМ/D. 19-JUN-2015

48°39'44.4"N 123°16'25.6"W

(P2015062) LL(225) DFO(6203060-01)

19-JUN-2015

LNМ/D. 24-APR-2015



Chart no. 3462

Replace VESSEL TRAFFIC SYSTEM SERVICES DU TRAFIC
MARITIME outside east border at 48-39-30.0N
3rd paragraph note with

48°39'30.0"N 122°34'16.7"W

DFO(6203038-05)

Limits of the Victoria or Seattle Vessel Traffic Services Zones.
Applicable vessels must participate fully on the appropriate
sector frequency reporting at all calling-in points and upon
entering or leaving these zones.

Limites des Zones de services du trafic maritime de Victoria
ou de Seattle. Les navires concernés doivent être à l'écoute
de la fréquence de secteur approprié et doivent envoyer
un compte rendu à chaque point d'appel radio, ainsi qu'à
l'entrée et à la sortie de ces zones.

24-APR-2015

LNM/D. 27-MAR-2015

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA370145

joining 48°52'27.9"N 123°17'20.7"W
48°52'35.2"N 123°17'36.5"W
48°52'48.1"N 123°17'53.3"W
48°52'52.3"N 123°18'14.1"W
48°52'45.7"N 123°18'32.0"W
and 48°52'46.4"N 123°18'46.9"W

DFO(6202988-03)

24-APR-2015

LNM/D. 27-MAR-2015

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA370367

joining 48°49'32.7"N 123°17'00.8"W
48°49'29.5"N 123°17'16.0"W
48°49'20.6"N 123°17'23.9"W
48°49'09.5"N 123°17'14.3"W
and 48°48'58.6"N 123°17'08.6"W

DFO(6202988-07)

27-MAR-2015

LNM/D. 20-MAR-2015

Add submarine pipeline
(See Chart No. 1, L41.1)
This notice affects Electronic Navigational Chart:
CA370145

between 48°53'17.4"N 123°29'39.9"W
and 48°53'15.7"N 123°28'50.9"W

DFO(6202982-02)

20-MAR-2015

LNM/D. 26-DEC-2014



Chart no. 3462

Add rock awash at chart datum 48°45'47.4"N 122°52'55.4"W
(See Chart No. 1, K12)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202974-01)*

26-DEC-2014 LNM/D. 03-OCT-2014
Add out of position white and orange cylindrical hazard buoy(See 48°45'37.4"N 122°52'34.2"W
Chart No. 1, Qs,a)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202936-01)*

03-OCT-2014 LNM/D. 12-SEP-2014
Add depth of 1.5 metres 48°27'53.5"N 123°02'58.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370367 *DFO(6202905-01)*

12-SEP-2014 LNM/D. 18-JUL-2014
Delete radio mast marked RLts 48°23'15.5"N 123°29'28.5"W
(See Chart No. 1, E28,P61.1)
DFO(6202898-01)

12-SEP-2014 LNM/D. 18-JUL-2014
Delete radio mast marked RLts 48°23'11.0"N 123°29'30.0"W
(See Chart No. 1, E28,P61.1)
DFO(6202898-02)

18-JUL-2014 LNM/D. 27-JUN-2014
Add on certain copies beacon marked "danger reef" 48°45'39.5"N 122°52'34.0"W
(See Chart No. 1, Q80)
DFO(6202883-01)

27-JUN-2014 LNM/D. 13-JUN-2014
Add submarine cable joining 48°25'54.0"N 123°26'20.0"W
(See Chart No. 1, L30.1) 48°25'52.0"N 123°26'27.0"W
and 48°24'39.0"N 123°26'59.0"W
DFO(6202866-10)

13-JUN-2014 LNM/D. 25-APR-2014



Chart no. 3462

Amend FR marked Priv to read FY marked Priv against light 48°50'33.5"N 122°43'19.5"W
(See Chart No. 1, P10.1)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202860-01)*

13-JUN-2014

LNM/D. 25-APR-2014

Amend FR marked Priv to read FY marked Priv against light 48°50'24.0"N 122°43'15.0"W
(See Chart No. 1, P10.1)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202860-02)*

13-JUN-2014

LNM/D. 25-APR-2014

Add beacon marked danger reef 48°45'39.5"N 122°52'34.0"W
(See Chart No. 1, Q80)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202861-01)*

25-APR-2014

LNM/D. 04-APR-2014

Amend FR marked Priv to read FY marked Priv against light 48°51'36.0"N 122°45'21.0"W
(See Chart No. 1, P10.1)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202828-01)*

25-APR-2014

LNM/D. 04-APR-2014

Amend FR marked Priv to read FY marked Priv against light 48°51'43.5"N 122°45'32.5"W
(See Chart No. 1, P10.1)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202828-02)*

25-APR-2014

LNM/D. 04-APR-2014

Add light F Y marked Priv 48°51'46.0"N 122°45'40.0"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202828-03)*

25-APR-2014

LNM/D. 04-APR-2014

Add light F Y marked Priv 48°51'51.5"N 122°45'51.5"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202828-04)*

04-APR-2014

LNM/D. 21-FEB-2014

Amend FR marked Priv to read FY marked Priv against light 48°49'39.5"N 122°43'09.5"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6202824-01)*



Chart no. 3462

04-APR-2014

LNМ/D. 21-FEB-2014

Amend FR marked Priv to read FY marked Priv against light
(See Chart No. 1, P1)

48°49'30.0"N 122°43'13.5"W

This notice affects Electronic Navigational Chart: CA370368

DFO(6202824-02)

21-FEB-2014

LNМ/D. 30-AUG-2013

Add Platform

48°37'20.0"N 123°29'56.0"W

(See Chart No. 1, L2)

This notice affects Electronic Navigational Chart: CA370367

DFO(6202807-01)

21-FEB-2014

LNМ/D. 30-AUG-2013

Add light Fl(5) Y(Priv)

48°37'20.0"N 123°29'56.0"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: CA370367

DFO(6202807-02)

21-FEB-2014

LNМ/D. 30-AUG-2013

Add submarine cable

joining 48°37'20.0"N 123°29'56.0"W

(See Chart No. 1, L30.1)

48°37'47.0"N 123°29'17.0"W

This notice affects Electronic Navigational Chart:

and 48°39'03.0"N 123°29'12.0"W

CA370367

DFO(6202807-03)

30-AUG-2013

LNМ/D. 31-MAY-2013

Amend Fl 6s 17m 9M to read Fl 6s 17m 7M against light

48°28'40.6"N 122°42'48.8"W

This notice affects Electronic Navigational Chart: CA370368

DFO(6202730-01)

31-MAY-2013

LNМ/D. 17-MAY-2013

Replace out of position green port hand can buoy, marked 3 with out
of position green port hand lighted pillar buoy Fl G,
marked 3 (See Chart No. 1, Qa, Qg)

48°27'00.0"N 122°47'30.0"W

DFO(6202696-01)

This notice affects Electronic Navigational Chart: CA370368

17-MAY-2013

LNМ/D. 15-FEB-2013

Add submarine pipeline

between 48°44'05.0"N 123°35'19.0"W

(See Chart No. 1, L40.1)

and 48°44'21.0"N 123°35'08.0"W

This notice affects Electronic Navigational Chart:

CA370367, CA470003, CA570237

DFO(6202693-01)



Chart no. 3462

15-FEB-2013

LNМ/D. 21-DEC-2012

Delete BELL against red starboard hand buoy
(See Chart No. 1, Qc, Qf)

48°38'17.4"N 122°40'04.6"W

This notice affects Electronic Navigational Chart: CA370368

DFO(6202677-01)

21-DEC-2012

LNМ/D. 31-AUG-2012

Delete green port hand can buoy, marked 5
(See Chart No. 1, Qg)

48°48'56.7"N 122°48'54.9"W

This notice affects Electronic Navigational Chart: CA370368

DFO(6202669-01)

31-AUG-2012

LNМ/D. 15-JUN-2012

Delete black, red and black isolated danger lighted pillar buoy Fl(2)
5s, marked BR
(See Chart No. 1, Q130.4)

48°29'36.5"N 122°44'56.5"W

DFO(6202589-01)

This notice affects Electronic Navigational Chart: CA370368

15-JUN-2012

LNМ/D. 27-APR-2012

Delete depth of 5.5 metres
(See Chart No. 1, I10)

48°24'12.6"N 123°17'06.8"W

DFO(6202566-01)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

15-JUN-2012

LNМ/D. 27-APR-2012

Add depth of 4.7 metres
(See Chart No. 1, I10)

48°24'12.5"N 123°17'06.2"W

DFO(6202566-02)

This notice affects Electronic Navigational Chart: CA470075,
CA570214

27-APR-2012

LNМ/D. 16-DEC-2011

Delete depth of 4.3 metres
(See Chart No. 1, I10)

48°35'46.6"N 122°41'12.1"W

DFO(6202553-01)

This notice affects Electronic Navigational Chart: CA370368



Chart no. 3462

27-APR-2012

LNМ/D. 16-DEC-2011

Add depth of 2.1 metres
(See Chart No. 1, I10)

48°35'46.8"N 122°41'13.0"W

DFO(6202553-02)

This notice affects Electronic Navigational Chart: CA370368

27-APR-2012

LNМ/D. 16-DEC-2011

Add depth of 9.7 metres
(See Chart No. 1, I10)

48°49'20.9"N 122°50'18.7"W

DFO(6202553-03)

This notice affects Electronic Navigational Chart: CA370368

16-DEC-2011

LNМ/D. 11-NOV-2011

Add black, red and black isolated danger lighted pillar buoy Fl(2) 5s,
marked BR
(See Chart No. 1, Q130.4)

48°29'36.5"N 122°44'56.5"W

LL(19397) DFO(6202529-01)

This notice affects Electronic Navigational Chart: CA370368

11-NOV-2011

LNМ/D. 24-DEC-2010

Delete depth out of position of 7.9 metres
(See Chart No. 1, I11)

48°31'46.0"N 122°40'44.9"W

DFO(6202521-01)

This notice affects Electronic Navigational Chart: CA370368

24-DEC-2010

LNМ/D. 12-NOV-2010

Delete GONG against buoy marked 4
(See Chart No. 1, R16)

48°26'50.3"N 122°42'24.9"W

DFO(6202381-01)

This notice affects Electronic Navigational Chart: CA370368

12-NOV-2010

LNМ/D. 01-OCT-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3462

Amend Fl(2+1) G 6s 6m 4M to read Fl(2+1) G 6s 6m 6M
against light

48°41'05.2"N 123°17'37.2"W

(P2010007) LL(254.3) DFO(6202362-01)

This notice affects Electronic Navigational Chart:
CA370367, CA470003

01-OCT-2010

Add non-dangerous wreck, depth unknown, marked PA
(See Chart No. 1, K29 and W)

LNM/D. 13-NOV-2009

48°26'19.7"N 123°00'11.3"W

DFO(6202346-01)

This notice affects Electronic Navigational Chart: CA370367

13-NOV-2009

Delete depth contour label 5
(See Chart No. 1, I30)

LNM/D. 23-OCT-2009

48°45'33.0"N 122°54'09.0"W

(USCG:USLNM13 41/09) DFO(6202156-01)

This notice affects Electronic Navigational
Chart: CA370368

13-NOV-2009

Add underwater rock of unknown depth, dangerous to
surface navigation and legend Rep(2009)
(See Chart No. 1, K13 and W)

LNM/D. 23-OCT-2009

48°45'34.8"N 122°54'10.0"W

(USCG:USLNM13 41/09) DFO(6202156-03)

This notice affects Electronic Navigational Chart:
CA370368

13-NOV-2009

Add underwater rock of unknown depth, dangerous to
surface navigation and legend Rep(2009)
(See Chart No. 1, K13 and W)

LNM/D. 23-OCT-2009

48°34'42.9"N 122°56'07.0"W

(USCG:USLNM13 41/09) DFO(6202156-04)

This notice affects Electronic Navigational Chart:
CA370368

23-OCT-2009

LNM/D. 18-SEP-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3462

Add platform
(See Chart No. 1, L2)

48°38'57.0"N 123°28'32.7"W

DFO(6202139-01)

This notice affects Electronic Navigational Chart: CA370367,
CA470003

23-OCT-2009

LNМ/D. 18-SEP-2009

Add light Fl(5) Y(Priv)
(See Chart No. 1, P1)

48°38'57.0"N 123°28'32.7"W

DFO(6202139-02)

This notice affects Electronic Navigational Chart: CA370367,
CA470003

23-OCT-2009

LNМ/D. 18-SEP-2009

Add submarine cable
(See Chart No. 1, L30.1)

between 48°38'57.0"N 123°28'32.7"W
and 48°39'03.2"N 123°29'12.2"W

DFO(6202139-06)

This notice affects Electronic Navigational Chart:
CA370367, CA470003

18-SEP-2009

LNМ/D. 15-AUG-2008

Add green port hand lighted pillar buoy Fl G 2½s,
marked 11
(See Chart No. 1, Q23 and Qg)

48°33'20.1"N 122°45'39.4"W

(USCG:USLNM13 32/09) DFO(6202124-01)

This notice affects Electronic Navigational Chart:
CA370368

15-AUG-2008

LNМ/D. 02-MAY-2008

Add light Fl G
(See Chart No. 1, P1)

48°39'57.4"N 123°23'31.8"W

(P2008076) LL(230.6) DFO(6201911-01)

This notice affects Electronic Navigational Chart:
CA370367, CA470003, CA570567

02-MAY-2008

LNМ/D. 16-NOV-2007



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3462

Reposition light Fl 24m 7M
(See Chart No. 1, P1)

from 48°35'17.4"N 123°12'04.7"W
to 48°35'18.8"N 123°12'07.2"W

(P2008020) LL(229) DFO(6201834-01)

This notice affects Electronic Navigational Chart:
CA370367

16-NOV-2007

Add depth of 7.9 metres
(See Chart No. 1, I11)

LNМ/D. 08-JUN-2007

48°31'46.0"N 122°40'44.9"W

(USCG:USLNM13 41/07) DFO(6201774-01)

This notice affects Electronic Navigational Chart:
CA370368

08-JUN-2007

Delete depth of 6.4 metres

LNМ/D. 23-MAR-2007

48°34'50.6"N 122°56'12.2"W

(USCG:USLNM13 17/07) DFO(6201690-01)

This notice affects Electronic Navigational
Chart: CA370368

08-JUN-2007

Add dangerous wreck, unknown depth, marked PA
(see Chart No.1 K28)

LNМ/D. 23-MAR-2007

48°34'49.0"N 122°56'06.0"W

(USCG:USLNM13 17/07) DFO(6201690-02)

This notice affects Electronic Navigational Chart:
CA370368

23-MAR-2007

Delete legend "HORN" against buoy

LNМ/D. 23-FEB-2007

48°38'15.4"N 123°10'57.7"W

(USCG:USLNM13 07/07) DFO(6201655-01)

This notice affects Electronic Navigational
Chart: CA370367

23-FEB-2007

LNМ/D. 05-JAN-2007



Chart no. 3462

Delete depth of 9.8 metres

48°45'48.9"N 122°57'19.1"W

(USCG:NM135006) DFO(6201652-01)

This notice affects Electronic Navigational Chart:
CA370368

23-FEB-2007

LNM/D. 05-JAN-2007

Add depth of 7.3 metres

48°45'47.2"N 122°57'21.3"W

(USCG:NM1350/06) DFO(6201652-02)

This notice affects Electronic Navigational Chart:
CA370368

23-FEB-2007

LNM/D. 05-JAN-2007

Add depth of 3.7 metres

48°41'07.3"N 122°35'59.5"W

(USCG:NM1350/06) DFO(6201652-03)

This notice affects Electronic Navigational Chart:
CA370368

23-FEB-2007

LNM/D. 05-JAN-2007

Add depth of 9.6 metres

48°46'48.7"N 122°53'58.5"W

(USCG:NM1350/06) DFO(6201652-04)

This notice affects Electronic Navigational Chart:
CA370368

05-JAN-2007

LNM/D. 07-JUL-2006

Add depth of 9.8 metres

48°33'16.6"N 123°19'59.0"W

DFO(6201636-03)

This notice affects Electronic Navigational Chart: CA370367,
CA470366

07-JUL-2006

LNM/D. 24-MAR-2006

Delete depth of 7.9 metres

48°40'04.8"N 123°20'55.6"W

DFO(6201460-02)

This notice affects Electronic Navigational Chart: CA370367,
CA470366



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3462

07-JUL-2006

Add depth of 5.7 metres

LNM/D. 24-MAR-2006

48°40'06.9"N 123°20'56.2"W

DFO(6201460-03)

This notice affects Electronic Navigational Chart: CA370367,
CA470366, CA570522

24-MAR-2006

Delete FogSig30s

LNM/D. 02-DEC-2005

48°47'20.3"N 122°58'16.9"W

DFO(6201383-01)

This notice affects Electronic Navigational Chart: CA370368

02-DEC-2005

Delete red starboard hand lighted spar buoy Fl R,
marked 2

LNM/D. 16-SEP-2005

48°31'48.3"N 122°47'06.1"W

(USCG:USLNM13 42/05) DFO(6201335-01)

02-DEC-2005

Replace beacon in general with light Fl R

LNM/D. 16-SEP-2005

48°31'51.8"N 122°47'20.5"W

(USCG:USLNM13 42/05) DFO(6201335-02)

16-SEP-2005

Replace depth of 88 metres with depth of 38 metres 48°30'18.0"N 123°16'23.0"W

LNM/D. 02-SEP-2005

DFO(6201305-01)

02-SEP-2005

Delete FogSig(2)30s

LNM/D. 05-AUG-2005

48°41'19.6"N 123°14'14.6"W

(P2005052) LL(255) DFO(6201301-01)

05-AUG-2005

Add depth of 2.1 metres

LNM/D. 28-JUN-2002

48°31'01.5"N 123°00'08.6"W

(USCG:USCG13 17/05) DFO(6201258-01)