



Chart no. 3908

3908 - Kitimat - New Chart - 15-MAR-2013 - NAD 1983

01-APR-2022

LNМ/D. 06-NOV-2020

Affix patch

54°00'00.0"N 128°41'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA570626

DFO(6204548-01)

06-NOV-2020

LNМ/D. 11-SEP-2020

Delete front range/leading light F G 9m marked Priv
(See Chart No. 1, P20.2)

53°59'48.8"N 128°40'57.0"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6204383-01)

06-NOV-2020

LNМ/D. 11-SEP-2020

Delete rear range/leading light F G 15m marked Priv with leading line
and bearings 178° - 358°
(See Chart No. 1, P20.2, Pe)

53°59'56.9"N 128°40'57.5"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6204383-02)

11-SEP-2020

LNМ/D. 28-AUG-2020

Add outfall pipe

(See Chart No. 1, L41.1)

This notice affects Electronic Navigational Chart:
CA570626

between 53°59'41.5"N 128°41'11.5"W
and 53°59'38.4"N 128°41'10.3"W

DFO(6204332-01)

27-MAR-2020

LNМ/D. 09-AUG-2019

Add foul ground

(See Chart No. 1, K31)

This notice affects Electronic Navigational Chart: CA570626

53°59'32.4"N 128°40'50.2"W

DFO(6204271-01)

09-AUG-2019

LNМ/D. 25-NOV-2016

Add pile

(See Chart No. 1, F22)

This notice affects Electronic Navigational Chart: CA570626

53°59'41.7"N 128°41'22.9"W

DFO(6204116-01)

09-AUG-2019

LNМ/D. 25-NOV-2016

Add light Fl R 10s, marked Priv
(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: CA570626

53°59'41.7"N 128°41'22.9"W

DFO(6204116-02)



Chart no. 3908

09-AUG-2019

LNМ/D. 25-NOV-2016

Add pile

53°59'40.9"N 128°41'22.8"W

(See Chart No. 1, F22)

This notice affects Electronic Navigational Chart: CA570626

DFO(6204116-03)

09-AUG-2019

LNМ/D. 25-NOV-2016

Add pile

53°59'40.1"N 128°41'22.7"W

(See Chart No. 1, F22)

This notice affects Electronic Navigational Chart: CA570626

DFO(6204116-04)

09-AUG-2019

LNМ/D. 25-NOV-2016

Add pile

53°59'39.3"N 128°41'22.6"W

(See Chart No. 1, F22)

This notice affects Electronic Navigational Chart: CA570626

DFO(6204116-05)

09-AUG-2019

LNМ/D. 25-NOV-2016

Add light Fl R 5s, marked Priv

53°59'39.3"N 128°41'22.6"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: CA570626

DFO(6204116-06)

25-NOV-2016

LNМ/D. 04-NOV-2016

Add obstruction with known depth of 31.0 metres

53°59'29.6"N 128°40'44.5"W

(See Chart No. 1, K41)

This notice affects Electronic Navigational Chart: CA570626

DFO(6203407-01)

25-NOV-2016

LNМ/D. 04-NOV-2016

Add obstruction with known depth of 53.0 metres

53°59'26.4"N 128°40'44.8"W

(See Chart No. 1, K41)

This notice affects Electronic Navigational Chart: CA570626

DFO(6203407-02)

04-NOV-2016

LNМ/D. 10-JUN-2016

Delete red starboard hand spar buoy, marked Priv

53°59'49.3"N 128°41'16.9"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart: CA570626

DFO(6203393-01)

04-NOV-2016

LNМ/D. 10-JUN-2016



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3908

Delete red starboard hand lighted pillar buoy QR, marked Priv 53°59'37.6"N 128°41'15.0"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6203393-02)*

24-MAY-2013

Add black colour fill to private green port hand lighted pillar buoy Fl 53°59'30.3"N 128°41'29.5"W
G, Priv
(See Chart No. 1, Qg) *DFO(6202694-01)*

This notice affects Electronic Navigational Chart: CA570626

24-MAY-2013

Amend Y to read R against buoy 53°59'35.7"N 128°41'22.4"W
This notice affects Electronic Navigational Chart: CA570626
DFO(6202694-02)

24-MAY-2013

Add red colour fill to private red starboard hand lighted pillar buoy Fl 53°59'35.7"N 128°41'22.4"W
R, Priv
(See Chart No. 1, Qf) *DFO(6202694-03)*

This notice affects Electronic Navigational Chart: CA570626

24-MAY-2013

Amend Y to read R against buoy 53°59'37.6"N 128°41'15.0"W
This notice affects Electronic Navigational Chart: CA570626
DFO(6202694-04)

24-MAY-2013

Add red colour fill to private red starboard hand lighted pillar buoy Q 53°59'37.6"N 128°41'15.0"W
R, Priv
(See Chart No. 1, Qf) *DFO(6202694-05)*

This notice affects Electronic Navigational Chart: CA570626

3908 - Kitimat Harbour - New Chart - 15-MAR-2013 - NAD 1983

01-APR-2022

LNMD/06-NOV-2020



Chart no. 3908

Affix patch

54°00'00.0"N 128°41'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA570626

DFO(6204548-02)

06-NOV-2020

LNМ/D. 11-SEP-2020

Delete front range/leading light F G marked Priv
(See Chart No. 1, P20.2)

53°59'48.8"N 128°40'57.0"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6204383-01)

06-NOV-2020

LNМ/D. 11-SEP-2020

Delete rear range/leading light F G marked Priv with leading line and
bearings 178° - 358°
(See Chart No. 1, P20.2, Pe)

53°59'56.9"N 128°40'57.5"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6204383-02)

11-SEP-2020

LNМ/D. 28-AUG-2020

Add outfall pipe

(See Chart No. 1, L41.1)

This notice affects Electronic Navigational Chart:
CA570626

between 53°59'41.5"N 128°41'11.5"W
and 53°59'38.4"N 128°41'10.3"W

DFO(6204332-01)

28-AUG-2020

LNМ/D. 27-MAR-2020

Delete obstruction with known depth of 38 metres
(See Chart No. 1, K41)

53°58'28.9"N 128°39'25.1"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6204357-01)

28-AUG-2020

LNМ/D. 27-MAR-2020

Delete submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:
CA570626

joining 53°58'28.2"N 128°39'24.7"W
53°58'23.6"N 128°39'21.9"W
53°58'22.4"N 128°39'19.3"W
and 53°58'23.5"N 128°39'06.8"W

DFO(6204357-02)

28-AUG-2020

LNМ/D. 27-MAR-2020



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3908

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA570626

joining 53°58'24.9"N 128°39'25.8"W
53°58'27.2"N 128°39'24.7"W
53°58'23.6"N 128°39'21.9"W
53°58'22.4"N 128°39'19.3"W
and 53°58'23.5"N 128°39'06.8"W

DFO(6204357-03)

28-AUG-2020 LNM/D. 27-MAR-2020

Add obstruction with known depth of 65 metres
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA570626

53°58'24.2"N 128°39'25.9"W
DFO(6204357-04)

27-MAR-2020 LNM/D. 09-AUG-2019

Add orange and white mooring lighted can buoy Fl Y, marked priv 53°58'40.0"N 128°41'47.0"W
(See Chart No. 1, Q41)
This notice affects Electronic Navigational Chart: CA570626

DFO(6204244-01)

27-MAR-2020 LNM/D. 09-AUG-2019

Add foul ground
(See Chart No. 1, K31)
This notice affects Electronic Navigational Chart: CA570626

53°59'32.4"N 128°40'50.2"W
DFO(6204271-01)

09-AUG-2019 LNM/D. 25-NOV-2016

Delete spoil ground
(See Chart No. 1, N62.1)
This notice affects Electronic Navigational Chart: CA370603,
CA570626

53°57'59.0"N 128°41'29.9"W
DFO(6204085-01)

09-AUG-2019 LNM/D. 25-NOV-2016

Add Spoil Ground / Dépôt de déblais
(See Chart No. 1, N62.1)
This notice affects Electronic Navigational Chart:
CA370603, CA570626

joining 53°58'19.1"N 128°41'09.8"W
53°57'17.5"N 128°41'27.5"W
53°57'12.2"N 128°40'35.9"W
53°58'13.9"N 128°40'18.2"W
and 53°58'19.1"N 128°41'09.8"W

DFO(6204085-02)

09-AUG-2019 LNM/D. 25-NOV-2016



Chart no. 3908

Add pile 53°59'41.7"N 128°41'22.9"W
(See Chart No. 1, F22)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6204116-01)*

09-AUG-2019 LNM/D. 25-NOV-2016
Add light Fl R 10s, marked Priv 53°59'41.7"N 128°41'22.9"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6204116-02)*

09-AUG-2019 LNM/D. 25-NOV-2016
Add pile 53°59'40.9"N 128°41'22.8"W
(See Chart No. 1, F22)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6204116-03)*

09-AUG-2019 LNM/D. 25-NOV-2016
Add pile 53°59'40.1"N 128°41'22.7"W
(See Chart No. 1, F22)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6204116-04)*

09-AUG-2019 LNM/D. 25-NOV-2016
Add pile 53°59'39.3"N 128°41'22.6"W
(See Chart No. 1, F22)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6204116-05)*

09-AUG-2019 LNM/D. 25-NOV-2016
Add light Fl R 5s, marked Priv 53°59'39.3"N 128°41'22.6"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6204116-06)*

25-NOV-2016 LNM/D. 04-NOV-2016
Add obstruction with known depth of 31.0 metres 53°59'29.6"N 128°40'44.5"W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6203407-01)*

25-NOV-2016 LNM/D. 04-NOV-2016
Add obstruction with known depth of 53.0 metres 53°59'26.4"N 128°40'44.8"W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA570626 *DFO(6203407-02)*



Chart no. 3908

04-NOV-2016

LNМ/D. 10-JUN-2016

Delete red starboard hand spar buoy, marked Priv
(See Chart No. 1, Qf)

53°59'49.3"N 128°41'16.9"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6203393-01)

04-NOV-2016

LNМ/D. 10-JUN-2016

Delete red starboard hand lighted pillar buoy QR, marked Priv
(See Chart No. 1, Qf)

53°59'37.6"N 128°41'15.0"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6203393-02)

10-JUN-2016

LNМ/D. 27-MAY-2016

Add submarine cable

joining 53°58'23.4"N 128°39'06.7"W

(See Chart No. 1, L30.1)

53°58'22.3"N 128°39'19.0"W

This notice affects Electronic Navigational Chart:
CA570626

53°58'23.4"N 128°39'21.8"W

and 53°58'28.8"N 128°39'25.2"W

DFO(6203280-01)

10-JUN-2016

LNМ/D. 27-MAY-2016

Add obstruction with known depth of 38 metres
(See Chart No. 1, K41)

53°58'28.8"N 128°39'25.2"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6203280-02)

27-MAY-2016

LNМ/D. 19-FEB-2016

Amend Adjoining Chart/Carte adjacente 3743 to read
Adjoining Chart/Carte adjacente 3977
(See Chart No. 1, A20)

outside south border at 128-44-30.0W

DFO(6203270-01)

19-FEB-2016

LNМ/D. 07-FEB-2014

Amend Fl 6s 7m to read Fl R 8m against light
(See Chart No. 1, P1)

53°54'23.6"N 128°42'38.4"W

This notice affects Electronic Navigational Chart: (P2016013) LL(654.9) DFO(6203201-01)
CA370603, CA570626

07-FEB-2014

LNМ/D. 17-JAN-2014

Add OrW against cylindrical mooring buoy marked Priv
(See Chart No. 1, Q40)

53°54'20.2"N 128°41'04.2"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6202795-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3908

17-JAN-2014

LN/D. 24-MAY-2013

Add cylindrical mooring buoy marked Priv
(See Chart No. 1, Q40)

53°54'20.2"N 128°41'04.2"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6202785-01)

24-MAY-2013

Add black colour fill to private green port hand lighted pillar buoy Fl
G, Priv
(See Chart No. 1, Qg)

53°59'30.3"N 128°41'29.5"W

DFO(6202694-01)

This notice affects Electronic Navigational Chart: CA570626

24-MAY-2013

Amend Y to read R against buoy

53°59'35.7"N 128°41'22.4"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6202694-02)

24-MAY-2013

Add red colour fill to private red starboard hand lighted pillar buoy Fl
R, Priv
(See Chart No. 1, Qf)

53°59'35.7"N 128°41'22.4"W

DFO(6202694-03)

This notice affects Electronic Navigational Chart: CA570626

24-MAY-2013

Amend Y to read R against buoy

53°59'37.6"N 128°41'15.0"W

This notice affects Electronic Navigational Chart: CA570626

DFO(6202694-04)

24-MAY-2013

Add red colour fill to private red starboard hand lighted pillar buoy Q
R, Priv
(See Chart No. 1, Qf)

53°59'37.6"N 128°41'15.0"W

DFO(6202694-05)

This notice affects Electronic Navigational Chart: CA570626