



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3938

3938 - Bella Bella - New Edition - 15-APR-2016 - World Geodetic System 1984

17-FEB-2023

LNМ/D. 15-MAY-2020

Add submarine cable (See Chart No. 1, L30.1)

between 52°09'36.2"N 128°08'00.0"W

This notice affects Electronic Navigational Chart:

and 52°09'42.7"N 128°08'32.7"W

CA470324, CA570566

DFO(6204697-07)

12-MAY-2017

Amend green port hand pillar buoy, marked E19 to read
green port hand lighted pillar buoy Fl G, marked
E19

52°10'22.9"N 128°08'20.9"W

(See Chart No. 1, Qg)

(P2017015) LL(610.5) DFO(6203487-01)

This notice affects Electronic Navigational Chart:

CA470324, CA570566

3938 - Queens Sound to/a Seaforth Channel - New Edition - 15-APR-2016 - World Geodetic System 1984

11-AUG-2023

LNМ/D. 17-FEB-2023

Delete depth of 5.4 metres 52°10'02.4"N 128°05'04.0"W

(See Chart 1, I10)

DFO(6204791-01)

11-AUG-2023

LNМ/D. 17-FEB-2023

Add rock which covers and uncovers with drying height of 0.3 metre 52°10'02.1"N 128°05'04.7"W

(See Chart 1, K11)

DFO(6204791-02)

11-AUG-2023

LNМ/D. 17-FEB-2023

Delete depth of 13.9 metres 52°10'06.8"N 128°04'47.5"W

(See Chart 1, I10)

DFO(6204792-01)

11-AUG-2023

LNМ/D. 17-FEB-2023

Add depth of 4.5 metres 52°10'06.9"N 128°04'45.8"W

(See Chart 1, I10)

DFO(6204792-02)



Chart no. 3938

11-AUG-2023

LNМ/D. 17-FEB-2023

Delete depth of 6.1 metres
(See Chart 1, I10)

52°09'10.5"N 128°05'20.3"W

This notice affects Electronic Navigational Chart: CA570327

DFO(6204792-03)

11-AUG-2023

LNМ/D. 17-FEB-2023

Add depth of 4.6 metres
(See Chart 1, I10)

52°09'10.4"N 128°05'20.5"W

This notice affects Electronic Navigational Chart: CA570327

DFO(6204792-04)

11-AUG-2023

LNМ/D. 17-FEB-2023

Add depth of 4.1 metres
(See Chart 1, I10)

52°08'58.8"N 128°05'12.8"W

This notice affects Electronic Navigational Chart: CA570327

DFO(6204792-05)

11-AUG-2023

LNМ/D. 17-FEB-2023

Add depth of 14.5 metres
(See Chart 1, I10)

52°10'06.9"N 128°04'51.3"W

DFO(6204792-07)

11-AUG-2023

LNМ/D. 17-FEB-2023

Add depth of 1.2 metres
(See Chart 1, I10)

52°09'00.5"N 128°05'26.4"W

This notice affects Electronic Navigational Chart: CA570327

DFO(6204792-08)

17-FEB-2023

LNМ/D. 15-MAY-2020

Add submarine cable (See Chart No. 1, L30.1)

joining 52°17'28.0"N 128°26'17.4"W

This notice affects Electronic Navigational Chart:

52°17'05.3"N 128°25'53.3"W

CA470568, CA470577, CA470726, CA570435, CA570450

52°16'23.2"N 128°25'34.9"W

52°16'04.8"N 128°24'25.8"W

and 52°16'09.1"N 128°24'23.5"W

DFO(6204697-03)

17-FEB-2023

LNМ/D. 15-MAY-2020



Chart no. 3938

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470322, CA470568, CA570460

joining 52°16'23.2"N 128°25'34.9"W
52°16'24.2"N 128°25'41.4"W
52°16'03.7"N 128°29'12.9"W
52°16'01.1"N 128°32'02.4"W
52°15'03.2"N 128°39'28.7"W
52°15'34.4"N 128°40'12.2"W
52°15'53.9"N 128°42'33.0"W
and 52°15'43.7"N 128°43'10.4"W

DFO(6204697-04)

17-FEB-2023

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA470568, CA470569, CA570435

LNLM/D. 15-MAY-2020
joining 52°16'08.9"N 128°24'24.0"W
52°15'58.3"N 128°24'00.5"W
52°15'37.0"N 128°24'04.8"W
52°15'17.4"N 128°21'50.7"W
52°14'42.2"N 128°20'40.6"W
52°14'53.6"N 128°16'19.4"W
52°14'16.5"N 128°14'25.6"W
52°13'41.7"N 128°14'08.0"W
52°13'33.5"N 128°13'38.6"W
52°13'26.5"N 128°09'35.7"W
52°11'14.3"N 128°06'27.4"W
52°11'01.5"N 128°06'39.3"W
and 52°11'06.1"N 128°06'43.2"W

DFO(6204697-05)

17-FEB-2023

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324

LNLM/D. 15-MAY-2020
joining 52°11'06.6"N 128°06'43.7"W
52°10'59.4"N 128°06'42.2"W
52°09'55.1"N 128°07'56.7"W
52°09'36.0"N 128°07'31.8"W
52°09'19.8"N 128°07'31.8"W
and 52°09'13.1"N 128°07'24.7"W

DFO(6204697-06)

17-FEB-2023

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA570566

LNLM/D. 15-MAY-2020
joining 52°09'19.9"N 128°07'31.8"W
52°09'34.2"N 128°07'55.1"W
and 52°09'42.5"N 128°08'33.0"W

DFO(6204697-07)



Chart no. 3938

17-FEB-2023

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA570327

LNLM/D. 15-MAY-2020
joining 52°09'36.0"N 128°07'31.9"W
52°09'49.5"N 128°07'22.1"W
52°09'42.4"N 128°06'02.8"W
52°09'20.8"N 128°05'39.1"W
52°09'02.9"N 128°05'28.3"W
and 52°09'01.3"N 128°05'30.9"W

DFO(6204697-08)

17-FEB-2023

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470318, CA470324

LNLM/D. 15-MAY-2020
joining 52°09'11.6"N 128°07'45.9"W
52°09'08.8"N 128°07'58.0"W
52°08'55.0"N 128°08'11.4"W
52°06'57.3"N 128°07'40.2"W
52°06'31.0"N 128°07'51.1"W
52°05'28.8"N 128°07'29.9"W
52°04'45.2"N 128°05'20.4"W
and 52°04'45.9"N 128°05'00.0"W

DFO(6204697-09)

15-MAY-2020

Replace red starboard hand conical buoy, marked E34 with yellow
and black south cardinal can buoy, marked ED
(See Chart No. 1, Qf, Q130.3)

LNLM/D. 06-DEC-2019
52°12'50.3"N 128°09'27.0"W
(P2019136) DFO(6204230-01)

This notice affects Electronic Navigational Chart: CA470324

15-MAY-2020

Delete depth of 14.0 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569

LNLM/D. 06-DEC-2019
52°05'16.7"N 128°17'35.0"W
DFO(6204299-01)

15-MAY-2020

Add depth of 3.9 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569

LNLM/D. 06-DEC-2019
52°05'16.2"N 128°17'32.7"W
DFO(6204299-02)

15-MAY-2020

LNLM/D. 06-DEC-2019



Chart no. 3938

Delete depth of 9 metres, Rep (2018) 52°09'03.0"N 128°05'24.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324, DFO(6204323-01)
CA570327

15-MAY-2020 LNM/D. 06-DEC-2019
Add depth of 9 metres 52°09'03.6"N 128°05'23.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324, DFO(6204323-02)
CA570327

06-DEC-2019 LNM/D. 04-OCT-2019
Amend Fl 6s5m5M to read Fl 6s8m5M against light 52°14'18.0"N 128°16'37.1"W
(See Chart No. 1, P1) (P2019104) LL(613) DFO(6204150-01)
This notice affects Electronic Navigational Chart:
CA470569

06-DEC-2019 LNM/D. 04-OCT-2019
Add depth of 0.9 metre 52°06'31.9"N 128°22'25.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470568 DFO(6204155-01)

06-DEC-2019 LNM/D. 04-OCT-2019
Delete depth of 1.9 metres 52°06'31.9"N 128°22'25.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470568 DFO(6204155-02)

06-DEC-2019 LNM/D. 04-OCT-2019
Delete depth of 6.8 metres 52°09'02.4"N 128°22'00.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470568 DFO(6204155-03)

06-DEC-2019 LNM/D. 04-OCT-2019
Add depth of 3.1 metres 52°09'02.4"N 128°22'00.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470568 DFO(6204155-05)

06-DEC-2019 LNM/D. 04-OCT-2019



Chart no. 3938

Delete depth of 8.3 metres 52°03'20.0"N 128°12'46.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569 *DFO(6204199-01)*

06-DEC-2019 LNM/D. 04-OCT-2019
Add depth of 2.1 metres 52°03'20.3"N 128°12'45.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569 *DFO(6204199-02)*

06-DEC-2019 LNM/D. 04-OCT-2019
Delete depth of 5.9 metres 52°04'20.7"N 128°13'52.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569 *DFO(6204199-03)*

06-DEC-2019 LNM/D. 04-OCT-2019
Add depth of 5.0 metres 52°04'21.3"N 128°13'52.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569 *DFO(6204199-04)*

06-DEC-2019 LNM/D. 04-OCT-2019
Delete depth of 28.3 metres 52°04'17.0"N 128°13'42.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569 *DFO(6204199-05)*

06-DEC-2019 LNM/D. 04-OCT-2019
Add depth of 4.6 metres 52°04'18.4"N 128°13'41.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569 *DFO(6204199-06)*

06-DEC-2019 LNM/D. 04-OCT-2019
Delete depth of 20.2 metres 52°02'32.7"N 128°15'23.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6204199-07)*

06-DEC-2019 LNM/D. 04-OCT-2019
Add depth of 4.7 metres 52°02'34.2"N 128°15'22.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6204199-08)*



Chart no. 3938

- 06-DEC-2019** LNM/D. 04-OCT-2019
Delete depth of 9.7 metres 52°02'38.6"N 128°15'24.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6204199-09)*
- 06-DEC-2019** LNM/D. 04-OCT-2019
Add depth of 2.6 metres 52°02'37.8"N 128°15'24.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6204199-10)*
- 06-DEC-2019** LNM/D. 04-OCT-2019
Add depth of 2.8 metres 52°03'47.4"N 128°15'41.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6204199-11)*
- 06-DEC-2019** LNM/D. 04-OCT-2019
Add depth of 1.7 metres 52°03'18.6"N 128°10'49.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6204200-01)*
- 06-DEC-2019** LNM/D. 04-OCT-2019
Delete depth of 6.3 metres 52°08'07.0"N 128°14'47.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569 *DFO(6204201-01)*
- 06-DEC-2019** LNM/D. 04-OCT-2019
Add depth of 2.6 metres 52°08'05.7"N 128°14'46.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470569 *DFO(6204201-02)*
- 04-OCT-2019** LNM/D. 17-AUG-2018
Affix patch 52°02'11.0"N 128°20'00.0"W
[PDF](#)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6204151-01)*
- 17-AUG-2018** LNM/D. 04-MAY-2018



Chart no. 3938

Add depth of 9.0 metres, Rep (2018) 52°09'03.1"N 128°05'24.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324, DFO(6203825-01)
CA570327

17-AUG-2018 LNM/D. 04-MAY-2018
Delete depth of 12.8 metres 52°09'03.0"N 128°05'22.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324, DFO(6203825-02)
CA570327

17-AUG-2018 LNM/D. 04-MAY-2018
Delete depth of 12.8 metres 52°03'14.0"N 128°08'18.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 DFO(6203837-01)

17-AUG-2018 LNM/D. 04-MAY-2018
Add depth of 3.8 metres 52°03'14.8"N 128°08'19.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 DFO(6203837-02)

17-AUG-2018 LNM/D. 04-MAY-2018
Add depth of 5.5 metres 52°03'19.1"N 128°08'22.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 DFO(6203837-03)

04-MAY-2018 LNM/D. 23-JUN-2017
Add depth of 0.3 metres 52°16'46.1"N 128°10'22.3"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470087 DFO(6203721-02)

23-JUN-2017 LNM/D. 12-MAY-2017
Amend sector light Oc WR white from 142°30' to 206°30', 52°11'06.5"N 128°06'42.0"W
red from 206°30' to 339°, white from 339° to 39°30'
to read sector light Oc WR 12m7M white from (P2017027) LL(611) DFO(6203504-01)
142°30' to 206°30', red from 206°30' to 336°30',
white from 336°30' to 39°30'
(see Chart No. 1, P40.1)
This notice affects Electronic Navigational Chart:
CA470324



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3938

12-MAY-2017

Amend green port hand pillar buoy, marked E19 to read
green port hand lighted pillar buoy Fl G, marked
E19

(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:
CA470324, CA570566

52°10'22.9"N 128°08'20.9"W

(P2017015) LL(610.5) DFO(6203487-01)