



Chart no. 3939

**3939 - Fisher Channel to/à Seaforth Channel and/et Dean Channel - New Edition - 01-
AUG-2014 - World Geodetic System 1984**

20-OCT-2023

LNМ/D. 11-AUG-2023

Add submarine cable joining 52°02'36.0"N 127°55'26.8"W
(See Chart 1, L30.1) 52°02'46.6"N 127°55'21.8"W
52°03'04.7"N 127°55'18.9"W
52°03'26.3"N 127°55'30.9"W
52°03'32.6"N 127°55'36.1"W
52°03'41.7"N 127°55'40.3"W
52°03'52.5"N 127°55'55.7"W
52°03'52.6"N 127°56'08.2"W
52°03'54.8"N 127°56'30.3"W
52°03'55.2"N 127°56'40.9"W
52°03'54.9"N 127°57'02.4"W
and 52°03'53.9"N 127°57'08.3"W

DFO(6204804-08)

11-AUG-2023

LNМ/D. 17-FEB-2023

Delete depth of 5.4 metres 52°10'02.4"N 128°05'04.0"W
(See Chart 1, I10)

DFO(6204791-01)

11-AUG-2023

LNМ/D. 17-FEB-2023

Add rock which covers and uncovers with drying height of 0.3 metre 52°10'02.1"N 128°05'04.7"W
(See Chart 1, K11)

DFO(6204791-02)

11-AUG-2023

LNМ/D. 17-FEB-2023

Delete depth of 13.9 metres 52°10'06.8"N 128°04'47.5"W
(See Chart 1, I10)

DFO(6204792-01)

11-AUG-2023

LNМ/D. 17-FEB-2023

Add depth of 4.5 metres 52°10'06.9"N 128°04'45.8"W
(See Chart 1, I10)

DFO(6204792-02)

11-AUG-2023

LNМ/D. 17-FEB-2023



Chart no. 3939

Delete depth of 6.1 metres 52°09'10.5"N 128°05'20.3"W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA570327 *DFO(6204792-03)*

11-AUG-2023 LNM/D. 17-FEB-2023
Add depth of 4.6 metres 52°09'10.4"N 128°05'20.5"W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA570327 *DFO(6204792-04)*

11-AUG-2023 LNM/D. 17-FEB-2023
Add depth of 4.1 metres 52°08'58.8"N 128°05'12.8"W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA570327 *DFO(6204792-05)*

11-AUG-2023 LNM/D. 17-FEB-2023
Add depth of 14.5 metres 52°10'06.9"N 128°04'51.3"W
(See Chart 1, I10)
DFO(6204792-07)

11-AUG-2023 LNM/D. 17-FEB-2023
Add depth of 1.2 metres 52°09'00.5"N 128°05'26.4"W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA570327 *DFO(6204792-08)*

17-FEB-2023 LNM/D. 30-SEP-2022
Add submarine cable (See Chart No. 1, L30.1) joining 52°13'35.0"N 128°13'48.0"W
This notice affects Electronic Navigational Chart: 52°13'26.5"N 128°09'35.7"W
CA470324, CA470568, CA470569, CA570435 52°11'14.3"N 128°06'27.4"W
52°11'01.5"N 128°06'39.3"W
and 52°11'06.1"N 128°06'43.2"W
DFO(6204697-05)

17-FEB-2023 LNM/D. 30-SEP-2022



Chart no. 3939

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324

joining 52°11'06.6"N 128°06'43.7"W
52°10'59.4"N 128°06'42.2"W
52°09'55.1"N 128°07'56.7"W
52°09'36.0"N 128°07'31.8"W
52°09'19.8"N 128°07'31.8"W
and 52°09'13.1"N 128°07'24.7"W

DFO(6204697-06)

17-FEB-2023

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA570566

LNLM/D. 30-SEP-2022
joining 52°09'19.9"N 128°07'31.8"W
52°09'34.2"N 128°07'55.1"W
and 52°09'42.5"N 128°08'33.0"W

DFO(6204697-07)

17-FEB-2023

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA570327

LNLM/D. 30-SEP-2022
joining 52°09'36.0"N 128°07'31.9"W
52°09'49.5"N 128°07'22.1"W
52°09'42.4"N 128°06'02.8"W
52°09'20.8"N 128°05'39.1"W
52°09'02.9"N 128°05'28.3"W
and 52°09'01.3"N 128°05'30.9"W

DFO(6204697-08)

17-FEB-2023

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470318, CA470324

LNLM/D. 30-SEP-2022
joining 52°09'11.6"N 128°07'46.0"W
52°08'55.0"N 128°08'11.4"W
52°06'57.3"N 128°07'40.2"W
52°06'31.0"N 128°07'51.1"W
52°05'28.8"N 128°07'29.9"W
52°04'45.2"N 128°05'20.4"W
52°04'47.2"N 128°04'09.3"W
52°04'28.1"N 128°03'02.1"W
52°04'43.4"N 127°59'28.9"W
52°04'04.4"N 127°57'16.5"W
and 52°03'48.0"N 127°57'11.6"W

DFO(6204697-09)

30-SEP-2022

LNLM/D. 15-MAY-2020



Chart no. 3939

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470318, CA470324

joining 52°16'04.4"N 127°47'24.9"W
52°15'58.9"N 127°47'24.6"W
52°15'39.8"N 127°47'20.7"W
52°15'01.6"N 127°47'31.3"W
52°13'50.9"N 127°48'23.7"W
52°09'41.1"N 127°51'53.7"W
52°07'35.6"N 127°52'38.1"W
52°06'33.9"N 127°54'06.3"W
52°04'47.5"N 127°55'15.5"W
52°04'29.7"N 127°55'35.7"W
52°04'13.1"N 127°56'05.5"W
52°04'01.3"N 127°57'04.4"W
and 52°03'48.1"N 127°57'11.5"W

DFO(6204641-04)

30-SEP-2022

LNLM/D. 15-MAY-2020

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA570326

joining 52°18'42.0"N 127°45'19.0"W
52°18'09.6"N 127°45'21.1"W
52°16'25.0"N 127°46'27.8"W
52°15'58.7"N 127°46'50.2"W
52°15'52.9"N 127°47'04.6"W
52°15'53.5"N 127°47'17.6"W
and 52°15'56.0"N 127°47'23.0"W

DFO(6204641-05)

30-SEP-2022

LNLM/D. 15-MAY-2020

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA370454, CA470324, CA570458

joining 52°15'55.9"N 127°47'22.8"W
52°15'41.3"N 127°46'47.7"W
52°15'36.1"N 127°45'11.0"W
52°15'48.4"N 127°42'46.2"W
52°16'49.4"N 127°39'57.3"W
52°16'30.8"N 127°37'57.4"W
52°17'13.0"N 127°35'39.0"W
and 52°17'23.6"N 127°35'24.0"W

DFO(6204641-07)

15-MAY-2020

LNLM/D. 15-NOV-2019

Replace red starboard hand conical buoy, marked E34 with yellow
and black south cardinal can buoy, marked ED
(See Chart No. 1, Qf, Q130.3)

52°12'50.3"N 128°09'27.0"W
(P2019136) DFO(6204230-01)

This notice affects Electronic Navigational Chart: CA470324



Chart no. 3939

15-MAY-2020

Delete depth of 9 metres, Rep (2018)
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470324,
CA570327

LNМ/D. 15-NOV-2019

52°09'03.0"N 128°05'24.0"W

DFO(6204323-01)

15-MAY-2020

Add depth of 9 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA470324,
CA570327

LNМ/D. 15-NOV-2019

52°09'03.6"N 128°05'23.1"W

DFO(6204323-02)

15-NOV-2019

Add light Fl R 6s6m3M

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA470324

LNМ/D. 23-NOV-2018

52°14'53.5"N 127°54'04.9"W

(P2019094) LL(594.8) DFO(6204137-01)

15-NOV-2019

Add light Fl(3)12s7m3M

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA470087

LNМ/D. 23-NOV-2018

52°18'31.6"N 127°56'37.2"W

(P2019095) LL(604.2) DFO(6204142-01)

15-NOV-2019

Amend Fl 6s4m5M to read Fl 6s8m5M against light (See
Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA470318

LNМ/D. 23-NOV-2018

52°07'33.8"N 127°53'26.2"W

(P2019100) LL(594) DFO(6204146-01)

15-NOV-2019

Delete port hand daybeacon

(See Chart No. 1, P1, Qt)

This notice affects Electronic Navigational Chart: CA470324

LNМ/D. 23-NOV-2018

52°11'11.7"N 127°53'03.8"W

(P2019101) DFO(6204147-01)

15-NOV-2019

LNМ/D. 23-NOV-2018



Chart no. 3939

Add light Fl G 6s 52°11'11.7"N 127°53'03.8"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: *(P2019101) LL(594.5) DFO(6204147-02)*
CA470324

15-NOV-2019 LNM/D. 23-NOV-2018
Amend Fl to read Fl 6s against the light (See Chart No.1,
P1) 52°17'42.1"N 127°56'41.9"W
This notice affects Electronic Navigational Chart: *(P2019116) LL(604) DFO(6204168-01)*
CA470087

17-AUG-2018 LNM/D. 04-MAY-2018
Delete reported anchorage 52°17'29.5"N 127°45'15.5"W
(See Chart No. 1, N10)
This notice affects Electronic Navigational Chart: CA470324 *DFO(6203814-01)*

17-AUG-2018 LNM/D. 04-MAY-2018
Add Booms/Pannes 52°17'26.0"N 127°45'15.0"W
This notice affects Electronic Navigational Chart: CA470324 *DFO(6203814-04)*

17-AUG-2018 LNM/D. 04-MAY-2018
Add depth of 9.0 metres, Rep (2018) 52°09'03.1"N 128°05'24.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324, *DFO(6203825-01)*
CA570327

17-AUG-2018 LNM/D. 04-MAY-2018
Delete depth of 12.8 metres 52°09'03.0"N 128°05'22.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324, *DFO(6203825-02)*
CA570327

17-AUG-2018 LNM/D. 04-MAY-2018
Delete depth of 12.8 metres 52°03'14.0"N 128°08'18.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6203837-01)*

17-AUG-2018 LNM/D. 04-MAY-2018



Chart no. 3939

- Add depth of 3.8 metres 52°03'14.8"N 128°08'19.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6203837-02)*
- 17-AUG-2018** LNM/D. 04-MAY-2018
Add depth of 5.5 metres 52°03'19.1"N 128°08'22.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470387 *DFO(6203837-03)*
- 04-MAY-2018** LNM/D. 23-JUN-2017
Add depth of 0.3 metres 52°16'46.1"N 128°10'22.3"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470087 *DFO(6203721-02)*
- 23-JUN-2017** LNM/D. 12-MAY-2017
Amend sector light Oc WR white from 142°30' to 206°30', 52°11'06.5"N 128°06'42.0"W
red from 206°30' to 339°, white from 339° to 39°30'
to read sector light Oc WR 12m7M white from *(P2017027) LL(611) DFO(6203504-01)*
142°30' to 206°30', red from 206°30' to 336°30',
white from 336°30' to 39°30'
(see Chart No. 1, P40.1)
This notice affects Electronic Navigational Chart:
CA470324
- 12-MAY-2017** LNM/D. 16-DEC-2016
Amend out of position green port hand pillar buoy, 52°10'22.9"N 128°08'20.9"W
marked E19 to read out of position green port
hand lighted pillar buoy Fl G, marked E19 *(P2017015) LL(610.5) DFO(6203487-01)*
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA470324, CA570566
- 16-DEC-2016** LNM/D. 15-APR-2016
Amend Fl to read Fl 6s against light 52°03'54.1"N 128°03'00.6"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA470318 *DFO(6203431-01)*
- 15-APR-2016** LNM/D. 04-MAR-2016



Chart no. 3939

Amend Fl to read Fl 6s against light 52°17'36.3"N 128°05'59.0"W
(See Chart No. 1,P1)
This notice affects Electronic Navigational Chart: (P2016023) LL(605) DFO(6203229-01)
CA470087

04-MAR-2016

Amend Fl to read Fl 6s against light LNM/D. 25-DEC-2015
(See Chart No. 1,P1) 52°05'57.5"N 128°07'01.0"W
This notice affects Electronic Navigational Chart: CA470318 LL(606) DFO(6203217-01)

25-DEC-2015

Amend Fl 6s 4m 6M to read Fl 6s 4m 5M against light LNM/D. 10-OCT-2014
(See Chart No. 1,P1) 52°07'33.8"N 127°53'26.2"W
LL(594) DFO(6203164-02)

10-OCT-2014

Add depth of 5.4 metres 52°10'22.0"N 128°05'49.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 DFO(6202908-01)

10-OCT-2014

Add depth of 5.3 metres 52°09'38.5"N 128°07'01.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 DFO(6202908-02)

10-OCT-2014

Delete depth of 6.5 metres 52°09'38.5"N 128°07'00.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 DFO(6202908-03)

10-OCT-2014

Add depth of 2.2 metres 52°10'38.5"N 128°05'34.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 DFO(6202908-04)

10-OCT-2014

Delete depth of 6.8 metres 52°10'40.0"N 128°05'34.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 DFO(6202908-05)



Chart no. 3939

10-OCT-2014

Add depth of 8.7 metres 52°10'36.0"N 128°04'49.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 *DFO(6202908-06)*

10-OCT-2014

Delete depth of 18.2 metres 52°10'37.5"N 128°04'48.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 *DFO(6202908-07)*

10-OCT-2014

Add depth of 9.4 metres 52°09'48.0"N 128°07'04.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 *DFO(6202908-08)*

10-OCT-2014

Delete depth of 22.2 metres 52°09'49.0"N 128°06'59.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324 *DFO(6202908-09)*

3939 - Ocean Falls - New Edition - 01-AUG-2014 - World Geodetic System 1984

30-SEP-2022

Add submarine cable LNM/D. 15-MAY-2020
(See Chart No. 1, L30.1) joining 52°21'33.3"N 127°43'16.1"W
This notice affects Electronic Navigational Chart: 52°21'30.4"N 127°43'18.2"W
CA470324, CA570326 52°21'26.5"N 127°43'17.4"W
52°21'10.2"N 127°43'27.3"W
and 52°21'02.2"N 127°43'36.0"W
DFO(6204641-05)

30-SEP-2022

Add submarine cable LNM/D. 15-MAY-2020
(See Chart No. 1, L30.1) joining 52°21'29.6"N 127°43'17.8"W
This notice affects Electronic Navigational Chart: 52°21'26.2"N 127°43'11.1"W
CA470324, CA570326 52°21'07.2"N 127°41'59.6"W
and 52°21'08.2"N 127°41'33.7"W
DFO(6204641-06)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 3939

15-NOV-2019

Amend Fl(3) to read Fl R 6s against the light (See Chart
No.1, P1)

This notice affects Electronic Navigational Chart:
CA470324, CA570326

LNМ/D. 23-NOV-2018

52°21'00.4"N 127°43'00.6"W

(P2019111) LL(600) DFO(6204162-01)

3939 - Shearwater - New Edition - 01-AUG-2014 - World Geodetic System 1984

11-AUG-2023

Delete depth of 6.1 metres
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA570327

LNМ/D. 17-FEB-2023

52°09'10.5"N 128°05'20.3"W

DFO(6204792-03)

11-AUG-2023

Add depth of 4.6 metres
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA570327

LNМ/D. 17-FEB-2023

52°09'10.4"N 128°05'20.5"W

DFO(6204792-04)

11-AUG-2023

Add depth of 4.1 metres
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA570327

LNМ/D. 17-FEB-2023

52°08'58.8"N 128°05'12.8"W

DFO(6204792-05)

11-AUG-2023

Add depth of 1.4 metres
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA570327

LNМ/D. 17-FEB-2023

52°09'09.1"N 128°05'20.2"W

DFO(6204792-06)

11-AUG-2023

Add depth of 1.2 metres
(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA570327

LNМ/D. 17-FEB-2023

52°09'00.5"N 128°05'26.4"W

DFO(6204792-08)

17-FEB-2023

LNМ/D. 30-SEP-2022



Chart no. 3939

Add submarine cable (See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA570327

joining 52°09'36.0"N 128°05'54.0"W
52°09'20.8"N 128°05'39.1"W
52°09'02.9"N 128°05'28.3"W
and 52°09'01.3"N 128°05'30.9"W

DFO(6204697-08)

15-MAY-2020

LNМ/D. 15-NOV-2019

Delete depth of 9 metres, Rep (2018)
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324,
CA570327

52°09'03.0"N 128°05'24.0"W

DFO(6204323-01)

15-MAY-2020

LNМ/D. 15-NOV-2019

Add depth of 9 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470324,
CA570327

52°09'03.6"N 128°05'23.1"W

DFO(6204323-02)

23-NOV-2018

LNМ/D. 17-AUG-2018

Add Booms/Pannes
This notice affects Electronic Navigational Chart: CA570327

52°08'59.6"N 128°04'17.8"W

DFO(6203925-01)

23-NOV-2018

LNМ/D. 17-AUG-2018

Delete fish haven
(See Chart No. 1, K46.1)
This notice affects Electronic Navigational Chart: CA570327

52°08'56.9"N 128°04'12.1"W

DFO(6203925-02)

23-NOV-2018

LNМ/D. 17-AUG-2018

Add pontoon
(See Chart No. 1, F16)
This notice affects Electronic Navigational Chart:
CA570327

joining 52°08'55.6"N 128°04'12.9"W
52°08'55.6"N 128°04'09.5"W
52°08'56.2"N 128°04'09.5"W
52°08'56.2"N 128°04'12.9"W
and 52°08'55.6"N 128°04'12.9"W

DFO(6203925-03)

17-AUG-2018

LNМ/D. 04-MAY-2018



Chart no. 3939

Add depth of 9.0 metres, Rep (2018)
(See Chart No. 1, I10)

52°09'03.1"N 128°05'24.0"W

This notice affects Electronic Navigational Chart: CA470324,
CA570327

DFO(6203825-01)

17-AUG-2018

LNМ/D. 04-MAY-2018

Delete depth of 12.8 metres
(See Chart No. 1, I10)

52°09'02.8"N 128°05'23.4"W

This notice affects Electronic Navigational Chart: CA470324,
CA570327

DFO(6203825-02)

3939 - Continuation A (Cousins Inlet) - New Edition - 01-AUG-2014 - World Geodetic System 1984

30-SEP-2022

LNМ/D. 15-MAY-2020

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA570326

joining 52°21'33.3"N 127°43'16.1"W
52°21'30.4"N 127°43'18.2"W
52°21'26.5"N 127°43'17.4"W
52°21'10.2"N 127°43'27.3"W
52°20'16.4"N 127°44'21.2"W
52°19'32.5"N 127°44'45.9"W
52°18'54.2"N 127°45'18.2"W
52°18'09.6"N 127°45'21.1"W
and 52°17'48.0"N 127°45'33.3"W

DFO(6204641-05)

30-SEP-2022

LNМ/D. 15-MAY-2020

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA470324, CA570326

joining 52°21'30.4"N 127°43'18.2"W
52°21'25.7"N 127°43'11.1"W
52°21'06.6"N 127°41'59.6"W
and 52°21'08.2"N 127°41'33.7"W

DFO(6204641-06)

15-NOV-2019

LNМ/D. 23-NOV-2018

Amend Fl(3) to read Fl R 6s against the light (See Chart
No.1, P1)

52°21'00.4"N 127°43'00.6"W

This notice affects Electronic Navigational Chart:
CA470324, CA570326

(P2019111) LL(600) DFO(6204162-01)