



Chart no. 4013

4013 - Halifax to / à Sydney - New Edition - 06-SEP-2002 - NAD 1983

07-JAN-2022

LNМ/D. 24-DEC-2021

Add maritime limit in general, usually implying permanent physical obstructions
(See Chart No. 1, N1.1)

between 44°07'25.0"N 059°15'11.1"W
and 44°12'33.8"N 059°04'48.5"W

This notice affects Electronic Navigational Chart:
CA276204, CA376289

DFO(6309783-01)

07-JAN-2022

LNМ/D. 24-DEC-2021

Add legend See/Voir note SCIENTIFIC MOORINGS MOUILLAGES
SCIENTIFIQUES

44°09'30.0"N 059°06'00.0"W

This notice affects Electronic Navigational Chart: CA276204,
CA376289

DFO(6309783-02)

07-JAN-2022

LNМ/D. 24-DEC-2021

Delete maritime limit in general, implying permanent physical obstructions
(See Chart No. 1, N1.1)

between 46°01'18.6"N 059°02'01.2"W
and 46°01'18.6"N 058°59'57.4"W

This notice affects Electronic Navigational Chart:
CA276271

DFO(6309784-01)

07-JAN-2022

LNМ/D. 24-DEC-2021

Delete maritime limit in general, implying permanent physical obstructions
(See Chart No. 1, N1.1)

between 46°10'38.4"N 059°13'25.2"W
and 46°13'24.0"N 059°04'57.6"W

This notice affects Electronic Navigational Chart:
CA276271

DFO(6309784-02)

07-JAN-2022

LNМ/D. 24-DEC-2021

Add maritime limit in general, implying permanent physical obstructions
(See Chart No. 1, N1.1)

joining 45°59'15.6"N 059°20'00.6"W
45°59'17.1"N 059°02'16.8"W
and 46°00'18.3"N 059°00'00.0"W

This notice affects Electronic Navigational Chart:
CA276204, CA276271

DFO(6309784-03)

07-JAN-2022

LNМ/D. 24-DEC-2021

Delete legend See/Voir note
SCIENTIFIC MOORINGS
MOUILLAGES SCIENTIFIQUES

46°11'30.0"N 059°06'00.0"W

This notice affects Electronic Navigational Chart: CA276271

DFO(6309784-04)



Chart no. 4013

07-JAN-2022

Add legend See/Voir note

SCIENTIFIC MOORINGS

MOUILLAGES SCIENTIFIQUES

This notice affects Electronic Navigational Chart: CA276204,
CA276271

LNM/D. 24-DEC-2021

45°56'07.8"N 059°05'39.0"W

DFO(6309784-05)

07-JAN-2022

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 58 fathoms

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA176140,
CA276204

LNM/D. 24-DEC-2021

45°08'36.1"N 059°42'54.9"W

DFO(6309970-01)

24-DEC-2021

Delete note GAS PIPELINES Gas pipelines and wells contain natural
gas under pressure and damage to these installations could
create an immediate fire hazard. Mariners are cautioned not to
anchor or trawl near pipelines or wellheads. GAZODUCS Les
gazoducs et les puits à gaz contiennent du gaz sous pression et
du dommage à ces installations pourrait créer un danger de
feu immédiat. Les navires ne devraient ni mouiller ni chaluter
près de pipelines ou de têtes de puits.

This notice affects Electronic Navigational Chart: CA276204

LNM/D. 17-DEC-2021

44°55'00.0"N 063°19'00.0"W

DFO(6309798-12)

24-DEC-2021

Delete legend See/Voir note GAS PIPELINES/GAZODUCS

This notice affects Electronic Navigational Chart: CA276204

LNM/D. 17-DEC-2021

43°55'26.0"N 060°19'09.0"W

DFO(6309798-13)

24-DEC-2021

Replace pipeline, Gas/Gaz with abandoned pipeline

(See Chart No. 1, L40.1, L44)

This notice affects Electronic Navigational Chart:
CA276204

LNM/D. 17-DEC-2021

joining 45°09'22.0"N 061°37'48.0"W

45°07'40.0"N 061°38'25.0"W

44°54'12.0"N 061°24'04.0"W

44°23'13.0"N 061°08'26.0"W

44°19'51.0"N 061°08'06.0"W

43°56'28.0"N 060°37'46.0"W

and 43°53'30.0"N 060°12'04.0"W

DFO(6309798-14)

24-DEC-2021

LNM/D. 17-DEC-2021



Chart no. 4013

Replace pipeline, Gas/Gaz with abandoned pipeline
(See Chart No. 1, L40.1, L44)

This notice affects Electronic Navigational Chart:
CA276204

between 43°53'30.0"N 060°12'04.0"W
and 43°52'04.0"N 060°13'23.0"W

DFO(6309798-15)

24-DEC-2021

Replace pipeline, Gas/Gaz with abandoned pipeline
(See Chart No. 1, L40.1, L44)

This notice affects Electronic Navigational Chart:
CA276204

LNM/D. 17-DEC-2021
between 43°53'30.0"N 060°12'04.0"W
and 43°52'04.0"N 060°09'28.0"W

DFO(6309798-16)

24-DEC-2021

Replace pipeline, Gas/Gaz with abandoned pipeline
(See Chart No. 1, L40.1, L44)

This notice affects Electronic Navigational Chart:
CA276204

LNM/D. 17-DEC-2021
joining 43°53'30.0"N 060°12'04.0"W
43°52'58.0"N 060°10'42.0"W
43°53'27.0"N 059°46'40.0"W
and 44°02'01.0"N 059°35'00.0"W

DFO(6309798-17)

24-DEC-2021

Replace pipeline, Gas/Gaz with abandoned pipeline
(See Chart No. 1, L40.1, L44)

This notice affects Electronic Navigational Chart:
CA276204

LNM/D. 17-DEC-2021
joining 45°06'42.5"N 061°37'05.0"W
44°54'20.0"N 061°24'53.5"W
44°23'19.0"N 061°08'37.0"W
44°19'52.0"N 061°08'50.0"W
44°10'30.0"N 060°56'35.0"W
and 43°52'04.0"N 060°43'41.0"W

DFO(6309798-34)

17-DEC-2021

Add subsurface Ocean Data Acquisition system
ODAS/SADO with known depth of 86 fathoms.
(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA176140,
CA276801

LNM/D. 22-OCT-2021
43°53'13.8"N 063°05'45.7"W

DFO(6309802-01)

17-DEC-2021

Add subsurface Ocean Data Acquisition system
ODAS/SADO with known depth of 87 fathoms.
(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA276801

LNM/D. 22-OCT-2021
43°53'46.2"N 063°04'46.0"W

DFO(6309802-02)



Chart no. 4013

17-DEC-2021

Add subsurface Ocean Data Acquisition system
ODAS/SADO with known depth of 125 fathoms.
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA176140,
CA276801

LNM/D. 22-OCT-2021
43°54'52.1"N 063°03'26.5"W
DFO(6309802-03)

22-OCT-2021

Delete lighted offshore platform Mo(U) 15M, marked Thebaud
(See Chart No. 1, P2)
This notice affects Electronic Navigational Chart: CA176140,
CA276204, CA376289

LNM/D. 02-APR-2021
43°53'29.0"N 060°12'03.0"W
DFO(6309440-03)

22-OCT-2021

Delete legend Fog Sig (U) 30s
(See Chart No. 1, R1)
This notice affects Electronic Navigational Chart: CA276204,
CA376289

LNM/D. 02-APR-2021
43°53'29.0"N 060°12'03.0"W
DFO(6309440-04)

22-OCT-2021

LNM/D. 02-APR-2021



Chart no. 4013

Delete note

45°20'00.0"N 061°50'00.0"W

"PRODUCTION PLATFORMS

Production Platforms and associated structures exhibit white lights Mo(U)15M, red air obstruction lights and sound fog signals Mo(U)30s. SAFETY ZONES have been established for the protection of the production facilities, other vessels and the marine environment. Unauthorized navigation within the Safety Zone is prohibited. Mariners are advised that any vessel proposing to transit the Safety Zone must contact the operator on VHF Channel 16 and, if approved, comply with the instructions given while transiting the area. Vessel movement in the area is monitored on a 24-hour basis. For additional information, consult Notices to Mariners No. 20, Annual Edition.

DFO(6309440-07)

PLATE-FORMES DE PRODUCTION

Les plates-formes de production et leurs structures annexes sont signalées par des feux blancs Mo(U)15M, des feux rouges d'obstacle aérien et par un signal de brume sonore Mo(U)30s. Des ZONES DE SÉCURITÉ ont été établies pour protéger les installations de production, les autres bâtiments et l'environnement marin. Toute navigation non autorisée est interdite à l'intérieur des limites de la zone de sécurité. Les navigateurs qui désirent traverser la zone de sécurité doivent contacter les responsables de la plate-forme sur la voie VHF 16 et, le cas échéant, se conformer aux instructions reçues pour traverser la zone de sécurité. Le trafic maritime est surveillé jour et nuit. Pour plus d'informations, reportez-vous aux Avis aux navigateurs n^o 20, Édition annuelle."

(See Chart No. 1, A14)

This notice affects Electronic Navigational Chart: CA276204

22-OCT-2021

LNМ/D. 02-APR-2021

Delete lighted offshore platform Mo(U) 15M, marked South Venture
(See Chart No. 1, P2)

43°59'51.0"N 059°37'36.0"W

This notice affects Electronic Navigational Chart: CA176140,
CA276204, CA376289

DFO(6309440-14)

22-OCT-2021

LNМ/D. 02-APR-2021

Delete legend Fog Sig Mo(U)
(See Chart No. 1, R1)

43°59'51.0"N 059°37'36.0"W

This notice affects Electronic Navigational Chart: CA176140,
CA276204, CA376289

DFO(6309440-16)

22-OCT-2021

LNМ/D. 02-APR-2021



Chart no. 4013

Delete lighted offshore platform Mo(U) 7M, marked Venture 44°02'02.0"N 059°34'58.0"W
(See Chart No. 1, P2)
This notice affects Electronic Navigational Chart: CA176140, DFO(6309440-18)
CA276204, CA376289

22-OCT-2021 LNM/D. 02-APR-2021
Delete legend Fog Sig (U) 30s 44°02'02.0"N 059°34'58.0"W
(See Chart No. 1, R1)
This notice affects Electronic Navigational Chart: CA176140, DFO(6309440-19)
CA276204, CA376289

02-APR-2021 LNM/D. 12-MAR-2021
Add depth of 1 fathom, 4 feet 45°44'33.4"N 060°12'16.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376295 DFO(6309337-02)

02-APR-2021 LNM/D. 12-MAR-2021
Delete depth of 2 fathoms 45°44'35.0"N 060°12'23.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376295 DFO(6309337-04)

12-MAR-2021 LNM/D. 23-OCT-2020
Add depth of 1 foot 45°16'47.6"N 061°01'37.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276204, DFO(6309308-13)
CA376067, CA476675

23-OCT-2020 LNM/D. 21-AUG-2020
Amend Fl 21s53ft17M to read Fl 21s42ft17M against light 45°45'56.0"N 060°06'49.0"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2020176) LL(750) DFO(6309205-01)
CA179245, CA276204, CA376295

21-AUG-2020 LNM/D. 07-AUG-2020
Delete depth of 1 fathom, 4 feet 45°45'10.9"N 063°18'18.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 DFO(6308867-01)

21-AUG-2020 LNM/D. 07-AUG-2020



Chart no. 4013

Add depth of 1 fathom 45°45'22.5"N 063°18'28.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308867-02)*

21-AUG-2020 LNM/D. 07-AUG-2020
Delete depth of 2 fathoms, 2 feet 45°46'25.3"N 063°16'51.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308867-03)*

21-AUG-2020 LNM/D. 07-AUG-2020
Add depth of 1 fathom, 4 feet 45°46'28.3"N 063°16'48.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308867-04)*

21-AUG-2020 LNM/D. 07-AUG-2020
Delete depth of 2 fathoms, 1 foot 45°45'40.6"N 063°18'08.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308867-05)*

21-AUG-2020 LNM/D. 07-AUG-2020
Add depth of 0 fathoms, 4 feet 45°45'59.2"N 063°18'04.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308867-06)*

21-AUG-2020 LNM/D. 07-AUG-2020
Affix patch 45°52'00.0"N 061°17'00.0"W
[PDF](#)
DFO(6308867-07)

21-AUG-2020 LNM/D. 07-AUG-2020
Delete depth of 2 fathoms, 3 feet 45°46'59.9"N 063°15'15.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308867-08)*

21-AUG-2020 LNM/D. 07-AUG-2020
Add depth of 2 fathoms, 1 foot 45°46'58.3"N 063°14'55.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308867-09)*



Chart no. 4013

21-AUG-2020

LNМ/D. 07-AUG-2020

Delete depth of 2 fathoms, 5 feet
(See Chart No. 1, I10)

45°50'33.0"N 063°09'06.0"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308868-01)

21-AUG-2020

LNМ/D. 07-AUG-2020

Add depth of 1 fathom, 3 feet
(See Chart No. 1, I10)

45°50'16.8"N 063°08'31.4"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308868-02)

21-AUG-2020

LNМ/D. 07-AUG-2020

Delete depth of 3 fathoms, 1 foot
(See Chart No. 1, I10)

45°46'08.0"N 063°08'05.0"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308869-01)

21-AUG-2020

LNМ/D. 07-AUG-2020

Add depth of 2 fathoms, 4 feet
(See Chart No. 1, I10)

45°46'11.5"N 063°07'52.3"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308869-02)

07-AUG-2020

LNМ/D. 10-JUL-2020

Amend Fl 20s53ft17M to read Fl 21s53ft17M against light
(See Chart No. 1, P16)

45°45'56.0"N 060°06'49.0"W

This notice affects Electronic Navigational Chart:
CA276204, CA376295

(G2020067) LL(750) DFO(6309032-01)

10-JUL-2020

LNМ/D. 05-JUN-2020

Delete legend 'Fog Sig' against light
(See Chart No. 1, R20)

44°49'25.0"N 062°20'10.0"W

This notice affects Electronic Navigational Chart:
CA176140, CA276204, CA376102

(F2020025) LL(602) DFO(6309001-01)

05-JUN-2020

LNМ/D. 29-MAY-2020

Amend Fl(3)20s 42ft 9M to read Fl(2) 18s42ft9M against
light

45°45'55.0"N 062°40'50.0"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA276286, CA376691, CA576464

(G2020015) LL(918) DFO(6308962-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

29-MAY-2020

Replace red starboard hand lighted pillar whistle buoy Q R,
with red starboard hand lighted spar buoy Q R,
marked C2

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA276286, CA376161, CA476179

LNМ/D. 08-NOV-2019

46°02'38.0"N 063°06'52.5"W

(G2020029) LL(984) DFO(6308984-01)

08-NOV-2019

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 89 fathoms.

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA276801

LNМ/D. 25-OCT-2019

44°14'56.9"N 063°09'53.6"W

DFO(6308831-02)

25-OCT-2019

Amend ON CERTAIN COPIES

Guysboroug to read Guysborough

(See Chart No 1, D3)

This notice affects Electronic Navigational Chart: CA276204

LNМ/D. 13-SEP-2019

45°23'53.7"N 061°28'30.6"W

DFO(6308814-01)

13-SEP-2019

Delete depth of 5 fathoms, 3 feet

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276286

LNМ/D. 23-AUG-2019

46°10'46.8"N 062°22'46.3"W

DFO(6308745-04)

13-SEP-2019

Add depth of 4 fathoms, 1 foot

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276286,
CA376248, CA476490

LNМ/D. 23-AUG-2019

46°10'43.8"N 062°22'36.6"W

DFO(6308745-05)

13-SEP-2019

Replace depth of 2 fathoms, 1 foot with depth of 0 fathoms, 5 feet

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276286

LNМ/D. 23-AUG-2019

45°58'23.4"N 062°51'46.2"W

DFO(6308774-02)

13-SEP-2019

LNМ/D. 23-AUG-2019



Chart no. 4013

- Replace depth of 1 fathom with depth of 0 fathoms, 5 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286
- 46°02'42.6"N 062°28'08.4"W
DFO(6308791-10)
- 13-SEP-2019**
- Add depth of 1 fathom
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA476490
- LNM/D. 23-AUG-2019
46°10'01.2"N 062°29'00.0"W
DFO(6308791-19)
- 13-SEP-2019**
- Delete depth of 2 fathoms, 5 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286
- LNM/D. 23-AUG-2019
46°06'00.6"N 062°26'07.4"W
DFO(6308791-20)
- 13-SEP-2019**
- Replace depth of 1 fathom, 1 foot with depth of 0 fathoms, 5 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286
- LNM/D. 23-AUG-2019
46°05'46.2"N 062°26'21.0"W
DFO(6308791-21)
- 13-SEP-2019**
- Delete depth of 2 fathoms, 2 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286
- LNM/D. 23-AUG-2019
46°10'08.6"N 062°28'46.0"W
DFO(6308791-22)
- 23-AUG-2019**
- Delete depth of 7 fathoms
(See Chart No. 1, I10)
- LNM/D. 09-AUG-2019
44°39'08.2"N 063°12'41.5"W
DFO(6308730-01)
- 23-AUG-2019**
- Add depth of 4 fathoms
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083
- LNM/D. 09-AUG-2019
44°38'58.3"N 063°12'43.9"W
DFO(6308730-02)
- 23-AUG-2019**
- LNM/D. 09-AUG-2019



Chart no. 4013

- Add depth of 5 fathoms, 3 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801,
CA376083
- 44°38'50.9"N 063°07'05.6"W
DFO(6308730-03)
- 23-AUG-2019** LNM/D. 09-AUG-2019
- Delete depth of 8 fathoms
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801
- 44°38'04.6"N 063°00'52.1"W
DFO(6308730-04)
- 23-AUG-2019** LNM/D. 09-AUG-2019
- Add depth of 5 fathoms, 5 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801,
CA376083
- 44°37'57.9"N 063°01'01.4"W
DFO(6308730-05)
- 09-AUG-2019** LNM/D. 21-JUN-2019
- Amend depth of 34 fathoms to read 39 fathoms against
subsurface Ocean Data Acquisition system
ODAS/SADO
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA179245,
CA276271
- 46°10'12.1"N 059°08'40.3"W
DFO(6308687-01)
- 21-JUN-2019** LNM/D. 10-MAY-2019
- Delete depth of 0 fathoms 4 feet
See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376161
- 46°13'03.6"N 063°07'24.1"W
DFO(6308641-03)
- 21-JUN-2019** LNM/D. 10-MAY-2019
- Add depth of 0 fathoms 1 foot
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376161, CA476179, CA576177
- 46°13'15.6"N 063°07'28.2"W
DFO(6308641-06)
- 10-MAY-2019** LNM/D. 08-FEB-2019
- Amend Fl 4 s 82 ft 17 M to read Fl 4s82ft19M 46°08'39.1"N 062°28'01.2"W
(See Chart No. 1, P16)
- LL(953) DFO(6308636-01)*



Chart no. 4013

10-MAY-2019

LNLM/D. 08-FEB-2019

Replace red and white fairway lighted pillar buoy Mo(A) with red and white fairway lighted spar buoy Mo(A)
(See Chart No. 1, Qh)

46°02'12.7"N 062°27'09.2"W

LL(961) DFO(6308636-02)

08-FEB-2019

LNLM/D. 11-JAN-2019

Add maritime limit in general, implying permanent physical obstructions
(See Chart No. 1, N1.1)
This notice affects Electronic Navigational Chart: CA276271

between 46°01'18.6"N 059°02'01.2"W
and 46°01'18.6"N 058°59'57.4"W

DFO(6308457-01)

08-FEB-2019

LNLM/D. 11-JAN-2019

Add maritime limit in general, implying permanent physical obstructions
(See Chart No. 1, N1.1)
This notice affects Electronic Navigational Chart: CA276271

between 46°10'38.4"N 059°13'25.2"W
and 46°13'24.0"N 059°04'57.6"W

DFO(6308457-02)

08-FEB-2019

LNLM/D. 11-JAN-2019

Add See/Voir note
SCIENTIFIC MOORINGS
MOUILLAGES SCIENTIFIQUES

46°11'57.4"N 059°05'00.0"W

DFO(6308457-04)

This notice affects Electronic Navigational Chart: CA276271

08-FEB-2019

LNLM/D. 11-JAN-2019

Amend 'Fl 5s60ft16M' to read 'LFl 6s60ft10M' against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA176140, CA276204, CA376067, CA476069

45°11'49.2"N 061°08'10.3"W

(G2018147) LL(659) DFO(6308526-01)

08-FEB-2019

LNLM/D. 11-JAN-2019

Delete 'Fog Sig' against light
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: CA176140, CA276204, CA376067, CA476069

45°11'49.2"N 061°08'10.3"W

(G2018147) LL(659) DFO(6308526-02)

11-JAN-2019

LNLM/D. 07-DEC-2018



Chart no. 4013

Delete light FRWG 45°47'37.2"N 063°02'53.0"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2018146) LL(920) DFO(6308524-01)
CA276286, CA376161

07-DEC-2018 LNM/D. 12-OCT-2018
Add yellow ODAS/SADO lighted pillar Fl(5) Y 20s 44°20'52.0"N 063°18'21.0"W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA176140, DFO(6308508-02)
CA276801, CA476009

12-OCT-2018 LNM/D. 23-MAR-2018
Delete subsurface Ocean Data Acquisition system ODAS/SADO with 44°02'54.1"N 060°35'41.1"W
known depth of 15 fathoms
(See Chart No. 1, L25) DFO(6308453-01)
This notice affects Electronic Navigational Chart: CA276204,
CA376137

23-MAR-2018 LNM/D. 06-OCT-2017
Replace depth of 1 fathom, 5 feet with depth of 1 fathom, 3 feet 45°47'47.3"N 062°38'19.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA179245 DFO(6308162-18)

23-MAR-2018 LNM/D. 06-OCT-2017
Replace depth of 4 fathoms, 3 feet with depth of 3 fathoms, 5 feet 45°47'30.1"N 062°42'40.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286, DFO(6308162-19)
CA376691

23-MAR-2018 LNM/D. 06-OCT-2017
Replace depth of 1 fathom, 5 feet with depth of 1 fathom 45°46'09.7"N 062°41'24.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 DFO(6308162-21)

23-MAR-2018 LNM/D. 06-OCT-2017
Replace depth of 1 fathom, 3 feet with depth of 0 fathoms, 4 feet 45°44'25.5"N 062°44'17.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 DFO(6308162-22)



Chart no. 4013

23-MAR-2018

LNМ/D. 06-OCT-2017

Replace depth of 3 fathoms, 5 feet with depth of 0 fathoms, 5 feet
(See Chart No. 1, I10)

45°44'23.6"N 062°42'41.5"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308162-24)

23-MAR-2018

LNМ/D. 06-OCT-2017

Delete depth of 4 fathoms, 3 feet 45°44'54.7"N 062°34'58.9"W
(See Chart No. 1, I10)

DFO(6308162-47)

23-MAR-2018

LNМ/D. 06-OCT-2017

Add depth of 3 fathoms, 4 feet
(See Chart No. 1, I10)

45°44'56.0"N 062°34'25.1"W

This notice affects Electronic Navigational Chart: CA276286,
CA376691

DFO(6308162-48)

06-OCT-2017

LNМ/D. 11-AUG-2017

Amend "WHIS" to read "BELL" against red and white
fairway pillar light buoy Mo(A)
(See Chart No. 1, R15, R14)

45°02'07.1"N 061°32'45.9"W

(G2017091) LL(635) DFO(6308058-01)

This notice affects Electronic Navigational Chart:
CA276204, CA376109

11-AUG-2017

LNМ/D. 07-JUL-2017

Add environmentally sensitive sea area with legend, St Anns
Bank Marine Protected Area / Zone de protection marine
du banc de Sainte-Anne

joining 45°53'00.0"N 059°00'00.0"W

45°47'00.0"N 059°39'00.0"W

46°10'00.0"N 059°39'00.0"W

(See Chart No. 1, N22)

46°10'00.0"N 059°20'00.0"W

This notice affects Electronic Navigational Chart:

46°16'00.0"N 059°20'00.0"W

CA179245, CA276090, CA276204, CA276271, CA276284,
CA376303

and 46°22'00.0"N 059°06'40.0"W

DFO(6308006-01)

11-AUG-2017

LNМ/D. 07-JUL-2017

Replace depth of 0 fathoms, 4 feet with depth of 0 fathoms, 3 feet
(See Chart No. 1, I10)

45°41'09.6"N 062°36'52.3"W

This notice affects Electronic Navigational Chart: CA276286,
CA376691

DFO(6308023-02)



Chart no. 4013

07-JUL-2017

Reposition red and white fairway lighted pillar bell buoy
Mo(A), BELL
(See Chart No. 1, Qh)
This notice affects Electronic Navigational
Chart: CA276271, CA376093

LNМ/D. 30-JUN-2017
from 46°13'38.0"N 059°55'26.0"W
to 46°13'28.8"N 059°55'37.8"W
(G2017022) LL(771) DFO(6307916-01)

30-JUN-2017

Delete light "Fl 3s125ft10M"
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA276286, CA376242, CA476678

LNМ/D. 31-MAR-2017
45°41'29.8"N 061°29'18.1"W
(G2017015) LL(883) DFO(6307918-01)

31-MAR-2017

Delete legend Fog Sig against light
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart:
CA179245, CA276204, CA376303

LNМ/D. 10-MAR-2017
45°54'24.0"N 059°57'30.4"W
(G2016158) LL(756) DFO(6307823-01)

10-MAR-2017

Delete legend FogSig against light
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart:
CA179245, CA376295

LNМ/D. 03-MAR-2017
45°43'02.8"N 060°13'46.4"W
(G2016140) LL(747) DFO(6307757-01)

03-MAR-2017

Add flame tower with elevation of 200 feet
(See Chart No. 1, E23)

LNМ/D. 03-FEB-2017
45°10'30.0"N 061°36'56.0"W

DFO(6307845-01)

This notice affects Electronic Navigational Chart: CA276204,
CA376109

03-FEB-2017

Amend Fl 6s53ft13M to read LFl 6s55ft15M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276286,
CA576695

LNМ/D. 25-NOV-2016
45°42'25.9"N 062°16'20.6"W

LL(895) DFO(6307785-01)

25-NOV-2016

LNМ/D. 26-AUG-2016



Chart no. 4013

Amend Fl 15s64ft13M to read Fl 3s64ft13M against light 46°02'04.3"N 059°40'48.0"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2016124) LL(767) DFO(6307705-01)
CA276271, CA376303

25-NOV-2016

Delete legend Fog Sig against light LNM/D. 26-AUG-2016
(See Chart No. 1, R1, R20) 46°02'04.3"N 059°40'48.0"W
This notice affects Electronic Navigational Chart: CA179245, DFO(6307705-02)
CA276271, CA376303

26-AUG-2016

Delete fog signal Fog Sig against light LNM/D. 29-JUL-2016
(See Chart No. 1, R1, R20) 45°45'54.0"N 060°06'48.0"W
This notice affects Electronic Navigational Chart: (G2016117) LL(750) DFO(6307659-01)
CA179245, CA276204, CA376295

29-JUL-2016

Delete legend Fog Sig against light LNM/D. 17-JUN-2016
(See Chart No 1 R20) 45°11'28.8"N 061°18'39.9"W
This notice affects Electronic Navigational Chart: (G2016089) LL(646) DFO(6307614-01)
CA276204, CA376067, CA476068

17-JUN-2016

Amend Fl 10s 105ft 16M to read LFl 6s 105ft LNM/D. 06-MAY-2016
13M against light 45°54'24.0"N 059°57'30.0"W
(See Chart No. 1, P16) (G2016037 & G2016052) LL(756) DFO(6307520-01)
This notice affects Electronic
Navigational Chart: CA179245,
CA276204

06-MAY-2016

Amend LFl 6s 84ft 14M to read LFl 6s 25ft 12M against LNM/D. 04-MAR-2016
light 44°39'53.5"N 062°51'50.8"W
(See Chart No. 1, P16) (F2016011) LL(580) DFO(6307493-01)
This notice affects Electronic Navigational Chart:
CA176140, CA276801, CA376083

04-MAR-2016

LNM/D. 12-FEB-2016



Chart no. 4013

Amend Fl 3s 64ft 15M to read Fl 15s 64ft 13M against light 46°02'03.0"N 059°40'47.1"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2015157) LL(767) DFO(6307448-01)
CA179245, CA276271, CA376303

12-FEB-2016 LNM/D. 05-FEB-2016
Amend LFl12s78ft8M to read LFl6s78ft7M against light 45°37'19.2"N 060°29'17.6"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2015163) LL(743) DFO(6307407-01)
CA276204, CA376295

12-FEB-2016 LNM/D. 05-FEB-2016
Amend F 12M to read LFl 12M against light 46°00'25.4"N 059°49'21.7"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2015162) LL(765.4) DFO(6307409-01)
CA376303

05-FEB-2016 LNM/D. 25-DEC-2015
Amend Fl5s 85ft 21M to read Fl 5s 85ft 18M against light 46°16'01.5"N 060°07'32.9"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276271, LL(775) DFO(6307366-05)
CA376093, CA576095

05-FEB-2016 LNM/D. 25-DEC-2015
Amend Fl20s 53ft 15M to read Fl20s 53ft 17M against light 45°46'00.0"N 060°06'46.5"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276204, LL(750) DFO(6307366-06)
CA376295

25-DEC-2015 LNM/D. 04-DEC-2015
Add subsurface Ocean Data Acquisition system ODAS/SADO with 44°03'00.0"N 060°35'40.0"W
known depth of 15 fathoms
(See Chart No. 1, L25) DFO(6307350-03)
This notice affects Electronic Navigational Chart: CA276204,
CA376137

04-DEC-2015 LNM/D. 27-NOV-2015



Chart no. 4013

Add submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:
CA276204

joining 45°23'21.1"N 058°59'57.4"W
45°12'27.0"N 059°52'03.9"W
45°02'58.4"N 060°35'29.9"W
44°56'56.6"N 060°57'51.1"W
44°43'13.9"N 061°48'00.0"W
44°31'28.4"N 062°29'32.3"W
44°26'56.0"N 062°47'31.1"W
44°25'06.1"N 063°05'48.5"W
44°25'19.8"N 063°07'38.5"W
44°33'29.2"N 063°24'39.7"W
44°33'58.6"N 063°26'21.4"W
and 44°33'34.0"N 063°33'34.3"W

DFO(6307267-01)

27-NOV-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 5 fathoms, 3 feet

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA276271

LNМ/D. 28-AUG-2015

46°15'18.8"N 059°08'28.6"W

DFO(6307340-01)

27-NOV-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 34 fathoms

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA276271,
CA376303

LNМ/D. 28-AUG-2015

46°07'47.6"N 059°19'49.7"W

DFO(6307340-02)

28-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 34 fathoms.

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA276271

LNМ/D. 27-MAR-2015

46°10'06.1"N 059°08'44.3"W

DFO(6307181-01)

27-MAR-2015

Delete red and white fairway lighted pillar buoy Mo(A)

(See Chart No. 1, Qh)

This notice affects Electronic Navigational Chart:
CA276271, CA376093

LNМ/D. 27-FEB-2015

46°18'24.2"N 060°07'50.6"W

(G2015009) LL(776) DFO(6307072-01)

27-FEB-2015

LNМ/D. 06-FEB-2015



Chart no. 4013

Delete National Park symbol 44°05'45.0"N 059°07'00.0"W
(See Chart No. 1, Ef)

DFO(6307023-02)

06-FEB-2015

Amend Fl(2)25s74ft10M to read LFl74ft8M against light
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA179172, CA276271, CA376093

LNm/D. 30-JAN-2015

46°10'51.0"N 059°46'13.2"W

(G2014202) LL(770) DFO(6307010-01)

06-FEB-2015

Delete legend FogSig against light
(See Chart No. 1, R20)

This notice affects Electronic Navigational Chart:
CA276271, CA376093

LNm/D. 30-JAN-2015

46°10'51.0"N 059°46'13.2"W

(G2014213) LL(770) DFO(6307010-02)

30-JAN-2015

Amend F 48ft 11M to read LFl 62ft 11M against light
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA276204, CA376295

LNm/D. 07-FEB-2014

45°43'02.8"N 060°13'46.4"W

(G2014197) LL(747) DFO(6306995-01)

07-FEB-2014

Amend Fl 3s 125ft 15M to read Fl 3s 125ft 10M against
light

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA276286, CA376242

LNm/D. 08-NOV-2013

45°41'27.4"N 061°29'25.0"W

(G2013008) LL(883) DFO(6306657-01)

08-NOV-2013

Add maritime limit in general implying: permanent physical
obstructions

(See Chart No. 1, N1.1)

This notice affects Electronic Navigational Chart:
CA276801, CA376032

LNm/D. 11-OCT-2013

joining 44°16'12.0"N 063°18'00.0"W

44°03'58.9"N 063°04'27.6"W

and 43°52'00.2"N 063°13'27.8"W

DFO(6306496-01)

11-OCT-2013

LNm/D. 30-AUG-2013



Chart no. 4013

Delete light F 84ft 12M 46°20'05.0"N 060°17'48.0"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2013017) LL(796) DFO(6306366-01)
CA276271, CA376093, CA476063

11-OCT-2013 LNM/D. 30-AUG-2013
Add light LFl 6s 88ft 14M 46°20'10.3"N 060°17'31.9"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2013017) LL(796) DFO(6306366-02)
CA276271, CA376093, CA476063

30-AUG-2013 LNM/D. 26-JUL-2013
Add red and white fairway lighted pillar whistle buoy 46°21'28.2"N 060°14'49.1"W
WHIS, LFl
(See Chart No. 1, Qh) (G2013018) LL(789.5) DFO(6306449-01)

26-JUL-2013 LNM/D. 19-APR-2013
Replace red starboard hand lighted pillar buoy QR with 46°00'44.2"N 062°26'17.1"W
black, yellow and black East cardinal lighted spar
buoy Q(3) 10s (G2013084) LL(970.4) DFO(6306435-01)

This notice affects Electronic Navigational Chart:
CA376248

19-APR-2013 LNM/D. 22-FEB-2013
Delete red starboard hand lighted pillar whistle buoy WHIS, 46°21'28.2"N 060°14'49.1"W
FIR
(See Chart No. 1, Qf) (G2013007) LL(795) DFO(6306343-01)
This notice affects Electronic Navigational Chart:
CA276271, CA376093

22-FEB-2013 LNM/D. 08-FEB-2013
Amend Chart/Carte 4306 to read Chart/carte 4302 45°32'30.0"N 061°23'00.0"W
(See Chart No. 1, A18)
DFO(6306324-01)

08-FEB-2013 LNM/D. 02-NOV-2012



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

Add maritime limit in general implying: permanent physical obstructions between 44°28'42.0"N 063°32'00.0"W
and 44°16'12.0"N 063°18'00.0"W

(see Chart 1, N1.1)

This notice affects Electronic Navigational Chart:
CA276801, CA376032, CA476009

DFO(6304781-01)

08-FEB-2013

LNM/D. 02-NOV-2012

Add See/Voir note

44°17'40.0"N 063°10'30.0"W

SCIENTIFIC MOORINGS

MOUILLAGES SCIENTIFIQUES

DFO(6304781-02)

08-FEB-2013

LNM/D. 02-NOV-2012

Add note:

46°15'45.0"N 060°56'20.0"W

SCIENTIFIC MOORINGS

Acoustic sensors, one metre high and positioned approximately 800 metres apart, along the line, directly on the seabed. Mariners are advised to avoid anchoring or conducting seabed operations in the vicinity of submarine moorings.

DFO(6304781-03)

MOUILLAGES SCIENTIFIQUES

Des capteurs acoustiques, d'une hauteur d'un mètre et positionnés à intervalles d'environ 800 mètres le long de la ligne, reposent directement sur le fond marin. Nous avisons les navigateurs d'éviter de mouiller ou d'effectuer des travaux sur le fond marin à proximité de ces mouillages sous-marins.

02-NOV-2012

LNM/D. 29-JUN-2012

Delete Legend 'Fog Sig' against light
(See Chart No 1 R20)

46°20'04.9"N 060°17'45.9"W

(G2012175) LL(796) DFO(6306188-01)

This notice affects Electronic Navigational Chart:
CA476063

29-JUN-2012

LNM/D. 13-JAN-2012

Delete light Fl 10s 118ft 18M
(See Chart No. 1, P1)

43°57'35.9"N 059°47'26.4"W

(F2012021) LL(666) DFO(6306034-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

29-JUN-2012

Add abandoned lighthouse with legend Lt Ho/Phare Aband

LNМ/D. 13-JAN-2012

43°57'35.9"N 059°47'26.4"W

(F2012021) DFO(6306034-02)

This notice affects Electronic Navigational Chart: CA176140,
CA276204, CA376289

13-JAN-2012

Delete legend Fog Sig against light
(See Chart No. 1, R1, R20)

LNМ/D. 09-DEC-2011

44°26'12.0"N 063°33'48.0"W

(F2011193) LL(507) DFO(6305873-01)

This notice affects Electronic Navigational Chart:
CA276801, CA476009

09-DEC-2011

Amend LFl Y 6s 74ft 10M to read LFl Y 6s 55ft 10M against
light
(See Chart No. 1, P16)

LNМ/D. 18-NOV-2011

46°00'11.1"N 062°27'34.0"W

(G2011309) LL(971) DFO(6305838-03)

This notice affects Electronic Navigational Chart:
CA276286, CA376248

18-NOV-2011

Delete light Fl 10s 52ft 8M
(See Chart No. 1, P1)

LNМ/D. 08-JUL-2011

44°35'00.4"N 063°27'34.5"W

(F2011184) LL(545) DFO(6305805-01)

This notice affects Electronic Navigational Chart:
CA276801, CA476009

08-JUL-2011

Amend LFl Y 6s 74ft 13M to read LFl Y 6s 74ft 10M against
light
(See Chart 1 P16)

LNМ/D. 06-MAY-2011

46°00'10.7"N 062°27'36.4"W

(G2011165) LL(971) DFO(6305550-01)

This notice affects Electronic Navigational Chart:
CA376248

06-MAY-2011

LNМ/D. 18-MAR-2011



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

Amend Fl 15s 64ft 17M to read Fl 3s 64ft 15M against light
(See Chart No 1 P16)

46°02'04.3"N 059°40'33.7"W

(G2011058) LL(767) DFO(6305358-01)

This notice affects Electronic Navigational Chart:
CA179172

18-MAR-2011

LNM/D. 11-FEB-2011

Delete depth of 1 fathom, 3 feet 45°43'13.5"N 060°13'26.0"W
(See Chart No. 1, I10)

DFO(6305289-10)

18-MAR-2011

LNM/D. 11-FEB-2011

Delete depth of 0 fathoms, 5 feet 46°07'08.0"N 062°54'09.0"W
(See Chart No. 1, I10)

DFO(6305295-12)

18-MAR-2011

LNM/D. 11-FEB-2011

Add depth of 0 fathoms, 4 feet 46°07'10.5"N 062°54'24.9"W
(See Chart No. 1, I10)

DFO(6305295-13)

11-FEB-2011

LNM/D. 14-JAN-2011

Amend Fl 30s 64ft 17M to read Fl 15s 64ft 17M against
light
(See Chart No. 1 P16)

46°02'04.3"N 059°40'33.7"W

(G2010239) LL(767) DFO(6305189-01)

14-JAN-2011

LNM/D. 27-AUG-2010



Chart no. 4013

Add pipeline with legend Gas/Gaz joining
(See Chart No 1 L40.1)

45°06'37.9"N 061°37'04.4"W
 45°06'00.8"N 061°36'08.2"W
 44°58'15.0"N 061°27'34.7"W
 44°56'06.3"N 061°26'26.1"W
 44°54'09.8"N 061°24'47.6"W
 44°28'31.0"N 061°10'25.3"W
 44°23'14.7"N 061°08'36.2"W
 44°20'59.4"N 061°09'14.0"W
 44°19'51.4"N 061°08'54.0"W
 44°17'57.2"N 061°05'49.1"W
 44°10'25.0"N 060°56'32.5"W
 44°07'23.3"N 060°54'56.1"W
 44°06'12.4"N 060°53'38.0"W
 and 43°52'00.2"N 060°43'40.0"W

DFO(6305195-01)

27-AUG-2010

LNM/D. 23-JUL-2010

Amend Fl 30s 64ft 23M to read Fl 30s 64ft 17M against light
(See Chart No. 1 P16)

46°02'04.3"N 059°40'33.7"W

LL(767) DFO(6304986-01)

This notice affects Electronic Navigational Chart: CA376303

27-AUG-2010

LNM/D. 23-JUL-2010

Amend F to read F 12M against light
(See Chart No. 1 P16)

46°00'25.4"N 059°49'21.7"W

LL(765.4) DFO(6304986-02)

This notice affects Electronic Navigational Chart: CA376303

23-JUL-2010

LNM/D. 11-JUN-2010

Amend Fl Y 6s 74ft to read LFl Y 6s 74ft 13M against light
(See Chart 1 P16)

46°00'10.7"N 062°27'36.4"W

LL(971) DFO(6304957-01)

This notice affects Electronic Navigational Chart: CA376248

11-JUN-2010

LNM/D. 04-JUN-2010

Add depth of 9 fathoms, 5 feet
(See Chart No. 1, I10)

44°02'53.0"N 059°17'06.0"W

DFO(6304901-01)

This notice affects Electronic Navigational Chart: CA276204



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

04-JUN-2010

LNМ/D. 23-APR-2010

Amend Fl(2) 20s 112ft 17M to read Fl(2) 20s 112ft 10M against light 45°28'41.3"N 060°53'57.6"W
(See Chart 1 P16)

LL(722) DFO(6304798-01)

This notice affects Electronic Navigational Chart: CA476277

04-JUN-2010

LNМ/D. 23-APR-2010

Amend Fl 20s 162ft 16M to read Fl 20s 157ft 10M against light 44°30'26.6"N 063°31'21.8"W
(See Chart 1 P16)

LL(513) DFO(6304817-01)

This notice affects Electronic Navigational Chart: CA176140

04-JUN-2010

LNМ/D. 23-APR-2010

Delete red starboard hand lighted pillar whistle buoy FlR 45°13'22.8"N 060°58'33.8"W
(See Chart 1 Qf)

(G2010046) LL(661) DFO(6304826-01)

This notice affects Electronic Navigational Chart:
CA376067

04-JUN-2010

LNМ/D. 23-APR-2010

Add yellow and black South cardinal lighted pillar whistle buoy WHIS, Q(6) + LFl 15s, marked PQ 45°13'28.0"N 060°58'46.7"W
(See Chart 1 Q130.3)

(G2010047) LL(661.2) DFO(6304827-01)

This notice affects Electronic Navigational Chart:
CA376067

23-APR-2010

LNМ/D. 12-FEB-2010

Amend Iso 8s 67ft 12M to read Fl 3s 68ft 17M against light 45°05'27.0"N 061°42'05.0"W
(See Chart 1 P16)

(G2010012) LL(629) DFO(6304754-01)

This notice affects Electronic Navigational Chart:
CA176140, CA376109

12-FEB-2010

LNМ/D. 11-DEC-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

Amend Fl 15s 84ft 9M to read LFl 6s 84ft 14M against light
(See Chart 1 P16)

44°39'53.1"N 062°51'48.3"W

(F2009078) LL(580) DFO(6304719-01)

This notice affects Electronic Navigational Chart:
CA176140, CA276801, CA376083

11-DEC-2009

LNM/D. 13-NOV-2009

Amend Fl 9s 105ft 17M to read Fl 10s 105ft 16M against light
(See Chart No 1 P16)

45°54'24.0"N 059°57'30.5"W

LL(756) DFO(6304648-01)

This notice affects Electronic Navigational Chart: CA179172

13-NOV-2009

LNM/D. 07-AUG-2009

Delete depth of 14 fathoms
(See Chart No. 1, I10)

44°41'06.5"N 062°41'28.0"W

DFO(6304638-01)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

LNM/D. 07-AUG-2009

Add depth of 7 fathoms, 4 feet
(See Chart No. 1, I10)

44°40'44.8"N 062°41'04.6"W

DFO(6304638-02)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

LNM/D. 07-AUG-2009

Delete depth of 10 fathoms
(See Chart No. 1, I10)

44°40'52.3"N 062°43'30.0"W

DFO(6304638-03)

13-NOV-2009

LNM/D. 07-AUG-2009

Add depth of 7 fathoms, 4 feet
(See Chart No. 1, I10)

44°40'24.0"N 062°43'08.7"W

DFO(6304638-04)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

LNM/D. 07-AUG-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

Delete depth of 11 fathoms
(See Chart No. 1, I10)

44°40'42.0"N 062°46'10.5"W

DFO(6304638-05)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

Add depth of 8 fathoms, 1 foot
(See Chart No. 1, I10)

LNМ/D. 07-AUG-2009

44°40'44.6"N 062°45'51.4"W

DFO(6304638-06)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

Delete depth of 16 fathoms
(See Chart No. 1, I10)

LNМ/D. 07-AUG-2009

44°39'16.2"N 062°45'25.9"W

DFO(6304638-07)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

Add depth of 8 fathoms, 4 feet
(See Chart No. 1, I10)

LNМ/D. 07-AUG-2009

44°39'19.6"N 062°45'21.7"W

DFO(6304638-08)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

Delete depth of 18 fathoms
(See Chart No. 1, I10)

LNМ/D. 07-AUG-2009

44°37'01.0"N 062°54'08.0"W

DFO(6304641-01)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

Delete depth of 14 fathoms
(See Chart No. 1, I10)

LNМ/D. 07-AUG-2009

44°37'22.5"N 062°55'11.3"W

DFO(6304641-02)

This notice affects Electronic Navigational Chart: CA276801



Chart no. 4013

13-NOV-2009

LNМ/D. 07-AUG-2009

Add depth of 10 fathoms
(See Chart No. 1, I10)

44°37'08.8"N 062°54'11.3"W

DFO(6304641-03)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

LNМ/D. 07-AUG-2009

Delete depth of 25 fathoms
(See Chart No. 1, I10)

44°35'36.2"N 062°54'31.3"W

DFO(6304642-01)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009

LNМ/D. 07-AUG-2009

Add depth of 16 fathoms
(See Chart No. 1, I10)

44°35'53.5"N 062°54'14.3"W

DFO(6304642-02)

This notice affects Electronic Navigational Chart: CA276801

07-AUG-2009

LNМ/D. 10-JUL-2009

Delete note:

45°20'30.0"N 061°49'30.0"W

PRODUCTION PLATFORMS

Platforms exhibit white lights and sound fog horns.

Unauthorized navigation within 500 metres of any platform
and its associated structures is prohibited.

DFO(6304291-01)

PLATES-FORMES DE PRODUCTION

Les plates-formes portent des feux blancs et sont équipés de
cornets de brume. Il est interdit de naviguer sans autorisation
à moins de 500 mètres d'une plate-forme et de ses structures
associées.

This notice affects Electronic Navigational Chart: CA276204

07-AUG-2009

LNМ/D. 10-JUL-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

Add note:

45°19'00.0"N 061°49'30.0"W

PRODUCTION PLATFORMS

Production Platforms and associated structures exhibit white lights Mo(U)15M and red air obstruction lights, and sound fog signals Mo(U)30s. SAFETY ZONES have been established for the protection of the production facilities, other vessels, and the marine environment. Unauthorized navigation within the Safety Zone is prohibited. Mariners are advised any vessel proposing to transit the Safety Zone must contact the operator on VHF Channel 16 and, if approved, comply with the instructions given while transiting the area. Vessel movement in the area is monitored on a 24-hour basis. For additional information, consult Notices to Mariners No. 20, Annual Edition.

DFO(6304291-02)

This notice affects Electronic Navigational Chart: CA276204

07-AUG-2009

LN/D. 10-JUL-2009

Reposition note:

from 45°20'00.0"N 061°49'30.0"W
to 44°55'30.0"N 063°19'00.0"W

GAS PIPELINES

Gas pipelines and wells contain natural gas under pressure and damage to these installations could create an immediate fire hazard. Mariners are cautioned not to anchor or trawl near pipelines or wellheads.

DFO(6304291-03)

GAZODUCS

Les gazoducs et les puits à gaz contiennent du gaz sous pression et du dommage à ces installations pourrait créer un danger de feu immédiat. Les navires ne devraient ni mouiller ni chaluter près de pipelines ou de têtes de puits..

This notice affects Electronic Navigational Chart:
CA276204

07-AUG-2009

LN/D. 10-JUL-2009



Chart no. 4013

Add note:

45°19'00.0"N 061°49'30.0"W

PLATEFORMES DE PRODUCTION

Les plateformes de production et leurs structures annexes sont signalées par des feux blancs Mo(U)15M, des feux rouges d'obstacle aérien et par un signal de brume sonore Mo(U)30s. Des ZONES DE SÉCURITÉ ont été établies pour protéger les installations de production, les autres bâtiments et l'environnement marin. Toute navigation non autorisée est interdite à l'intérieur des limites de la zone de sécurité. Les navigateurs qui désirent traverser la zone de sécurité doivent contacter les responsables de la plateforme sur la voie VHF 16 et, le cas échéant, se conformer aux instructions reçues pour traverser la zone de sécurité. Le trafic maritime est surveillé jour et nuit. Pour plus d'informations, reportez-vous aux Avis aux navigateurs n° 20, Édition annuelle.

DFO(6304291-04)

10-JUL-2009

LNM/D. 17-APR-2009

(P)Add pipeline and legend Gas/Gaz
(See Chart No 1 L40.1)

Encana will commence constructing a gas pipeline from Goldboro to the Deep Panuke Gasfield in July 2009. The proposed completion date is October 2009. The work is completed. Notice 10-JUL-2009(P), DFO(6304478) is cancelled.
Cancelled on 14-JAN-11

joining 45°09'24.7"N 061°37'44.1"W
45°08'19.3"N 061°39'45.4"W
45°07'28.3"N 061°38'24.1"W
45°06'31.7"N 061°36'53.8"W
45°06'31.5"N 061°36'36.8"W
45°06'08.5"N 061°36'23.4"W
45°04'50.4"N 061°34'59.6"W
44°58'50.1"N 061°27'57.6"W
44°55'58.9"N 061°26'20.5"W
44°54'20.6"N 061°24'55.4"W
44°54'14.7"N 061°24'50.3"W
44°28'39.6"N 061°10'24.5"W
44°23'24.9"N 061°08'31.3"W
44°19'57.2"N 061°09'39.8"W
44°18'01.9"N 061°05'54.9"W
44°09'53.5"N 060°55'54.0"W
44°07'14.1"N 060°54'57.2"W
44°06'28.0"N 060°53'49.1"W
and 43°52'00.2"N 060°43'40.7"W

DFO(6304478-01)

17-APR-2009

LNM/D. 13-FEB-2009

Amend MO(U) 8M FogSig20s to read Mo(U) 15M FogSig(U)30s against light
(See Chart No 1 P16 and R20)

43°53'28.2"N 060°12'00.0"W

DFO(6304301-01)

This notice affects Electronic Navigational Chart: CA176140, CA276204, CA376289



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

17-APR-2009

LNM/D. 13-FEB-2009

Amend MO(U) 8M FogSig20s to read Mo(U) 7M FogSig(U)30s against 44°01'59.9"N 059°34'57.1"W
light

(See Chart No 1 P16 and R20)

DFO(6304302-01)

This notice affects Electronic Navigational Chart: CA176140,
CA276204, CA376289

13-FEB-2009

LNM/D. 31-OCT-2008

Amend Fl 15s 55ft 16M to read Fl 15s 55ft 21M against light
(See Chart No 1 P16)

45°19'29.6"N 060°55'38.2"W

LL(668) DFO(6304203-01)

This notice affects Electronic Navigational Chart: CA179172,
CA276204, CA476277, CA576527

31-OCT-2008

LNM/D. 26-SEP-2008

Amend Fl 12s 78ft 8M to read LFl 12s 78ft 8M against light
(See Chart No 1 P16)

45°37'19.2"N 060°29'17.6"W

LL(743) DFO(6304039-01)

This notice affects Electronic Navigational Chart: CA179172

26-SEP-2008

LNM/D. 01-AUG-2008

Amend Fl 5s 140ft 24M to read Fl 6s 140ft 23M against
light
(See Chart No 1 P16)

44°26'12.0"N 063°33'51.0"W

(F2008068) LL(507) DFO(6303952-01)

This notice affects Electronic Navigational Chart:
CA476009

01-AUG-2008

LNM/D. 25-JUL-2008

Add submarine cable

between 46°22'00.2"N 060°01'16.0"W
and 46°20'10.3"N 060°03'12.1"W

This notice affects Electronic Navigational Chart:
CA179172, CA276271, CA576095

DFO(6303984-01)

25-JUL-2008

LNM/D. 09-MAY-2008



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

Add submarine cable

between 46°20'18.5"N 060°09'14.4"W
and 46°22'00.2"N 060°07'53.0"W

This notice affects Electronic Navigational Chart:
CA179172, CA276271, CA576095

DFO(6303964-01)

09-MAY-2008

LNM/D. 04-APR-2008

Delete light FlG

45°34'39.0"N 060°53'22.3"W

(See Chart No 1 P16)

(G2007181) LL(728) DFO(6303790-01)

04-APR-2008

LNM/D. 01-FEB-2008

(T)Add scientific subsurface mooring at a depth of 107 fathoms below the surface 44°02'58.0"N 063°04'58.0"W

Proposed date of removal is June 2008.

DFO(6303821-01)

The mooring has been removed. Notice 04-April-2008(T), DFO (6303821) is now cancelled.

Cancelled on 26-SEP-08

04-APR-2008

LNM/D. 01-FEB-2008

Add private yellow lighted spherical buoy Fl(5) Y 20s 44°00'00.0"N 059°32'00.0"W
(See Chart No 1 Q22)

DFO(6303827-02)

01-FEB-2008

LNM/D. 18-JAN-2008

Delete legend Fog Sig against light
(See Chart No 1 R20)

46°16'01.5"N 060°07'32.9"W

(G2007178) LL(775) DFO(6303745-01)

This notice affects Electronic Navigational Chart:
CA276271, CA576095

18-JAN-2008

LNM/D. 10-AUG-2007

Affix patch 45°28'00.0"N 061°05'00.0"W

DFO(6303770-01)

[PDF](#)

10-AUG-2007

LNM/D. 13-JUL-2007



Chart no. 4013

Replace red starboard hand lighted pillar buoy F1R with
red and white fairway lighted pillar buoy Mo(A)

46°05'29.1"N 061°29'28.0"W

(G2007051) LL(874.5) DFO(6303498-01)

This notice affects Electronic Navigational Chart:
CA276271, CA376242

13-JUL-2007

LNm/D. 06-JUL-2007

Replace red and white fairway pillar whistle buoy Mo(A), WHIS with a
red and white fairway lighted pillar buoy Mo(A)

46°18'24.2"N 060°07'50.6"W

DFO(6303451-02)

06-JUL-2007

LNm/D. 09-DEC-2005

(T)Add yellow ODAS/SADO lighted super-buoy Fl (5) Y
Proposed date of removal is November 2007
Caution note advertised on Chart 4320. See Notice 14-
December-2007, DFO(6303647). Notice 6-July-2007(T),
DFO(6303535) is now cancelled.
Cancelled on 14-DEC-07

44°17'18.0"N 063°14'18.0"W

DFO(6303535-01)

06-JUL-2007

LNm/D. 09-DEC-2005

(T)Add yellow ODAS/SADO lighted super-buoy Fl (5) Y
Proposed date of removal is November 2007
Caution note advertised on Chart 4320. See Notice 14-
December-2007, DFO(6303647). Notice 6-July-2007(T),
DFO(6303535) is now cancelled.
Cancelled on 14-DEC-07

44°17'46.3"N 063°14'19.0"W

DFO(6303535-02)

06-JUL-2007

LNm/D. 09-DEC-2005

(T)Add yellow ODAS/SADO lighted super-buoy Fl (5) Y
Proposed date of removal is November 2007
Caution note advertised on Chart 4320. See Notice 14-
December-2007, DFO(6303647). Notice 6-July-2007(T),
DFO(6303535) is now cancelled.
Cancelled on 14-DEC-07

44°17'50.6"N 063°15'41.6"W

DFO(6303535-03)

06-JUL-2007

LNm/D. 09-DEC-2005



Chart no. 4013

(T)Add yellow ODAS/SADO lighted super-buoy Fl (5) Y 44°17'15.7"N 063°14'12.7"W
 Proposed date of removal is November 2007
 Caution note advertised on Chart 4320. See Notice 14-December-2007, DFO(6303647). Notice 6-July-2007(T), *DFO(6303535-04)*
 DFO(6303535) is now cancelled.
 Cancelled on 14-DEC-07

06-JUL-2007 LNM/D. 09-DEC-2005
 (T)Add subsurface mooring 44°17'15.6"N 063°14'12.6"W
 Proposed date for removal is November 2007
 Caution note advertised on Chart 4320. See Notice 14-December-2007, DFO(6303647). Notice 6-July-2007(T), *DFO(6303535-05)*
 DFO(6303535) is now cancelled.
 Cancelled on 14-DEC-07

09-DEC-2005 LNM/D. 25-NOV-2005
 Add submarine cable joining 46°05'48.3"N 062°27'07.5"W
46°06'14.2"N 062°23'41.3"W
46°06'13.3"N 062°21'08.3"W
 This notice affects Electronic Navigational Chart: 46°07'25.8"N 061°56'53.7"W
 CA376248 46°01'24.4"N 061°32'54.0"W
and 46°01'34.5"N 061°32'25.8"W
DFO(6302323-01)

25-NOV-2005 LNM/D. 18-NOV-2005
 Amend "Mo(U)" to read "Mo(U) 8M" against Thebaud production 43°53'27.0"N 060°11'58.0"W
 platform *DFO(6302596-01)*

This notice affects Electronic Navigational Chart: CA376137

25-NOV-2005 LNM/D. 18-NOV-2005
 Amend "Mo(U)" to read "Mo(U) 8M" against Venture production 44°02'00.0"N 059°34'56.0"W
 platform *DFO(6302596-02)*

25-NOV-2005 LNM/D. 18-NOV-2005
 Delete "6Lts Q (Hor)" against Thebaud production platform 43°53'27.0"N 060°11'58.0"W
DFO(6302596-04)



Chart no. 4013

25-NOV-2005

LNM/D. 18-NOV-2005

Delete "4Lts Q (Hor)" against Venture production platform 44°02'00.0"N 059°34'56.0"W

DFO(6302596-05)

18-NOV-2005

LNM/D. 16-SEP-2005

Add production platform with light and legend "South Venture" 43°59'50.9"N 059°37'36.8"W

DFO(6302550-01)

18-NOV-2005

LNM/D. 16-SEP-2005

Add light Mo(U) 15M 43°59'50.9"N 059°37'36.8"W

DFO(6302550-02)

18-NOV-2005

LNM/D. 16-SEP-2005

Add fog signal "Fog Sig Mo(U)" 43°59'50.9"N 059°37'36.8"W

DFO(6302550-03)

18-NOV-2005

LNM/D. 16-SEP-2005

Add note:

45°21'45.0"N 061°48'30.0"W

PRODUCTION PLATFORMS

Platforms exhibit white lights and sound fog horns. Unauthorized navigation within 500 metres of any platform and its associated structures is prohibited.

DFO(6302590-01)

PLATES-FORMES DE PRODUCTION

Les plates-formes portent des feux blancs et sont équipés de cornets de brume. Il est interdit de naviguer sans autorisation à moins de 500 mètres d'une plate-forme et de ses structures associées.

16-SEP-2005

LNM/D. 11-FEB-2005

Delete legend "WHIS" against red starboard pillar light and whistle buoy Fl R, WHIS

45°35'12.2"N 060°30'25.6"W

(G2005077) LL(742) DFO(6302432-01)

11-FEB-2005

LNM/D. 07-JAN-2005



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

Amend "Fl 20s 54ft 14M" to read "LFl 20s 54ft 10M" against light 45°05'59.8"N 061°32'31.9"W

LL(639) DFO(6302110-01)

11-FEB-2005

LNM/D. 07-JAN-2005

Amend "Fl 10s 72ft 20M" to read "Fl 10s 72ft 15M" against light 44°59'15.8"N 061°57'58.4"W

LL(615) DFO(6302110-02)

07-JAN-2005

LNM/D. 26-NOV-2004

Amend "Fl(2) 25s 70ft 16M" to read "Fl(2) 25s 74ft 10M"
against light

46°10'48.9"N 059°46'13.2"W

(G2004198) LL(770) DFO(6302126-01)

26-NOV-2004

LNM/D. 01-OCT-2004

Add pipeline, Gas/Gaz

between 43°52'00.2"N 060°13'24.6"W
and 43°53'28.9"N 060°12'05.7"W

This notice affects Electronic Navigational Chart:
CA376137

DFO(6300633-01)

01-OCT-2004

LNM/D. 25-JUN-2004

Delete light Fl 15s 105ft 20M

43°55'54.7"N 060°01'22.1"W

(F2004109) LL(665) DFO(6301913-01)

This notice affects Electronic Navigational Chart:
CA376137

25-JUN-2004

LNM/D. 18-JUN-2004

Add maritime limit in general usually implying: no permanent joining 44°08'00.0"N 058°59'57.4"W
obstructions 44°13'00.0"N 059°06'00.0"W

44°06'00.0"N 059°20'00.0"W

43°55'00.0"N 059°08'00.0"W

and 43°52'00.2"N 059°08'00.0"W

This notice affects Electronic Navigational Chart:
CA276090

DFO(6301285-01)

25-JUN-2004

LNM/D. 18-JUN-2004



Chart no. 4013

Add legend "Gully Marine Protected Area/Zone de protection marine
du Gully" 44°05'00.0"N 059°10'00.0"W

DFO(6301285-03)

18-JUN-2004

LNM/D. 28-MAY-2004

Delete red and white fairway pillar light and whistle buoy
Mo(A), WHIS

45°23'53.5"N 060°41'38.2"W

(G2004064) LL(686) DFO(6301440-01)

18-JUN-2004

LNM/D. 28-MAY-2004

Delete red and white fairway pillar light and bell buoy,
Mo(A), BELL

45°23'54.4"N 060°50'16.3"W

(G2004065) LL(686.3) DFO(6301441-01)

18-JUN-2004

LNM/D. 28-MAY-2004

Delete red and white fairway pillar light buoy Mo(A)

45°23'54.3"N 060°58'45.6"W

(G2004066) LL(686.4) DFO(6301442-01)

28-MAY-2004

LNM/D. 07-MAY-2004

Delete radar transponder beacon Racon against red and
white fairway pillar light buoy Mo (A), WHIS

44°21'45.0"N 063°24'15.0"W

(F2004054) LL(510) DFO(6301423-01)

07-MAY-2004

LNM/D. 24-OCT-2003

Add yellow cautionary can light buoy Fl Y, marked NAVY 44°05'58.4"N 063°30'03.0"W

DFO(6301249-01)

07-MAY-2004

LNM/D. 24-OCT-2003

Amend "Fl 10s 52ft 13M" to read "Fl 10s 52ft 8M" against
light

44°34'51.7"N 063°27'28.1"W

(F2004016) LL(545) DFO(6301329-01)

24-OCT-2003

LNM/D. 08-AUG-2003

Amend legend Fl(3) 24s 42 ft 12M to read Fl(3) 20s 42ft 9M

45°45'52.0"N 062°40'52.7"W

(G2002189) LL(918) DFO(6300756-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4013

08-AUG-2003

Delete fog signal

45°37'50.0"N 060°34'00.0"W

(G2003007) LL(740) DFO(6300980-01)