



Chart no. 4015

4015 - Sydney to / à Saint-Pierre - New Edition - 28-MAR-2003 - NAD 1983

29-JUL-2022

LNLM/D. 17-JUN-2022

Delete ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA276091, CA276271, CA276284, CA376093,
CA376164, CA376166, CA376173

joining 46°18'27.6"N 060°07'12.2"W
46°34'12.4"N 056°34'42.4"W
and 46°37'14.9"N 055°53'56.5"W

DFO(6310118-01)

29-JUL-2022

LNLM/D. 17-JUN-2022

Delete ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA276091, CA276284, CA376164, CA376166,
CA376176, CA576095

between 46°34'12.4"N 056°34'42.4"W
and 46°42'49.6"N 055°53'57.6"W

DFO(6310118-02)

29-JUL-2022

LNLM/D. 17-JUN-2022

Add ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA276091, CA276271, CA276284, CA376093, CA376166,
CA376176, CA576095

joining 46°42'20.7"N 055°53'57.2"W
46°39'08.9"N 056°11'14.3"W
46°44'21.1"N 056°46'58.2"W
46°44'19.1"N 057°15'13.5"W
and 46°18'26.0"N 060°07'11.7"W

DFO(6310118-03)

29-JUL-2022

LNLM/D. 17-JUN-2022

Add ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA276091, CA376164, CA376166, CA376176

between 46°40'32.0"N 055°53'57.5"W
and 46°39'08.8"N 056°11'14.2"W

DFO(6310118-04)

17-JUN-2022

LNLM/D. 25-MAR-2022



Chart no. 4015

Add environmentally sensitive sea area with legend,
Laurentian Channel Marine Protected Area / Zone de
protection marine du chenal Laurentien
(See Chart No. 1, N22)

This notice affects Electronic Navigational Chart:
CA276090, CA276091, CA276271, CA276284

joining 45°30'00.0"N 057°10'56.0"W
45°34'06.0"N 057°10'30.0"W
46°23'01.0"N 058°01'20.0"W
46°46'55.0"N 058°45'44.0"W
47°03'23.0"N 059°04'03.0"W
47°06'05.0"N 058°45'09.0"W
46°56'00.0"N 058°27'47.0"W
47°01'27.0"N 058°04'19.0"W
46°57'06.0"N 057°59'00.0"W
46°44'27.0"N 057°50'49.0"W
46°38'58.0"N 057°43'45.0"W
46°39'18.0"N 057°37'07.0"W
and 45°30'00.0"N 056°32'52.0"W

DFO(6310080-01)

25-MAR-2022

Delete fog signal Fog Sig against light
(See Chart No. 1, R1)

This notice affects Electronic Navigational Chart:
CA276271, CA376625, CA576304

LNLM/D. 18-FEB-2022

47°33'51.0"N 059°07'11.0"W

(N2022029) LL(160) DFO(6310030-01)

18-FEB-2022

Delete red starboard hand lighted pillar whistle buoy FLR
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA276271, CA376625

LNLM/D. 07-JAN-2022

47°36'10.0"N 058°39'15.2"W

(N2021261) LL(149.7) DFO(6309981-01)

07-JAN-2022

Delete maritime limit in general, implying permanent
physical obstructions
(See Chart No. 1, N1.1)

This notice affects Electronic Navigational Chart:
CA276271

LNLM/D. 30-APR-2021

between 46°01'18.6"N 059°02'01.2"W
and 46°01'18.6"N 058°52'41.4"W

DFO(6309784-01)

07-JAN-2022

Delete maritime limit in general, implying permanent
physical obstructions
(See Chart No. 1, N1.1)

This notice affects Electronic Navigational Chart:
CA276271

LNLM/D. 30-APR-2021

between 46°10'38.4"N 059°13'25.2"W
and 46°13'24.0"N 059°04'57.6"W

DFO(6309784-02)

07-JAN-2022

LNLM/D. 30-APR-2021



Chart no. 4015

Add maritime limit in general, implying permanent physical obstructions
(See Chart No. 1, N1.1)
This notice affects Electronic Navigational Chart: CA276204, CA276271

joining 45°59'15.6"N 059°20'00.6"W
45°59'17.1"N 059°02'16.8"W
and 46°06'58.5"N 058°45'06.8"W

DFO(6309784-03)

30-APR-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 65 fathoms
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276271

LNM/D. 23-APR-2021
47°22'47.6"N 060°17'48.8"W

DFO(6309412-01)

23-APR-2021

Add wreck, least depth unknown, with legend 'PA'
(See Chart No. 1, K29, B7)
This notice affects Electronic Navigational Chart: CA176030, CA276090

LNM/D. 02-APR-2021
45°43'36.0"N 057°03'45.0"W

DFO(6309407-01)

02-APR-2021

Add depth of 1 fathom, 4 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376295

LNM/D. 23-OCT-2020
45°44'33.4"N 060°12'16.0"W

DFO(6309337-02)

02-APR-2021

Delete depth of 2 fathoms
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376295

LNM/D. 23-OCT-2020
45°44'36.2"N 060°12'14.9"W

DFO(6309337-04)

23-OCT-2020

Amend Fl 21s53ft17M to read Fl 21s42ft17M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA179245, CA276204, CA376295

LNM/D. 07-AUG-2020
45°45'57.0"N 060°06'46.0"W

(G2020176) LL(750) DFO(6309205-01)

07-AUG-2020

Amend Fl 20s53ft17M to read Fl 21s53ft17M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276204, CA376295

LNM/D. 17-JUL-2020
45°45'57.0"N 060°06'46.0"W

(G2020067) LL(750) DFO(6309032-01)



Chart no. 4015

17-JUL-2020

LN/D. 22-MAY-2020

Delete legend WHIS against black, yellow and black East cardinal
lighted pillar buoy

47°03'22.0"N 056°11'18.0"W

(See Chart No. 1, Qd)

DFO(6308979-05)

This notice affects Electronic Navigational Chart: CA276091,
CA376627

17-JUL-2020

LN/D. 22-MAY-2020

Amend WHIS to read Bell against red and white fairway lighted pillar
buoy

46°48'22.0"N 056°07'47.0"W

(See Chart No. 1, Qc, Qd)

DFO(6308979-06)

This notice affects Electronic Navigational Chart: CA276091,
CA376164

17-JUL-2020

LN/D. 22-MAY-2020

Delete legend WHIS against black, yellow and black East cardinal
lighted pillar buoy

46°47'17.0"N 056°06'02.0"W

(See Chart No. 1, Qd)

DFO(6308979-07)

This notice affects Electronic Navigational Chart: CA276091,
CA376164

17-JUL-2020

LN/D. 22-MAY-2020

Delete legend WHIS against yellow and black South cardinal lighted
pillar buoy

46°43'49.0"N 056°12'54.0"W

(See Chart No. 1, Qd)

DFO(6308979-08)

This notice affects Electronic Navigational Chart: CA276091,
CA376164

17-JUL-2020

LN/D. 22-MAY-2020

Delete legend WHIS against yellow, black and yellow West cardinal
lighted pillar buoy

46°45'25.0"N 056°15'22.0"W

(See Chart No. 1, Qd)

DFO(6308979-09)

This notice affects Electronic Navigational Chart: CA276091,
CA376164

17-JUL-2020

LN/D. 22-MAY-2020

Replace depth of 18 fathoms with depth of 14 fathoms 47°06'48.0"N 056°17'48.0"W

(See Chart No. 1, I10)

DFO(6308997-02)



Chart no. 4015

17-JUL-2020

LN/D. 22-MAY-2020

Replace depth of 17 fathoms with depth of 13 fathoms 46°43'24.0"N 056°14'12.0"W
(See Chart No. 1, I10)

DFO(6308997-05)

17-JUL-2020

LN/D. 22-MAY-2020

Replace depth of 24 fathoms with depth of 22 fathoms
(See Chart No. 1, I10)

46°43'00.0"N 056°15'30.0"W

This notice affects Electronic Navigational Chart: CA276091

DFO(6308997-07)

22-MAY-2020

LN/D. 15-MAY-2020

Amend "WHIS" to read "Bell" against red starboard hand
pillar light buoy Fl R
(See Chart No. 1, Qc, Qd)

47°37'29.6"N 058°23'01.4"W

This notice affects Electronic Navigational Chart:
CA276271, CA376616

(N2020030) LL(145.8) DFO(6308974-01)

15-MAY-2020

LN/D. 09-AUG-2019

Delete legend WHIS against red and white fairway pillar
light buoy Mo(A)
(See Chart No. 1, Qd)

47°35'27.0"N 058°41'42.0"W

This notice affects Electronic Navigational Chart:
CA276271, CA376625

(N2020012) LL(148.9) DFO(6308958-01)

09-AUG-2019

LN/D. 08-FEB-2019

Amend depth of 34 fathoms to read 39 fathoms against
subsurface Ocean Data Acquisition system

46°10'12.1"N 059°08'40.3"W

ODAS/SADO

(See Chart No. 1, L25)

DFO(6308687-01)

This notice affects Electronic Navigational Chart: CA179245,
CA276271

09-AUG-2019

LN/D. 08-FEB-2019

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 44 fathoms
(See Chart No. 1, L25)

46°17'40.4"N 058°49'01.6"W

This notice affects Electronic Navigational Chart: CA179245,
CA276271

DFO(6308713-01)



Chart no. 4015

08-FEB-2019

LNLM/D. 11-JAN-2019

Add maritime limit in general, implying permanent physical obstructions between 46°01'18.6"N 059°02'01.2"W and 46°01'18.6"N 058°52'41.4"W

(See Chart No. 1, N1.1)

This notice affects Electronic Navigational Chart:
CA276271

DFO(6308457-01)

08-FEB-2019

LNLM/D. 11-JAN-2019

Add maritime limit in general, implying permanent physical obstructions between 46°10'38.4"N 059°13'25.2"W and 46°13'24.0"N 059°04'57.6"W

(See Chart No. 1, N1.1)

This notice affects Electronic Navigational Chart:
CA276271

DFO(6308457-02)

08-FEB-2019

LNLM/D. 11-JAN-2019

Add See/Voir note 46°07'45.6"N 059°03'05.7"W

SCIENTIFIC MOORINGS

MOUILLAGES SCIENTIFIQUES

DFO(6308457-04)

This notice affects Electronic Navigational Chart: CA276271

11-JAN-2019

LNLM/D. 23-NOV-2018

Affix patch 47°00'00.0"N 056°00'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA276091

DFO(6308543-01)

23-NOV-2018

LNLM/D. 09-NOV-2018

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 175 fathoms 46°18'17.9"N 058°52'29.6"W

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA179245,
CA276271

DFO(6308502-01)

09-NOV-2018

LNLM/D. 26-OCT-2018

Amend depth of 223 fathoms to read 199 fathoms against subsurface Ocean Data Acquisition system ODAS/SADO 45°41'48.4"N 057°15'13.7"W

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA176030,
CA276090

DFO(6308438-01)



Chart no. 4015

09-NOV-2018

LNM/D. 26-OCT-2018

Amend depth of 180 fathoms to read 184 fathoms against subsurface
Ocean Data Acquisition system ODAS/SADO (See Chart No. 1,
L25)

45°30'52.8"N 056°40'19.4"W

DFO(6308438-02)

This notice affects Electronic Navigational Chart: CA176030,
CA276090

09-NOV-2018

LNM/D. 26-OCT-2018

Reposition subsurface Ocean Data Acquisition system
ODAS/SADO with known depth of 199 fathoms
(See Chart No. 1, L25)

from 45°41'48.4"N 057°15'13.7"W
to 45°41'48.0"N 057°13'24.0"W

DFO(6308438-03)

This notice affects Electronic Navigational Chart:
CA276090

26-OCT-2018

LNM/D. 06-APR-2018

Add depth of 50 fathoms
(See Chart No. 1, I10)

47°08'10.1"N 056°08'09.7"W

This notice affects Electronic Navigational Chart: CA376627

DFO(6308428-03)

26-OCT-2018

LNM/D. 06-APR-2018

Delete depth of 64 fathoms
(See Chart No. 1, I10)

47°08'20.0"N 056°09'43.0"W

DFO(6308428-04)

26-OCT-2018

LNM/D. 06-APR-2018

Add depth of 33 fathoms
(See Chart No. 1, I10)

47°07'58.9"N 056°10'06.4"W

This notice affects Electronic Navigational Chart: CA376627

DFO(6308428-05)

26-OCT-2018

LNM/D. 06-APR-2018

Delete depth of 67 fathoms
(See Chart No. 1, I10)

47°11'37.0"N 056°13'12.0"W

This notice affects Electronic Navigational Chart: CA276274

DFO(6308428-06)

26-OCT-2018

LNM/D. 06-APR-2018

Add depth of 54 fathoms
(See Chart No. 1, I10)

47°11'56.1"N 056°13'24.1"W

This notice affects Electronic Navigational Chart: CA276274,
CA376627

DFO(6308428-07)



Chart no. 4015

26-OCT-2018

Add depth of 26 fathoms

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276274,
CA376627

LNM/D. 06-APR-2018

47°10'03.7"N 056°20'41.9"W

DFO(6308428-08)

26-OCT-2018

Delete depth of 12 fathoms

(See Chart No. 1, I10)

LNM/D. 06-APR-2018

46°59'45.0"N 056°12'17.0"W

DFO(6308428-10)

26-OCT-2018

Add depth of 5 fathoms, 2 feet

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376164

LNM/D. 06-APR-2018

46°59'23.8"N 056°12'14.9"W

DFO(6308428-11)

26-OCT-2018

Replace depth of 12 fathoms with depth of 8 fathoms, 4 feet

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276091

LNM/D. 06-APR-2018

46°49'26.5"N 056°02'06.4"W

DFO(6308428-13)

26-OCT-2018

Add depth of 4 fathoms, 3 feet

(See Chart No. 1, I10)

LNM/D. 06-APR-2018

47°05'13.0"N 056°17'17.5"W

DFO(6308428-15)

26-OCT-2018

Add depth of 37 fathoms

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376627

LNM/D. 06-APR-2018

47°06'06.5"N 056°09'16.7"W

DFO(6308428-18)

26-OCT-2018

Replace depth of 2 fathoms, 5 feet with depth of 2 fathoms

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376627

LNM/D. 06-APR-2018

47°04'03.2"N 056°14'45.7"W

DFO(6308428-19)

26-OCT-2018

LNM/D. 06-APR-2018



Chart no. 4015

Replace depth of 39 fathoms with depth of 33 fathoms 47°06'43.9"N 056°09'45.2"W
(See Chart No. 1, I10)

DFO(6308428-22)

06-APR-2018

LNM/D. 02-FEB-2018

Delete yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 44255 47°16'00.0"N 057°21'00.0"W
(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart: CA179245,
CA276284

DFO(6308224-01)

02-FEB-2018

LNM/D. 29-DEC-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 2 fathoms, 4 feet
(See Chart No. 1, L25)

46°52'47.0"N 056°01'37.0"W

This notice affects Electronic Navigational Chart: CA376164

DFO(6308177-02)

02-FEB-2018

LNM/D. 29-DEC-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 2 fathoms, 4 feet
(See Chart No. 1, L25)

46°45'27.0"N 056°26'37.0"W

This notice affects Electronic Navigational Chart: CA376166

DFO(6308177-03)

29-DEC-2017

LNM/D. 08-DEC-2017

Add submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:

CA179245, CA276271, CA376093, CA376167, CA376625

joining 46°22'45.0"N 060°17'21.0"W

46°23'49.0"N 060°18'06.0"W

46°32'04.0"N 060°12'35.0"W

46°40'48.0"N 060°07'47.0"W

47°16'22.0"N 059°37'03.0"W

and 47°36'45.0"N 059°18'13.0"W

DFO(6308158-01)

08-DEC-2017

LNM/D. 01-DEC-2017

Replace depth of 5 fathoms, 1 foot with depth of 4 fathoms, 3 feet
(See Chart No. 1, I10)

47°35'55.4"N 057°42'18.3"W

This notice affects Electronic Navigational Chart: CA276284,
CA376616, CA476622

DFO(6308153-01)

08-DEC-2017

LNM/D. 01-DEC-2017



Chart no. 4015

Replace depth of 10 fathoms with depth of 4 fathoms, 2 feet
(See Chart No. 1, I10)

47°34'25.5"N 057°38'05.9"W

This notice affects Electronic Navigational Chart: CA276284,
CA376619, CA476622

DFO(6308153-05)

01-DEC-2017

LNLM/D. 11-AUG-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 37 fathoms (See Chart No. 1, L25)

47°34'16.8"N 058°46'46.2"W

This notice affects Electronic Navigational Chart: CA179245,
CA276271, CA376625

DFO(6308142-01)

01-DEC-2017

LNLM/D. 11-AUG-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 49 fathoms (See Chart No. 1, L25)

46°58'29.4"N 057°57'32.4"W

This notice affects Electronic Navigational Chart: CA179245,
CA276284

DFO(6308142-02)

01-DEC-2017

LNLM/D. 11-AUG-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 49 fathoms (See Chart No. 1, L25)

46°28'57.6"N 057°22'08.4"W

This notice affects Electronic Navigational Chart: CA179245,
CA276284

DFO(6308142-03)

11-AUG-2017

LNLM/D. 07-JUL-2017

Add environmentally sensitive sea area with legend, St Anns
Bank Marine Protected Area / Zone de protection marine
du banc de Sainte-Anne
(See Chart No. 1, N22)

joining 46°10'00.0"N 059°39'00.0"W

45°47'00.0"N 059°39'00.0"W

45°56'00.0"N 058°40'00.0"W

46°04'00.0"N 058°40'00.0"W

46°04'00.0"N 058°32'00.0"W

46°14'00.0"N 058°22'00.0"W

46°25'00.0"N 058°40'00.0"W

46°25'00.0"N 059°00'00.0"W

46°16'00.0"N 059°20'00.0"W

46°10'00.0"N 059°20'00.0"W

and 46°10'00.0"N 059°39'00.0"W

This notice affects Electronic Navigational Chart:
CA179245, CA276090, CA276204, CA276271, CA276284,
CA376303

DFO(6308006-01)

07-JUL-2017

LNLM/D. 09-JUN-2017



Chart no. 4015

Reposition red and white fairway lighted pillar bell buoy
Mo(A), BELL
(See Chart No. 1, Qh)
This notice affects Electronic Navigational
Chart: CA276271, CA376093

from 46°13'40.0"N 059°55'31.0"W
to 46°13'28.8"N 059°55'37.8"W

(G2017022) LL(771) DFO(6307916-01)

09-JUN-2017

Delete light LF1R 12s 89ft 7M
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA276271, CA376093

LNМ/D. 31-MAR-2017
46°23'06.4"N 060°22'25.8"W
(G2017016) LL(844) DFO(6307919-01)

31-MAR-2017

Delete legend Fog Sig against light
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart:
CA179245, CA276204, CA376303

LNМ/D. 10-MAR-2017
45°54'24.0"N 059°57'30.4"W
(G2016158) LL(756) DFO(6307823-01)

10-MAR-2017

Delete legend FogSig against light
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart:
CA179245, CA376295

LNМ/D. 25-NOV-2016
45°43'02.8"N 060°13'46.4"W
(G2016140) LL(747) DFO(6307757-01)

25-NOV-2016

Amend Fl 15s64ft13M to read Fl 3s64ft13M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA276271, CA376303

LNМ/D. 02-SEP-2016
46°02'04.3"N 059°40'42.0"W
(G2016124) LL(767) DFO(6307705-01)

25-NOV-2016

Delete legend Fog Sig against light
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA179245,
CA276271, CA376303

LNМ/D. 02-SEP-2016
46°02'04.3"N 059°40'42.0"W
DFO(6307705-02)

02-SEP-2016

LNМ/D. 26-AUG-2016



Chart no. 4015

Delete legend Fog Sig against light
(See Chart No. 1, R1, R20) 46°46'00.2"N 056°09'12.3"W
This notice affects Electronic Navigational Chart: CA276091, DFO(6307665-01)
CA376164

26-AUG-2016

Delete fog signal Fog Sig against light LNM/D. 17-JUN-2016
(See Chart No. 1, R1, R20) 45°45'57.0"N 060°06'45.0"W
This notice affects Electronic Navigational Chart: (G2016117) LL(750) DFO(6307659-01)
CA179245, CA276204, CA376295

17-JUN-2016

Amend Fl 10s 105ft 16M to read LFl 6s 105ft LNM/D. 06-MAY-2016
13M against light 45°54'24.0"N 059°57'30.0"W
(See Chart No. 1, P16) (G2016037 & G2016052) LL(756) DFO(6307520-01)
This notice affects Electronic
Navigational Chart: CA179245,
CA276204

06-MAY-2016

Replace depth of 9 fathoms, 1 foot with depth of 8 fathoms LNM/D. 04-MAR-2016
(See Chart No. 1, I10) 47°05'04.4"N 056°09'07.9"W
This notice affects Electronic Navigational Chart: CA276091 DFO(6307517-02)

04-MAR-2016

Amend Fl 3s 64ft 15M to read Fl 15s 64ft 13M against light LNM/D. 12-FEB-2016
(See Chart No. 1, P16) 46°02'03.0"N 059°40'47.1"W
This notice affects Electronic Navigational Chart: (G2015157) LL(767) DFO(6307448-01)
CA179245, CA276271, CA376303

12-FEB-2016

Replace depth of 9 fathoms, 3 feet with depth of 4 fathoms LNM/D. 05-FEB-2016
(See Chart No. 1, I10) 47°05'13.5"N 056°11'42.8"W
This notice affects Electronic Navigational Chart: CA376627 DFO(6307382-14)

12-FEB-2016

Amend F 12M to read LFl 12M against light LNM/D. 05-FEB-2016
(See Chart No. 1, P16) 46°00'25.4"N 059°49'21.7"W
This notice affects Electronic Navigational Chart: (G2015162) LL(765.4) DFO(6307409-01)
CA376303



Chart no. 4015

05-FEB-2016

Amend LFl 6s 111ft 9M to read LFl 6s 111ft 8M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276271,
CA376167

LNM/D. 04-DEC-2015
47°01'43.6"N 060°23'30.6"W
LL(854) DFO(6307366-04)

05-FEB-2016

Amend Fl 5s 85ft 21M to read Fl 5s 85ft 18M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276271,
CA376093, CA576095

LNM/D. 04-DEC-2015
46°15'55.8"N 060°07'32.6"W
LL(775) DFO(6307366-05)

05-FEB-2016

Amend Fl20s 53ft 15M to read Fl20s 53ft 17M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276204,
CA376295

LNM/D. 04-DEC-2015
45°46'00.0"N 060°06'46.5"W
LL(750) DFO(6307366-06)

04-DEC-2015

Add submarine cable joining 45°58'38.1"N 055°53'56.6"W
(See Chart No. 1, L30.1) 45°50'46.9"N 056°38'07.0"W
45°39'21.8"N 057°39'26.6"W
and 45°30'00.6"N 058°27'10.5"W

LNM/D. 27-NOV-2015

DFO(6307279-01)

27-NOV-2015

Delete legend WHIS against yellow, black and yellow West cardinal
pillar buoy
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA276284,
CA376166

LNM/D. 28-AUG-2015
47°01'51.0"N 056°31'44.6"W
DFO(6307313-01)

27-NOV-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 5 fathoms, 3 feet
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276271

LNM/D. 28-AUG-2015
46°15'18.8"N 059°08'28.6"W
DFO(6307340-01)

27-NOV-2015

LNM/D. 28-AUG-2015



Chart no. 4015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 34 fathoms
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276271, CA376303

46°07'47.6"N 059°19'49.7"W
DFO(6307340-02)

28-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 34 fathoms.
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276271

LN/D. 29-MAY-2015
46°10'06.1"N 059°08'44.3"W
DFO(6307181-01)

28-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 143 fathoms.
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276271

LN/D. 29-MAY-2015
46°21'19.4"N 058°43'39.7"W
DFO(6307181-02)

29-MAY-2015

Add obstruction with known depth of 223 fathoms and legend ODAS/SADO
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA176030, CA276090

LN/D. 27-MAR-2015
45°41'45.0"N 057°15'14.4"W
DFO(6307121-01)

29-MAY-2015

Add obstruction with known depth of 180 fathoms and legend ODAS/SADO
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA176030, CA276090

LN/D. 27-MAR-2015
45°30'57.0"N 056°40'19.2"W
DFO(6307121-02)

27-MAR-2015

Delete red and white fairway lighted pillar buoy Mo(A)
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA276271, CA376093

LN/D. 20-FEB-2015
46°18'24.2"N 060°07'50.6"W
(G2015009) LL(776) DFO(6307072-01)

20-FEB-2015

LN/D. 06-FEB-2015



Chart no. 4015

Add subsurface Ocean Data Acquisition system and legend
ODAS/SADO (See Chart No. 1, L25)
This notice affects Electronic Navigational Chart:
CA276271, CA376093

joining 46°34'47.3"N 060°10'46.3"W
46°35'00.2"N 060°11'29.2"W
46°30'45.2"N 060°13'59.6"W
46°30'33.0"N 060°13'16.0"W
and 46°34'47.3"N 060°10'46.3"W

DFO(6307036-02)

06-FEB-2015

Delete green port hand lighted spar buoy FlG, marked
V23
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA276274

LNm/D. 30-JAN-2015
47°28'41.6"N 056°03'24.9"W

(N2014077) LL(130.31) DFO(6307002-01)

06-FEB-2015

Amend Fl(2)25s74ft10M to read LFl74ft8M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA179172, CA276271, CA376093

LNm/D. 30-JAN-2015
46°10'51.0"N 059°46'13.2"W

(G2014202) LL(770) DFO(6307010-01)

06-FEB-2015

Delete legend FogSig against light
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart:
CA276271, CA376093

LNm/D. 30-JAN-2015
46°10'51.0"N 059°46'13.2"W

(G2014213) LL(770) DFO(6307010-02)

30-JAN-2015

Amend F 48ft 11M to read LFl 62ft 11M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA276204, CA376295

LNm/D. 09-JAN-2015
45°43'02.8"N 060°13'46.4"W

(G2014197) LL(747) DFO(6306995-01)

09-JAN-2015

Delete light Fl 12s 131ft 12M
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA179172, CA276271, CA376167

LNm/D. 25-JUL-2014
47°13'35.0"N 060°08'24.0"W

(G2014187) LL(1476) DFO(6306973-01)

09-JAN-2015

LNm/D. 25-JUL-2014



Chart no. 4015

Delete light Fl 4s 150ft 7M 47°11'15.0"N 060°09'36.0"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2014188) LL(1477) DFO(6306973-02)
CA179172, CA276271, CA376167

25-JUL-2014

Add wreck, least depth unknown LNM/D. 07-FEB-2014
(See Chart No. 1, K29) 46°49'38.4"N 056°05'09.0"W
This notice affects Electronic Navigational Chart: CA276091, DFO(6306742-01)
CA376164

25-JUL-2014

Add wreck, least depth unknown LNM/D. 07-FEB-2014
(See Chart No. 1, K29) 46°49'19.4"N 056°06'49.3"W
This notice affects Electronic Navigational Chart: CA276091, DFO(6306742-02)
CA376164

07-FEB-2014

Reposition Non-dangerous wreck, depth unknown with legend LNM/D. 27-DEC-2013
"PA" from 46°30'00.0"N 056°51'54.0"W
to 46°31'48.0"N 056°55'15.0"W
(See Chart No. 1, K29)
This notice affects Electronic Navigational Chart: DFO(6306621-01)
CA276284

07-FEB-2014

Reposition black and yellow North cardinal lighted pillar LNM/D. 27-DEC-2013
whistle buoy Q, WHIS. from 47°29'55.8"N 057°05'35.4"W
to 47°28'26.4"N 057°05'35.4"W
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: (N2014001) LL(139.21) DFO(6306660-01)
CA276284

27-DEC-2013

Delete black and yellow North cardinal lighted pillar LNM/D. 20-DEC-2013
whistle buoy Q, WHIS. 47°28'41.8"N 057°05'24.7"W
(See Chart No. 1, Q130.3) (N2013038) LL(139.21) DFO(6306583-01)
This notice affects Electronic Navigational Chart: CA276284

27-DEC-2013

LNM/D. 20-DEC-2013



Chart no. 4015

Add black and yellow North cardinal lighted pillar
whistle buoy Q, WHIS. 47°29'55.8"N 057°05'35.4"W
(See Chart No. 1, Q130.3) (N2013038) LL(139.21) DFO(6306583-02)
This notice affects Electronic Navigational Chart:
CA276284

20-DEC-2013 LNM/D. 22-NOV-2013
Delete depth of 44 fathoms over artificial feature 46°56'48.0"N 060°06'37.2"W
(See Chart No. 1, Ka)
This notice affects Electronic Navigational Chart: CA276271, DFO(6306525-02)
CA376167

22-NOV-2013 LNM/D. 18-OCT-2013
Delete maritime limit in general implying: no permanent between 47°01'50.0"N 060°22'48.0"W
obstructions and 47°10'48.5"N 060°09'55.5"W
(See Chart No. 1, N1.2)
This notice affects Electronic Navigational Chart: DFO(6306508-01)
CA276271, CA376167

22-NOV-2013 LNM/D. 18-OCT-2013
Delete maritime limit in general implying: no permanent between 47°15'28.8"N 060°05'54.2"W
obstructions and 47°17'24.2"N 060°04'31.4"W
(See Chart No. 1 N1.2)
This notice affects Electronic Navigational Chart: DFO(6306508-02)
CA276271

22-NOV-2013 LNM/D. 18-OCT-2013
Add maritime limit in general implying: permanent physical between 47°02'47.0"N 060°21'56.0"W
obstructions and 47°10'40.6"N 060°10'07.0"W
(See Chart No. 1, N1.1)
This notice affects Electronic Navigational Chart: DFO(6306508-03)
CA276271, CA376167

22-NOV-2013 LNM/D. 18-OCT-2013
Add maritime limit in general implying: permanent physical between 47°13'37.0"N 060°07'25.0"W
obstructions and 47°36'47.2"N 059°19'24.4"W
(see Chart 1, N1.1)
This notice affects Electronic Navigational Chart: DFO(6306508-04)
CA276271, CA376167

22-NOV-2013 LNM/D. 18-OCT-2013



Chart no. 4015

Add maritime limit in general implying: permanent physical obstructions (see Chart 1, N1.1)
This notice affects Electronic Navigational Chart: CA276271

joining 47°14'55.6"N 060°04'42.4"W
47°22'10.6"N 060°14'20.4"W
and 47°26'18.2"N 059°59'00.0"W

DFO(6306508-05)

22-NOV-2013

Reposition See/Voir note SCIENTIFIC MOORINGS
MOUILLAGES SCIENTIFIQUES

LNM/D. 18-OCT-2013
from 47°07'32.0"N 060°09'00.0"W
to 47°22'00.0"N 059°40'00.0"W

DFO(6306508-06)

18-OCT-2013

Add WHIS to red and white fairway lighted pillar whistle buoy, marked U
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA276271, CA376093

LNM/D. 11-OCT-2013
46°21'28.2"N 060°14'49.1"W

DFO(6306469-01)

11-OCT-2013

Delete light F 84ft 12M
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA276271, CA376093, CA476063

LNM/D. 21-JUN-2013
46°20'13.0"N 060°17'36.0"W

(G2013017) LL(796) DFO(6306366-01)

11-OCT-2013

Add light LFl 6s 88ft 14M
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276271, CA376093, CA476063

LNM/D. 21-JUN-2013
46°20'10.3"N 060°17'31.9"W

(G2013017) LL(796) DFO(6306366-02)

21-JUN-2013

Add red and white fairway lighted pillar whistle buoy LFl, marked U
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA276271, CA376093

LNM/D. 19-APR-2013
46°21'28.2"N 060°14'49.1"W

(G2013018) LL(789.5) DFO(6306369-01)

19-APR-2013

LNM/D. 02-NOV-2012



Chart no. 4015

Delete red starboard hand lighted pillar whistle buoy WHIS,
FIR

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA276271, CA376093

46°21'28.2"N 060°14'49.1"W

(G2013007) LL(795) DFO(6306343-01)

02-NOV-2012

Delete Legend 'Fog Sig' against light
(See Chart No 1 R20)

This notice affects Electronic Navigational Chart:
CA476063

LNМ/D. 30-MAR-2012

46°20'13.6"N 060°17'36.8"W

(G2012175) LL(796) DFO(6306188-01)

30-MAR-2012

Delete depth of 12 fathoms 47°14'00.0"N 055°58'45.0"W
(See Chart No. 1, I10)

DFO(6305953-01)

LNМ/D. 24-FEB-2012

30-MAR-2012

Add depth of 7 fathoms, 4 feet 47°13'54.7"N 055°58'34.5"W
(See Chart No. 1, I10)

DFO(6305953-02)

LNМ/D. 24-FEB-2012

24-FEB-2012

Amend F 59ft 13 M to read LFl 59ft 9 M against light
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA276271, CA376167

LNМ/D. 03-FEB-2012

46°48'31.3"N 060°19'07.5"W

(G2012007) LL(851) DFO(6305919-01)

03-FEB-2012

Add yellow ODAS/SADO lighted super-buoy Fl (5) Y
(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart: CA276091,
CA376164

LNМ/D. 06-JAN-2012

46°42'06.0"N 056°11'18.0"W

DFO(6305904-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4015

06-JAN-2012

Delete depth of 19 fathoms
(See Chart No. 1, I10)

LN/D. 08-JUL-2011

47°24'54.5"N 055°56'47.0"W

DFO(6305865-01)

This notice affects Electronic Navigational Chart: CA276274

06-JAN-2012

Add depth of 10 fathoms, 2 feet
(See Chart No. 1, I10)

LN/D. 08-JUL-2011

47°24'57.2"N 055°56'58.0"W

DFO(6305865-02)

This notice affects Electronic Navigational Chart: CA276274

08-JUL-2011

Add black, yellow, black East cardinal pillar light buoy, Q (3) 10s,
marked KF
(See Chart No. 1, Q130.3)

LN/D. 06-MAY-2011

46°41'13.1"N 060°19'23.5"W

LL(848.5) DFO(6305544-01)

06-MAY-2011

Amend Fl 15s 64ft 17M to read Fl 3s 64ft 15M against light
(See Chart No 1 P16)

LN/D. 18-MAR-2011

46°02'04.3"N 059°40'33.7"W

(G2011058) LL(767) DFO(6305358-01)

This notice affects Electronic Navigational Chart:
CA179172

18-MAR-2011

Amend FLR 12s 89ft 5M to read LFLR 12s 89ft 7M against
light
(See Chart No. 1 P16)

LN/D. 04-MAR-2011

46°23'06.4"N 060°22'25.8"W

(G2011051) LL(844) DFO(6305271-01)

18-MAR-2011

Delete depth of 1 fathom, 3 feet 45°43'13.5"N 060°13'26.0"W
(See Chart No. 1, I10)

LN/D. 04-MAR-2011

DFO(6305289-10)

04-MAR-2011

LN/D. 11-FEB-2011



Chart no. 4015

Add depth of 44 fathoms over artificial feature
(See Chart No 1 Ka) 46°56'48.0"N 060°06'37.2"W
The mooring is temporary. The proposed date of removal is June *DFO(6305243-02)*
2011.

This notice affects Electronic Navigational Chart: CA376167

11-FEB-2011 LNM/D. 27-AUG-2010
Amend Fl 30s 64ft 17M to read Fl 15s 64ft 17M against 46°02'04.3"N 059°40'33.7"W
light
(See Chart No. 1 P16) *(G2010239) LL(767) DFO(6305189-01)*

27-AUG-2010 LNM/D. 04-JUN-2010
Amend Fl 30s 64ft 23M to read Fl 30s 64ft 17M against light 46°02'04.3"N 059°40'33.7"W
(See Chart No. 1 P16) *LL(767) DFO(6304986-01)*

This notice affects Electronic Navigational Chart: CA376303

27-AUG-2010 LNM/D. 04-JUN-2010
Amend F to read F 12M against light 46°00'25.4"N 059°49'21.7"W
(See Chart No. 1 P16) *LL(765.4) DFO(6304986-02)*

This notice affects Electronic Navigational Chart: CA376303

04-JUN-2010 LNM/D. 26-MAR-2010
Amend Fl12s 126ft 18M to read Fl12s 131ft 12M against light. 47°13'35.1"N 060°08'25.5"W
(See Chart No 1 P16) *LL(1476) DFO(6304795-01)*

04-JUN-2010 LNM/D. 26-MAR-2010
Reposition red and white fairway lighted pillar bell buoy from 47°33'46.0"N 057°07'14.0"W
BELL, Mo(A) to 47°33'51.5"N 057°06'43.7"W
(See Chart No 1 Qh) *(N2010016) LL(139.3) DFO(6304883-01)*

26-MAR-2010 LNM/D. 11-DEC-2009



Chart no. 4015

Add maritime limit in general implying: no permanent obstructions
(see Chart 1, N1.2)

between 47°01'50.0"N 060°22'48.0"W
and 47°10'48.5"N 060°09'55.5"W

DFO(6304706-01)

This notice affects Electronic Navigational Chart:
CA376167

26-MAR-2010

LNM/D. 11-DEC-2009

Add maritime limit in general implying: no permanent obstructions
(see Chart 1 N1.2)

between 47°15'28.8"N 060°05'54.2"W
and 47°17'24.2"N 060°04'31.4"W

DFO(6304706-02)

26-MAR-2010

LNM/D. 11-DEC-2009

Add See/Voir note
SCIENTIFIC MOORINGS
MOUILLAGES SCIENTIFIQUES

47°07'32.0"N 060°09'00.0"W

DFO(6304706-03)

This notice affects Electronic Navigational Chart: CA376167

26-MAR-2010

LNM/D. 11-DEC-2009

Add note:
SCIENTIFIC MOORINGS
Acoustic sensors, one metre high and positioned approximately 800 metres apart, along the line, directly on the seabed. Mariners are advised to avoid anchoring or conducting seabed operations in the vicinity of submarine moorings.

46°04'00.0"N 060°19'00.0"W

DFO(6304706-04)

MOUILLAGES SCIENTIFIQUES

Des capteurs acoustiques, d'une hauteur d'un mètre et positionnés à intervalles d'environ 800 mètres le long de la ligne, reposent directement sur le fond marin. Nous avisons les navigateurs d'éviter de mouiller ou d'effectuer des travaux sur le fond marin à proximité de ces mouillages sous-marins.

This notice affects Electronic Navigational Chart: CA376167

11-DEC-2009

LNM/D. 21-AUG-2009



Chart no. 4015

Delete red starboard hand lighted pillar buoy QR,
marked V30
(See Chart No 1 Qf) 47°28'01.0"N 056°01'00.5"W
(N2009049) LL(130.32) DFO(6304639-01)

11-DEC-2009 LNM/D. 21-AUG-2009
Delete black and yellow North cardinal lighted pillar
buoy Q 47°28'35.5"N 057°05'54.0"W
(See Chart No 1 Q130.3) (N2009051) LL(139.21) DFO(6304640-01)

This notice affects Electronic Navigational Chart:
CA276284

11-DEC-2009 LNM/D. 21-AUG-2009
Add black and yellow North cardinal lighted pillar
whistle buoy Q 47°28'41.6"N 057°05'25.0"W
(See Chart No 1 Q130.3) (N2009051) LL(139.21) DFO(6304640-02)

11-DEC-2009 LNM/D. 21-AUG-2009
Amend Fl 9s 105ft 17M to read Fl 10s 105ft 16M against light 45°54'30.0"N 059°57'30.5"W
(See Chart No 1 P16) LL(756) DFO(6304648-01)

This notice affects Electronic Navigational Chart: CA179172

21-AUG-2009 LNM/D. 22-MAY-2009
Amend legend Fl 6s 104ft 13M to read LFl 6s 111ft 9M against light 47°01'44.0"N 060°23'30.1"W
(See Chart No 1 P16) LL(854) DFO(6304519-01)

This notice affects Electronic Navigational Chart: CA179172,
CA276271

22-MAY-2009 LNM/D. 06-FEB-2009
Add legend Chart/Carte 4827 47°17'47.0"N 056°26'00.0"W
(See Chart No 1 A18) DFO(6304355-05)

06-FEB-2009 LNM/D. 31-OCT-2008



Chart no. 4015

Add submarine cable joining 47°36'54.2"N 057°34'39.1"W
(See Chart No 1 L30.1) 47°36'13.8"N 057°33'59.7"W
47°35'23.1"N 057°34'16.8"W
47°32'33.2"N 057°40'30.9"W
47°36'39.4"N 058°06'18.5"W
and 47°35'47.0"N 058°41'16.9"W

DFO(6304173-01)

06-FEB-2009

LNM/D. 31-OCT-2008

Add submarine cable joining 47°23'12.0"N 055°53'56.6"W
(See Chart No 1 L30.1) 47°22'41.8"N 055°54'41.2"W
47°21'32.2"N 055°59'40.7"W
47°34'47.3"N 057°30'56.1"W
47°35'49.8"N 057°32'42.7"W
47°36'26.7"N 057°33'04.0"W
and 47°36'56.7"N 057°34'36.0"W

DFO(6304173-02)

31-OCT-2008

LNM/D. 01-AUG-2008

Add depth of 8 fathoms, 2 feet
(See Chart No. 1, I10)

47°26'55.8"N 057°16'17.4"W

DFO(6304083-08)

This notice affects Electronic Navigational Chart: CA276284

31-OCT-2008

LNM/D. 01-AUG-2008

Add depth of 7 fathoms, 3 feet
(See Chart No. 1, I10)

47°26'41.4"N 057°10'38.9"W

DFO(6304083-13)

This notice affects Electronic Navigational Chart: CA276284

31-OCT-2008

LNM/D. 01-AUG-2008

Delete depth of 11 fathoms
(See Chart No. 1, I10)

47°27'03.8"N 057°08'04.0"W

DFO(6304083-17)

This notice affects Electronic Navigational Chart: CA276284

31-OCT-2008

LNM/D. 01-AUG-2008



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4015

Add depth of 6 fathoms, 1 foot
(See Chart No. 1, I10)

47°27'05.9"N 057°07'56.3"W

DFO(6304083-18)

This notice affects Electronic Navigational Chart: CA276284

31-OCT-2008

Delete depth of 11 fathoms
(See Chart No. 1, I10)

LNM/D. 01-AUG-2008
47°22'45.3"N 056°57'31.7"W

DFO(6304083-20)

This notice affects Electronic Navigational Chart: CA276284

31-OCT-2008

Add depth of 4 fathoms, 5 feet
(See Chart No. 1, I10)

LNM/D. 01-AUG-2008
47°22'55.1"N 056°57'38.0"W

DFO(6304083-22)

This notice affects Electronic Navigational Chart: CA276284

01-AUG-2008

Add submarine cable

LNM/D. 25-JUL-2008
between 47°34'44.2"N 058°42'35.6"W
and 46°20'10.3"N 060°03'12.1"W

This notice affects Electronic Navigational Chart:
CA179172, CA276271, CA576095

DFO(6303984-01)

25-JUL-2008

Add submarine cable

LNM/D. 04-APR-2008
joining 46°20'18.5"N 060°09'14.4"W
46°46'07.1"N 059°47'30.8"W
and 47°32'45.3"N 059°08'03.2"W

This notice affects Electronic Navigational Chart:
CA179172, CA276271, CA576095

DFO(6303964-01)

04-APR-2008

Reposition red starboard hand lighted pillar buoy QR, marked
V30
(See Chart No 1 Qf)

LNM/D. 01-FEB-2008
from 47°29'00.0"N 056°01'30.0"W
to 47°28'01.0"N 056°01'00.5"W

LL(130.32) DFO(6303795-01)

01-FEB-2008

LNM/D. 17-AUG-2007



Chart no. 4015

Delete legend Fog Sig against light
(See Chart No 1 R20)

46°16'01.5"N 060°07'32.9"W

(G2007178) LL(775) DFO(6303745-01)

This notice affects Electronic Navigational Chart:
CA276271, CA576095

17-AUG-2007

LNМ/D. 13-JUL-2007

Delete red starboard hand lighted pillar bell buoy FlR,
BELL

47°37'00.0"N 058°27'00.0"W

(N2005012) LL(145.5) DFO(6303555-01)

This notice affects Electronic Navigational Chart:
CA276271

13-JUL-2007

LNМ/D. 17-NOV-2006

Delete WHIS against red and white fairway lighted pillar
whistle buoy Mo(A)

46°18'24.2"N 060°07'50.6"W

(G2007037) LL(776) DFO(6303451-01)

17-NOV-2006

LNМ/D. 03-NOV-2006

Reposition yellow ODAS/SADO lighted super-buoy Fl (5) Y,
marked 44255

from 47°16'54.0"N 057°21'06.0"W
to 47°16'06.0"N 057°21'06.0"W

(BRITAD:3816) DFO(6303120-01)

03-NOV-2006

LNМ/D. 28-APR-2006

Delete legend "Chart/Carte 4633" 47°20'00.0"N 056°52'00.0"W

DFO(6303058-06)

03-NOV-2006

LNМ/D. 28-APR-2006

Add legend "Chart/Carte 4826" 47°22'00.0"N 057°10'00.0"W

DFO(6303058-07)

28-APR-2006

LNМ/D. 30-DEC-2005

Amend "Fl" to read "Q G" against light

47°34'30.0"N 057°06'46.0"W

(N2005082) LL(139.5) DFO(6302569-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4015

30-DEC-2005

LNM/D. 08-JUL-2005

Amend "Fl 5s 207ft 6M" to read "Fl 5s 207ft 16M" against light 47°36'23.2"N 057°35'12.2"W

LL(144) DFO(6302647-01)

08-JUL-2005

LNM/D. 24-JUN-2005

Delete green port hand lighted pillar buoy FlG

47°29'44.9"N 057°27'03.2"W

(N2005026) LL(140.9) DFO(6302329-01)

24-JUN-2005

LNM/D. 08-APR-2005

Add WHIS to red and white fairway pillar light buoy

47°35'28.1"N 058°41'42.8"W

(N2005025) LL(148.9) DFO(6302326-01)

24-JUN-2005

LNM/D. 08-APR-2005

Amend 'Chart/Carte 4635' to read 'Chart/Carte 4823' 47°24'30.0"N 058°45'00.0"W

DFO(6302335-01)

24-JUN-2005

LNM/D. 08-APR-2005

Amend 'Chart/Carte 4634' to read 'Chart/Carte 4824' 47°25'00.0"N 057°53'00.0"W

DFO(6302335-02)

08-APR-2005

LNM/D. 07-JAN-2005

Delete sounding of 8 fathoms 4 feet 47°04'36.0"N 056°12'18.0"W

DFO(6302256-01)

08-APR-2005

LNM/D. 07-JAN-2005

Add sounding of 6 fathoms 47°04'30.0"N 056°12'23.0"W

DFO(6302256-02)

08-APR-2005

LNM/D. 07-JAN-2005



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4015

Add sounding of 57 fathoms 46°07'15.0"N 058°56'20.0"W

DFO(6302257-01)

08-APR-2005

LNМ/D. 07-JAN-2005

Add sounding of 54 fathoms 46°02'45.0"N 058°54'48.0"W

DFO(6302257-02)

08-APR-2005

LNМ/D. 07-JAN-2005

Add sounding of 53 fathoms 46°01'06.0"N 058°54'54.0"W

DFO(6302257-03)

08-APR-2005

LNМ/D. 07-JAN-2005

Add sounding of 39 fathoms 46°02'18.0"N 058°49'21.0"W

DFO(6302257-04)

08-APR-2005

LNМ/D. 07-JAN-2005

Add sounding of 83 fathoms 46°05'18.0"N 058°44'00.0"W

DFO(6302257-05)

07-JAN-2005

Amend "Fl(2) 25s 70ft 16M" to read "Fl(2) 25s 74ft 10M"
against light

LNМ/D. 31-DEC-2004

46°10'48.9"N 059°46'08.0"W

(G2004198) LL(770) DFO(6302126-01)

31-DEC-2004

LNМ/D. 10-DEC-2004

Amend "Fl 10s 72ft 6M" to read "Fl 10s 72ft 17M" against light 47°22'53.5"N 056°59'17.0"W

LL(139) DFO(6302111-02)

31-DEC-2004

LNМ/D. 10-DEC-2004

Amend "Fl 3s 125ft 8M" to read "Fl 3s 125ft 14M" against light 47°30'45.0"N 057°24'32.0"W

LL(141) DFO(6302111-03)



Chart no. 4015

10-DEC-2004 LNM/D. 03-DEC-2004
Add legend 'Aband' 46°39'20.0"N 060°05'20.0"W

DFO(6302050-03)

10-DEC-2004 LNM/D. 03-DEC-2004
Add legend 'Aband' 46°40'40.0"N 060°11'15.0"W

DFO(6302050-04)

10-DEC-2004 LNM/D. 03-DEC-2004
Add legend 'Aband' 47°21'45.0"N 058°17'30.0"W

DFO(6302050-05)

10-DEC-2004 LNM/D. 03-DEC-2004
Add legend 'Aband' 47°17'30.0"N 058°16'45.0"W

DFO(6302050-06)

10-DEC-2004 LNM/D. 03-DEC-2004
Add legend 'Aband' 47°15'45.0"N 056°22'15.0"W

DFO(6302050-07)

10-DEC-2004 LNM/D. 03-DEC-2004
Add legend 'Aband' 47°21'00.0"N 056°21'00.0"W

DFO(6302050-08)

10-DEC-2004
Delete green port hand pillar light and whistle buoy FlG,
WHIS

LNM/D. 03-DEC-2004
47°31'54.4"N 057°18'57.1"W

(N2004184) LL(140) DFO(6302057-01)

03-DEC-2004

LNM/D. 04-JUN-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4015

Amend "Fl 15s 118ft 23M" to read "Fl 15s 118ft 17M" against light 47°37'16.0"N 059°18'00.0"W

LL(173) DFO(6302007-01)

04-JUN-2004

LNМ/D. 12-MAR-2004

Add red and white fairway pillar light buoy Mo (A) 47°35'28.1"N 058°41'42.8"W

LL(148.9) DFO(6301438-01)

12-MAR-2004

LNМ/D. 27-FEB-2004

Delete legend "Fog Sig" 47°01'44.3"N 060°23'28.9"W

(G2003150) LL(854) DFO(6301187-01)

12-MAR-2004

LNМ/D. 27-FEB-2004

Add light FlR 10s 95ft 13M 47°36'06.5"N 058°41'40.4"W

(N2004008) LL(150.19) DFO(6301252-02)

12-MAR-2004

LNМ/D. 27-FEB-2004

Delete light FlR 10s 50ft 8M, Fog Sig 47°36'05.9"N 058°42'02.0"W

(N2004008) LL(150.19) DFO(6301252-04)

27-FEB-2004

LNМ/D. 13-FEB-2004

Replace red starboard hand pillar light buoy FlR, BELL,
with red starboard hand spar light buoy FlR 47°29'40.0"N 057°22'30.0"W

(N2003060) LL(140.5) DFO(6301164-01)

13-FEB-2004

LNМ/D. 23-JAN-2004

Delete Fog Sig 47°33'40.0"N 056°44'05.0"W

(N2002122) LL(137.2) DFO(6300546-01)

13-FEB-2004

LNМ/D. 23-JAN-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4015

Amend "Fl 5s 151ft 8M" to read "FlG 5s 151ft 15M" against
light

47°33'40.0"N 056°44'05.0"W

(N2002125) LL(137) DFO(6300550-01)

13-FEB-2004

LN/D. 23-JAN-2004

Add green port hand spar light buoy Fl G, marked V23

47°28'41.6"N 056°03'24.9"W

(N2002134) LL(130.31) DFO(6300570-01)

23-JAN-2004

Delete red and white fairway pillar light buoy Mo(A), WHIS 47°35'30.0"N 058°41'45.0"W

DFO(6301144-01)