



**Chart no. 4210**

**4210 - Cape Sable to / à Pubnico Harbour - New Chart - 05-APR-1991 - NAD 1983**

**13-AUG-2021**

LN/D. 23-APR-2021

Add depth of 1.9 metres

43°33'12.1"N 065°46'58.1"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476043

*DFO(6309560-01)*

**13-AUG-2021**

LN/D. 23-APR-2021

Add drying height of 0.8 metres

43°33'00.7"N 065°46'49.9"W

(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA476043

*DFO(6309560-02)*

**13-AUG-2021**

LN/D. 23-APR-2021

Delete depth of 2.4 metres

43°32'13.6"N 065°44'41.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476043

*DFO(6309560-03)*

**13-AUG-2021**

LN/D. 23-APR-2021

Add depth of 0.5 metres

43°32'12.7"N 065°44'43.4"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476043

*DFO(6309560-04)*

**13-AUG-2021**

LN/D. 23-APR-2021

Add drying height of 0.7 metres

43°31'04.8"N 065°44'46.7"W

(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA476043

*DFO(6309560-05)*

**13-AUG-2021**

LN/D. 23-APR-2021

Delete depth of 0.6 metres

43°30'33.7"N 065°45'10.9"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476043

*DFO(6309560-06)*

**13-AUG-2021**

LN/D. 23-APR-2021

Add drying height of 0.3 metres

43°30'32.7"N 065°45'10.5"W

(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA476043

*DFO(6309560-07)*

**13-AUG-2021**

LN/D. 23-APR-2021



### Chart no. 4210

Delete depth of 7.3 metres 43°29'13.2"N 065°43'17.8"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476043 *DFO(6309560-08)*

**13-AUG-2021** LNM/D. 23-APR-2021  
Add depth of 4.6 metres 43°29'15.0"N 065°43'18.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476043 *DFO(6309560-09)*

**13-AUG-2021** LNM/D. 23-APR-2021  
Add depth of 0.5 metres 43°29'21.4"N 065°41'47.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476043 *DFO(6309560-10)*

**13-AUG-2021** LNM/D. 23-APR-2021  
Delete depth of 3 metres 43°29'11.4"N 065°41'29.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476043 *DFO(6309560-11)*

**13-AUG-2021** LNM/D. 23-APR-2021  
Add depth of 0.6 metres 43°29'10.0"N 065°41'27.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476043 *DFO(6309560-12)*

**13-AUG-2021** LNM/D. 23-APR-2021  
Add depth of 0.1 metres 43°28'25.8"N 065°41'08.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476043 *DFO(6309560-13)*

**13-AUG-2021** LNM/D. 23-APR-2021  
Add depth of 0.6 metres 43°28'37.1"N 065°40'58.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476043 *DFO(6309560-14)*

**13-AUG-2021** LNM/D. 23-APR-2021  
Add depth of 3.9 metres 43°28'21.7"N 065°38'50.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476043 *DFO(6309560-15)*



## Chart no. 4210

### 13-AUG-2021

Add WARNING Recent bathymetric surveys show the presence of shallower depths compared to what is presently charted. The shallower depths considered the most hazardous to navigation and within or near main shipping channels will be published in Notices to Mariners (WWW.NOTMAR.CA). Mariners are advised to exercise extreme caution, specifically when they navigate outside of the marked navigation channels. AVERTISSEMENT Des levés bathymétriques récents ont révélé la présence de profondeurs moindres que celles portées sur les cartes marines. Les profondeurs moindres les plus dangereuses pour la navigation et dans ou près des principales voies de navigation seront publiées dans les Avis aux navigateurs (WWW.NOTMAR.CA). Nous demandons aux navigateurs d'exercer la plus grande prudence, particulièrement lors de la navigation en dehors des voies de navigation balisées. This notice affects Electronic Navigational Chart: CA476043

LNM/D. 23-APR-2021  
43°34'12.6"N 065°41'52.6"W

*DFO(6309560-16)*

### 23-APR-2021

Delete drying height of 0.2 metres  
(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA476105

LNM/D. 10-MAY-2019  
43°37'10.9"N 065°47'13.1"W

*DFO(6309390-01)*

### 23-APR-2021

Add pier  
(See Chart No. 1, F14)  
This notice affects Electronic Navigational Chart:  
CA376014, CA476105

LNM/D. 10-MAY-2019  
joining 43°37'10.4"N 065°47'20.8"W  
43°37'11.8"N 065°47'13.4"W  
and 43°37'10.0"N 065°47'12.8"W

*DFO(6309390-02)*

### 10-MAY-2019

Delete legend "Hospital Reef" 43°26'40.4"N 065°39'33.8"W

*DFO(6308621-02)*

LNM/D. 05-JAN-2018

### 05-JAN-2018

Delete fog signal against light  
(See Chart No. 1, R1)

This notice affects Electronic Navigational Chart:  
CA376014, CA476043

LNM/D. 09-JUN-2017  
43°31'10.0"N 065°44'43.2"W

*(F2017020) LL(312) DFO(6307973-01)*

### 09-JUN-2017

LNM/D. 24-MAR-2017



**Chart no. 4210**

Add marine farm 43°36'23.7"N 065°47'02.0"W  
 (See Chart No. 1, K48.2)  
 This notice affects Electronic Navigational Chart: CA476043 *DFO(6307872-03)*

**09-JUN-2017** LNM/D. 24-MAR-2017  
 Add marine farm 43°27'54.5"N 065°38'57.3"W  
 (See Chart No. 1, K48.2)  
 This notice affects Electronic Navigational Chart: CA376047, *DFO(6307872-04)*  
 CA476043

**09-JUN-2017** LNM/D. 24-MAR-2017  
 Add marine farm 43°37'46.7"N 065°49'28.0"W  
 (See Chart No. 1, K48.2)  
 This notice affects Electronic Navigational Chart: CA476043 *DFO(6307872-05)*

**24-MAR-2017** LNM/D. 07-OCT-2016  
 Add light FLR 43°31'50.7"N 065°44'33.2"W  
 (See Chart No. 1, P1)  
 This notice affects Electronic Navigational Chart: *(F2016063) LL(315.4) DFO(6307799-01)*  
 CA376014, CA476043

**07-OCT-2016** LNM/D. 06-MAY-2016  
 Add private light Fl R(Priv) 43°27'35.6"N 065°39'07.4"W  
 (See Chart No. 1, P65)  
 This notice affects Electronic Navigational Chart: CA476043 *LL(319.2) DFO(6307681-01)*

**07-OCT-2016** LNM/D. 06-MAY-2016  
 Add light FLG 43°27'35.4"N 065°39'04.9"W  
 (See Chart No. 1, P65)  
 This notice affects Electronic Navigational Chart: CA476043 *LL(319.4) DFO(6307681-03)*

**07-OCT-2016** LNM/D. 06-MAY-2016  
 Add breakwater with legend Bkw joining 43°27'35.4"N 065°39'04.9"W  
 (See Chart No. 1, F4.1) 43°27'34.6"N 065°38'57.6"W  
 This notice affects Electronic Navigational Chart: 43°27'32.2"N 065°38'58.0"W  
 CA476043 and 43°27'30.8"N 065°38'55.1"W  
*DFO(6307681-04)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4210

### 06-MAY-2016

LNМ/D. 26-FEB-2016

Add light Fl G against beacon with radar reflector  
(See Chart No. 1, Q81, P16)

43°26'06.5"N 065°39'13.2"W

This notice affects Electronic Navigational Chart:  
CA376047, CA476043

(F2016010) LL(323.6) DFO(6307486-01)

### 26-FEB-2016

LNМ/D. 09-SEP-2011

Amend Fl to read LFl against light  
(See Chart No. 1, P16)

43°32'11.8"N 065°44'36.4"W

This notice affects Electronic Navigational Chart:  
CA376014, CA476043

(F2015042) LL(315.3) DFO(6307424-01)

### 09-SEP-2011

LNМ/D. 26-AUG-2011

Delete radar reflector  
(See Chart No. 1, S4)

43°30'51.3"N 065°48'17.9"W

This notice affects Electronic Navigational Chart: CA376014,  
CA476043

(F2011161) DFO(6305681-01)

### 09-SEP-2011

LNМ/D. 26-AUG-2011

Delete radar reflector  
(See Chart No. 1, S4)

43°25'13.6"N 065°40'42.1"W

This notice affects Electronic Navigational Chart: CA376014,  
CA476043

(F2011162) DFO(6305682-01)

### 26-AUG-2011

LNМ/D. 15-JUL-2011

Delete depth of 2 metres, 1 decimetre  
(See Chart No. 1, I10)

43°31'33.6"N 065°44'39.6"W

This notice affects Electronic Navigational Chart: CA476043

DFO(6305662-01)

### 26-AUG-2011

LNМ/D. 15-JUL-2011

Add depth of 1 metre, 8 decimetres  
(See Chart No. 1, I10)

43°31'36.3"N 065°44'40.0"W

This notice affects Electronic Navigational Chart: CA476043

DFO(6305662-02)



### Chart no. 4210

**15-JUL-2011**

LNМ/D. 08-JUL-2011

Delete depth of 0 metres, 9 decimetres 43°28'24.5"N 065°37'56.3"W  
(See Chart No. 1, I10)

*DFO(6305367-01)*

**15-JUL-2011**

LNМ/D. 08-JUL-2011

Add breakwater with legend Bkw between 43°28'26.4"N 065°37'59.2"W  
(See Chart 1 F4.1) and 43°28'19.6"N 065°37'54.0"W

*DFO(6305367-02)*

**15-JUL-2011**

LNМ/D. 08-JUL-2011

Add light FLG 43°28'26.4"N 065°37'59.2"W  
(See Chart No. 1, P1)

*(F2011088) LL(317.1) DFO(6305367-03)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Delete rock dries 3 metres 43°31'50.5"N 065°44'30.0"W  
(See Chart No. 1, K11)

*DFO(6305537-01)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Delete depth of 1 metre, 5 decimetres 43°31'44.7"N 065°44'27.3"W  
(See Chart No. 1, I10)

*DFO(6305537-02)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Add breakwater with legend Bkw joining 43°31'53.6"N 065°44'28.6"W  
(See Chart No. 1, F4.1) 43°31'51.1"N 065°44'28.6"W  
43°31'50.6"N 065°44'33.6"W  
43°31'46.3"N 065°44'33.2"W  
and 43°31'44.7"N 065°44'26.5"W

*DFO(6305537-03)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Add depth of 1 metre, 6 decimetres 43°31'44.7"N 065°44'21.5"W  
(See Chart No. 1, I10)

*DFO(6305537-04)*



### Chart no. 4210

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Add depth of 1 metre, 3 decimetres 43°31'42.4"N 065°44'34.8"W  
(See Chart No. 1, I10)

*DFO(6305537-05)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Add depth of 2 metres, 1 decimetre 43°31'33.6"N 065°44'39.6"W  
(See Chart No. 1, I10)

*DFO(6305537-06)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Add depth of 2 metres, 7 decimetres 43°31'28.7"N 065°44'40.6"W  
(See Chart No. 1, I10)

*DFO(6305537-07)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Add depth of 1 metre, 2 decimetres 43°31'31.2"N 065°44'52.8"W  
(See Chart No. 1, I10)

*DFO(6305537-08)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Add depth of 2 metres 43°31'37.3"N 065°44'33.4"W  
(See Chart No. 1, I10)

*DFO(6305537-09)*

**08-JUL-2011**

LNМ/D. 01-JUL-2011

Delete depth of 2 metres, 4 decimetres 43°31'36.0"N 065°44'34.1"W  
(See Chart No. 1, I10)

*DFO(6305537-10)*

**01-JUL-2011**

LNМ/D. 05-JUN-2009

Amend FLR to read LFLR against light  
(See Chart No 1 P16)

43°28'24.6"N 065°38'01.7"W

*(F2011089) LL(318.5) DFO(6305368-01)*

**05-JUN-2009**

LNМ/D. 07-NOV-2008



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4210

Amend LFl R to read LFl G against light  
(See Chart No 1 P16)

43°25'56.9"N 065°37'54.9"W

(F2009019) LL(323.5) DFO(6304402-01)

This notice affects Electronic Navigational Chart:  
CA376047

#### 07-NOV-2008

LNM/D. 17-OCT-2008

Delete red starboard hand conical buoy, marked CC2  
(See Chart No 1 Qf)

43°26'11.0"N 065°38'41.5"W

(F2008126) DFO(6304056-01)

#### 17-OCT-2008

LNM/D. 14-MAR-2008

Add starboard hand daybeacon with radar reflector  
(See Chart No 1 Qt, S4)

43°26'02.0"N 065°38'50.0"W

(F2008127) DFO(6304000-01)

#### 14-MAR-2008

LNM/D. 15-FEB-2008

Add red starboard hand conical buoy, marked PB2  
(See Chart No 1 Qf)

43°37'06.2"N 065°47'08.3"W

(F2007050) LL(5300.75) DFO(6303791-01)

#### 15-FEB-2008

LNM/D. 28-DEC-2007

Amend Fl R to read LFl R against light  
(See Chart No 1 P16)

43°25'56.9"N 065°37'54.9"W

LL(323.5) DFO(6303799-01)

#### 28-DEC-2007

LNM/D. 21-SEP-2007

Replace yellow, black and yellow West cardinal lighted spar  
buoy Q(9) 15s, marked NAC with yellow, black and  
yellow West cardinal lighted pillar buoy Q(9) 15s,  
marked NAC

43°24'59.3"N 065°39'18.9"W

(F2007083) LL(324) DFO(6303674-01)

#### 21-SEP-2007

LNM/D. 18-MAY-2007

Amend FR to read FlR against light

43°29'32.9"N 065°42'18.0"W

(F2007038) LL(309) DFO(6303595-01)





### Chart no. 4210

#### 09-FEB-2007

Add light 'FlG' against green port hand can buoy, marked  
CC3

LNМ/D. 11-AUG-2006

43°26'05.0"N 065°38'29.0"W

(F2006171) LL(322.07) DFO(6303261-01)

#### 09-FEB-2007

Reposition green port hand lighted spar buoy FlG, marked  
P1

LNМ/D. 11-AUG-2006

from 43°35'12.0"N 065°48'10.5"W  
to 43°35'10.3"N 065°48'13.9"W

(F2006181) LL(302.5) DFO(6303271-01)

#### 09-FEB-2007

Add red starboard hand spar buoy, marked NF2

LNМ/D. 11-AUG-2006

43°29'17.2"N 065°43'06.3"W

(F2006183) LL(5306.02) DFO(6303273-01)

#### 11-AUG-2006

(T)Replace yellow, black and yellow West cardinal lighted  
spar buoy Q(9) 15s, marked NAC with red  
starboard hand lighted spar buoy FlR, marked  
NA6

LNМ/D. 23-JUN-2006

43°24'59.3"N 065°39'18.9"W

(F2006015) LL(324) DFO(6303060-01)

Buoy permanently established. Notice 11-  
August-2006(T), DFO (6303060-01) is now  
cancelled. See reference DFO(6303674-01)  
appearing in this edition.  
Cancelled on 28-DEC-07

#### 23-JUN-2006

Add light FlG

LNМ/D. 16-JUN-2006

43°25'25.8"N 065°39'25.6"W

(F2006076) LL(323.91) DFO(6302871-01)

#### 23-JUN-2006

Amend "FlR" to read "QR" against red starboard pillar light  
buoy marked D2

LNМ/D. 16-JUN-2006

43°29'35.3"N 065°45'39.9"W

(F2006077) LL(305) DFO(6302881-01)

#### 23-JUN-2006

LNМ/D. 16-JUN-2006



**Chart no. 4210**

Delete light FLR 43°28'25.1"N 065°38'13.5"W

*(F2006080) LL(318) DFO(6302883-01)*

**16-JUN-2006**

LNM/D. 05-MAY-2006

Add red starboard hand spar buoy, marked P12 43°37'38.0"N 065°46'41.0"W

*DFO(6302801-01)*

**16-JUN-2006**

LNM/D. 05-MAY-2006

Add red starboard hand spar buoy, marked P14 43°37'49.5"N 065°46'39.0"W

*DFO(6302802-01)*

**16-JUN-2006**

LNM/D. 05-MAY-2006

Add green port hand spar buoy, marked P15 43°37'57.0"N 065°46'40.0"W

*DFO(6302803-01)*

**16-JUN-2006**

LNM/D. 05-MAY-2006

Reposition red starboard hand spar buoy, marked P8 from 43°36'57.9"N 065°46'48.0"W  
to 43°36'57.5"N 065°46'50.8"W

*DFO(6302809-01)*

**05-MAY-2006**

LNM/D. 28-APR-2006

Add light FLG 43°29'20.3"N 065°43'04.4"W

*(F2006019) LL(306.003) DFO(6302783-01)*

**28-APR-2006**

LNM/D. 24-FEB-2006

Replace red and white fairway lighted pillar buoy Mo(A),  
marked NAC with yellow, black and yellow West  
cardinal lighted spar buoy Q(9) 15s, marked NAC

43°24'59.3"N 065°39'18.9"W

*(F2006015) LL(324) DFO(6302779-01)*

**28-APR-2006**

LNM/D. 24-FEB-2006



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4210

Delete red, green and red starboard bifurcation conical buoy,  
marked C 43°27'38.5"N 065°39'35.0"W

*(F2006017) DFO(6302781-01)*

**28-APR-2006**

LNM/D. 24-FEB-2006

Add red starboard hand conical buoy, marked C6 43°27'37.0"N 065°39'30.9"W

*(F2006017) DFO(6302781-02)*

**24-FEB-2006**

LNM/D. 10-FEB-2006

Delete legend "BELL" against red starboard hand pillar light  
and bell buoy FIR, BELL marked ND4 43°30'30.3"N 065°49'10.4"W

*(F2005141) LL(303) DFO(6302725-01)*

**10-FEB-2006**

LNM/D. 06-JAN-2006

Delete green port hand spar buoy, marked CE1 43°28'25.5"N 065°37'58.5"W

*(F2005094) DFO(6302671-01)*

**10-FEB-2006**

LNM/D. 06-JAN-2006

Add green port hand lighted spar buoy QG, marked D3 43°30'00.1"N 065°45'18.0"W

*(F2005100) LL(305.5) DFO(6302672-01)*

**10-FEB-2006**

LNM/D. 06-JAN-2006

Replace green port hand can buoy, marked D1, with green  
port hand pillar light buoy FlG, marked D1 43°29'29.8"N 065°45'58.5"W

*(F2005101) LL(304.1) DFO(6302673-01)*

**10-FEB-2006**

LNM/D. 06-JAN-2006

Delete red starboard hand spar buoy, marked D6 43°30'37.0"N 065°44'54.5"W

*(F2005102) DFO(6302674-01)*

**10-FEB-2006**

LNM/D. 06-JAN-2006

Add red starboard hand lighted pillar buoy FIR, marked  
D6 43°30'32.6"N 065°45'00.1"W

*(F2005102) LL(311.6) DFO(6302674-02)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4210

- 10-FEB-2006** LNM/D. 06-JAN-2006  
Add red starboard hand lighted spar buoy FIR, marked C10 43°28'26.9"N 065°38'16.9"W  
(F2005103) LL(318.01) DFO(6302675-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006  
Replace green port hand can buoy, marked C1 with green port hand lighted spar buoy QG, marked C1 43°27'22.5"N 065°41'05.0"W  
(F2005104) LL(320.01) DFO(6302676-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006  
Add light 'FIG' against green port hand spar buoy, marked CA5 43°26'28.0"N 065°38'34.0"W  
(F2005105) LL(323.07) DFO(6302677-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006  
Reposition green port hand can buoy, marked DC13 from 43°33'08.0"N 065°47'05.0"W to 43°33'08.4"N 065°47'02.9"W  
(F2005107) DFO(6302679-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006  
Replace green port hand can buoy, marked CA1 with green port hand lighted spar buoy FIG, marked CA1 43°26'42.0"N 065°39'40.0"W  
(F2005117) LL(322.1) DFO(6302685-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006  
Amend "FIR" to read "QR" against red starboard hand spar light buoy, marked NA4 43°23'46.5"N 065°39'13.0"W  
(F2005137) LL(326.02) DFO(6302698-01)
- 06-JAN-2006** LNM/D. 18-NOV-2005  
Reposition green port hand lighted pillar buoy FIG, marked D5 from 43°30'33.0"N 065°44'55.0"W to 43°30'30.0"N 065°45'07.0"W  
(F2005098) LL(311.5) DFO(6302657-01)



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4210

**18-NOV-2005**

Delete red starboard hand lighted pillar bell buoy FlR,  
BELL, marked P2

LNM/D. 07-OCT-2005

43°35'55.5"N 065°47'03.8"W

*(F2005083) LL(298.4) DFO(6302554-01)*

**18-NOV-2005**

Delete light FlR and radar reflector

LNM/D. 07-OCT-2005

43°31'41.2"N 065°44'59.6"W

*(F2005084) LL(314) DFO(6302557-01)*

**18-NOV-2005**

Delete legend "Fog Sig 20s" against light

LNM/D. 07-OCT-2005

43°27'23.2"N 065°44'36.2"W

*(F2005085) LL(307) DFO(6302558-01)*

**07-OCT-2005**

Amend "FG" to read "FlG" against light

LNM/D. 22-JUL-2005

43°31'46.0"N 065°44'23.7"W

*(F2005064) LL(315) DFO(6302470-01)*

**07-OCT-2005**

Amend "FY" to read "FlY" against light

LNM/D. 22-JUL-2005

43°29'23.9"N 065°43'08.2"W

*(F2005066) LL(311) DFO(6302480-01)*

**22-JUL-2005**

Add light 'FlR' against red starboard hand spar buoy,  
marked NA4

LNM/D. 20-MAY-2005

43°23'46.5"N 065°39'13.0"W

*(F2005035) LL(326.02) DFO(6302362-01)*

**20-MAY-2005**

(T)Add green port hand pillar light buoy FlG, marked  
NA5

LNM/D. 25-FEB-2005

43°25'27.6"N 065°39'17.3"W

This buoy is temporarily established.

*(F2005013T) LL(323.9) DFO(6302270-01)*

This buoy is permanently discontinued. Notice  
20-May-2005(T), DFO(6302270) is now cancelled.  
Cancelled on 18-NOV-05

**20-MAY-2005**

LNM/D. 25-FEB-2005



**Chart no. 4210**

Add light FIR 43°35'53.4"N 065°46'55.6"W

*(F2005019) LL(299) DFO(6302276-01)*

**25-FEB-2005**

Replace red starboard hand conical buoy, marked NC2  
with red starboard hand pillar light buoy FIR,  
marked N2

LNM/D. 17-DEC-2004

43°22'51.0"N 065°41'49.5"W

*(F2004212) LL(307.02) DFO(6302175-01)*

**25-FEB-2005**

Replace red and white fairway pillar, light buoy Mo (A),  
BELL, marked NA with red starboard hand pillar  
light buoy FIR, marked NA2

LNM/D. 17-DEC-2004

43°23'30.3"N 065°38'42.9"W

*(F2004213) LL(326) DFO(6302181-01)*

**25-FEB-2005**

Add green port hand spar light buoy FlG, marked P1

LNM/D. 17-DEC-2004

43°35'12.0"N 065°48'10.5"W

*(F2004214) LL(302.5) DFO(6302182-01)*

**25-FEB-2005**

Delete legend "BELL" against red starboard hand pillar light  
and bell buoy FIR, BELL marked D2

LNM/D. 17-DEC-2004

43°29'35.3"N 065°45'39.9"W

*(F2004190) LL(305) DFO(6302184-01)*

**25-FEB-2005**

Delete red and white fairway pillar light and whistle buoy  
Mo(A), WHIS, marked P

LNM/D. 17-DEC-2004

43°34'51.0"N 065°48'12.0"W

*(F2004194) LL(302) DFO(6302188-01)*

**25-FEB-2005**

Delete legend "BELL" against red and white fairway pillar  
light and bell buoy Mo (A), BELL, marked D

LNM/D. 17-DEC-2004

43°29'09.3"N 065°46'28.9"W

*(F2004197) LL(304) DFO(6302191-01)*

**25-FEB-2005**

LNM/D. 17-DEC-2004



**Chart no. 4210**

Replace red starboard hand pillar light and bell buoy F1R, 43°26'23.3"N 065°44'43.9"W  
BELL, marked ND2 with red and white fairway  
pillar, light buoy Mo (A), marked C (F2004202) LL(306) DFO(6302195-01)

**25-FEB-2005** LNM/D. 17-DEC-2004  
Delete legend "BELL" against red starboard hand pillar light 43°26'46.3"N 065°40'19.9"W  
and bell buoy F1R, BELL marked C2 (F2004203) LL(321) DFO(6302197-01)

**25-FEB-2005** LNM/D. 17-DEC-2004  
Amend "F1R" to read "QR" against red starboard pillar light 43°26'36.3"N 065°39'45.9"W  
buoy marked CA2 (F2004204) LL(322) DFO(6302198-01)

**25-FEB-2005** LNM/D. 17-DEC-2004  
Replace red starboard hand pillar light and whistle buoy 43°20'12.3"N 065°40'45.9"W  
F1R, WHIS, marked N2 with red and white fairway  
pillar, light buoy Mo (A), marked N (F2004205) LL(325) DFO(6302200-01)

**25-FEB-2005** LNM/D. 17-DEC-2004  
Replace red starboard hand conical buoy, marked NA2, with red 43°23'46.5"N 065°39'13.0"W  
starboard hand spar buoy, marked NA4 (F2004102) DFO(6302204-01)

**17-DEC-2004** LNM/D. 29-OCT-2004  
Delete green port hand spar buoy, marked PB1 43°36'55.5"N 065°47'06.0"W  
(F2004160) DFO(6302086-01)

**29-OCT-2004** LNM/D. 02-JUL-2004  
Add water intake pipe joining 43°26'07.7"N 065°38'25.0"W  
43°26'12.0"N 065°38'16.2"W  
43°26'18.7"N 065°38'07.0"W  
43°26'29.9"N 065°38'02.2"W  
and 43°26'41.9"N 065°38'01.5"W  
DFO(6301964-01)



### Chart no. 4210

**02-JUL-2004**

Amend "Fl 10s 14m 16M" to read "Fl 10s 14m 10M" against  
light

LNM/D. 26-MAR-2004

43°27'23.2"N 065°44'36.2"W

*(F2004059) LL(307) DFO(6301606-01)*

**26-MAR-2004**

Delete light FLR

LNM/D. 12-MAR-2004

43°29'23.6"N 065°42'56.4"W

*(F2003106) LL(310) DFO(6301205-01)*

**26-MAR-2004**

Delete light FLR

LNM/D. 12-MAR-2004

43°28'35.0"N 065°43'08.5"W

*(F2003118) LL(308) DFO(6301206-01)*

**26-MAR-2004**

Add yellow, black, yellow West cardinal spar light buoy  
Q(9) 15s, marked NF

LNM/D. 12-MAR-2004

43°28'50.1"N 065°43'24.4"W

*(F2003132) LL(306.002) DFO(6301212-01)*

**26-MAR-2004**

Delete green, port hand can buoy, marked NC5 43°28'45.0"N 065°43'21.5"W

LNM/D. 12-MAR-2004

*(F2003146) DFO(6301229-01)*

**12-MAR-2004**

Delete green port pillar light buoy Fl G marked NC15

LNM/D. 21-MAR-2003

43°28'42.3"N 065°41'47.9"W

*(F2003107) LL(307.5) DFO(6301174-01)*

**12-MAR-2004**

Delete red, starboard hand conical buoy, marked NC4 43°28'25.0"N 065°43'27.0"W

LNM/D. 21-MAR-2003

*(F2003108) DFO(6301175-01)*

**12-MAR-2004**

LNM/D. 21-MAR-2003





### Chart no. 4210

Delete green, port hand spar buoy, marked NC7 43°28'45.5"N 065°42'53.5"W

*(F2003109) DFO(6301176-01)*

**12-MAR-2004**

LNM/D. 21-MAR-2003

Delete red, starboard hand spar buoy, marked NC8 43°28'48.0"N 065°42'36.5"W

*(F2003110) DFO(6301177-01)*

**12-MAR-2004**

LNM/D. 21-MAR-2003

Delete red, starboard hand spar buoy, marked NC10 43°28'48.5"N 065°42'15.0"W

*(F2003111) DFO(6301178-01)*

**12-MAR-2004**

LNM/D. 21-MAR-2003

Delete green, port hand spar buoy, marked NC13 43°28'42.0"N 065°42'01.0"W

*(F2003112) DFO(6301179-01)*

**12-MAR-2004**

LNM/D. 21-MAR-2003

Delete green, port hand spar buoy, marked NC17 43°28'55.0"N 065°41'10.0"W

*(F2003113) DFO(6301180-01)*

**12-MAR-2004**

LNM/D. 21-MAR-2003

Delete red, starboard hand spar buoy, marked NC18 43°29'15.0"N 065°41'40.0"W

*(F2003114) DFO(6301181-01)*

**12-MAR-2004**

LNM/D. 21-MAR-2003

Delete red, starboard hand spar buoy, marked CM2 43°29'14.0"N 065°37'20.0"W

*(F2003124) DFO(6301183-01)*

**12-MAR-2004**

LNM/D. 21-MAR-2003

Delete red, starboard hand spar buoy, marked CM4 43°28'43.0"N 065°36'48.0"W

*(F2003125) DFO(6301184-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4210

**21-MAR-2003**

LNM/D. 14-FEB-2003

Delete light FLR 12s 8m 5M

43°31'20.5"N 065°44'13.0"W

*(F2001026) LL(313) DFO(6300597-01)*

**21-MAR-2003**

LNM/D. 14-FEB-2003

Add breakwater joining 43°31'16.2"N 065°44'11.1"W

43°31'17.5"N 065°44'16.2"W

and 43°31'22.1"N 065°44'15.3"W

*DFO(6300597-02)*

**21-MAR-2003**

LNM/D. 14-FEB-2003

Add light FIR

43°31'22.0"N 065°44'15.3"W

*(F2002050) LL(313) DFO(6300597-03)*

**14-FEB-2003**

LNM/D. 11-JAN-2002

Amend Iso G to read FlG against light

43°26'33.5"N 065°38'08.7"W

*(F2002031) LL(323) DFO(6300473-01)*

**11-JAN-2002**

LNM/D. 30-NOV-2001

Amend Fl (2+1) 6s to read Fl (2+1) G 43°37'03.0"N 065°47'02.0"W

*DFO(6829815-01)*

**30-NOV-2001**

LNM/D. 27-APR-2001

Amend FR to read FLR

43°36'21.3"N 065°46'41.9"W

*(F2001116) LL(300.5) DFO(6829785-01)*

**27-APR-2001**

LNM/D. 07-JUL-2000

(T)Delete The temporary deletion of the legend BELL  
against buoy D2

43°29'35.3"N 065°45'39.9"W

*(F2001-014T) LL(305) DFO(6829435-01)*

With this notification, temporary action dated  
27-APR-2001 is cancelled. The bell is back in  
service.

Cancelled on 21-MAR-03



**Chart no. 4210**

**07-JUL-2000**

LNM/D. 16-JUN-2000

Add rock which covers and uncovers

43°32'11.8"N 065°44'36.4"W

*(F2000-097) LL(315.3) DFO(6828640-01)*

**07-JUL-2000**

LNM/D. 16-JUN-2000

Add light, Fl

43°32'11.8"N 065°44'36.4"W

*(F2000-097) LL(315.3) DFO(6828640-02)*

**16-JUN-2000**

LNM/D. 26-MAY-2000

Amend Fl R to read, Fl R 12s 8m 5M

43°31'20.5"N 065°44'13.0"W

*(F2000093) LL(313) DFO(6828621-02)*

**26-MAY-2000**

LNM/D. 14-APR-2000

Add green, port hand, spar buoy, marked "PB1", on certain copies. 43°36'55.5"N 065°47'06.0"W

*DFO(6500283-01)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Amend P8 to read "P6" against red conical buoy

43°36'34.0"N 065°46'51.0"W

*(F1999045) LL(5300.800) DFO(6300003-01)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Amend P6 to read "P4" against red spar buoy

43°36'14.8"N 065°46'47.5"W

*(F1999046) LL(5300.600) DFO(6300003-02)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Delete red conical buoy P4

43°35'55.5"N 065°47'03.8"W

*(F1999048) LL(5298.400) DFO(6300003-03)*

**14-APR-2000**

LNM/D. 25-JUN-1999



### Chart no. 4210

Delete green spar buoy P9 43°37'01.3"N 065°46'59.0"W  
*(F1999055) LL(5300.900) DFO(6300003-04)*

**14-APR-2000** LNM/D. 25-JUN-1999  
Amend P10 to read "P8" against red spar buoy 43°36'57.5"N 065°46'50.8"W  
*(F1999062) LL(5300.100) DFO(6300003-05)*

**14-APR-2000** LNM/D. 25-JUN-1999  
Delete light 43°37'00.1"N 065°47'10.4"W  
*(F1999058) LL(301.000) DFO(6300003-06)*

**14-APR-2000** LNM/D. 25-JUN-1999  
Amend P12 to read "P10" against red spar buoy 43°37'13.5"N 065°46'52.0"W  
*(F1999063) LL(5300.120) DFO(6300003-07)*

**14-APR-2000** LNM/D. 25-JUN-1999  
Add green spar buoy, marked "PB1" 43°36'55.5"N 065°47'06.0"W  
*(F1999077) LL(5300.910) DFO(6300003-08)*

**14-APR-2000** LNM/D. 25-JUN-1999  
Add port bifurcation light buoy, "Fl(2+1)6s", marked 43°37'03.0"N 065°47'02.0"W  
"PB" *(F1999072) LL(301.500) DFO(6300003-10)*

**14-APR-2000** LNM/D. 25-JUN-1999  
Delete light and Fog Sig 43°35'53.4"N 065°46'55.5"W  
*(F1999057) LL(299.000) DFO(6300003-11)*

**14-APR-2000** LNM/D. 25-JUN-1999  
Reposition red and white light and whistle buoy "P" from 43°31'14.3"N 065°52'00.0"W  
to 43°34'51.0"N 065°48'12.0"W  
*(F1999052) LL(302.000) DFO(6300003-12)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4210

**14-APR-2000**

Add red light and bell buoy "Fl R", "BELL",  
marked "P2"

LNM/D. 25-JUN-1999

43°35'55.5"N 065°47'03.8"W

(F1999049) LL(298.400 SUGG) DFO(6300003-13)

**14-APR-2000**

Delete green light and bell buoy P1

LNM/D. 25-JUN-1999

43°34'55.3"N 065°48'10.9"W

(F1999047) LL(298.000) DFO(6300003-14)

## 4210 - Continuation A - New Chart - 05-APR-1991 - NAD 1983

**23-APR-2021**

Delete drying height of 0.2 metres  
(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA476105

LNM/D. 10-MAY-2019

43°37'11.5"N 065°47'13.5"W

DFO(6309390-01)

**23-APR-2021**

Add pier  
(See Chart No. 1, F14)  
This notice affects Electronic Navigational Chart:  
CA376014, CA476105

LNM/D. 10-MAY-2019

joining 43°37'10.5"N 065°47'20.5"W  
43°37'11.8"N 065°47'13.4"W  
and 43°37'10.0"N 065°47'12.8"W

DFO(6309390-02)

**18-MAY-2007**

Add red starboard hand conical buoy, marked PB2

LNM/D. 09-FEB-2007

43°37'06.2"N 065°47'08.3"W

(F2007050) LL(5300.75) DFO(6303401-01)

**16-JUN-2006**

Add red starboard hand spar buoy, marked P12 43°37'38.0"N 065°46'41.0"W

LNM/D. 05-MAY-2006

DFO(6302801-01)

**16-JUN-2006**

Add red starboard hand spar buoy, marked P14 43°37'49.5"N 065°46'39.0"W

LNM/D. 05-MAY-2006

DFO(6302802-01)



### Chart no. 4210

**16-JUN-2006**

LNМ/D. 05-MAY-2006

Add green port hand spar buoy, marked P15 43°37'57.0"N 065°46'40.0"W

*DFO(6302803-01)*

**16-JUN-2006**

LNМ/D. 05-MAY-2006

Add green port hand spar buoy, marked P17 43°38'05.5"N 065°46'34.0"W

*DFO(6302804-01)*

**16-JUN-2006**

LNМ/D. 05-MAY-2006

Add red starboard hand spar buoy, marked P18 43°38'14.4"N 065°46'30.0"W

*DFO(6302805-01)*

**16-JUN-2006**

LNМ/D. 05-MAY-2006

Add green port hand spar buoy, marked P19 43°38'14.9"N 065°46'33.3"W

*DFO(6302806-01)*

**16-JUN-2006**

LNМ/D. 05-MAY-2006

Delete legend "Channel Buoyed/Chenal balisé" 43°38'18.0"N 065°46'28.0"W

*DFO(6302807-01)*

**16-JUN-2006**

LNМ/D. 05-MAY-2006

Reposition red starboard hand spar buoy, marked P8 from 43°36'57.9"N 065°46'48.0"W  
to 43°36'57.5"N 065°46'50.8"W

*DFO(6302809-01)*

**17-DEC-2004**

LNМ/D. 29-OCT-2004

Delete green port hand spar buoy, marked PB1 43°36'55.5"N 065°47'06.0"W

*(F2004160) DFO(6302086-01)*

**11-JAN-2002**

LNМ/D. 30-NOV-2001



### Chart no. 4210

Amend Fl (2+1) 6s to read Fl (2+1) G 43°37'03.0"N 065°47'02.0"W

*DFO(6829815-01)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Delete green spar buoy P9

43°37'01.3"N 065°46'59.0"W

*(F1999055) LL(5300.900) DFO(6300003-04)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Amend P10 to "P8" against red spar buoy

43°36'57.5"N 065°46'50.8"W

*(F1999062) LL(5300.100) DFO(6300003-05)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Delete light

43°37'00.1"N 065°47'10.4"W

*(F1999058) LL(301.000) DFO(6300003-06)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Amend P12 to read "P10" against red spar buoy

43°37'13.5"N 065°46'52.0"W

*(F1999063) LL(5300.120) DFO(6300003-07)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Add green spar buoy, marked "PB1"

43°36'55.5"N 065°47'06.0"W

*(F1999077) LL(5300.910) DFO(6300003-08)*

**14-APR-2000**

LNM/D. 25-JUN-1999

Add port bifurcation light buoy, "Fl(2+1)6s", marked  
"PB"

43°37'03.0"N 065°47'02.0"W

*(F1999072) LL(301.500) DFO(6300003-10)*