



Chart no. 4211

4211 - Cape Lahave to / à Liverpool Bay - New Edition - 20-JUN-2003 - NAD 1983

19-JUL-2024

LNМ/D. 20-JAN-2023

Amend LFl to read Fl R against light
(See Chart 1, P16)

44°02'40.4"N 064°41'30.3"W

(F2024022) LL(409) DFO(6311185-01)

20-JAN-2023

LNМ/D. 22-APR-2022

Affix patch

44°02'52.0"N 064°42'03.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA476202

DFO(6310442-02)

22-APR-2022

LNМ/D. 06-AUG-2021

Add depth of 2 fathoms, 2 feet
(See Chart No. 1, I10)

44°02'45.5"N 064°42'18.9"W

This notice affects Electronic Navigational Chart: CA376045,
CA476202

DFO(6310059-08)

06-AUG-2021

LNМ/D. 26-MAR-2021

Delete depth of 6 fathoms, 3 feet
(See Chart No. 1, I10)

44°02'16.3"N 064°40'35.5"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-01)

06-AUG-2021

LNМ/D. 26-MAR-2021

Add depth of 4 fathoms, 5 feet
(See Chart No. 1, I10)

44°02'17.9"N 064°40'38.6"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-02)

06-AUG-2021

LNМ/D. 26-MAR-2021

Delete depth of 5 fathoms, 1 foot
(See Chart No. 1, I10)

44°02'17.2"N 064°39'06.7"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-03)

06-AUG-2021

LNМ/D. 26-MAR-2021

Add depth of 4 fathoms, 3 feet
(See Chart No. 1, I10)

44°02'18.4"N 064°39'06.5"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-04)



Chart no. 4211

06-AUG-2021

LN/D. 26-MAR-2021

Add depth of 1 fathom, 3 feet
(See Chart No. 1, I10)

44°03'24.5"N 064°37'47.6"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-05)

06-AUG-2021

LN/D. 26-MAR-2021

Replace depth of 4 fathoms, 5 feet with depth of 3 fathoms, 5 feet
(See Chart No. 1, I10)

44°06'46.4"N 064°31'52.7"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-06)

06-AUG-2021

LN/D. 26-MAR-2021

Delete depth of 4 fathoms, 4 feet
(See Chart No. 1, I10)

44°07'55.9"N 064°32'25.5"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-07)

06-AUG-2021

LN/D. 26-MAR-2021

Add depth of 3 fathoms, 2 feet
(See Chart No. 1, I10)

44°07'56.1"N 064°32'22.9"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-08)

06-AUG-2021

LN/D. 26-MAR-2021

Delete depth of 5 fathoms, 2 feet
(See Chart No. 1, I10)

44°08'08.2"N 064°33'21.0"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-09)

06-AUG-2021

LN/D. 26-MAR-2021

Replace depth of 1 fathom, 1 foot with depth of 3 feet
(See Chart No. 1, I10)

44°08'43.0"N 064°35'45.1"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-10)

06-AUG-2021

LN/D. 26-MAR-2021

Add depth of 3 fathoms, 5 feet
(See Chart No. 1, I10)

44°08'09.3"N 064°33'24.2"W

This notice affects Electronic Navigational Chart: CA476202

DFO(6309509-11)

06-AUG-2021

LN/D. 26-MAR-2021



Chart no. 4211

Add depth of 1 fathom, 2 feet 44°08'27.6"N 064°32'23.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476202 *DFO(6309509-12)*

06-AUG-2021 LNM/D. 26-MAR-2021
Add depth of 1 fathom, 1 foot 44°08'45.8"N 064°32'12.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476202 *DFO(6309509-13)*

06-AUG-2021 LNM/D. 26-MAR-2021
Affix patch 44°11'18.0"N 064°37'06.0"W
[PDF](#)
DFO(6309509-14)

26-MAR-2021 LNM/D. 27-JUL-2018
Amend QG to read Iso G against light 44°01'09.4"N 064°39'45.9"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: *(F2021004) LL(408.2) DFO(6309357-01)*
CA376045, CA476202

27-JUL-2018 LNM/D. 05-AUG-2016
Reposition light Fl 4s 61ft 7M from 44°02'01.1"N 064°37'41.8"W
(See Chart No. 1, P1) to 44°02'03.5"N 064°37'42.5"W
This notice affects Electronic Navigational Chart:
CA276800, CA376045, CA476202 *(F2018021) LL(407) DFO(6308352-01)*

27-JUL-2018 LNM/D. 05-AUG-2016
Amend Fl 4s 61ft 7M to read Fl 4s49ft7M against light 44°02'03.5"N 064°37'42.5"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: *(F2018021) LL(407) DFO(6308352-02)*
CA276800, CA376045, CA476202

05-AUG-2016 LNM/D. 21-SEP-2012
Delete legend Fog Sig against light 44°09'30.9"N 064°28'51.3"W
(See Chart No 1 R20)
This notice affects Electronic Navigational Chart: *(F2016034) LL(417.5) DFO(6307628-01)*
CA476664

21-SEP-2012 LNM/D. 17-AUG-2012



Chart no. 4211

Add marine farm
(See Chart No. 1, K48.2)

44°02'30.2"N 064°38'25.2"W

DFO(6306164-03)

This notice affects Electronic Navigational Chart: CA376045,
CA476202

17-AUG-2012

Amend 11ft (2008) to read 10ft (2010)
(See Chart No. 1, I22)

LNM/D. 20-MAY-2011

44°02'52.3"N 064°42'20.7"W

DFO(6306041-08)

This notice affects Electronic Navigational Chart: CA476202

20-MAY-2011

Delete depth of 4 fathoms, 4 feet
(See Chart No. 1, I10)

LNM/D. 05-MAR-2010

44°09'40.2"N 064°28'33.8"W

DFO(6305440-01)

This notice affects Electronic Navigational Chart: CA476664

20-MAY-2011

Delete depth of 1 fathom, 5 feet
(See Chart No. 1, I10)

LNM/D. 05-MAR-2010

44°09'39.7"N 064°28'42.2"W

DFO(6305440-02)

This notice affects Electronic Navigational Chart: CA476664

20-MAY-2011

Add depth of 0 fathoms, 4 feet
(See Chart No. 1, I10)

LNM/D. 05-MAR-2010

44°09'40.4"N 064°28'40.4"W

DFO(6305440-03)

This notice affects Electronic Navigational Chart: CA476664

20-MAY-2011

Add depth of 0 fathoms, 2 feet
(See Chart No. 1, I10)

LNM/D. 05-MAR-2010

44°09'35.3"N 064°28'41.4"W

DFO(6305440-04)

This notice affects Electronic Navigational Chart: CA476664



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4211

20-MAY-2011

LNМ/D. 05-MAR-2010

Delete depth of 5 fathoms, 2 feet 44°09'35.4"N 064°28'36.9"W
(See Chart No. 1, I10)

DFO(6305440-05)

05-MAR-2010

LNМ/D. 27-NOV-2009

Amend FG to read Iso G against light
(See Chart No 1 P10.3)

44°09'29.8"N 064°28'53.3"W

(F2010004) LL(417.5) DFO(6304737-01)

This notice affects Electronic Navigational Chart:
CA476664

27-NOV-2009

LNМ/D. 24-APR-2009

Delete BELL against green port hand lighted pillar bell buoy
QG, BELL marked UM53
(See Chart No 1 Qg)

44°02'46.3"N 064°42'03.9"W

(F2006159) LL(410) DFO(6304650-01)

24-APR-2009

LNМ/D. 06-MAR-2009

Delete fog signal Fog Sig
(See Chart No 1 R20)

44°01'09.0"N 064°39'53.0"W

(F2009002) LL(408.3) DFO(6304317-01)

This notice affects Electronic Navigational Chart:
CA376045

06-MAR-2009

LNМ/D. 09-JAN-2009

Delete green port hand spar buoy, marked UJ61 44°04'09.4"N 064°35'01.5"W
(See Chart No 1 Qg)

(F2008166) DFO(6304237-01)

06-MAR-2009

LNМ/D. 09-JAN-2009

Add green port hand lighted spar buoy FlG, marked UJ61
(See Chart No 1 Qg)

44°04'10.3"N 064°35'00.8"W

(F2008166) LL(416.55) DFO(6304237-02)

06-MAR-2009

LNМ/D. 09-JAN-2009



Chart no. 4211

Add Channel Buoy/Chenal balisé 44°04'15.0"N 064°34'40.0"W

(F2008167) LL(416.51) DFO(6304238-01)

06-MAR-2009

LNM/D. 09-JAN-2009

Delete red starboard hand lighted pillar buoy FIR, marked UJ52 44°04'00.8"N 064°35'11.3"W
(See Chart No 1 Qf)

LL(412.5) DFO(6304273-01)

06-MAR-2009

LNM/D. 09-JAN-2009

Add red starboard hand lighted spar buoy FIR, marked UJ52 44°04'01.3"N 064°35'10.8"W
(See Chart No 1 Qf)

LL(412.5) DFO(6304273-02)

09-JAN-2009

LNM/D. 10-OCT-2008

Delete green port hand lighted pillar buoy FlG, marked
UE51
(See Chart No 1 Qg)

44°08'33.3"N 064°32'27.0"W

(F2008151) LL(416.4) DFO(6304188-01)

09-JAN-2009

LNM/D. 10-OCT-2008

Add green port hand lighted spar buoy FlG, marked UE51
(See Chart No 1 Qg)

44°08'33.3"N 064°32'28.8"W

(F2008151) LL(416.4) DFO(6304188-02)

10-OCT-2008

LNM/D. 08-FEB-2008

Amend legend 13ft (2004) to read 11ft (2008) 44°02'52.0"N 064°42'21.0"W
(See Chart No. 1, I22)

DFO(6304053-13)

08-FEB-2008

LNM/D. 21-DEC-2007

Amend FR to read FIR against light
(See Chart No 1 P16)

44°09'09.7"N 064°32'43.4"W

(F2007121) LL(416.5) DFO(6303757-01)

21-DEC-2007

LNM/D. 21-SEP-2007



Chart no. 4211

Add light FIG against green port hand spar buoy, marked
TU53
(See Chart No 1, Qg) 44°09'36.8"N 064°28'40.3"W
(F2007094) LL(417.81) DFO(6303692-01)

21-DEC-2007 LNM/D. 21-SEP-2007
Add red starboard hand lighted spar buoy FIR, marked
TU54 44°09'37.7"N 064°28'48.2"W
(See Chart No 1, Qf) (F2007097) LL(419) DFO(6303705-01)

21-SEP-2007 LNM/D. 20-APR-2007
Delete green port hand lighted pillar bell buoy FIG, BELL,
marked TU51 44°09'36.3"N 064°28'12.8"W
(F2007076) LL(417.8) DFO(6303623-01)

21-SEP-2007 LNM/D. 20-APR-2007
Add red and white fairway lighted pillar buoy Mo(A),
marked TU 44°09'36.3"N 064°28'17.8"W
(F2007077) LL(418) DFO(6303623-02)

20-APR-2007 LNM/D. 09-FEB-2007
Delete red and white fairway lighted pillar bell buoy
Mo(A), marked UC 44°05'16.3"N 064°32'21.3"W
(F2007049) LL(414.5) DFO(6303397-01)

20-APR-2007 LNM/D. 09-FEB-2007
Add black, yellow and black East cardinal lighted pillar
buoy Q(3) 10s, marked UC 44°05'12.0"N 064°32'14.0"W
(F2007049) LL(414.5) DFO(6303397-02)

09-FEB-2007 LNM/D. 27-OCT-2006
Delete red and white fairway lighted pillar bell buoy Mo(A),
BELL, marked UM 44°00'52.8"N 064°37'47.8"W
(F2006174) LL(406) DFO(6303264-01)

09-FEB-2007 LNM/D. 27-OCT-2006



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4211

Delete legend "BELL" against green port hand lighted pillar
bell buoy FIG, BELL marked UA51

44°03'23.3"N 064°31'28.8"W

(F2006176) LL(413) DFO(6303266-01)

09-FEB-2007

LNМ/D. 27-OCT-2006

Reposition red, green and red starboard bifurcation
spar buoy, marked UE

from 44°08'40.3"N 064°32'22.8"W
to 44°08'38.3"N 064°32'21.3"W

(F2006187) LL(5416.44) DFO(6303277-01)

09-FEB-2007

LNМ/D. 27-OCT-2006

Add green port hand spar buoy, marked UD57

44°09'15.0"N 064°32'01.2"W

(F2006188) LL(5416.477) DFO(6303278-01)

27-OCT-2006

LNМ/D. 28-APR-2006

Reposition green port hand spar buoy, marked TU53

from 44°09'35.3"N 064°28'44.8"W
to 44°09'36.8"N 064°28'40.3"W

(F2006132) LL(5417.81) DFO(6303095-01)

28-APR-2006

LNМ/D. 24-MAR-2006

Amend "Fl 12s 79ft 8M" to read "LFl 12s 79ft 11M" against light

44°06'10.6"N 064°32'23.3"W

LL(415) DFO(6302776-02)

This notice affects Electronic Navigational Chart: CA276800

24-MAR-2006

LNМ/D. 04-NOV-2005

Add non-dangerous wreck 44°09'10.0"N 064°19'36.0"W

DFO(6302754-01)

04-NOV-2005

LNМ/D. 24-JUN-2005

Amend "Fl" to read "LFl" against light

44°02'40.6"N 064°41'30.2"W

(F2005076) LL(409) DFO(6302546-01)

24-JUN-2005

LNМ/D. 24-DEC-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4211

Amend "FIY" to read "QG" against light 44°01'10.3"N 064°39'45.6"W

(F2004025) LL(408.2) DFO(6301349-01)

24-DEC-2004

LNM/D. 02-APR-2004

Amend legend "15ft (1998)" to read "13ft (2004)" 44°02'52.0"N 064°42'21.0"W

DFO(6301890-04)

02-APR-2004

Replace red and white fairway pillar, light buoy Mo (A), 44°03'40.0"N 064°35'18.8"W
BELL, marked UJ, with red and white fairway,
spar light buoy Mo (A), marked UJ *(F2003135) LL(412.2) DFO(6301214-01)*