



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4227

4227 - Country Harbour to / au Ship Harbour - New Chart - 24-MAY-1991 - NAD 1983

21-JUL-2023

LNМ/D. 22-JUL-2022

Delete Starboard day beacon
(See Chart 1, Q80, Q81)

45°00'39.9"N 061°57'13.1"W

This notice affects Electronic Navigational Chart: CA376109 (F2023002) DFO(6310679-01)

21-JUL-2023

LNМ/D. 22-JUL-2022

Delete Starboard day beacon
(See Chart 1, Q80, Q81)

45°00'39.9"N 061°57'13.1"W

This notice affects Electronic Navigational Chart: CA376109 (F2023003) DFO(6310679-02)

22-JUL-2022

LNМ/D. 15-JUL-2022

Add depth of 12.2 metres
(See Chart No. 1, I10)

44°55'53.4"N 062°07'25.0"W

DFO(6310183-10)

This notice affects Electronic Navigational Chart: CA376102,
CA476104

22-JUL-2022

LNМ/D. 15-JUL-2022

Add depth of 9.9 metres
(See Chart No. 1, I10)

44°55'23.7"N 062°07'07.2"W

DFO(6310183-11)

This notice affects Electronic Navigational Chart: CA376102,
CA476104

22-JUL-2022

LNМ/D. 15-JUL-2022

Add depth of 18 metres
(See Chart No. 1, I10)

44°55'20.6"N 062°06'33.0"W

DFO(6310183-16)

This notice affects Electronic Navigational Chart: CA376102,
CA476104

22-JUL-2022

LNМ/D. 15-JUL-2022

Add depth of 18.2 metres
(See Chart No. 1, I10)

44°55'12.6"N 062°02'39.2"W

DFO(6310184-03)

This notice affects Electronic Navigational Chart: CA376109

22-JUL-2022

LNМ/D. 15-JUL-2022

Add depth of 9.5 metres
(See Chart No. 1, I10)

44°55'32.6"N 062°02'30.8"W

DFO(6310184-04)

This notice affects Electronic Navigational Chart: CA376109



Chart no. 4227

22-JUL-2022

LNМ/D. 15-JUL-2022

Add depth of 9.8 metres

44°56'07.1"N 062°00'50.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

DFO(6310184-11)

22-JUL-2022

LNМ/D. 15-JUL-2022

Delete wreck PA, depth unknown

44°55'36.9"N 061°56'56.4"W

(See Chart No. 1, K28 , B7)

This notice affects Electronic Navigational Chart: CA376109

DFO(6310184-20)

22-JUL-2022

LNМ/D. 15-JUL-2022

Add depth of 9.7 metres

44°56'06.6"N 061°57'04.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

DFO(6310184-24)

22-JUL-2022

LNМ/D. 15-JUL-2022

Add wreck with known depth of 26.3 metres

44°55'41.2"N 061°57'02.6"W

(See Chart No. 1, K26)

This notice affects Electronic Navigational Chart: CA376109

DFO(6310184-26)

15-JUL-2022

LNМ/D. 06-MAY-2022

Replace depth of 5.5 metres with depth of 4.8 metres

44°51'56.7"N 062°04'25.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276204,
CA376109

DFO(6310119-01)

15-JUL-2022

LNМ/D. 06-MAY-2022

Replace depth of 9.4 metres with depth of 9.1 metres

44°52'42.2"N 062°04'38.5"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

DFO(6310119-06)

15-JUL-2022

LNМ/D. 06-MAY-2022

Replace depth of 18.7 metres with depth of 17.1 metres

44°54'17.9"N 062°08'20.8"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376102,
CA476104

DFO(6310119-21)

15-JUL-2022

LNМ/D. 06-MAY-2022



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4227

Add depth of 9.2 metres 44°51'49.4"N 062°08'31.2"W
(See Chart No. 1, I10)

DFO(6310119-31)

LNМ/D. 06-MAY-2022

15-JUL-2022

Add depth of 9.2 metres

44°53'44.2"N 062°10'06.1"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376102,
CA476104

DFO(6310122-03)

LNМ/D. 06-MAY-2022

15-JUL-2022

Delete depth of 21.9 metres

44°53'02.9"N 062°10'58.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376102,
CA476104

DFO(6310122-12)

LNМ/D. 06-MAY-2022

15-JUL-2022

Add depth of 16.3 metres

44°53'09.5"N 062°10'56.2"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376102,
CA476104

DFO(6310122-13)

LNМ/D. 06-MAY-2022

15-JUL-2022

Delete depth of 10.4 metres

44°53'46.0"N 062°10'11.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376102,
CA476104

DFO(6310122-18)

LNМ/D. 22-APR-2022

06-MAY-2022

Replace depth of 19 metres with depth of 16.9 metres

44°51'11.1"N 062°10'20.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376102

DFO(6310060-03)

LNМ/D. 22-APR-2022

06-MAY-2022

Delete depth of 25.6 metres

44°54'13.3"N 062°13'43.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376102

DFO(6310060-06)

LNМ/D. 22-APR-2022

06-MAY-2022



Chart no. 4227

Add depth of 14 metres 44°54'08.8"N 062°13'47.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6310060-07)*

22-APR-2022 LNM/D. 15-APR-2022
Delete depth of 9.8 metres 44°54'58.8"N 062°13'50.5"W
(See Chart No. 1, I10)
DFO(6310058-04)

22-APR-2022 LNM/D. 15-APR-2022
Add depth of 9.7 metres 44°55'01.7"N 062°13'32.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6310058-05)*

22-APR-2022 LNM/D. 15-APR-2022
Add depth of 9.4 metres 44°54'30.2"N 062°13'37.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6310058-06)*

22-APR-2022 LNM/D. 15-APR-2022
Add depth of 9.7 metres 44°53'30.8"N 062°13'28.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6310058-07)*

22-APR-2022 LNM/D. 15-APR-2022
Add depth of 9.8 metres 44°54'07.3"N 062°14'46.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6310058-08)*

22-APR-2022 LNM/D. 15-APR-2022
Add depth of 10.5 metres 44°51'25.5"N 062°13'46.3"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6310058-09)*

22-APR-2022 LNM/D. 15-APR-2022
Add depth of 8.3 metres 44°51'12.4"N 062°19'21.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6310058-16)*



Chart no. 4227

- 22-APR-2022** LNM/D. 15-APR-2022
Add depth of 8 metres 44°52'12.4"N 062°18'03.2"W
(See Chart No. 1, I10)
DFO(6310058-18)
- 22-APR-2022** LNM/D. 15-APR-2022
Replace depth of 6.4 metres with depth of 6.1 metres 44°48'28.6"N 062°24'06.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6310058-23)*
- 15-APR-2022** LNM/D. 24-DEC-2021
Delete depth of 24 metres 45°01'51.0"N 061°44'00.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310054-12)*
- 15-APR-2022** LNM/D. 24-DEC-2021
Add depth of 17.5 metres 45°01'48.8"N 061°43'54.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310054-13)*
- 24-DEC-2021** LNM/D. 27-AUG-2021
Delete note GAS PIPELINES Gas pipelines and wells contain natural gas under pressure and damage to these installations could create an immediate fire hazard. Mariners are cautioned not to anchor or trawl near pipelines or wellheads. GAZODUCS Les gazoducs et les puits à gaz contiennent du gaz sous pression et du dommage à ces installations pourraient créer un danger de feu immédiat. Les navires ne devraient ni mouiller ni chaluter près de pipelines ou de têtes de puits. 45°03'27.0"N 062°46'17.0"W
DFO(6309793-13)
- 24-DEC-2021** LNM/D. 27-AUG-2021
Delete legend See/Voir note GAS PIPELINES/GAZODUCS 45°01'46.4"N 061°34'16.3"W
DFO(6309793-14)
- 24-DEC-2021** LNM/D. 27-AUG-2021



Chart no. 4227

Replace pipeline, Gas/Gaz with abandoned pipeline joining 45°09'25.7"N 061°37'43.6"W
(See Chart No. 1, L40.1, L44) 45°08'35.0"N 061°38'48.0"W
45°07'41.5"N 061°38'41.0"W
45°06'03.0"N 061°36'10.5"W
and 45°00'35.7"N 061°29'58.5"W

DFO(6309793-15)

24-DEC-2021

LNM/D. 27-AUG-2021

Replace pipeline, Gas/Gaz with abandoned pipeline joining 45°09'23.5"N 061°37'42.5"W
(See Chart No. 1, L40.1, L44) 45°08'28.7"N 061°38'33.5"W
45°07'40.0"N 061°38'20.9"W
45°05'39.4"N 061°34'57.0"W
and 45°00'52.0"N 061°29'58.3"W

DFO(6309793-16)

27-AUG-2021

LNM/D. 30-APR-2021

Replace depth of 4 metres with depth of 2.8 metres 44°53'12.0"N 062°20'17.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6309424-01)*

27-AUG-2021

LNM/D. 30-APR-2021

Add depth of 1.2 metres 44°51'47.2"N 062°18'34.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6309424-05)*

27-AUG-2021

LNM/D. 30-APR-2021

Add depth of 1.6 metres 44°54'22.3"N 062°14'24.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6309424-14)*

30-APR-2021

LNM/D. 25-DEC-2020

Add wreck, least depth unknown, dangerous to surface navigation 44°55'37.2"N 061°56'57.0"W
with legend 'PA'
(See Chart No. 1, K28, B7) *DFO(6309403-01)*
This notice affects Electronic Navigational Chart: CA376109

25-DEC-2020

LNM/D. 18-DEC-2020



Chart no. 4227

Delete sector light FRWG23m, and limits of arcs of visibility. 44°49'21.8"N 062°35'54.3"W
(See Chart No. 1, P40.1)

This notice affects Electronic Navigational Chart: (F2020047) LL(591) DFO(6309299-01)
CA376083

25-DEC-2020

LNМ/D. 18-DEC-2020

Add abandoned lighthouse with legend Lt Ho/Phare Aband 44°49'21.8"N 062°35'54.3"W
(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: CA376083 DFO(6309299-02)

18-DEC-2020

LNМ/D. 16-OCT-2020

Add depth of 1.2 metres 45°00'06.7"N 062°04'02.2"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109 DFO(6309279-12)

18-DEC-2020

LNМ/D. 16-OCT-2020

Add depth of 1.1 metres 45°01'22.8"N 061°58'56.9"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109 DFO(6309279-15)

18-DEC-2020

LNМ/D. 16-OCT-2020

Add depth of 5.1 metres 45°00'17.1"N 061°55'27.5"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109 DFO(6309279-17)

18-DEC-2020

LNМ/D. 16-OCT-2020

Add depth of 8.5 metres 45°01'49.8"N 061°51'19.9"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109 DFO(6309279-18)

16-OCT-2020

LNМ/D. 10-JUL-2020

Add light Fl G against green port hand spar buoy, 44°46'43.2"N 062°34'37.9"W
marked YA3

(See Chart No. 1, Qg) (F2020034) LL(590.01) DFO(6309237-01)

This notice affects Electronic Navigational Chart:
CA376083

16-OCT-2020

LNМ/D. 10-JUL-2020



Chart no. 4227

Add light Fl R against red starboard hand spar buoy, marked YA4 44°46'42.7"N 062°33'50.0"W
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart: CA376102 (F2020035) DFO(6309238-01)

10-JUL-2020

LNLM/D. 06-DEC-2019

Delete legend 'Fog Sig 60s' against light
(See Chart No. 1, R20)

44°49'29.0"N 062°20'16.0"W

(F2020025) LL(602) DFO(6309001-01)

This notice affects Electronic Navigational Chart:
CA176140, CA276204, CA376102

06-DEC-2019

LNLM/D. 28-DEC-2018

Delete BELL against black, yellow and black East cardinal
lighted pillar buoy Q(3) 10s, marked YS
(See Chart No 1 Q130.3)

44°39'48.0"N 062°50'30.0"W

(F2019038) LL(580.3) DFO(6308835-01)

This notice affects Electronic Navigational Chart:
CA376083

28-DEC-2018

LNLM/D. 03-AUG-2018

Amend "LFIR 12s 9m 5M" to read "Fl R 9m8M" against light
(See Chart No. 1, P16)

44°47'40.3"N 062°39'01.4"W

This notice affects Electronic Navigational Chart: CA376083 (F2018045) LL(589) DFO(6308528-01)

03-AUG-2018

LNLM/D. 06-OCT-2017

Add pilot boarding station
(See Chart No. 1, T1.1)

45°02'00.0"N 061°33'00.0"W

This notice affects Electronic Navigational Chart: CA376109 DFO(6308388-04)

06-OCT-2017

LNLM/D. 11-AUG-2017

Amend "WHIS" to read "BELL" against red and white
fairway pillar light buoy Mo(A), marked TT
(See Chart No. 1, R15, R14)

45°02'11.5"N 061°32'29.0"W

(G2017091) LL(635) DFO(6308058-01)

This notice affects Electronic Navigational Chart:
CA276204, CA376109

11-AUG-2017

LNLM/D. 03-MAR-2017



Chart no. 4227

Replace depth of 7 metres with depth of 5 metres, 8 decimetres 44°47'41.7"N 062°34'47.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308020-06)*

03-MAR-2017

Add flame tower with elevation of 61 metres 45°10'30.0"N 061°36'56.0"W
(See Chart No. 1, E23) *DFO(6307845-01)*

This notice affects Electronic Navigational Chart: CA276204,
CA376109

06-MAY-2016

Amend LFl 6s 26m 14M to read LFl 6s 8m 12M against light 44°39'52.5"N 062°51'48.8"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (F2016011) LL(580) *DFO(6307493-01)*
CA176140, CA276801, CA376083

04-DEC-2015

Add submarine cable joining 44°48'10.2"N 061°29'57.5"W
(See Chart No. 1, L30.1) 44°39'52.1"N 061°59'52.1"W
This notice affects Electronic Navigational Chart: 44°31'28.4"N 062°29'32.3"W
CA376061 44°28'45.4"N 062°40'20.3"W
44°27'56.5"N 062°43'42.6"W
44°27'04.5"N 062°46'42.2"W
and 44°26'03.9"N 062°55'33.5"W
DFO(6307260-01)

12-AUG-2011

Reposition green port hand lighted pillar bell buoy FlG, 44°53'02.0"N 062°06'27.0"W
marked VV1 to 44°52'59.8"N 062°06'16.3"W
(See Chart No. 1, Qg) *(F2011151) LL(608) DFO(6305651-01)*

This notice affects Electronic Navigational Chart:
CA376109

01-APR-2011

Amend FLR 12s 13m 6M to read FLR 12s 9m 5M against 44°47'40.3"N 062°39'01.4"W
light (See Chart No 1 P16) *(F2011038) LL(589) DFO(6305337-01)*



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4227

25-MAR-2011

LNM/D. 14-JAN-2011

Amend F 22m to read F 20m 18M against light
(See Chart No 1 P16)

44°51'38.6"N 062°26'57.2"W

(F2011026) LL(599) DFO(6305288-01)

14-JAN-2011

LNM/D. 23-APR-2010

Add pipeline with legend Gas/Gaz joining
(See Chart No 1 L40.1)

45°09'25.1"N 061°37'43.3"W

45°08'59.2"N 061°38'29.4"W

45°08'38.6"N 061°38'47.9"W

45°08'09.3"N 061°38'53.7"W

45°07'41.7"N 061°38'40.2"W

45°06'03.6"N 061°36'11.5"W

45°02'33.6"N 061°32'24.5"W

and 45°00'34.6"N 061°29'57.5"W

DFO(6305194-01)

23-APR-2010

LNM/D. 12-FEB-2010

Amend Iso 8s 20m 12M to read Fl 3s 21m 17M against light
(See Chart 1 P16)

45°05'24.0"N 061°42'01.7"W

(G2010012) LL(629) DFO(6304754-01)

This notice affects Electronic Navigational Chart:
CA176140, CA376109

12-FEB-2010

LNM/D. 31-JUL-2009

Amend Fl 15s 26m 9M to read LFl 6s 26m 14M against light
(See Chart 1 P16)

44°39'53.1"N 062°51'48.3"W

(F2009078) LL(580) DFO(6304719-01)

This notice affects Electronic Navigational Chart:
CA176140, CA276801, CA376083

31-JUL-2009

LNM/D. 10-JUL-2009

Delete BELL against red starboard hand lighted pillar bell
buoy FlR, marked TT2
(See Chart No 1 Qf)

45°04'28.0"N 061°33'04.0"W

(G2009055) LL(635.5) DFO(6304458-01)

This notice affects Electronic Navigational Chart:
CA376109



Chart no. 4227

31-JUL-2009

Delete red starboard hand lighted pillar bell buoy FlR,
BELL, marked TT4.
(See Chart No 1 Qf)

LNМ/D. 10-JUL-2009

45°06'24.0"N 061°35'05.0"W

(G2009056) LL(636) DFO(6304459-04)

31-JUL-2009

Add red starboard hand lighted pillar buoy QR, marked TT4.
(See Chart No 1 Qf)

LNМ/D. 10-JUL-2009

45°05'54.6"N 061°34'36.3"W

(G2009056) LL(636) DFO(6304459-05)

10-JUL-2009

(P)Add pipeline and legend Gas/Gaz
(See Chart No 1 L40.1)
Encana will commence constructing a gas pipeline
from Goldboro to the Deep Panuke Gasfield in July
2009. The proposed completion date is October 2009.
The work is completed. Notice 10-JUL-2009(P),
DFO(6304483) is cancelled.
Cancelled on 14-JAN-11

LNМ/D. 24-APR-2009

joining 45°09'24.7"N 061°37'44.1"W
45°08'19.3"N 061°39'45.4"W
45°06'31.7"N 061°36'53.8"W
45°06'31.5"N 061°36'36.8"W
45°06'08.5"N 061°36'23.4"W
45°04'48.6"N 061°34'57.7"W
and 45°00'34.6"N 061°29'57.5"W

DFO(6304483-01)

24-APR-2009

Delete light F 25m 12M
(See Chart No 1 P1)

LNМ/D. 27-FEB-2009

45°09'52.8"N 061°39'16.5"W

(G2009010) LL(637) DFO(6304315-01)

This notice affects Electronic Navigational Chart:
CA376109, CA476111

27-FEB-2009

Amend Fl G 12s 23m 8M to read LFl G 6s 23m 4M against
light
(See Chart No 1 P16)

LNМ/D. 26-SEP-2008

44°44'55.6"N 062°45'24.2"W

(F2008175) LL(585) DFO(6304263-01)

This notice affects Electronic Navigational Chart:
CA376083, CA476084

26-SEP-2008

LNМ/D. 28-DEC-2007



Chart no. 4227

Amend VC to read V against red and white fairway lighted
pillar bell buoy Mo(A)
(See Chart No 1 Qh)

45°01'13.0"N 061°39'09.0"W

(G2008025) LL(632) DFO(6303902-01)

This notice affects Electronic Navigational Chart:
CA376109

28-DEC-2007

LNМ/D. 06-JUL-2007

Delete green port hand spar buoy, marked TU1
(See Chart No 1 Qg)

45°02'36.0"N 061°37'42.0"W

(G2007175) LL(5634.41) DFO(6303727-01)

06-JUL-2007

LNМ/D. 11-FEB-2005

Replace red, green and red starboard bifurcation lighted
pillar bell buoy Fl(2+1)R, marked TY with yellow
and black South cardinal lighted pillar buoy
Q(6)+LFl 15s, marked TY

45°04'33.0"N 061°37'20.0"W

(G2007044) LL(633) DFO(6303456-01)

This notice affects Electronic Navigational Chart:
CA376067

06-JUL-2007

LNМ/D. 11-FEB-2005

Delete BELL against yellow and black South cardinal
lighted pillar bell buoy Q(6)+LFl 15s, marked TU

45°02'45.0"N 061°35'12.0"W

(G2007078) LL(634.4) DFO(6303485-01)

This notice affects Electronic Navigational Chart:
CA376061

11-FEB-2005

LNМ/D. 25-JUN-2004

Amend "Fl 20s 17m 16M" to read "LFl 20s 16m 10M" against light 45°05'59.8"N 061°32'31.9"W

LL(639) DFO(6302110-01)

11-FEB-2005

LNМ/D. 25-JUN-2004

Amend "Fl 10s 22m 20M" to read "Fl 10s 22m 15M" against light 44°59'15.8"N 061°57'58.4"W

LL(615) DFO(6302110-02)



Chart no. 4227

25-JUN-2004 LNM/D. 13-JUN-2003

Amend "Bn R" to read "2 Bns" 45°00'39.4"N 061°57'12.6"W

(G2004063) DFO(6301439-01)

13-JUN-2003 LNM/D. 26-JUL-2002

Add depth of 11 metres, 8 decimetres 44°52'40.5"N 062°10'57.7"W

DFO(6300871-01)

13-JUN-2003 LNM/D. 26-JUL-2002

Add depth of 16 metres, 3 decimetres 44°52'45.7"N 062°13'19.8"W

DFO(6300871-02)

13-JUN-2003 LNM/D. 26-JUL-2002

Add depth of 19 metres 44°51'11.4"N 062°10'18.9"W

DFO(6300871-03)

13-JUN-2003 LNM/D. 26-JUL-2002

Add depth of 18 metres, 4 decimetres 44°49'58.4"N 062°12'30.7"W

DFO(6300871-04)

13-JUN-2003 LNM/D. 26-JUL-2002

Delete depth of 26 metres 44°49'58.0"N 062°12'24.0"W

DFO(6300871-05)

13-JUN-2003 LNM/D. 26-JUL-2002

Delete depth of 18 metres, 3 decimetres 44°52'32.0"N 062°11'00.0"W

DFO(6300871-06)

13-JUN-2003 LNM/D. 26-JUL-2002



Chart no. 4227

Replace depth of 17 metres, 1 decimetre with 13 metres, 9 decimetres 44°52'33.2"N 062°06'57.2"W

DFO(6300871-07)

26-JUL-2002

LNМ/D. 30-MAR-2001

Delete green port hand pillar light buoy FIG, BELL, marked VH3 45°03'14.0"N 061°48'22.0"W

DFO(6300287-01)

30-MAR-2001

LNМ/D. 01-DEC-2000

Delete legend "Aband" 44°46'40.0"N 062°12'36.0"W

DFO(6829338-02)

30-MAR-2001

LNМ/D. 01-DEC-2000

Delete legend "Aband" 44°42'30.0"N 061°46'30.0"W

DFO(6829338-03)

01-DEC-2000

LNМ/D. 06-OCT-2000

Add gas pipeline joining 45°09'23.8"N 061°37'41.9"W
45°08'47.7"N 061°38'24.1"W
45°08'31.2"N 061°38'32.6"W
45°08'05.7"N 061°38'34.7"W
45°07'39.0"N 061°38'20.3"W
45°07'24.8"N 061°38'02.2"W
45°05'41.2"N 061°34'59.1"W
45°04'09.8"N 061°33'42.0"W
and 45°00'51.1"N 061°29'57.5"W

(H2000-003) DFO(6828771-01)

01-DEC-2000

LNМ/D. 06-OCT-2000

Add legend "Gas/Gaz" 45°04'08.0"N 061°33'54.0"W

(H2000-003) DFO(6828771-02)

01-DEC-2000

LNМ/D. 06-OCT-2000



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4227

Add legend "See/Voir note GAS PIPELINES/GAZODUCS" 45°01'50.0"N 061°33'50.0"W

(H2000-003) DFO(6828771-03)

01-DEC-2000

LNM/D. 06-OCT-2000

Add note "GAS PIPELINES Gas pipelines and wells contain natural gas under pressure and damage to these installations could create an immediate fire hazard. Mariners are cautioned not to anchor or trawl near pipelines or wellheads. GAZODUCS Les gazoducs et les puits à gaz contiennent du gaz sous pression et du dommage à ces installations pourrait créer un danger de feu immédiat. Les navires ne devraient ni mouiller ni chaluter près de pipelines ou de têtes de puits." 45°06'03.0"N 062°46'36.0"W (H2000-003) DFO(6828771-04)

06-OCT-2000

LNM/D. 19-MAR-1999

Amend Fl(3)20s 20m 13M to read "Fl 7s 20m 14M" 44°49'29.2"N 062°20'16.0"W

(F1999-015) LL(602) DFO(6828748-02)