



### Chart no. 4234

#### 4234 - Country Harbour - New Chart - 10-APR-1987 - NAD 1983

**15-APR-2022**

LNM/D. 11-MAR-2022

Replace depth of 8 metres with depth of 6.5 metres

45°13'08.5"N 061°44'09.9"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476111

*DFO(6310054-01)*

**15-APR-2022**

LNM/D. 11-MAR-2022

Delete depth of 17.4 metres

45°13'02.0"N 061°44'02.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476111

*DFO(6310054-02)*

**15-APR-2022**

LNM/D. 11-MAR-2022

Add depth of 12.7 metres

45°13'02.9"N 061°44'01.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476111

*DFO(6310054-03)*

**15-APR-2022**

LNM/D. 11-MAR-2022

Delete depth of 12.5 metres

45°12'52.5"N 061°43'41.9"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476111

*DFO(6310054-04)*

**15-APR-2022**

LNM/D. 11-MAR-2022

Add depth of 11.3 metres

45°12'52.2"N 061°43'45.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476111

*DFO(6310054-05)*

**15-APR-2022**

LNM/D. 11-MAR-2022

Replace depth of 11.6 metres with depth of 10.6 metres

45°11'07.6"N 061°42'37.9"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476111

*DFO(6310054-06)*

**15-APR-2022**

LNM/D. 11-MAR-2022

Replace depth of 21.9 metres with depth of 16.2 metres

45°10'45.2"N 061°42'26.1"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476111

*DFO(6310054-07)*

**15-APR-2022**

LNM/D. 11-MAR-2022



### Chart no. 4234

Add depth of 14.2 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109,  
CA476111

45°09'15.2"N 061°39'28.8"W  
*DFO(6310054-08)*

**24-DEC-2021** LNM/D. 18-JUN-2021  
Delete legend See/Voir note GAS PIPELINES/GAZODUCS  
This notice affects Electronic Navigational Chart: CA376109,  
CA476111

45°09'07.0"N 061°38'45.0"W  
*DFO(6309793-02)*

**24-DEC-2021** LNM/D. 18-JUN-2021  
Replace pipeline, Gas/Gaz with abandoned pipeline  
(See Chart No. 1, L40.1, L44)  
This notice affects Electronic Navigational Chart:  
CA376109, CA476111

between 45°09'10.1"N 061°37'57.6"W  
and 45°09'00.0"N 061°38'08.8"W  
*DFO(6309793-03)*

**24-DEC-2021** LNM/D. 18-JUN-2021  
Replace pipeline, Gas/Gaz with abandoned pipeline  
(See Chart No. 1, L40.1, L44)  
This notice affects Electronic Navigational Chart:  
CA376109, CA476111

between 45°09'17.0"N 061°37'57.6"W  
and 45°09'00.3"N 061°38'27.7"W  
*DFO(6309793-04)*

**14-JAN-2011** LNM/D. 23-APR-2010  
Add pipeline with legend Gas/Gaz  
(See Chart No 1 L40.1)

between 45°09'17.4"N 061°37'57.5"W  
and 45°09'00.3"N 061°38'27.9"W  
*DFO(6305191-01)*

This notice affects Electronic Navigational Chart:  
CA476111

**10-JUL-2009** LNM/D. 24-APR-2009  
(P)Add pipeline and legend Gas/Gaz  
(See Chart No 1 L40.1)  
Encana will commence constructing a gas pipeline  
from Goldboro to the Deep Panuke Gasfield in July  
2009. The proposed completion date is October 2009.  
The work is completed. Notice 10-JUL-2009(P),  
DFO(6304485-1) is cancelled.  
Cancelled on 14-JAN-11

joining 45°09'17.7"N 061°37'57.0"W  
45°09'05.9"N 061°38'19.0"W  
and 45°09'00.0"N 061°38'29.9"W  
*DFO(6304485-01)*

**24-APR-2009** LNM/D. 27-FEB-2009



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4234

Delete light F 25m 12M  
(See Chart No 1 P1)

45°09'52.8"N 061°39'16.5"W

*(G2009010) LL(637) DFO(6304315-01)*

This notice affects Electronic Navigational Chart:  
CA376109, CA476111

#### 27-FEB-2009

LNM/D. 13-FEB-2009

(T)Add private yellow cautionary lighted spar buoy Fl Y  
(See Chart No 1 Qm)

45°09'09.2"N 061°37'59.8"W

The mooring is temporary and will be removed by October  
2009.

*DFO(6304249-03)*

Goldboro Construction completed. Notice 27-FEB-2009(T),  
DFO(6304249-3) is cancelled.

Cancelled on 06-NOV-09

#### 13-FEB-2009

LNM/D. 28-NOV-2008

Replace green port hand can buoy, marked TT7 with  
green port hand lighted spar buoy QG, marked  
TT7  
(See Chart No 1 Qg)

45°09'34.0"N 061°39'20.0"W

*(G2008088) LL(636.04) DFO(6304204-01)*

This notice affects Electronic Navigational  
Chart: CA376109

#### 24-NOV-2000

LNM/D. 19-MAR-1999

Add gas pipeline between 45°09'10.7"N 061°37'57.5"W  
and 45°09'00.3"N 061°38'09.6"W

*(H2000-003) DFO(6828774-01)*

#### 24-NOV-2000

LNM/D. 19-MAR-1999

Add legend "Gas/Gaz" 45°09'04.5"N 061°38'12.0"W

*(H2000-003) DFO(6828774-02)*

#### 24-NOV-2000

LNM/D. 19-MAR-1999

Add legend "See/Voir note GAS PIPELINES/GAZODUCS" 45°09'08.0"N 061°38'43.0"W

*(H200-003) DFO(6828774-03)*



### Chart no. 4234

#### 4234 - Country Island to / à Barren Island - New Chart - 10-APR-1987 - NAD 1983

**08-SEP-2023**

LNM/D. 21-JUL-2023

Reposition green port hand spar buoy, marked VK5  
(See Chart 1, Qc)  
This notice affects Electronic Navigational Chart:  
CA376109

from 45°02'43.1"N 061°53'26.5"W  
to 45°02'45.0"N 061°53'23.4"W  
*(F2023011) DFO(6310718-01)*

**21-JUL-2023**

LNM/D. 22-JUL-2022

Delete Starboard day beacon  
(See Chart 1, Q80, Q81)

45°00'39.7"N 061°57'12.3"W

This notice affects Electronic Navigational Chart: CA376109 *(F2023002) DFO(6310679-01)*

**21-JUL-2023**

LNM/D. 22-JUL-2022

Delete Starboard day beacon  
(See Chart 1, Q80, Q81)

45°00'39.7"N 061°57'12.3"W

This notice affects Electronic Navigational Chart: CA376109 *(F2023003) DFO(6310679-02)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Add depth of 7.8 metres  
(See Chart No. 1, I10)

44°55'07.8"N 062°04'31.1"W

This notice affects Electronic Navigational Chart: CA376109 *DFO(6310183-18)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Add depth of 15.8 metres  
(See Chart No. 1, I10)

44°53'58.0"N 062°04'36.9"W

This notice affects Electronic Navigational Chart: CA376109 *DFO(6310183-19)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Replace depth of 9.9 metres with depth of 9.1 metres  
(See Chart No. 1, I10)

44°55'05.9"N 062°04'14.4"W

This notice affects Electronic Navigational Chart: CA376109 *DFO(6310183-20)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Replace depth of 11 metres with depth of 9.6 metres  
(See Chart No. 1, I10)

44°57'15.4"N 062°03'27.9"W

This notice affects Electronic Navigational Chart: CA376109 *DFO(6310183-21)*



**Chart no. 4234**

**22-JUL-2022**

LNМ/D. 15-JUL-2022

Add depth of 5.3 metres

44°55'54.2"N 062°03'05.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-01)*

**22-JUL-2022**

LNМ/D. 15-JUL-2022

Add depth of 18.2 metres

44°55'12.6"N 062°02'39.2"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-03)*

**22-JUL-2022**

LNМ/D. 15-JUL-2022

Add depth of 9.5 metres

44°55'32.6"N 062°02'30.8"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-04)*

**22-JUL-2022**

LNМ/D. 15-JUL-2022

Add depth of 8.4 metres

44°54'38.1"N 062°02'10.8"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-05)*

**22-JUL-2022**

LNМ/D. 15-JUL-2022

Add depth of 4.7 metres

44°54'36.6"N 062°01'37.9"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-06)*

**22-JUL-2022**

LNМ/D. 15-JUL-2022

Add depth of 3 metres

44°55'00.4"N 062°01'55.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-07)*

**22-JUL-2022**

LNМ/D. 15-JUL-2022

Add depth of 7 metres

44°54'42.8"N 062°00'45.1"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-08)*

**22-JUL-2022**

LNМ/D. 15-JUL-2022



### Chart no. 4234

Replace depth of 8.9 metres with depth of 8.1 metres 44°54'41.0"N 062°00'12.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-09)*

**22-JUL-2022** LNM/D. 15-JUL-2022  
Add depth of 4.2 metres 44°56'10.8"N 062°01'06.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-10)*

**22-JUL-2022** LNM/D. 15-JUL-2022  
Add depth of 9.8 metres 44°56'07.1"N 062°00'50.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-11)*

**22-JUL-2022** LNM/D. 15-JUL-2022  
Replace depth of 6.7 metres with depth of 6.1 metres 44°57'47.4"N 062°02'40.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-12)*

**22-JUL-2022** LNM/D. 15-JUL-2022  
Add depth of 9.6 metres 44°58'09.8"N 062°01'55.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-13)*

**22-JUL-2022** LNM/D. 15-JUL-2022  
Replace depth of 8.9 metres with depth of 8.2 metres 44°57'34.4"N 062°01'14.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-14)*

**22-JUL-2022** LNM/D. 15-JUL-2022  
Replace depth of 5.2 metres with depth of 4.7 metres 44°56'50.8"N 062°00'48.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-15)*

**22-JUL-2022** LNM/D. 15-JUL-2022  
Add depth of 3.9 metres 44°56'15.0"N 062°00'14.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-16)*



### Chart no. 4234

**22-JUL-2022**

LNM/D. 15-JUL-2022

Add depth of 9.1 metres

44°56'28.0"N 061°57'53.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-17)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Replace depth of 13.5 metres with depth of 12.7 metres

44°55'03.0"N 061°57'40.2"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-19)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Delete wreck PA, depth unknown

44°55'37.7"N 061°56'57.1"W

(See Chart No. 1, K28 , B7)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-20)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Delete depth of 11.5 metres

44°56'04.5"N 061°57'00.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-23)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Add depth of 9.7 metres

44°56'06.6"N 061°57'04.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-24)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Delete depth of 20.6 metres

44°55'13.5"N 062°02'47.4"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-25)*

**22-JUL-2022**

LNM/D. 15-JUL-2022

Add wreck with known depth of 26.3 metres

44°55'41.2"N 061°57'02.6"W

(See Chart No. 1, K26)

This notice affects Electronic Navigational Chart: CA376109

*DFO(6310184-26)*

**15-JUL-2022**

LNM/D. 15-APR-2022



### Chart no. 4234

Replace depth of 5.5 metres with depth of 4.8 metres  
(See Chart No. 1, I10) 44°51'56.7"N 062°04'25.7"W  
This notice affects Electronic Navigational Chart: CA276204, DFO(6310119-01)  
CA376109

**15-JUL-2022** LNM/D. 15-APR-2022  
Delete depth of 20.6 metres 44°52'07.0"N 062°05'08.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 DFO(6310119-02)

**15-JUL-2022** LNM/D. 15-APR-2022  
Add depth of 16.6 metres 44°52'08.2"N 062°05'02.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 DFO(6310119-03)

**15-JUL-2022** LNM/D. 15-APR-2022  
Delete depth of 21.3 metres 44°52'18.5"N 062°04'27.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 DFO(6310119-04)

**15-JUL-2022** LNM/D. 15-APR-2022  
Add depth of 15.2 metres 44°52'15.7"N 062°04'28.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 DFO(6310119-05)

**15-JUL-2022** LNM/D. 15-APR-2022  
Replace depth of 9.4 metres with depth of 9.1 metres 44°52'42.2"N 062°04'38.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 DFO(6310119-06)

**15-JUL-2022** LNM/D. 15-APR-2022  
Add depth of 17.9 metres 44°53'12.0"N 062°06'13.9"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109, DFO(6310119-07)  
CA476104

**15-APR-2022** LNM/D. 11-MAR-2022





### Chart no. 4234

Add depth of 14.2 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109,  
CA476111

45°09'15.2"N 061°39'28.8"W  
*DFO(6310054-08)*

**15-APR-2022** LNM/D. 11-MAR-2022  
Add depth of 23.9 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109

45°02'56.0"N 061°36'14.4"W  
*DFO(6310054-09)*

**15-APR-2022** LNM/D. 11-MAR-2022  
Delete depth of 18.9 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109

45°02'09.5"N 061°40'18.4"W  
*DFO(6310054-10)*

**15-APR-2022** LNM/D. 11-MAR-2022  
Add depth of 17.3 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109

45°02'05.0"N 061°40'13.0"W  
*DFO(6310054-11)*

**15-APR-2022** LNM/D. 11-MAR-2022  
Delete depth of 24 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109

45°01'51.0"N 061°43'58.6"W  
*DFO(6310054-12)*

**15-APR-2022** LNM/D. 11-MAR-2022  
Add depth of 17.5 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109

45°01'48.8"N 061°43'54.8"W  
*DFO(6310054-13)*

**24-DEC-2021** LNM/D. 18-JUN-2021



### Chart no. 4234

- Delete note 45°10'58.0"N 061°35'20.0"W  
GAS PIPELINES Gas pipelines and wells contain natural gas  
under pressure and damage to these installations could create *DFO(6309793-01)*  
an immediate fire hazard. Mariners are cautioned not to  
anchor or trawl near pipelines or wellheads.  
GAZODUCS Les gazoducs et les puits à gaz contiennent du gaz  
sous pression et du dommage à ces installations pourraient  
créer un danger de feu immédiat. Les navires ne devraient ni  
mouiller ni chaluter près de pipelines ou de têtes de puits.  
This notice affects Electronic Navigational Chart: CA376109
- 24-DEC-2021** LNM/D. 18-JUN-2021  
Delete legend See/Voir note GAS PIPELINES/GAZODUCS 45°07'57.0"N 061°37'40.0"W  
This notice affects Electronic Navigational Chart: CA376109,  
CA476111 *DFO(6309793-02)*
- 24-DEC-2021** LNM/D. 18-JUN-2021  
Replace pipeline, Gas/Gaz with abandoned pipeline joining 45°09'24.0"N 061°37'40.8"W  
(See Chart No. 1, L40.1, L44) 45°08'48.5"N 061°38'22.7"W  
This notice affects Electronic Navigational Chart: 45°08'09.7"N 061°38'34.7"W  
CA376109, CA476111 45°07'42.9"N 061°38'23.4"W  
45°05'42.1"N 061°34'59.1"W  
and 45°02'53.3"N 061°32'13.9"W  
*DFO(6309793-03)*
- 24-DEC-2021** LNM/D. 18-JUN-2021  
Replace pipeline, Gas/Gaz with abandoned pipeline joining 45°09'25.2"N 061°37'43.4"W  
(See Chart No. 1, L40.1, L44) 45°09'01.8"N 061°38'26.5"W  
This notice affects Electronic Navigational Chart: 45°08'39.9"N 061°38'48.4"W  
CA376109, CA476111 45°08'12.1"N 061°38'55.3"W  
45°07'43.2"N 061°38'43.1"W  
45°06'04.0"N 061°36'12.8"W  
and 45°02'24.8"N 061°32'15.6"W  
*DFO(6309793-04)*
- 18-JUN-2021** LNM/D. 30-APR-2021  
Add depth of 6.9 metres 45°08'35.4"N 061°36'39.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309441-01)*
- 30-APR-2021** LNM/D. 18-DEC-2020



### Chart no. 4234

Add wreck, least depth unknown, dangerous to surface navigation with legend 'PA' 44°55'37.2"N 061°56'57.0"W  
(See Chart No. 1, K28, B7) *DFO(6309403-01)*  
This notice affects Electronic Navigational Chart: CA376109

**18-DEC-2020** LNM/D. 03-AUG-2018  
Delete depth of 3.8 metres 44°56'35.6"N 062°00'32.7"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-07)*

**18-DEC-2020** LNM/D. 03-AUG-2018  
Add depth of 1.8 metres 44°56'36.5"N 062°00'29.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-08)*

**18-DEC-2020** LNM/D. 03-AUG-2018  
Delete depth of 13.2 metres 44°58'10.5"N 061°58'00.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-09)*

**18-DEC-2020** LNM/D. 03-AUG-2018  
Add depth of 7 metres 44°58'08.5"N 061°57'56.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-10)*

**18-DEC-2020** LNM/D. 03-AUG-2018  
Replace depth of 3.5 metres with depth of 3.1 metres 45°00'00.4"N 062°02'12.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-11)*

**18-DEC-2020** LNM/D. 03-AUG-2018  
Add depth of 1.2 metres 45°00'06.7"N 062°04'02.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-12)*

**18-DEC-2020** LNM/D. 03-AUG-2018  
Replace depth of 2.2 metres with depth of 1.5 metres 45°01'28.5"N 061°59'38.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-13)*



### Chart no. 4234

**18-DEC-2020**

LNМ/D. 03-AUG-2018

Delete depth of 2.1 metres  
(See Chart No. 1, I10)

45°01'24.0"N 061°58'55.3"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6309279-14)*

**18-DEC-2020**

LNМ/D. 03-AUG-2018

Add depth of 1.1 metres  
(See Chart No. 1, I10)

45°01'22.8"N 061°58'56.9"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6309279-15)*

**18-DEC-2020**

LNМ/D. 03-AUG-2018

Delete depth of 10.7 metres  
(See Chart No. 1, I10)

45°00'21.0"N 061°55'24.0"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6309279-16)*

**18-DEC-2020**

LNМ/D. 03-AUG-2018

Add depth of 5.1 metres  
(See Chart No. 1, I10)

45°00'17.1"N 061°55'27.5"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6309279-17)*

**18-DEC-2020**

LNМ/D. 03-AUG-2018

Add depth of 8.5 metres  
(See Chart No. 1, I10)

45°01'49.8"N 061°51'19.9"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6309279-18)*

**18-DEC-2020**

LNМ/D. 03-AUG-2018

Delete depth of 5.2 metres  
(See Chart No. 1, I10)

45°03'18.0"N 061°44'44.8"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6309279-19)*

**18-DEC-2020**

LNМ/D. 03-AUG-2018

Add depth of 4.4 metres  
(See Chart No. 1, I10)

45°03'20.8"N 061°44'49.9"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6309279-20)*

**03-AUG-2018**

LNМ/D. 06-OCT-2017



### Chart no. 4234

Reposition green port hand can buoy, marked VM9  
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:  
CA376109

from 45°00'30.0"N 061°57'31.0"W  
to 45°00'29.4"N 061°57'28.2"W

*(F2018015) DFO(6308295-01)*

### 03-AUG-2018

Reposition red starboard hand conical buoy, marked VM18  
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:  
CA376109

LNM/D. 06-OCT-2017

from 45°01'29.0"N 061°59'28.0"W  
to 45°01'26.1"N 061°59'31.8"W

*(F2018017) DFO(6308297-01)*

### 03-AUG-2018

Add pilot boarding station  
(See Chart No. 1, T1.1)

This notice affects Electronic Navigational Chart: CA376109

LNM/D. 06-OCT-2017

45°02'00.0"N 061°33'00.0"W

*DFO(6308388-04)*

### 06-OCT-2017

Amend "WHIS" to read "BELL" against red and white  
fairway pillar light buoy Mo(A), marked TT  
(See Chart No. 1, R15, R14)

This notice affects Electronic Navigational Chart:  
CA276204, CA376109

LNM/D. 28-JUL-2017

45°02'15.3"N 061°32'32.9"W

*(G2017091) LL(635) DFO(6308058-01)*

### 28-JUL-2017

Replace depth of 3 metres with depth of 2 metres, 2 decimetres  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376109

LNM/D. 03-MAR-2017

45°01'31.9"N 061°58'23.1"W

*DFO(6308010-01)*

### 03-MAR-2017

Add flame tower with elevation of 61 metres  
(See Chart No. 1, E23)

This notice affects Electronic Navigational Chart: CA276204,  
CA376109

LNM/D. 11-MAR-2016

45°10'30.0"N 061°36'56.0"W

*DFO(6307845-01)*

### 11-MAR-2016

Add wreck Wk with known depth of 18 metres, 2 decimetres.  
(See Chart No. 1, K26)

This notice affects Electronic Navigational Chart: CA376109

LNM/D. 08-JAN-2016

45°07'30.2"N 061°37'05.0"W

*DFO(6307464-01)*



### Chart no. 4234

#### 08-JAN-2016

LNМ/D. 29-JUN-2012

Delete depth of 3 metres, 4 decimetres  
(See Chart No. 1, I10)

44°57'47.3"N 062°04'28.5"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6307378-01)*

#### 08-JAN-2016

LNМ/D. 29-JUN-2012

Add depth of 2 metres, 6 decimetres  
(See Chart No. 1, I10)

44°57'45.6"N 062°04'27.1"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6307378-02)*

#### 08-JAN-2016

LNМ/D. 29-JUN-2012

Delete depth of 12 metres, 2 decimetres  
(See Chart No. 1, I10)

44°56'50.0"N 062°05'33.6"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6307378-03)*

#### 08-JAN-2016

LNМ/D. 29-JUN-2012

Add depth of 6 metres, 5 decimetres  
(See Chart No. 1, I10)

44°56'52.1"N 062°05'29.0"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6307378-04)*

#### 08-JAN-2016

LNМ/D. 29-JUN-2012

Delete depth of 11 metres  
(See Chart No. 1, I10)

44°56'45.2"N 062°05'57.0"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6307378-05)*

#### 08-JAN-2016

LNМ/D. 29-JUN-2012

Add depth of 4 metres, 2 decimetres  
(See Chart No. 1, I10)

44°56'47.3"N 062°06'00.1"W

This notice affects Electronic Navigational Chart: CA376109

*DFO(6307378-06)*

#### 11-MAY-2012

LNМ/D. 12-AUG-2011

Amend FR 6m 8M to read FLR against light  
(See Chart No. 1, P1)

45°08'43.2"N 061°36'09.2"W

*(G2012026) LL(638) DFO(6305969-01)*

This notice affects Electronic Navigational Chart:  
CA376109

#### 12-AUG-2011

LNМ/D. 27-MAY-2011



**Chart no. 4234**

Reposition green port hand lighted pillar bell buoy FLG,  
marked VV1  
(See Chart No. 1, Qg)

from 44°53'02.0"N 062°06'27.0"W  
to 44°52'59.8"N 062°06'16.3"W

*(F2011151) LL(608) DFO(6305651-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**14-JAN-2011**

LNLM/D. 23-APR-2010

Add pipeline with legend Gas/Gaz  
(See Chart No 1 L40.1)

joining 45°09'24.9"N 061°37'43.6"W  
45°09'01.5"N 061°38'26.1"W  
45°08'39.9"N 061°38'47.1"W  
45°08'12.2"N 061°38'54.0"W  
45°07'44.3"N 061°38'42.5"W  
45°07'29.9"N 061°38'26.6"W  
45°06'02.9"N 061°36'10.7"W  
45°04'46.0"N 061°34'54.7"W  
and 45°02'24.2"N 061°32'13.5"W

This notice affects Electronic Navigational Chart:  
CA476111

*DFO(6305191-01)*

**23-APR-2010**

LNLM/D. 01-JAN-2010

Amend Iso 8s 20m 12M to read Fl 3s 21m 17M against light  
(See Chart 1 P16)

45°05'24.0"N 061°42'01.7"W

*(G2010012) LL(629) DFO(6304754-01)*

This notice affects Electronic Navigational Chart:  
CA176140, CA376109

**01-JAN-2010**

LNLM/D. 31-JUL-2009

Delete light FR  
(See Chart No 1 P1)

45°06'19.1"N 061°43'22.7"W

*(G2009153) LL(631) DFO(6304658-01)*

**01-JAN-2010**

LNLM/D. 31-JUL-2009

Add light Iso R  
(See Chart No 1 P1)

45°06'18.8"N 061°43'21.9"W

*(G2009154) LL(631.2) DFO(6304659-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**01-JAN-2010**

LNLM/D. 31-JUL-2009



**Chart no. 4234**

Add rescue station  
(See Chart No 1 T12)

45°06'26.0"N 061°43'16.0"W

*DFO(6304664-01)*

This notice affects Electronic Navigational Chart: CA576110

**31-JUL-2009**

LNМ/D. 10-JUL-2009

Delete BELL against red starboard hand lighted pillar bell  
buoy F1R, marked TT2  
(See Chart No 1 Qf)

45°04'28.0"N 061°33'04.0"W

*(G2009055) LL(635.5) DFO(6304458-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**31-JUL-2009**

LNМ/D. 10-JUL-2009

Delete red starboard hand lighted pillar bell buoy F1R,  
BELL, marked TT4.  
(See Chart No 1 Qf)

45°06'24.0"N 061°35'05.0"W

*(G2009056) LL(636) DFO(6304459-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**31-JUL-2009**

LNМ/D. 10-JUL-2009

Add red starboard hand lighted pillar buoy QR, marked TT4.  
(See Chart No 1 Qf)

45°05'54.6"N 061°34'36.3"W

*(G2009056) LL(636) DFO(6304459-02)*

This notice affects Electronic Navigational Chart:  
CA376109

**10-JUL-2009**

LNМ/D. 24-APR-2009

(P)Add pipeline and legend Gas/Gaz  
(See Chart No 1 L40.1)  
Encana will commence constructing a gas pipeline  
from Goldboro to the Deep Panuke Gasfield in July  
2009. The proposed completion date is October 2009.  
The work is completed. Notice 10-JUL-2009(P),  
DFO(6304485-2) is cancelled.  
Cancelled on 14-JAN-11

joining 45°09'24.7"N 061°37'44.1"W  
45°08'19.3"N 061°39'45.4"W  
45°06'31.7"N 061°36'53.8"W  
45°06'31.5"N 061°36'36.8"W  
45°06'08.5"N 061°36'23.4"W  
and 45°02'24.3"N 061°32'13.5"W

*DFO(6304485-02)*

**24-APR-2009**

LNМ/D. 27-FEB-2009





### Chart no. 4234

Delete light F 25m 12M  
(See Chart No 1 P1)

45°09'52.8"N 061°39'16.5"W

*(G2009010) LL(637) DFO(6304315-01)*

This notice affects Electronic Navigational Chart:  
CA376109, CA476111

#### 27-FEB-2009

LN/D. 13-FEB-2009

(T)Add private yellow cautionary lighted spar buoy Fl Y  
(See Chart No 1 Qm)  
The mooring is temporary and will be removed by October  
2009.  
Goldboro Construction completed. Notice 27-FEB-2009(T),  
DFO(6304249-1) is cancelled.  
Cancelled on 06-NOV-09

45°09'19.1"N 061°37'48.0"W

*DFO(6304249-01)*

#### 27-FEB-2009

LN/D. 13-FEB-2009

(T)Add private yellow cautionary lighted spar buoy Fl Y  
(See Chart No 1 Qm)  
The mooring is temporary and will be removed by October  
2009.  
Goldboro Construction completed. Notice 27-FEB-2009(T),  
DFO(6304249-2) is cancelled.  
Cancelled on 06-NOV-09

45°09'14.1"N 061°37'53.9"W

*DFO(6304249-02)*

#### 27-FEB-2009

LN/D. 13-FEB-2009

(T)Add private yellow cautionary lighted spar buoy Fl Y  
(See Chart No 1 Qm)  
The mooring is temporary and will be removed by October  
2009.  
Goldboro Construction completed. Notice 27-FEB-2009(T),  
DFO(6304249-3) is cancelled.  
Cancelled on 06-NOV-09

45°09'09.2"N 061°37'59.8"W

*DFO(6304249-03)*

#### 13-FEB-2009

LN/D. 28-NOV-2008

Replace green port hand can buoy, marked TT7 with  
green port hand lighted spar buoy QG, marked  
TT7  
(See Chart No 1 Qg)

45°09'34.0"N 061°39'20.0"W

*(G2008088) LL(636.04) DFO(6304204-01)*

This notice affects Electronic Navigational  
Chart: CA376109



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4234

**26-SEP-2008**

Add green port hand lighted spar buoy FlG, marked V1  
(See Chart No 1 Qg)

LNМ/D. 28-DEC-2007

45°05'02.0"N 061°42'04.0"W

*(G2008013) LL(626.9) DFO(6303890-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**26-SEP-2008**

Amend VC to read V against red and white fairway lighted  
pillar bell buoy Mo(A)  
(See Chart No 1 Qh)

LNМ/D. 28-DEC-2007

45°01'13.0"N 061°39'09.0"W

*(G2008025) LL(632) DFO(6303902-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**26-SEP-2008**

Delete green port hand spar buoy, marked VC1  
(See Chart No 1 Qg)

LNМ/D. 28-DEC-2007

45°05'02.0"N 061°42'04.0"W

*(G2008030) DFO(6303907-01)*

This notice affects Electronic Navigational Chart: CA376109

**26-SEP-2008**

Delete rear range/leading light FR with leading line and  
bearing legend 320½°  
(See Chart No 1Pe )

LNМ/D. 28-DEC-2007

45°06'27.6"N 061°43'32.5"W

*(G2008045) LL(631.1) DFO(6303982-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**28-DEC-2007**

Delete green port hand spar buoy, marked TU1  
(See Chart No 1 Qg)

LNМ/D. 10-AUG-2007

45°02'36.0"N 061°37'42.0"W

*(G2007175) LL(5634.41) DFO(6303727-01)*

**10-AUG-2007**

LNМ/D. 27-JUL-2007



**Chart no. 4234**

Add depth of 2 metres, 6 decimetres 45°00'46.3"N 061°59'46.1"W

*DFO(6303586-01)*

**10-AUG-2007**

LN/D. 27-JUL-2007

Add depth of 2 metres, 9 decimetres 45°01'18.2"N 061°59'32.0"W

*DFO(6303586-02)*

**10-AUG-2007**

LN/D. 27-JUL-2007

Add depth of 1 metre, 4 decimetres 45°01'27.2"N 061°59'30.8"W

*DFO(6303586-03)*

**27-JUL-2007**

LN/D. 06-JUL-2007

Amend FLG to read QG against green port hand lighted  
spar buoy, marked TY5

45°05'11.0"N 061°38'32.5"W

*(G2007070) LL(633.02) DFO(6303580-01)*

**06-JUL-2007**

LN/D. 24-MAR-2006

Replace red, green and red starboard bifurcation lighted  
pillar bell buoy Fl(2+1)R, marked TY with yellow  
and black South cardinal lighted pillar buoy  
Q(6)+LFl 15s, marked TY

45°04'33.0"N 061°37'20.0"W

*(G2007044) LL(633) DFO(6303456-01)*

This notice affects Electronic Navigational Chart:  
CA376067

**06-JUL-2007**

LN/D. 24-MAR-2006

Add light FLG against green port hand spar buoy,  
marked TY5

45°05'11.0"N 061°38'32.5"W

*(G2007070) LL(5633.02) DFO(6303478-01)*

**06-JUL-2007**

LN/D. 24-MAR-2006

Reposition red starboard hand spar buoy, marked TY4

from 45°05'01.0"N 061°38'04.0"W  
to 45°05'04.0"N 061°37'57.0"W

*(G2007072) LL(5633.01) DFO(6303484-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4234

**06-JUL-2007**

Delete BELL against yellow and black South cardinal  
lighted pillar bell buoy Q(6)+LFl 15s, marked TU

LNM/D. 24-MAR-2006

45°02'45.0"N 061°35'12.0"W

*(G2007078) LL(634.4) DFO(6303485-01)*

This notice affects Electronic Navigational Chart:  
CA376061

**24-MAR-2006**

Delete anchorage symbol 44°57'41.4"N 062°05'28.0"W

LNM/D. 11-FEB-2005

*DFO(6302755-01)*

**24-MAR-2006**

Add marine farm 44°57'42.0"N 062°05'48.0"W

LNM/D. 11-FEB-2005

*DFO(6302755-02)*

**11-FEB-2005**

Amend "Fl 20s 17m 16M" to read "LFl 20s 16m 10M" against light 45°05'59.8"N 061°32'31.9"W

LNM/D. 25-JUN-2004

*LL(639) DFO(6302110-01)*

**11-FEB-2005**

Amend "Fl 10s 22m 20M" to read "Fl 10s 22m 15M" against light 44°59'15.8"N 061°57'58.4"W

LNM/D. 25-JUN-2004

*LL(615) DFO(6302110-02)*

**25-JUN-2004**

Amend "Bn R" to read "2 Bns" 45°00'39.4"N 061°57'12.6"W

LNM/D. 24-NOV-2000

*(G2004063) DFO(6301439-01)*

**24-NOV-2000**

LNM/D. 19-MAR-1999



### Chart no. 4234

Add gas pipeline joining 45°09'24.0"N 061°37'41.0"W  
45°08'47.7"N 061°38'24.1"W  
45°08'33.5"N 061°38'31.7"W  
45°08'09.2"N 061°38'35.3"W  
45°07'42.3"N 061°38'23.2"W  
45°07'24.8"N 061°38'02.2"W  
45°05'42.3"N 061°35'00.4"W  
45°04'09.8"N 061°33'42.0"W  
and 45°02'52.5"N 061°32'13.5"W

*(H2000-003) DFO(6828773-01)*

**24-NOV-2000** LNM/D. 19-MAR-1999  
Add legend "Gas/Gaz" 45°07'06.0"N 061°37'24.0"W

*(H2000-003) DFO(6828773-02)*

**24-NOV-2000** LNM/D. 19-MAR-1999  
Add legend "See/Voir note GAS PIPELINES/GAZODUCS" 45°07'57.5"N 061°37'36.0"W

*(H2000-003) DFO(6828773-03)*

**24-NOV-2000** LNM/D. 19-MAR-1999  
Add note "GAS PIPELINES Gas pipelines and wells contain natural gas under pressure and damage to these installations could create an immediate fire hazard. Mariners are cautioned not to anchor or trawl near pipelines or wellheads. GAZODUCS Les gazoducs et les puits à gaz contiennent du gaz sous pression et du dommage à ces installations pourraient créer un danger de feu immédiat. Les navires ne devraient ni mouiller ni chaluter près de pipelines ou de têtes de puits." 45°05'55.0"N 061°54'18.0"W  
*(H2000-003) DFO(6828773-04)*

### 4234 - Port Bickerton - New Chart - 10-APR-1987 - NAD 1983

**11-MAR-2022** LNM/D. 24-DEC-2021  
Affix patch 45°06'19.0"N 061°43'21.0"W  
[PDF](#)  
This notice affects Electronic Navigational Chart: CA376109, *DFO(6309979-01)*  
CA576110

**27-MAY-2011** LNM/D. 14-JAN-2011



### Chart no. 4234

Delete depth of 2 metres, 1 decimetre 45°06'18.1"N 061°43'22.9"W  
(See Chart No. 1, I10)

*DFO(6305441-01)*

**27-MAY-2011**

LNМ/D. 14-JAN-2011

Add depth of 1 metre, 8 decimetres 45°06'19.0"N 061°43'24.0"W  
(See Chart No. 1, I10)

*DFO(6305441-02)*

**27-MAY-2011**

LNМ/D. 14-JAN-2011

Add depth of 2 metres 45°06'14.4"N 061°43'21.9"W  
(See Chart No. 1, I10)

*DFO(6305441-03)*

**27-MAY-2011**

LNМ/D. 14-JAN-2011

Add depth of 0 metres, 9 decimetres 45°06'13.3"N 061°43'25.0"W  
(See Chart No. 1, I10)

*DFO(6305441-04)*

**27-MAY-2011**

LNМ/D. 14-JAN-2011

Add depth of 1 metre, 9 decimetres 45°06'17.1"N 061°43'22.5"W  
(See Chart No. 1, I10)

*DFO(6305441-05)*

**27-MAY-2011**

LNМ/D. 14-JAN-2011

Add depth of 3 metres, 3 decimetres 45°05'58.3"N 061°43'06.2"W  
(See Chart No. 1, I10)

*DFO(6305441-06)*

**27-MAY-2011**

LNМ/D. 14-JAN-2011

Delete depth of 2 metres, 9 decimetres 45°05'39.3"N 061°43'29.6"W  
(See Chart No. 1, I10)

*DFO(6305442-01)*

**27-MAY-2011**

LNМ/D. 14-JAN-2011

Delete depth of 2 metres, 7 decimetres 45°05'33.4"N 061°42'58.6"W  
(See Chart No. 1, I10)

*DFO(6305442-02)*



### Chart no. 4234

**27-MAY-2011** LNM/D. 14-JAN-2011

Add depth of 0 metres, 2 decimetres 45°05'44.2"N 061°43'40.1"W  
(See Chart No. 1, I10)

*DFO(6305442-03)*

**27-MAY-2011** LNM/D. 14-JAN-2011

Add depth of 1 metre, 6 decimetres 45°05'39.0"N 061°43'31.2"W  
(See Chart No. 1, I10)

*DFO(6305442-04)*

**27-MAY-2011** LNM/D. 14-JAN-2011

Add depth of 2 metres, 3 decimetres 45°05'37.5"N 061°43'25.9"W  
(See Chart No. 1, I10)

*DFO(6305442-05)*

**27-MAY-2011** LNM/D. 14-JAN-2011

Add awash 0 metres 45°05'39.8"N 061°43'23.3"W  
(See Chart No. 1, Kb)

*DFO(6305442-06)*

**27-MAY-2011** LNM/D. 14-JAN-2011

Add depth of 1 metre, 8 decimetres 45°05'35.8"N 061°43'13.2"W  
(See Chart No. 1, I10)

*DFO(6305442-07)*

**27-MAY-2011** LNM/D. 14-JAN-2011

Add depth of 2 metres 45°05'33.1"N 061°42'58.8"W  
(See Chart No. 1, I10)

*DFO(6305442-08)*

**27-MAY-2011** LNM/D. 14-JAN-2011

Add depth of 1 metre, 9 decimetres 45°05'35.2"N 061°42'57.0"W  
(See Chart No. 1, I10)

*DFO(6305442-09)*

**27-MAY-2011** LNM/D. 14-JAN-2011



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4234

Add depth of 1 metre, 2 decimetres 45°05'32.6"N 061°42'52.3"W  
(See Chart No. 1, I10)

*DFO(6305442-10)*

**23-APR-2010**

LNМ/D. 01-JAN-2010

Amend Iso 8s 20m 12M to read Fl 3s 21m 17M against light  
(See Chart 1 P16)

45°05'24.0"N 061°42'01.7"W

*(G2010012) LL(629) DFO(6304754-01)*

This notice affects Electronic Navigational Chart:  
CA176140, CA376109

**01-JAN-2010**

LNМ/D. 31-JUL-2009

Amend FLR to read Iso R against light  
(See Chart No 1 P16)

45°05'40.8"N 061°43'28.5"W

*(G2009150) LL(629.8) DFO(6304655-01)*

**01-JAN-2010**

LNМ/D. 31-JUL-2009

Amend FG 4m to read FlG against light  
(See Chart No 1 P16)

45°05'41.8"N 061°43'35.1"W

*(G2009151) LL(629.9) DFO(6304657-01)*

**01-JAN-2010**

LNМ/D. 31-JUL-2009

Delete light FR 4m  
(See Chart No 1 P1)

45°06'19.1"N 061°43'22.7"W

*(G2009153) LL(631) DFO(6304658-01)*

**01-JAN-2010**

LNМ/D. 31-JUL-2009

Add light Iso R 4s  
(See Chart No 1 P1)

45°06'18.8"N 061°43'21.9"W

*(G2009154) LL(631.2) DFO(6304659-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**01-JAN-2010**

LNМ/D. 31-JUL-2009





Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4234

Add rescue station  
(See Chart No 1 T12)

45°06'25.0"N 061°43'23.0"W

*DFO(6304664-01)*

This notice affects Electronic Navigational Chart: CA576110

#### 01-JAN-2010

Delete radio tower, Ro Tr, with elevation of 31m, RLts  
(See Chart No 1 E28)

LNМ/D. 31-JUL-2009

45°06'19.2"N 061°43'23.1"W

*DFO(6304665-01)*

This notice affects Electronic Navigational Chart: CA576110

#### 01-JAN-2010

Add radio tower, Ro Tr, with elevation of 30m, RLts 45°06'23.5"N 061°43'18.9"W  
(See Chart No 1 E28)

LNМ/D. 31-JUL-2009

*DFO(6304665-02)*

#### 01-JAN-2010

Replace wharf with submerged ruins with legend Ru joining  
(See Chart No 1 F33.1)

LNМ/D. 31-JUL-2009

45°05'37.8"N 061°43'37.0"W  
45°05'36.8"N 061°43'36.6"W  
and 45°05'36.7"N 061°43'37.1"W

*DFO(6304666-01)*

#### 01-JAN-2010

Delete legend Public 45°05'36.5"N 061°43'39.8"W

LNМ/D. 31-JUL-2009

*DFO(6304666-02)*

#### 01-JAN-2010

Delete legend Ru 45°05'39.6"N 061°43'37.9"W

LNМ/D. 31-JUL-2009

*DFO(6304666-03)*

#### 28-NOV-2008

Add green port hand spar buoy, marked V7  
(See Chart No 1 Qg)

LNМ/D. 07-NOV-2008

*(G2008072) DFO(6304144-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4234

**07-NOV-2008**

Delete red starboard hand lighted pillar buoy FIR, marked  
VC10  
(See Chart No 1 Qf)

LNM/D. 26-SEP-2008

45°05'33.5"N 061°43'10.5"W

*(G2008054) LL(626) DFO(6304071-01)*

**07-NOV-2008**

Delete red starboard hand spar buoy, marked VC16  
(See Chart No 1 Qf)

LNM/D. 26-SEP-2008

45°05'44.0"N 061°43'41.0"W

*(G2008055) DFO(6304072-01)*

**07-NOV-2008**

Delete red starboard hand lighted pillar buoy FIR, marked  
VD2  
(See Chart No 1 Qf)

LNM/D. 26-SEP-2008

45°05'43.0"N 061°42'57.0"W

*(G2008056) LL(626.5) DFO(6304073-01)*

**26-SEP-2008**

Delete rear range/leading light FG 7m with leading line  
and bearing legend 118° 298°  
(See Chart No 1Pe )

LNM/D. 28-DEC-2007

45°05'47.0"N 061°43'50.0"W

*(G2008012) LL(630.1) DFO(6303889-01)*

**26-SEP-2008**

Add green port hand lighted spar buoy FlG, marked V1  
(See Chart No 1 Qg)

LNM/D. 28-DEC-2007

45°05'02.0"N 061°42'04.0"W

*(G2008013) LL(626.9) DFO(6303890-01)*

This notice affects Electronic Navigational Chart:  
CA376109

**26-SEP-2008**

Add green, red and green port bifurcation lighted spar  
buoy Fl(2+1)6s G, marked VCC  
(See Chart No 1 Qj)

LNM/D. 28-DEC-2007

45°05'36.2"N 061°42'33.0"W

*(G2008014) LL(627.1) DFO(6303891-01)*

**26-SEP-2008**

LNM/D. 28-DEC-2007



### Chart no. 4234

- Add green port hand lighted spar buoy FlG, marked V3  
(See Chart No 1 Qg) 45°05'42.7"N 061°42'38.3"W  
*(G2008015) LL(627.5) DFO(6303892-01)*
- 26-SEP-2008** LNM/D. 28-DEC-2007  
Add red starboard hand lighted spar buoy FIR, marked V4  
(See Chart No 1 Qf) 45°05'55.9"N 061°43'03.9"W  
*(G2008016) LL(628.1) DFO(6303893-01)*
- 26-SEP-2008** LNM/D. 28-DEC-2007  
Add red starboard hand lighted spar buoy QR, marked V6  
(See Chart No 1 Qf) 45°06'12.2"N 061°43'22.1"W  
*(G2008017) LL(628.5) DFO(6303894-01)*
- 26-SEP-2008** LNM/D. 28-DEC-2007  
Add green port hand lighted spar buoy QG, marked VC1  
(See Chart No 1 Qg) 45°05'34.3"N 061°42'53.7"W  
*(G2008018) LL(626.1) DFO(6303895-01)*
- 26-SEP-2008** LNM/D. 28-DEC-2007  
Add red starboard hand lighted spar buoy FIR, marked  
VC2 45°05'34.5"N 061°42'56.0"W  
(See Chart No 1 Qf) *(G2008019) LL(626.2) DFO(6303896-01)*
- 26-SEP-2008** LNM/D. 28-DEC-2007  
Add green port hand lighted spar buoy FlG, marked VC3  
(See Chart No 1 Qg) 45°05'33.6"N 061°43'00.4"W  
*(G2008020) LL(626.3) DFO(6303897-01)*
- 26-SEP-2008** LNM/D. 28-DEC-2007  
Add red starboard hand lighted spar buoy QR, marked  
VC4 45°05'34.7"N 061°43'14.2"W  
(See Chart No 1 Qf) *(G2008021) LL(626.4) DFO(6303898-01)*
- 26-SEP-2008** LNM/D. 28-DEC-2007



### Chart no. 4234

Add green port hand lighted spar buoy FlG, marked VC5 45°05'34.4"N 061°43'15.8"W  
(See Chart No 1 Qg)  
(G2008022) LL(626.6) DFO(6303899-01)

**26-SEP-2008** LNM/D. 28-DEC-2007  
Add green port hand lighted spar buoy FlG, marked VC7 45°05'37.9"N 061°43'26.0"W  
(See Chart No 1 Qg)  
(G2008023) LL(626.7) DFO(6303900-01)

**26-SEP-2008** LNM/D. 28-DEC-2007  
Amend VC14 to read VC8 against red starboard hand spar buoy 45°05'43.5"N 061°43'35.5"W  
(G2008024) DFO(6303901-01)

**26-SEP-2008** LNM/D. 28-DEC-2007  
Delete green port hand lighted pillar buoy FlG, marked VC3 45°05'34.0"N 061°42'41.4"W  
(See Chart No 1 Qg)  
(G2008029) LL(627) DFO(6303906-01)

**26-SEP-2008** LNM/D. 28-DEC-2007  
Delete green port hand spar buoy, marked VC1 45°05'02.0"N 061°42'03.5"W  
(See Chart No 1 Qg)  
(G2008030) DFO(6303907-01)

This notice affects Electronic Navigational Chart: CA376109

**26-SEP-2008** LNM/D. 28-DEC-2007  
Delete rear range/leading light FR 12m with leading line 45°06'27.6"N 061°43'32.5"W  
and bearing legend 140½° 320½°  
(See Chart No 1Pe)  
(G2008045) LL(631.1) DFO(6303982-01)

This notice affects Electronic Navigational Chart:  
CA376109

**4234 - St Marys River - New Chart - 10-APR-1987 - NAD 1983**

**08-SEP-2023** LNM/D. 21-JUL-2023



### Chart no. 4234

Reposition green port hand spar buoy, marked VK5  
(See Chart 1, Qc)

This notice affects Electronic Navigational Chart:  
CA376109

from 45°02'43.9"N 061°53'26.8"W  
to 45°02'45.0"N 061°53'23.4"W

*(F2023011) DFO(6310718-01)*

#### 08-SEP-2023

Reposition green port hand can buoy, marked VK55  
(See Chart 1, Qc)

This notice affects Electronic Navigational Chart:  
CA376109

LNМ/D. 21-JUL-2023

from 45°06'53.0"N 061°58'11.4"W  
to 45°06'52.8"N 061°58'07.8"W

*(F2023012) DFO(6310719-01)*

#### 08-SEP-2023

Reposition green port hand can buoy, marked VK57  
(See Chart 1, Qc)

This notice affects Electronic Navigational Chart:  
CA376109

LNМ/D. 21-JUL-2023

from 45°07'01.0"N 061°58'16.2"W  
to 45°06'58.8"N 061°58'10.2"W

*(F2023014) DFO(6310721-01)*

#### 08-SEP-2023

Reposition red starboard hand conical buoy, marked VK66  
(See Chart 1, Qb)

This notice affects Electronic Navigational Chart:  
CA376109

LNМ/D. 21-JUL-2023

from 45°07'32.4"N 061°58'43.9"W  
to 45°07'31.2"N 061°58'45.0"W

*(F2023015) DFO(6310722-01)*

#### 29-JUN-2012

Reposition red starboard hand conical buoy, marked VK24  
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:  
CA476112

LNМ/D. 11-MAY-2012

from 45°04'00.4"N 061°54'46.2"W  
to 45°04'08.3"N 061°54'51.9"W

*(F2012029) DFO(6306049-01)*

#### 29-JUN-2012

Reposition green port hand can buoy, marked VK25  
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:  
CA476112

LNМ/D. 11-MAY-2012

from 45°04'06.0"N 061°54'57.0"W  
to 45°04'10.1"N 061°55'00.2"W

*(F2012030) DFO(6306050-01)*

#### 29-JUN-2012

LNМ/D. 11-MAY-2012



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

**Chart no. 4234**

Reposition green port hand can buoy, marked VK27  
(See Chart No. 1, Qg)

from 45°04'10.0"N 061°55'09.0"W  
to 45°04'13.6"N 061°55'11.6"W

*(F2012031) DFO(6306051-01)*

This notice affects Electronic Navigational Chart:  
CA476112