



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4237

#### 4237 - Sambro Harbour - New Edition - 02-JUN-2000 - NAD 1983

**14-MAR-2008**

LNМ/D. 27-JUL-2007

Add red starboard hand lighted conical buoy QR, marked  
HR2  
(See Chart No 1 Qf)

44°28'41.3"N 063°35'22.1"W

(F2007140) LL(505.1) DFO(6303786-01)

This notice affects Electronic Navigational Chart:  
CA476009, CA576010

**14-MAR-2008**

LNМ/D. 27-JUL-2007

Add red starboard hand lighted conical buoy FlR, marked  
HR4  
(See Chart No 1 Qf)

44°28'47.8"N 063°35'13.4"W

(F2007141) LL(505.2) DFO(6303787-01)

This notice affects Electronic Navigational Chart:  
CA476009

**14-MAR-2008**

LNМ/D. 27-JUL-2007

Add green port hand lighted can buoy FlG, marked HR5  
(See Chart No 1 Qg)

44°28'51.2"N 063°35'10.7"W

(F2007142) LL(505.3) DFO(6303788-01)

This notice affects Electronic Navigational Chart:  
CA476009, CA576010

**16-MAY-2008**

LNМ/D. 14-MAR-2008

Delete red starboard hand lighted pillar buoy FlR, marked  
HS12  
(See Chart 1 No Qf)

44°28'18.7"N 063°35'33.7"W

(F2008007) LL(504.5) DFO(6303838-01)

This notice affects Electronic Navigational Chart:  
CA476009, CA576010

**16-MAY-2008**

LNМ/D. 14-MAR-2008



**Chart no. 4237**

Add red starboard hand lighted spar buoy F1R, marked  
HS12  
(See Chart 1 No Qf)

44°28'21.4"N 063°35'35.3"W

(F2008007) LL(504.5) DFO(6303838-02)

This notice affects Electronic Navigational Chart:  
CA576010

**07-NOV-2008**

LNМ/D. 26-SEP-2008

Add light F1R against red starboard hand spar buoy,  
marked HA2  
(See Chart No 1 Q7)

44°27'22.0"N 063°35'09.0"W

(F2008120) LL(504.01) DFO(6304049-01)

**07-NOV-2008**

LNМ/D. 26-SEP-2008

Add light Fl(2+1) R against red, green and red starboard  
bifurcation spar buoy, marked HSA  
(See Chart No 1 Q7)

44°27'32.0"N 063°35'46.5"W

(F2008122) LL(504.02) DFO(6304051-01)

**10-JUN-2011**

LNМ/D. 18-FEB-2011

Delete red starboard hand spar buoy, marked HS24  
(See Chart No. 1, Qf)

44°28'43.7"N 063°35'52.3"W  
(F2011129) DFO(6305475-01)

**10-JUN-2011**

LNМ/D. 18-FEB-2011

Add red starboard hand lighted spar buoy F1R, marked  
HS24  
(See Chart No. 1, Qf)

44°28'43.1"N 063°35'53.0"W

(F2011133) LL(505.83) DFO(6305475-02)

**10-JUN-2011**

LNМ/D. 18-FEB-2011

Add light F1R against red starboard hand spar buoy,  
marked HS20  
(See Chart No. 1, Q7)

44°28'38.0"N 063°35'45.5"W

(F2011135) LL(505.81) DFO(6305478-01)

**10-JUN-2011**

LNМ/D. 18-FEB-2011



**Chart no. 4237**

Add light FiR against red starboard hand spar buoy,  
marked HS22

44°28'41.0"N 063°35'49.0"W

(See Chart No. 1, Q7)

(F2011137) LL(505.82) DFO(6305480-01)

**15-JUL-2011**

LNМ/D. 08-JUL-2011

Delete depth of 4 metres, 6 decimetres 44°28'42.0"N 063°35'52.7"W  
(See Chart No. 1, I10)

DFO(6305547-01)

**15-JUL-2011**

LNМ/D. 08-JUL-2011

Add rock with known depth of 1 metre, 6 decimetres, dangerous to  
surface navigation

44°28'42.9"N 063°35'52.7"W

(See Chart No. 1, K14/K14.2)

DFO(6305547-02)

**08-NOV-2013**

LNМ/D. 28-JUN-2013

Reposition red starboard hand spar buoy, marked HE12  
(See Chart No. 1, Qf)

from 44°27'02.5"N 063°34'15.0"W  
to 44°27'04.8"N 063°34'12.5"W

This notice affects Electronic Navigational Chart:  
CA476009

(F2013028) DFO(6306500-04)

**26-JUN-2015**

LNМ/D. 19-JUN-2015

Add light FlR against red starboard hand spar buoy,  
marked HE10

44°26'51.2"N 063°34'50.6"W

(See Chart No. 1, Q7)

(F2015017) LL(503.05) DFO(6307148-01)

This notice affects Electronic Navigational Chart:  
CA476009, CA576010

**05-AUG-2016**

LNМ/D. 04-DEC-2015

Affix patch

44°28'00.0"N 063°36'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576010

DFO(6307651-01)

**4237 - Approaches to / Approches de Halifax Harbour - New Edition - 02-JUN-2000 - NAD 1983**

**26-JUL-2002**

LNМ/D. 25-JAN-2002



**Chart no. 4237**

Amend HE2 to read HS2 against red, starboard hand spar buoy 44°26'20.0"N 063°34'34.5"W

*DFO(6300196-01)*

**23-AUG-2002**

LNM/D. 26-JUL-2002

Add submarine cable joining 44°33'32.4"N 063°33'33.7"W  
44°33'05.3"N 063°32'49.3"W  
44°32'46.0"N 063°32'27.4"W  
44°32'29.3"N 063°32'14.4"W  
44°32'07.1"N 063°31'46.3"W  
44°31'54.4"N 063°31'23.5"W  
44°31'44.3"N 063°31'12.1"W  
44°31'32.7"N 063°31'04.1"W  
44°30'57.5"N 063°30'57.2"W  
44°30'34.6"N 063°30'49.2"W  
44°30'10.1"N 063°30'27.3"W  
44°29'42.9"N 063°30'13.1"W  
44°28'54.6"N 063°30'11.0"W  
44°27'41.9"N 063°30'22.6"W  
44°27'15.1"N 063°30'23.5"W  
44°27'02.6"N 063°30'26.3"W  
44°26'25.8"N 063°30'42.3"W  
44°26'00.0"N 063°30'57.0"W  
44°25'40.1"N 063°30'58.3"W  
44°25'29.7"N 063°30'52.1"W  
44°25'05.2"N 063°30'26.5"W  
44°23'00.2"N 063°26'34.3"W  
44°21'57.5"N 063°24'05.6"W  
44°21'49.4"N 063°23'51.9"W  
44°21'13.3"N 063°23'07.1"W  
44°20'33.6"N 063°22'07.3"W  
44°20'23.5"N 063°21'56.9"W  
44°19'12.5"N 063°21'09.0"W  
44°18'17.0"N 063°20'42.9"W  
44°17'47.7"N 063°20'12.6"W  
and 44°17'00.0"N 063°19'42.6"W

*DFO(6300453-01)*

**23-AUG-2002**

LNM/D. 26-JUL-2002



**Chart no. 4237**

Add submarine cable joining 44°29'30.5"N 063°33'01.1"W  
44°29'23.1"N 063°33'01.2"W  
44°29'03.0"N 063°32'53.4"W  
44°28'37.2"N 063°32'23.7"W  
44°28'29.4"N 063°31'52.1"W  
44°27'18.2"N 063°31'07.3"W  
44°26'38.8"N 063°30'59.8"W  
44°25'51.1"N 063°31'10.7"W  
44°25'38.5"N 063°31'09.4"W  
44°25'25.0"N 063°31'03.3"W  
44°24'47.1"N 063°30'19.8"W  
44°24'02.4"N 063°29'37.8"W  
44°23'47.9"N 063°29'30.9"W  
44°23'28.1"N 063°29'37.8"W  
44°23'14.3"N 063°29'46.8"W  
44°23'04.4"N 063°29'57.5"W  
44°22'37.7"N 063°30'43.0"W  
44°22'26.4"N 063°31'14.9"W  
44°22'23.5"N 063°31'58.2"W  
44°22'09.0"N 063°32'57.8"W  
44°22'00.3"N 063°33'07.5"W  
44°21'36.4"N 063°33'25.2"W  
44°21'13.7"N 063°33'32.9"W  
44°20'59.7"N 063°33'43.6"W  
44°20'46.4"N 063°34'01.7"W  
44°19'49.4"N 063°34'44.3"W  
44°18'57.6"N 063°34'56.1"W  
44°18'36.8"N 063°35'13.4"W  
44°18'16.0"N 063°35'42.3"W  
44°18'02.6"N 063°35'51.3"W  
44°17'21.7"N 063°36'51.5"W  
and 44°17'00.0"N 063°37'09.7"W

*DFO(6300453-02)*

**23-AUG-2002**

LNM/D. 26-JUL-2002



**Chart no. 4237**

Add submarine cable joining 44°29'03.6"N 063°32'54.6"W  
44°28'55.2"N 063°32'48.6"W  
44°28'36.1"N 063°32'30.0"W  
44°28'19.4"N 063°31'59.5"W  
44°26'53.0"N 063°31'12.6"W  
44°26'22.7"N 063°31'10.2"W  
44°26'09.4"N 063°31'15.0"W  
44°25'52.5"N 063°31'44.0"W  
44°25'45.2"N 063°31'50.9"W  
44°24'52.9"N 063°32'10.2"W  
44°24'23.3"N 063°32'48.1"W  
44°24'04.5"N 063°32'55.5"W  
44°23'11.0"N 063°32'48.6"W  
44°22'56.6"N 063°32'55.5"W  
44°22'33.5"N 063°33'29.0"W  
44°22'23.8"N 063°33'36.6"W  
44°22'02.0"N 063°34'19.3"W  
44°21'11.5"N 063°35'23.9"W  
44°20'53.4"N 063°36'05.9"W  
44°20'00.4"N 063°37'16.3"W  
and 44°18'37.5"N 063°39'14.7"W

*DFO(6300453-03)*

**02-MAY-2003**

LN/D. 23-AUG-2002

Add restricted zone between 44°30'11.4"N 063°31'11.4"W  
and 44°35'33.0"N 063°26'36.6"W

*DFO(6300860-01)*

**02-MAY-2003**

LN/D. 23-AUG-2002

Add legend Contolled Access Zone/Zone d'accès contrôlé 44°33'28.0"N 063°29'22.0"W

*DFO(6300860-02)*

**02-MAY-2003**

LN/D. 23-AUG-2002

Add note CONTROLLED ACCESS ZONE

44°39'40.0"N 063°31'05.0"W

For addition information, consult Notice to Mariners No. 43 of  
each year.

*DFO(6300860-03)*

ZONES D'ACCÈS CONTRÔLÉ

Pour plus de renseignement, consulter l'Avis aux navigateurs n°. 43 de chaque année.



**Chart no. 4237**

**19-MAR-2004**

LNM/D. 02-MAY-2003

Amend "F" to read "FlR" against light

44°34'09.3"N 063°33'25.0"W

*(F2003104) LL(522.1) DFO(6301203-01)*

**07-MAY-2004**

LNM/D. 19-MAR-2004

Amend "Fl 10s 16m 13M" to read "Fl 10s 16m 8M" against  
light

44°34'51.7"N 063°27'28.1"W

*(F2004016) LL(545) DFO(6301329-01)*

**07-MAY-2004**

LNM/D. 19-MAR-2004

Amend "Fl Y 30s 17m 13M" to read "Fl 30s 17m 11M"  
against light

44°36'08.2"N 063°32'00.9"W

*(F2004018) LL(527) DFO(6301331-01)*

**28-MAY-2004**

LNM/D. 07-MAY-2004

Delete radar transponder beacon Racon against red and  
white fairway pillar light buoy Mo (A), WHIS, marked  
HA

44°21'45.0"N 063°24'15.0"W

*(F2004054) LL(510) DFO(6301423-01)*

**08-OCT-2004**

LNM/D. 28-MAY-2004

Delete legend "WHIS" against red starboard pillar light buoy  
Fl R, WHIS, marked H4

44°31'39.5"N 063°30'03.6"W

*(F2004116) LL(516) DFO(6301905-01)*

**05-NOV-2004**

LNM/D. 08-OCT-2004

Delete legend "BELL" against green port hand pillar light  
buoy FlG, marked HD5, BELL

44°29'00.0"N 063°31'03.0"W

*(F2004127) LL(512) DFO(6301958-01)*

**06-APR-2007**

LNM/D. 05-NOV-2004

Delete legend "WHIS" against green port hand lighted pillar  
whistle buoy FlG, marked HE19

44°28'19.6"N 063°32'16.0"W

*(F2007028) LL(511) DFO(6303378-01)*

**27-JUL-2007**

LNM/D. 06-APR-2007



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

**Chart no. 4237**

Affix patch 44°38'00.0"N 063°31'33.0"W

*DFO(6303582-01)*

[PDF](#)

**26-SEP-2008**

LNМ/D. 16-MAY-2008





### Chart no. 4237

(T)Add The positions of the subsurface moorings for the OTN between 44°28'42.0"N 063°32'00.0"W  
project are: and 44°19'40.3"N 063°21'53.3"W

OTN1 44° 28' 42.00" N 63° 32' 00.00" W  
OTN2 44° 28' 21.17" N 63° 31' 36.67" W  
OTN3 44° 28' 00.33" N 63° 31' 13.33" W  
OTN4 44° 27' 39.50" N 63° 30' 50.00" W  
OTN5 44° 27' 18.67" N 63° 30' 26.67" W  
OTN6 44° 26' 57.83" N 63° 30' 03.33" W  
OTN7 44° 26' 37.00" N 63° 29' 40.00" W  
OTN8 44° 26' 16.17" N 63° 29' 16.67" W  
OTN9 44° 25' 55.33" N 63° 28' 53.33" W  
OTN10 44° 25' 34.50" N 63° 28' 30.00" W  
OTN11 44° 25' 13.67" N 63° 28' 06.67" W  
OTN12 44° 24' 52.83" N 63° 27' 43.33" W  
OTN13 44° 24' 32.00" N 63° 27' 20.00" W  
OTN14 44° 24' 11.17" N 63° 26' 56.67" W  
OTN15 44° 23' 50.33" N 63° 26' 33.33" W  
OTN16 44° 23' 29.50" N 63° 26' 10.00" W  
OTN17 44° 23' 08.67" N 63° 25' 46.67" W  
OTN18 44° 22' 47.83" N 63° 25' 23.33" W  
OTN19 44° 22' 27.00" N 63° 25' 00.00" W  
OTN20 44° 22' 06.17" N 63° 24' 36.67" W  
OTN21 44° 21' 45.33" N 63° 24' 13.33" W  
OTN22 44° 21' 24.50" N 63° 23' 50.00" W  
OTN23 44° 21' 03.67" N 63° 23' 26.67" W  
OTN24 44° 20' 42.83" N 63° 23' 03.33" W  
OTN25 44° 20' 22.00" N 63° 22' 40.00" W  
OTN26 44° 20' 01.17" N 63° 22' 16.67" W  
OTN27 44° 19' 40.33" N 63° 21' 53.33" W  
OTN28 44° 19' 19.50" N 63° 21' 30.00" W  
OTN29 44° 18' 58.67" N 63° 21' 06.67" W  
OTN30 44° 18' 37.83" N 63° 20' 43.33" W  
OTN31 44° 18' 17.00" N 63° 20' 20.00" W  
OTN32 44° 17' 56.17" N 63° 19' 56.67" W  
OTN33 44° 17' 35.33" N 63° 19' 33.33" W  
OTN34 44° 17' 14.50" N 63° 19' 10.00" W  
OTN35 44° 16' 53.67" N 63° 18' 46.67" W  
OTN36 44° 16' 32.83" N 63° 18' 23.33" W  
OTN37 44° 16' 12.00" N 63° 18' 00.00" W

*DFO(6303910-01)*

Proposed date of removal is April 2013.  
Moorings permanently established. Notice  
2008-09-26(T), is cancelled. See reference  
DFO(6304781) appearing in this edition.  
Cancelled on

**26-SEP-2008**

LN/D. 16-MAY-2008



**Chart no. 4237**

Amend Fl 5s 43m 24M to read Fl 6s 43m 23M against light  
(See Chart No 1 P16)

44°26'12.0"N 063°33'48.0"W

*(F2008068) LL(507) DFO(6303952-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**07-NOV-2008**

LNМ/D. 26-SEP-2008

Add light FLR against red starboard hand spar buoy,  
marked HE16  
(See Chart No 1 Q7)

44°27'33.0"N 063°32'42.0"W

*(F2008115) LL(503.1) DFO(6304045-01)*

**07-NOV-2008**

LNМ/D. 26-SEP-2008

Add light FLG against green port hand spar buoy, marked  
HE17  
(See Chart No 1 Q7)

44°28'02.0"N 063°32'47.0"W

*(F2008117) LL(503.11) DFO(6304047-01)*

**20-FEB-2009**

LNМ/D. 07-NOV-2008

Add green port hand lighted can buoy FLG, marked AA55  
(See Chart No 1 Qg)

44°27'48.3"N 063°38'28.2"W

*(F2008158) LL(501.2) DFO(6304230-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**20-FEB-2009**

LNМ/D. 07-NOV-2008

Add green port hand lighted can buoy FLG, marked AA57  
(See Chart No 1 Qg)

44°28'01.9"N 063°38'15.1"W

*(F2008157) LL(501.1) DFO(6304231-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**20-FEB-2009**

LNМ/D. 07-NOV-2008



### Chart no. 4237

Add green, red and green port bifurcation lighted spar  
buoy Fl (2+1)G 6s, marked AAA  
(See Chart No 1 Qj)

44°27'09.9"N 063°38'55.9"W

*(F2008161) LL(501.4) DFO(6304232-01)*

This notice affects Electronic Navigational Chart:  
CA476009

#### 20-FEB-2009

LNМ/D. 07-NOV-2008

Add red starboard hand lighted conical buoy FlR, marked  
AA54  
(See Chart No 1 Qf)

44°27'38.0"N 063°38'30.8"W

*(F2008163) LL(501.3) DFO(6304234-01)*

This notice affects Electronic Navigational Chart:  
CA476009

#### 22-MAY-2009

LNМ/D. 20-FEB-2009

Add green port hand spar buoy, marked HF1  
(See Chart No 1 Qg)

44°28'58.7"N 063°32'53.8"W

*DFO(6304350-01)*

This notice affects Electronic Navigational Chart: CA476009

#### 14-AUG-2009

LNМ/D. 22-MAY-2009

Delete depth of 13 metres, 4 decimetres  
(See Chart No. 1, I10)

44°39'24.4"N 063°34'14.0"W

*DFO(6304488-05)*

This notice affects Electronic Navigational Chart: CA476009,  
CA576003

#### 14-AUG-2009

LNМ/D. 22-MAY-2009

Add depth of 16 metres.  
(See Chart No. 1, I10)

44°39'23.9"N 063°34'15.7"W

*DFO(6304488-06)*

This notice affects Electronic Navigational Chart: CA476009,  
CA576003

#### 15-JAN-2010

LNМ/D. 14-AUG-2009



**Chart no. 4237**

Add depth of 96 metres, over artificial feature  
(See Chart No 1 Ka)

44°21'07.8"N 063°18'17.7"W

*DFO(6304670-01)*

This notice affects Electronic Navigational Chart: CA476009

**15-JAN-2010**

LNM/D. 14-AUG-2009

Reposition red starboard hand lighted pillar bell buoy BELL,  
FlR, marked HP2  
(See Chart No 1 Qf)

from 44°35'11.0"N 063°28'36.0"W  
to 44°35'11.2"N 063°28'47.3"W

*(F2009072) LL(544) DFO(6304677-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**12-MAR-2010**

LNM/D. 15-JAN-2010

Delete green port hand lighted pillar buoy QG, marked  
HG1  
(See Chart 1 Qg)

44°35'11.5"N 063°27'37.0"W

*(F2010001) LL(544.5) DFO(6304743-01)*

**12-MAR-2010**

LNM/D. 15-JAN-2010

Amend HP2 to read HP2/2 against buoy  
(See Chart No 1 Qf)

44°35'11.2"N 063°28'47.3"W

*(F2010002) LL(544) DFO(6304744-01)*

**12-MAR-2010**

LNM/D. 15-JAN-2010

Add red starboard hand lighted pillar bell buoy QR,  
marked HP2  
(See Chart 1 Qf)

44°34'29.6"N 063°27'47.2"W

*(F2010003T) LL(544.02) DFO(6304745-01)*

**08-FEB-2013**

LNM/D. 13-JAN-2012

Add maritime limit in general implying: permanent physical  
obstructions  
(see Chart 1, N1.1)

between 44°28'42.0"N 063°32'00.0"W  
and 44°17'00.0"N 063°18'53.8"W

This notice affects Electronic Navigational Chart:  
CA276801, CA376032, CA476009

*DFO(6304781-01)*

**08-FEB-2013**

LNM/D. 13-JAN-2012



**Chart no. 4237**

Add See/Voir note 44°17'34.0"N 063°18'33.0"W  
SCIENTIFIC MOORINGS  
MOUILLAGES SCIENTIFIQUES *DFO(6304781-02)*

**08-FEB-2013**

Add note:

SCIENTIFIC MOORINGS

Acoustic sensors, one metre high and positioned approximately 800 metres apart, along the line, directly on the seabed. Mariners are advised to avoid anchoring or conducting seabed operations in the vicinity of submarine moorings.

MOUILLAGES SCIENTIFIQUES

Des capteurs acoustiques, d'une hauteur d'un mètre et positionnés à intervalles d'environ 800 mètres le long de la ligne, reposent directement sur le fond marin. Nous avisons les navigateurs d'éviter de mouiller ou d'effectuer des travaux sur le fond marin à proximité de ces mouillages sous-marins.

LNM/D. 13-JAN-2012  
to the North margin of chart

*DFO(6304781-03)*

**04-JUN-2010**

Amend Fl 20s 49m 16M to read Fl 20s 48m 10M against light  
(See Chart 1 P16)

LNM/D. 12-MAR-2010  
44°30'26.6"N 063°31'21.8"W

*LL(513) DFO(6304817-01)*

This notice affects Electronic Navigational Chart: CA176140

**18-FEB-2011**

Delete depth of 96 metres, over artificial feature  
(See Chart No 1 Ka)

LNM/D. 04-JUN-2010  
44°21'07.8"N 063°18'17.7"W

*DFO(6305214-01)*

This notice affects Electronic Navigational Chart: CA476009

**18-FEB-2011**

Add depth of 106 metres, over artificial feature  
(See Chart No 1 Ka)

LNM/D. 04-JUN-2010  
44°21'02.3"N 063°18'09.8"W

*DFO(6305214-02)*

This notice affects Electronic Navigational Chart: CA476009



**Chart no. 4237**

**08-JUL-2011**

LNМ/D. 10-JUN-2011

Delete depth of 14 metres, 8 decimetres 44°37'44.1"N 063°33'31.9"W  
(See Chart No 1 I10)

*DFO(6305552-03)*

**08-JUL-2011**

LNМ/D. 10-JUN-2011

Add depth of 16 metres, 2 decimetres 44°37'43.7"N 063°33'32.0"W  
(See Chart No 1 I10)

*DFO(6305552-11)*

**08-JUL-2011**

LNМ/D. 10-JUN-2011

Add depth of 16 metres 44°37'33.0"N 063°33'31.4"W  
(See Chart No 1 I10)

*DFO(6305552-15)*

**08-JUL-2011**

LNМ/D. 10-JUN-2011

Delete depth of 11 metres, 9 decimetres 44°37'32.0"N 063°33'32.0"W  
(See Chart No 1 I10)

*DFO(6305552-16)*

**12-AUG-2011**

LNМ/D. 15-JUL-2011

Delete depth of 106 metres over artificial feature  
(See Chart No. 1, Ka, Ib)

44°21'02.3"N 063°18'09.8"W

*DFO(6305660-01)*

This notice affects Electronic Navigational Chart: CA376032

**12-AUG-2011**

LNМ/D. 15-JUL-2011

Add obstruction with known depth of 122 metres with legend  
ODAS/SADO  
The mooring is temporary. The proposed date of removal is July  
2012.

44°20'51.3"N 063°18'20.8"W

*DFO(6305660-04)*

**09-SEP-2011**

LNМ/D. 12-AUG-2011



**Chart no. 4237**

Delete red starboard hand lighted pillar bell buoy QR,  
marked HP2  
(See Chart No. 1, Qf)

44°34'29.6"N 063°27'47.2"W

(F2011164) LL(544.02) DFO(6305693-01)

This notice affects Electronic Navigational Chart:  
CA476009

**11-NOV-2011**

LNМ/D. 09-SEP-2011

Delete red starboard hand spar buoy, marked HS2  
(See Chart No. 1, Qf)

44°26'20.0"N 063°34'34.5"W

(F2011173) DFO(6305793-01)

This notice affects Electronic Navigational Chart: CA476009

**11-NOV-2011**

LNМ/D. 09-SEP-2011

Add black, yellow and black East cardinal lighted spar  
buoy Q(3) 10s, marked HSE  
(See Chart No. 1, Q130.3)

44°26'44.0"N 063°35'42.4"W

(F2011179) LL(508.44) DFO(6305796-01)

**11-NOV-2011**

LNМ/D. 09-SEP-2011

Add red starboard hand lighted conical buoy QR, marked  
HS4/2  
(See Chart No. 1, Qf)

44°26'23.6"N 063°35'08.0"W

(F2011180) LL(508.42) DFO(6305797-01)

This notice affects Electronic Navigational Chart:  
CA476009

**11-NOV-2011**

LNМ/D. 09-SEP-2011

Add red starboard hand lighted conical buoy FLR, marked  
HS4  
(See Chart No. 1, Qf)

44°26'00.0"N 063°34'42.0"W

(F2011181) LL(508.4) DFO(6305798-01)

This notice affects Electronic Navigational Chart:  
CA476009

**11-NOV-2011**

LNМ/D. 09-SEP-2011



**Chart no. 4237**

Add red starboard hand lighted conical buoy FIR,  
marked HS2/2  
(See Chart No. 1, Qf)

44°25'38.5"N 063°34'16.3"W

*(F2011182) LL(508.22) DFO(6305799-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**11-NOV-2011**

LNМ/D. 09-SEP-2011

Add red starboard hand lighted conical buoy FIR, marked  
HS2  
(See Chart No. 1, Qf)

44°25'15.8"N 063°33'49.6"W

*(F2011183) LL(508.2) DFO(6305800-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**18-NOV-2011**

LNМ/D. 11-NOV-2011

Delete light Fl 10s 16m 8M  
(See Chart No. 1, P1)

44°34'51.7"N 063°27'28.1"W

*(F2011184) LL(545) DFO(6305805-01)*

This notice affects Electronic Navigational Chart:  
CA276801, CA476009

**18-NOV-2011**

LNМ/D. 11-NOV-2011

Add abandoned lighthouse with legend Lt Ho/Phare Aband

44°34'51.7"N 063°27'28.1"W

*(F2011184) DFO(6305805-02)*

This notice affects Electronic Navigational Chart: CA276801,  
CA476009

**18-NOV-2011**

LNМ/D. 11-NOV-2011

Add light LFIR  
(See Chart No. 1, P1)

44°34'49.5"N 063°27'35.3"W

*(F2011184) LL(545) DFO(6305805-03)*

This notice affects Electronic Navigational Chart:  
CA476009

**13-JAN-2012**

LNМ/D. 18-NOV-2011





### Chart no. 4237

Delete legend Fog Sig (3) 60s against light  
(See Chart No. 1, R1, R20)

44°26'12.0"N 063°33'48.0"W

*(F2011193) LL(507) DFO(6305873-01)*

This notice affects Electronic Navigational Chart:  
CA276801, CA476009

#### 05-APR-2013

LNM/D. 08-FEB-2013

Add depth of 17 metres, 1 decimetre  
(See Chart No. 1, I10)

44°37'07.3"N 063°30'44.0"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6306342-01)*

#### 07-JUN-2013

LNM/D. 05-APR-2013

Reposition red starboard hand lighted pillar bell buoy FIR,  
marked HE2  
(See Chart No. 1, Qf)

from 44°24'15.3"N 063°36'29.7"W  
to 44°24'16.4"N 063°36'59.4"W

This notice affects Electronic Navigational Chart: *(F2013003) LL(503) DFO(6306367-01)*  
CA476009

#### 21-JUN-2013

LNM/D. 07-JUN-2013

Reposition green port hand lighted pillar buoy FIG,  
marked HE3  
(See Chart No 1 Qg)

from 44°25'28.0"N 063°37'03.0"W  
to 44°25'25.0"N 063°36'41.6"W

This notice affects Electronic Navigational Chart: *(F2013004) LL(503.5) DFO(6306368-01)*  
CA476009

#### 28-JUN-2013

LNM/D. 21-JUN-2013

Add restricted area with legend Explos  
(See Chart No.1 N23.1b)

44°26'59.0"N 063°32'10.0"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6306402-01)*

#### 08-NOV-2013

LNM/D. 28-JUN-2013

Reposition red starboard hand spar buoy, marked HE4  
(See Chart No. 1, Qf)

from 44°25'01.5"N 063°36'10.5"W  
to 44°24'47.4"N 063°36'37.2"W

This notice affects Electronic Navigational Chart:  
CA476009

*(F2013022) DFO(6306500-01)*

#### 08-NOV-2013

LNM/D. 28-JUN-2013



### Chart no. 4237

Reposition green port hand spar buoy, marked HE5  
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:  
CA476009

from 44°25'48.0"N 063°36'35.0"W  
to 44°25'49.4"N 063°36'18.7"W

*(F2013029) DFO(6306500-02)*

#### 08-NOV-2013

Reposition red starboard hand spar buoy, marked HE8  
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:  
CA476009

LNM/D. 28-JUN-2013

from 44°25'47.0"N 063°35'50.1"W  
to 44°25'48.8"N 063°35'52.6"W

*(F2013023) DFO(6306500-03)*

#### 08-NOV-2013

Reposition red starboard hand spar buoy, marked HE12  
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:  
CA476009

LNM/D. 28-JUN-2013

from 44°27'02.5"N 063°34'15.0"W  
to 44°27'04.8"N 063°34'12.5"W

*(F2013028) DFO(6306500-04)*

#### 08-NOV-2013

Reposition red starboard hand spar buoy, marked HE14  
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:  
CA476009

LNM/D. 28-JUN-2013

from 44°27'16.0"N 063°33'34.0"W  
to 44°27'19.2"N 063°33'36.5"W

*(F2013027) DFO(6306500-05)*

#### 08-NOV-2013

Reposition green port hand spar buoy, marked HE15  
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:  
CA476009

LNM/D. 28-JUN-2013

from 44°27'37.2"N 063°33'33.0"W  
to 44°27'34.2"N 063°33'31.4"W

*(F2013026) DFO(6306500-06)*

#### 08-NOV-2013

Reposition red starboard hand lighted spar buoy FIR,  
marked HE16

(See Chart No. 1, Qf)  
This notice affects Electronic Navigational  
Chart: CA476009

LNM/D. 28-JUN-2013

from 44°27'33.0"N 063°32'41.6"W  
to 44°27'40.6"N 063°32'49.6"W

*(F2013025) LL(503.1) DFO(6306500-07)*

#### 08-NOV-2013

LNM/D. 28-JUN-2013



### Chart no. 4237

Reposition green port hand lighted spar buoy FlG,  
marked HE17  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: CA476009

from 44°28'02.0"N 063°32'46.6"W  
to 44°28'00.6"N 063°32'40.9"W

(F2013024) LL(503.11) DFO(6306500-08)

#### 15-NOV-2013

Delete red starboard hand spar buoy, marked HW2  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA376083,  
CA476009

LNm/D. 08-NOV-2013  
44°37'59.0"N 063°18'28.0"W  
(F2013030) DFO(6306520-01)

#### 15-NOV-2013

Delete red and white fairway can buoy, marked HW  
(See Chart No. 1, Qh)  
This notice affects Electronic Navigational Chart: CA376083,  
CA476009

LNm/D. 08-NOV-2013  
44°37'31.0"N 063°18'15.0"W  
(F2013031) DFO(6306520-02)

#### 27-DEC-2013

Add yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s.  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA476009,  
CA576002

LNm/D. 15-NOV-2013  
44°33'31.3"N 063°32'43.9"W  
LL(521.5) DFO(6306585-01)

#### 10-JAN-2014

Add fish haven  
(See Chart No. 1, K46.1)  
This notice affects Electronic Navigational Chart: CA476009,  
CA576002, CA576003

LNm/D. 27-DEC-2013  
44°37'23.0"N 063°33'45.7"W  
DFO(6306603-01)

#### 10-JAN-2014

Add fish haven  
(See Chart No. 1, K46.1)  
This notice affects Electronic Navigational Chart: CA476009,  
CA576002, CA576003

LNm/D. 27-DEC-2013  
44°37'19.5"N 063°32'36.3"W  
DFO(6306603-02)

#### 15-AUG-2014

LNm/D. 10-JAN-2014



### Chart no. 4237

- Delete pilot boarding station 44°31'24.0"N 063°30'21.7"W  
(See Chart No. 1, T1.1)  
This notice affects Electronic Navigational Chart: CA476009 DFO(6306785-01)
- 15-AUG-2014** LNM/D. 10-JAN-2014  
Add pilot boarding station 44°30'24.0"N 063°29'30.0"W  
(See Chart No. 1, T1.1)  
This notice affects Electronic Navigational Chart: CA476009 DFO(6306785-02)
- 10-APR-2015** LNM/D. 15-AUG-2014  
Add fish haven with depth of 5 metres over an artificial feature 44°39'16.0"N 063°33'17.0"W  
(See Chart No. 1, K46.2)  
DFO(6307084-01)  
This notice affects Electronic Navigational Chart: CA476009,  
CA576003
- 22-MAY-2015** LNM/D. 10-APR-2015  
Add red starboard hand lighted spar buoy F1R, marked HE6 44°25'17.1"N 063°36'15.6"W  
(See Chart No. 1, Qf) (F2015012) LL(503.52) DFO(6307113-01)  
This notice affects Electronic Navigational Chart:  
CA476009
- 19-JUN-2015** LNM/D. 22-MAY-2015  
Delete green port hand spar buoy, marked HE7 44°26'10.5"N 063°36'03.0"W  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: CA476009 (F2015016) DFO(6307147-01)
- 19-JUN-2015** LNM/D. 22-MAY-2015  
Add green port hand lighted spar buoy F1G, marked HE7 44°26'14.5"N 063°35'52.8"W  
(See Chart No. 1, Q7)  
This notice affects Electronic Navigational Chart: (F2015016) LL(503.03) DFO(6307147-02)  
CA476009
- 26-JUN-2015** LNM/D. 19-JUN-2015  
Add light F1R against red starboard hand spar buoy, marked HE10 44°26'51.2"N 063°34'51.1"W  
(See Chart No. 1, Q7) (F2015017) LL(503.05) DFO(6307148-01)  
This notice affects Electronic Navigational Chart:  
CA476009, CA576010



## Chart no. 4237

### 04-DEC-2015

Add submarine cable  
(See Chart No. 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA476009

LNLM/D. 26-JUN-2015  
joining 44°29'36.7"N 063°16'37.7"W  
44°33'39.2"N 063°24'39.7"W  
44°33'53.2"N 063°25'29.2"W  
44°33'58.6"N 063°26'21.4"W  
44°33'40.0"N 063°31'38.8"W  
44°33'40.1"N 063°32'25.4"W  
44°33'28.4"N 063°33'19.0"W  
and 44°33'32.1"N 063°33'32.9"W

*DFO(6307258-01)*

### 05-AUG-2016

Affix patch  
[PDF](#)  
This notice affects Electronic Navigational Chart: CA476009

LNLM/D. 04-DEC-2015  
44°26'00.0"N 063°35'00.0"W

*DFO(6307651-02)*

### 05-AUG-2016

Replace depth of 11 metres, 3 decimetres with depth of 1 metre, 9  
decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNLM/D. 04-DEC-2015  
44°26'25.9"N 063°31'49.1"W

*DFO(6307651-04)*

### 16-DEC-2016

Delete light FG  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart:  
CA476009

LNLM/D. 05-AUG-2016  
44°28'15.5"N 063°38'03.5"W  
*(F2016052) LL(501) DFO(6307737-01)*

### 13-APR-2018

Replace depth of 7 metres with depth of 5 metres, 8 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNLM/D. 17-NOV-2017  
44°27'27.5"N 063°32'39.5"W  
*DFO(6307886-01)*

### 13-APR-2018

Replace depth of 12 metres, 8 decimetres with depth of 9 metres, 3  
decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNLM/D. 17-NOV-2017  
44°27'30.9"N 063°32'45.4"W  
*DFO(6307886-02)*



### Chart no. 4237

**13-APR-2018**

LNM/D. 17-NOV-2017

Delete depth of 7 metres, 3 decimetres  
(See Chart No. 1, I10)

44°27'25.2"N 063°32'54.0"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-03)*

**13-APR-2018**

LNM/D. 17-NOV-2017

Add depth of 4 metres, 8 decimetres  
(See Chart No. 1, I10)

44°27'23.1"N 063°32'55.7"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-04)*

**13-APR-2018**

LNM/D. 17-NOV-2017

Delete depth of 8 metres, 8 decimetres  
(See Chart No. 1, I10)

44°26'33.0"N 063°31'36.4"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-05)*

**13-APR-2018**

LNM/D. 17-NOV-2017

Replace depth of 5 metres, 8 decimetres with depth of 3 metres  
(See Chart No. 1, I10)

44°26'52.4"N 063°32'10.7"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-06)*

**13-APR-2018**

LNM/D. 17-NOV-2017

Replace depth of 7 metres, 6 decimetres with depth of 5 metres, 7  
decimetres  
(See Chart No. 1, I10)

44°26'43.2"N 063°32'26.2"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-07)*

**13-APR-2018**

LNM/D. 17-NOV-2017

Replace depth of 11 metres with depth of 8 metres, 6 decimetres  
(See Chart No. 1, I10)

44°26'43.5"N 063°32'16.9"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-08)*

**13-APR-2018**

LNM/D. 17-NOV-2017

Replace depth of 4 metres, with depth of 3 metres  
(See Chart No. 1, I10)

44°26'32.3"N 063°31'55.0"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-09)*

**13-APR-2018**

LNM/D. 17-NOV-2017



### Chart no. 4237

- Replace depth of 4 metres with depth of 1 metre, 5 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009
- 44°26'18.7"N 063°32'20.7"W  
*DFO(6307886-10)*
- 13-APR-2018**
- Replace depth of 4 metres, 9 decimetres with depth of 3 metres, 8  
decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009
- 44°26'12.6"N 063°32'38.9"W  
*DFO(6307886-11)*
- 13-APR-2018**
- Replace depth of 9 metres, 4 decimetres with depth of 6 metres, 6  
decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009
- 44°26'13.9"N 063°32'54.7"W  
*DFO(6307886-12)*
- 13-APR-2018**
- Replace depth of 10 metres, 1 decimetre with depth of 5 metres, 1  
decimetre  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009
- 44°25'59.7"N 063°32'42.6"W  
*DFO(6307886-13)*
- 13-APR-2018**
- Replace depth of 2 metres, 7 decimetres with depth of 1 metre, 9  
decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009
- 44°25'51.9"N 063°33'12.6"W  
*DFO(6307886-14)*
- 13-APR-2018**
- Replace depth of 6 metres, 7 decimetres with depth of 4 metres, 9  
decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009
- 44°26'21.3"N 063°37'36.8"W  
*DFO(6307886-15)*
- 13-APR-2018**
- Replace depth of 10 metres, 7 decimetres with depth of 5 metres, 2  
decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009
- 44°25'52.8"N 063°38'05.8"W  
*DFO(6307886-16)*



**Chart no. 4237**

**13-APR-2018**

Replace depth of 2 metres, 4 decimetres with depth of 1 metre, 6 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 17-NOV-2017  
44°26'48.1"N 063°32'34.1"W  
*DFO(6307886-17)*

**13-APR-2018**

Add depth of 5 metres, 7 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 17-NOV-2017  
44°25'39.7"N 063°37'35.1"W  
*DFO(6307886-18)*

**13-APR-2018**

Replace depth of 6 metres, 7 decimetres with rock which covers and uncovers with drying height of 0 metres, 8 decimetres  
(See Chart No. 1, K11)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 17-NOV-2017  
44°25'45.8"N 063°37'45.9"W  
*DFO(6307886-19)*

**13-APR-2018**

Replace depth of 4 metres, 6 decimetres with depth of 2 metres, 5 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 17-NOV-2017  
44°25'57.1"N 063°39'10.0"W  
*DFO(6307886-20)*

**13-APR-2018**

Replace depth of 4 metres, 3 decimetres with depth of 2 metres, 6 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 17-NOV-2017  
44°27'15.1"N 063°38'57.0"W  
*DFO(6307886-21)*

**13-APR-2018**

Add depth of 4 metres, 5 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 17-NOV-2017  
44°26'34.5"N 063°31'34.1"W  
*DFO(6307886-22)*

**13-APR-2018**

Replace depth of 12 metres, 5 decimetres with depth of 8 metres, 4 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 17-NOV-2017  
44°27'13.2"N 063°38'47.8"W  
*DFO(6307886-25)*





### Chart no. 4237

#### 13-APR-2018

LNМ/D. 17-NOV-2017

Delete depth of 9 metres, 1 decimetre  
(See Chart No. 1, I10)

44°27'45.9"N 063°39'04.1"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-26)*

#### 13-APR-2018

LNМ/D. 17-NOV-2017

Add depth of 3 metres  
(See Chart No. 1, I10)

44°27'44.9"N 063°39'00.4"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6307886-27)*

#### 28-JUL-2017

LNМ/D. 16-DEC-2016

Amend Fl 30s 17m11M to read Iso 17m11M against light  
(See Chart No. 1, P16)

44°36'08.2"N 063°32'00.9"W

*(F2017017) LL(527) DFO(6307965-01)*

This notice affects Electronic Navigational Chart:  
CA476009, CA576002

#### 17-NOV-2017

LNМ/D. 28-JUL-2017

Add drying height of 0 metres, 8 decimetres  
(See Chart No. 1, I15)

44°36'59.6"N 063°16'48.7"W

This notice affects Electronic Navigational Chart: CA376083,  
CA476009

*DFO(6308122-02)*

#### 17-NOV-2017

LNМ/D. 28-JUL-2017

Add depth of 1 metre, 1 decimetre  
(See Chart No. 1, I10)

44°38'02.9"N 063°22'08.1"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308122-03)*

#### 17-NOV-2017

LNМ/D. 28-JUL-2017

Delete yellow ODAS/SADO lighted pillar Fl (5) Y20s  
(See Chart No. 1, Q58)

44°33'31.3"N 063°32'43.9"W

This notice affects Electronic Navigational Chart: (F2017030) LL(521.5) DFO(6308135-01)  
CA476009, CA576002

#### 17-NOV-2017

LNМ/D. 28-JUL-2017

Add yellow ODAS/SADO lighted pillar Fl (5) Y20s  
(See Chart No. 1, Q58)

44°33'21.3"N 063°32'38.6"W

This notice affects Electronic Navigational Chart: (F2017030) LL(521.5) DFO(6308135-02)  
CA476009, CA576002



### Chart no. 4237

#### 31-AUG-2018

Replace depth of 44 metres with wreck Wk with known depth of 43 metres  
(See Chart No. 1, I10, K26)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 13-APR-2018  
44°32'46.0"N 063°20'42.0"W  
*DFO(6308400-01)*

#### 07-DEC-2018

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 122 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 31-AUG-2018  
44°20'52.0"N 063°18'21.0"W  
*DFO(6308508-01)*

#### 07-DEC-2018

Add yellow ODAS/SADO lighted pillar Fl(5) Y 20s  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA176140,  
CA276801, CA476009

LNM/D. 31-AUG-2018  
44°20'52.0"N 063°18'21.0"W  
*DFO(6308508-02)*

#### 31-MAY-2019

Delete depth of 2.6 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 07-DEC-2018  
44°38'03.5"N 063°16'40.4"W  
*DFO(6308648-07)*

#### 31-MAY-2019

Add depth of 0.4 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 07-DEC-2018  
44°38'04.8"N 063°16'39.5"W  
*DFO(6308648-08)*

#### 10-JAN-2020

Add fish haven  
(See Chart No. 1, K46.1)  
This notice affects Electronic Navigational Chart: CA476009,  
CA576003

LNM/D. 31-MAY-2019  
44°40'12.9"N 063°35'30.9"W  
*DFO(6308830-02)*

#### 10-JAN-2020

Replace depth of 8.1 metres with depth of 6.9 metres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476009

LNM/D. 31-MAY-2019  
44°25'33.3"N 063°37'14.0"W  
*DFO(6308832-01)*



### Chart no. 4237

**10-JAN-2020**

LN/D. 31-MAY-2019

Replace depth of 11.6 metres with depth of 8.9 metres  
(See Chart No. 1, I10)

44°25'44.7"N 063°37'27.5"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308832-02)*

**10-JAN-2020**

LN/D. 31-MAY-2019

Add depth of 4.3 metres  
(See Chart No. 1, I10)

44°25'40.0"N 063°37'44.2"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308832-03)*

**10-JAN-2020**

LN/D. 31-MAY-2019

Add depth of 7.5 metres  
(See Chart No. 1, I10)

44°25'55.6"N 063°37'55.0"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308832-04)*

**10-JAN-2020**

LN/D. 31-MAY-2019

Add depth of 7.6 metres  
(See Chart No. 1, I10)

44°26'02.5"N 063°37'52.1"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308832-06)*

**10-JAN-2020**

LN/D. 31-MAY-2019

Add depth of 3.2 metres  
(See Chart No. 1, I10)

44°26'08.4"N 063°36'45.5"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308832-07)*

**13-APR-2001**

Delete yellow ODAS/SADO light buoy, Fl (5) Y 44°29'26.0"N 063°24'13.0"W

*DFO(6829388-01)*

**25-JAN-2002**

LN/D. 13-APR-2001

Add yellow ODAS/SADO light buoy Fl (5) Y 44°30'08.0"N 063°24'10.0"W

*DFO(6829779-01)*