



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4242

4242 - Cape Sable Island to / aux Tusket Islands - New Edition - 28-AUG-1992 - NAD 1983

21-APR-2023

LNМ/D. 17-FEB-2023

Amend Fl(2) 5s to read Fl(2)10s against black, red and
black isolated danger lighted pillar buoy, marked
NSE

43°39'24.0"N 066°02'27.9"W

(See Chart 1, Q130.4)

(F2023001) LL(274.22) DFO(6310616-01)

This notice affects Electronic Navigational Chart:
CA376018, CA476048

17-FEB-2023

LNМ/D. 26-AUG-2022

Add wreck, least depth unknown, with legend PA Rep (2022)
(See Chart 1, K29, B7, I3)

43°21'00.0"N 065°45'00.0"W

This notice affects Electronic Navigational Chart: CA276206,
CA376014, CA476043

DFO(6310555-01)

26-AUG-2022

LNМ/D. 24-DEC-2021

Add rock which covers and uncovers with legend Rep (2022)
(See Chart No. 1, K11, I3)

43°31'12.9"N 065°45'16.8"W

This notice affects Electronic Navigational Chart: CA376014,
CA476043

DFO(6310227-01)

24-DEC-2021

LNМ/D. 23-APR-2021

Add depth of 4.7 metres
(See Chart No. 1, I10)

43°29'22.8"N 065°31'47.5"W

This notice affects Electronic Navigational Chart: CA376047

DFO(6309877-01)

24-DEC-2021

LNМ/D. 23-APR-2021

Replace depth of 5.2 metres with depth of 3.4 metres
(See Chart No. 1, I10)

43°31'18.2"N 065°35'14.4"W
DFO(6309877-02)

24-DEC-2021

LNМ/D. 23-APR-2021

Delete depth of 0.3 metres
(See Chart No. 1, I10)

43°33'01.5"N 065°35'02.6"W

This notice affects Electronic Navigational Chart: CA376047

DFO(6309877-03)

24-DEC-2021

LNМ/D. 23-APR-2021



Chart no. 4242

Add drying height of 0.9 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA376047	43°32'59.8"N 065°35'05.4"W <i>DFO(6309877-04)</i>
24-DEC-2021 Delete depth of 4.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376047	LNM/D. 23-APR-2021 43°28'21.3"N 065°38'46.9"W <i>DFO(6309877-05)</i>
24-DEC-2021 Add depth of 3.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376047	LNM/D. 23-APR-2021 43°28'21.6"N 065°38'50.1"W <i>DFO(6309877-06)</i>
24-DEC-2021 Add depth of 0.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376014	LNM/D. 23-APR-2021 43°28'37.0"N 065°40'58.5"W <i>DFO(6309877-07)</i>
24-DEC-2021 Add depth of 0.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376014	LNM/D. 23-APR-2021 43°28'25.7"N 065°41'08.1"W <i>DFO(6309877-08)</i>
24-DEC-2021 Add depth of 0.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376014	LNM/D. 23-APR-2021 43°29'09.9"N 065°41'26.9"W <i>DFO(6309877-09)</i>
24-DEC-2021 Add depth of 4.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376014	LNM/D. 23-APR-2021 43°29'14.9"N 065°43'18.1"W <i>DFO(6309877-10)</i>
24-DEC-2021 Delete depth of 2.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376014	LNM/D. 23-APR-2021 43°32'13.8"N 065°44'41.4"W <i>DFO(6309877-11)</i>



Chart no. 4242

24-DEC-2021

Add depth of 0.5 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376014

LNМ/D. 23-APR-2021

43°32'12.5"N 065°44'43.4"W

DFO(6309877-12)

24-DEC-2021

Add drying height of 0.7 metres

(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA376014

LNМ/D. 23-APR-2021

43°31'04.7"N 065°44'46.6"W

DFO(6309877-13)

24-DEC-2021

Add drying height of 0.3 metres

(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA376014

LNМ/D. 23-APR-2021

43°30'32.6"N 065°45'10.4"W

DFO(6309877-14)

24-DEC-2021

Delete depth of 1.2 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376014,
CA476043

LNМ/D. 23-APR-2021

43°32'15.1"N 065°46'04.1"W

DFO(6309877-15)

24-DEC-2021

Add depth of 0.7 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376014,
CA476043

LNМ/D. 23-APR-2021

43°32'18.1"N 065°45'59.9"W

DFO(6309877-16)

24-DEC-2021

Delete depth of 3 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376014

LNМ/D. 23-APR-2021

43°32'56.7"N 065°46'51.7"W

DFO(6309877-17)

24-DEC-2021

Add drying height of 0.8 metres

(See Chart No. 1, I15)

This notice affects Electronic Navigational Chart: CA376014

LNМ/D. 23-APR-2021

43°33'00.5"N 065°46'49.8"W

DFO(6309877-18)

24-DEC-2021

LNМ/D. 23-APR-2021



Chart no. 4242

- Add depth of 1.9 metres 43°33'12.0"N 065°46'58.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376014 *DFO(6309877-19)*
- 24-DEC-2021** LNM/D. 23-APR-2021
Delete depth of 3 metres 43°38'35.9"N 065°58'26.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376018, *DFO(6309877-20)*
CA476048
- 24-DEC-2021** LNM/D. 23-APR-2021
Add depth of 0.5 metres 43°38'35.3"N 065°58'29.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376018, *DFO(6309877-21)*
CA476048
- 24-DEC-2021** LNM/D. 23-APR-2021
Delete depth of 2.1 metres 43°29'11.0"N 066°00'41.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376014 *DFO(6309877-22)*
- 24-DEC-2021** LNM/D. 23-APR-2021
Add depth of 1.7 metres 43°29'09.4"N 066°00'44.3"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376014 *DFO(6309877-23)*
- 24-DEC-2021** LNM/D. 23-APR-2021
Add WARNING Recent bathymetric surveys show the presence of 43°36'00.0"N 065°35'00.0"W
shallower depths compared to what is presently charted. The *DFO(6309877-24)*
shallower depths considered the most hazardous to navigation
and within or near main shipping channels will be published in
Notices to Mariners (WWW.NOTMAR.CA). Mariners are advised
to exercise extreme caution, specifically when they navigate
outside of the marked navigation channels. AVERTISSEMENT
Des levés bathymétriques récents ont révélé la présence de
profondeurs moindres que celles portées sur les cartes marines.
Les profondeurs moindres les plus dangereuses pour la
navigation et dans ou près des principales voies de navigation
seront publiées dans les Avis aux navigateurs
(WWW.NOTMAR.CA). Nous demandons aux navigateurs
d'exercer la plus grande prudence, particulièrement lors de la
navigation en dehors des voies de navigation balisées.



Chart no. 4242

23-APR-2021

Add pier

(See Chart No. 1, F14)

This notice affects Electronic Navigational Chart:
CA376014, CA476105

LNМ/D. 19-JUN-2020

joining 43°37'10.4"N 065°47'20.0"W

43°37'11.4"N 065°47'13.4"W

and 43°37'10.0"N 065°47'12.8"W

DFO(6309390-02)

23-APR-2021

Add depth of 1.6 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376047

LNМ/D. 19-JUN-2020

43°27'23.7"N 065°34'41.4"W

DFO(6309392-01)

23-APR-2021

Add wreck, least depth unknown, dangerous to surface navigation
with legend PA

(See Chart No. 1, K28, B7)

This notice affects Electronic Navigational Chart: CA376047

LNМ/D. 19-JUN-2020

43°27'24.6"N 065°34'31.8"W

DFO(6309392-02)

19-JUN-2020

Amend FI R to read ISO R 2s against light

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA476048

LNМ/D. 10-MAY-2019

43°38'08.2"N 066°00'59.6"W

(F2020022) LL(284) DFO(6308987-01)

19-JUN-2020

Amend FI6s 16m 9M to read LFI 6s16m9M against light

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA276206, CA376018, CA476048

LNМ/D. 10-MAY-2019

43°37'43.1"N 066°01'35.9"W

(F2020023) LL(283) DFO(6308988-01)

10-MAY-2019

Amend "Hospital Reef" to read "Kelp Shoal"

This notice affects Electronic Navigational Chart: CA376047

LNМ/D. 05-JAN-2018

43°26'41.2"N 065°39'27.5"W

DFO(6308621-01)

05-JAN-2018

Delete fog signal against light

(See Chart No. 1, R1)

This notice affects Electronic Navigational Chart:
CA376014, CA476043

LNМ/D. 09-JUN-2017

43°31'10.5"N 065°44'43.1"W

(F2017020) LL(312) DFO(6307973-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4242

09-JUN-2017

Add marine farm

(See Chart No. 1, K48.1, K48.2)

This notice affects Electronic Navigational Chart: CA376047,
CA476043

LNМ/D. 24-MAR-2017

43°27'54.5"N 065°38'57.3"W

DFO(6307872-04)

24-MAR-2017

Add light FLR

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA376014, CA476043

LNМ/D. 06-MAY-2016

43°31'50.7"N 065°44'33.2"W

(F2016063) LL(315.4) DFO(6307799-01)

06-MAY-2016

Add light Fl G against beacon with radar reflector

(See Chart No. 1, Q81, P16)

This notice affects Electronic Navigational Chart:
CA376047, CA476043

LNМ/D. 26-FEB-2016

43°26'06.5"N 065°39'13.2"W

(F2016010) LL(323.6) DFO(6307486-01)

26-FEB-2016

Amend Fl to read LFl against light

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA376014, CA476043

LNМ/D. 31-JUL-2015

43°32'11.8"N 065°44'36.4"W

(F2015042) LL(315.3) DFO(6307424-01)

31-JUL-2015

Amend FogSig 20s (Occas) to read FogSig 20s

(See Chart No. 1, R20)

This notice affects Electronic Navigational Chart:
CA276800, CA376047

LNМ/D. 05-JUN-2015

43°26'58.9"N 065°28'14.1"W

(F2015022) LL(336) DFO(6307210-01)

05-JUN-2015

Amend FogSig 20s to read FogSig 20s (Occas)

(See Chart No. 1, R20)

This notice affects Electronic Navigational Chart:
CA276800, CA376047

LNМ/D. 18-OCT-2013

43°26'59.0"N 065°28'15.0"W

(F2015014) LL(336) DFO(6307115-01)

18-OCT-2013

Add wreck with legend "PA Rep(2011)", least depth unknown
(See Chart No. 1, K28)

This notice affects Electronic Navigational Chart: CA376014

LNМ/D. 30-AUG-2013

43°18'15.6"N 066°00'45.0"W

DFO(6306427-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4242

30-AUG-2013

LNM/D. 09-SEP-2011

Delete red starboard hand spar buoy, marked JR52
(See Chart No. 1, Qf)

43°29'24.2"N 065°33'34.9"W

This notice affects Electronic Navigational Chart: CA376047 (F2013017) DFO(6306463-01)

09-SEP-2011

LNM/D. 15-JUL-2011

Delete radar reflector
(See Chart No. 1, S4)

43°30'51.3"N 065°48'17.9"W

(F2011161) DFO(6305681-01)

This notice affects Electronic Navigational Chart: CA376014,
CA476043

09-SEP-2011

LNM/D. 15-JUL-2011

Delete radar reflector
(See Chart No. 1, S4)

43°25'13.6"N 065°40'42.1"W

(F2011162) DFO(6305682-01)

This notice affects Electronic Navigational Chart: CA376014,
CA476043

15-JUL-2011

LNM/D. 08-JUL-2011

Delete depth of 0 metres, 9 decimetres 43°28'24.5"N 065°37'56.3"W
(See Chart No. 1, I10)

DFO(6305367-01)

15-JUL-2011

LNM/D. 08-JUL-2011

Add breakwater between 43°28'26.4"N 065°37'59.2"W
(See Chart 1 F4.1) and 43°28'19.6"N 065°37'54.0"W

DFO(6305367-02)

15-JUL-2011

LNM/D. 08-JUL-2011

Add light FLG
(See Chart No. 1, P1)

43°28'26.4"N 065°37'59.2"W

(F2011088) LL(317.1) DFO(6305367-03)

08-JUL-2011

LNM/D. 01-JUL-2011



Chart no. 4242

Add breakwater joining 43°31'53.6"N 065°44'28.6"W
(See Chart No. 1, F4.1) 43°31'51.1"N 065°44'28.6"W
43°31'50.6"N 065°44'33.6"W
43°31'46.3"N 065°44'33.2"W
and 43°31'44.7"N 065°44'26.5"W

DFO(6305537-03)

08-JUL-2011 LNM/D. 01-JUL-2011

Add depth of 1 metre, 3 decimetres 43°31'42.4"N 065°44'34.8"W
(See Chart No. 1, I10)

DFO(6305537-05)

08-JUL-2011 LNM/D. 01-JUL-2011

Add depth of 2 metres, 7 decimetres 43°31'28.7"N 065°44'40.6"W
(See Chart No. 1, I10)

DFO(6305537-07)

08-JUL-2011 LNM/D. 01-JUL-2011

Add depth of 1 metre, 2 decimetres 43°31'31.2"N 065°44'52.8"W
(See Chart No. 1, I10)

DFO(6305537-08)

01-JUL-2011 LNM/D. 05-JUN-2009

Amend FIR 12s to read LFIR against light 43°28'24.6"N 065°38'01.7"W
(See Chart No 1 P16)

(F2011089) LL(318.5) DFO(6305368-01)

05-JUN-2009 LNM/D. 27-FEB-2009

Amend LFl R to read LFl G against light 43°25'56.9"N 065°37'54.9"W
(See Chart No 1 P16)

(F2009019) LL(323.5) DFO(6304402-01)

This notice affects Electronic Navigational Chart:
CA376047

27-FEB-2009 LNM/D. 07-NOV-2008



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4242

Reposition red starboard hand lighted pillar buoy F1R,
marked JQ52
(See Chart No 1 Qf)

from 43°28'01.0"N 065°33'49.0"W
to 43°27'57.5"N 065°33'40.3"W

(F2008172) LL(331.44) DFO(6304248-01)

This notice affects Electronic Navigational
Chart: CA376047

07-NOV-2008

Delete circular radiobeacon against light Fl 10s 31m
(See Chart No 1 S10)

LNLM/D. 15-FEB-2008

43°23'40.0"N 066°00'51.0"W

DFO(6304021-01)

This notice affects Electronic Navigational Chart: CA276206,
CA376014

15-FEB-2008

Amend Fl R to read LFl R against light 43°25'56.9"N 065°37'54.0"W
(See Chart No 1 P16)

LNLM/D. 28-DEC-2007

LL(323.5) DFO(6303799-01)

28-DEC-2007

Replace yellow, black and yellow West cardinal lighted spar
buoy Q(9) 15s, marked NAC with yellow, black and
yellow West cardinal lighted pillar buoy Q(9) 15s,
marked NAC
(See Chart No 1, Q130.3.)

LNLM/D. 21-SEP-2007

43°24'59.3"N 065°39'18.9"W

(F2007083) LL(324) DFO(6303674-01)

21-SEP-2007

Amend FR to read F1R against light

LNLM/D. 09-FEB-2007

43°29'32.9"N 065°42'18.0"W

(F2007038) LL(309) DFO(6303595-01)

09-FEB-2007

Reposition green port hand lighted spar buoy FIG, marked
P1

LNLM/D. 12-JAN-2007

from 43°35'12.0"N 065°48'10.5"W
to 43°35'10.3"N 065°48'13.9"W

(F2006181) LL(302.5) DFO(6303271-01)

12-JAN-2007

LNLM/D. 24-NOV-2006



Chart no. 4242

Delete light "Q(2)G 5s" 43°29'19.1"N 065°33'35.1"W

(F2006045) LL(331.5) DFO(6302870-01)

12-JAN-2007 LNM/D. 24-NOV-2006

Add light "Iso G 4s" 43°29'22.5"N 065°33'35.3"W

(F2006075) LL(331.5) DFO(6302870-02)

12-JAN-2007 LNM/D. 24-NOV-2006

Delete depth of 1 metre, 2 decimetres 43°29'21.8"N 065°33'33.0"W

DFO(6302870-03)

12-JAN-2007 LNM/D. 24-NOV-2006

Add breakwater joining 43°29'17.1"N 065°33'32.4"W
43°29'21.8"N 065°33'33.0"W
and 43°29'22.5"N 065°33'35.3"W

DFO(6302870-04)

12-JAN-2007 LNM/D. 24-NOV-2006

Add red starboard hand spar buoy, marked JR52 43°29'24.2"N 065°33'34.9"W

(F2006143) LL(5331.7) DFO(6303124-01)

24-NOV-2006 LNM/D. 25-AUG-2006

Replace red starboard hand spar buoy, marked JQ52 with
red starboard hand lighted pillar buoy FIR,
marked JQ52 43°28'01.0"N 065°33'49.0"W

(F2006109) LL(5331) DFO(6303066-01)

24-NOV-2006 LNM/D. 25-AUG-2006

Delete legend "WHIS" against red starboard hand lighted
pillar whistle buoy FIR, WHIS marked JS56 43°25'42.0"N 065°29'16.0"W

(F2006124) LL(337) DFO(6303090-01)

24-NOV-2006 LNM/D. 25-AUG-2006



Chart no. 4242

Delete green port hand lighted pillar bell buoy FlG, BELL
marked JS53

43°23'58.0"N 065°35'18.0"W

(F2006127) LL(328) DFO(6303091-01)

24-NOV-2006

LN/D. 25-AUG-2006

Add green port hand lighted pillar buoy FlG, marked JS53

43°23'58.0"N 065°35'20.0"W

(F2006127) LL(328) DFO(6303091-02)

24-NOV-2006

LN/D. 25-AUG-2006

Delete legend "BELL" against green port hand lighted pillar
bell buoy FlG, BELL marked JS55

43°25'13.0"N 065°34'17.5"W

(F2006129) LL(329) DFO(6303092-01)

24-NOV-2006

LN/D. 25-AUG-2006

Delete legend 'WHIS' against red and white fairway lighted
pillar whistle buoy Mo(A), WHIS, marked 'JQ'

43°27'24.5"N 065°32'44.5"W

(F2006130) LL(330) DFO(6303093-01)

24-NOV-2006

LN/D. 25-AUG-2006

Replace green port hand lighted pillar bell buoy FlG, BELL
marked JS59 with green port hand lighted spar
buoy FlG, marked JS59

43°27'58.0"N 065°32'48.0"W

(F2006131) LL(331) DFO(6303094-01)

25-AUG-2006

LN/D. 11-AUG-2006

Amend "FlG 12s" to read "FlG" against light

43°28'06.4"N 065°33'56.1"W

(F2006074) LL(331.2) DFO(6302869-01)

11-AUG-2006

LN/D. 21-JUL-2006



Chart no. 4242

(T)Replace yellow, black and yellow West cardinal lighted spar buoy Q(9) 15s, marked NAC with red starboard hand lighted spar buoy FIR, marked NA6

43°24'59.3"N 065°39'18.9"W

(F2006015) LL(324) DFO(6303060-01)

Buoy permanently established. Notice 11-August-2006(T), DFO (6303060-01) is now cancelled. See reference DFO(6303674-01) appearing in this edition.
Cancelled on 28-DEC-07

21-JUL-2006

LN/D. 14-JUL-2006

Add black, red and black isolated danger lighted pillar buoy Fl(2)5s, marked NSE

43°39'24.0"N 066°02'28.5"W

(F2006090) LL(274.22) DFO(6302954-02)

This notice affects Electronic Navigational Chart:
CA376018

14-JUL-2006

LN/D. 23-JUN-2006

Delete legend "BELL" against red starboard hand lighted pillar bell buoy FIR, marked N6

43°36'38.3"N 066°12'45.0"W

(F2006087) LL(273) DFO(6302894-01)

This notice affects Electronic Navigational Chart:
CA276206, CA276800, CA376018

23-JUN-2006

LN/D. 16-JUN-2006

Add light FLG

43°25'25.8"N 065°39'25.6"W

(F2006076) LL(323.91) DFO(6302871-01)

23-JUN-2006

LN/D. 16-JUN-2006

Amend "FIR" to read "QR" against red starboard pillar light buoy marked D2

43°29'35.3"N 065°45'39.9"W

(F2006077) LL(305) DFO(6302881-01)

23-JUN-2006

LN/D. 16-JUN-2006

Delete light FIR

43°28'25.1"N 065°38'13.5"W

(F2006080) LL(318) DFO(6302883-01)



Chart no. 4242

16-JUN-2006

LNM/D. 05-MAY-2006

Add legend "Channel Buoyed/Chenal balisé" 43°38'15.0"N 065°45'30.0"W

DFO(6302808-01)

16-JUN-2006

LNM/D. 05-MAY-2006

Delete green port hand pillar light and bell buoy FlG,
marked JS61

43°29'21.0"N 065°33'16.0"W

(F2006056) LL(331.6) DFO(6302835-01)

16-JUN-2006

LNM/D. 05-MAY-2006

Add green port hand lighted spar buoy FlG, marked JS61

43°29'21.0"N 065°33'18.0"W

(F2006056) LL(331.6) DFO(6302835-02)

05-MAY-2006

LNM/D. 28-APR-2006

Add light FlG

43°29'20.3"N 065°43'04.4"W

(F2006019) LL(306.003) DFO(6302783-01)

28-APR-2006

LNM/D. 03-MAR-2006

Replace red and white fairway lighted pillar buoy Mo(A),
marked NAC with yellow, black and yellow West
cardinal lighted spar buoy Q(9) 15s, marked NAC

43°24'59.3"N 065°39'18.9"W

(F2006015) LL(324) DFO(6302779-01)

28-APR-2006

LNM/D. 03-MAR-2006

Delete legend "BELL" against green, red and green port
bifurcation lighted pillar bell buoy Fl(2+1) G,
marked TA

43°39'27.3"N 065°58'20.9"W

(F2006016) LL(293.55) DFO(6302780-01)

28-APR-2006

LNM/D. 03-MAR-2006

Delete red, green and red starboard bifurcation conical buoy,
marked C

43°27'38.5"N 065°39'32.0"W

(F2006017) DFO(6302781-01)

28-APR-2006

LNM/D. 03-MAR-2006



Chart no. 4242

Add red starboard hand conical buoy, marked C6 43°27'37.0"N 065°39'30.9"W

(F2006017) DFO(6302781-02)

03-MAR-2006

LNM/D. 24-FEB-2006

Delete legend "BELL" against red and white fairway pillar
light and bell buoy Mo (A), BELL, marked NSC

43°35'59.6"N 066°03'47.6"W

(F2005138) LL(288) DFO(6302723-01)

03-MAR-2006

LNM/D. 24-FEB-2006

Delete legend "BELL" against red starboard hand pillar
light and bell buoy FIR, BELL marked NE2

43°37'08.6"N 065°54'51.4"W

(F2005139) LL(285.2) DFO(6302724-01)

03-MAR-2006

LNM/D. 24-FEB-2006

Delete legend "BELL" against green port hand pillar light
buoy FIG, BELL marked T3

43°38'05.8"N 065°59'59.3"W

(F2006001) LL(285) DFO(6302733-01)

24-FEB-2006

LNM/D. 10-FEB-2006

Delete legend "BELL" against red starboard hand pillar light
and bell buoy FIR, BELL marked ND4

43°30'30.3"N 065°49'10.4"W

(F2005141) LL(303) DFO(6302725-01)

10-FEB-2006

LNM/D. 06-JAN-2006

Add green port hand lighted spar buoy QG, marked D3

43°30'00.1"N 065°45'18.0"W

(F2005100) LL(305.5) DFO(6302672-01)

10-FEB-2006

LNM/D. 06-JAN-2006

Replace green port hand can buoy, marked D1, with green
port hand pillar light buoy FIG, marked D1

43°29'29.8"N 065°45'58.5"W

(F2005101) LL(304.1) DFO(6302673-01)

10-FEB-2006

LNM/D. 06-JAN-2006

Delete red starboard hand spar buoy, marked D6 43°30'37.0"N 065°44'54.5"W

(F2005102) DFO(6302674-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4242

- 10-FEB-2006** LNM/D. 06-JAN-2006
Add red starboard hand lighted pillar buoy FIR, marked D6 43°30'32.6"N 065°45'00.1"W
(F2005102) LL(311.6) DFO(6302674-02)
- 10-FEB-2006** LNM/D. 06-JAN-2006
Add red starboard hand lighted spar buoy FIR, marked C10 43°28'26.9"N 065°38'16.9"W
(F2005103) LL(318.01) DFO(6302675-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006
Replace green port hand can buoy, marked C1 with green port hand lighted spar buoy QG, marked C1 43°27'22.5"N 065°41'05.0"W
(F2005104) LL(320.01) DFO(6302676-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006
Reposition green port hand can buoy, marked DC13 from 43°33'08.0"N 065°47'05.0"W to 43°33'08.4"N 065°47'02.9"W
(F2005107) DFO(6302679-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006
Replace green port hand can buoy, marked CA1 with green port hand lighted spar buoy FIG, marked CA1 43°26'42.0"N 065°39'40.0"W
(F2005117) LL(322.1) DFO(6302685-01)
- 10-FEB-2006** LNM/D. 06-JAN-2006
Amend "FIR" to read "QR" against red starboard hand spar light buoy, marked NA4 43°23'46.5"N 065°39'11.0"W
(F2005137) LL(326.02) DFO(6302698-01)
- 06-JAN-2006** LNM/D. 18-NOV-2005
Reposition green port hand lighted pillar buoy FIG, marked D5 from 43°30'33.0"N 065°44'55.0"W to 43°30'30.0"N 065°45'07.0"W
(F2005098) LL(311.5) DFO(6302657-01)



Chart no. 4242

18-NOV-2005

Delete red starboard hand lighted pillar bell buoy FLR,
BELL, marked P2

LNM/D. 07-OCT-2005

43°35'55.5"N 065°47'03.8"W

(F2005083) LL(298.4) DFO(6302554-01)

18-NOV-2005

Delete light FLR and radar reflector

LNM/D. 07-OCT-2005

43°31'41.2"N 065°44'59.6"W

(F2005084) LL(314) DFO(6302557-01)

18-NOV-2005

Delete legend "Fog Sig 20s" against light

LNM/D. 07-OCT-2005

43°27'23.2"N 065°44'36.2"W

(F2005085) LL(307) DFO(6302558-01)

07-OCT-2005

Amend "FG" to read "FIG" against light

LNM/D. 22-JUL-2005

43°31'46.0"N 065°44'23.7"W

(F2005064) LL(315) DFO(6302470-01)

07-OCT-2005

Amend "FY" to read "FIY" against light

LNM/D. 22-JUL-2005

43°29'23.9"N 065°43'08.2"W

(F2005066) LL(311) DFO(6302480-01)

22-JUL-2005

Add light 'FLR' against red starboard hand spar buoy,
marked NA4

LNM/D. 27-MAY-2005

43°23'46.5"N 065°39'11.0"W

(F2005035) LL(326.02) DFO(6302362-01)

27-MAY-2005

Delete fog signal "Fog Sig (Occas)"

LNM/D. 20-MAY-2005

43°26'39.4"N 065°35'05.9"W

(F2005017) LL(329.4) DFO(6302274-01)

20-MAY-2005

LNM/D. 06-MAY-2005



Chart no. 4242

(T)Add green port hand pillar light buoy FIG, marked 43°25'27.6"N 065°39'17.3"W
NA5
This buoy is temporarily established. (F2005013T) LL(323.9) DFO(6302270-01)
This buoy is permanently discontinued. Notice
20-May-2005(T), DFO(6302270) is now cancelled.
Cancelled on 18-NOV-05

20-MAY-2005 LNM/D. 06-MAY-2005
Add light FIR 43°35'53.4"N 065°46'55.6"W
(F2005019) LL(299) DFO(6302276-01)

06-MAY-2005 LNM/D. 08-APR-2005
Delete red starboard hand conical buoy, marked NK2 43°20'08.3"N 065°58'45.9"W
(F2004211) DFO(6302220-01)

06-MAY-2005 LNM/D. 08-APR-2005
Add black, yellow and black East cardinal pillar light buoy 43°20'26.9"N 065°58'43.4"W
Q(3) 10s, marked NK
(F2004211) LL(290.2) DFO(6302220-02)

08-APR-2005 LNM/D. 04-MAR-2005
Delete rock awash 43°20'27.8"N 065°59'09.0"W
DFO(6302248-01)

08-APR-2005 LNM/D. 04-MAR-2005
Add rock which covers and uncovers with drying height of 0.4 metres 43°20'27.2"N 065°59'11.0"W
DFO(6302248-02)

04-MAR-2005 LNM/D. 25-FEB-2005
Delete green port hand can buoy, marked NJ1 43°32'53.3"N 066°02'08.9"W
(F2004193) DFO(6302187-01)
This notice affects Electronic Navigational Chart: CA376018

04-MAR-2005 LNM/D. 25-FEB-2005



Chart no. 4242

Delete red and white fairway pillar light and bell buoy
Mo(A), BELL, marked NS

43°31'33.3"N 066°05'06.0"W

(F2004196) LL(274) DFO(6302190-01)

04-MAR-2005

LNМ/D. 25-FEB-2005

Add yellow and black South cardinal pillar light buoy
'Q(6)+LFl 15s', marked NSA

43°30'45.3"N 066°02'31.0"W

(F2004207) LL(274.2) DFO(6302202-01)

04-MAR-2005

LNМ/D. 25-FEB-2005

Add black and yellow North cardinal pillar light buoy Q,
marked NSB

43°33'23.5"N 066°03'00.0"W

(F2004210) LL(274.4) DFO(6302205-01)

This notice affects Electronic Navigational Chart:
CA376018

25-FEB-2005

LNМ/D. 28-JAN-2005

Replace red starboard hand conical buoy, marked NC2
with red starboard hand pillar light buoy FlR,
marked N2

43°22'51.0"N 065°41'49.5"W

(F2004212) LL(307.02) DFO(6302175-01)

25-FEB-2005

LNМ/D. 28-JAN-2005

Replace red and white fairway pillar, light buoy Mo (A),
BELL, marked NA with red starboard hand pillar
light buoy FlR, marked NA2

43°23'30.3"N 065°38'42.0"W

(F2004213) LL(326) DFO(6302181-01)

25-FEB-2005

LNМ/D. 28-JAN-2005

Add green port hand spar light buoy FlG, marked P1

43°35'12.0"N 065°48'10.5"W

(F2004214) LL(302.5) DFO(6302182-01)

25-FEB-2005

LNМ/D. 28-JAN-2005

Delete legend "BELL" against red starboard hand pillar light
and bell buoy FlR, BELL marked D2

43°29'35.3"N 065°45'39.9"W

(F2004190) LL(305) DFO(6302184-01)



Chart no. 4242

25-FEB-2005

Delete red and white fairway pillar light and whistle buoy
Mo(A), WHIS, marked P

LN/D. 28-JAN-2005

43°34'51.0"N 065°48'12.0"W

(F2004194) LL(302) DFO(6302188-01)

25-FEB-2005

Delete legend "BELL" against red and white fairway pillar
light and bell buoy Mo (A), BELL, marked D

LN/D. 28-JAN-2005

43°29'09.3"N 065°46'28.9"W

(F2004197) LL(304) DFO(6302191-01)

25-FEB-2005

Replace red starboard hand pillar light and bell buoy FIR,
BELL, marked ND2 with red and white fairway
pillar, light buoy Mo (A), marked C

LN/D. 28-JAN-2005

43°26'23.3"N 065°44'43.9"W

(F2004202) LL(306) DFO(6302195-01)

25-FEB-2005

Delete legend "BELL" against red starboard hand pillar light
and bell buoy FIR, BELL marked C2

LN/D. 28-JAN-2005

43°26'46.3"N 065°40'18.0"W

(F2004203) LL(321) DFO(6302197-01)

25-FEB-2005

Amend "FIR" to read "QR" against red starboard pillar light
buoy marked CA2

LN/D. 28-JAN-2005

43°26'36.0"N 065°39'45.9"W

(F2004204) LL(322) DFO(6302198-01)

25-FEB-2005

Replace red starboard hand pillar light and whistle buoy
FIR, WHIS, marked N2 with red and white fairway
pillar, light buoy Mo (A), marked N

LN/D. 28-JAN-2005

43°20'12.3"N 065°40'45.9"W

(F2004205) LL(325) DFO(6302200-01)

25-FEB-2005

Replace red starboard hand conical buoy, marked NA2, with red
starboard hand spar buoy, marked NA4

LN/D. 28-JAN-2005

43°23'46.0"N 065°39'11.0"W

(F2004102) DFO(6302204-01)

28-JAN-2005

LN/D. 14-JAN-2005



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4242

Add light Q(2)G 5s 43°29'19.1"N 065°33'36.0"W

(F2004217) LL(331.5) DFO(6302183-01)

14-JAN-2005

Delete red starboard hand pillar light and bell buoy FLR,
BELL marked N4

LNМ/D. 05-NOV-2004

43°18'36.0"N 066°00'02.0"W

(F2004185) LL(290) DFO(6302146-01)

05-NOV-2004

Delete legend, Fog Sig (Occas)

LNМ/D. 02-JUL-2004

43°29'18.5"N 065°33'36.4"W

(F2004125) LL(331.4) DFO(6301938-01)

02-JUL-2004

Amend "Fl 10s 14m 16M" to read "Fl 10s 14m 10M" against
light

LNМ/D. 25-JUN-2004

43°27'23.2"N 065°44'36.2"W

(F2004059) LL(307) DFO(6301606-01)

02-JUL-2004

Amend "Fl 6s 16m 16M" to read "Fl 6s 16m 9M" against light

LNМ/D. 25-JUN-2004

43°37'42.6"N 066°01'37.0"W
LL(283) DFO(6301613-01)

25-JUN-2004

Amend "Fl (3) 10s 16m 16M" to read "Mo (D) 10s 15m 12M" against
light

LNМ/D. 07-MAY-2004

43°26'59.0"N 065°28'15.0"W

LL(336) DFO(6301236-01)

07-MAY-2004

Amend "WHIS" to read "BELL" against red starboard hand
pillar light buoy FLR, marked N4, WHIS

LNМ/D. 26-MAR-2004

43°18'36.0"N 066°00'02.0"W

(F2004006) LL(290) DFO(6301321-01)

07-MAY-2004

Amend "WHIS" to read "BELL" against red and white
fairway pillar light buoy Mo(A) marked NS, WHIS

LNМ/D. 26-MAR-2004

43°31'33.3"N 066°05'06.0"W

(F2004007) LL(274) DFO(6301322-01)



Chart no. 4242

26-MAR-2004 LNM/D. 12-MAR-2004
Delete light FLR 43°29'23.6"N 065°42'56.4"W

(F2003106) LL(310) DFO(6301205-01)

26-MAR-2004 LNM/D. 12-MAR-2004
Delete light FLR 43°28'35.0"N 065°43'08.5"W

(F2003118) LL(308) DFO(6301206-01)

26-MAR-2004 LNM/D. 12-MAR-2004
Add yellow, black, yellow West cardinal spar light buoy 43°28'50.1"N 065°43'24.4"W
Q(9) 15s, marked NF

(F2003132) LL(306.002) DFO(6301212-01)

26-MAR-2004 LNM/D. 12-MAR-2004
Delete green, port hand can buoy, marked NC5 43°28'45.0"N 065°43'21.5"W

(F2003146) DFO(6301229-01)

12-MAR-2004 LNM/D. 21-MAR-2003
Delete green port pillar light buoy Fl G marked NC15 43°28'42.3"N 065°41'47.9"W

(F2003107) LL(307.5) DFO(6301174-01)

12-MAR-2004 LNM/D. 21-MAR-2003
Delete red, starboard hand conical buoy, marked NC4 43°28'25.0"N 065°43'27.0"W

(F2003108) DFO(6301175-01)

12-MAR-2004 LNM/D. 21-MAR-2003
Delete green, port hand spar buoy, marked NC17 43°28'55.0"N 065°41'10.0"W

(F2003113) DFO(6301180-01)

12-MAR-2004 LNM/D. 21-MAR-2003



Chart no. 4242

Delete red, starboard hand spar buoy, marked NC18 43°29'15.0"N 065°41'40.0"W
(F2003114) DFO(6301181-01)

12-MAR-2004 LNM/D. 21-MAR-2003
Delete red, starboard hand spar buoy, marked CM2 43°29'14.0"N 065°37'20.0"W
(F2003124) DFO(6301183-01)

12-MAR-2004 LNM/D. 21-MAR-2003
Delete red, starboard hand spar buoy, marked CM4 43°28'43.0"N 065°36'48.0"W
(F2003125) DFO(6301184-01)

21-MAR-2003 LNM/D. 14-FEB-2003
Delete light FLR 12s 8m 5M 43°31'20.5"N 065°44'13.0"W
(F2001026) LL(313) DFO(6300597-01)

21-MAR-2003 LNM/D. 14-FEB-2003
Add breakwater joining 43°31'16.2"N 065°44'11.1"W
43°31'17.5"N 065°44'16.2"W
and 43°31'22.1"N 065°44'15.3"W
DFO(6300597-02)

21-MAR-2003 LNM/D. 14-FEB-2003
Add light FIR 43°31'22.0"N 065°44'15.3"W
(F2002050) LL(313) DFO(6300597-03)

14-FEB-2003 LNM/D. 11-JAN-2002
Amend Iso G to read FIG against light 43°26'33.5"N 065°38'08.7"W
(F2002031) LL(323) DFO(6300473-01)

11-JAN-2002 LNM/D. 30-NOV-2001



Chart no. 4242

Amend Fl (2+1) 6s to read Fl (2+1) G 43°37'03.0"N 065°47'02.0"W

DFO(6829815-01)

30-NOV-2001

LNМ/D. 27-APR-2001

Amend FR to read FIR

43°36'21.3"N 065°46'41.9"W

(F2001116) LL(300.5) DFO(6829785-01)

27-APR-2001

LNМ/D. 07-JUL-2000

(T)Delete The temporary deletion of the legend BELL
against buoy D2

43°29'35.3"N 065°45'39.9"W

(F2001-014T) LL(305) DFO(6829435-01)

With this notification, temporary action dated
27-APR-2001 is cancelled. The bell is back in
service.

Cancelled on 21-MAR-03

07-JUL-2000

LNМ/D. 14-APR-2000

Add light, Fl

43°32'11.8"N 065°44'36.4"W

(F2000-097) LL(315.3) DFO(6828640-02)

14-APR-2000

LNМ/D. 26-NOV-1999

Delete light

43°37'00.1"N 065°47'10.4"W

(F1999058) LL(301.000) DFO(6300003-06)

14-APR-2000

LNМ/D. 26-NOV-1999

Add port bifurcation light buoy, "Fl(2+1)6s", marked
"PB"

43°37'03.0"N 065°47'02.0"W

(F1999072) LL(301.500) DFO(6300003-10)

14-APR-2000

LNМ/D. 26-NOV-1999

Delete light and Fog Sig

43°35'53.4"N 065°46'55.5"W

(F1999057) LL(299.000) DFO(6300003-11)

14-APR-2000

LNМ/D. 26-NOV-1999



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4242

Reposition red and white light and whistle buoy "P"

from 43°31'14.3"N 065°52'00.0"W
to 43°34'51.0"N 065°48'12.0"W

(F1999052) LL(302.000) DFO(6300003-12)

14-APR-2000

Add red light and bell buoy "Fl R", "BELL",
marked "P2"

LN/D. 26-NOV-1999

43°35'55.5"N 065°47'03.8"W

(F1999049) LL(298.400 SUGG) DFO(6300003-13)

14-APR-2000

Delete green light and bell buoy P1

LN/D. 26-NOV-1999

43°34'55.3"N 065°48'10.9"W

(F1999047) LL(298.000) DFO(6300003-14)