



Chart no. 4243

4243 - Cape St Marys - New Edition - 11-OCT-2002 - NAD 1983

04-MAR-2016

LNM/D. 05-FEB-2016

Delete light FLG

44°05'03.1"N 066°12'20.7"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (F2016002) LL(243) DFO(6307455-01)
CA576060

04-MAR-2016

LNM/D. 05-FEB-2016

Add Breakwater with loose boulders

joining 44°05'03.5"N 066°12'20.5"W

(See Chart No. 1, F4.2)

44°05'03.7"N 066°12'15.0"W

This notice affects Electronic Navigational Chart:

44°05'03.3"N 066°12'15.0"W

CA576060

and 44°05'03.2"N 066°12'20.3"W

(F2016002) DFO(6307455-02)

04-MAR-2016

LNM/D. 05-FEB-2016

Add light FLG

44°05'03.5"N 066°12'15.0"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (F2016002) LL(243.0) DFO(6307455-03)
CA576060

04-MAR-2016

LNM/D. 05-FEB-2016

Delete depth of 2 metres, 4 decimetres

44°05'03.2"N 066°12'19.2"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576060

DFO(6307455-10)

27-FEB-2009

LNM/D. 19-OCT-2007

Delete light FLG

44°05'03.1"N 066°12'20.5"W

(See Chart No 1 P1)

(F2008143) LL(243) DFO(6304243-01)

This notice affects Electronic Navigational Chart:

CA576060

27-FEB-2009

LNM/D. 19-OCT-2007

Add light FLG

44°05'03.1"N 066°12'20.7"W

(See Chart No 1 P1)

(F2008143) LL(243) DFO(6304243-02)

This notice affects Electronic Navigational Chart:

CA576060



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4243

05-MAY-2006

Delete light FLG and radar reflector

LNМ/D. 28-APR-2006

44°05'03.0"N 066°12'23.1"W

(F2004107) LL(243) DFO(6301880-01)

This notice affects Electronic Navigational Chart:
CA376018

05-MAY-2006

Add breakwater with loose boulders

LNМ/D. 28-APR-2006

joining 44°05'03.5"N 066°12'23.2"W

44°05'03.5"N 066°12'20.4"W

44°05'03.2"N 066°12'20.2"W

This notice affects Electronic Navigational Chart:
CA376018

44°05'03.1"N 066°12'20.4"W

and 44°05'02.9"N 066°12'23.1"W

DFO(6301880-02)

05-MAY-2006

Add light FLG

LNМ/D. 28-APR-2006

44°05'03.1"N 066°12'20.5"W

(F2004107) LL(243) DFO(6301880-03)

This notice affects Electronic Navigational Chart:
CA376018

4243 - Tusket Islands to / à Cape St Marys - New Edition - 11-OCT-2002 - NAD 1983

21-APR-2023

Amend Fl(2) 5s to read Fl(2)10s against black, red and
black isolated danger lighted pillar buoy marked
NSE

(See Chart 1, Q130.4)

This notice affects Electronic Navigational Chart:
CA376018, CA476048

LNМ/D. 06-MAY-2022

43°39'24.5"N 066°02'26.1"W

(F2023001) LL(274.22) DFO(6310616-01)

06-MAY-2022

Amend Fl 5s 25m 19M to read Oc 3s25m19M against light
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA276206, CA376018

LNМ/D. 07-JAN-2022

43°41'23.6"N 066°08'38.3"W

(F2022001) LL(272) DFO(6310079-01)

07-JAN-2022

LNМ/D. 19-JUN-2020



Chart no. 4243

Delete depth of 3 metres 43°38'35.9"N 065°58'27.9"W
(See Chart No. 1, I10)

DFO(6309964-01)

07-JAN-2022

LNM/D. 19-JUN-2020

Add depth of 0.5 metres 43°38'35.3"N 065°58'29.7"W
(See Chart No. 1, I10)

DFO(6309964-02)

07-JAN-2022

LNM/D. 19-JUN-2020

Add WARNING Recent bathymetric surveys show the presence of shallower depths compared to what is presently charted. The shallower depths considered the most hazardous to navigation and within or near main shipping channels will be published in Notices to Mariners (WWW.NOTMAR.CA). Mariners are advised to exercise extreme caution, specifically when they navigate outside of the marked navigation channels. AVERTISSEMENT Des levés bathymétriques récents ont révélé la présence de profondeurs moindres que celles portées sur les cartes marines. Les profondeurs moindres les plus dangereuses pour la navigation et dans ou près des principales voies de navigation seront publiées dans les Avis aux navigateurs (WWW.NOTMAR.CA). Nous demandons aux navigateurs d'exercer la plus grande prudence, particulièrement lors de la navigation en dehors des voies de navigation balisées. This notice affects Electronic Navigational Chart: CA376018

44°04'02.0"N 066°06'45.0"W

DFO(6309964-03)

19-JUN-2020

LNM/D. 15-MAY-2020

Amend FI 6s 16m 9M to read LFI 6s16m9M against light
(See Chart No. 1, P16)

43°37'42.7"N 066°01'37.2"W

This notice affects Electronic Navigational Chart:
CA276206, CA376018, CA476048

(F2020023) LL(283) DFO(6308988-01)

15-MAY-2020

LNM/D. 11-OCT-2019

Delete light FG
(See Chart No. 1, P1)

43°48'56.7"N 066°09'09.0"W

This notice affects Electronic Navigational Chart:
CA376018, CA576020

(F2020010) LL(257) DFO(6308960-01)

11-OCT-2019

LNM/D. 09-FEB-2018



Chart no. 4243

Add wreck Wk with known depth of 16.5 metres 44°03'41.3"N 066°16'05.4"W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA376018 *DFO(6308803-01)*

09-FEB-2018 LNM/D. 12-MAY-2017
Add beacon with radar reflector 43°39'16.2"N 066°03'21.4"W
(See Chart No. 1, Q80/S4)
This notice affects Electronic Navigational Chart: CA376018 *DFO(6308185-01)*

12-MAY-2017 LNM/D. 23-DEC-2016
Amend Fl to read FlG against light 43°42'12.7"N 066°03'10.5"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (F2017005) LL(278) *DFO(6307889-01)*
CA376018, CA476048

23-DEC-2016 LNM/D. 04-MAR-2016
Replace submarine cable with abandoned submarine cable joining 43°41'26.0"N 066°08'32.0"W
(See Chart No 1 Section L32.) 43°42'25.0"N 066°05'19.0"W
This notice affects Electronic Navigational Chart: 43°42'39.0"N 066°04'56.0"W
CA376018 43°42'53.0"N 066°04'39.0"W
43°43'11.0"N 066°04'23.0"W
and 43°43'27.0"N 066°04'09.0"W
DFO(6307727-01)

23-DEC-2016 LNM/D. 04-MAR-2016
Delete legend Public against pier 43°56'16.0"N 066°08'58.0"W
(See Chart No. 1, Uc)
This notice affects Electronic Navigational Chart: CA376018 *DFO(6307729-01)*

23-DEC-2016 LNM/D. 04-MAR-2016
Amend pier to pier in ruins joining 43°56'19.3"N 066°09'08.3"W
(See Chart No 1 F33) 43°56'19.8"N 066°09'09.6"W
43°56'20.7"N 066°09'08.7"W
This notice affects Electronic Navigational Chart: 43°56'21.0"N 066°09'09.8"W
CA376018 43°56'20.2"N 066°09'10.7"W
43°56'20.9"N 066°09'12.5"W
43°56'20.1"N 066°09'13.1"W
and 43°56'18.2"N 066°09'08.6"W
DFO(6307729-02)



Chart no. 4243

23-DEC-2016

Amend pier to pier in ruins
(See Chart No 1 F33)
This notice affects Electronic Navigational Chart:
CA376018

LN/D. 04-MAR-2016
joining 43°56'23.9"N 066°09'07.0"W
43°56'22.0"N 066°09'11.3"W
43°56'21.4"N 066°09'10.9"W
and 43°56'23.0"N 066°09'07.4"W

DFO(6307729-03)

05-FEB-2016

Add depth of 3 metres, 1 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376018,
CA576020

LN/D. 27-MAR-2015
43°47'49.5"N 066°09'33.9"W

DFO(6307394-01)

05-FEB-2016

Add wreck WK with known depth of 19 metres, 7 decimetres
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA376018,
CA576020

LN/D. 27-MAR-2015
43°45'06.5"N 066°10'11.6"W

DFO(6307394-02)

27-MAR-2015

Add light FIR
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA376018

LN/D. 10-OCT-2014
43°59'09.6"N 066°09'39.6"W
(F2015005) LL(250.1) DFO(6307066-01)

10-OCT-2014

Delete fog signal Fog Sig 20s against light
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart:
CA276206, CA376018

LN/D. 18-APR-2014
43°41'23.1"N 066°08'38.3"W
(F2014029) LL(272) DFO(6306854-01)

18-APR-2014

Delete red starboard hand lighted spar buoy FIR, marked
NU2.
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA376018

LN/D. 11-NOV-2011
43°59'12.1"N 066°09'40.4"W
(F2014007) LL(250.01) DFO(6306710-01)

11-NOV-2011

LN/D. 05-AUG-2011



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4243

Amend FLG to read LFIG against light
(See Chart No. 1, P1)

43°59'09.5"N 066°09'32.9"W

(F2011178) LL(247) DFO(6305794-01)

This notice affects Electronic Navigational Chart:
CA376018

05-AUG-2011

LNМ/D. 01-APR-2011

Amend FL 12s 35m 13M to read LFl 12s 35m 13M (Priv)
against light
(See Chart No. 1, P16)

43°47'38.8"N 066°09'19.3"W

(F2011102) LL(260) DFO(6305611-01)

This notice affects Electronic Navigational Chart:
CA576020

01-APR-2011

LNМ/D. 11-MAR-2011

Reposition red, green and red starboard bifurcation lighted
pillar buoy Fl(2+1)R, with racon, marked NM
(See Chart No 1 Qi)

from 43°49'00.3"N 066°29'58.0"W
to 43°48'57.2"N 066°29'58.0"W

(F2011020) LL(251) DFO(6305284-01)

11-MAR-2011

LNМ/D. 27-FEB-2009

Add breakwater between 43°55'08.8"N 066°09'13.2"W
(See Chart 1 F4.1) and 43°55'12.8"N 066°09'19.5"W

DFO(6305287-01)

11-MAR-2011

LNМ/D. 27-FEB-2009

Add private light FIY(Priv) 43°55'12.8"N 066°09'19.5"W
(See Chart No 1 P1)

DFO(6305287-02)

19-OCT-2007

LNМ/D. 11-AUG-2006

Amend E13/15 to read E13/5 against green port hand
lighted spar buoy FIG
(See Chart No 1 Section Q 11.)

43°45'41.5"N 066°05'25.5"W

(F2006070) LL(272.135) DFO(6303645-01)

11-AUG-2006

LNМ/D. 21-JUL-2006



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4243

Add fog signal 43°42'11.6"N 066°03'12.1"W

(F2006043) LL(278.2) DFO(6302853-01)

11-AUG-2006 LNM/D. 21-JUL-2006

Add light Fl 43°42'12.7"N 066°03'10.5"W

LL(278) DFO(6302892-01)

21-JUL-2006

Add black, red and black isolated danger lighted pillar
buoy Fl(2)5s, marked NSE

LNM/D. 14-JUL-2006

43°39'24.0"N 066°02'28.5"W

(F2006090) LL(274.22) DFO(6302954-02)

This notice affects Electronic Navigational Chart:
CA376018

14-JUL-2006

Delete legend "BELL" against red starboard hand lighted
pillar bell buoy FIR, marked N6

LNM/D. 16-JUN-2006

43°36'38.3"N 066°12'45.0"W

(F2006087) LL(273) DFO(6302894-01)

This notice affects Electronic Navigational Chart:
CA276206, CA276800, CA376018

16-JUN-2006

Add light 'FIG' against green port hand spar buoy, marked
E9

LNM/D. 05-MAY-2006

43°45'11.3"N 066°05'08.0"W

(F2006069) LL(271.9) DFO(6302841-01)

This notice affects Electronic Navigational Chart:
CA376018

16-JUN-2006

Add light 'FIG' against green port hand spar buoy,
marked E13/15

LNM/D. 05-MAY-2006

43°45'41.5"N 066°05'28.3"W

(F2006070) LL(272.135) DFO(6302842-01)

This notice affects Electronic Navigational Chart:
CA376018



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4243

16-JUN-2006

Add light 'FLR' against red starboard hand spar buoy,
marked E18

LNLM/D. 05-MAY-2006

43°46'09.3"N 066°05'40.0"W

(F2006071) LL(272.18) DFO(6302843-01)

This notice affects Electronic Navigational Chart:
CA376018

05-MAY-2006

Delete light FLG and radar reflector

LNLM/D. 28-APR-2006

44°05'03.0"N 066°12'23.1"W

(F2004107) LL(243) DFO(6301880-01)

This notice affects Electronic Navigational Chart:
CA376018

05-MAY-2006

Add breakwater extension

LNLM/D. 28-APR-2006

between 44°05'03.0"N 066°12'23.1"W
and 44°05'03.1"N 066°12'20.2"W

DFO(6301880-02)

This notice affects Electronic Navigational Chart:
CA376018

05-MAY-2006

Add light FLG

LNLM/D. 28-APR-2006

44°05'03.1"N 066°12'20.5"W

(F2004107) LL(243) DFO(6301880-03)

This notice affects Electronic Navigational Chart:
CA376018

28-APR-2006

Add green, red and green port bifurcation lighted pillar buoy Fl(2+1)
G, marked TA

LNLM/D. 03-MAR-2006

43°39'27.3"N 065°58'20.9"W

LL(293.55) DFO(6302780-02)

This notice affects Electronic Navigational Chart: CA376018

03-MAR-2006

Delete legend "BELL" against red and white fairway pillar
light and bell buoy Mo (A), BELL, marked NSC

LNLM/D. 24-FEB-2006

43°35'59.6"N 066°03'47.6"W

(F2005138) LL(288) DFO(6302723-01)



Chart no. 4243

03-MAR-2006

Add green port hand lighted pillar buoy FlG, marked T3

LNМ/D. 24-FEB-2006

43°38'05.8"N 065°59'59.3"W

(F2006001) LL(285) DFO(6302733-02)

24-FEB-2006

Delete legend "WHIS" against green port hand pillar light and whistle buoy FlG, WHIS, marked Y3

LNМ/D. 10-FEB-2006

43°46'57.3"N 066°09'29.5"W

(F2005142) LL(259) DFO(6302726-01)

10-FEB-2006

Add black and yellow North cardinal spar buoy, marked EA

LNМ/D. 25-NOV-2005

43°43'24.4"N 066°08'01.1"W

(F2005106) DFO(6302678-01)

This notice affects Electronic Navigational Chart: CA376018

25-NOV-2005

Delete legend "BELL" against red starboard hand pillar light and bell buoy FlR, BELL marked Y2

LNМ/D. 04-NOV-2005

43°45'10.3"N 066°09'41.0"W

(F2005088) LL(268) DFO(6302598-01)

This notice affects Electronic Navigational Chart:
CA376018

04-NOV-2005

Delete legend "BELL" against red and white fairway pillar light and bell buoy Mo (A), BELL, marked NSH

LNМ/D. 06-MAY-2005

43°40'06.0"N 066°03'40.0"W

(F2005077) LL(275) DFO(6302547-01)

This notice affects Electronic Navigational Chart:
CA376018

06-MAY-2005

Replace green port hand spar buoy, marked E3 with green port hand spar light buoy FlG, marked E3

LNМ/D. 04-MAR-2005

43°44'54.3"N 066°06'04.0"W

(F2004222) LL(271.3) DFO(6302225-01)

This notice affects Electronic Navigational Chart:
CA376018



Chart no. 4243

06-MAY-2005

Replace green port hand can buoy, marked EA1 with
green port hand can light buoy FlG, marked EA1

LNМ/D. 04-MAR-2005

43°43'09.3"N 066°07'34.5"W

(F2004223) LL(272.23) DFO(6302226-01)

This notice affects Electronic Navigational
Chart: CA376018

06-MAY-2005

Add green port hand spar buoy, marked E13/15

LNМ/D. 04-MAR-2005

43°45'41.5"N 066°05'28.3"W

(F2004224) DFO(6302227-01)

This notice affects Electronic Navigational Chart: CA376018

06-MAY-2005

Replace red starboard hand spar buoy, marked E8 with
red starboard hand spar light buoy FlR, marked
E8

LNМ/D. 04-MAR-2005

43°45'05.3"N 066°05'17.0"W

(F2004225) LL(271.8) DFO(6302228-01)

This notice affects Electronic Navigational Chart:
CA376018

06-MAY-2005

Replace green port hand spar buoy, marked E11 with
green port hand spar light buoy FlG, marked
E11

LNМ/D. 04-MAR-2005

43°45'18.3"N 066°05'08.5"W

(F2005011) LL(272.11) DFO(6302241-01)

This notice affects Electronic Navigational
Chart: CA376018

04-MAR-2005

Delete green port hand can buoy, marked NJ1

LNМ/D. 11-FEB-2005

43°32'53.3"N 066°02'09.0"W

(F2004193) DFO(6302187-01)

This notice affects Electronic Navigational Chart: CA376018

04-MAR-2005

LNМ/D. 11-FEB-2005



Chart no. 4243

Add black and yellow North cardinal pillar light buoy Q,
marked NSB

43°33'23.5"N 066°03'00.0"W

(F2004210) LL(274.4) DFO(6302205-01)

This notice affects Electronic Navigational Chart:
CA376018

11-FEB-2005

LN/D. 14-JAN-2005

Delete legend "WHIS" against red, green and red starboard
bifurcation pillar light and whistle buoy Fl(2+1) R,
WHIS, marked NP

43°58'47.3"N 066°18'26.0"W

(F2004198) LL(245) DFO(6302192-01)

This notice affects Electronic Navigational Chart:
CA376018

11-FEB-2005

LN/D. 14-JAN-2005

Delete legend "BELL" against red and white fairway pillar
light and bell buoy Mo (A), BELL, marked NU

43°59'36.3"N 066°10'18.0"W

(F2004199) LL(246) DFO(6302193-01)

This notice affects Electronic Navigational Chart:
CA376018

11-FEB-2005

LN/D. 14-JAN-2005

Delete legend "WHIS" against red, green and red starboard
bifurcation pillar light and whistle buoy Fl(2+1) R,
WHIS, marked NM

43°49'00.3"N 066°29'58.0"W

(F2004200) LL(251) DFO(6302194-01)

This notice affects Electronic Navigational Chart:
CA376018

11-FEB-2005

LN/D. 14-JAN-2005

Delete legend "WHIS" against green port hand pillar light
and whistle buoy FIG, WHIS, marked N9

43°53'00.3"N 066°26'10.0"W

(F2004201) LL(251.5) DFO(6302196-01)

This notice affects Electronic Navigational Chart:
CA376018

11-FEB-2005

LN/D. 14-JAN-2005



Chart no. 4243

Delete red and white fairway pillar light and bell buoy
Mo(A), BELL, marked E

43°43'46.3"N 066°07'28.0"W

(F2004208) LL(271) DFO(6302203-01)

This notice affects Electronic Navigational Chart:
CA376018

11-FEB-2005

LN/D. 14-JAN-2005

Add yellow and black South cardinal pillar light buoy
'Q(6)+LFl 15s', marked E

43°43'46.6"N 066°07'06.8"W

(F2004201) LL(271) DFO(6302203-02)

14-JAN-2005

LN/D. 07-JAN-2005

Replace green port hand pillar light and bell buoy FlG,
BELL, with green port hand spar light buoy FlG,
marked NS17

43°41'52.3"N 066°03'16.0"W

(F2004189) LL(277) DFO(6302150-01)

14-JAN-2005

LN/D. 07-JAN-2005

Add red starboard hand spar light buoy FIR, marked
NU2

43°59'12.1"N 066°09'40.4"W

(F2004182) LL(250.01) DFO(6302152-01)

This notice affects Electronic Navigational Chart:
CA376018

07-JAN-2005

LN/D. 05-NOV-2004

Amend legend 'Fl 5s 25m 12M' to read 'Fl 5s 25m 19M' against light 43°41'23.1"N 066°08'38.3"W

LL(272) DFO(6302112-01)

This notice affects Electronic Navigational Chart: CA376018

05-NOV-2004

LN/D. 29-OCT-2004

Delete legend "BELL" against red and white fairway pillar
light buoy Mo (A), marked NV, BELL

44°04'10.3"N 066°12'35.0"W

(F2004114) LL(242) DFO(6301918-01)

This notice affects Electronic Navigational Chart:
CA376018

05-NOV-2004

LN/D. 29-OCT-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4243

Delete legend "BELL" against red starboard pillar light buoy
Fl R, BELL, marked NT2

43°55'50.8"N 066°10'53.0"W

(F2004115) LL(252) DFO(6301919-01)

05-NOV-2004

Delete fog signal

LN/D. 29-OCT-2004

43°59'03.3"N 066°09'28.3"W

(F2004130) LL(248) DFO(6301961-01)

This notice affects Electronic Navigational Chart:
CA376018

29-OCT-2004

Replace red starboard pillar light and bell buoy FlR, BELL,
marked NQ2 with green port hand pillar light buoy
FlG, marked NQ1

43°50'35.2"N 066°10'38.5"W

(F2004113) LL(256) DFO(6301917-01)

This notice affects Electronic Navigational Chart:
CA376018