



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4367

### 4367 - Flint Island to / à Cape Smokey - New Edition - 03-APR-2003 - NAD 1983

#### 07-JUL-2023

LNМ/D. 02-SEP-2022

Delete Legend Fog Sig 30 s against light  
(See Chart 1, R1)

46°18'18.8"N 060°23'29.5"W

This notice affects Electronic Navigational Chart: (G2023021) LL(799) DFO(6310674-01)  
CA376093, CA476063, CA576064

#### 02-SEP-2022

LNМ/D. 29-JUL-2022

Add depth of 6 fathoms, 1 foot  
(See Chart No. 1, I10)

46°10'44.2"N 060°13'06.3"W

This notice affects Electronic Navigational Chart: CA376093 DFO(6310228-27)

#### 02-SEP-2022

LNМ/D. 29-JUL-2022

Add depth of 7 fathoms, 3 feet  
(See Chart No. 1, I10)

46°10'18.8"N 060°12'58.1"W

This notice affects Electronic Navigational Chart: CA376093 DFO(6310228-28)

#### 02-SEP-2022

LNМ/D. 29-JUL-2022

Delete depth of 7 fathoms, 5 feet  
(See Chart No. 1, I10)

46°12'01.9"N 060°13'15.1"W

This notice affects Electronic Navigational Chart: CA376093 DFO(6310228-29)

#### 02-SEP-2022

LNМ/D. 29-JUL-2022

Add depth of 7 fathoms, 3 feet  
(See Chart No. 1, I10)

46°12'04.4"N 060°13'16.3"W

This notice affects Electronic Navigational Chart: CA376093 DFO(6310228-30)

#### 29-JUL-2022

LNМ/D. 04-MAR-2022

Add ferry route  
(See Chart No. 1, M50)

between 46°18'21.1"N 060°07'39.1"W  
and 46°22'31.4"N 059°39'57.0"W

This notice affects Electronic Navigational Chart:  
CA276091, CA276271, CA276284, CA376093, DFO(6310118-03)  
CA376166, CA376176, CA576095

#### 04-MAR-2022

LNМ/D. 26-FEB-2021

Amend QR to read Fl R against light  
(See Chart No. 1, P16)

46°41'15.1"N 060°21'35.1"W

This notice affects Electronic Navigational Chart: (G2021258) LL(849.4) DFO(6309996-01)  
CA376167, CA576742



### Chart no. 4367

**26-FEB-2021**

LNМ/D. 28-DEC-2018

Amend ISO Y 4s 56ft 14M to read OC G 10s56ft17M against  
light

46°10'51.0"N 060°15'07.2"W

(See Chart No. 1, P16)

(G2020262) LL(782) DFO(6309335-01)

This notice affects Electronic Navigational Chart:  
CA376093, CA576095

**26-FEB-2021**

LNМ/D. 28-DEC-2018

Amend ISO Y 4s 122ft 14M to read F G 122ft19M against  
light

46°10'30.4"N 060°15'25.8"W

(See Chart No. 1, P16)

(G2020263) LL(783) DFO(6309336-01)

This notice affects Electronic Navigational Chart:  
CA376093, CA576095

**28-DEC-2018**

LNМ/D. 03-AUG-2018

Reposition red starboard hand lighted spar buoy Fl R,  
marked KQ2

from 46°13'45.0"N 060°02'02.4"W

(See Chart No. 1, Qf)

to 46°13'45.5"N 060°02'04.7"W

This notice affects Electronic Navigational  
Chart: CA376093

(G2018138) LL(774.4) DFO(6308538-01)

**28-DEC-2018**

LNМ/D. 03-AUG-2018

Replace red starboard hand lighted spar buoy Fl R,  
marked KQ2 with red starboard hand lighted  
pillar buoy Fl R, marked KQ2

46°13'45.5"N 060°02'04.7"W

(See Chart No. 1, Qf)

(G2018138) LL(774.4) DFO(6308538-02)

This notice affects Electronic Navigational Chart:  
CA376093

**03-AUG-2018**

LNМ/D. 29-DEC-2017

Delete pilot boarding station

46°18'35.0"N 060°07'29.0"W

(See Chart No. 1, T1.1)

This notice affects Electronic Navigational Chart: CA376093

DFO(6308388-01)

**03-AUG-2018**

LNМ/D. 29-DEC-2017

Add pilot boarding station

46°20'30.0"N 060°07'00.0"W

(See Chart No. 1, T1.1)

This notice affects Electronic Navigational Chart: CA376093

DFO(6308388-02)



**Chart no. 4367**

**03-AUG-2018**

Add pilot boarding station  
(See Chart No. 1, T1.1)

This notice affects Electronic Navigational Chart: CA376093,  
CA476063

LNLM/D. 29-DEC-2017

46°22'00.0"N 060°17'30.0"W

*DFO(6308388-03)*

**29-DEC-2017**

Add submarine cable  
(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:  
CA179245, CA276271, CA376093, CA376167, CA376625

LNLM/D. 17-NOV-2017

joining 46°41'34.0"N 060°07'28.9"W  
46°40'53.8"N 060°08'04.9"W  
46°35'04.4"N 060°11'20.1"W  
46°33'21.4"N 060°12'01.3"W  
46°32'07.5"N 060°12'44.1"W  
46°31'10.6"N 060°12'39.6"W  
46°30'35.2"N 060°13'22.4"W  
46°30'22.5"N 060°14'15.3"W  
46°29'12.1"N 060°15'08.7"W  
46°28'01.3"N 060°15'41.8"W  
46°27'38.2"N 060°15'32.2"W  
46°27'01.3"N 060°15'41.9"W  
46°26'49.6"N 060°16'20.6"W  
46°23'51.3"N 060°18'07.5"W  
46°23'27.3"N 060°17'28.7"W  
46°22'44.7"N 060°17'20.7"W  
46°21'33.4"N 060°18'15.7"W  
46°20'54.4"N 060°18'30.3"W  
46°20'34.8"N 060°19'40.6"W  
46°20'03.0"N 060°20'09.7"W  
and 46°19'27.3"N 060°20'14.3"W

*DFO(6308158-01)*

**29-DEC-2017**

LNLM/D. 17-NOV-2017



**Chart no. 4367**

Add submarine cable  
(See Chart No. 1, L30.1)  
This notice affects Electronic Navigational Chart:  
CA376093, CA376167

joining 46°41'34.0"N 060°06'33.2"W  
46°40'12.4"N 060°07'32.9"W  
46°33'37.7"N 060°11'32.8"W  
46°30'35.8"N 060°12'52.0"W  
46°29'58.6"N 060°14'10.2"W  
46°29'30.2"N 060°14'31.0"W  
46°28'54.5"N 060°14'44.9"W  
46°28'01.2"N 060°14'42.0"W  
46°27'05.7"N 060°15'20.1"W  
46°26'35.5"N 060°16'02.0"W  
46°25'58.5"N 060°16'05.6"W  
46°24'16.8"N 060°17'35.9"W  
46°23'49.3"N 060°17'50.3"W  
46°23'27.4"N 060°17'17.1"W  
46°22'44.4"N 060°17'11.7"W  
46°21'44.8"N 060°17'55.9"W  
46°21'29.6"N 060°18'13.1"W  
46°20'50.5"N 060°18'27.2"W  
46°20'32.4"N 060°19'38.9"W  
46°20'03.4"N 060°20'04.8"W  
and 46°19'27.4"N 060°20'12.9"W

*DFO(6308158-02)*

**17-NOV-2017**

LNLM/D. 07-JUL-2017

Amend LFl 6s 26m 13M to read LFl 6s 85ft 13M against light 46°18'18.8"N 060°23'29.5"W  
(See Chart No. 1, P16)

*LL(799) DFO(6308133-01)*

**07-JUL-2017**

LNLM/D. 09-JUN-2017

Reposition red and white fairway lighted pillar bell buoy  
Mo(A), BELL marked KV  
(See Chart No. 1, Qh)  
This notice affects Electronic Navigational  
Chart: CA276271, CA376093

from 46°13'38.0"N 059°55'30.4"W  
to 46°13'28.8"N 059°55'37.8"W

*(G2017022) LL(771) DFO(6307916-01)*

**09-JUN-2017**

LNLM/D. 10-JUN-2016

Delete light LFlR 12s 89ft 7M  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart:  
CA276271, CA376093

46°23'05.3"N 060°22'28.0"W

*(G2017016) LL(844) DFO(6307919-01)*

**10-JUN-2016**

LNLM/D. 29-APR-2016



**Chart no. 4367**

Add light QG 46°11'56.2"N 059°56'51.0"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: *(G2016027) LL(773.5) DFO(6307502-01)*  
CA376093

**29-APR-2016** LNM/D. 05-FEB-2016  
Delete fog signal Fog Sig against light 46°11'56.0"N 059°56'56.1"W  
(See Chart No. 1, R1)  
This notice affects Electronic Navigational Chart: *(G2016026) LL(774) DFO(6307496-01)*  
CA376093

**05-FEB-2016** LNM/D. 27-MAR-2015  
Amend Fl 5s 85ft 19M to read Fl 5s 85ft 18M against light 46°16'01.5"N 060°07'32.9"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA276271, *LL(775) DFO(6307366-05)*  
CA376093, CA576095

**27-MAR-2015** LNM/D. 20-FEB-2015  
Delete red and white fairway lighted pillar buoy Mo(A), 46°18'24.2"N 060°07'50.6"W  
marked SA  
(See Chart No. 1, Qh) *(G2015009) LL(776) DFO(6307072-01)*  
This notice affects Electronic Navigational Chart:  
CA276271, CA376093

**20-FEB-2015** LNM/D. 06-FEB-2015  
Add subsurface Ocean Data Acquisition system and legend joining 46°20'33.0"N 060°19'22.0"W  
ODAS/SADO 46°20'33.0"N 060°18'50.0"W  
(See Chart No. 1, L25) 46°20'56.0"N 060°18'39.0"W  
This notice affects Electronic Navigational Chart: 46°20'58.7"N 060°19'10.0"W  
CA376093, CA476063 and 46°20'33.0"N 060°19'22.0"W  
*DFO(6307036-01)*

**20-FEB-2015** LNM/D. 06-FEB-2015  
Add subsurface Ocean Data Acquisition system and legend joining 46°34'47.3"N 060°10'46.3"W  
ODAS/SADO (See Chart No. 1, L25) 46°35'00.2"N 060°11'29.2"W  
This notice affects Electronic Navigational Chart: 46°30'45.2"N 060°13'59.6"W  
CA276271, CA376093 46°30'33.0"N 060°13'16.0"W  
and 46°34'47.3"N 060°10'46.3"W  
*DFO(6307036-02)*



## Chart no. 4367

### 06-FEB-2015

Amend Fl(2)25s74ft10M to read LF174ft8M against light  
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:  
CA179172, CA276271, CA376093

LNМ/D. 15-AUG-2014

46°10'51.0"N 059°46'13.2"W

(G2014202) LL(770) DFO(6307010-01)

### 06-FEB-2015

Delete legend FogSig30s against light  
(See Chart No. 1, R20)

This notice affects Electronic Navigational Chart:  
CA276271, CA376093

LNМ/D. 15-AUG-2014

46°10'51.0"N 059°46'13.2"W

(G2014213) LL(770) DFO(6307010-02)

### 15-AUG-2014

Delete red and white fairway lighted pillar buoy Mo(A),  
marked SC

(See Chart No. 1, Qh)

This notice affects Electronic Navigational Chart:  
CA376093, CA576095

LNМ/D. 18-OCT-2013

46°14'37.5"N 060°11'21.0"W

(G2014062) LL(777) DFO(6306795-01)

### 18-OCT-2013

Add WHIS to red and white fairway lighted pillar whistle buoy,  
marked U

(See Chart No. 1, Qh)

This notice affects Electronic Navigational Chart: CA276271,  
CA376093

LNМ/D. 11-OCT-2013

46°21'28.2"N 060°14'49.1"W

DFO(6306469-01)

### 11-OCT-2013

Delete light F 84ft 12M

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:  
CA276271, CA376093, CA476063

LNМ/D. 21-JUN-2013

46°20'08.9"N 060°17'34.5"W

(G2013017) LL(796) DFO(6306366-01)

### 11-OCT-2013

Add light LFl 6s 88ft 14M

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:  
CA276271, CA376093, CA476063

LNМ/D. 21-JUN-2013

46°20'10.3"N 060°17'31.9"W

(G2013017) LL(796) DFO(6306366-02)

### 21-JUN-2013

LNМ/D. 19-APR-2013



**Chart no. 4367**

Add red and white fairway lighted pillar whistle buoy LFl,  
marked U

46°21'28.2"N 060°14'49.1"W

(See Chart No. 1, Qh)

(G2013018) LL(789.5) DFO(6306369-01)

This notice affects Electronic Navigational Chart:  
CA276271, CA376093

**19-APR-2013**

LN/D. 02-NOV-2012

Delete red starboard hand lighted pillar whistle buoy WHIS,  
FIR, marked K6

46°21'28.2"N 060°14'49.1"W

(See Chart No. 1, Qf)

(G2013007) LL(795) DFO(6306343-01)

This notice affects Electronic Navigational Chart:  
CA276271, CA376093

**02-NOV-2012**

LN/D. 04-MAY-2012

Delete Legend 'Fog Sig 60s' against light  
(See Chart No 1 R20)

46°20'08.8"N 060°17'34.7"W

(G2012175) LL(796) DFO(6306188-01)

This notice affects Electronic Navigational Chart:  
CA476063

**02-NOV-2012**

LN/D. 04-MAY-2012

Affix patch 46°10'45.0"N 060°12'00.0"W

DFO(6306237-20)

[PDF](#)

**04-MAY-2012**

LN/D. 24-FEB-2012

Delete front range/leading light FY 22ft 46°26'42.0"N 060°27'40.1"W  
(See Chart No 1Pe)

LL(845.7) DFO(6305963-01)

**04-MAY-2012**

LN/D. 24-FEB-2012

Delete rear range/leading light FY 32ft with leading line  
and legend 111<sup>o</sup> 291<sup>o</sup>  
(See Chart No 1Pe)

46°26'42.7"N 060°27'42.8"W

(G2012024) LL(845.8) DFO(6305963-02)

**04-MAY-2012**

LN/D. 24-FEB-2012



**Chart no. 4367**

Add front range/leading light FY 24ft 46°26'41.2"N 060°27'38.7"W  
(See Chart No 1Pe)

*LL(845.7) DFO(6305963-03)*

**04-MAY-2012**

LNM/D. 24-FEB-2012

Add rear range/leading light FY 35ft  
(See Chart No 1Pe)

46°26'42.1"N 060°27'42.2"W

*(G2012024) LL(845.8) DFO(6305963-04)*

**04-MAY-2012**

LNM/D. 24-FEB-2012

Add leading line bearing 111° from the rear range with  
legend 111° - 291°  
(See Chart No 1Pe)

between 46°26'42.1"N 060°27'42.2"W  
and 46°26'05.6"N 060°25'24.5"W

Usable portion of leading line is east of longitude  
60°27'30"W.

*(G2012024) LL(845.8) DFO(6305963-05)*

**24-FEB-2012**

LNM/D. 11-NOV-2011

Add light FLR  
(See Chart No. 1, P1)

46°26'42.6"N 060°27'30.5"W

*(G2012006) LL(845.9) DFO(6305917-01)*

**11-NOV-2011**

LNM/D. 12-AUG-2011

Delete light FG  
(See Chart No. 1, P1)

46°37'56.3"N 060°23'17.5"W

*(G2011294) LL(847) DFO(6305795-01)*

This notice affects Electronic Navigational Chart:  
CA376167

**11-NOV-2011**

LNM/D. 12-AUG-2011

Add light Iso 4s  
(See Chart No. 1, P1)

46°38'00.5"N 060°23'17.0"W

*(G2011294) LL(847) DFO(6305795-02)*

**12-AUG-2011**

LNM/D. 05-AUG-2011

Delete depth of 4 fathoms, 1 foot 46°12'33.8"N 060°32'19.8"W  
(See Chart No. 1, I10)

*DFO(6305563-04)*





Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

**Chart no. 4367**

**12-AUG-2011**

Add depth of 1 fathom, 5 feet  
(See Chart No. 1, I10)

LNМ/D. 05-AUG-2011

46°12'34.5"N 060°32'17.0"W

*DFO(6305563-08)*

This notice affects Electronic Navigational Chart: CA576066

**12-AUG-2011**

Delete depth of 5 fathoms, 4 feet 46°17'01.7"N 060°26'19.6"W  
(See Chart No. 1, I10)

LNМ/D. 05-AUG-2011

*DFO(6305564-01)*

**12-AUG-2011**

Add depth of 5 fathoms 46°16'59.4"N 060°26'24.4"W  
(See Chart No. 1, I10)

LNМ/D. 05-AUG-2011

*DFO(6305564-06)*

**12-AUG-2011**

Add depth of 5 fathoms, 5 feet 46°15'44.5"N 060°28'07.2"W  
(See Chart No. 1, I10)

LNМ/D. 05-AUG-2011

*DFO(6305569-08)*

**12-AUG-2011**

Add depth of 5 fathoms, 4 feet 46°11'53.5"N 060°32'25.0"W  
(See Chart No. 1, I10)

LNМ/D. 05-AUG-2011

*DFO(6305569-12)*

**12-AUG-2011**

Add depth of 9 fathoms, 5 feet 46°11'34.1"N 060°33'02.8"W  
(See Chart No. 1, I10)

LNМ/D. 05-AUG-2011

*DFO(6305569-13)*

**12-AUG-2011**

Delete depth of 13 fathoms 46°11'30.5"N 060°33'03.7"W  
(See Chart No. 1, I10)

LNМ/D. 05-AUG-2011

*DFO(6305569-22)*

**12-AUG-2011**

LNМ/D. 05-AUG-2011



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4367

Delete depth of 6 fathoms 46°15'49.1"N 060°28'09.4"W  
(See Chart No. 1, I10)

*DFO(6305569-23)*

#### 05-AUG-2011

LNМ/D. 01-JUL-2011

Amend Iso Y 4s 60ft to read Iso Y 4s 56ft 14M against light  
(See Chart No. 1, P16)

46°10'49.0"N 060°15'06.0"W

*(G2011222) LL(782) DFO(6305624-01)*

#### 05-AUG-2011

LNМ/D. 01-JUL-2011

Amend Iso Y 4s 125ft to read Iso Y 4s 122ft 14M against  
light  
(See Chart No. 1, P16)

46°10'30.0"N 060°15'25.5"W

*(G2011223) LL(783) DFO(6305625-01)*

#### 01-JUL-2011

LNМ/D. 18-MAR-2011

Add yellow and black South cardinal lighted pillar buoy  
Q(6) + LFl 15s, marked KH  
(See Chart No. 1, Q130.3)

46°40'44.4"N 060°20'38.1"W

*(G2011162) LL(849) DFO(6305536-01)*

#### 18-MAR-2011

LNМ/D. 29-OCT-2010

Amend FLR 12s 89ft 5M to read LFLR 12s 89ft 7M against  
light  
(See Chart No. 1 P16)

46°23'06.4"N 060°22'25.8"W

*(G2011051) LL(844) DFO(6305271-01)*

#### 29-OCT-2010

LNМ/D. 22-OCT-2010

Amend FG to read Fl R against light  
(See Chart No. 1 P16)

46°11'56.0"N 059°56'56.0"W

*(G2010140) LL(774) DFO(6305038-01)*

#### 22-OCT-2010

LNМ/D. 09-JAN-2009

Delete light F  
(See Chart No. 1 P1)

46°17'26.0"N 060°32'31.0"W

*(G2010134) LL(845) DFO(6305028-01)*

#### 09-JAN-2009

LNМ/D. 01-AUG-2008



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4367

Amend FY 60ft to read Iso Y 4s 60ft against light  
(See Chart No 1 P16)

46°10'48.6"N 060°15'05.0"W

(G2008083) LL(782) DFO(6304164-01)

This notice affects Electronic Navigational Chart:  
CA576095

#### 09-JAN-2009

LNМ/D. 01-AUG-2008

Amend FY 125ft to read Iso Y 4s 125ft against light  
(See Chart No 1 P16)

46°10'27.9"N 060°15'24.0"W

(G2008084) LL(783) DFO(6304164-02)

This notice affects Electronic Navigational Chart:  
CA576095

#### 01-AUG-2008

LNМ/D. 25-JUL-2008

Add submarine cable

joining 46°41'34.0"N 059°40'35.9"W

46°18'27.4"N 060°05'02.4"W

46°18'19.1"N 060°05'03.2"W

This notice affects Electronic Navigational Chart:  
CA179172, CA276271, CA576095

46°18'00.9"N 060°05'30.9"W

46°16'40.6"N 060°06'56.2"W

and 46°15'51.4"N 060°07'19.8"W

DFO(6303984-01)

#### 25-JUL-2008

LNМ/D. 01-FEB-2008

Add submarine cable

joining 46°41'34.0"N 059°51'39.2"W

46°16'53.3"N 060°12'06.3"W

46°16'03.1"N 060°13'58.9"W

This notice affects Electronic Navigational Chart:  
CA179172, CA276271, CA576095

and 46°15'39.8"N 060°13'54.8"W

DFO(6303964-01)

#### 01-FEB-2008

LNМ/D. 13-JUL-2007

Delete legend Fog Sig (2) 60s against light  
(See Chart No 1 R20)

46°16'01.5"N 060°07'32.9"W

(G2007178) LL(775) DFO(6303745-01)

This notice affects Electronic Navigational Chart:  
CA276271, CA576095

#### 13-JUL-2007

LNМ/D. 29-JUN-2007



**Chart no. 4367**

Delete WHIS against red and white fairway lighted pillar  
whistle buoy Mo(A), marked SA

46°18'24.2"N 060°07'50.6"W

(G2007037) LL(776) DFO(6303451-01)

**29-JUN-2007**

LNМ/D. 18-NOV-2005

Delete BELL against red starboard hand lighted pillar bell  
buoy FlR, marked S2

46°16'26.0"N 060°11'29.0"W

(G2007038) LL(789) DFO(6303452-01)

This notice affects Electronic Navigational Chart:  
CA576095

**29-JUN-2007**

LNМ/D. 18-NOV-2005

Delete BELL against red and white fairway lighted pillar  
bell buoy Mo(A), marked SC

46°14'37.5"N 060°11'21.0"W

(G2007039) LL(777) DFO(6303453-01)

This notice affects Electronic Navigational Chart:  
CA576095

**18-NOV-2005**

LNМ/D. 29-JUL-2005

Delete green port hand lighted spar buoy FlG, marked KQ7 46°13'43.2"N 060°02'28.2"W

DFO(6302552-01)

**18-NOV-2005**

LNМ/D. 29-JUL-2005

Add legend "Channel Buoyed/Chenal balisé" 46°13'30.0"N 060°01'12.0"W

DFO(6302552-02)

**29-JUL-2005**

LNМ/D. 07-JAN-2005

Add red starboard hand lighted spar buoy FlR, marked  
KQ2

46°13'45.0"N 060°02'02.4"W

(G2005037) LL(774.4) DFO(6302353-01)

**29-JUL-2005**

LNМ/D. 07-JAN-2005

Add green port hand lighted spar buoy FlG, marked KQ7

46°13'43.2"N 060°02'28.2"W

(G2005039) LL(774.5) DFO(6302354-01)



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4367

**29-JUL-2005**

LNM/D. 07-JAN-2005

Amend "Fl 6s 36m 17M" to read "LFl 6s 26m 13M" against light 46°18'18.8"N 060°23'29.8"W

*LL(799) DFO(6302372-01)*

**07-JAN-2005**

LNM/D. 31-DEC-2004

Amend "Fl(2) 25s 70ft 16M" to read "Fl(2) 25s 74ft 10M"  
against light

46°10'51.0"N 059°46'13.2"W

*(G2004198) LL(770) DFO(6302126-01)*

**31-DEC-2004**

LNM/D. 05-NOV-2004

Amend "Fl 6s 75ft 17M" to read "LFl 6s 85ft 13M" against  
light

46°18'18.8"N 060°23'29.8"W

*(G2004199) LL(799) DFO(6302127-01)*

**05-NOV-2004**

LNM/D. 30-APR-2004

Delete legend "Fog Sig" against light

46°12'20.7"N 060°13'07.1"W

*(G2004159) LL(778) DFO(6301940-01)*

**30-APR-2004**

LNM/D. 05-MAR-2004

Amend "FG" to read "FIG" against light

46°12'20.7"N 060°13'07.1"W

*(G2004040) LL(778) DFO(6301295-01)*

**05-MAR-2004**

Add light QR

46°41'15.2"N 060°21'35.0"W

*(G2003155) LL(849.4) DFO(6301188-01)*

**05-MAR-2004**

Delete light FLR

46°41'16.4"N 060°21'25.7"W

*(G2003157) LL(849.2) DFO(6301189-01)*