



Chart no. 4374

4374 - Red Point to / à Guyon Island - New Edition - 08-NOV-2002 - NAD 1983

02-APR-2021

LNМ/D. 23-OCT-2020

Delete depth of 4 fathoms, 4 feet 45°44'42.7"N 060°11'22.8"W
(See Chart No. 1, I10)

DFO(6309337-01)

02-APR-2021

LNМ/D. 23-OCT-2020

Add depth of 1 fathom, 4 feet
(See Chart No. 1, I10)

45°44'33.4"N 060°12'16.0"W

This notice affects Electronic Navigational Chart: CA376295

DFO(6309337-02)

02-APR-2021

LNМ/D. 23-OCT-2020

Add depth of 1 fathom, 5 feet 45°44'44.0"N 060°11'32.2"W
(See Chart No. 1, I10)

DFO(6309337-03)

02-APR-2021

LNМ/D. 23-OCT-2020

Delete depth of 2 fathoms
(See Chart No. 1, I10)

45°44'33.8"N 060°12'13.4"W

This notice affects Electronic Navigational Chart: CA376295

DFO(6309337-04)

23-OCT-2020

LNМ/D. 07-AUG-2020

Amend Fl 21s53ft17M to read Fl 21s42ft17M against light
(See Chart No. 1, P16)

45°46'00.5"N 060°06'46.4"W

This notice affects Electronic Navigational Chart:
CA179245, CA276204, CA376295

(G2020176) LL(750) DFO(6309205-01)

07-AUG-2020

LNМ/D. 10-MAR-2017

Amend Fl 20s53ft17M to read Fl 21s53ft17M against light
(See Chart No. 1, P16)

45°46'00.0"N 060°06'46.4"W

This notice affects Electronic Navigational Chart:
CA276204, CA376295

(G2020067) LL(750) DFO(6309032-01)

10-MAR-2017

LNМ/D. 26-AUG-2016

Delete legend FogSig against light
(See Chart No. 1, R20)

45°43'02.8"N 060°13'46.4"W

This notice affects Electronic Navigational Chart:
CA179245, CA376295

(G2016140) LL(747) DFO(6307757-01)



Chart no. 4374

26-AUG-2016

LNМ/D. 22-JUL-2016

Delete fog signal Fog Sig 60 s against light
(See Chart No. 1, R1, R20)

45°46'00.0"N 060°06'46.0"W

This notice affects Electronic Navigational Chart: (G2016117) LL(750) DFO(6307659-01)
CA179245, CA276204, CA376295

22-JUL-2016

LNМ/D. 12-FEB-2016

Amend NH6 to read NH4 against buoy
(See Chart No 1 Q130.1)

45°37'15.5"N 060°34'24.8"W

This notice affects Electronic Navigational Chart: (G2016084) LL(741.03) DFO(6307609-01)
CA376295

22-JUL-2016

LNМ/D. 12-FEB-2016

Amend NH8 to read NH6 against buoy
(See Chart No 1 Q130.1)

45°37'17.5"N 060°34'30.8"W

(G2016085) DFO(6307609-02)

This notice affects Electronic Navigational Chart: CA376295

22-JUL-2016

LNМ/D. 12-FEB-2016

Add red and white fairway lighted spar buoy Mo(A), marked
NH

45°36'57.1"N 060°34'01.0"W

(See Chart No. 1, Qh)

(G2016086) LL(741) DFO(6307609-03)

This notice affects Electronic Navigational Chart:
CA376295

22-JUL-2016

LNМ/D. 12-FEB-2016

Add red starboard hand lighted spar buoy QR, marked
NH8

45°37'21.9"N 060°34'36.8"W

(See Chart No. 1, Qf)

(Q2016087) LL(741.04) DFO(6307609-04)

This notice affects Electronic Navigational Chart:
CA376295

22-JUL-2016

LNМ/D. 12-FEB-2016

Add green port hand spar buoy, marked NH7
(See Chart No. 1, Qg)

45°37'19.0"N 060°34'35.9"W

This notice affects Electronic Navigational Chart: CA376295 (G2016088) DFO(6307609-05)

12-FEB-2016

LNМ/D. 05-FEB-2016



Chart no. 4374

Amend LFl 12s to read LFl 6s against light 45°37'19.2"N 060°29'17.6"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2015163) LL(743) DFO(6307407-01)
CA276204, CA376295

05-FEB-2016 LNM/D. 27-NOV-2015
Amend Fl20s 53ft 18M to read Fl20s 53ft 17M against light 45°46'00.0"N 060°06'46.5"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276204, LL(750) DFO(6307366-06)
CA376295

27-NOV-2015 LNM/D. 30-JAN-2015
Delete front range/leading light FY 10ft 45°43'08.0"N 060°14'43.0"W
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart: (G2015137) LL(748) DFO(6307307-01)
CA376295

27-NOV-2015 LNM/D. 30-JAN-2015
Delete rear range/leading light FY 27ft with leading line 45°43'06.0"N 060°14'52.0"W
and bearing 255°
(See Chart No. 1, P20.2) (G2015138) LL(749) DFO(6307307-02)
This notice affects Electronic Navigational Chart:
CA376295

30-JAN-2015 LNM/D. 20-DEC-2013
Amend F to read LFl against light 45°43'02.8"N 060°13'46.4"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2014197) LL(747) DFO(6306995-01)
CA276204, CA376295

20-DEC-2013 LNM/D. 26-AUG-2011
Add overhead power cable with vertical clearance of 23 feet between 45°43'01.4"N 060°14'17.7"W
(See Chart No. 1, D20 and D26) and 45°43'04.2"N 060°14'02.4"W
This notice affects Electronic Navigational Chart:
CA376295 DFO(6306527-01)

26-AUG-2011 LNM/D. 18-MAR-2011



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4374

Add wreck with legend Rep(2011)
(See Chart No. 1, K29)

45°23'00.6"N 060°45'30.0"W

DFO(6305673-01)

This notice affects Electronic Navigational Chart: CA376295

18-MAR-2011

Delete depth of 1 fathom
(See Chart No. 1, I10)

LNМ/D. 12-JUN-2009

45°43'04.4"N 060°14'45.0"W

DFO(6305289-01)

This notice affects Electronic Navigational Chart: CA376295

18-MAR-2011

Add depth of 0 fathoms, 2 feet 45°43'03.7"N 060°14'43.4"W
(See Chart No. 1, I10)

LNМ/D. 12-JUN-2009

DFO(6305289-02)

18-MAR-2011

Delete depth of 1 fathom 45°43'15.1"N 060°14'07.6"W
(See Chart No. 1, I10)

LNМ/D. 12-JUN-2009

DFO(6305289-03)

18-MAR-2011

Add depth of 0 fathoms, 3 feet 45°43'16.2"N 060°14'05.2"W
(See Chart No. 1, I10)

LNМ/D. 12-JUN-2009

DFO(6305289-04)

18-MAR-2011

Delete depth of 1 fathom, 5 feet 45°43'19.5"N 060°13'49.3"W
(See Chart No. 1, I10)

LNМ/D. 12-JUN-2009

DFO(6305289-05)

18-MAR-2011

Add depth of 1 fathom, 2 feet 45°43'18.6"N 060°13'50.9"W
(See Chart No. 1, I10)

LNМ/D. 12-JUN-2009

DFO(6305289-06)

18-MAR-2011

LNМ/D. 12-JUN-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4374

Add depth of 0 fathoms, 2 feet 45°43'11.2"N 060°13'24.9"W
(See Chart No. 1, I10)

DFO(6305289-07)

18-MAR-2011

LNM/D. 12-JUN-2009

Delete depth of 1 fathom, 3 feet 45°43'10.5"N 060°12'57.5"W
(See Chart No. 1, I10)

DFO(6305289-08)

18-MAR-2011

LNM/D. 12-JUN-2009

Add depth of 0 fathoms, 4 feet 45°43'11.0"N 060°13'01.4"W
(See Chart No. 1, I10)

DFO(6305289-09)

12-JUN-2009

LNM/D. 07-NOV-2008

Delete depth of 1 fathom, 1 foot
(See Chart No. 1, I10)

45°37'11.4"N 060°34'31.6"W

DFO(6304407-01)

This notice affects Electronic Navigational Chart: CA376295

12-JUN-2009

LNM/D. 07-NOV-2008

Add drying height of 0 fathom, 1 foot
(See Chart No. 1, I15)

45°37'11.2"N 060°34'26.3"W

DFO(6304407-02)

This notice affects Electronic Navigational Chart: CA376295

07-NOV-2008

LNM/D. 31-OCT-2008

Reposition green port hand lighted spar buoy FIG,
marked NH3
(See Chart No 1 Qg)

from 45°36'54.2"N 060°34'03.6"W
to 45°37'12.1"N 060°34'21.4"W

(G2008049) LL(741.01) DFO(6304066-01)

07-NOV-2008

LNM/D. 31-OCT-2008

Reposition green port hand spar buoy, marked NH5 from 45°37'02.7"N 060°34'17.6"W
(See Chart No 1 Qg) to 45°37'15.3"N 060°34'29.8"W

(G2008050) DFO(6304067-01)



Chart no. 4374

07-NOV-2008

Reposition red starboard hand lighted spar buoy FlR,
marked NH6
(See Chart No 1 Qf)

LNМ/D. 31-OCT-2008

from 45°37'08.2"N 060°34'15.6"W
to 45°37'15.5"N 060°34'24.8"W

(G2008051) LL(741.03) DFO(6304068-01)

07-NOV-2008

Reposition red starboard hand spar buoy, marked NH8 from 45°37'15.7"N 060°34'24.6"W
(See Chart No 1 Qf)

LNМ/D. 31-OCT-2008

to 45°37'17.5"N 060°34'30.8"W

(G2008052) DFO(6304069-01)

07-NOV-2008

Reposition red starboard hand lighted spar buoy QR,
marked NH10
(See Chart No 1 Qf)

LNМ/D. 31-OCT-2008

from 45°37'17.8"N 060°34'29.3"W
to 45°37'27.6"N 060°34'32.2"W

(G2008053) LL(741.05) DFO(6304070-01)

31-OCT-2008

Amend Fl to read LFl 12s against light
(See Chart No 1 P16)

LNМ/D. 22-DEC-2006

45°37'19.2"N 060°29'17.6"W

LL(743) DFO(6304039-01)

This notice affects Electronic Navigational Chart: CA179172

22-DEC-2006

LNМ/D. 16-SEP-2005

Add rock awash 45°41'15.3"N 060°19'35.9"W

DFO(6303214-01)

16-SEP-2005

Delete legend "WHIS" against red starboard pillar light and
whistle buoy Fl R, WHIS, marked N16

LNМ/D. 15-APR-2005

45°35'12.2"N 060°30'25.6"W

(G2005077) LL(742) DFO(6302432-01)

15-APR-2005

LNМ/D. 25-MAR-2005

Add light flash against buoy marked NHA 45°35'24.9"N 060°34'48.2"W

LL(739) DFO(6302246-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4374

25-MAR-2005

Delete green port hand pillar light and bell buoy FlG, BELL
marked NH1

LNM/D. 15-OCT-2004

45°36'38.2"N 060°33'36.6"W

(G2005003) LL(741) DFO(6302245-01)

15-OCT-2004

Replace red starboard hand spar buoy, marked NH10
with red starboard hand spar light buoy QR,
marked NH10

LNM/D. 18-JUN-2004

45°37'17.8"N 060°34'29.3"W

(G2004143) LL(741.05) DFO(6301855-01)

15-OCT-2004

Add yellow and black, South cardinal spar light buoy
Q(6)+LFl 15s, marked NHA

LNM/D. 18-JUN-2004

45°35'24.9"N 060°34'48.2"W

(G2004144) LL(739) DFO(6301856-01)

15-OCT-2004

Replace red starboard hand spar buoy, marked NH6
with red starboard hand spar light buoy FlR,
marked NH6

LNM/D. 18-JUN-2004

45°37'08.2"N 060°34'15.6"W

(G2004146) LL(741.03) DFO(6301857-01)

15-OCT-2004

Replace green port hand spar buoy, marked NH3 with
green port hand spar light buoy FlG, marked
NH3

LNM/D. 18-JUN-2004

45°36'54.2"N 060°34'03.6"W

(G2004147) LL(741.01) DFO(6301866-01)

18-JUN-2004

Delete red and white fairway pillar light and whistle buoy
Mo(A), WHIS, marked CA

LNM/D. 23-JAN-2004

45°23'53.5"N 060°41'38.2"W

(G2004064) LL(686) DFO(6301440-01)

23-JAN-2004

Delete red, starboard hand spar buoy, marked NM2 45°35'02.2"N 060°44'42.4"W

LNM/D. 26-DEC-2003

DFO(6301124-03)

26-DEC-2003

LNM/D. 23-MAY-2003



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4374

Add red, starboard hand spar buoy, marked NH10 45°37'17.8"N 060°34'29.3"W

(G2003126) DFO(6301127-01)

26-DEC-2003

LNМ/D. 23-MAY-2003

Add red, starboard hand spar buoy, marked NH8 45°37'15.7"N 060°34'24.6"W

(G2003127) DFO(6301128-01)

23-MAY-2003

LNМ/D. 16-MAY-2003

Add rock which covers and uncovers with drying height of 5 feet 45°43'21.0"N 060°14'00.0"W

DFO(6300875-01)

16-MAY-2003

Delete fog signal 45°37'19.2"N 060°34'21.6"W

(G2003007) LL(740) DFO(6300820-01)