



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4375

4375 - Guyon Island to / à Flint Island - New Edition - 11-OCT-2002 - NAD 1983

13-SEP-2024

LNМ/D. 01-MAR-2024

Add green port hand can buoy, marked JM7 45°57'11.5"N 059°49'56.9"W
(See Chart 1, Qc)

LL(5762.05) DFO(6311467-01)

01-MAR-2024

LNМ/D. 16-DEC-2022

Delete subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 23 fathoms
(See Chart 1, L25)

45°58'31.8"N 059°25'20.0"W

DFO(6311005-04)

This notice affects Electronic Navigational Chart: CA376303

16-DEC-2022

LNМ/D. 07-JAN-2022

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 23 fathoms
(See Chart 1, L25)

45°58'31.6"N 059°25'20.4"W

DFO(6310470-03)

This notice affects Electronic Navigational Chart: CA376303

07-JAN-2022

LNМ/D. 26-FEB-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 45 fathoms (See Chart No. 1, L25)

45°59'15.6"N 059°20'00.6"W

This notice affects Electronic Navigational Chart: CA376303

DFO(6309784-06)

07-JAN-2022

LNМ/D. 26-FEB-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 46 fathoms (See Chart No. 1, L25)

45°59'15.7"N 059°19'14.5"W

This notice affects Electronic Navigational Chart: CA376303

DFO(6309784-07)

07-JAN-2022

LNМ/D. 26-FEB-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 44 fathoms (See Chart No. 1, L25)

45°59'15.8"N 059°18'26.3"W

This notice affects Electronic Navigational Chart: CA376303

DFO(6309784-08)

07-JAN-2022

LNМ/D. 26-FEB-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 51 fathoms (See Chart No. 1, L25)

45°59'15.9"N 059°17'38.4"W

This notice affects Electronic Navigational Chart: CA376303

DFO(6309784-09)



Chart no. 4375

07-JAN-2022

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 40 fathoms (See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA376303

LNМ/D. 26-FEB-2021
45°59'16.0"N 059°16'46.9"W
DFO(6309784-10)

07-JAN-2022

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 37 fathoms (See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA376303

LNМ/D. 26-FEB-2021
45°59'16.1"N 059°16'00.5"W
DFO(6309784-11)

07-JAN-2022

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 32 fathoms (See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA376303

LNМ/D. 26-FEB-2021
45°59'16.2"N 059°15'12.6"W
DFO(6309784-12)

26-FEB-2021

Delete depth of 5 fathoms, 1 foot
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376303

LNМ/D. 30-OCT-2020
45°50'39.8"N 060°08'28.6"W
DFO(6309296-01)

26-FEB-2021

Add depth of 0 fathoms, 4 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376303

LNМ/D. 30-OCT-2020
45°50'42.0"N 060°08'33.2"W
DFO(6309296-02)

26-FEB-2021

Add depth of 1 fathom, 4 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376303

LNМ/D. 30-OCT-2020
45°50'42.7"N 060°09'01.0"W
DFO(6309296-03)

26-FEB-2021

Add depth of 1 fathom, 1 foot
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376303

LNМ/D. 30-OCT-2020
45°52'10.3"N 060°01'34.4"W
DFO(6309296-04)

26-FEB-2021

LNМ/D. 30-OCT-2020



Chart no. 4375

Add depth of 3 fathoms, 5 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376303	45°52'14.0"N 060°00'46.6"W <i>DFO(6309296-05)</i>
26-FEB-2021 Add depth of 0 fathoms, 4 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376303	LNM/D. 30-OCT-2020 45°52'29.3"N 060°00'36.5"W <i>DFO(6309296-06)</i>
26-FEB-2021 Replace depth of 7 fathoms with depth of 1 fathom (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376303	LNM/D. 30-OCT-2020 45°52'19.7"N 059°59'29.9"W <i>DFO(6309296-07)</i>
26-FEB-2021 Replace depth of 1 fathom, 5 feet with depth of 1 fathom, 1 foot (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376303	LNM/D. 30-OCT-2020 45°57'02.4"N 059°51'32.0"W <i>DFO(6309296-08)</i>
26-FEB-2021 Add depth of 2 fathoms, 4 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376303	LNM/D. 30-OCT-2020 45°56'33.0"N 059°50'23.6"W <i>DFO(6309296-09)</i>
26-FEB-2021 Delete depth of 5 fathoms, 3 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376303	LNM/D. 30-OCT-2020 45°56'22.0"N 059°48'57.0"W <i>DFO(6309296-10)</i>
26-FEB-2021 Add depth of 4 fathoms, 4 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376303	LNM/D. 30-OCT-2020 45°56'19.9"N 059°48'54.5"W <i>DFO(6309296-11)</i>
26-FEB-2021 Add depth of 1 fathom, 3 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376303	LNM/D. 30-OCT-2020 45°56'31.3"N 059°47'20.3"W <i>DFO(6309296-12)</i>



Chart no. 4375

26-FEB-2021

LNМ/D. 30-OCT-2020

Delete depth of 8 fathoms, 4 feet
(See Chart No. 1, I10)

45°59'32.1"N 059°42'36.4"W

This notice affects Electronic Navigational Chart: CA376303

DFO(6309296-13)

26-FEB-2021

LNМ/D. 30-OCT-2020

Add depth of 0 fathoms, 5 feet
(See Chart No. 1, I10)

45°59'30.7"N 059°42'30.2"W

This notice affects Electronic Navigational Chart: CA376303

DFO(6309296-14)

30-OCT-2020

LNМ/D. 23-OCT-2020

Delete depth of 5 fathoms
(See Chart No. 1, I10)

45°56'47.0"N 059°47'47.6"W

This notice affects Electronic Navigational Chart: CA376303

DFO(6309194-02)

30-OCT-2020

LNМ/D. 23-OCT-2020

Add depth of 1 fathom, 1 foot
(See Chart No. 1, I10)

45°56'48.2"N 059°47'43.9"W

This notice affects Electronic Navigational Chart: CA376303

DFO(6309194-03)

23-OCT-2020

LNМ/D. 07-AUG-2020

Amend Fl 21s53ft17M to read Fl 21s42ft17M against light
(See Chart No. 1, P16)

45°46'00.5"N 060°06'46.4"W

This notice affects Electronic Navigational Chart:
CA179245, CA276204, CA376295

(G2020176) LL(750) DFO(6309205-01)

07-AUG-2020

LNМ/D. 21-DEC-2018

Amend Fl 20s53ft17M to read Fl 21s53ft17M against light
(See Chart No. 1, P16)

45°46'00.5"N 060°06'46.4"W

This notice affects Electronic Navigational Chart:
CA276204, CA376295

(G2020067) LL(750) DFO(6309032-01)

21-DEC-2018

LNМ/D. 11-AUG-2017

Delete light FRG
(See Chart No. 1, P1)

46°02'11.0"N 059°58'07.0"W

This notice affects Electronic Navigational Chart:
CA376303

(G2018144) LL(767.6) DFO(6308521-01)

11-AUG-2017

LNМ/D. 31-MAR-2017



Chart no. 4375

Add environmentally sensitive sea area with legend, St Anns Bank Marine Protected Area / Zone de protection marine du banc de Sainte-Anne (See Chart No. 1, N22)
 This notice affects Electronic Navigational Chart: CA179245, CA276090, CA276204, CA276271, CA276284, CA376303

joining 45°50'43.0"N 059°14'37.0"W
 45°47'00.0"N 059°39'00.0"W
 46°10'00.0"N 059°39'00.0"W
 46°10'00.0"N 059°20'00.0"W
 and 46°11'23.5"N 059°20'00.0"W

DFO(6308006-01)

31-MAR-2017 LNM/D. 25-NOV-2016
 Delete legend Fog Sig 20s against light (See Chart No. 1, R1, R20)
 This notice affects Electronic Navigational Chart: CA179245, CA276204, CA376303 *(G2016158) LL(756) DFO(6307823-01)*

25-NOV-2016 LNM/D. 26-AUG-2016
 Amend Fl 15s64ft13M to read Fl 3s64ft13M against light (See Chart No. 1, P16)
 This notice affects Electronic Navigational Chart: CA276271, CA376303 *(G2016124) LL(767) DFO(6307705-01)*

25-NOV-2016 LNM/D. 26-AUG-2016
 Delete legend Fog Sig (3) 60 s against light (See Chart No. 1, R1, R20)
 This notice affects Electronic Navigational Chart: CA179245, CA276271, CA376303 *DFO(6307705-02)*

26-AUG-2016 LNM/D. 22-JUL-2016
 Delete fog signal Fog Sig 60 s against light (See Chart No. 1, R1, R20)
 This notice affects Electronic Navigational Chart: CA179245, CA276204, CA376295 *(G2016117) LL(750) DFO(6307659-01)*

22-JUL-2016 LNM/D. 17-JUN-2016
 Replace red starboard hand lighted pillar bell buoy FIR, BELL, marked JA2 with red starboard hand lighted spar buoy FIR, marked JA2 (See Chart No. 1, Qf)
 This notice affects Electronic Navigational Chart: CA376303 *(G2016081) LL(769) DFO(6307606-01)*



Chart no. 4375

17-JUN-2016

LNМ/D. 04-MAR-2016

Replace light Fl 10s 105ft 16M with all-round
light LFl 6s 105ft 13M with obscured
sector. Obscured through an arc of
210°, from 250° to 100°
(See Chart No. 1, P43)
This notice affects Electronic
Navigational Chart: CA376303

45°54'24.0"N 059°57'30.4"W

(G2016037 & G2016052) LL(756) DFO(6307520-02)

04-MAR-2016

LNМ/D. 12-FEB-2016

Amend Fl 3s 64ft 15M to read Fl 15s 64ft 13M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA179245, CA276271, CA376303

46°02'03.0"N 059°40'33.5"W

(G2015157) LL(767) DFO(6307448-01)

12-FEB-2016

LNМ/D. 05-FEB-2016

Amend F 12M to read LFl 12M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart:
CA376303

46°00'25.4"N 059°49'21.7"W

(G2015162) LL(765.4) DFO(6307409-01)

05-FEB-2016

LNМ/D. 27-NOV-2015

Amend Fl20s 53ft 15M to read Fl20s 53ft 17M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276204,
CA376295

45°46'00.0"N 060°06'46.5"W

LL(750) DFO(6307366-06)

27-NOV-2015

LNМ/D. 29-MAY-2015

Amend Fog Sig 20s to read (Occas) Fog Sig 20s against
light
(See Chart No. 1, P50)
This notice affects Electronic Navigational Chart:
CA376303

45°56'55.7"N 059°51'31.7"W

(G2015149) LL(761) DFO(6307331-01)

27-NOV-2015

LNМ/D. 29-MAY-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 34 fathoms
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276271,
CA376303

46°07'47.6"N 059°19'49.7"W

DFO(6307340-02)



Chart no. 4375

29-MAY-2015

LNМ/D. 27-FEB-2015

Amend "FY to read LFLY against light
(See Chart No. 1, P16)"

45°50'35.6"N 060°07'56.8"W

This notice affects Electronic Navigational Chart: (G2015024) LL(752.6) DFO(6307118-01)
CA376303

27-FEB-2015

LNМ/D. 06-FEB-2015

Delete light FR

46°07'51.8"N 059°52'09.6"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (G2014205) LL(768) DFO(6307014-01)
CA376303

27-FEB-2015

LNМ/D. 06-FEB-2015

Add light FLR

46°07'50.8"N 059°52'13.2"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (G2014205) LL(768) DFO(6307014-02)
CA376303

06-FEB-2015

LNМ/D. 09-JAN-2015

Amend Fl(2)25s74ft10m to read LFl74ft8M against light
(See Chart No. 1, P16)

46°10'51.0"N 059°46'13.2"W

This notice affects Electronic Navigational Chart: (G2014202) LL(770) DFO(6307010-01)
CA179172, CA276271, CA376093

06-FEB-2015

LNМ/D. 09-JAN-2015

Delete legend FogSig30s against light

46°10'51.0"N 059°46'13.2"W

(See Chart No. 1, R20)

This notice affects Electronic Navigational Chart: (G2014213) LL(770) DFO(6307010-02)
CA276271, CA376093

09-JAN-2015

LNМ/D. 14-JUN-2013

Replace red starboard hand lighted pillar buoy FLR,
marked JA6 with red starboard hand lighted spar
buoy QR, marked JA6
(See Chart No. 1, Qf)

46°07'41.3"N 059°52'03.7"W

(G2014191) LL(768.5) DFO(6306990-01)

This notice affects Electronic Navigational Chart:
CA376303

14-JUN-2013

LNМ/D. 15-FEB-2013



Chart no. 4375

Reposition green port hand lighted pillar bell buoy FlG,
marked JJ3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational
Chart: CA376303

from 45°59'00.1"N 059°46'58.2"W
to 45°59'10.4"N 059°46'50.2"W

(G2013020) LL(764) DFO(6306372-01)

15-FEB-2013

Delete FogSig against light
(See Chart No 1, R1)

This notice affects Electronic Navigational Chart:
CA376303

LN/D. 06-MAY-2011

45°50'35.0"N 060°07'54.8"W

(G2013001) LL(752.6) DFO(6306320-01)

06-MAY-2011

Amend Fl 15s 64ft 17M to read Fl 3s 64ft 15M against light
(See Chart No 1 P16)

This notice affects Electronic Navigational Chart:
CA179172

LN/D. 11-FEB-2011

46°02'04.3"N 059°40'33.7"W

(G2011058) LL(767) DFO(6305358-01)

11-FEB-2011

Amend Fl 30s 64ft 17M to read Fl 15s 64ft 17M against
light
(See Chart No. 1 P16)

This notice affects Electronic Navigational Chart: CA376303

LN/D. 27-AUG-2010

46°02'04.3"N 059°40'33.7"W

(G2010239) LL(767) DFO(6305189-01)

27-AUG-2010

Amend Fl 30s 64ft 23M to read Fl 30s 64ft 17M against light
(See Chart No. 1 P16)

This notice affects Electronic Navigational Chart: CA376303

LN/D. 02-APR-2010

46°02'04.3"N 059°40'33.7"W

LL(767) DFO(6304986-01)

27-AUG-2010

Amend F to read F 12M against light
(See Chart No. 1 P16)

This notice affects Electronic Navigational Chart: CA376303

LN/D. 02-APR-2010

46°00'25.4"N 059°49'21.7"W

LL(765.4) DFO(6304986-02)

02-APR-2010

LN/D. 11-DEC-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4375

Add depth of 10 fathoms
(See Chart No. 1, I10)

45°59'39.7"N 059°45'08.3"W

DFO(6304704-06)

This notice affects Electronic Navigational Chart: CA376303

02-APR-2010

LNМ/D. 11-DEC-2009

Add dangerous underwater rock of unknown depth with legend Rep
(2010)
(See Chart No 1 K13 and I3.2)

46°01'38.0"N 059°40'49.2"W

DFO(6304759-01)

This notice affects Electronic Navigational Chart: CA376303

11-DEC-2009

LNМ/D. 15-AUG-2008

Amend Fl 9s 105ft 17M to read Fl 10s 105ft 16M against light
(See Chart No 1 P16)

45°54'24.0"N 059°57'30.4"W

LL(756) DFO(6304648-01)

This notice affects Electronic Navigational Chart: CA179172

15-AUG-2008

LNМ/D. 07-JAN-2005

Delete dangerous underwater rock of 6ft or less, PA, Rep 2004
(See Chart No 1 K13)

45°59'40.0"N 059°45'30.0"W

DFO(6303879-01)

07-JAN-2005

LNМ/D. 29-OCT-2004

Amend "Fl(2) 25s 70ft 16M" to read "Fl(2) 25s 74ft 10M"
against light

46°10'48.9"N 059°46'13.2"W

(G2004198) LL(770) DFO(6302126-01)

29-OCT-2004

Add dangerous underwater rock of 6ft or less, Rep 2004

DFO(6301993-01)