



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4385

4385 - Chebucto Head to / à Betty Island - New Edition - 07-JUN-1996 - NAD 1983

25-NOV-2022

LNМ/D. 01-JAN-2021

Delete legend Fog Sig (2) 60 s against light
(See Chart No 1 R20)

44°30'26.9"N 063°31'21.8"W

This notice affects Electronic Navigational Chart: (F2022018) LL(513) DFO(6310357-01)
CA276801, CA476009

25-NOV-2022

LNМ/D. 01-JAN-2021

Replace depth of 3 fathoms with depth of 0 fathoms, 4 feet
(See Chart 1, I10)

44°26'50.5"N 063°43'16.2"W

This notice affects Electronic Navigational Chart: CA476189 DFO(6310443-01)

25-NOV-2022

LNМ/D. 01-JAN-2021

Add depth of 0 fathoms, 1 foot
(See Chart 1, I10)

44°26'50.5"N 063°43'08.2"W

This notice affects Electronic Navigational Chart: CA476189 DFO(6310443-02)

01-JAN-2021

LNМ/D. 10-JAN-2020

Amend Fl 15s63ft13M to read LFl 6s63ft13M
(See Chart No. 1, P16)

44°26'19.7"N 063°46'00.4"W

This notice affects Electronic Navigational Chart: (F2020049) LL(495) DFO(6309314-01)
CA276801, CA476195

10-JAN-2020

LNМ/D. 01-MAR-2019

Replace depth of 4 fathoms 2 feet with depth of 3 fathoms 5 feet
(See Chart No. 1, I10)

44°25'33.3"N 063°37'14.0"W

This notice affects Electronic Navigational Chart: CA476009 DFO(6308832-01)

10-JAN-2020

LNМ/D. 01-MAR-2019

Replace depth of 6 fathoms, 1 foot with depth of 4 fathoms, 5 feet
(See Chart No. 1, I10)

44°25'44.7"N 063°37'27.5"W

This notice affects Electronic Navigational Chart: CA476009 DFO(6308832-02)

10-JAN-2020

LNМ/D. 01-MAR-2019

Add depth of 2 fathoms, 2 feet
(See Chart No. 1, I10)

44°25'40.0"N 063°37'44.2"W

This notice affects Electronic Navigational Chart: CA476009 DFO(6308832-03)



Chart no. 4385

- 10-JAN-2020** LNM/D. 01-MAR-2019
Replace depth of 5 fathoms, 5 feet with depth of 4 fathoms, 1 foot 44°25'55.6"N 063°37'55.0"W
(See Chart No. 1, I10)
DFO(6308832-05)
- 10-JAN-2020** LNM/D. 01-MAR-2019
Add depth of 4 fathoms, 1 foot 44°26'02.5"N 063°37'52.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476009 *DFO(6308832-06)*
- 10-JAN-2020** LNM/D. 01-MAR-2019
Add depth of 1 fathom, 4 feet 44°26'08.4"N 063°36'45.5"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476009 *DFO(6308832-07)*
- 10-JAN-2020** LNM/D. 01-MAR-2019
Add depth of 1 fathom, 5 feet 44°26'51.5"N 063°44'34.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-01)*
- 10-JAN-2020** LNM/D. 01-MAR-2019
Reposition drying height of 6 feet from 44°27'32.6"N 063°45'23.1"W
(See Chart No. 1, Ia) to 44°27'35.6"N 063°45'22.8"W
This notice affects Electronic Navigational Chart:
CA476189 *DFO(6308833-02)*
- 10-JAN-2020** LNM/D. 01-MAR-2019
Add depth of 3 fathoms, 4 feet 44°27'32.7"N 063°45'23.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-03)*
- 10-JAN-2020** LNM/D. 01-MAR-2019
Add depth of 2 fathoms 44°27'56.4"N 063°45'10.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-04)*
- 10-JAN-2020** LNM/D. 01-MAR-2019



Chart no. 4385

Add depth of 2 fathoms, 4 feet 44°27'34.0"N 063°44'02.3"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-05)*

10-JAN-2020 LNM/D. 01-MAR-2019
Delete depth of 20 fathoms 44°26'51.6"N 063°44'41.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-06)*

10-JAN-2020 LNM/D. 01-MAR-2019
Add depth of 4 fathoms 44°26'52.6"N 063°44'39.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-07)*

10-JAN-2020 LNM/D. 01-MAR-2019
Delete depth of 8 fathoms, 3 feet 44°26'44.0"N 063°46'54.9"W
(See Chart No. 1, I10)
DFO(6308836-02)

10-JAN-2020 LNM/D. 01-MAR-2019
Add depth of 3 fathoms, 5 feet 44°26'45.9"N 063°46'53.6"W
(See Chart No. 1, I10)
DFO(6308836-03)

10-JAN-2020 LNM/D. 01-MAR-2019
Add depth of 3 fathoms, 1 foot 44°28'14.5"N 063°46'27.0"W
(See Chart No. 1, I10)
DFO(6308836-04)

10-JAN-2020 LNM/D. 01-MAR-2019
Add depth of 1 fathom, 1 foot 44°28'46.1"N 063°46'05.0"W
(See Chart No. 1, I10)
DFO(6308836-05)

10-JAN-2020 LNM/D. 01-MAR-2019
Add depth of 4 fathoms, 2 feet 44°27'36.6"N 063°46'11.8"W
(See Chart No. 1, I10)
DFO(6308836-06)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4385

01-MAR-2019

LNM/D. 13-JUL-2018

Amend F R 48 ft 6 M to read LFl 6s8M against light

44°27'36.6"N 063°42'20.4"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA476189

(F2019001) LL(498) DFO(6308559-01)

13-JUL-2018

LNM/D. 16-DEC-2016

Add depth of 2 fathoms, 3 feet 44°26'34.5"N 063°31'34.0"W

(See Chart No. 1, I10)

DFO(6307791-01)

13-JUL-2018

LNM/D. 16-DEC-2016

Delete depth of 3 fathoms, 5 feet 44°27'24.8"N 063°32'52.8"W

(See Chart No. 1, I10)

DFO(6307791-02)

13-JUL-2018

LNM/D. 16-DEC-2016

Add depth of 2 fathoms, 4 feet 44°27'23.1"N 063°32'55.7"W

(See Chart No. 1, I10)

DFO(6307791-03)

13-JUL-2018

LNM/D. 16-DEC-2016

Replace depth of 4 fathoms, 4 feet with depth of 2 fathoms, 5 feet 44°26'50.8"N 063°32'40.9"W

(See Chart No. 1, I10)

DFO(6307791-04)

13-JUL-2018

LNM/D. 16-DEC-2016

Replace depth of 5 fathoms, 5 feet with depth of 4 fathoms, 4 feet 44°26'43.4"N 063°32'16.9"W

(See Chart No. 1, I10)

DFO(6307791-05)

13-JUL-2018

LNM/D. 16-DEC-2016

Replace depth of 4 fathoms with depth of 3 fathoms, 1 foot 44°26'43.2"N 063°32'26.2"W

(See Chart No. 1, I10)

DFO(6307791-06)

13-JUL-2018

LNM/D. 16-DEC-2016



Chart no. 4385

Replace depth of 5 fathoms, 2 feet with depth of 2 fathoms, 5 feet 44°25'59.7"N 063°32'42.6"W
(See Chart No. 1, I10)

DFO(6307791-07)

13-JUL-2018

LNM/D. 16-DEC-2016

Delete depth of 4 fathoms, 4 feet 44°26'32.8"N 063°31'35.3"W
(See Chart No. 1, I10)

DFO(6307791-08)

13-JUL-2018

LNM/D. 16-DEC-2016

Replace depth of 5 fathoms with depth of 3 fathoms, 4 feet 44°26'13.9"N 063°32'54.7"W
(See Chart No. 1, I10)

DFO(6307791-09)

13-JUL-2018

LNM/D. 16-DEC-2016

Add depth of 3 fathoms, 1 foot 44°25'39.7"N 063°37'35.1"W
(See Chart No. 1, I10)

DFO(6307791-10)

13-JUL-2018

LNM/D. 16-DEC-2016

Replace depth of 3 fathoms, 3 feet with depth of 2 fathoms, 4 feet 44°26'21.3"N 063°37'36.8"W
(See Chart No. 1, I10)

DFO(6307791-11)

13-JUL-2018

LNM/D. 16-DEC-2016

Replace depth of 6 fathoms, 5 feet with depth of 5 fathoms, 0 feet 44°27'30.9"N 063°32'45.4"W
(See Chart No. 1, I10)

DFO(6307791-12)

13-JUL-2018

LNM/D. 16-DEC-2016

Replace depth of 6 fathoms, 4 feet with depth of 4 fathoms, 4 feet 44°27'13.2"N 063°38'47.8"W
(See Chart No. 1, I10)

DFO(6307791-13)

13-JUL-2018

LNM/D. 16-DEC-2016

Replace depth of 2 fathoms, 1 foot with depth of 1 fathom, 3 feet 44°27'15.1"N 063°38'57.0"W
(See Chart No. 1, I10)

DFO(6307791-14)



Chart no. 4385

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 4 fathoms, 5 feet with depth of 1 fathom, 4 feet 44°27'44.9"N 063°39'00.4"W
(See Chart No. 1, I10)

DFO(6307791-15)

13-JUL-2018

LNМ/D. 16-DEC-2016

Add depth of 2 fathoms, 5 feet 44°25'52.8"N 063°38'05.8"W
(See Chart No. 1, I10)

DFO(6307791-16)

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 2 fathoms, 4 feet with depth of 1 fathom, 5 feet 44°27'55.4"N 063°41'00.9"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-01)

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 4 fathoms, 5 feet with depth of 3 fathoms, 3 feet 44°27'50.7"N 063°40'25.4"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-02)

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 7 fathoms, 4 feet with depth of 4 fathoms, 1 foot 44°28'04.5"N 063°41'22.6"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-03)

13-JUL-2018

LNМ/D. 16-DEC-2016

Add depth of 1 fathom, 4 feet 44°29'33.5"N 063°46'14.7"W
(See Chart No. 1, I10)

DFO(6307884-04)

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 3 fathoms, 4 feet with 2 fathoms, 0 feet 44°27'42.1"N 063°41'03.6"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-05)

13-JUL-2018

LNМ/D. 16-DEC-2016



Chart no. 4385

Replace depth of 6 fathoms, 3 feet with depth of 2 fathoms, 5 feet 44°26'34.9"N 063°42'00.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-06)*

13-JUL-2018 LNM/D. 16-DEC-2016
Replace depth of 8 fathoms, 5 feet with depth of 5 fathoms, 2 feet 44°26'47.8"N 063°42'05.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-07)*

13-JUL-2018 LNM/D. 16-DEC-2016
Replace depth of 6 fathoms with depth of 3 fathoms, 3 feet 44°27'03.3"N 063°42'17.3"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-08)*

13-JUL-2018 LNM/D. 16-DEC-2016
Replace depth of 2 fathoms, 2 feet with depth of 1 fathom, 2 feet 44°25'57.1"N 063°39'10.0"W
(See Chart No. 1, I10)
DFO(6307884-09)

13-JUL-2018 LNM/D. 16-DEC-2016
Add depth of 3 fathoms, 2 feet 44°27'09.4"N 063°42'24.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-10)*

13-JUL-2018 LNM/D. 16-DEC-2016
Delete depth of 4 fathoms, 3 feet 44°27'14.7"N 063°42'18.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-11)*

13-JUL-2018 LNM/D. 16-DEC-2016
Add depth of 2 fathoms 44°27'13.9"N 063°42'20.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-12)*

13-JUL-2018 LNM/D. 16-DEC-2016
Replace depth of 4 fathoms, 1 foot with depth of 1 fathom, 5 feet 44°27'18.6"N 063°43'02.2"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-13)*



Chart no. 4385

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 5 fathoms, 2 feet with depth of 3 fathoms
(See Chart No. 1, I10)

44°26'29.3"N 063°44'08.6"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-17)

13-JUL-2018

LNМ/D. 16-DEC-2016

Add depth of 5 fathoms, 2 feet
(See Chart No. 1, I10)

44°26'47.2"N 063°44'26.7"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-18)

13-JUL-2018

LNМ/D. 16-DEC-2016

Add depth of 2 fathoms, 4 feet
(See Chart No. 1, I10)

44°27'13.7"N 063°44'47.9"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-19)

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 8 fathoms, 3 feet with depth of 2 fathoms, 4 feet
(See Chart No. 1, I10)

44°27'27.2"N 063°44'01.3"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-20)

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 4 fathoms, 4 feet with depth of 1 fathom, 4 feet
(See Chart No. 1, I10)

44°27'43.1"N 063°43'44.6"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-21)

13-JUL-2018

LNМ/D. 16-DEC-2016

Add depth of 3 fathoms, 3 feet
(See Chart No. 1, I10)

44°27'21.8"N 063°45'24.1"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-23)

13-JUL-2018

LNМ/D. 16-DEC-2016

Replace depth of 6 fathoms with depth of 2 fathoms, 2 feet
(See Chart No. 1, I10)

44°27'44.2"N 063°45'20.1"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-24)

13-JUL-2018

LNМ/D. 16-DEC-2016



Chart no. 4385

Add depth of 4 fathoms, 1 foot 44°27'41.5"N 063°45'48.4"W
(See Chart No. 1, I10)

DFO(6307884-25)

LNМ/D. 16-DEC-2016

13-JUL-2018

Replace depth of 7 fathoms with depth of 0 fathoms, 5 feet
(See Chart No. 1, I10)

44°28'00.4"N 063°45'33.2"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6307884-26)

LNМ/D. 16-DEC-2016

13-JUL-2018

Replace depth of 6 fathoms, 3 feet with depth of 1 fathom, 5 feet 44°28'49.4"N 063°46'24.8"W
(See Chart No. 1, I10)

DFO(6307884-27)

LNМ/D. 16-DEC-2016

13-JUL-2018

Add depth of 4 fathoms, 3 feet 44°26'29.3"N 063°46'32.7"W
(See Chart No. 1, I10)

DFO(6307884-28)

LNМ/D. 16-DEC-2016

13-JUL-2018

Add rock which covers and uncovers with drying height of 1 foot 44°26'49.3"N 063°46'54.9"W
(See Chart No. 1, K11)

DFO(6307884-30)

16-DEC-2016

LNМ/D. 05-AUG-2016

Delete light FG
(See Chart No. 1, P1)

44°28'15.5"N 063°38'03.5"W

This notice affects Electronic Navigational Chart:
CA476009

(F2016052) LL(501) DFO(6307737-01)

05-AUG-2016

LNМ/D. 26-JUN-2015

Delete legend FogSig 60s against light
(See Chart No 1 R20)

44°26'19.7"N 063°46'00.4"W

This notice affects Electronic Navigational Chart:
CA276801, CA476195

(F2016032) LL(495) DFO(6307615-01)

05-AUG-2016

LNМ/D. 26-JUN-2015



Chart no. 4385

Affix patch 44°26'00.0"N 063°35'00.0"W
[PDF](#)

DFO(6307651-03)

05-AUG-2016 LNM/D. 26-JUN-2015

Delete depth of 6 fathoms 44°26'24.7"N 063°31'46.9"W
(See Chart No. 1, I10)

DFO(6307651-05)

05-AUG-2016 LNM/D. 26-JUN-2015

Add depth of 1 fathom 44°26'25.9"N 063°31'49.1"W
(See Chart No. 1, I10)

DFO(6307651-06)

26-JUN-2015

LNM/D. 19-JUN-2015

Add light FIR against red starboard hand spar buoy,
marked HE10
(See Chart No. 1, Q7)

44°26'50.8"N 063°34'50.9"W

(F2015017) LL(503.05) DFO(6307148-01)

This notice affects Electronic Navigational Chart:
CA476009, CA576010

19-JUN-2015

LNM/D. 22-MAY-2015

Delete green port hand spar buoy, marked HE7
(See Chart No. 1, Qg)

44°26'10.1"N 063°36'02.4"W

This notice affects Electronic Navigational Chart: CA476009 *(F2015016) DFO(6307147-01)*

19-JUN-2015

LNM/D. 22-MAY-2015

Add green port hand lighted spar buoy FlG, marked HE7
(See Chart No. 1, Q7)

44°26'14.5"N 063°35'52.8"W

This notice affects Electronic Navigational Chart: *(F2015016) LL(503.03) DFO(6307147-02)*
CA476009

22-MAY-2015

LNM/D. 15-AUG-2014

Add red starboard hand lighted spar buoy FIR, marked
HE6

44°25'17.1"N 063°36'16.6"W

(See Chart No. 1, Qf) *(F2015012) LL(503.52) DFO(6307113-01)*
This notice affects Electronic Navigational Chart:
CA476009



Chart no. 4385

15-AUG-2014

Delete pilot boarding station
(See Chart No. 1, T1.1)

This notice affects Electronic Navigational Chart: CA476009

LNМ/D. 08-NOV-2013
44°31'24.0"N 063°30'21.7"W

DFO(6306785-01)

08-NOV-2013

Reposition red starboard hand spar buoy, marked HE4
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476009

LNМ/D. 28-JUN-2013
from 44°25'01.1"N 063°36'08.7"W
to 44°24'47.4"N 063°36'37.2"W

(F2013022) DFO(6306500-01)

08-NOV-2013

Reposition green port hand spar buoy, marked HE5
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:
CA476009

LNМ/D. 28-JUN-2013
from 44°25'47.5"N 063°36'32.7"W
to 44°25'49.4"N 063°36'18.7"W

(F2013029) DFO(6306500-02)

08-NOV-2013

Reposition red starboard hand spar buoy, marked HE8
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476009

LNМ/D. 28-JUN-2013
from 44°25'46.3"N 063°35'48.6"W
to 44°25'48.8"N 063°35'52.6"W

(F2013023) DFO(6306500-03)

08-NOV-2013

Reposition red starboard hand spar buoy, marked HE12
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476009

LNМ/D. 28-JUN-2013
from 44°27'02.5"N 063°34'15.0"W
to 44°27'04.8"N 063°34'12.5"W

(F2013028) DFO(6306500-04)

08-NOV-2013

Reposition red starboard hand spar buoy, marked HE14
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA476009

LNМ/D. 28-JUN-2013
from 44°27'16.0"N 063°33'33.4"W
to 44°27'19.2"N 063°33'36.5"W

(F2013027) DFO(6306500-05)

08-NOV-2013

Reposition green port hand spar buoy, marked HE15
(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:
CA476009

LNМ/D. 28-JUN-2013
from 44°27'36.5"N 063°33'33.6"W
to 44°27'34.2"N 063°33'31.4"W

(F2013026) DFO(6306500-06)



Chart no. 4385

08-NOV-2013

Reposition red starboard hand lighted spar buoy FLR,
marked HE16
(See Chart No. 1, Qf)
This notice affects Electronic Navigational
Chart: CA476009

LNМ/D. 28-JUN-2013
from 44°27'34.1"N 063°32'40.5"W
to 44°27'40.6"N 063°32'49.6"W
(F2013025) LL(503.1) DFO(6306500-07)

08-NOV-2013

Reposition green port hand lighted spar buoy FIG,
marked HE17
(See Chart No. 1, Qg)
This notice affects Electronic Navigational
Chart: CA476009

LNМ/D. 28-JUN-2013
from 44°28'02.0"N 063°32'45.3"W
to 44°28'00.6"N 063°32'40.9"W
(F2013024) LL(503.11) DFO(6306500-08)

28-JUN-2013

Add restricted area with legend Explos
(See Chart No.1 N23.1b)
This notice affects Electronic Navigational Chart: CA476009

LNМ/D. 21-JUN-2013
44°26'59.0"N 063°32'10.0"W
DFO(6306402-01)

21-JUN-2013

Reposition green port hand lighted pillar buoy FIG,
marked HE3
(See Chart No 1 Qg)
This notice affects Electronic Navigational
Chart: CA476009

LNМ/D. 07-JUN-2013
from 44°25'28.0"N 063°37'03.0"W
to 44°25'25.0"N 063°36'41.6"W
(F2013004) LL(503.5) DFO(6306368-01)

07-JUN-2013

Reposition red starboard hand lighted pillar bell buoy Fl R,
marked HE2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476009

LNМ/D. 08-FEB-2013
from 44°24'15.3"N 063°36'29.7"W
to 44°24'16.4"N 063°36'59.4"W
(F2013003) LL(503) DFO(6306367-01)

08-FEB-2013

Add maritime limit in general implying: permanent physical
obstructions
(see Chart 1, N1.1)
This notice affects Electronic Navigational Chart:
CA276801, CA376032, CA476009

LNМ/D. 13-JAN-2012
between 44°28'42.0"N 063°32'00.0"W
and 44°26'55.0"N 063°30'00.0"W
DFO(6304781-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4385

08-FEB-2013

LNМ/D. 13-JAN-2012

Add See/Voir note

44°28'25.0"N 063°30'51.5"W

SCIENTIFIC MOORINGS

MOUILLAGES SCIENTIFIQUES

DFO(6304781-02)

08-FEB-2013

LNМ/D. 13-JAN-2012

Add note:

to the lower east margin of chart

SCIENTIFIC MOORINGS

Acoustic sensors, one metre high and positioned approximately 800 metres apart, along the line, directly on the seabed. Mariners are advised to avoid anchoring or conducting seabed operations in the vicinity of submarine moorings.

DFO(6304781-03)

MOUILLAGES SCIENTIFIQUES

Des capteurs acoustiques, d'une hauteur d'un mètre et positionnés à intervalles d'environ 800 mètres le long de la ligne, reposent directement sur le fond marin. Nous avisons les navigateurs d'éviter de mouiller ou d'effectuer des travaux sur le fond marin à proximité de ces mouillages sous-marins.

13-JAN-2012

LNМ/D. 11-NOV-2011

Delete legend Fog Sig (3) 60s against light
(See Chart No. 1, R1, R20)

44°26'12.0"N 063°33'48.0"W

(F2011193) LL(507) DFO(6305873-01)

This notice affects Electronic Navigational Chart:
CA276801, CA476009

11-NOV-2011

LNМ/D. 15-JUL-2011

Delete red starboard hand spar buoy, marked HS2
(See Chart No. 1, Qf)

44°26'20.0"N 063°34'34.5"W

(F2011173) DFO(6305793-01)

This notice affects Electronic Navigational Chart: CA476009

11-NOV-2011

LNМ/D. 15-JUL-2011



Chart no. 4385

Add black, yellow and black East cardinal lighted spar buoy Q(3) 10s, marked HSE
(See Chart No. 1, Q130.3) 44°26'44.0"N 063°35'42.4"W
(F2011179) LL(508.44) DFO(6305796-01)

11-NOV-2011 LNM/D. 15-JUL-2011
Add red starboard hand lighted conical buoy QR, marked HS4/2
(See Chart No. 1, Qf) 44°26'23.6"N 063°35'08.0"W
(F2011180) LL(508.42) DFO(6305797-01)

This notice affects Electronic Navigational Chart:
CA476009

11-NOV-2011 LNM/D. 15-JUL-2011
Add red starboard hand lighted conical buoy FIR, marked HS4
(See Chart No. 1, Qf) 44°26'00.0"N 063°34'42.0"W
(F2011181) LL(508.4) DFO(6305798-01)

This notice affects Electronic Navigational Chart:
CA476009

11-NOV-2011 LNM/D. 15-JUL-2011
Add red starboard hand lighted conical buoy FIR, marked HS2/2
(See Chart No. 1, Qf) 44°25'38.5"N 063°34'16.3"W
(F2011182) LL(508.22) DFO(6305799-01)

This notice affects Electronic Navigational Chart:
CA476009

11-NOV-2011 LNM/D. 15-JUL-2011
Add red starboard hand lighted conical buoy FIR, marked HS2
(See Chart No. 1, Qf) 44°25'15.8"N 063°33'49.6"W
(F2011183) LL(508.2) DFO(6305800-01)

This notice affects Electronic Navigational Chart:
CA476009

15-JUL-2011 LNM/D. 04-JUN-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4385

Add rock with known depth of 5 feet, dangerous to surface navigation 44°28'42.9"N 063°35'52.7"W
(See Chart No. 1, K14/K14.2)

DFO(6305547-02)

04-JUN-2010

LNM/D. 25-SEP-2009

Amend Fl 20s 162ft 16M to read Fl 20s 157ft 10M against light
(See Chart 1 P16)

44°30'26.6"N 063°31'21.8"W

LL(513) DFO(6304817-01)

This notice affects Electronic Navigational Chart: CA176140

25-SEP-2009

LNM/D. 22-MAY-2009

Amend FG to read FlG against light
(see Chart No 1 P16)

44°28'07.9"N 063°47'03.3"W

(F2009052) LL(492) DFO(6304559-01)

This notice affects Electronic Navigational Chart:
CA476195

25-SEP-2009

LNM/D. 22-MAY-2009

Amend F to read LFl against light
(See Chart No 1 P16)

44°28'04.5"N 063°42'52.2"W

(F2009053) LL(499) DFO(6304560-01)

This notice affects Electronic Navigational Chart:
CA476189

25-SEP-2009

LNM/D. 22-MAY-2009

Amend F to read Fl against light
(See Chart No 1 P16)

44°27'03.4"N 063°43'32.1"W

(F2009054) LL(496.5) DFO(6304561-01)

This notice affects Electronic Navigational Chart:
CA476189

22-MAY-2009

LNM/D. 27-MAR-2009

Add green port hand spar buoy, marked HF1
(See Chart No 1 Qg)

44°28'58.7"N 063°32'53.8"W

DFO(6304350-01)

This notice affects Electronic Navigational Chart: CA476009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4385

22-MAY-2009

LNМ/D. 27-MAR-2009

Add Channel Buoyed/Chenal balisé 44°29'12.0"N 063°33'18.0"W

DFO(6304350-02)

27-MAR-2009

LNМ/D. 20-FEB-2009

Replace red starboard hand conical light buoy F1R, marked AM64
with red starboard hand spar light buoy F1R, marked AM64
(See Chart No 1 Qf)

44°28'03.3"N 063°46'49.8"W

LL(494.01) DFO(6304267-01)

This notice affects Electronic Navigational Chart: CA476195

20-FEB-2009

LNМ/D. 07-NOV-2008

Add yellow, black and yellow West cardinal lighted spar
buoy Q(9) 15s, marked AAB
(See Chart No 1 Q130.3)

44°27'32.9"N 063°39'33.7"W

(F2008156) LL(499.9) DFO(6304216-01)

This notice affects Electronic Navigational Chart:
CA476189

20-FEB-2009

LNМ/D. 07-NOV-2008

Add green port hand lighted can buoy F1G, marked AA55
(See Chart No 1 Qg)

44°27'48.3"N 063°38'28.2"W

(F2008158) LL(501.2) DFO(6304230-01)

This notice affects Electronic Navigational Chart:
CA476009

20-FEB-2009

LNМ/D. 07-NOV-2008

Add green port hand lighted can buoy F1G, marked AA57
(See Chart No 1 Qg)

44°28'01.9"N 063°38'15.1"W

(F2008157) LL(501.1) DFO(6304231-01)

This notice affects Electronic Navigational Chart:
CA476009

20-FEB-2009

LNМ/D. 07-NOV-2008



Chart no. 4385

Add green, red and green port bifurcation lighted spar
buoy Fl (2+1)G 6s, marked AAA
(See Chart No 1 Qj)

44°27'09.9"N 063°38'55.9"W

(F2008161) LL(501.4) DFO(6304232-01)

This notice affects Electronic Navigational Chart:
CA476009

20-FEB-2009

LNМ/D. 07-NOV-2008

Add green port hand lighted spar buoy FlG, marked AA53
(See Chart No 1 Qg)

44°26'48.2"N 063°39'23.6"W

(F2008162) LL(501.5) DFO(6304233-01)

This notice affects Electronic Navigational Chart:
CA476189

20-FEB-2009

LNМ/D. 07-NOV-2008

Add red starboard hand lighted conical buoy FlR, marked
AA54
(See Chart No 1 Qf)

44°27'38.0"N 063°38'30.8"W

(F2008163) LL(501.3) DFO(6304234-01)

This notice affects Electronic Navigational Chart:
CA476009

20-FEB-2009

LNМ/D. 07-NOV-2008

Add green port hand lighted spar buoy FlG, marked AA51
(See Chart No 1 Qg)

44°26'32.6"N 063°39'48.0"W

(F2008164) LL(501.6) DFO(6304235-01)

This notice affects Electronic Navigational Chart:
CA476189

20-FEB-2009

LNМ/D. 07-NOV-2008

Add red starboard hand lighted spar buoy FlR, marked
AA52
(See Chart No 1 Qf)

44°26'10.3"N 063°39'36.6"W

(F2008165) LL(501.7) DFO(6304236-01)

This notice affects Electronic Navigational Chart:
CA476189

07-NOV-2008

LNМ/D. 26-SEP-2008



Chart no. 4385

Add light FLR against red starboard hand spar buoy,
marked HE16
(See Chart No 1 Q7)

44°27'33.0"N 063°32'42.0"W

(F2008115) LL(503.1) DFO(6304045-01)

07-NOV-2008

LNLM/D. 26-SEP-2008

Add light FLG against green port hand spar buoy, marked
HE17
(See Chart No 1 Q7)

44°28'02.0"N 063°32'47.0"W

(F2008117) LL(503.11) DFO(6304047-01)

26-SEP-2008

LNLM/D. 13-JUN-2008

(T)Add The positions of the subsurface moorings for the OTN between 44°28'42.0"N 063°32'00.0"W
project are: and 44°26'57.8"N 063°30'03.3"W

OTN1 44° 28' 42.00" N 63° 32' 00.00" W

DFO(6303910-01)

OTN2 44° 28' 21.17" N 63° 31' 36.67" W

OTN3 44° 28' 00.33" N 63° 31' 13.33" W

OTN4 44° 27' 39.50" N 63° 30' 50.00" W

OTN5 44° 27' 18.67" N 63° 30' 26.67" W

OTN6 44° 26' 57.83" N 63° 30' 03.33" W

Proposed date of removal is April 2013.

Moorings permanently established. Notice

2008-09-26(T), is cancelled. See reference

DFO(6304781) appearing in this edition.

Cancelled on

26-SEP-2008

LNLM/D. 13-JUN-2008

Amend Fl 5s 140ft 24M to read Fl 6s 140ft 23M against
light
(See Chart No 1 P16)

44°26'12.0"N 063°33'48.0"W

(F2008068) LL(507) DFO(6303952-01)

This notice affects Electronic Navigational Chart:
CA476009

13-JUN-2008

LNLM/D. 06-APR-2007

Add light FLR against red starboard hand conical buoy,
marked AM64
(See Chart No 1 Qf)

44°28'03.3"N 063°46'49.8"W

(F2004177) LL(494.01) DFO(6303852-01)

06-APR-2007

LNLM/D. 12-AUG-2005



Chart no. 4385

Delete legend "WHIS" against green port hand lighted pillar
whistle buoy FIG, marked HE19

44°28'19.6"N 063°32'16.0"W

(F2007028) LL(511) DFO(6303378-01)

12-AUG-2005

LNM/D. 05-NOV-2004

Delete light F

44°28'02.0"N 063°46'54.0"W

(F2005049) LL(493) DFO(6302386-01)

05-NOV-2004

LNM/D. 08-OCT-2004

Delete legend "BELL" against green port hand pillar light
buoy FIG, marked HD5, BELL

44°29'00.0"N 063°31'03.0"W

(F2004127) LL(512) DFO(6301958-01)

08-OCT-2004

LNM/D. 15-NOV-2002

Delete legend "WHIS" against red starboard pillar light buoy
Fl R, WHIS, marked H4

44°31'39.5"N 063°30'03.6"W

(F2004116) LL(516) DFO(6301905-01)

15-NOV-2002

LNM/D. 25-OCT-2002

Amend measured distance with bearing 154°20'-334°20' 6078ft to
read 154°20'-334°20' 6118ft

44°31'24.0"N 063°30'37.0"W

With this notification, action dated 31-MAR-2000 is cancelled.
See reference DFO(6500084) appearing in this edition.

DFO(6300609-01)

25-OCT-2002

LNM/D. 23-AUG-2002

Delete submarine cable between 44°26'49.8"N 063°35'40.2"W
and 44°27'30.0"N 063°36'54.0"W

DFO(6300592-01)

25-OCT-2002

LNM/D. 23-AUG-2002

Add submarine cable joining 44°26'49.8"N 063°35'40.2"W
44°27'22.8"N 063°36'24.0"W
and 44°27'30.0"N 063°36'54.0"W

DFO(6300592-02)



Chart no. 4385

23-AUG-2002

LNM/D. 31-MAR-2000

Add submarine cable joining 44°32'00.0"N 063°31'33.6"W
44°31'44.3"N 063°31'12.1"W
44°31'32.7"N 063°31'04.1"W
44°30'57.5"N 063°30'57.2"W
44°30'34.6"N 063°30'49.2"W
44°30'10.1"N 063°30'27.3"W
44°29'42.9"N 063°30'13.1"W
44°28'54.6"N 063°30'11.0"W
44°27'41.9"N 063°30'22.6"W
44°27'15.1"N 063°30'23.5"W
44°27'02.6"N 063°30'26.3"W
44°26'25.8"N 063°30'42.3"W
44°26'00.0"N 063°30'57.0"W
44°25'40.1"N 063°30'58.3"W
44°25'14.5"N 063°30'38.5"W
44°25'05.2"N 063°30'26.5"W
and 44°24'51.0"N 063°30'00.0"W

DFO(6300455-01)

23-AUG-2002

LNM/D. 31-MAR-2000

Add submarine cable joining 44°29'32.8"N 063°33'01.1"W
44°29'23.1"N 063°33'01.2"W
44°29'07.8"N 063°32'53.4"W
44°29'03.0"N 063°32'53.4"W
44°28'37.2"N 063°32'23.7"W
44°28'29.4"N 063°31'52.1"W
44°27'18.2"N 063°31'07.3"W
44°26'38.8"N 063°30'59.8"W
44°25'51.1"N 063°31'10.7"W
44°25'38.5"N 063°31'09.4"W
44°25'25.0"N 063°31'03.3"W
44°24'47.1"N 063°30'19.8"W
and 44°24'26.0"N 063°30'00.0"W

DFO(6300455-02)

23-AUG-2002

LNM/D. 31-MAR-2000



Chart no. 4385

Add submarine cable joining 44°23'02.9"N 063°30'00.0"W
44°22'37.7"N 063°30'43.0"W
44°22'26.4"N 063°31'14.9"W
44°22'23.5"N 063°31'58.2"W
44°22'09.0"N 063°32'57.8"W
44°22'00.3"N 063°33'07.5"W
44°21'36.4"N 063°33'25.2"W
and 44°21'30.0"N 063°33'27.4"W

DFO(6300455-03)

23-AUG-2002

LN/D. 31-MAR-2000

Add submarine cable joining 44°29'09.6"N 063°32'54.6"W
44°29'03.6"N 063°32'54.6"W
44°28'55.2"N 063°32'48.6"W
44°28'36.1"N 063°32'30.0"W
44°28'19.4"N 063°31'59.5"W
44°26'53.0"N 063°31'12.6"W
44°26'22.7"N 063°31'10.2"W
44°26'09.4"N 063°31'15.0"W
44°25'52.5"N 063°31'44.0"W
44°25'45.2"N 063°31'50.9"W
44°24'52.9"N 063°32'10.2"W
44°24'23.3"N 063°32'48.1"W
44°24'04.5"N 063°32'55.5"W
44°23'11.0"N 063°32'48.6"W
44°22'56.6"N 063°32'55.5"W
44°22'33.5"N 063°33'29.0"W
44°22'23.8"N 063°33'36.6"W
44°22'02.0"N 063°34'19.3"W
and 44°21'30.0"N 063°35'00.3"W

DFO(6300455-04)

31-MAR-2000

LN/D. 02-APR-1999

(P)Amend measured distance with bearing 154°20'-334°20' 6078ft to 44°31'24.0"N 063°30'37.0"W
read 154°20'-334°20' 6118ft

DFO(6500084-01)

The Preliminary action dated 31-MAR-2000, is now a permanent action. See reference DFO(6300609) appearing in this edition.

Cancelled on 15-NOV-02