



### Chart no. 4385

#### 4385 - Chebucto Head to / à Betty Island - New Edition - 07-JUN-1996 - NAD 1983

**10-MAY-2024**

LNМ/D. 25-NOV-2022

Delete red and white fairway lighted pillar bell buoy Mo(A),  
marked HC  
(See Chart 1, Qd)

44°30'36.5"N 063°30'13.3"W

(F2024010) LL(514) DFO(6311059-02)

**25-NOV-2022**

LNМ/D. 01-JAN-2021

Delete legend Fog Sig (2) 60 s against light  
(See Chart No 1 R20)

44°30'26.9"N 063°31'21.8"W

This notice affects Electronic Navigational Chart:  
CA276801, CA476009

(F2022018) LL(513) DFO(6310357-01)

**25-NOV-2022**

LNМ/D. 01-JAN-2021

Replace depth of 3 fathoms with depth of 0 fathoms, 4 feet  
(See Chart 1, I10)

44°26'50.5"N 063°43'16.2"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6310443-01)

**25-NOV-2022**

LNМ/D. 01-JAN-2021

Add depth of 0 fathoms, 1 foot  
(See Chart 1, I10)

44°26'50.5"N 063°43'08.2"W

This notice affects Electronic Navigational Chart: CA476189

DFO(6310443-02)

**01-JAN-2021**

LNМ/D. 10-JAN-2020

Amend Fl 15s63ft13M to read LFl 6s63ft13M  
(See Chart No. 1, P16)

44°26'19.7"N 063°46'00.4"W

This notice affects Electronic Navigational Chart:  
CA276801, CA476195

(F2020049) LL(495) DFO(6309314-01)

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Replace depth of 4 fathoms 2 feet with depth of 3 fathoms 5 feet  
(See Chart No. 1, I10)

44°25'33.3"N 063°37'14.0"W

This notice affects Electronic Navigational Chart: CA476009

DFO(6308832-01)

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Replace depth of 6 fathoms, 1 foot with depth of 4 fathoms, 5 feet  
(See Chart No. 1, I10)

44°25'44.7"N 063°37'27.5"W

This notice affects Electronic Navigational Chart: CA476009

DFO(6308832-02)



### Chart no. 4385

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Add depth of 2 fathoms, 2 feet  
(See Chart No. 1, I10)

44°25'40.0"N 063°37'44.2"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308832-03)*

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Replace depth of 5 fathoms, 5 feet with depth of 4 fathoms, 1 foot  
(See Chart No. 1, I10)

44°25'55.6"N 063°37'55.0"W

*DFO(6308832-05)*

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Add depth of 4 fathoms, 1 foot  
(See Chart No. 1, I10)

44°26'02.5"N 063°37'52.1"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308832-06)*

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Add depth of 1 fathom, 4 feet  
(See Chart No. 1, I10)

44°26'08.4"N 063°36'45.5"W

This notice affects Electronic Navigational Chart: CA476009

*DFO(6308832-07)*

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Add depth of 1 fathom, 5 feet  
(See Chart No. 1, I10)

44°26'51.5"N 063°44'34.9"W

This notice affects Electronic Navigational Chart: CA476189

*DFO(6308833-01)*

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Reposition drying height of 6 feet  
(See Chart No. 1, Ia)

from 44°27'32.6"N 063°45'23.1"W  
to 44°27'35.6"N 063°45'22.8"W

This notice affects Electronic Navigational Chart:  
CA476189

*DFO(6308833-02)*

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Add depth of 3 fathoms, 4 feet  
(See Chart No. 1, I10)

44°27'32.7"N 063°45'23.2"W

This notice affects Electronic Navigational Chart: CA476189

*DFO(6308833-03)*

**10-JAN-2020**

LNМ/D. 01-MAR-2019



### Chart no. 4385

Add depth of 2 fathoms 44°27'56.4"N 063°45'10.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-04)*

**10-JAN-2020** LNM/D. 01-MAR-2019  
Add depth of 2 fathoms, 4 feet 44°27'34.0"N 063°44'02.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-05)*

**10-JAN-2020** LNM/D. 01-MAR-2019  
Delete depth of 20 fathoms 44°26'51.6"N 063°44'41.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-06)*

**10-JAN-2020** LNM/D. 01-MAR-2019  
Add depth of 4 fathoms 44°26'52.6"N 063°44'39.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6308833-07)*

**10-JAN-2020** LNM/D. 01-MAR-2019  
Delete depth of 8 fathoms, 3 feet 44°26'44.0"N 063°46'54.9"W  
(See Chart No. 1, I10)  
*DFO(6308836-02)*

**10-JAN-2020** LNM/D. 01-MAR-2019  
Add depth of 3 fathoms, 5 feet 44°26'45.9"N 063°46'53.6"W  
(See Chart No. 1, I10)  
*DFO(6308836-03)*

**10-JAN-2020** LNM/D. 01-MAR-2019  
Add depth of 3 fathoms, 1 foot 44°28'14.5"N 063°46'27.0"W  
(See Chart No. 1, I10)  
*DFO(6308836-04)*

**10-JAN-2020** LNM/D. 01-MAR-2019  
Add depth of 1 fathom, 1 foot 44°28'46.1"N 063°46'05.0"W  
(See Chart No. 1, I10)  
*DFO(6308836-05)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4385

**10-JAN-2020**

LNМ/D. 01-MAR-2019

Add depth of 4 fathoms, 2 feet 44°27'36.6"N 063°46'11.8"W  
(See Chart No. 1, I10)

*DFO(6308836-06)*

**01-MAR-2019**

LNМ/D. 13-JUL-2018

Amend F R 48 ft 6 M to read LFl 6s8M against light  
(See Chart No. 1, P16)

44°27'36.6"N 063°42'20.4"W

This notice affects Electronic Navigational Chart:  
CA476189

*(F2019001) LL(498) DFO(6308559-01)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Add depth of 2 fathoms, 3 feet 44°26'34.5"N 063°31'34.0"W  
(See Chart No. 1, I10)

*DFO(6307791-01)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Delete depth of 3 fathoms, 5 feet 44°27'24.8"N 063°32'52.8"W  
(See Chart No. 1, I10)

*DFO(6307791-02)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Add depth of 2 fathoms, 4 feet 44°27'23.1"N 063°32'55.7"W  
(See Chart No. 1, I10)

*DFO(6307791-03)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Replace depth of 4 fathoms, 4 feet with depth of 2 fathoms, 5 feet 44°26'50.8"N 063°32'40.9"W  
(See Chart No. 1, I10)

*DFO(6307791-04)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Replace depth of 5 fathoms, 5 feet with depth of 4 fathoms, 4 feet 44°26'43.4"N 063°32'16.9"W  
(See Chart No. 1, I10)

*DFO(6307791-05)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016



**Chart no. 4385**

Replace depth of 4 fathoms with depth of 3 fathoms, 1 foot 44°26'43.2"N 063°32'26.2"W  
(See Chart No. 1, I10)

*DFO(6307791-06)*

**13-JUL-2018**

LNM/D. 16-DEC-2016

Replace depth of 5 fathoms, 2 feet with depth of 2 fathoms, 5 feet 44°25'59.7"N 063°32'42.6"W  
(See Chart No. 1, I10)

*DFO(6307791-07)*

**13-JUL-2018**

LNM/D. 16-DEC-2016

Delete depth of 4 fathoms, 4 feet 44°26'32.8"N 063°31'35.3"W  
(See Chart No. 1, I10)

*DFO(6307791-08)*

**13-JUL-2018**

LNM/D. 16-DEC-2016

Replace depth of 5 fathoms with depth of 3 fathoms, 4 feet 44°26'13.9"N 063°32'54.7"W  
(See Chart No. 1, I10)

*DFO(6307791-09)*

**13-JUL-2018**

LNM/D. 16-DEC-2016

Add depth of 3 fathoms, 1 foot 44°25'39.7"N 063°37'35.1"W  
(See Chart No. 1, I10)

*DFO(6307791-10)*

**13-JUL-2018**

LNM/D. 16-DEC-2016

Replace depth of 3 fathoms, 3 feet with depth of 2 fathoms, 4 feet 44°26'21.3"N 063°37'36.8"W  
(See Chart No. 1, I10)

*DFO(6307791-11)*

**13-JUL-2018**

LNM/D. 16-DEC-2016

Replace depth of 6 fathoms, 5 feet with depth of 5 fathoms, 0 feet 44°27'30.9"N 063°32'45.4"W  
(See Chart No. 1, I10)

*DFO(6307791-12)*

**13-JUL-2018**

LNM/D. 16-DEC-2016

Replace depth of 6 fathoms, 4 feet with depth of 4 fathoms, 4 feet 44°27'13.2"N 063°38'47.8"W  
(See Chart No. 1, I10)

*DFO(6307791-13)*



**Chart no. 4385**

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Replace depth of 2 fathoms, 1 foot with depth of 1 fathom, 3 feet 44°27'15.1"N 063°38'57.0"W  
(See Chart No. 1, I10)

*DFO(6307791-14)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Replace depth of 4 fathoms, 5 feet with depth of 1 fathom, 4 feet 44°27'44.9"N 063°39'00.4"W  
(See Chart No. 1, I10)

*DFO(6307791-15)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Add depth of 2 fathoms, 5 feet 44°25'52.8"N 063°38'05.8"W  
(See Chart No. 1, I10)

*DFO(6307791-16)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Replace depth of 2 fathoms, 4 feet with depth of 1 fathom, 5 feet 44°27'55.4"N 063°41'00.9"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189

*DFO(6307884-01)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Replace depth of 4 fathoms, 5 feet with depth of 3 fathoms, 3 feet 44°27'50.7"N 063°40'25.4"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189

*DFO(6307884-02)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Replace depth of 7 fathoms, 4 feet with depth of 4 fathoms, 1 foot 44°28'04.5"N 063°41'22.6"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189

*DFO(6307884-03)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016

Add depth of 1 fathom, 4 feet 44°29'33.5"N 063°46'14.7"W  
(See Chart No. 1, I10)

*DFO(6307884-04)*

**13-JUL-2018**

LNМ/D. 16-DEC-2016



### Chart no. 4385

Replace depth of 3 fathoms, 4 feet with 2 fathoms, 0 feet 44°27'42.1"N 063°41'03.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-05)*

**13-JUL-2018** LNM/D. 16-DEC-2016  
Replace depth of 6 fathoms, 3 feet with depth of 2 fathoms, 5 feet 44°26'34.9"N 063°42'00.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-06)*

**13-JUL-2018** LNM/D. 16-DEC-2016  
Replace depth of 8 fathoms, 5 feet with depth of 5 fathoms, 2 feet 44°26'47.8"N 063°42'05.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-07)*

**13-JUL-2018** LNM/D. 16-DEC-2016  
Replace depth of 6 fathoms with depth of 3 fathoms, 3 feet 44°27'03.3"N 063°42'17.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-08)*

**13-JUL-2018** LNM/D. 16-DEC-2016  
Replace depth of 2 fathoms, 2 feet with depth of 1 fathom, 2 feet 44°25'57.1"N 063°39'10.0"W  
(See Chart No. 1, I10)  
*DFO(6307884-09)*

**13-JUL-2018** LNM/D. 16-DEC-2016  
Add depth of 3 fathoms, 2 feet 44°27'09.4"N 063°42'24.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-10)*

**13-JUL-2018** LNM/D. 16-DEC-2016  
Delete depth of 4 fathoms, 3 feet 44°27'14.7"N 063°42'18.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-11)*

**13-JUL-2018** LNM/D. 16-DEC-2016  
Add depth of 2 fathoms 44°27'13.9"N 063°42'20.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-12)*



### Chart no. 4385

- 13-JUL-2018** LNM/D. 16-DEC-2016  
Replace depth of 4 fathoms, 1 foot with depth of 1 fathom, 5 feet 44°27'18.6"N 063°43'02.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-13)*
- 13-JUL-2018** LNM/D. 16-DEC-2016  
Replace depth of 5 fathoms, 2 feet with depth of 3 fathoms 44°26'29.3"N 063°44'08.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-17)*
- 13-JUL-2018** LNM/D. 16-DEC-2016  
Add depth of 5 fathoms, 2 feet 44°26'47.2"N 063°44'26.7"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-18)*
- 13-JUL-2018** LNM/D. 16-DEC-2016  
Add depth of 2 fathoms, 4 feet 44°27'13.7"N 063°44'47.9"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-19)*
- 13-JUL-2018** LNM/D. 16-DEC-2016  
Replace depth of 8 fathoms, 3 feet with depth of 2 fathoms, 4 feet 44°27'27.2"N 063°44'01.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-20)*
- 13-JUL-2018** LNM/D. 16-DEC-2016  
Replace depth of 4 fathoms, 4 feet with depth of 1 fathom, 4 feet 44°27'43.1"N 063°43'44.6"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-21)*
- 13-JUL-2018** LNM/D. 16-DEC-2016  
Add depth of 3 fathoms, 3 feet 44°27'21.8"N 063°45'24.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-23)*
- 13-JUL-2018** LNM/D. 16-DEC-2016





**Chart no. 4385**

Replace depth of 6 fathoms with depth of 2 fathoms, 2 feet 44°27'44.2"N 063°45'20.1"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-24)*

**13-JUL-2018** LNM/D. 16-DEC-2016

Add depth of 4 fathoms, 1 foot 44°27'41.5"N 063°45'48.4"W  
(See Chart No. 1, I10)

*DFO(6307884-25)*

**13-JUL-2018** LNM/D. 16-DEC-2016

Replace depth of 7 fathoms with depth of 0 fathoms, 5 feet 44°28'00.4"N 063°45'33.2"W  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476189 *DFO(6307884-26)*

**13-JUL-2018** LNM/D. 16-DEC-2016

Replace depth of 6 fathoms, 3 feet with depth of 1 fathom, 5 feet 44°28'49.4"N 063°46'24.8"W  
(See Chart No. 1, I10)

*DFO(6307884-27)*

**13-JUL-2018** LNM/D. 16-DEC-2016

Add depth of 4 fathoms, 3 feet 44°26'29.3"N 063°46'32.7"W  
(See Chart No. 1, I10)

*DFO(6307884-28)*

**13-JUL-2018** LNM/D. 16-DEC-2016

Add rock which covers and uncovers with drying height of 1 foot 44°26'49.3"N 063°46'54.9"W  
(See Chart No. 1, K11)

*DFO(6307884-30)*

**16-DEC-2016** LNM/D. 05-AUG-2016

Delete light FG 44°28'15.5"N 063°38'03.5"W  
(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: *(F2016052) LL(501) DFO(6307737-01)*  
CA476009

**05-AUG-2016** LNM/D. 26-JUN-2015



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4385

Delete legend FogSig 60s against light  
(See Chart No 1 R20)

44°26'19.7"N 063°46'00.4"W

This notice affects Electronic Navigational Chart:  
CA276801, CA476195

(F2016032) LL(495) DFO(6307615-01)

**05-AUG-2016** LNM/D. 26-JUN-2015

Affix patch 44°26'00.0"N 063°35'00.0"W  
[PDF](#)

DFO(6307651-03)

**05-AUG-2016** LNM/D. 26-JUN-2015

Delete depth of 6 fathoms 44°26'24.7"N 063°31'46.9"W  
(See Chart No. 1, I10)

DFO(6307651-05)

**05-AUG-2016** LNM/D. 26-JUN-2015

Add depth of 1 fathom 44°26'25.9"N 063°31'49.1"W  
(See Chart No. 1, I10)

DFO(6307651-06)

**26-JUN-2015**

LNM/D. 19-JUN-2015

Add light FLR against red starboard hand spar buoy,  
marked HE10  
(See Chart No. 1, Q7)

44°26'50.8"N 063°34'50.9"W

This notice affects Electronic Navigational Chart:  
CA476009, CA576010

(F2015017) LL(503.05) DFO(6307148-01)

**19-JUN-2015**

LNM/D. 22-MAY-2015

Delete green port hand spar buoy, marked HE7  
(See Chart No. 1, Qg)

44°26'10.1"N 063°36'02.4"W

This notice affects Electronic Navigational Chart: CA476009 (F2015016) DFO(6307147-01)

**19-JUN-2015**

LNM/D. 22-MAY-2015

Add green port hand lighted spar buoy FLG, marked HE7  
(See Chart No. 1, Q7)

44°26'14.5"N 063°35'52.8"W

This notice affects Electronic Navigational Chart:  
CA476009

(F2015016) LL(503.03) DFO(6307147-02)

**22-MAY-2015**

LNM/D. 15-AUG-2014



### Chart no. 4385

Add red starboard hand lighted spar buoy FIR, marked  
HE6  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476009

44°25'17.1"N 063°36'16.6"W

(F2015012) LL(503.52) DFO(6307113-01)

### 15-AUG-2014

Delete pilot boarding station  
(See Chart No. 1, T1.1)

This notice affects Electronic Navigational Chart: CA476009

LNМ/D. 08-NOV-2013  
44°31'24.0"N 063°30'21.7"W

DFO(6306785-01)

### 08-NOV-2013

Reposition red starboard hand spar buoy, marked HE4  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476009

LNМ/D. 28-JUN-2013  
from 44°25'01.1"N 063°36'08.7"W  
to 44°24'47.4"N 063°36'37.2"W

(F2013022) DFO(6306500-01)

### 08-NOV-2013

Reposition green port hand spar buoy, marked HE5  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart:  
CA476009

LNМ/D. 28-JUN-2013  
from 44°25'47.5"N 063°36'32.7"W  
to 44°25'49.4"N 063°36'18.7"W

(F2013029) DFO(6306500-02)

### 08-NOV-2013

Reposition red starboard hand spar buoy, marked HE8  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476009

LNМ/D. 28-JUN-2013  
from 44°25'46.3"N 063°35'48.6"W  
to 44°25'48.8"N 063°35'52.6"W

(F2013023) DFO(6306500-03)

### 08-NOV-2013

Reposition red starboard hand spar buoy, marked HE12  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476009

LNМ/D. 28-JUN-2013  
from 44°27'02.5"N 063°34'15.0"W  
to 44°27'04.8"N 063°34'12.5"W

(F2013028) DFO(6306500-04)

### 08-NOV-2013

Reposition red starboard hand spar buoy, marked HE14  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart:  
CA476009

LNМ/D. 28-JUN-2013  
from 44°27'16.0"N 063°33'33.4"W  
to 44°27'19.2"N 063°33'36.5"W

(F2013027) DFO(6306500-05)



## Chart no. 4385

### 08-NOV-2013

Reposition green port hand spar buoy, marked HE15  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart:  
CA476009

LNМ/D. 28-JUN-2013  
from 44°27'36.5"N 063°33'33.6"W  
to 44°27'34.2"N 063°33'31.4"W  
(F2013026) DFO(6306500-06)

### 08-NOV-2013

Reposition red starboard hand lighted spar buoy FIR,  
marked HE16  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational  
Chart: CA476009

LNМ/D. 28-JUN-2013  
from 44°27'34.1"N 063°32'40.5"W  
to 44°27'40.6"N 063°32'49.6"W  
(F2013025) LL(503.1) DFO(6306500-07)

### 08-NOV-2013

Reposition green port hand lighted spar buoy FIG,  
marked HE17  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational  
Chart: CA476009

LNМ/D. 28-JUN-2013  
from 44°28'02.0"N 063°32'45.3"W  
to 44°28'00.6"N 063°32'40.9"W  
(F2013024) LL(503.11) DFO(6306500-08)

### 28-JUN-2013

Add restricted area with legend Explos  
(See Chart No.1 N23.1b)  
This notice affects Electronic Navigational Chart: CA476009

LNМ/D. 21-JUN-2013  
44°26'59.0"N 063°32'10.0"W  
DFO(6306402-01)

### 21-JUN-2013

Reposition green port hand lighted pillar buoy FIG,  
marked HE3  
(See Chart No 1 Qg)  
This notice affects Electronic Navigational  
Chart: CA476009

LNМ/D. 07-JUN-2013  
from 44°25'28.0"N 063°37'03.0"W  
to 44°25'25.0"N 063°36'41.6"W  
(F2013004) LL(503.5) DFO(6306368-01)

### 07-JUN-2013

Reposition red starboard hand lighted pillar bell buoy Fl R,  
marked HE2  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA476009

LNМ/D. 08-FEB-2013  
from 44°24'15.3"N 063°36'29.7"W  
to 44°24'16.4"N 063°36'59.4"W  
(F2013003) LL(503) DFO(6306367-01)

### 08-FEB-2013

LNМ/D. 13-JAN-2012



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4385

Add maritime limit in general implying: permanent physical obstructions between 44°28'42.0"N 063°32'00.0"W  
and 44°26'55.0"N 063°30'00.0"W

(see Chart 1, N1.1)

This notice affects Electronic Navigational Chart:  
CA276801, CA376032, CA476009

*DFO(6304781-01)*

**08-FEB-2013**

LNM/D. 13-JAN-2012

Add See/Voir note

44°28'25.0"N 063°30'51.5"W

SCIENTIFIC MOORINGS

MOUILLAGES SCIENTIFIQUES

*DFO(6304781-02)*

**08-FEB-2013**

LNM/D. 13-JAN-2012

Add note:

to the lower east margin of chart

SCIENTIFIC MOORINGS

Acoustic sensors, one metre high and positioned approximately 800 metres apart, along the line, directly on the seabed. Mariners are advised to avoid anchoring or conducting seabed operations in the vicinity of submarine moorings.

*DFO(6304781-03)*

MOUILLAGES SCIENTIFIQUES

Des capteurs acoustiques, d'une hauteur d'un mètre et positionnés à intervalles d'environ 800 mètres le long de la ligne, reposent directement sur le fond marin. Nous avisons les navigateurs d'éviter de mouiller ou d'effectuer des travaux sur le fond marin à proximité de ces mouillages sous-marins.

**13-JAN-2012**

LNM/D. 11-NOV-2011

Delete legend Fog Sig (3) 60s against light  
(See Chart No. 1, R1, R20)

44°26'12.0"N 063°33'48.0"W

*(F2011193) LL(507) DFO(6305873-01)*

This notice affects Electronic Navigational Chart:  
CA276801, CA476009

**11-NOV-2011**

LNM/D. 15-JUL-2011



**Chart no. 4385**

Delete red starboard hand spar buoy, marked HS2  
(See Chart No. 1, Qf)

44°26'20.0"N 063°34'34.5"W  
*(F2011173) DFO(6305793-01)*

This notice affects Electronic Navigational Chart: CA476009

**11-NOV-2011**

Add black, yellow and black East cardinal lighted spar  
buoy Q(3) 10s, marked HSE  
(See Chart No. 1, Q130.3)

LNМ/D. 15-JUL-2011  
44°26'44.0"N 063°35'42.4"W  
*(F2011179) LL(508.44) DFO(6305796-01)*

**11-NOV-2011**

Add red starboard hand lighted conical buoy QR, marked  
HS4/2  
(See Chart No. 1, Qf)

LNМ/D. 15-JUL-2011  
44°26'23.6"N 063°35'08.0"W  
*(F2011180) LL(508.42) DFO(6305797-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**11-NOV-2011**

Add red starboard hand lighted conical buoy F1R, marked  
HS4  
(See Chart No. 1, Qf)

LNМ/D. 15-JUL-2011  
44°26'00.0"N 063°34'42.0"W  
*(F2011181) LL(508.4) DFO(6305798-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**11-NOV-2011**

Add red starboard hand lighted conical buoy F1R,  
marked HS2/2  
(See Chart No. 1, Qf)

LNМ/D. 15-JUL-2011  
44°25'38.5"N 063°34'16.3"W  
*(F2011182) LL(508.22) DFO(6305799-01)*

This notice affects Electronic Navigational Chart:  
CA476009

**11-NOV-2011**

LNМ/D. 15-JUL-2011



**Chart no. 4385**

Add red starboard hand lighted conical buoy FIR, marked  
HS2

44°25'15.8"N 063°33'49.6"W

(See Chart No. 1, Qf)

(F2011183) LL(508.2) DFO(6305800-01)

This notice affects Electronic Navigational Chart:  
CA476009

**15-JUL-2011**

LNМ/D. 04-JUN-2010

Add rock with known depth of 5 feet, dangerous to surface navigation 44°28'42.9"N 063°35'52.7"W  
(See Chart No. 1, K14/K14.2)

DFO(6305547-02)

**04-JUN-2010**

LNМ/D. 25-SEP-2009

Amend Fl 20s 162ft 16M to read Fl 20s 157ft 10M against light  
(See Chart 1 P16)

44°30'26.6"N 063°31'21.8"W

LL(513) DFO(6304817-01)

This notice affects Electronic Navigational Chart: CA176140

**25-SEP-2009**

LNМ/D. 22-MAY-2009

Amend FG to read FlG against light  
(see Chart No 1 P16)

44°28'07.9"N 063°47'03.3"W

(F2009052) LL(492) DFO(6304559-01)

This notice affects Electronic Navigational Chart:  
CA476195

**25-SEP-2009**

LNМ/D. 22-MAY-2009

Amend F to read LFl against light  
(See Chart No 1 P16)

44°28'04.5"N 063°42'52.2"W

(F2009053) LL(499) DFO(6304560-01)

This notice affects Electronic Navigational Chart:  
CA476189

**25-SEP-2009**

LNМ/D. 22-MAY-2009



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4385

Amend F to read Fl against light  
(See Chart No 1 P16)

44°27'03.4"N 063°43'32.1"W

(F2009054) LL(496.5) DFO(6304561-01)

This notice affects Electronic Navigational Chart:  
CA476189

#### 22-MAY-2009

LNМ/D. 27-MAR-2009

Add green port hand spar buoy, marked HF1  
(See Chart No 1 Qg)

44°28'58.7"N 063°32'53.8"W

DFO(6304350-01)

This notice affects Electronic Navigational Chart: CA476009

#### 22-MAY-2009

LNМ/D. 27-MAR-2009

Add Channel Buoyed/Chenal balisé 44°29'12.0"N 063°33'18.0"W

DFO(6304350-02)

#### 27-MAR-2009

LNМ/D. 20-FEB-2009

Replace red starboard hand conical light buoy FlR, marked AM64  
with red starboard hand spar light buoy FlR, marked AM64  
(See Chart No 1 Qf)

44°28'03.3"N 063°46'49.8"W

LL(494.01) DFO(6304267-01)

This notice affects Electronic Navigational Chart: CA476195

#### 20-FEB-2009

LNМ/D. 07-NOV-2008

Add yellow, black and yellow West cardinal lighted spar  
buoy Q(9) 15s, marked AAB  
(See Chart No 1 Q130.3)

44°27'32.9"N 063°39'33.7"W

(F2008156) LL(499.9) DFO(6304216-01)

This notice affects Electronic Navigational Chart:  
CA476189

#### 20-FEB-2009

LNМ/D. 07-NOV-2008





Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4385

Add green port hand lighted can buoy FlG, marked AA55  
(See Chart No 1 Qg)

44°27'48.3"N 063°38'28.2"W

*(F2008158) LL(501.2) DFO(6304230-01)*

This notice affects Electronic Navigational Chart:  
CA476009

#### 20-FEB-2009

LNМ/D. 07-NOV-2008

Add green port hand lighted can buoy FlG, marked AA57  
(See Chart No 1 Qg)

44°28'01.9"N 063°38'15.1"W

*(F2008157) LL(501.1) DFO(6304231-01)*

This notice affects Electronic Navigational Chart:  
CA476009

#### 20-FEB-2009

LNМ/D. 07-NOV-2008

Add green, red and green port bifurcation lighted spar  
buoy Fl (2+1)G 6s, marked AAA  
(See Chart No 1 Qj)

44°27'09.9"N 063°38'55.9"W

*(F2008161) LL(501.4) DFO(6304232-01)*

This notice affects Electronic Navigational Chart:  
CA476009

#### 20-FEB-2009

LNМ/D. 07-NOV-2008

Add green port hand lighted spar buoy FlG, marked AA53  
(See Chart No 1 Qg)

44°26'48.2"N 063°39'23.6"W

*(F2008162) LL(501.5) DFO(6304233-01)*

This notice affects Electronic Navigational Chart:  
CA476189

#### 20-FEB-2009

LNМ/D. 07-NOV-2008

Add red starboard hand lighted conical buoy FlR, marked  
AA54  
(See Chart No 1 Qf)

44°27'38.0"N 063°38'30.8"W

*(F2008163) LL(501.3) DFO(6304234-01)*

This notice affects Electronic Navigational Chart:  
CA476009

#### 20-FEB-2009

LNМ/D. 07-NOV-2008



**Chart no. 4385**

Add green port hand lighted spar buoy FLG, marked AA51  
(See Chart No 1 Qg)

44°26'32.6"N 063°39'48.0"W

*(F2008164) LL(501.6) DFO(6304235-01)*

This notice affects Electronic Navigational Chart:  
CA476189

**20-FEB-2009**

LNМ/D. 07-NOV-2008

Add red starboard hand lighted spar buoy FIR, marked  
AA52  
(See Chart No 1 Qf)

44°26'10.3"N 063°39'36.6"W

*(F2008165) LL(501.7) DFO(6304236-01)*

This notice affects Electronic Navigational Chart:  
CA476189

**07-NOV-2008**

LNМ/D. 26-SEP-2008

Add light FIR against red starboard hand spar buoy,  
marked HE16  
(See Chart No 1 Q7)

44°27'33.0"N 063°32'42.0"W

*(F2008115) LL(503.1) DFO(6304045-01)*

**07-NOV-2008**

LNМ/D. 26-SEP-2008

Add light FLG against green port hand spar buoy, marked  
HE17  
(See Chart No 1 Q7)

44°28'02.0"N 063°32'47.0"W

*(F2008117) LL(503.11) DFO(6304047-01)*

**26-SEP-2008**

LNМ/D. 13-JUN-2008

(T)Add The positions of the subsurface moorings for the OTN between 44°28'42.0"N 063°32'00.0"W  
project are: and 44°26'57.8"N 063°30'03.3"W

OTN1 44° 28' 42.00" N 63° 32' 00.00" W

*DFO(6303910-01)*

OTN2 44° 28' 21.17" N 63° 31' 36.67" W

OTN3 44° 28' 00.33" N 63° 31' 13.33" W

OTN4 44° 27' 39.50" N 63° 30' 50.00" W

OTN5 44° 27' 18.67" N 63° 30' 26.67" W

OTN6 44° 26' 57.83" N 63° 30' 03.33" W

Proposed date of removal is April 2013.

Moorings permanently established. Notice

2008-09-26(T), is cancelled. See reference

DFO(6304781) appearing in this edition.

Cancelled on



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4385

### 26-SEP-2008

Amend Fl 5s 140ft 24M to read Fl 6s 140ft 23M against  
light  
(See Chart No 1 P16)

LNМ/D. 13-JUN-2008

44°26'12.0"N 063°33'48.0"W

(F2008068) LL(507) DFO(6303952-01)

This notice affects Electronic Navigational Chart:  
CA476009

### 13-JUN-2008

Add light FLR against red starboard hand conical buoy,  
marked AM64  
(See Chart No 1 Qf)

LNМ/D. 06-APR-2007

44°28'03.3"N 063°46'49.8"W

(F2004177) LL(494.01) DFO(6303852-01)

### 06-APR-2007

Delete legend "WHIS" against green port hand lighted pillar  
whistle buoy FlG, marked HE19

LNМ/D. 12-AUG-2005

44°28'19.6"N 063°32'16.0"W

(F2007028) LL(511) DFO(6303378-01)

### 12-AUG-2005

Delete light F

LNМ/D. 05-NOV-2004

44°28'02.0"N 063°46'54.0"W

(F2005049) LL(493) DFO(6302386-01)

### 05-NOV-2004

Delete legend "BELL" against green port hand pillar light  
buoy FlG, marked HD5, BELL

LNМ/D. 08-OCT-2004

44°29'00.0"N 063°31'03.0"W

(F2004127) LL(512) DFO(6301958-01)

### 08-OCT-2004

Delete legend "WHIS" against red starboard pillar light buoy  
Fl R, WHIS, marked H4

LNМ/D. 15-NOV-2002

44°31'39.5"N 063°30'03.6"W

(F2004116) LL(516) DFO(6301905-01)

### 15-NOV-2002

LNМ/D. 25-OCT-2002



### Chart no. 4385

Amend measured distance with bearing 154°20'-334°20' 6078ft to 44°31'24.0"N 063°30'37.0"W  
read 154°20'-334°20' 6118ft  
With this notification, action dated 31-MAR-2000 is cancelled. *DFO(6300609-01)*  
See reference DFO(6500084) appearing in this edition.

**25-OCT-2002** LNM/D. 23-AUG-2002  
Delete submarine cable between 44°26'49.8"N 063°35'40.2"W  
and 44°27'30.0"N 063°36'54.0"W  
*DFO(6300592-01)*

**25-OCT-2002** LNM/D. 23-AUG-2002  
Add submarine cable joining 44°26'49.8"N 063°35'40.2"W  
44°27'22.8"N 063°36'24.0"W  
and 44°27'30.0"N 063°36'54.0"W  
*DFO(6300592-02)*

**23-AUG-2002** LNM/D. 31-MAR-2000  
Add submarine cable joining 44°32'00.0"N 063°31'33.6"W  
44°31'44.3"N 063°31'12.1"W  
44°31'32.7"N 063°31'04.1"W  
44°30'57.5"N 063°30'57.2"W  
44°30'34.6"N 063°30'49.2"W  
44°30'10.1"N 063°30'27.3"W  
44°29'42.9"N 063°30'13.1"W  
44°28'54.6"N 063°30'11.0"W  
44°27'41.9"N 063°30'22.6"W  
44°27'15.1"N 063°30'23.5"W  
44°27'02.6"N 063°30'26.3"W  
44°26'25.8"N 063°30'42.3"W  
44°26'00.0"N 063°30'57.0"W  
44°25'40.1"N 063°30'58.3"W  
44°25'14.5"N 063°30'38.5"W  
44°25'05.2"N 063°30'26.5"W  
and 44°24'51.0"N 063°30'00.0"W  
*DFO(6300455-01)*

**23-AUG-2002** LNM/D. 31-MAR-2000



**Chart no. 4385**

Add submarine cable joining 44°29'32.8"N 063°33'01.1"W  
44°29'23.1"N 063°33'01.2"W  
44°29'07.8"N 063°32'53.4"W  
44°29'03.0"N 063°32'53.4"W  
44°28'37.2"N 063°32'23.7"W  
44°28'29.4"N 063°31'52.1"W  
44°27'18.2"N 063°31'07.3"W  
44°26'38.8"N 063°30'59.8"W  
44°25'51.1"N 063°31'10.7"W  
44°25'38.5"N 063°31'09.4"W  
44°25'25.0"N 063°31'03.3"W  
44°24'47.1"N 063°30'19.8"W  
and 44°24'26.0"N 063°30'00.0"W

*DFO(6300455-02)*

**23-AUG-2002**

LNM/D. 31-MAR-2000

Add submarine cable joining 44°23'02.9"N 063°30'00.0"W  
44°22'37.7"N 063°30'43.0"W  
44°22'26.4"N 063°31'14.9"W  
44°22'23.5"N 063°31'58.2"W  
44°22'09.0"N 063°32'57.8"W  
44°22'00.3"N 063°33'07.5"W  
44°21'36.4"N 063°33'25.2"W  
and 44°21'30.0"N 063°33'27.4"W

*DFO(6300455-03)*

**23-AUG-2002**

LNM/D. 31-MAR-2000



### Chart no. 4385

Add submarine cable joining 44°29'09.6"N 063°32'54.6"W  
44°29'03.6"N 063°32'54.6"W  
44°28'55.2"N 063°32'48.6"W  
44°28'36.1"N 063°32'30.0"W  
44°28'19.4"N 063°31'59.5"W  
44°26'53.0"N 063°31'12.6"W  
44°26'22.7"N 063°31'10.2"W  
44°26'09.4"N 063°31'15.0"W  
44°25'52.5"N 063°31'44.0"W  
44°25'45.2"N 063°31'50.9"W  
44°24'52.9"N 063°32'10.2"W  
44°24'23.3"N 063°32'48.1"W  
44°24'04.5"N 063°32'55.5"W  
44°23'11.0"N 063°32'48.6"W  
44°22'56.6"N 063°32'55.5"W  
44°22'33.5"N 063°33'29.0"W  
44°22'23.8"N 063°33'36.6"W  
44°22'02.0"N 063°34'19.3"W  
and 44°21'30.0"N 063°35'00.3"W

*DFO(6300455-04)*

### 31-MAR-2000

LN/D. 02-APR-1999

(P)Amend measured distance with bearing 154°20'-334°20' 6078ft to 44°31'24.0"N 063°30'37.0"W  
read 154°20'-334°20' 6118ft

*DFO(6500084-01)*

The Preliminary action dated 31-MAR-2000, is now a permanent action. See reference DFO(6300609) appearing in this edition.

Cancelled on 15-NOV-02