



### Chart no. 4394

## 4394 - LaHave River: West Ironbound Island to / à Riverport - New Edition - 26-JUL-2002 - NAD 1983

**11-FEB-2022** LNM/D. 17-DEC-2021

Add black and yellow North cardinal spar buoy, marked TSB 44°14'51.5"N 064°21'40.3"W  
(See Chart No. 1, Q130.3)

*(F2021069) DFO(6309908-01)*

**11-FEB-2022** LNM/D. 17-DEC-2021

Add black and yellow North cardinal spar buoy, marked TSC 44°14'39.6"N 064°22'07.1"W  
(See Chart No. 1, Q130.3)

*(F2021070) DFO(6309909-01)*

**11-FEB-2022** LNM/D. 17-DEC-2021

Add red starboard hand spar buoy, marked TS74 44°14'21.2"N 064°22'37.0"W  
(See Chart No. 1, Qf)

*(F2021071) DFO(6309910-01)*

**11-FEB-2022** LNM/D. 17-DEC-2021

Add green port hand spar buoy, marked TS75 44°14'21.0"N 064°22'42.7"W  
(See Chart No. 1, Qg)

*(F2021072) DFO(6309911-01)*

**11-FEB-2022** LNM/D. 17-DEC-2021

Delete red starboard hand conical buoy, marked TK60 44°14'52.6"N 064°23'01.7"W  
(See Chart No. 1, Qf)

*(F2021073) DFO(6309912-01)*

**11-FEB-2022** LNM/D. 17-DEC-2021

Add green port hand spar buoy, marked TS77 44°14'35.1"N 064°22'54.0"W  
(See Chart No. 1, Qg)

*(F2021074) DFO(6309913-01)*

**11-FEB-2022** LNM/D. 17-DEC-2021

Add red starboard hand spar buoy, marked TS78 44°14'49.3"N 064°22'54.5"W  
(See Chart No. 1, Qf)

*(F2021075) DFO(6309914-01)*



### Chart no. 4394

- 11-FEB-2022** LNM/D. 17-DEC-2021  
Delete green port hand can buoy, marked TK55 44°15'07.4"N 064°22'42.3"W  
(See Chart No. 1, Qg)  
(F2021083) DFO(6309917-01)
- 11-FEB-2022** LNM/D. 17-DEC-2021  
Delete green port hand can buoy, marked TK51 44°15'30.9"N 064°22'07.3"W  
(See Chart No. 1, Qg)  
(F2021084) DFO(6309918-01)
- 11-FEB-2022** LNM/D. 17-DEC-2021  
Add yellow and black South cardinal spar buoy, marked TSD 44°14'52.6"N 064°23'01.7"W  
(See Chart No. 1, Q130.3)  
(F2021076) DFO(6309958-01)
- 11-FEB-2022** LNM/D. 17-DEC-2021  
Add red starboard hand spar buoy, marked TS80 44°14'57.7"N 064°22'54.2"W  
(See Chart No. 1, Qf)  
(F2021077) DFO(6309959-01)
- 11-FEB-2022** LNM/D. 17-DEC-2021  
Add red starboard hand spar buoy, marked TS82 44°15'07.4"N 064°22'43.8"W  
(See Chart No. 1, Qf)  
(F2021078) DFO(6309960-01)
- 11-FEB-2022** LNM/D. 17-DEC-2021  
Add green port hand spar buoy, marked TS83 44°15'31.2"N 064°22'09.8"W  
(See Chart No. 1, Qg)  
(F2021079) DFO(6309961-01)
- 11-FEB-2022** LNM/D. 17-DEC-2021  
Add red starboard hand spar buoy, marked TS84 44°15'31.0"N 064°22'06.2"W  
(See Chart No. 1, Qf)  
(F2021080) DFO(6309980-01)
- 17-DEC-2021** LNM/D. 20-AUG-2021



### Chart no. 4394

Add red starboard hand lighted spar buoy Fl R, marked TS56 44°13'31.9"N 064°22'51.3"W  
(See Chart No. 1, Qf) (F2021049) LL(421.2) DFO(6309832-01)

**17-DEC-2021** LNM/D. 20-AUG-2021

Add red starboard hand spar buoy, marked TS58 44°13'36.8"N 064°22'44.8"W  
(See Chart No. 1, Qf) (F2021050) DFO(6309833-01)

**17-DEC-2021** LNM/D. 20-AUG-2021

Add green port hand lighted spar buoy Fl G, marked TS65 44°14'22.5"N 064°21'58.5"W  
(See Chart No. 1, Qg) (F2021051) LL(424.1) DFO(6309834-01)

**17-DEC-2021** LNM/D. 20-AUG-2021

Delete red starboard hand spar buoy, marked TN60 44°13'37.8"N 064°22'46.2"W  
(See Chart No. 1, Qf) (F2021052) DFO(6309835-01)

**17-DEC-2021** LNM/D. 20-AUG-2021

Delete green port hand spar buoy, marked TN57 44°13'47.1"N 064°22'39.7"W  
(See Chart No. 1, Qg) (F2021053) DFO(6309836-01)

**17-DEC-2021** LNM/D. 20-AUG-2021

Delete green port hand spar buoy, marked TN61 44°13'31.9"N 064°22'51.1"W  
(See Chart No. 1, Qg) (F2021055) DFO(6309838-01)

**17-DEC-2021** LNM/D. 20-AUG-2021

Add red starboard hand spar buoy, marked TS60 44°13'47.5"N 064°22'39.1"W  
(See Chart No. 1, Qf) (F2021056) DFO(6309839-01)

**17-DEC-2021** LNM/D. 20-AUG-2021

Delete red starboard hand spar buoy, marked TN56 44°13'51.0"N 064°22'29.8"W  
(See Chart No. 1, Qf) (F2021057) DFO(6309840-01)



### Chart no. 4394

- 17-DEC-2021** LNM/D. 20-AUG-2021  
Delete green port hand lighted pillar buoy FlG, marked 44°14'03.8"N 064°22'08.2"W  
TN51  
(See Chart No. 1, Qg) (F2021058) LL(423.6) DFO(6309841-01)
- 17-DEC-2021** LNM/D. 20-AUG-2021  
Delete green port hand can buoy, marked TP51 44°14'37.7"N 064°22'09.6"W  
(See Chart No. 1, Qg) (F2021059) DFO(6309842-01)
- 17-DEC-2021** LNM/D. 20-AUG-2021  
Add green port hand lighted spar buoy Fl G, marked TS61 44°13'50.9"N 064°22'29.9"W  
(See Chart No. 1, Qg) (F2021060) LL(421.5) DFO(6309844-01)
- 17-DEC-2021** LNM/D. 20-AUG-2021  
Add red starboard hand spar buoy, marked TS62 44°13'56.7"N 064°22'21.1"W  
(See Chart No. 1, Qf) (F2021061) DFO(6309845-01)
- 17-DEC-2021** LNM/D. 20-AUG-2021  
Add green port hand spar buoy, marked TS63 44°14'04.7"N 064°22'08.7"W  
(See Chart No. 1, Qg) (F2021062) DFO(6309846-01)
- 17-DEC-2021** LNM/D. 20-AUG-2021  
Add red starboard hand lighted pillar buoy Fl R, marked 44°14'03.9"N 064°22'08.2"W  
TS64  
(See Chart No. 1, Qf) (F2021063) LL(423.8) DFO(6309847-01)
- 17-DEC-2021** LNM/D. 20-AUG-2021  
Delete green port hand can buoy, marked TM51 44°14'25.6"N 064°22'05.2"W  
(See Chart No. 1, Qg) (F2021064) DFO(6309848-01)
- 17-DEC-2021** LNM/D. 20-AUG-2021



### Chart no. 4394

Add green port hand can buoy, marked TS67 44°14'25.9"N 064°22'05.3"W  
(See Chart No. 1, Qg)

(F2021064) DFO(6309848-02)

**17-DEC-2021**

LNМ/D. 20-AUG-2021

Add red starboard hand conical buoy, marked TS68 44°14'27.0"N 064°22'08.0"W  
(See Chart No. 1, Qf)

(F2021065) DFO(6309849-01)

**17-DEC-2021**

LNМ/D. 20-AUG-2021

Delete red starboard hand conical buoy, marked TM54 44°14'28.0"N 064°22'11.8"W  
(See Chart No. 1, Qf)

(F2021066) DFO(6309850-01)

**17-DEC-2021**

LNМ/D. 20-AUG-2021

Add red starboard hand lighted spar buoy Fl R, marked  
TS70  
(See Chart No. 1, Qf)

44°14'28.4"N 064°22'11.8"W

(F2021066) LL(424.7) DFO(6309850-02)

**17-DEC-2021**

LNМ/D. 20-AUG-2021

Add green port hand spar buoy, marked TS59 44°13'37.6"N 064°22'45.9"W  
(See Chart No. 1, Qg)

(F2021067) DFO(6309881-01)

**17-DEC-2021**

LNМ/D. 20-AUG-2021

Delete green port hand can buoy, marked TM55 44°14'31.3"N 064°22'14.5"W  
(See Chart No. 1, Qg)

(F2021068) DFO(6309882-01)

**17-DEC-2021**

LNМ/D. 20-AUG-2021

Add green port hand can buoy, marked TS71 44°14'31.4"N 064°22'14.7"W  
(See Chart No. 1, Qg)

(F2021068) DFO(6309882-02)

**20-AUG-2021**

LNМ/D. 18-DEC-2020

Delete legend Fog Sig 20s against light  
(See Chart No 1 R20)

44°14'14.8"N 064°18'58.9"W

This notice affects Electronic Navigational Chart: (F2021038) LL(423) DFO(6309461-01)  
CA276801, CA476664



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4394

**20-AUG-2021**

Amend F77ft11M to read F 76ft13M against light  
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart: CA276801,  
CA476664

LNM/D. 18-DEC-2020

44°14'14.8"N 064°18'58.9"W

*LL(423) DFO(6309461-02)*

**18-DEC-2020**

Add depth of 13 feet

(See Chart No. 1, I10)

LNM/D. 27-MAR-2020

44°17'48.5"N 064°21'25.7"W

*DFO(6309301-02)*

**18-DEC-2020**

Replace depth of 24 feet with depth of 18 feet 44°17'56.7"N 064°21'13.5"W  
(See Chart No. 1, I10)

LNM/D. 27-MAR-2020

*DFO(6309301-05)*

**18-DEC-2020**

Replace depth of 38 feet with depth of 31 feet 44°17'54.4"N 064°21'12.9"W  
(See Chart No. 1, I10)

LNM/D. 27-MAR-2020

*DFO(6309301-06)*

**18-DEC-2020**

Replace depth of 30 feet with depth of 20 feet 44°17'52.5"N 064°21'08.6"W  
(See Chart No. 1, I10)

LNM/D. 27-MAR-2020

*DFO(6309301-07)*

**18-DEC-2020**

Replace depth of 18 feet with depth of 14 feet  
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA476664

LNM/D. 27-MAR-2020

44°15'50.6"N 064°21'51.7"W

*DFO(6309301-11)*

**18-DEC-2020**

Replace depth of 20 feet with depth of 16 feet 44°15'47.5"N 064°21'48.7"W  
(See Chart No. 1, I10)

LNM/D. 27-MAR-2020

*DFO(6309301-12)*

**18-DEC-2020**

LNM/D. 27-MAR-2020



### Chart no. 4394

Replace depth of 30 feet with depth of 26 feet 44°15'49.1"N 064°21'34.0"W  
(See Chart No. 1, I10)

*DFO(6309301-13)*

**18-DEC-2020**

LNМ/D. 27-MAR-2020

Replace depth of 27 feet with depth of 20 feet 44°15'47.4"N 064°21'36.7"W  
(See Chart No. 1, I10)

*DFO(6309301-14)*

**18-DEC-2020**

LNМ/D. 27-MAR-2020

Replace depth of 27 feet with depth of 22 feet 44°15'37.1"N 064°21'05.3"W  
(See Chart No. 1, I10)

*DFO(6309301-16)*

**18-DEC-2020**

LNМ/D. 27-MAR-2020

Replace depth of 26 feet with depth of 22 feet 44°15'34.2"N 064°21'06.0"W  
(See Chart No. 1, I10)

*DFO(6309301-17)*

**18-DEC-2020**

LNМ/D. 27-MAR-2020

Replace depth of 24 feet with depth of 18 feet 44°15'23.3"N 064°21'03.0"W  
(See Chart No. 1, I10)

*DFO(6309301-18)*

**18-DEC-2020**

LNМ/D. 27-MAR-2020

Replace depth of 25 feet with depth of 20 feet 44°15'36.9"N 064°20'50.7"W  
(See Chart No. 1, I10)

*DFO(6309301-20)*

**18-DEC-2020**

LNМ/D. 27-MAR-2020

Replace depth of 25 feet with depth of 21 feet 44°15'35.4"N 064°20'53.6"W  
(See Chart No. 1, I10)

*DFO(6309301-21)*

**18-DEC-2020**

LNМ/D. 27-MAR-2020

Replace depth of 25 feet with depth of 21 feet  
(See Chart No. 1, I10)

44°15'34.2"N 064°20'51.0"W

This notice affects Electronic Navigational Chart: CA476664

*DFO(6309301-22)*



**Chart no. 4394**

**18-DEC-2020**

LNM/D. 27-MAR-2020

Replace depth of 26 feet with depth of 22 feet  
(See Chart No. 1, I10)

44°15'32.4"N 064°20'54.5"W

This notice affects Electronic Navigational Chart: CA476664

*DFO(6309301-23)*

**18-DEC-2020**

LNM/D. 27-MAR-2020

Replace depth of 26 feet with depth of 22 feet 44°15'32.3"N 064°20'50.7"W  
(See Chart No. 1, I10)

*DFO(6309301-24)*

**18-DEC-2020**

LNM/D. 27-MAR-2020

Replace depth of 25 feet with depth of 21 feet 44°15'32.2"N 064°20'41.4"W  
(See Chart No. 1, I10)

*DFO(6309301-26)*

**18-DEC-2020**

LNM/D. 27-MAR-2020

Replace depth of 25 feet with depth of 20 feet 44°15'31.3"N 064°20'29.7"W  
(See Chart No. 1, I10)

*DFO(6309301-27)*

**18-DEC-2020**

LNM/D. 27-MAR-2020

Delete depth of 13 feet 44°17'23.3"N 064°20'50.3"W  
(See Chart No. 1, I10)

*DFO(6309301-30)*

**18-DEC-2020**

LNM/D. 27-MAR-2020

Add depth of 2 feet 44°17'23.1"N 064°20'49.8"W  
(See Chart No. 1, I10)

*DFO(6309301-31)*

**18-DEC-2020**

LNM/D. 27-MAR-2020

Replace depth of 26 feet with depth of 22 feet 44°15'36.9"N 064°21'00.6"W  
(See Chart No. 1, I10)

*DFO(6309301-32)*

**18-DEC-2020**

LNM/D. 27-MAR-2020





### Chart no. 4394

Replace depth of 26 feet with depth of 22 feet 44°15'32.5"N 064°20'59.2"W  
(See Chart No. 1, I10)

*DFO(6309301-33)*

**18-DEC-2020**

LNM/D. 27-MAR-2020

Replace depth of 13 feet with depth of 2 feet 44°15'59.7"N 064°21'49.3"W  
(See Chart No. 1, I10)

*DFO(6309301-34)*

**27-MAR-2020**

LNM/D. 25-AUG-2017

Amend Fl 12s80ft8M to read LFl 12s77ft8M against light  
(See Chart No. 1, P16)

44°13'43.6"N 064°16'27.5"W

This notice affects Electronic Navigational Chart:  
CA276801, CA476664

*(F2020003) LL(432) DFO(6308940-01)*

**25-AUG-2017**

LNM/D. 05-AUG-2016

Replace depth of 14 feet with depth of 7 feet  
(See Chart No. 1, I10)

44°14'45.7"N 064°21'56.2"W

This notice affects Electronic Navigational Chart: CA476664

*DFO(6308029-01)*

**25-AUG-2017**

LNM/D. 05-AUG-2016

Delete depth of 23 feet 44°14'41.0"N 064°22'05.1"W  
(See Chart No. 1, I10)

*DFO(6308029-02)*

**25-AUG-2017**

LNM/D. 05-AUG-2016

Add depth of 15 feet 44°14'40.5"N 064°22'06.3"W  
(See Chart No. 1, I10)

*DFO(6308029-03)*

**25-AUG-2017**

LNM/D. 05-AUG-2016

Replace depth of 22 feet with depth of 6 feet 44°14'31.3"N 064°22'11.4"W  
(See Chart No. 1, I10)

*DFO(6308029-04)*

**25-AUG-2017**

LNM/D. 05-AUG-2016

Replace depth of 17 feet with depth of 5 feet 44°14'28.9"N 064°22'10.3"W  
(See Chart No. 1, I10)

*DFO(6308029-08)*



**Chart no. 4394**

**25-AUG-2017** LNM/D. 05-AUG-2016

Add depth of 1 foot 44°14'27.5"N 064°22'08.0"W  
(See Chart No. 1, I10)

*DFO(6308029-09)*

**25-AUG-2017** LNM/D. 05-AUG-2016

Delete depth of 33 feet 44°14'27.4"N 064°22'08.0"W  
(See Chart No. 1, I10)

*DFO(6308029-10)*

**05-AUG-2016** LNM/D. 17-JUN-2016

Replace depth of 28 feet with depth of 19 feet 44°15'40.2"N 064°21'08.0"W  
(See Chart No. 1, I10)

*DFO(6307649-01)*

**05-AUG-2016** LNM/D. 17-JUN-2016

Replace depth of 27 feet with depth of 16 feet 44°15'41.1"N 064°21'11.6"W  
(See Chart No. 1, I10)

*DFO(6307649-02)*

**05-AUG-2016** LNM/D. 17-JUN-2016

Replace depth of 27 feet with depth of 13 feet 44°15'42.5"N 064°21'18.1"W  
(See Chart No. 1, I10)

*DFO(6307649-03)*

**17-JUN-2016** LNM/D. 06-MAY-2016

Amend Fl to read Q(6)+LFl 15s against light 44°16'01.3"N 064°21'50.5"W  
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart: *(F2016017) LL(428) DFO(6307540-01)*  
CA476664

**06-MAY-2016** LNM/D. 19-FEB-2016

Replace depth of 23 feet with depth of 16 feet 44°15'28.6"N 064°20'08.6"W  
(See Chart No. 1, I10)

*DFO(6307499-01)*

**06-MAY-2016** LNM/D. 19-FEB-2016



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4394

Replace depth of 30 feet with depth of 16 feet 44°15'46.8"N 064°21'29.2"W  
(See Chart No. 1, I10)

*DFO(6307499-05)*

**06-MAY-2016** LNM/D. 19-FEB-2016

Add depth of 11 feet 44°15'55.4"N 064°20'07.6"W  
(See Chart No. 1, I10)

*DFO(6307499-06)*

**06-MAY-2016** LNM/D. 19-FEB-2016

Replace depth of 22 feet with depth of 16 feet 44°15'50.4"N 064°19'57.5"W  
(See Chart No. 1, I10)

*DFO(6307499-07)*

**06-MAY-2016** LNM/D. 19-FEB-2016

Replace depth of 19 feet with depth of 10 feet 44°15'53.4"N 064°20'20.0"W  
(See Chart No. 1, I10)

*DFO(6307499-08)*

**19-FEB-2016** LNM/D. 28-NOV-2014

Delete red starboard hand spar buoy, marked T60 44°16'18.3"N 064°21'07.8"W  
(See Chart No. 1, Qf)

*(F2015036) DFO(6307414-01)*

**19-FEB-2016** LNM/D. 28-NOV-2014

Add red starboard hand spar buoy, marked T62 44°16'19.0"N 064°21'07.9"W  
(See Chart No. 1, Qf)

*(F2015036) DFO(6307414-02)*

**19-FEB-2016** LNM/D. 28-NOV-2014

Reposition green port hand lighted pillar buoy Fl G, marked from 44°16'15.3"N 064°21'19.7"W  
T59 to 44°16'14.4"N 064°21'17.2"W  
(See Chart No. 1, Qg)

*(F2015038) LL(429) DFO(6307414-03)*

**19-FEB-2016** LNM/D. 28-NOV-2014

Add red starboard hand lighted pillar buoy FlR, marked 44°16'13.3"N 064°21'14.7"W  
T60  
(See Chart No. 1, Qf)

*(F2015039) LL(429.2) DFO(6307414-04)*



### Chart no. 4394

**28-NOV-2014** LNM/D. 29-MAR-2013

Affix patch 44°16'45.0"N 064°20'50.0"W  
[PDF](#)

*DFO(6306969-17)*

**29-MAR-2013** LNM/D. 13-MAY-2011

Add submarine cable between 44°14'00.9"N 064°22'17.5"W  
(See Chart No. 1, L31.1) and 44°13'59.4"N 064°22'15.3"W

*DFO(6306333-01)*

**13-MAY-2011** LNM/D. 01-MAY-2009

Delete depth of 21 feet 44°13'34.8"N 064°22'49.3"W  
(See Chart No. 1, I10)

*DFO(6305432-01)*

**13-MAY-2011** LNM/D. 01-MAY-2009

Delete depth of 21 feet 44°13'36.3"N 064°22'46.8"W  
(See Chart No. 1, I10)

*DFO(6305432-02)*

**13-MAY-2011** LNM/D. 01-MAY-2009

Delete depth of 18 feet 44°13'35.1"N 064°22'47.4"W  
(See Chart No. 1, I10)

*DFO(6305432-03)*

**13-MAY-2011** LNM/D. 01-MAY-2009

Delete depth of 20 feet 44°13'37.4"N 064°22'44.9"W  
(See Chart No. 1, I10)

*DFO(6305432-04)*

**13-MAY-2011** LNM/D. 01-MAY-2009

Delete depth of 21 feet 44°14'32.1"N 064°22'14.5"W  
(See Chart No. 1, I10)

*DFO(6305432-05)*

**13-MAY-2011**

LNM/D. 01-MAY-2009



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4394

Delete depth of 9 feet  
(See Chart No. 1, I10)

44°14'04.6"N 064°22'06.6"W

*DFO(6305432-07)*

This notice affects Electronic Navigational Chart: CA476664

**13-MAY-2011**

LNМ/D. 01-MAY-2009

Delete depth of 18 feet  
(See Chart No. 1, I10)

44°14'45.0"N 064°21'57.8"W

*DFO(6305432-08)*

**13-MAY-2011**

LNМ/D. 01-MAY-2009

Delete depth of 17 feet  
(See Chart No. 1, I10)

44°13'53.3"N 064°22'25.6"W

*DFO(6305432-09)*

**13-MAY-2011**

LNМ/D. 01-MAY-2009

Delete depth of 16 feet  
(See Chart No. 1, I10)

44°13'51.9"N 064°22'25.5"W

*DFO(6305432-10)*

**13-MAY-2011**

LNМ/D. 01-MAY-2009

Add depth of 12 feet  
(See Chart No. 1, I10)

44°13'34.8"N 064°22'48.5"W

*DFO(6305432-12)*

This notice affects Electronic Navigational Chart: CA476664

**13-MAY-2011**

LNМ/D. 01-MAY-2009

Add depth of 15 feet  
(See Chart No. 1, I10)

44°13'36.1"N 064°22'47.4"W

*DFO(6305432-13)*

**13-MAY-2011**

LNМ/D. 01-MAY-2009

Add depth of 10 feet  
(See Chart No. 1, I10)

44°14'32.0"N 064°22'13.8"W

*DFO(6305432-14)*

This notice affects Electronic Navigational Chart: CA476664



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4394

**13-MAY-2011**

Add depth of 5 feet  
(See Chart No. 1, I10)

LNМ/D. 01-MAY-2009

44°14'04.3"N 064°22'06.7"W

*DFO(6305432-15)*

This notice affects Electronic Navigational Chart: CA476664

**13-MAY-2011**

Add depth of 14 feet  
(See Chart No. 1, I10)

LNМ/D. 01-MAY-2009

44°14'45.7"N 064°21'56.5"W

*DFO(6305432-16)*

This notice affects Electronic Navigational Chart: CA476664

**13-MAY-2011**

Add depth of 10 feet  
(See Chart No. 1, I10)

LNМ/D. 01-MAY-2009

44°13'53.2"N 064°22'25.6"W

*DFO(6305432-17)*

This notice affects Electronic Navigational Chart: CA476664

**01-MAY-2009**

Amend FR to read Fl against light  
(See Chart No 1 P16)

LNМ/D. 05-SEP-2008

44°16'01.2"N 064°21'50.2"W

*(F2009004) LL(428) DFO(6304319-01)*

This notice affects Electronic Navigational Chart:  
CA476664

**05-SEP-2008**

Amend FR to read FIR against light  
(See Chart No 1 P16)

LNМ/D. 13-JUN-2008

44°17'24.9"N 064°20'47.1"W

*(F2008030) LL(431.5) DFO(6303915-01)*

**13-JUN-2008**

Replace red starboard hand lighted pillar bell buoy QR,  
marked T54 with red, green and red starboard  
bifurcation lighted pillar bell buoy Fl(2+1) 6s,  
marked TD

LNМ/D. 04-APR-2008

44°15'30.4"N 064°20'15.7"W

*(F2008010) LL(426) DFO(6303849-01)*



### Chart no. 4394

#### 04-APR-2008

LNM/D. 14-DEC-2007

Delete BELL against green port hand lighted pillar bell buoy  
FlG, marked T63  
(See Chart No 1 Qg)

44°16'22.4"N 064°20'54.8"W

(F2008005) LL(430) DFO(6303828-01)

#### 14-DEC-2007

LNM/D. 05-MAR-2004

Delete red starboard hand lighted pillar buoy FIR, marked  
T56  
(See Chart No 1 Qf)

44°15'45.3"N 064°21'34.8"W

(F2007101) LL(427) DFO(6303716-01)

#### 14-DEC-2007

LNM/D. 05-MAR-2004

Add red starboard hand lighted pillar buoy QR, marked T56  
(See Chart No 1 Qf)

44°15'50.6"N 064°21'32.8"W

(F2007101) LL(427) DFO(6303716-02)

#### 14-DEC-2007

LNM/D. 05-MAR-2004

Delete green port hand spar buoy, marked TD51  
(See Chart No 1 Qg)

44°15'43.3"N 064°20'40.5"W

(F2007102) DFO(6303717-01)

#### 14-DEC-2007

LNM/D. 05-MAR-2004

Add green port hand can buoy, marked TD51  
(See Chart No 1 Qg)

44°15'57.0"N 064°20'46.0"W

(F2007102) LL(5426.01) DFO(6303717-02)

#### 14-DEC-2007

LNM/D. 05-MAR-2004

Add red starboard hand lighted spar buoy FIR, marked  
T54/2  
(See Chart No 1 Qf)

44°15'41.8"N 064°21'26.3"W

(F2007109) LL(426.5) DFO(6303739-01)

#### 05-MAR-2004

LNM/D. 02-MAY-2003

Add dangerous wreck, depth unknown 44°14'36.0"N 064°19'48.0"W

DFO(6301065-01)

#### 02-MAY-2003



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### **Chart no. 4394**

Delete vertical clearance of 30 feet 44°14'29.5"N 064°21'37.7"W

*DFO(6829358-01)*

### **02-MAY-2003**

Replace power transmission line with submarine power cable between 44°14'28.4"N 064°21'36.5"W  
and 44°14'25.4"N 064°21'31.7"W

*DFO(6829358-02)*

### **02-MAY-2003**

Add vertical clearance of 11 feet 44°14'20.2"N 064°21'24.9"W

*DFO(6829358-03)*

### **02-MAY-2003**

Delete power transmission line between 44°14'24.5"N 064°21'29.5"W  
and 44°14'21.5"N 064°21'24.5"W

*DFO(6829358-04)*

### **02-MAY-2003**

Add power transmission line between 44°14'22.9"N 064°21'31.1"W  
and 44°14'22.0"N 064°21'25.6"W

*DFO(6829358-05)*