



### Chart no. 4509

#### 4509 - Cape Norman Bay and / et Cooks Harbour - New Edition - 06-JUN-2003 - Unknown

**13-JAN-2023**

LNМ/D. 18-MAR-2022

Add red starboard hand lighted pillar buoy Fl R, marked  
XC2

51°37'53.1"N 055°50'26.4"W

(See Chart 1, Qb)

(N2022294) LL(233.14) DFO(6310535-01)

This notice affects Electronic Navigational Chart:  
CA376094

**18-MAR-2022**

LNМ/D. 25-APR-2014

Delete green port hand lighted spar buoy FlG, marked  
XC1

51°37'06.7"N 055°49'57.0"W

(See Chart No. 1, Qg)

(N2022018) LL(233.2) DFO(6310020-01)

**18-MAR-2022**

LNМ/D. 25-APR-2014

Add green port hand lighted spar buoy Fl G, marked XC1  
(See Chart No. 1, Qg)

51°37'15.5"N 055°49'32.7"W

(N2022018) LL(233.2) DFO(6310020-02)

**25-APR-2014**

LNМ/D. 06-AUG-2010

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R1, R20)

51°38'04.0"N 055°54'37.5"W

This notice affects Electronic Navigational Chart:  
CA376094

(N2014024) LL(223) DFO(6306720-01)

**06-AUG-2010**

Delete green port hand lighted spar buoy FlG, marked  
XC7

51°36'41.0"N 055°52'00.0"W

(See Chart No 1 Qg)

(N2010016) LL(232.22) DFO(6304978-01)

**06-AUG-2010**

Delete green port hand lighted spar buoy FlG, marked  
XC5

51°36'43.0"N 055°51'54.0"W

(See Chart No 1 Qg)

(N2010016) LL(233.21) DFO(6304978-02)

**06-AUG-2010**



### Chart no. 4509

Delete red starboard hand lighted spar buoy FlR, 51°36'45.0"N 055°51'30.0"W  
marked XC4  
(See Chart No 1 Qg) (N2010016) LL(233.17) DFO(6304978-03)

#### 06-AUG-2010

Delete red starboard hand lighted spar buoy FlR, 51°37'52.0"N 055°51'09.0"W  
marked XC2  
(See Chart No 1 Qg) (N2010016) LL(233.18) DFO(6304978-04)

#### 06-AUG-2010

Add Channel Buoyed/Chenal balisé 51°37'00.0"N 055°50'55.0"W  
DFO(6304978-05)

### 4509 - Pistolet Bay - New Edition - 06-JUN-2003 - Unknown

#### 13-JAN-2023

Add red starboard hand lighted pillar buoy Fl R, marked LNM/D. 18-MAR-2022  
XC2 51°37'53.0"N 055°50'26.7"W  
(See Chart 1, Qb) (N2022294) LL(233.14) DFO(6310535-01)  
This notice affects Electronic Navigational Chart:  
CA376094

#### 18-MAR-2022

Delete green port hand lighted spar buoy FlG, marked LNM/D. 25-APR-2014  
XC1 51°37'07.0"N 055°49'55.0"W  
(See Chart No. 1, Qg) (N2022018) LL(233.2) DFO(6310020-01)

#### 18-MAR-2022

Add green port hand lighted spar buoy Fl G, marked XC1 LNM/D. 25-APR-2014  
(See Chart No. 1, Qg) 51°37'15.5"N 055°49'32.7"W  
(N2022018) LL(233.2) DFO(6310020-02)

#### 25-APR-2014

LNM/D. 06-AUG-2010



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4509

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R1, R20) 51°38'04.4"N 055°54'37.5"W  
This notice affects Electronic Navigational Chart: *(N2014024) LL(223) DFO(6306720-01)*  
CA376094

#### 06-AUG-2010

Delete green port hand lighted spar buoy FlG, marked 51°36'41.0"N 055°52'00.0"W  
XC7 *(N2010016) LL(232.22) DFO(6304978-01)*  
(See Chart No 1 Qg)

#### 06-AUG-2010

Delete green port hand lighted spar buoy FlG, marked 51°36'43.0"N 055°51'54.0"W  
XC5 *(N2010016) LL(233.21) DFO(6304978-02)*  
(See Chart No 1 Qg)

#### 06-AUG-2010

Delete red starboard hand lighted spar buoy FlR, 51°36'45.0"N 055°51'30.0"W  
marked XC4 *(N2010016) LL(233.17) DFO(6304978-03)*  
(See Chart No 1 Qg)

#### 06-AUG-2010

Delete red starboard hand lighted spar buoy FlR, 51°36'52.0"N 055°51'09.0"W  
marked XC2 *(N2010016) LL(233.18) DFO(6304978-04)*  
(See Chart No 1 Qg)