



Chart no. 4530

4530 - Carmanville - New Edition - 15-MAR-2002 - NAD 1983

18-MAR-2022

Replace green port hand lighted pillar buoy Fl G, marked DC7 with green port hand lighted spar buoy Fl G, marked DC7.
(See Chart No. 1, Qg)

LNМ/D. 31-DEC-2021
49°24'46.9"N 054°16'11.6"W
(N2022014) LL(390) DFO(6310016-01)

31-DEC-2021

Delete green port hand lighted spar buoy Fl G, marked DC13
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476813, CA576280

LNМ/D. 08-OCT-2021
49°23'34.9"N 054°16'54.6"W
(N2021171) LL(390.131) DFO(6309893-01)

31-DEC-2021

Add black, red and black isolated danger lighted spar buoy Fl(2)5s, marked DC
(See Chart No. 1, Q130.4)
This notice affects Electronic Navigational Chart: CA476813, CA576280

LNМ/D. 08-OCT-2021
49°23'34.9"N 054°16'54.6"W
(N2021171) LL(390.131) DFO(6309893-02)

28-OCT-2011

Add yellow cautionary lighted spar buoy Fl Y, marked DCK
(See Chart No. 1, Qm)

LNМ/D. 10-DEC-2010
49°24'12.6"N 054°16'57.5"W
(N2011082) LL(390.15) DFO(6305784-01)

This notice affects Electronic Navigational Chart: CA576280

10-DEC-2010

Delete depth of 6 metres, 7 decimetres
(See Chart No 1 I10)

LNМ/D. 01-OCT-2010
49°23'53.3"N 054°16'55.7"W
DFO(6305132-04)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010

LNМ/D. 01-OCT-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4530

Add depth of 5 metres, 5 decimetres
(See Chart No 1 I10)

49°23'53.9"N 054°16'55.0"W

DFO(6305132-05)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

LNM/D. 01-OCT-2010

Add depth of 3 metres, 9 decimetres
(See Chart No 1 I10)

49°23'50.7"N 054°16'46.9"W

DFO(6305132-06)

This notice affects Electronic Navigational Chart: CA576280

10-DEC-2010

LNM/D. 01-OCT-2010

Add depth of 7 metres, 3 decimetres
(See Chart No 1 I10)

49°24'40.9"N 054°16'13.7"W

DFO(6305132-08)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

LNM/D. 01-OCT-2010

Add depth of 8 metres, 3 decimetres
(See Chart No 1 I10)

49°25'20.2"N 054°15'39.9"W

DFO(6305132-10)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

LNM/D. 01-OCT-2010

Delete depth of 3 metres, 7 decimetres
(See Chart No 1 I10)

49°24'16.9"N 054°16'17.9"W

DFO(6305132-11)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

LNM/D. 01-OCT-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4530

Add depth of 2 metres, 1 decimetre
(See Chart No 1 I10)

49°24'16.0"N 054°16'17.7"W

DFO(6305132-12)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

4530 - Hamilton Sound: Eastern Portion / Partie-est - New Edition - 15-MAR-2002 - NAD 1983

18-MAR-2022

LNM/D. 31-DEC-2021

Replace green port hand lighted pillar buoy Fl G, marked
DC7 with green port hand lighted spar buoy Fl G,
marked DC7.
(See Chart No. 1, Qg)

49°24'46.9"N 054°16'11.6"W

(N2022014) LL(390) DFO(6310016-01)

31-DEC-2021

LNM/D. 08-OCT-2021

Add black, red and black isolated danger lighted spar
buoy Fl(2)5s, marked DC
(See Chart No. 1, Q130.4)
This notice affects Electronic Navigational Chart:
CA476813, CA576280

49°23'34.9"N 054°16'54.6"W

(N2021171) LL(390.131) DFO(6309893-02)

08-OCT-2021

LNM/D. 10-SEP-2021

Reposition red starboard hand lighted pillar buoy Fl R,
marked DX8
(See Chart No. 1, Qf)
This notice affects Electronic Navigational
Chart: CA476813

from 49°33'33.8"N 054°17'03.6"W
to 49°33'34.1"N 054°17'12.3"W

(N2021058) LL(373) DFO(6309538-01)

08-OCT-2021

LNM/D. 10-SEP-2021

Add black, yellow and black East cardinal lighted spar
buoy Q(3)10s, marked DX
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart:
CA476813

49°34'07.7"N 054°15'55.5"W

(N2021096) LL(372.6) DFO(6309570-01)

10-SEP-2021

LNM/D. 25-SEP-2020



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4530

Amend Fl R to read Fl against light 49°27'36.2"N 053°57'19.7"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (N2021049) LL(396.75) DFO(6309530-01)
CA376655, CA476279, CA576504

10-SEP-2021 LNM/D. 25-SEP-2020
Amend Oc G to read Fl G against light 49°27'23.1"N 053°56'28.5"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (N2021062) LL(399) DFO(6309541-01)
CA376655, CA476279

25-SEP-2020 LNM/D. 17-AUG-2018
Amend Fl 6s9m to read Fl 4s10m against light 49°26'55.9"N 054°13'41.6"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (N2020073) LL(389) DFO(6309151-01)
CA376655, CA476813

17-AUG-2018 LNM/D. 15-SEP-2017
Add light Fl R 49°27'36.2"N 053°57'19.7"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (N2018038) LL(396.75) DFO(6308330-01)
CA376655, CA476279

15-SEP-2017 LNM/D. 25-AUG-2017
Add ON CERTAIN COPIES between 49°34'10.4"N 054°18'15.1"W
ferry route and 49°34'12.0"N 054°18'26.6"W
(See Chart No. 1, M50)
DFO(6308059-01)

25-AUG-2017 LNM/D. 26-JUN-2015
Add ferry route joining 49°34'03.5"N 054°18'26.6"W
(See Chart No. 1, M50) 49°34'10.4"N 054°18'15.1"W
This notice affects Electronic Navigational Chart: and 49°34'14.5"N 054°18'08.1"W
CA376655, CA476813
DFO(6308011-06)

26-JUN-2015 LNM/D. 16-JAN-2015



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4530

Add breakwater extension
(See Chart No. 1, F4.1)

This notice affects Electronic Navigational Chart:
CA476279

between 49°27'32.7"N 053°57'22.6"W
and 49°27'32.2"N 053°57'24.9"W

DFO(6307149-01)

16-JAN-2015

Delete legend Fog Sig 30s against light
(See Chart No. 1, R20)

This notice affects Electronic Navigational Chart:
CA276092, CA376655, CA476279

LNM/D. 29-JUN-2012

49°31'49.6"N 053°51'04.8"W

(N2014067) LL(395) DFO(6306987-01)

29-JUN-2012

Affix patch

LNM/D. 16-MAR-2012

49°27'19.0"N 053°57'19.0"W

DFO(6306039-01)

[PDF](#)

This notice affects Electronic Navigational Chart: CA476279

16-MAR-2012

Reposition red starboard hand lighted spar buoy F1R, marked
DX6
(See Chart No. 1, Qf)

LNM/D. 28-OCT-2011
from 49°33'39.5"N 054°16'49.5"W
to 49°33'39.8"N 054°16'38.6"W

LL(372.62) DFO(6305947-01)

10-DEC-2010

Delete depth of 6 metres, 7 decimetres
(See Chart No 1 I10)

LNM/D. 01-OCT-2010

49°23'53.3"N 054°16'55.7"W

DFO(6305132-04)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

Add depth of 5 metres, 5 decimetres
(See Chart No 1 I10)

LNM/D. 01-OCT-2010

49°23'53.9"N 054°16'55.0"W

DFO(6305132-05)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

LNM/D. 01-OCT-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4530

Delete depth of 10 metres, 1 decimetre
(See Chart No 1 I10)

49°24'41.9"N 054°16'11.5"W

DFO(6305132-07)

This notice affects Electronic Navigational Chart: CA476813

10-DEC-2010

Add depth of 7 metres, 3 decimetres
(See Chart No 1 I10)

LNM/D. 01-OCT-2010

49°24'40.9"N 054°16'13.7"W

DFO(6305132-08)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

Delete depth of 8 metres, 8 decimetres
(See Chart No 1 I10)

LNM/D. 01-OCT-2010

49°25'21.2"N 054°15'37.9"W

DFO(6305132-09)

10-DEC-2010

Add depth of 8 metres, 3 decimetres
(See Chart No 1 I10)

LNM/D. 01-OCT-2010

49°25'20.2"N 054°15'39.9"W

DFO(6305132-10)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

Delete depth of 3 metres, 7 decimetres
(See Chart No 1 I10)

LNM/D. 01-OCT-2010

49°24'16.9"N 054°16'17.9"W

DFO(6305132-11)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

Add depth of 2 metres, 1 decimetre
(See Chart No 1 I10)

LNM/D. 01-OCT-2010

49°24'16.0"N 054°16'17.7"W

DFO(6305132-12)

This notice affects Electronic Navigational Chart: CA476813,
CA576280



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4530

01-OCT-2010

LNМ/D. 17-SEP-2010

Delete note:

49°27'06.0"N 053°58'15.0"W

DIAGRAM / DIAGRAMME

See Sailing Directions

DFO(6305060-01)

Voir Instructions nautiques

This notice affects Electronic Navigational Chart: CA476279

17-SEP-2010

LNМ/D. 23-OCT-2009

Amend Fl 6s 13m 8M to read Fl 6s 13m 16M against light
(See Chart No. 1 P16)

49°36'03.6"N 054°09'29.3"W

LL(378) DFO(6305022-01)

This notice affects Electronic Navigational Chart: CA476279

17-SEP-2010

LNМ/D. 23-OCT-2009

Delete green port hand lighted spar buoy FlG, marked JM3/1
(See Chart No 1 Qg)

49°27'48.0"N 053°57'00.0"W

LL(399.125) DFO(6305044-01)

This notice affects Electronic Navigational Chart: CA476279

17-SEP-2010

LNМ/D. 23-OCT-2009

Add green port hand lighted spar buoy FlG, marked JM1
(See Chart No 1 Qg)

49°27'44.6"N 053°56'55.4"W

LL(399.41) DFO(6305045-01)

This notice affects Electronic Navigational Chart: CA476279

17-SEP-2010

LNМ/D. 23-OCT-2009

Add red starboard hand lighted spar buoy FlR, marked JM2
(See Chart No 1 Qf)

49°27'46.7"N 053°57'02.7"W

LL(400) DFO(6305046-01)

This notice affects Electronic Navigational Chart: CA476279

23-OCT-2009

LNМ/D. 26-OCT-2007



Chart no. 4530

Add breakwater with legend Bkw

joining 49°27'36.3"N 053°57'28.8"W
49°27'35.5"N 053°57'23.3"W
and 49°27'32.6"N 053°57'22.2"W

This notice affects Electronic Navigational Chart:
CA476279

DFO(6304612-01)

23-OCT-2009

Delete light FLR
(See Chart No 1 P1)

LNМ/D. 26-OCT-2007
49°27'32.2"N 053°57'27.0"W

(N2008041) LL(397) DFO(6304612-02)

This notice affects Electronic Navigational Chart:
CA476279

23-OCT-2009

Add light FLR
(See Chart No 1 P1)

LNМ/D. 26-OCT-2007
49°27'32.6"N 053°57'22.2"W

(N2008041) LL(397) DFO(6304612-03)

This notice affects Electronic Navigational Chart:
CA476279

26-OCT-2007

Amend note Adjoining Chart/Carte adjacente 4531 to read Adjoining
Chart/Carte adjacente 4862

LNМ/D. 09-DEC-2005
centre of west border

DFO(6303536-12)

26-OCT-2007

Amend note Adjoining Chart/Carte adjacente 4520 to read Adjoining
Chart/Carte adjacente 4820

LNМ/D. 09-DEC-2005
right side of north border

DFO(6303536-13)

09-DEC-2005

Amend Fl to read Fl G against buoy marked JM3/1 49°27'47.8"N 053°57'00.0"W

LNМ/D. 18-NOV-2005

LL(399.125) DFO(6302485-01)

18-NOV-2005

LNМ/D. 22-JUL-2005



Chart no. 4530

Add light FIR 49°28'25.0"N 054°03'27.0"W

(N2004154) LL(393.7) DFO(6301846-01)

18-NOV-2005 LNM/D. 22-JUL-2005

Add wharf between 49°28'25.0"N 054°03'27.0"W
and 49°28'26.6"N 054°03'27.4"W

DFO(6301846-02)

22-JUL-2005 LNM/D. 14-JAN-2005

Add light 'FIG' against green port hand spar buoy, marked JA1 49°28'34.8"N 054°02'58.0"W

LL(393.5) DFO(6302370-01)

22-JUL-2005 LNM/D. 14-JAN-2005

Add light 'FIR' against red starboard hand spar buoy, marked JA2 49°28'29.4"N 054°03'09.6"W

LL(393.6) DFO(6302370-02)

14-JAN-2005 LNM/D. 02-MAY-2003

Delete light FIG 49°36'36.6"N 054°10'57.4"W

(N2004191) LL(378.7) DFO(6302102-01)

14-JAN-2005 LNM/D. 02-MAY-2003

Delete depth of 5 metres, 8 decimetres 49°36'37.8"N 054°10'56.3"W

DFO(6302102-02)

14-JAN-2005 LNM/D. 02-MAY-2003

Add breakwater joining 49°36'34.4"N 054°10'54.9"W
49°36'36.3"N 054°10'55.0"W
and 49°36'38.5"N 054°10'56.4"W

DFO(6302102-03)

14-JAN-2005 LNM/D. 02-MAY-2003



Chart no. 4530

Add light FLG 49°36'38.5"N 054°10'56.4"W

(N2004191) LL(378.7) DFO(6302102-04)

02-MAY-2003 LNM/D. 14-MAR-2003

Delete light FR 49°27'15.8"N 053°57'26.7"W

(N2002041) LL(398) DFO(6300283-01)

02-MAY-2003 LNM/D. 14-MAR-2003

Replace red starboard hand pillar light and whistle buoy Fl R, WHIS, marked J4 with red starboard hand pillar light buoy Fl R, marked J4 49°28'44.9"N 053°54'08.6"W

(N2002071) LL(402) DFO(6300423-01)

14-MAR-2003 LNM/D. 21-FEB-2003

Delete light FIR 49°34'17.0"N 054°18'01.0"W

LL(372.7) DFO(6300764-01)

14-MAR-2003 LNM/D. 21-FEB-2003

Add light FIR 49°34'15.8"N 054°18'05.5"W

LL(372.7) DFO(6300764-02)

14-MAR-2003 LNM/D. 21-FEB-2003

Delete dolphin and legend "Dn" 49°34'17.0"N 054°18'01.0"W

DFO(6300764-03)

21-FEB-2003 LNM/D. 27-DEC-2002

Delete dangerous underwater rock of 2m or less 49°29'19.0"N 053°48'54.0"W

DFO(6300810-01)

27-DEC-2002

Delete green, port hand can buoy, marked DX5 49°33'45.0"N 054°16'04.0"W

(N2000177) DFO(6828994-01)



Chart no. 4530

27-DEC-2002

Add green port hand spar light buoy FIG, marked DX5

49°33'43.4"N 054°16'16.4"W

(N2000177) LL(372.63) DFO(6828994-02)

27-DEC-2002

Delete red, starboard hand conical buoy, marked DX6

49°33'40.0"N 054°16'38.5"W

(N2000178) DFO(6828995-01)

27-DEC-2002

Add red starboard hand spar light buoy FIR, marked
DX6

49°33'39.5"N 054°16'49.5"W

(N2000178) LL(372.62) DFO(6828995-02)

27-DEC-2002

Replace red, starboard hand spar buoy, marked DS2, with
red starboard hand spar light buoy FIR, marked
DS2

49°36'41.3"N 054°11'02.9"W

(N2000179) LL(378.9) DFO(6828996-01)

27-DEC-2002

Replace red, starboard hand spar buoy, marked DG2, with
red starboard hand spar light buoy FIR, marked
DG2

49°34'28.9"N 054°16'29.8"W

(N2000180) LL(372.2) DFO(6828997-01)

27-DEC-2002

Replace green, port hand can buoy, marked DW3, with
green port hand spar light buoy FIG, marked
DW3

49°34'03.4"N 054°13'58.9"W

(N2000397) LL(346.4) DFO(6829312-01)