



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4616

4616 - Burin Harbours and Approches / et les approches - New Edition - 06-JUN-2003 - NAD 1983

13-MAY-2022

LNМ/D. 25-MAR-2022

Delete red starboard hand lighted pillar buoy FIR, marked
PBB2

46°59'04.7"N 055°09'35.1"W

(See Chart No. 1, Qf)

(N2022045) LL(71.4) DFO(6310066-01)

This notice affects Electronic Navigational Chart:
CA376176

25-MAR-2022

LNМ/D. 24-SEP-2021

Amend FIR to read Q R against red starboard hand lighted
pillar buoy, marked PB2

46°59'49.3"N 055°10'59.6"W

(See Chart No. 1, Qf)

(N2022035) LL(70) DFO(6310038-01)

This notice affects Electronic Navigational Chart:
CA376176

25-MAR-2022

LNМ/D. 24-SEP-2021

Delete red starboard hand lighted pillar buoy Fl R, marked
PB8

47°02'29.1"N 055°09'21.6"W

(See Chart No. 1, Qf)

(N2022036) LL(67.4) DFO(6310039-01)

25-MAR-2022

LNМ/D. 24-SEP-2021

Add red starboard hand lighted spar buoy Q R, marked
PB8

47°02'29.1"N 055°09'21.6"W

(See Chart No. 1, Qf)

(N2022036) LL(67.4) DFO(6310039-02)

24-SEP-2021

LNМ/D. 20-MAY-2011

Delete light FlR 6s 85ft

46°57'15.0"N 055°14'02.7"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA276091, CA376176

(N2021115) LL(72) DFO(6309604-01)

20-MAY-2011

LNМ/D. 06-AUG-2010

Delete light 2Lts FlR & FlG

47°01'51.7"N 055°10'21.9"W

(See Chart No. 1, P1)

(N2011014) LL(68.52) DFO(6305426-01)

20-MAY-2011

LNМ/D. 06-AUG-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4616

Add light FIG 47°01'53.1"N 055°10'20.2"W
(See Chart No. 1, P1)
(N2011016) LL(68.55) DFO(6305427-01)

20-MAY-2011 LNM/D. 06-AUG-2010
Delete depth of 1 fathom 47°01'51.4"N 055°10'19.3"W
(See Chart No. 1, I10)
DFO(6305427-02)

20-MAY-2011 LNM/D. 06-AUG-2010
Delete depth of 7 fathoms 47°01'53.5"N 055°10'19.4"W
(See Chart No. 1, I10)
DFO(6305427-03)

20-MAY-2011 LNM/D. 06-AUG-2010
Add breakwater with legend Bkw joining 47°01'50.7"N 055°10'19.1"W
(See Chart 1 F4.1) 47°01'52.2"N 055°10'19.5"W
and 47°01'53.1"N 055°10'20.2"W
DFO(6305427-04)

20-MAY-2011 LNM/D. 06-AUG-2010
Add depth of 5 fathoms 47°01'54.0"N 055°10'20.6"W
(See Chart No. 1, I10)
DFO(6305427-05)

06-AUG-2010 LNM/D. 04-JUN-2010
Amend Fl 6s 110ft 6M to read Fl 6s 110ft 16M against light 47°06'21.8"N 055°04'19.8"W
(See Chart No. 1 P16)
LL(65) DFO(6304966-01)

This notice affects Electronic Navigational Chart: CA276091,
CA576225

04-JUN-2010 LNM/D. 13-MAR-2009
Reposition red and white fairway lighted pillar bell buoy from 46°58'54.2"N 055°10'02.7"W
BELL, Mo(A), marked PB to 46°58'52.7"N 055°10'01.8"W
(See Chart No 1 Qh)
(N2010016) LL(71.5) DFO(6304878-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4616

13-MAR-2009

LNM/D. 19-SEP-2008

Add non-dangerous wreck 46°59'54.0"N 055°04'30.0"W
(See Chart No. 1, K29)

DFO(6304264-01)

19-SEP-2008

LNM/D. 13-JUN-2008

Add green port hand lighted pillar buoy FlG, marked PR3
(See Chart No 1 Qg)

47°02'00.4"N 055°07'16.8"W

(N2008026) LL(66.5) DFO(6304017-01)

13-JUN-2008

LNM/D. 14-DEC-2007

Delete overhead cable with vertical clearance of 100 feet between 46°59'00.0"N 055°12'15.0"W
and 46°58'48.0"N 055°11'57.0"W

DFO(6303839-01)

14-DEC-2007

LNM/D. 10-FEB-2006

Amend FlG to read 2Lts FlR & FlG against light
(See Chart No 1 P16)

47°01'51.7"N 055°10'21.9"W

(N2007052) LL(68.52) DFO(6303644-01)

4616 - Burin Public Wharf / quai public - New Edition - 06-JUN-2003 - NAD 1983

10-FEB-2006

Affix patch Northwest corner of Burin inset.

DFO(6302665-01)

[PDF](#)