



Chart no. 4625

4625 - Burin Peninsula to / à Saint-Pierre - New Edition - 24-JAN-2003 - NAD 1983

26-DEC-2003

Delete red and white fairway pillar light buoy Mo (A), BELL, 47°06'27.0"N 055°43'55.0"W
marked VG
(N2002082) LL(111) DFO(6300471-01)

26-DEC-2003

Delete front range light and legend 2 Lts F G 47°06'03.7"N 055°45'03.7"W
(N2002120) LL(109) DFO(6300544-01)

26-DEC-2003

Delete leading line and legend "064½°" "244½°" 47°06'03.7"N 055°45'03.7"W
(N2002120) LL(109) DFO(6300544-02)

26-DEC-2003

Delete rear range light 47°06'02.0"N 055°45'08.4"W
(N2002121) LL(110) DFO(6300544-03)

30-APR-2004

Add green port hand spar light buoy FlG, marked VG1 LNM/D. 26-DEC-2003
47°06'11.9"N 055°44'13.4"W
(N2002077) LL(111.09) DFO(6301248-01)

14-OCT-2005

Amend legend "PAG1" to read "PAG3" against porthand LNM/D. 30-APR-2004
buoy 46°50'56.8"N 055°44'23.2"W
(N2005062) LL(75.53) DFO(6302489-01)

14-OCT-2005

Add green port hand lighted spar buoy QG, marked PAG1 LNM/D. 30-APR-2004
46°50'31.0"N 055°44'36.2"W
(N2005063) LL(75.54) DFO(6302490-01)



Chart no. 4625

02-NOV-2007

LNM/D. 14-OCT-2005

(T)Add subsurface mooring at a depth of 1 metre 5 decimetres (5 feet) 46°55'53.2"N 055°59'52.4"W
The mooring is temporary and will be removed by July 2008.
The mooring has been removed. Notice 02-NOV-2007(T), DFO
(6303670) is cancelled. *DFO(6303670-01)*
Cancelled on 20-FEB-09

30-MAY-2008

LNM/D. 02-NOV-2007

Replace green port hand lighted pillar bell buoy FlG, marked VF1 with 47°04'39.9"N 055°49'31.0"W
a green port hand lighted can buoy FlG, marked VF1
(See Chart No 1 Qg) *LL(103) DFO(6303886-01)*

20-FEB-2009

LNM/D. 30-JAN-2009

Add light Fl(2) RWG 47°06'02.9"N 055°45'03.0"W
(See Chart No 1 P1)
(N2008044) LL(106.5) DFO(6304159-01)

30-JAN-2009

LNM/D. 30-MAY-2008

Add submarine cable joining 47°08'28.8"N 055°31'02.5"W
(See Chart No 1 L30.1) 47°08'44.3"N 055°30'49.1"W
47°09'01.3"N 055°30'46.8"W
and 47°11'29.8"N 055°32'39.1"W
DFO(6304180-01)

20-FEB-2009

LNM/D. 30-JAN-2009

Delete light FlR 47°06'07.8"N 055°44'51.8"W
(See Chart No 1 P1)
DFO(6304213-01)

20-FEB-2009

LNM/D. 30-JAN-2009

Add breakwater joining 47°06'06.3"N 055°44'59.3"W
(See Chart No 1 F4.1) 47°06'07.2"N 055°44'53.2"W
and 47°06'05.8"N 055°44'52.6"W
DFO(6304213-02)

20-FEB-2009

LNM/D. 30-JAN-2009



Chart no. 4625

Add light FLR 47°06'05.8"N 055°44'52.6"W
(See Chart No 1 P1)
LL(108) DFO(6304213-03)

20-FEB-2009 LNM/D. 30-JAN-2009
Delete light FLR 47°06'05.0"N 055°44'55.2"W
(See Chart No 1 P1)
DFO(6304214-01)

20-FEB-2009 LNM/D. 30-JAN-2009
Add light QR 47°06'04.3"N 055°44'58.6"W
(See Chart No 1 P1)
LL(107) DFO(6304214-02)

20-FEB-2009 LNM/D. 30-JAN-2009
Delete light Fl 47°06'03.8"N 055°44'55.6"W
(See Chart No 1 P1)
DFO(6304215-01)

20-FEB-2009 LNM/D. 30-JAN-2009
Delete breakwater between 47°06'02.0"N 055°44'55.2"W
(See Chart No 1 F4.1) and 47°06'05.0"N 055°44'55.6"W
DFO(6304215-02)

20-FEB-2009 LNM/D. 30-JAN-2009
Add wharf between 47°06'02.9"N 055°44'57.5"W
(See Chart No 1 F14) and 47°06'01.2"N 055°44'57.5"W
DFO(6304215-03)

20-FEB-2009 LNM/D. 30-JAN-2009
Add light QG 47°06'02.9"N 055°44'57.5"W
(See Chart No 1 P1)
DFO(6304215-04)

06-NOV-2009

LNM/D. 22-MAY-2009



Chart no. 4625

Add breakwater
(See Chart 1 F4.1)

joining 46°51'24.0"N 055°48'22.6"W
46°51'24.9"N 055°48'17.8"W
and 46°51'22.4"N 055°48'16.8"W

This notice affects Electronic Navigational Chart:
CA376164

DFO(6304354-02)

06-NOV-2009

LNM/D. 22-MAY-2009

Add light FLR
(See Chart No 1 P1)

46°51'22.4"N 055°48'16.8"W

(N2009006) LL(75.52) DFO(6304354-03)

This notice affects Electronic Navigational Chart:
CA376164

22-MAY-2009

LNM/D. 20-FEB-2009

Add legend Adjoining Chart/Carte adjacente 4827 north border of chart at 56°02'30"W
(See Chart No 1 A20)

DFO(6304355-07)

26-FEB-2010

LNM/D. 06-NOV-2009

Amend Fl 15s 88ft 11M to read Fl 15s 88ft 17M against light
(See Chart No 1 P16)

46°53'52.8"N 055°20'51.2"W

LL(73) DFO(6304696-01)

This notice affects Electronic Navigational Chart: CA276091

04-JUN-2010

LNM/D. 26-FEB-2010

Delete red starboard hand lighted spar buoy FLR, marked
PC2
(See Chart No 1 Qf)

46°52'24.4"N 055°39'54.9"W

(N2010016) LL(74.6) DFO(6304881-01)

This notice affects Electronic Navigational Chart:
CA376164

04-JUN-2010

LNM/D. 26-FEB-2010

Add red starboard hand lighted pillar buoy FLR, marked PC2
(See Chart No 1 Qf)

46°52'17.5"N 055°39'52.0"W

LL(74.6) DFO(6304881-02)

This notice affects Electronic Navigational Chart: CA376164



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4625

18-MAR-2011

LNМ/D. 04-JUN-2010

Delete circular radiobeacon with legend RRT 46°55'43.0"N 055°22'47.0"W
(See Chart No 1 S15)

DFO(6305286-01)

04-NOV-2011

LNМ/D. 18-MAR-2011

Delete red starboard hand lighted pillar bell buoy FlR,
BELL, marked PK2
(See Chart No. 1, Qf)

46°54'09.0"N 055°31'10.0"W

(N2011063) LL(73.7) DFO(6305747-01)

This notice affects Electronic Navigational Chart:
CA376164

04-NOV-2011

LNМ/D. 18-MAR-2011

Add red starboard hand lighted pillar buoy FlR, marked
PK2
(See Chart No. 1, Qf)

46°54'08.0"N 055°31'15.0"W

(N2011063) LL(73.7) DFO(6305747-02)

This notice affects Electronic Navigational Chart:
CA376164

04-NOV-2011

LNМ/D. 18-MAR-2011

Delete red starboard hand spar buoy FlR, marked PK4
(See Chart No. 1, Qc)

46°54'29.7"N 055°32'41.0"W

(N2011064) LL(73.8) DFO(6305748-01)

This notice affects Electronic Navigational Chart:
CA376164

04-NOV-2011

LNМ/D. 18-MAR-2011

Add red starboard hand lighted pillar bell buoy FlR, BELL,
marked PK4
(See Chart No. 1, Qf)

46°54'32.9"N 055°32'38.0"W

(N2011064) LL(73.8) DFO(6305748-02)

This notice affects Electronic Navigational Chart:
CA376164

03-FEB-2012

LNМ/D. 04-NOV-2011



Chart no. 4625

Add yellow ODAS/SADO lighted super-buoy Fl (5) Y 20s
(See Chart No. 1, Q58)

46°42'06.0"N 056°11'18.0"W

DFO(6305904-01)

This notice affects Electronic Navigational Chart: CA276091,
CA376164

03-JAN-2014

LNМ/D. 03-FEB-2012

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA376164

joining 46°52'06.0"N 055°39'43.0"W
46°52'44.0"N 055°40'04.0"W
and 46°52'43.0"N 055°40'10.0"W

DFO(6306591-02)

03-JAN-2014

LNМ/D. 03-FEB-2012

Add private yellow cautionary spherical buoy
(See Chart No 1 Q22)
This notice affects Electronic Navigational Chart: CA376164

46°52'06.0"N 055°39'43.0"W

DFO(6306591-03)

03-JAN-2014

LNМ/D. 03-FEB-2012

Add private yellow cautionary spherical buoy
(See Chart No 1 Q22)
This notice affects Electronic Navigational Chart: CA376164

46°52'20.0"N 055°39'52.0"W

DFO(6306591-04)

03-JAN-2014

LNМ/D. 03-FEB-2012

Add private yellow cautionary spherical buoy
(See Chart No 1 Q22)
This notice affects Electronic Navigational Chart: CA376164

46°52'36.0"N 055°40'00.7"W

DFO(6306591-05)

25-APR-2014

LNМ/D. 03-JAN-2014

Delete legend Fog Sig 30s against light
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart:
CA276091, CA376164

46°50'48.0"N 055°47'51.5"W

(N2014020) LL(76) DFO(6306716-01)

25-APR-2014

LNМ/D. 03-JAN-2014

Delete legend Fog Sig
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart:
CA376164

46°51'06.8"N 055°49'39.2"W

(N2014021) LL(78.51) DFO(6306716-02)



Chart no. 4625

25-JUL-2014

Add wreck, least depth unknown
(See Chart No. 1, K29)

This notice affects Electronic Navigational Chart: CA276091,
CA376164

LNLM/D. 25-APR-2014

46°49'38.4"N 056°05'09.0"W

DFO(6306742-01)

25-JUL-2014

Add wreck, least depth unknown
(See Chart No. 1, K29)

This notice affects Electronic Navigational Chart: CA276091,
CA376164

LNLM/D. 25-APR-2014

46°49'19.4"N 056°06'49.3"W

DFO(6306742-02)

25-JUL-2014

Add obstruction, depth unknown with legend "Obstn"
(See Chart No. 1, K40)

This notice affects Electronic Navigational Chart: CA376164

LNLM/D. 25-APR-2014

46°45'42.1"N 056°07'37.7"W

DFO(6306742-03)

25-JUL-2014

Add obstruction, depth unknown with legend "Obstn"
(See Chart No. 1, K40)

This notice affects Electronic Navigational Chart: CA376164

LNLM/D. 25-APR-2014

46°45'31.4"N 056°07'55.7"W

DFO(6306742-04)

05-DEC-2014

Add legend Fog Sig 30s against light
(See Chart No. 1, R1, R20)

This notice affects Electronic Navigational Chart:
CA276091, CA376164

LNLM/D. 25-JUL-2014

46°50'48.0"N 055°47'51.5"W

(N2014079) LL(76) DFO(6307007-02)

08-MAY-2015

Replace depth of 39 fathoms with depth of 36 Fathoms
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376164

LNLM/D. 05-DEC-2014

46°50'30.6"N 056°06'00.0"W

DFO(6307112-04)

08-MAY-2015

Add marine farm
(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA376164

LNLM/D. 05-DEC-2014

47°01'49.9"N 056°12'49.6"W

DFO(6307112-05)

12-FEB-2016

LNLM/D. 08-MAY-2015



Chart no. 4625

Replace depth of 7 fathoms, 1 foot with depth of 5 fathoms, 5 feet 46°49'01.4"N 056°10'56.6"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376164 *DFO(6307382-13)*

12-FEB-2016 LNM/D. 08-MAY-2015
Replace depth of 9 fathoms, 3 feet with depth of 4 fathoms 47°05'13.5"N 056°11'42.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6307382-14)*

12-FEB-2016 LNM/D. 08-MAY-2015
Replace depth of 15 fathoms with depth of 9 fathoms, 4 feet 47°05'22.6"N 056°10'29.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6307382-15)*

12-FEB-2016 LNM/D. 08-MAY-2015
Delete depth of 17 fathoms 47°04'38.9"N 056°09'51.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6307382-16)*

12-FEB-2016 LNM/D. 08-MAY-2015
Add depth of 11 fathoms 47°04'32.6"N 056°09'43.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6307382-17)*

12-FEB-2016 LNM/D. 08-MAY-2015
Replace depth of 9 fathoms with depth of 5 fathoms 47°03'03.5"N 056°13'48.2"W
(See Chart No. 1, I10)
DFO(6307382-18)

06-MAY-2016 LNM/D. 12-FEB-2016
Add depth of 8 fathoms 47°05'04.4"N 056°09'07.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6307517-01)*

02-SEP-2016 LNM/D. 06-MAY-2016
Delete beacon with legend Fog Sig (2) 60s 46°45'51.5"N 056°09'12.1"W
(See Chart No. 1, R1)
This notice affects Electronic Navigational Chart: CA276091, *DFO(6307665-01)*
CA376164



Chart no. 4625

- 02-FEB-2018** LNM/D. 02-SEP-2016
Add subsurface Ocean Data Acquisition system ODAS/SADO with 46°48'23.0"N 056°05'38.0"W
known depth of 4 fathoms, 2 feet
(See Chart No. 1, L25) *DFO(6308177-01)*
This notice affects Electronic Navigational Chart: CA376164
- 02-FEB-2018** LNM/D. 02-SEP-2016
Add subsurface Ocean Data Acquisition system ODAS/SADO with 46°52'47.0"N 056°01'37.0"W
known depth of 2 fathoms, 4 feet
(See Chart No. 1, L25) *DFO(6308177-02)*
This notice affects Electronic Navigational Chart: CA376164
- 26-OCT-2018** LNM/D. 02-FEB-2018
Delete depth of 12 fathoms 46°49'29.9"N 056°02'14.9"W
(See Chart No. 1, I10) *DFO(6308428-01)*
This notice affects Electronic Navigational Chart: CA376164
- 26-OCT-2018** LNM/D. 02-FEB-2018
Add depth of 8 fathoms, 4 feet 46°49'26.5"N 056°02'06.4"W
(See Chart No. 1, I10) *DFO(6308428-02)*
This notice affects Electronic Navigational Chart: CA376164
- 26-OCT-2018** LNM/D. 02-FEB-2018
Add depth of 50 fathoms 47°08'10.1"N 056°08'09.7"W
(See Chart No. 1, I10) *DFO(6308428-03)*
This notice affects Electronic Navigational Chart: CA376627
- 26-OCT-2018** LNM/D. 02-FEB-2018
Add depth of 33 fathoms 47°07'58.9"N 056°10'06.4"W
(See Chart No. 1, I10) *DFO(6308428-05)*
This notice affects Electronic Navigational Chart: CA376627
- 26-OCT-2018** LNM/D. 02-FEB-2018
Replace depth of 13 fathoms with depth of 9 fathoms, 2 feet 46°59'28.7"N 056°11'47.6"W
(See Chart No. 1, I10) *DFO(6308428-09)*
This notice affects Electronic Navigational Chart: CA376164
- 26-OCT-2018** LNM/D. 02-FEB-2018



Chart no. 4625

- Add depth of 5 fathoms, 2 feet 46°59'23.8"N 056°12'14.9"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376164 *DFO(6308428-11)*
- 26-OCT-2018** LNM/D. 02-FEB-2018
Delete depth of 15 fathoms 46°43'34.7"N 056°13'53.1"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376164 *DFO(6308428-12)*
- 26-OCT-2018** LNM/D. 02-FEB-2018
Add depth of 19 fathoms 47°06'13.3"N 056°10'14.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6308428-17)*
- 26-OCT-2018** LNM/D. 02-FEB-2018
Add depth of 37 fathoms 47°06'06.5"N 056°09'16.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6308428-18)*
- 26-OCT-2018** LNM/D. 02-FEB-2018
Replace depth of 2 fathoms, 5 feet with depth of 2 fathoms 47°04'03.2"N 056°14'45.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6308428-19)*
- 26-OCT-2018** LNM/D. 02-FEB-2018
Replace depth of 3 fathoms with depth of 2 fathoms, 1 foot 47°03'54.8"N 056°14'44.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376627 *DFO(6308428-20)*
- 26-OCT-2018** LNM/D. 02-FEB-2018
Delete depth of 8 fathoms, 4 feet 47°03'59.8"N 056°14'20.7"W
(See Chart No. 1, I10)
DFO(6308428-21)
- 26-OCT-2018** LNM/D. 02-FEB-2018
Delete depth of 16 fathoms 46°49'30.1"N 056°01'58.3"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376164 *DFO(6308428-23)*



Chart no. 4625

26-OCT-2018

LNМ/D. 02-FEB-2018

Add depth of 10 fathoms

46°43'30.2"N 056°13'49.9"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376164

DFO(6308428-29)

26-OCT-2018

LNМ/D. 02-FEB-2018

Add depth of 4 fathoms, 2 feet 47°04'00.9"N 056°14'28.6"W

(See Chart No. 1, I10)

DFO(6308428-30)

26-OCT-2018

LNМ/D. 02-FEB-2018

Delete depth of 39 fathoms 47°06'48.7"N 056°09'51.8"W

(See Chart No. 1, I10)

DFO(6308428-31)

26-OCT-2018

LNМ/D. 02-FEB-2018

Add depth of 33 fathoms 47°06'43.9"N 056°09'45.2"W

(See Chart No. 1, I10)

DFO(6308428-32)

26-OCT-2018

LNМ/D. 02-FEB-2018

Delete depth of 6 fathoms, 3 feet

47°03'00.1"N 056°14'03.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376164

DFO(6308452-01)

26-OCT-2018

LNМ/D. 02-FEB-2018

Add depth of 2 fathoms, 5 feet

47°02'54.5"N 056°14'08.2"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376164

DFO(6308452-02)

26-OCT-2018

LNМ/D. 02-FEB-2018

Delete depth of 9 fathoms, 1 foot

47°02'49.4"N 056°13'54.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376164

DFO(6308452-03)

26-OCT-2018

LNМ/D. 02-FEB-2018



Chart no. 4625

Add depth of 4 fathoms, 1 foot (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376164	47°02'54.1"N 056°13'51.1"W <i>DFO(6308452-04)</i>
26-OCT-2018 Delete depth of 17 fathoms (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376164	LNМ/D. 02-FEB-2018 46°58'53.6"N 056°12'33.1"W <i>DFO(6308452-05)</i>
26-OCT-2018 Add depth of 8 fathoms, 2 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376164	LNМ/D. 02-FEB-2018 46°58'59.2"N 056°12'42.4"W <i>DFO(6308452-06)</i>
26-OCT-2018 Delete depth of 8 fathoms, 3 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376164	LNМ/D. 02-FEB-2018 46°51'47.9"N 056°06'04.7"W <i>DFO(6308452-07)</i>
26-OCT-2018 Add depth of 3 fathoms, 2 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376164	LNМ/D. 02-FEB-2018 46°51'42.5"N 056°06'08.5"W <i>DFO(6308452-08)</i>
26-OCT-2018 Delete depth of 4 fathoms, 1 foot (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376164	LNМ/D. 02-FEB-2018 46°51'37.3"N 056°06'04.7"W <i>DFO(6308452-09)</i>
26-OCT-2018 Add depth of 0 fathoms, 1 foot (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376164	LNМ/D. 02-FEB-2018 46°51'32.1"N 056°06'04.0"W <i>DFO(6308452-10)</i>
26-OCT-2018 Add depth of 16 fathoms (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376164	LNМ/D. 02-FEB-2018 46°51'14.6"N 056°05'46.7"W <i>DFO(6308452-12)</i>



Chart no. 4625

26-OCT-2018

LNМ/D. 02-FEB-2018

Add wreck WK with known depth of 31 fathoms
(See Chart No. 1, K26)

46°48'12.5"N 056°14'46.3"W

This notice affects Electronic Navigational Chart: CA376164

DFO(6308452-13)

26-OCT-2018

LNМ/D. 02-FEB-2018

Delete depth of 37 fathoms
(See Chart No. 1, I10)

46°47'03.4"N 056°15'54.1"W

This notice affects Electronic Navigational Chart: CA376164

DFO(6308452-14)

26-OCT-2018

LNМ/D. 02-FEB-2018

Add wreck WK with known depth of 35 fathoms
(See Chart No. 1, K26)

46°46'56.9"N 056°15'59.2"W

This notice affects Electronic Navigational Chart: CA376164

DFO(6308452-15)

26-OCT-2018

LNМ/D. 02-FEB-2018

Delete depth of 7 fathoms, 1 foot
(See Chart No. 1, I10)

46°51'28.6"N 056°06'06.3"W

This notice affects Electronic Navigational Chart: CA376164

DFO(6308452-16)

11-JAN-2019

LNМ/D. 26-OCT-2018



Chart no. 4625

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA276091, CA376164, CA376627

joining 46°46'19.6"N 056°09'14.5"W
46°46'20.1"N 056°08'47.1"W
46°46'05.6"N 056°08'28.4"W
46°45'44.8"N 056°08'14.5"W
46°45'16.5"N 056°07'08.9"W
46°45'19.6"N 056°06'18.8"W
46°45'33.7"N 056°05'32.8"W
46°46'02.1"N 056°05'01.4"W
46°46'55.8"N 056°04'51.3"W
46°47'37.9"N 056°05'11.7"W
46°49'49.3"N 056°08'03.4"W
46°50'30.8"N 056°08'35.1"W
46°54'27.3"N 056°08'11.9"W
46°55'14.3"N 056°08'17.2"W
46°56'05.0"N 056°07'57.0"W
46°57'37.6"N 056°07'45.4"W
46°59'53.5"N 056°07'15.9"W
47°01'15.7"N 056°07'25.2"W
47°02'54.4"N 056°06'54.7"W
47°04'29.5"N 056°06'52.3"W
47°06'00.3"N 056°07'15.3"W
47°06'53.3"N 056°07'58.9"W
47°07'29.0"N 056°10'12.2"W
47°07'56.5"N 056°15'02.8"W
and 47°07'56.2"N 056°16'57.7"W

DFO(6308456-01)

11-JAN-2019

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA276091, CA376233, CA376627

LNM/D. 26-OCT-2018
joining 47°08'08.2"N 056°16'57.7"W
47°08'19.4"N 056°08'55.5"W
47°08'32.4"N 056°08'03.2"W
47°08'28.5"N 056°06'11.2"W
47°08'34.8"N 056°03'10.7"W
47°08'37.0"N 055°54'26.0"W
47°08'05.0"N 055°52'50.0"W
47°07'35.4"N 055°52'09.8"W
and 47°04'43.0"N 055°48'47.0"W

DFO(6308456-03)

11-JAN-2019

LNM/D. 26-OCT-2018



Chart no. 4625

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA376164

joining 46°46'17.7"N 056°09'14.3"W
46°46'16.7"N 056°08'52.5"W
46°46'08.8"N 056°08'37.2"W
46°45'41.2"N 056°08'19.9"W
46°44'59.2"N 056°07'17.4"W
46°44'51.5"N 056°06'46.7"W
46°44'51.5"N 056°06'12.1"W
46°46'10.5"N 055°57'12.0"W
46°46'53.9"N 055°54'47.6"W
46°47'50.2"N 055°53'11.6"W
46°48'31.8"N 055°51'25.4"W
46°48'58.6"N 055°50'34.9"W
46°49'41.0"N 055°49'53.1"W
46°49'55.7"N 055°49'30.2"W
and 46°51'12.0"N 055°48'28.0"W

DFO(6308456-04)

08-FEB-2019

LNM/D. 11-JAN-2019

Delete subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 4 fathoms, 2 feet
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA376164

46°48'23.0"N 056°05'38.0"W

DFO(6308530-01)

08-FEB-2019

LNM/D. 11-JAN-2019

Delete subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 2 fathoms, 4 feet
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA376164

46°52'46.9"N 056°01'36.6"W

DFO(6308530-02)

11-OCT-2019

LNM/D. 08-FEB-2019

Amend Fl 5s 78ft 5M to read Fl 5s78ft15M against light 47°04'28.0"N 055°51'34.0"W
(See Chart No. 1, P16)

LL(102) DFO(6308728-01)

11-OCT-2019

LNM/D. 08-FEB-2019

Amend Fl10s149ft11M to read Iso 10s149ft15M against light 46°52'47.5"N 056°05'07.5"W
(See Chart No. 1, P16)

LL(100.0) DFO(6308728-02)

11-OCT-2019

LNM/D. 08-FEB-2019



Chart no. 4625

Amend Fl 4s 64ft 12M to read Fl 4s64ft16M against light 46°50'47.7"N 055°47'50.2"W
(See Chart No. 1, P16)

LL(76.0) DFO(6308728-03)

11-OCT-2019

LNM/D. 08-FEB-2019

Amend Fl(2) 10s 158ft 25M to read Fl(2) 10s158ft22M against light 46°45'54.4"N 056°09'14.0"W
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart: CA376164

DFO(6308728-04)

11-OCT-2019

LNM/D. 08-FEB-2019

Amend Fl WR 2s 43ft 11M & 8M to read Fl WR 2s33ft9M&6M against 46°47'55.0"N 056°08'54.2"W
light

(See Chart No. 1, P16)

DFO(6308728-07)

This notice affects Electronic Navigational Chart: CA376164

11-OCT-2019

LNM/D. 08-FEB-2019

Reposition yellow, black and yellow West cardinal lighted pillar from 46°45'25.3"N 056°15'17.3"W
whistle buoy Q(9) 15s, WHIS, marked Savoyard-SPM to 46°45'25.6"N 056°15'09.1"W
(See Chart No. 1, Q130.3)

This notice affects Electronic Navigational Chart:
CA376164

DFO(6308728-11)

11-OCT-2019

LNM/D. 08-FEB-2019

Reposition yellow and black South cardinal lighted pillar whistle from 46°43'51.6"N 056°13'20.2"W
buoy Q(6) + LFl 15s, WHIS, marked La Marne - SPM to 46°43'48.5"N 056°13'13.0"W
(See Chart No. 1, Q130.3)

This notice affects Electronic Navigational Chart:
CA376164

DFO(6308728-12)

11-OCT-2019

LNM/D. 08-FEB-2019

Delete radar transponder beacon marked Aero RC
(See Chart No. 1, S3.1/S3.4)

46°45'44.9"N 056°10'09.7"W

This notice affects Electronic Navigational Chart: CA376164

DFO(6308728-15)

11-OCT-2019

LNM/D. 08-FEB-2019

Delete radar transponder beacon marked R
(See Chart No. 1, S3.1/S3.4)

46°46'52.7"N 056°10'49.8"W

This notice affects Electronic Navigational Chart: CA376164

DFO(6308728-16)



Chart no. 4625

22-NOV-2019

Replace green port hand can light buoy FlG , marked VF1
with green port hand spar light buoy Fl G, marked
VF1

(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:
CA376233, CA576235

LNМ/D. 11-OCT-2019

47°04'40.8"N 055°49'30.1"W

(N2019066) LL(103) DFO(6308780-01)

27-MAR-2020

Add Breakwater

(See Chart No. 1, F4.1)

This notice affects Electronic Navigational Chart:
CA376164

LNМ/D. 22-NOV-2019

joining 46°56'33.4"N 055°32'25.8"W

46°56'29.1"N 055°32'29.3"W

and 46°56'27.2"N 055°32'29.3"W

DFO(6308937-01)

27-MAR-2020

Reposition light Fl G

(See Chart No. 1, P1)

This notice affects Electronic Navigational
Chart: CA376164

LNМ/D. 22-NOV-2019

from 46°56'34.4"N 055°32'27.5"W

to 46°56'27.2"N 055°32'29.3"W

(N2020010) LL(73.84) DFO(6308937-02)

17-JUL-2020

Delete depth of 12 fathoms

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376627

LNМ/D. 27-MAR-2020

47°03'55.0"N 056°13'03.0"W

DFO(6308979-03)

17-JUL-2020

Add depth of 7 fathoms, 5 feet

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376627

LNМ/D. 27-MAR-2020

47°03'55.3"N 056°12'55.5"W

DFO(6308979-04)

17-JUL-2020

Delete legend WHIS against black, yellow and black East cardinal
lighted pillar buoy, marked Les Rochers-SPM

(See Chart No. 1, Qd)

This notice affects Electronic Navigational Chart: CA276091,
CA376627

LNМ/D. 27-MAR-2020

47°03'20.2"N 056°11'38.3"W

DFO(6308979-05)

17-JUL-2020

LNМ/D. 27-MAR-2020



Chart no. 4625

Amend WHIS to read Bell against red and white fairway lighted pillar buoy, marked Nord-Est-SPM 46°48'21.2"N 056°07'38.2"W
(See Chart No. 1, Qc, Qd) *DFO(6308979-06)*
This notice affects Electronic Navigational Chart: CA276091,
CA376164

17-JUL-2020

LNLM/D. 27-MAR-2020

Delete legend WHIS against black, yellow and black East cardinal lighted pillar buoy, marked Grande-Basse-SPM 46°47'12.1"N 056°06'06.0"W
(See Chart No. 1, Qd) *DFO(6308979-07)*
This notice affects Electronic Navigational Chart: CA276091,
CA376164

17-JUL-2020

LNLM/D. 27-MAR-2020

Delete legend WHIS against yellow and black South cardinal lighted pillar buoy, marked La Marne-SPM 46°43'48.2"N 056°13'12.6"W
(See Chart No. 1, Qd) *DFO(6308979-08)*
This notice affects Electronic Navigational Chart: CA276091,
CA376164

17-JUL-2020

LNLM/D. 27-MAR-2020

Delete legend WHIS against yellow, black and yellow West cardinal lighted pillar buoy, marked Savoyard-SPM 46°45'25.6"N 056°15'09.2"W
(See Chart No. 1, Qd) *DFO(6308979-09)*
This notice affects Electronic Navigational Chart: CA276091,
CA376164

17-JUL-2020

LNLM/D. 27-MAR-2020

Delete depth of 17 fathoms 46°43'28.0"N 056°14'16.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376164 *DFO(6308997-03)*

17-JUL-2020

LNLM/D. 27-MAR-2020

Add depth of 13 fathoms 46°43'24.0"N 056°14'12.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376164 *DFO(6308997-04)*

17-JUL-2020

LNLM/D. 27-MAR-2020



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4625

Add depth of 22 fathoms
(See Chart No. 1, I10)

46°43'00.0"N 056°15'30.0"W

This notice affects Electronic Navigational Chart: CA376164

DFO(6308997-06)