



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4663

4663 - Cow Head to / à Pointe Riche - New Edition - 01-AUG-2003 - NAD 1983

17-MAR-2023

LNM/D. 24-SEP-2021

Delete Note

49°53'25.0"N 057°47'31.0"W

DIAGRAM/DIAGRAMME

See Sailing Directions

DFO(6310567-01)

Voir Instructions nautiques

(See Chart No. 1, A18)

24-SEP-2021

LNM/D. 10-APR-2020

Add black and yellow North cardinal lighted pillar buoy

50°44'00.2"N 057°20'37.2"W

VQ W, marked XPB (See Chart No. 1, Q130.3)

(N2021072) LL(211.15) DFO(6309549-01)

24-SEP-2021

LNM/D. 10-APR-2020

Delete red starboard hand lighted spar buoy Fl R, marked

50°44'14.0"N 057°19'51.0"W

XP2

(See Chart No. 1, Qf)

(N2021134) LL(211.5) DFO(6309575-01)

24-SEP-2021

LNM/D. 10-APR-2020

Add red starboard hand lighted pillar buoy Fl R, marked

50°44'17.9"N 057°20'04.2"W

XP2

(See Chart No. 1, Qf)

(N2021134) LL(211.5) DFO(6309575-02)

10-APR-2020

LNM/D. 27-MAR-2020

Add wreck Wk with known depth of 11 fathoms 50°36'18.7"N 057°14'24.4"W

(See Chart No. 1, K26)

DFO(6308915-02)

10-APR-2020

LNM/D. 27-MAR-2020

Add wreck Wk with known depth of 2 fathoms 50°36'19.7"N 057°11'08.4"W

(See Chart No. 1, K26)

DFO(6308915-04)

27-MAR-2020

LNM/D. 14-FEB-2020

Delete depth of 13 fathoms 50°36'29.3"N 057°14'55.2"W

(See Chart No. 1, I10)

DFO(6308820-02)



Chart no. 4663

27-MAR-2020 LNM/D. 14-FEB-2020

Add depth of 8 fathoms 50°36'29.3"N 057°14'44.0"W
(See Chart No. 1, I10)

DFO(6308820-03)

27-MAR-2020 LNM/D. 14-FEB-2020

Delete depth of 9 fathoms 50°41'33.8"N 057°26'26.8"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276138 *DFO(6308865-01)*

27-MAR-2020 LNM/D. 14-FEB-2020

Add depth of 6 fathoms 50°41'28.0"N 057°26'30.1"W
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276138 *DFO(6308865-02)*

27-MAR-2020 LNM/D. 14-FEB-2020

Add depth of 8 fathoms 50°41'22.1"N 057°22'45.0"W
(See Chart No. 1, I10)

DFO(6308865-05)

27-MAR-2020 LNM/D. 14-FEB-2020

Delete depth of 13 fathoms 50°41'15.6"N 057°22'41.2"W
(See Chart No. 1, I10)

DFO(6308865-06)

27-MAR-2020 LNM/D. 14-FEB-2020

Delete depth of 12 fathoms 50°41'37.0"N 057°22'03.7"W
(See Chart No. 1, I10)

DFO(6308865-07)

27-MAR-2020 LNM/D. 14-FEB-2020

Add depth of 10 fathoms 50°41'37.9"N 057°22'05.6"W
(See Chart No. 1, I10)

DFO(6308865-08)

14-FEB-2020 LNM/D. 27-OCT-2017



Chart no. 4663

Delete depth of 16 fathoms 50°40'47.3"N 057°21'39.2"W
(See Chart No. 1, I10)

DFO(6308902-01)

14-FEB-2020

LNM/D. 27-OCT-2017

Add depth of 12 fathoms
(See Chart No. 1, I10)

50°40'47.4"N 057°21'51.6"W

This notice affects Electronic Navigational Chart: CA276138

DFO(6308902-02)

14-FEB-2020

LNM/D. 27-OCT-2017

Add depth of 9 fathoms
(See Chart No. 1, I10)

50°41'32.1"N 057°22'21.0"W

This notice affects Electronic Navigational Chart: CA276138

DFO(6308902-04)

14-FEB-2020

LNM/D. 27-OCT-2017

Delete depth of 6 fathoms 50°41'58.4"N 057°25'04.8"W
(See Chart No. 1, I10)

DFO(6308902-05)

14-FEB-2020

LNM/D. 27-OCT-2017

Delete depth of 4 fathoms 50°41'50.5"N 057°24'56.5"W
(See Chart No. 1, I10)

DFO(6308902-06)

14-FEB-2020

LNM/D. 27-OCT-2017

Add depth of 4 fathoms 50°41'52.7"N 057°25'07.6"W
(See Chart No. 1, I10)

DFO(6308902-08)

14-FEB-2020

LNM/D. 27-OCT-2017

Add depth of 1 fathoms 50°42'07.6"N 057°25'15.0"W
(See Chart No. 1, I10)

DFO(6308902-10)

14-FEB-2020

LNM/D. 27-OCT-2017

Delete depth of 12 fathoms 50°43'20.9"N 057°23'15.9"W
(See Chart No. 1, I10)

DFO(6308902-11)



Chart no. 4663

- 14-FEB-2020** LNM/D. 27-OCT-2017
Add depth of 10 fathoms 50°43'26.8"N 057°23'16.9"W
(See Chart No. 1, I10)
DFO(6308902-13)
- 27-OCT-2017** LNM/D. 30-JUN-2017
Delete green port hand lighted can buoy Fl G, marked 49°55'22.0"N 057°47'58.5"W
XW3
(See Chart No. 1, Qg) *(N2017039) LL(202.4) DFO(6308079-01)*
- 27-OCT-2017** LNM/D. 30-JUN-2017
Delete green port hand lighted can buoy Fl G, marked 49°55'28.5"N 057°48'15.0"W
XW1
(See Chart No. 1, Qg) *(N2017040) LL(202.6) DFO(6308079-02)*
- 27-OCT-2017** LNM/D. 30-JUN-2017
Add legend "Buoyed / Balisé" 49°55'34.0"N 057°48'46.0"W
DFO(6308079-03)
- 30-JUN-2017** LNM/D. 03-OCT-2014
Delete light Fl R, 50°01'44.0"N 057°42'47.3"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: *(N2017011) LL(203) DFO(6307906-01)*
CA276138
- 03-OCT-2014** LNM/D. 22-JUN-2012
Delete Fog Signal Fog Sig 30 sec 50°43'48.8"N 057°20'42.4"W
(See Chart No. 1, R1) *(N2014045) LL(211.4) DFO(6306847-01)*
- 22-JUN-2012** LNM/D. 30-JUL-2010
Add red starboard hand lighted spar buoy FlR, marked 50°14'33.6"N 057°35'16.3"W
XDH2
(See Chart No. 1, Qf) *(N2012009) LL(207.2) DFO(6306027-01)*
- 30-JUL-2010** LNM/D. 07-AUG-2009



Chart no. 4663

Amend Fl 5s 96ft to read Fl 5s 96ft 15M against light 50°41'54.6"N 057°24'36.8"W
(See Chart No 1 P16)

LL(211) DFO(6304958-01)

07-AUG-2009

Delete light Fl 6s 54ft
(See Chart No 1 P1)

LNM/D. 21-NOV-2008

50°14'28.0"N 057°35'20.0"W

(N2009016) LL(207) DFO(6304431-01)

This notice affects Electronic Navigational Chart:
CA276138

21-NOV-2008

Amend Fl 15s 108ft 8M to read Fl 15s 108ft 17M against light 50°37'58.9"N 057°19'19.9"W
(See Chart No 1 P16)

LNM/D. 14-NOV-2008

LL(208.0) DFO(6304132-01)

14-NOV-2008

Add note:
DIAGRAM / DIAGRAMME
See Sailing Directions
Voir Instructions nautiques

LNM/D. 26-OCT-2007

49°53'54.0"N 057°46'30.0"W

DFO(6304065-01)

26-OCT-2007

Add green port hand lighted spar buoy FlG, marked XPP1
(See Chart No 1 Section Q 24.)

50°02'02.5"N 057°42'50.9"W

(N2007036) LL(203.2) DFO(6303629-01)

26-OCT-2007

Add red starboard hand lighted spar buoy FlR, marked
XPP2
(See Chart No 1 Section Q 24.)

50°02'01.4"N 057°42'51.2"W

(N2007037) LL(203.1) DFO(6303630-01)