



Chart no. 4745

4745 - White Point to / à Sandy Island - New Edition - 07-MAR-2003 - NAD 1983

15-JAN-2016

LNМ/D. 30-JUL-2010

Add depth of 5 fathoms, 5 feet
(See Chart No. 1, I10)

53°34'09.8"N 056°00'20.7"W

This notice affects Electronic Navigational Chart: CA376596

DFO(6307408-01)

15-JAN-2016

LNМ/D. 30-JUL-2010

Add depth of 4 fathoms, 4 feet

53°32'59.0"N 055°57'33.4"W

(See Chart No. 1, I10)

DFO(6307408-02)

This notice affects Electronic Navigational Chart: CA376596

30-JUL-2010

LNМ/D. 23-JUL-2010

Reposition black, yellow and black East cardinal lighted
pillar buoy Q(3) 10s, marked NLG
(See Chart No 1 Q130.3)

from 53°21'00.4"N 055°43'36.5"W
to 53°20'56.6"N 055°43'42.4"W

(N2010016) LL(280.15) DFO(6304967-01)

23-JUL-2010

LNМ/D. 03-APR-2009

Reposition red starboard hand lighted spar buoy FIR,
marked N14
(See Chart No 1 Qf)

from 53°33'33.4"N 055°59'21.0"W
to 53°33'35.3"N 055°59'23.5"W

(N2010016) LL(281.8) DFO(6304961-01)

This notice affects Electronic Navigational
Chart: CA376596

03-APR-2009

LNМ/D. 15-SEP-2006

Add ferry route joining 53°36'25.3"N 055°51'42.0"W
(See Chart No 1 M50) 53°33'06.0"N 055°44'30.0"W
and 53°32'32.6"N 055°43'40.6"W

DFO(6303319-01)

03-APR-2009

LNМ/D. 15-SEP-2006

Add ferry route between 53°33'06.0"N 055°44'30.0"W
(See Chart No 1 M50) and 53°32'15.3"N 055°43'40.6"W

DFO(6303319-02)



Chart no. 4745

15-SEP-2006

Delete red starboard hand lighted spar buoy FIR, marked
NTK2

LNМ/D. 08-SEP-2006

53°33'02.2"N 055°58'40.0"W

(N2006050) LL(281.7) DFO(6302938-02)

15-SEP-2006

Add red starboard hand lighted spar buoy FIR, marked
N12

LNМ/D. 08-SEP-2006

53°33'02.2"N 055°58'35.6"W

(N2006050) LL(281.7) DFO(6302938-03)

15-SEP-2006

Amend "NTK5" to read "N15" against green port hand
spar light buoy FIG

LNМ/D. 08-SEP-2006

53°33'32.3"N 055°59'42.6"W

(N2006053) LL(281.9) DFO(6302941-01)

15-SEP-2006

Amend "NTK6" to read "N14" against red starboard hand
lighted spar buoy FIR

LNМ/D. 08-SEP-2006

53°33'33.4"N 055°59'21.0"W

(N2006054) LL(281.8) DFO(6302942-01)

08-SEP-2006

Replace green port hand lighted pillar buoy FIG, marked
NBT5 with green port hand lighted spar buoy
FIG, marked NBT1

LNМ/D. 24-SEP-2004

53°27'07.2"N 055°45'49.5"W

(N2006051) LL(280.91) DFO(6302939-02)

24-SEP-2004

Reposition green port hand spar light buoy FIG, marked
NTK5

from 53°33'33.4"N 055°59'55.6"W

to 53°33'32.3"N 055°59'42.6"W

(N2004150) LL(281.9) DFO(6301836-01)