



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4820

### 4820 - Cape Freels to / à Exploits Islands - New Chart - 01-JUL-2005 - NAD 1983

**11-NOV-2022** LNM/D. 07-OCT-2022

Affix patch 49°12'11.0"N 054°48'59.0"W  
[PDF](#)

*DFO(6310338-11)*

**07-OCT-2022**

LNM/D. 12-AUG-2022

Add light Fl 6s4M

49°27'22.5"N 054°53'04.1"W

(See Chart 1, P1)

This notice affects Electronic Navigational Chart: *(N2022141) LL(354.5) DFO(6310235-01)*  
CA376655, CA476803

**07-OCT-2022**

LNM/D. 12-AUG-2022

Amend Fl 6s to read LFl 6s against light

49°45'06.8"N 054°09'11.9"W

(See Chart 1, P16)

This notice affects Electronic Navigational Chart: *(N2022169) LL(384) DFO(6310277-01)*  
CA376655, CA476719

**12-AUG-2022**

LNM/D. 11-FEB-2022

Add black and yellow North cardinal pillar buoy Q,  
marked DDR

49°46'53.8"N 054°06'35.0"W

(See Chart No. 1, Q130.3)

This notice affects Electronic Navigational Chart: *(N2022085) LL(383.3) DFO(6310136-01)*  
CA376655, CA476719

**11-FEB-2022**

LNM/D. 10-SEP-2021

Add light Fl R

49°32'37.3"N 054°52'40.9"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: *(N2021175) LL(355.3) DFO(6309897-01)*  
CA376655, CA476803

**11-FEB-2022**

LNM/D. 10-SEP-2021

Add light Fl

49°34'33.8"N 054°22'10.1"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: *(N2021176) LL(371.1) DFO(6309898-01)*  
CA376655, CA476813

**10-SEP-2021**

LNM/D. 25-SEP-2020



### Chart no. 4820

Amend Fl R to read Fl against light 49°27'36.2"N 053°57'19.7"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: (N2021049) LL(396.75) DFO(6309530-01)  
CA376655, CA476279, CA576504

#### 10-SEP-2021

LNМ/D. 25-SEP-2020

Amend Oc G to read Fl G against light 49°27'23.1"N 053°56'28.5"W  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: (N2021062) LL(399) DFO(6309541-01)  
CA376655, CA476279

#### 25-SEP-2020

LNМ/D. 07-AUG-2020

Amend Fl 6s10m6M to read Fl 4s10m5M against light 49°26'56.1"N 054°13'41.6"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (N2020073) LL(389) DFO(6309151-01)  
CA376655, CA476813

#### 07-AUG-2020

LNМ/D. 03-JUL-2020

Amend QG to read Fl G against light 49°38'40.0"N 054°46'18.0"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (N2020044) LL(361) DFO(6309011-01)  
CA376655, CA476804

#### 03-JUL-2020

LNМ/D. 17-AUG-2018

Amend Fl G(Priv) to read Fl G against light 49°40'07.7"N 054°24'49.0"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (N2020041) LL(372) DFO(6309008-01)  
CA376655, CA476814

#### 17-AUG-2018

LNМ/D. 20-OCT-2017

Add light Fl R 49°27'36.2"N 053°57'19.7"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: (N2018038) LL(396.75) DFO(6308330-01)  
CA376655, CA476279

#### 20-OCT-2017

LNМ/D. 25-AUG-2017

Delete yellow ODAS/SADO lighted can buoy OcY 49°35'35.8"N 054°56'11.8"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA376655, DFO(6308067-01)  
CA476804



## Chart no. 4820

### 20-OCT-2017

Add yellow ODAS/SADO lighted pillar Fl (5) Y 20s  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA376655,  
CA476804

LNМ/D. 25-AUG-2017  
49°35'49.8"N 054°56'03.6"W  
*DFO(6308067-02)*

### 25-AUG-2017

Delete ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

LNМ/D. 26-FEB-2016  
joining 49°33'24.1"N 054°28'31.7"W  
49°34'07.8"N 054°24'09.1"W  
and 49°34'14.1"N 054°24'09.1"W  
*DFO(6308011-03)*

### 25-AUG-2017

Add ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

LNМ/D. 26-FEB-2016  
between 49°33'30.1"N 054°26'04.2"W  
and 49°34'08.2"N 054°23'40.4"W  
*DFO(6308011-04)*

### 25-AUG-2017

Delete ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

LNМ/D. 26-FEB-2016  
joining 49°33'24.1"N 054°28'31.7"W  
49°33'31.5"N 054°19'15.4"W  
and 49°34'10.4"N 054°18'15.1"W  
*DFO(6308011-05)*

### 25-AUG-2017

Add ferry route  
(See Chart No. 1, M50)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476813

LNМ/D. 26-FEB-2016  
joining 49°33'24.1"N 054°28'31.7"W  
49°33'30.1"N 054°26'04.2"W  
49°33'17.2"N 054°20'00.0"W  
49°33'24.1"N 054°19'14.2"W  
and 49°34'10.4"N 054°18'15.1"W  
*DFO(6308011-06)*

### 26-FEB-2016

Replace yellow ODAS/SADO lighted pillar Fl (5)Y20s with  
yellow ODAS/SADO lighted can buoy OcY  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart:  
CA376655, CA476804

LNМ/D. 06-NOV-2015  
49°35'36.0"N 054°56'12.0"W  
*(N2015086) LL(NULL) DFO(6307421-01)*



## Chart no. 4820

### 06-NOV-2015

Add ferry route

(See Chart No. 1, M50)

This notice affects Electronic Navigational Chart:  
CA376655, CA476813

LNМ/D. 16-JAN-2015

joining 49°34'14.1"N 054°24'03.5"W  
49°34'02.3"N 054°23'18.8"W  
49°34'53.1"N 054°22'04.6"W  
and 49°34'10.4"N 054°18'15.5"W

*DFO(6307250-03)*

### 16-JAN-2015

Delete legend Fog Sig 60s against light

(See Chart No. 1, R20)

This notice affects Electronic Navigational Chart:  
CA276092, CA376371, CA576373

LNМ/D. 12-DEC-2014

49°10'28.1"N 053°22'03.3"W

*(N2014066) LL(406) DFO(6306986-01)*

### 16-JAN-2015

Delete legend Fog Sig 30s against light

(See Chart No. 1, R20)

This notice affects Electronic Navigational Chart:  
CA276092, CA376655, CA476279

LNМ/D. 12-DEC-2014

49°31'49.6"N 053°51'04.8"W

*(N2014067) LL(395) DFO(6306987-01)*

### 12-DEC-2014

Add yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s

(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart: CA376655,  
CA476804

LNМ/D. 28-MAR-2014

49°35'34.4"N 054°56'09.7"W

*DFO(6306965-01)*

### 28-MAR-2014

Amend sector light FRWG to read FRWG (Occas) against light

(See Chart No 1 P50)

This notice affects Electronic Navigational Chart: CA376655,  
CA476814

LNМ/D. 28-OCT-2011

49°41'14.5"N 054°33'17.1"W

*LL(362.5) DFO(6306703-01)*

### 28-OCT-2011

Delete light FlR

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:  
CA376655

LNМ/D. 10-DEC-2010

49°21'18.4"N 054°29'21.4"W

*(N2011073) LL(386.1) DFO(6305763-01)*



## Chart no. 4820

### 10-DEC-2010

Add yellow, black and yellow West cardinal lighted spar  
buoy VQ(9) 10s, marked DSR  
(See Chart No 1 Q130.3)

LNM/D. 17-SEP-2010

49°32'32.4"N 054°57'19.2"W

*(N2010056) LL(359.9) DFO(6305123-01)*

This notice affects Electronic Navigational Chart:  
CA376655

### 10-DEC-2010

Add depth of 4 metres, 8 decimetres  
(See Chart No 1 I10)

LNM/D. 17-SEP-2010

49°33'23.1"N 054°25'38.0"W

*DFO(6305132-02)*

This notice affects Electronic Navigational Chart: CA376655,  
CA476813

### 17-SEP-2010

Amend Fl 6s 13m 17M to read Fl 6s 13m 16M against light  
(See Chart No. 1 P16)

LNM/D. 27-AUG-2010

49°36'03.6"N 054°09'29.3"W

*LL(378) DFO(6305022-01)*

This notice affects Electronic Navigational Chart: CA476279

### 27-AUG-2010

Delete depth of 3 metres, 8 decimetres  
(See Chart No. 1, I10)

LNM/D. 23-JUL-2010

49°45'15.0"N 054°18'42.5"W

*DFO(6304983-01)*

This notice affects Electronic Navigational Chart: CA476814

### 27-AUG-2010

Add depth of 3 metres, 3 decimetres  
(See Chart No. 1, I10)

LNM/D. 23-JUL-2010

49°45'15.0"N 054°18'40.8"W

*DFO(6304983-02)*

This notice affects Electronic Navigational Chart: CA476814

### 27-AUG-2010

LNM/D. 23-JUL-2010



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4820

Delete depth of 18 metres, 3 decimetres  
(See Chart No. 1, I10)

49°43'12.0"N 054°19'53.8"W

*DFO(6304983-03)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Add depth of 16 metres, 8 decimetres  
(See Chart No. 1, I10)

LN/D. 23-JUL-2010

49°43'13.8"N 054°19'57.0"W

*DFO(6304983-04)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Delete depth of 5 metres, 3 decimetres  
(See Chart No. 1, I10)

LN/D. 23-JUL-2010

49°37'59.0"N 054°21'00.0"W

*DFO(6304983-05)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Add depth of 4 metres, 9 decimetres  
(See Chart No. 1, I10)

LN/D. 23-JUL-2010

49°37'58.8"N 054°21'00.0"W

*DFO(6304983-06)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Delete depth of 4 metres, 2 decimetres  
(See Chart No. 1, I10)

LN/D. 23-JUL-2010

49°39'10.4"N 054°21'35.0"W

*DFO(6304983-07)*

This notice affects Electronic Navigational Chart: CA476814

#### **27-AUG-2010**

Add depth of 3 metres, 8 decimetres  
(See Chart No. 1, I10)

LN/D. 23-JUL-2010

49°39'10.2"N 054°21'37.2"W

*DFO(6304983-08)*

This notice affects Electronic Navigational Chart: CA476814



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4820

### 27-AUG-2010

Delete depth of 14 metres, 3 decimetres  
(See Chart No. 1, I10)

LNМ/D. 23-JUL-2010

49°39'16.8"N 054°20'02.7"W

*DFO(6304983-09)*

This notice affects Electronic Navigational Chart: CA476814

### 27-AUG-2010

Add depth of 13 metres, 8 decimetres  
(See Chart No. 1, I10)

LNМ/D. 23-JUL-2010

49°39'16.2"N 054°20'01.8"W

*DFO(6304983-10)*

This notice affects Electronic Navigational Chart: CA476814

### 23-JUL-2010

Delete radio mast with elevation of 49 metres  
(See Chart No 1 E28)

LNМ/D. 04-JUN-2010

49°24'02.0"N 054°51'02.0"W

*DFO(6304923-01)*

This notice affects Electronic Navigational Chart: CA476168

### 23-JUL-2010

Add radio mast, Ro, RLts  
(See Chart No 1 E28, P61.2)

LNМ/D. 04-JUN-2010

49°24'03.6"N 054°51'31.1"W

*DFO(6304923-02)*

This notice affects Electronic Navigational Chart: CA476168

### 23-JUL-2010

Delete radio mast, Ro, with elevation of 198 metres, RLts  
(See Chart No 1 E28)

LNМ/D. 04-JUN-2010

49°20'37.0"N 054°52'09.0"W

*DFO(6304923-03)*

This notice affects Electronic Navigational Chart: CA476168

### 23-JUL-2010

Delete radio mast  
(See Chart No 1 E28)

LNМ/D. 04-JUN-2010

49°19'57.0"N 054°51'56.0"W

*DFO(6304923-05)*

This notice affects Electronic Navigational Chart: CA476168



**Chart no. 4820**

**23-JUL-2010**

Delete radiobeacon, R  
(See Chart No 1, S15)

LNМ/D. 04-JUN-2010

49°20'04.0"N 054°51'29.0"W

*DFO(6304923-06)*

This notice affects Electronic Navigational Chart: CA476168

**23-JUL-2010**

Amend RoTrs Loran to read Ro Tr against radio mast  
(See Chart No 1 E28)

LNМ/D. 04-JUN-2010

49°19'53.5"N 054°51'42.3"W

*DFO(6304923-13)*

This notice affects Electronic Navigational Chart: CA476168

**04-JUN-2010**

Reposition green port spar light buoy Fl G, marked DBE3  
(See Chart No 1 Qg)

LNМ/D. 31-JUL-2009

from 49°28'42.0"N 055°01'17.5"W  
to 49°28'52.1"N 055°01'12.4"W

*(N2010016) LL(347.3) DFO(6304804-01)*

**31-JUL-2009**

Delete depth of 19 metres, 9 decimetres 49°47'59.6"N 054°14'35.6"W  
(See Chart No 1 I10)

LNМ/D. 10-OCT-2008

*DFO(6304450-01)*

**31-JUL-2009**

Delete depth of 24 metres, 9 decimetres 49°48'25.4"N 054°13'43.6"W  
(See Chart No 1 I10)

LNМ/D. 10-OCT-2008

*DFO(6304450-02)*

**31-JUL-2009**

Delete depth of 15 metres, 4 decimetres 49°49'59.0"N 054°09'41.6"W  
(See Chart No 1 I10)

LNМ/D. 10-OCT-2008

*DFO(6304450-03)*

**31-JUL-2009**

Delete depth of 2 metres, 4 decimetres 49°51'19.1"N 054°03'10.5"W  
(See Chart No 1 I10)

LNМ/D. 10-OCT-2008

*DFO(6304450-04)*





**Chart no. 4820**

**31-JUL-2009**

LNМ/D. 10-OCT-2008

Delete depth of 4 metres, 5 decimetres 49°51'26.8"N 054°02'04.1"W  
(See Chart No 1 I10)

*DFO(6304450-05)*

**31-JUL-2009**

LNМ/D. 10-OCT-2008

Add depth of 1 metre, 9 decimetres 49°47'51.8"N 054°14'30.7"W  
(See Chart No 1 I10)

*DFO(6304450-06)*

**31-JUL-2009**

LNМ/D. 10-OCT-2008

Add depth of 1 metre, 4 decimetres 49°48'18.2"N 054°13'41.3"W  
(See Chart No 1 I10)

*DFO(6304450-07)*

**31-JUL-2009**

LNМ/D. 10-OCT-2008

Add depth of 3 metres, 3 decimetres 49°49'59.7"N 054°09'30.0"W  
(See Chart No 1 I10)

*DFO(6304450-08)*

**31-JUL-2009**

LNМ/D. 10-OCT-2008

Add depth of 1 metre, 6 decimetres 49°51'19.0"N 054°03'05.6"W  
(See Chart No 1 I10)

*DFO(6304450-09)*

**31-JUL-2009**

LNМ/D. 10-OCT-2008

Add depth of 2 metres, 2 decimetres 49°51'22.3"N 054°02'11.5"W  
(See Chart No 1 I10)

*DFO(6304450-10)*

**10-OCT-2008**

LNМ/D. 25-MAY-2007

Add sector light F RWG 49°41'14.5"N 054°33'17.1"W  
(See Chart No 1 P1)

*(N2008040) LL(362.5) DFO(6304063-02)*

**25-MAY-2007**

LNМ/D. 08-SEP-2006



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

**Chart no. 4820**

Add light FIR 49°21'18.4"N 054°29'21.4"W

*(N2005074) LL(386.1) DFO(6303416-01)*

**08-SEP-2006**

LN/D. 17-MAR-2006

Delete ferry route between 49°35'12.0"N 054°56'45.0"W  
and 50°09'30.0"N 055°06'45.0"W

*DFO(6302973-01)*

**08-SEP-2006**

LN/D. 17-MAR-2006

Add ferry route between 49°35'12.0"N 054°56'45.0"W  
and 50°09'30.0"N 054°59'24.0"W

*DFO(6302973-02)*

**17-MAR-2006**

Delete light Fl 49°21'20.0"N 054°29'30.0"W

*DFO(6302760-01)*