



### Chart no. 4831

#### 4831 - Fortune Bay: Northern Portion / Partie Nord - New Chart - 26-DEC-1986 - NAD 1983

**12-NOV-2021**

LNМ/D. 24-SEP-2021

Amend FLR 4s to read Fl Y 4s against light  
(See Chart No. 1, P16)

47°38'08.4"N 055°12'40.4"W

This notice affects Electronic Navigational Chart: (N2021165) LL(115.9) DFO(6309729-01)  
CA376316

**24-SEP-2021**

LNМ/D. 18-SEP-2020

Add light Fl G  
(See Chart No. 1, P1)

47°37'56.3"N 054°53'07.9"W

This notice affects Electronic Navigational Chart: (N2021078) LL(113.06) DFO(6309554-01)  
CA376316

**24-SEP-2021**

LNМ/D. 18-SEP-2020

Add pier  
(See Chart No. 1, F14)

between 47°37'55.5"N 054°53'10.5"W  
and 47°37'56.3"N 054°53'07.9"W

This notice affects Electronic Navigational Chart: DFO(6309554-02)  
CA376316

**18-SEP-2020**

LNМ/D. 31-JUL-2020

Delete light F R  
(See Chart No. 1, P1)

47°39'51.0"N 054°43'40.0"W

This notice affects Electronic Navigational Chart: CA376316 DFO(6309183-01)

**18-SEP-2020**

LNМ/D. 31-JUL-2020

Delete pier  
(See Chart No. 1, F14)

between 47°39'50.7"N 054°43'40.2"W  
and 47°39'52.0"N 054°43'39.8"W

This notice affects Electronic Navigational Chart: DFO(6309183-02)  
CA376316

**31-JUL-2020**

LNМ/D. 10-APR-2020

Amend Fl3s62m to read Fl 4s62m against light  
(See Chart No. 1, P16)

47°33'28.5"N 054°52'33.0"W

This notice affects Electronic Navigational Chart: (N2020038) LL(113) DFO(6309013-01)  
CA276274, CA376316

**10-APR-2020**

LNМ/D. 31-AUG-2018



### Chart no. 4831

Add marine farm (See Chart No. 1, K48.2) This notice affects Electronic Navigational Chart: CA376316	47°38'36.1"N 055°08'56.1"W  <i>DFO(6308949-01)</i>
<b>31-AUG-2018</b> Add marine farm (See Chart No. 1, K48.2) This notice affects Electronic Navigational Chart: CA376316	LNM/D. 14-JUL-2017 47°39'30.7"N 055°22'06.6"W  <i>DFO(6308406-01)</i>
<b>31-AUG-2018</b> Add marine farm (See Chart No. 1, K48.2) This notice affects Electronic Navigational Chart: CA376316	LNM/D. 14-JUL-2017 47°39'52.0"N 055°22'31.0"W  <i>DFO(6308406-02)</i>
<b>14-JUL-2017</b> Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres (See Chart No. 1, L25) This notice affects Electronic Navigational Chart: CA376233	LNM/D. 14-APR-2017 47°31'25.7"N 055°20'26.4"W  <i>DFO(6307974-03)</i>
<b>14-JUL-2017</b> Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres (See Chart No. 1, L25) This notice affects Electronic Navigational Chart: CA376316	LNM/D. 14-APR-2017 47°38'22.9"N 055°17'49.6"W  <i>DFO(6307974-04)</i>
<b>14-JUL-2017</b> Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres (See Chart No. 1, L25) This notice affects Electronic Navigational Chart: CA376233	LNM/D. 14-APR-2017 47°26'03.4"N 055°29'27.3"W  <i>DFO(6307974-06)</i>
<b>14-JUL-2017</b> Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres (See Chart No. 1, L25) This notice affects Electronic Navigational Chart: CA276274, CA376316	LNM/D. 14-APR-2017 47°38'08.1"N 055°23'11.7"W  <i>DFO(6307974-07)</i>



### Chart no. 4831

#### 14-JUL-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNM/D. 14-APR-2017  
47°34'47.3"N 055°10'05.0"W  
*DFO(6307974-08)*

#### 14-JUL-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNM/D. 14-APR-2017  
47°28'43.2"N 055°09'57.1"W  
*DFO(6307974-09)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNM/D. 05-FEB-2016  
47°42'17.0"N 055°23'02.7"W  
*DFO(6307848-01)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

LNM/D. 05-FEB-2016  
47°38'08.1"N 055°23'11.7"W  
*DFO(6307848-02)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNM/D. 05-FEB-2016  
47°37'59.1"N 055°26'25.1"W  
*DFO(6307848-03)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNM/D. 05-FEB-2016  
47°38'22.9"N 055°17'49.6"W  
*DFO(6307848-04)*

#### 14-APR-2017

LNM/D. 05-FEB-2016



### Chart no. 4831

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

47°37'57.0"N 055°16'39.0"W  
*DFO(6307848-06)*

**14-APR-2017** LNM/D. 05-FEB-2016  
Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

47°34'47.3"N 055°10'05.0"W  
*DFO(6307848-07)*

**14-APR-2017** LNM/D. 05-FEB-2016  
Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376233

47°33'29.4"N 055°19'44.4"W  
*DFO(6307848-08)*

**14-APR-2017** LNM/D. 05-FEB-2016  
Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376233

47°33'26.0"N 055°19'54.0"W  
*DFO(6307848-09)*

**14-APR-2017** LNM/D. 05-FEB-2016  
Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

47°32'57.0"N 055°16'39.0"W  
*DFO(6307848-10)*

**14-APR-2017** LNM/D. 05-FEB-2016  
Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376233

47°31'25.7"N 055°20'26.4"W  
*DFO(6307848-11)*

**14-APR-2017** LNM/D. 05-FEB-2016



### Chart no. 4831

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

47°28'43.2"N 055°09'57.1"W

*DFO(6307848-12)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376233

LNМ/D. 05-FEB-2016

47°26'03.4"N 055°29'27.3"W

*DFO(6307848-13)*

#### 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNМ/D. 05-FEB-2016

47°38'09.6"N 055°16'51.6"W

*DFO(6307848-16)*

#### 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

LNМ/D. 07-AUG-2015

47°32'57.0"N 055°16'39.0"W

*DFO(6307401-01)*

#### 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres.  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

LNМ/D. 20-MAR-2015

47°37'57.0"N 055°16'39.0"W

*DFO(6307179-01)*

#### 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres.  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNМ/D. 20-MAR-2015

47°38'09.6"N 055°16'51.6"W

*DFO(6307179-02)*

#### 07-AUG-2015

LNМ/D. 20-MAR-2015



### Chart no. 4831

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres. 47°33'29.4"N 055°19'44.4"W  
(See Chart No. 1, L25) *DFO(6307179-03)*  
This notice affects Electronic Navigational Chart: CA276274,  
CA376233

### 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres. LNM/D. 20-MAR-2015  
(See Chart No. 1, L25) 47°33'26.4"N 055°19'55.8"W  
This notice affects Electronic Navigational Chart: CA376233 *DFO(6307179-04)*

### 20-MAR-2015

Delete light Fl6s50m LNM/D. 10-JAN-2014  
(See Chart No. 1, P1) 47°34'42.0"N 055°07'05.0"W  
This notice affects Electronic Navigational Chart: (N2015008) LL(115) *DFO(6307061-01)*  
CA276274, CA376316

### 10-JAN-2014

Add yellow and black South cardinal lighted spar buoy LNM/D. 20-DEC-2013  
VQ(6)+ LF110s, marked VRE 47°38'08.1"N 055°12'46.0"W  
(See Chart No. 1, Q130.3) (N2013029) LL(115.8) *DFO(6306564-01)*

### 20-DEC-2013

Delete red starboard hand lighted spar buoy FlR, marked LNM/D. 29-MAR-2013  
VV2 47°36'18.0"N 055°06'35.4"W  
(See Chart No. 1, Qf) (N2013016) LL(115.2) *DFO(6306542-01)*

### 29-MAR-2013

Add marine farm LNM/D. 29-OCT-2010  
47°33'18.0"N 055°23'28.4"W  
(See Chart No. 1, K48.2) *DFO(6306337-01)*

### 29-OCT-2010

Add wharf LNM/D. 23-JUL-2010  
between 47°31'36.5"N 055°24'33.9"W  
(See Chart No. 1 F13) and 47°31'34.8"N 055°24'33.6"W  
*DFO(6305015-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4831

**29-OCT-2010**

LNМ/D. 23-JUL-2010

Add wharf between 47°31'36.5"N 055°24'33.9"W  
(See Chart No. 1 F13) and 47°31'35.6"N 055°24'31.3"W

*DFO(6305015-02)*

**29-OCT-2010**

LNМ/D. 23-JUL-2010

Add light Fl G 47°31'34.8"N 055°24'33.6"W  
(See Chart No. 1 P1)

*(N2010043) LL(116.9) DFO(6305015-03)*

**23-JUL-2010**

LNМ/D. 18-JUN-2010

Delete light FR 47°40'48.0"N 055°25'48.0"W  
(See Chart 1 P16)

*(N2010033) LL(116.3) DFO(6304906-01)*

**23-JUL-2010**

LNМ/D. 18-JUN-2010

Add extension to wharf between 47°40'48.0"N 055°25'48.0"W  
(See Chart 1 F14) and 47°40'49.6"N 055°25'46.2"W

*DFO(6304906-02)*

**23-JUL-2010**

LNМ/D. 18-JUN-2010

Add light FlR 47°40'49.6"N 055°25'46.2"W  
(See Chart 1 P16)

*(N2010033) LL(116.3) DFO(6304906-03)*

**18-JUN-2010**

LNМ/D. 02-JAN-2009

Add light FlR 4s 47°38'08.4"N 055°12'41.5"W  
(See Chart 1 P16)

*LL(115.9) DFO(6304801-01)*

**02-JAN-2009**

LNМ/D. 19-SEP-2008

Add yellow and black South cardinal lighted pillar buoy  
VQ(6)+LFl 10s, marked VL

47°34'37.0"N 055°09'29.0"W

(See Chart No 1 Qm)

*(N2008045) LL(114.9) DFO(6304169-01)*

**19-SEP-2008**

LNМ/D. 29-AUG-2008



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4831

Add black and yellow North cardinal lighted pillar buoy Q,  
marked VB  
(See Chart No 1 Q130.3) 47°35'52.7"N 055°19'41.9"W  
(N2008027) LL(116.6) DFO(6304018-01)

**29-AUG-2008** LNM/D. 02-NOV-2007  
Add dangerous underwater rock of 2 metres or less, reported 2008 47°35'48.0"N 054°59'00.3"W  
(See Chart No 1 K13, I3.2) DFO(6303999-01)

**02-NOV-2007** LNM/D. 11-AUG-2006  
Add green port hand lighted spar buoy FIG, marked VJF1 47°31'48.0"N 054°55'30.0"W  
(N2007051) LL(113.6) DFO(6303641-01)

**11-AUG-2006** LNM/D. 26-MAY-2006  
Add red starboard hand lighted spar buoy FIR, marked  
VM2 47°35'06.5"N 054°53'05.1"W  
(N2006018) LL(113.08) DFO(6302897-01)

**26-MAY-2006** LNM/D. 07-OCT-2005  
Add light FIR 47°32'51.0"N 054°52'52.0"W  
(N1998117) LL(113.2) DFO(6300722-01)

**07-OCT-2005** LNM/D. 16-APR-2004  
Add breakwater between 47°27'05.0"N 055°33'34.0"W  
and 47°27'05.2"N 055°33'28.2"W  
DFO(6302416-01)

**07-OCT-2005** LNM/D. 16-APR-2004  
Reposition light FIG from 47°27'06.5"N 055°33'30.8"W  
to 47°27'05.2"N 055°33'28.2"W  
(N2005039) LL(119.5) DFO(6302416-02)

**16-APR-2004** LNM/D. 26-DEC-2003





### Chart no. 4831

Amend Fl to read Fl R 4s 14m 5M against light 47°27'18.0"N 055°29'33.0"W

*(N2002103) LL(119) DFO(6300521-01)*

**26-DEC-2003**

LNM/D. 11-APR-2003

Amend Fl R 3s 17m to read Fl 3s 17m 47°24'13.8"N 055°35'02.5"W

*LL(120) DFO(6300972-01)*

**11-APR-2003**

LNM/D. 15-MAR-2002

Delete green, port hand can buoy, marked VE1 47°27'29.0"N 055°29'44.0"W

*(N2000260) DFO(6829120-01)*

**11-APR-2003**

LNM/D. 15-MAR-2002

Add green port hand spar light buoy FIG, marked VE1 47°27'29.0"N 055°29'41.7"W

*(N2000260) LL(116.410) DFO(6829120-02)*

**11-APR-2003**

LNM/D. 15-MAR-2002

Replace red, starboard hand spar buoy, marked VV2 with  
red starboard hand spar light buoy FlR, marked  
VV2 47°36'18.0"N 055°06'35.4"W

*(N2001130) LL(115.2) DFO(6829755-01)*

**11-APR-2003**

LNM/D. 15-MAR-2002

Replace green, port hand spar buoy, marked VS1, with  
green port hand spar light buoy FIG, marked VS1 47°31'47.8"N 054°57'09.2"W

*(N2001131) LL(113.4) DFO(6829756-01)*

**15-MAR-2002**

LNM/D. 25-JAN-2002

Add non-dangerous wreck 47°34'56.4"N 054°56'14.4"W

*(N2002001) DFO(6300102-01)*

**25-JAN-2002**

LNM/D. 07-DEC-2001



**Chart no. 4831**

Amend FI R 6s 14m to read Fl 47°27'18.0"N 055°29'33.0"W  
(N2000037) LL(119) DFO(6828798-01)

**25-JAN-2002** LNM/D. 07-DEC-2001  
Add light FIG 47°27'06.5"N 055°33'30.8"W  
(N2000246) LL(119.5) DFO(6829093-01)

**25-JAN-2002** LNM/D. 07-DEC-2001  
Delete anchorage symbol 47°28'36.0"N 055°28'18.0"W  
DFO(6829829-01)

**07-DEC-2001** LNM/D. 11-MAY-2001  
Replace green port hand spar buoy, marked VD5, with  
green light, port hand spar buoy FIG, marked  
VD5 47°35'47.8"N 055°25'00.0"W  
(N2000261) LL(116.4) DFO(6829121-01)

**07-DEC-2001** LNM/D. 11-MAY-2001  
Add submerged wreck 47°31'41.5"N 054°58'02.3"W  
(N2001146) DFO(6829827-01)

**11-MAY-2001** LNM/D. 12-MAR-1999  
Delete green, red, green port bifurcation pillar light  
buoy, FL (2+1) G, marked VBL 47°29'13.0"N 055°22'43.0"W  
(N2000-213) LL(117.5) DFO(6829032-01)

**11-MAY-2001** LNM/D. 12-MAR-1999  
Delete red and white fairway pillar, light buoy Mo (A),  
marked VSJ 47°27'36.0"N 055°26'00.0"W  
(N2000-214) LL(118.5) DFO(6829033-01)