



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4831

### 4831 - Fortune Bay: Northern Portion / Partie Nord - New Chart - 26-DEC-1986 - NAD 1983

**26-JUL-2024**

LNLM/D. 28-APR-2023

Amend light Fl 4s62m to read Fl 5s62m against light  
(See Chart 1, P16)

47°33'28.6"N 054°52'33.3"W

(N2024088) LL(113) DFO(6311259-01)

**28-APR-2023**

LNLM/D. 30-SEP-2022

Add green port hand lighted spar buoy Fl G, marked  
VJK1

47°37'38.0"N 054°52'55.4"W

(See Chart 1, Qc)

(N2023053) LL(113.07) DFO(6310652-01)

This notice affects Electronic Navigational Chart:  
CA376316

**30-SEP-2022**

LNLM/D. 12-NOV-2021

Add marine farm limits

joining 47°39'26.6"N 055°08'35.8"W

(See Chart No. 1, K48.1)

47°39'20.9"N 055°08'19.2"W

This notice affects Electronic Navigational Chart:  
CA376316

47°39'51.1"N 055°07'57.6"W

47°39'56.6"N 055°08'14.3"W

and 47°39'26.6"N 055°08'35.8"W

DFO(6310318-01)

**12-NOV-2021**

LNLM/D. 24-SEP-2021

Amend FLR 4s to read Fl Y 4s against light

47°38'08.4"N 055°12'40.4"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:  
CA376316

(N2021165) LL(115.9) DFO(6309729-01)

**24-SEP-2021**

LNLM/D. 18-SEP-2020

Add light Fl G

47°37'56.3"N 054°53'07.9"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:  
CA376316

(N2021078) LL(113.06) DFO(6309554-01)

**24-SEP-2021**

LNLM/D. 18-SEP-2020

Add pier

between 47°37'55.5"N 054°53'10.5"W

(See Chart No. 1, F14)

and 47°37'56.3"N 054°53'07.9"W

This notice affects Electronic Navigational Chart:  
CA376316

DFO(6309554-02)



### Chart no. 4831

#### 18-SEP-2020

Delete light F R

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: CA376316

LNLM/D. 31-JUL-2020

47°39'51.0"N 054°43'40.0"W

*DFO(6309183-01)*

#### 18-SEP-2020

Delete pier

(See Chart No. 1, F14)

This notice affects Electronic Navigational Chart:  
CA376316

LNLM/D. 31-JUL-2020

between 47°39'50.7"N 054°43'40.2"W  
and 47°39'52.0"N 054°43'39.8"W

*DFO(6309183-02)*

#### 31-JUL-2020

Amend Fl3s62m to read Fl 4s62m against light

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:  
CA276274, CA376316

LNLM/D. 10-APR-2020

47°33'28.5"N 054°52'33.0"W

*(N2020038) LL(113) DFO(6309013-01)*

#### 10-APR-2020

Add marine farm

(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA376316

LNLM/D. 31-AUG-2018

47°38'36.1"N 055°08'56.1"W

*DFO(6308949-01)*

#### 31-AUG-2018

Add marine farm

(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA376316

LNLM/D. 14-JUL-2017

47°39'30.7"N 055°22'06.6"W

*DFO(6308406-01)*

#### 31-AUG-2018

Add marine farm

(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA376316

LNLM/D. 14-JUL-2017

47°39'52.0"N 055°22'31.0"W

*DFO(6308406-02)*

#### 14-JUL-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA376233

LNLM/D. 14-APR-2017

47°31'25.7"N 055°20'26.4"W

*DFO(6307974-03)*

#### 14-JUL-2017

LNLM/D. 14-APR-2017



### Chart no. 4831

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

47°38'22.9"N 055°17'49.6"W  
*DFO(6307974-04)*

#### 14-JUL-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376233

LNM/D. 14-APR-2017  
47°26'03.4"N 055°29'27.3"W  
*DFO(6307974-06)*

#### 14-JUL-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274,  
CA376316

LNM/D. 14-APR-2017  
47°38'08.1"N 055°23'11.7"W  
*DFO(6307974-07)*

#### 14-JUL-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNM/D. 14-APR-2017  
47°34'47.3"N 055°10'05.0"W  
*DFO(6307974-08)*

#### 14-JUL-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNM/D. 14-APR-2017  
47°28'43.2"N 055°09'57.1"W  
*DFO(6307974-09)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNM/D. 05-FEB-2016  
47°42'17.0"N 055°23'02.7"W  
*DFO(6307848-01)*

#### 14-APR-2017

LNM/D. 05-FEB-2016



### Chart no. 4831

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

47°38'08.1"N 055°23'11.7"W  
*DFO(6307848-02)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNМ/D. 05-FEB-2016  
47°37'59.1"N 055°26'25.1"W  
*DFO(6307848-03)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNМ/D. 05-FEB-2016  
47°38'22.9"N 055°17'49.6"W  
*DFO(6307848-04)*

#### 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

LNМ/D. 05-FEB-2016  
47°37'57.0"N 055°16'39.0"W  
*DFO(6307848-06)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNМ/D. 05-FEB-2016  
47°34'47.3"N 055°10'05.0"W  
*DFO(6307848-07)*

#### 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376233

LNМ/D. 05-FEB-2016  
47°33'29.4"N 055°19'44.4"W  
*DFO(6307848-08)*

#### 14-APR-2017

LNМ/D. 05-FEB-2016



### Chart no. 4831

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 50 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376233

47°33'26.0"N 055°19'54.0"W  
*DFO(6307848-09)*

#### 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 10 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274,  
CA376316

LNМ/D. 05-FEB-2016  
47°32'57.0"N 055°16'39.0"W  
*DFO(6307848-10)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376233

LNМ/D. 05-FEB-2016  
47°31'25.7"N 055°20'26.4"W  
*DFO(6307848-11)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNМ/D. 05-FEB-2016  
47°28'43.2"N 055°09'57.1"W  
*DFO(6307848-12)*

#### 14-APR-2017

Add subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 8 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376233

LNМ/D. 05-FEB-2016  
47°26'03.4"N 055°29'27.3"W  
*DFO(6307848-13)*

#### 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 50 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNМ/D. 05-FEB-2016  
47°38'09.6"N 055°16'51.6"W  
*DFO(6307848-16)*

#### 05-FEB-2016

LNМ/D. 07-AUG-2015



### Chart no. 4831

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

47°32'57.0"N 055°16'39.0"W  
*DFO(6307401-01)*

#### 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres.  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

LNМ/D. 20-MAR-2015  
47°37'57.0"N 055°16'39.0"W  
*DFO(6307179-01)*

#### 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres.  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376316

LNМ/D. 20-MAR-2015  
47°38'09.6"N 055°16'51.6"W  
*DFO(6307179-02)*

#### 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres.  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA276274, CA376233

LNМ/D. 20-MAR-2015  
47°33'29.4"N 055°19'44.4"W  
*DFO(6307179-03)*

#### 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres.  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376233

LNМ/D. 20-MAR-2015  
47°33'26.4"N 055°19'55.8"W  
*DFO(6307179-04)*

#### 20-MAR-2015

Delete light Fl6s50m  
(See Chart No. 1, P1)  
This notice affects Electronic Navigational Chart: CA276274, CA376316

LNМ/D. 10-JAN-2014  
47°34'42.0"N 055°07'05.0"W  
*(N2015008) LL(115) DFO(6307061-01)*

#### 10-JAN-2014

LNМ/D. 20-DEC-2013



### Chart no. 4831

Add yellow and black South cardinal lighted spar buoy 47°38'08.1"N 055°12'46.0"W  
VQ(6)+ LF110s, marked VRE  
(See Chart No. 1, Q130.3) (N2013029) LL(115.8) DFO(6306564-01)

**20-DEC-2013** LNM/D. 29-MAR-2013  
Delete red starboard hand lighted spar buoy F1R, marked 47°36'18.0"N 055°06'35.4"W  
VV2  
(See Chart No. 1, Qf) (N2013016) LL(115.2) DFO(6306542-01)

**29-MAR-2013** LNM/D. 29-OCT-2010  
Add marine farm 47°33'18.0"N 055°23'28.4"W  
(See Chart No. 1, K48.2) DFO(6306337-01)

**29-OCT-2010** LNM/D. 23-JUL-2010  
Add wharf between 47°31'36.5"N 055°24'33.9"W  
(See Chart No. 1 F13) and 47°31'34.8"N 055°24'33.6"W  
DFO(6305015-01)

**29-OCT-2010** LNM/D. 23-JUL-2010  
Add wharf between 47°31'36.5"N 055°24'33.9"W  
(See Chart No. 1 F13) and 47°31'35.6"N 055°24'31.3"W  
DFO(6305015-02)

**29-OCT-2010** LNM/D. 23-JUL-2010  
Add light Fl G 47°31'34.8"N 055°24'33.6"W  
(See Chart No. 1 P1) (N2010043) LL(116.9) DFO(6305015-03)

**23-JUL-2010** LNM/D. 18-JUN-2010  
Delete light FR 47°40'48.0"N 055°25'48.0"W  
(See Chart 1 P16) (N2010033) LL(116.3) DFO(6304906-01)

**23-JUL-2010** LNM/D. 18-JUN-2010



**Chart no. 4831**

Add extension to wharf between 47°40'48.0"N 055°25'48.0"W  
(See Chart 1 F14) and 47°40'49.6"N 055°25'46.2"W

*DFO(6304906-02)*

**23-JUL-2010**

LNM/D. 18-JUN-2010

Add light FIR 47°40'49.6"N 055°25'46.2"W  
(See Chart 1 P16)

*(N2010033) LL(116.3) DFO(6304906-03)*

**18-JUN-2010**

LNM/D. 02-JAN-2009

Add light FIR 4s 47°38'08.4"N 055°12'41.5"W  
(See Chart 1 P16)

*LL(115.9) DFO(6304801-01)*

**02-JAN-2009**

LNM/D. 19-SEP-2008

Add yellow and black South cardinal lighted pillar buoy  
VQ(6)+LFl 10s, marked VL  
(See Chart No 1 Qm)

47°34'37.0"N 055°09'29.0"W

*(N2008045) LL(114.9) DFO(6304169-01)*

**19-SEP-2008**

LNM/D. 29-AUG-2008

Add black and yellow North cardinal lighted pillar buoy Q,  
marked VB  
(See Chart No 1 Q130.3)

47°35'52.7"N 055°19'41.9"W

*(N2008027) LL(116.6) DFO(6304018-01)*

**29-AUG-2008**

LNM/D. 02-NOV-2007

Add dangerous underwater rock of 2 metres or less, reported 2008 47°35'48.0"N 054°59'00.3"W  
(See Chart No 1 K13, I3.2)

*DFO(6303999-01)*

**02-NOV-2007**

LNM/D. 11-AUG-2006

Add green port hand lighted spar buoy FlG, marked VJF1

47°31'48.0"N 054°55'30.0"W

*(N2007051) LL(113.6) DFO(6303641-01)*

**11-AUG-2006**

LNM/D. 26-MAY-2006





**Chart no. 4831**

Add red starboard hand lighted spar buoy FIR, marked  
VM2

47°35'06.5"N 054°53'05.1"W

*(N2006018) LL(113.08) DFO(6302897-01)*

**26-MAY-2006**

LNM/D. 07-OCT-2005

Add light FIR

47°32'51.0"N 054°52'52.0"W

*(N1998117) LL(113.2) DFO(6300722-01)*

**07-OCT-2005**

LNM/D. 16-APR-2004

Add breakwater between 47°27'05.0"N 055°33'34.0"W  
and 47°27'05.2"N 055°33'28.2"W

*DFO(6302416-01)*

**07-OCT-2005**

LNM/D. 16-APR-2004

Reposition light FlG

from 47°27'06.5"N 055°33'30.8"W  
to 47°27'05.2"N 055°33'28.2"W

*(N2005039) LL(119.5) DFO(6302416-02)*

**16-APR-2004**

LNM/D. 26-DEC-2003

Amend Fl to read Fl R 4s 14m 5M against light

47°27'18.0"N 055°29'33.0"W

*(N2002103) LL(119) DFO(6300521-01)*

**26-DEC-2003**

LNM/D. 11-APR-2003

Amend Fl R 3s 17m to read Fl 3s 17m 47°24'13.8"N 055°35'02.5"W

*LL(120) DFO(6300972-01)*

**11-APR-2003**

LNM/D. 15-MAR-2002

Delete green, port hand can buoy, marked VE1 47°27'29.0"N 055°29'44.0"W

*(N2000260) DFO(6829120-01)*

**11-APR-2003**

LNM/D. 15-MAR-2002



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4831

Add green port hand spar light buoy FIG, marked VE1 47°27'29.0"N 055°29'41.7"W

*(N2000260) LL(116.410) DFO(6829120-02)*

#### 11-APR-2003

LNM/D. 15-MAR-2002

Replace red, starboard hand spar buoy, marked VV2 with  
red starboard hand spar light buoy FIR, marked  
VV2

47°36'18.0"N 055°06'35.4"W

*(N2001130) LL(115.2) DFO(6829755-01)*

#### 11-APR-2003

LNM/D. 15-MAR-2002

Replace green, port hand spar buoy, marked VS1, with  
green port hand spar light buoy FIG, marked VS1

47°31'47.8"N 054°57'09.2"W

*(N2001131) LL(113.4) DFO(6829756-01)*

#### 15-MAR-2002

LNM/D. 25-JAN-2002

Add non-dangerous wreck 47°34'56.4"N 054°56'14.4"W

*(N2002001) DFO(6300102-01)*

#### 25-JAN-2002

LNM/D. 07-DEC-2001

Amend FI R 6s 14m to read FI

47°27'18.0"N 055°29'33.0"W

*(N2000037) LL(119) DFO(6828798-01)*

#### 25-JAN-2002

LNM/D. 07-DEC-2001

Add light FIG

47°27'06.5"N 055°33'30.8"W

*(N2000246) LL(119.5) DFO(6829093-01)*

#### 25-JAN-2002

LNM/D. 07-DEC-2001

Delete anchorage symbol 47°28'36.0"N 055°28'18.0"W

*DFO(6829829-01)*

#### 07-DEC-2001

LNM/D. 11-MAY-2001



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4831

Replace green port hand spar buoy, marked VD5, with green light, port hand spar buoy FIG, marked VD5

47°35'47.8"N 055°25'00.0"W

(N2000261) LL(116.4) DFO(6829121-01)

#### 07-DEC-2001

LN/D. 11-MAY-2001

Add submerged wreck 47°31'41.5"N 054°58'02.3"W

(N2001146) DFO(6829827-01)

#### 11-MAY-2001

LN/D. 12-MAR-1999

Delete green, red, green port bifurcation pillar light buoy, FL (2+1) G, marked VBL

47°29'13.0"N 055°22'43.0"W

(N2000-213) LL(117.5) DFO(6829032-01)

#### 11-MAY-2001

LN/D. 12-MAR-1999

Delete red and white fairway pillar, light buoy Mo (A), marked VSJ

47°27'36.0"N 055°26'00.0"W

(N2000-214) LL(118.5) DFO(6829033-01)