



### Chart no. 4849

#### 4849 - Bonavista Harbour - New Chart - 30-DEC-1988 - NAD 1983

**11-JAN-2019**

LNM/D. 29-JUN-2018

Affix patch

48°38'56.0"N 053°06'48.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576310

*DFO(6308542-01)*

**29-JUN-2018**

LNM/D. 12-MAY-2017

Affix patch

48°39'00.0"N 053°07'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576310

*DFO(6308316-01)*

**24-MAR-2017**

LNM/D. 28-OCT-2016

Delete light Fl

48°39'06.1"N 053°07'42.6"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (N2016083P) LL(446) DFO(6307807-01)  
CA376340, CA576310

**24-JUL-2015**

LNM/D. 27-MAR-2015

Affix patch

48°39'00.0"N 053°06'50.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576310

*DFO(6307176-01)*

**10-FEB-2012**

LNM/D. 04-JUN-2010

Delete green port hand lighted spar buoy FlG, marked JB7 48°39'00.1"N 053°07'54.8"W  
(See Chart No. 1, Qg)

*LL(445.4) DFO(6305912-01)*

**10-FEB-2012**

LNM/D. 04-JUN-2010

Add green port hand lighted spar buoy FlG, marked JB7 48°39'00.1"N 053°07'11.6"W  
(See Chart No. 1, Qg)

*LL(445.4) DFO(6305912-02)*

**03-OCT-2008**

LNM/D. 28-DEC-2007

Delete green port hand lighted spar buoy FlG, marked  
JB3

48°39'02.5"N 053°07'54.8"W

(See Chart No 1 Qg)

*(N2008008) LL(445.2) DFO(6303961-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4849

**03-OCT-2008**

LNM/D. 28-DEC-2007

Add green port hand lighted pillar buoy FlG, marked JB5

48°39'02.5"N 053°07'54.8"W

*(N2008007) LL(446.1) DFO(6303961-02)*

**19-OCT-2007**

LNM/D. 01-JUN-2007

Add breakwater extension and legend Breakwater/Brise-lames joining  
(See Chart No 1 Section F 4.3.)

48°38'57.5"N 053°07'06.0"W

48°38'58.2"N 053°07'06.3"W

48°38'58.3"N 053°07'05.8"W

and 48°38'57.7"N 053°07'05.6"W

*DFO(6303605-01)*

**19-OCT-2007**

LNM/D. 01-JUN-2007

Delete light QR

48°38'57.5"N 053°07'06.0"W

(See Chart No 1 Section P 16.)

*(N2005105) LL(447) DFO(6303605-02)*

**19-OCT-2007**

LNM/D. 01-JUN-2007

Add light QR

48°38'58.1"N 053°07'06.2"W

(See Chart No 1 Section P 16.)

*(N2005105) LL(447) DFO(6303605-03)*

**19-OCT-2007**

LNM/D. 01-JUN-2007

Delete depth of 4 metres, 6 decimetres

(See Chart No 1 Section I 10.)

*DFO(6303605-04)*

**01-JUN-2007**

LNM/D. 01-SEP-2006

Delete light QR

48°38'57.2"N 053°07'04.5"W

*(N2005105) LL(447) DFO(6302708-01)*

**01-JUN-2007**

LNM/D. 01-SEP-2006

Add light QR

48°38'57.5"N 053°07'06.0"W

*(N2005105) LL(447) DFO(6302708-02)*

**01-SEP-2006**

LNM/D. 11-AUG-2006



### Chart no. 4849

Delete red starboard hand lighted spar buoy FLR, marked JB8 48°38'55.5"N 053°06'56.7"W  
*(N2006093) LL(447.2) DFO(6303002-01)*

**01-SEP-2006** LNM/D. 11-AUG-2006  
Add green port hand lighted spar buoy FIG, marked JB7 48°39'00.1"N 053°07'54.8"W  
*(N2006102) LL(445.4) DFO(6303013-01)*

**01-SEP-2006** LNM/D. 11-AUG-2006  
Add green port hand lighted spar buoy FIG, marked JB3 48°39'02.5"N 053°07'54.8"W  
*(N2006103) LL(445.2) DFO(6303014-01)*

**01-SEP-2006** LNM/D. 11-AUG-2006  
Reposition red starboard hand lighted spar buoy FLR, marked JB6 from 48°38'56.0"N 053°06'59.5"W  
to 48°38'55.9"N 053°06'58.2"W  
*(N2006105) LL(447.1) DFO(6303017-01)*

**03-JUN-2005** LNM/D. 28-JAN-2005  
Add floating dock between 48°39'01.0"N 053°06'53.8"W  
and 48°38'59.7"N 053°06'53.2"W  
*(N2000371) LL(448.1) DFO(6829260-01)*

**03-JUN-2005** LNM/D. 28-JAN-2005  
Add light FIG 48°38'59.7"N 053°06'53.2"W  
*(N2000371) LL(448.1) DFO(6829260-02)*

**10-OCT-2003** LNM/D. 20-JUN-2003  
Delete red and white fairway pillar, light and whistle buoy Mo (A), WHIS, marked JB 48°38'49.8"N 053°08'33.5"W  
*(N2002060) LL(445) DFO(6300418-01)*

**25-JAN-2002** LNM/D. 30-MAR-2001



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4849

Amend FG to read FIG 48°39'00.8"N 053°06'50.5"W

*(N2000062) LL(448) DFO(6828822-01)*

#### 25-JAN-2002

LNМ/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked JB6, with  
red light, starboard hand spar buoy FIR, marked  
JB6

48°38'56.0"N 053°06'59.5"W

*(N2000271) LL(447.1) DFO(6829131-01)*

#### 25-JAN-2002

LNМ/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked JB8, with  
red light, starboard hand spar buoy FIR, marked  
JB8

48°38'55.5"N 053°06'56.7"W

*(N2000272) LL(447.2) DFO(6829132-01)*

### 4849 - Catalina and / et Port Union - New Chart - 30-DEC-1988 - NAD 1983

#### 24-DEC-2021

LNМ/D. 26-APR-2019

Delete light FIR

48°30'40.3"N 053°04'03.5"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:  
CA576394

*(N2021229) LL(458) DFO(6309876-01)*

#### 04-JUN-2010

LNМ/D. 08-MAY-2009

Reposition red starboard hand lighted pillar buoy FIR,  
marked TC2  
(See Chart No 1 Qf)

from 48°30'13.7"N 053°01'26.6"W  
to 48°30'12.9"N 053°01'26.5"W

*(N2010016) LL(452) DFO(6304837-01)*

#### 19-DEC-2003

LNМ/D. 10-OCT-2003

Amend Fl (3) 12s 28m 18M to read Fl 4s 28m 16M against  
light

48°30'14.8"N 053°02'37.4"W

*(N2003039) LL(453) DFO(6301008-01)*

#### 20-JUN-2003

LNМ/D. 13-JUN-2003



### Chart no. 4849

Replace red starboard hand pillar light buoy FIR, WHIS,  
marked TC2 with red starboard hand pillar light  
buoy FIR, marked TC2

48°30'14.0"N 053°01'26.3"W

(N2002049) LL(452) DFO(6300408-01)

#### 25-JAN-2002

LNМ/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked TC6 with  
red light, starboard hand spar buoy FIR, marked  
TC6

48°30'41.0"N 053°04'16.4"W

(N2000273) LL(458.81) DFO(6829133-01)

### 4849 - Catalina Harbour - New Chart - 30-DEC-1988 - NAD 1983

#### 24-DEC-2021

LNМ/D. 26-APR-2019

Delete light Fl R

48°30'40.2"N 053°04'03.1"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:  
CA576394

(N2021229) LL(458) DFO(6309876-01)

#### 26-APR-2019

LNМ/D. 11-JAN-2019

Affix patch

48°31'00.0"N 053°04'30.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576394

DFO(6308617-01)

#### 27-MAR-2015

LNМ/D. 10-FEB-2012

Amend FlG to read QG against green port hand pillar light  
buoy, marked TC11  
(See Chart No. 1, Qg)

48°30'51.1"N 053°04'18.1"W

(N2015011) LL(460) DFO(6307070-01)

This notice affects Electronic Navigational Chart:  
CA576395

#### 11-AUG-2006

LNМ/D. 26-MAY-2006

Amend "FR" to read "FIR" against light

48°30'55.3"N 053°04'30.1"W

(N2006020) LL(461) DFO(6302910-01)

#### 28-JAN-2005

LNМ/D. 19-DEC-2003



**Chart no. 4849**

Delete light FR 48°30'54.8"N 053°04'32.5"W

*(N2004200) LL(461) DFO(6302129-01)*

**28-JAN-2005**

LNM/D. 19-DEC-2003

Delete depth of 4 metres, 9 decimetres 48°30'54.8"N 053°04'32.1"W

*DFO(6302129-02)*

**28-JAN-2005**

LNM/D. 19-DEC-2003

Add wharf extension joining 48°30'54.7"N 053°04'32.5"W  
(See Chart No 1 F14) 48°30'55.2"N 053°04'30.0"W  
48°30'55.4"N 053°04'30.1"W  
and 48°30'55.0"N 053°04'32.6"W

*DFO(6302129-03)*

**28-JAN-2005**

LNM/D. 19-DEC-2003

Add light FR 48°30'55.3"N 053°04'30.1"W

*(N2004200) LL(461) DFO(6302129-04)*

**28-JAN-2005**

LNM/D. 19-DEC-2003

Add depth of 3 metres, 7 decimetres 48°30'55.2"N 053°04'32.3"W

*DFO(6302129-05)*

**28-JAN-2005**

LNM/D. 19-DEC-2003

Add depth of 3 metres, 9 decimetres 48°30'55.3"N 053°04'30.0"W

*DFO(6302129-06)*

**28-JAN-2005**

LNM/D. 19-DEC-2003

Add depth of 4 metres, 2 decimetres 48°30'54.8"N 053°04'31.1"W

*DFO(6302129-07)*

**07-JUN-2002**

LNM/D. 25-JAN-2002



### Chart no. 4849

Replace red, starboard hand spar buoy, marked TC10  
with red starboard hand spar light buoy FIR,  
marked TC10

48°30'51.0"N 053°04'14.8"W

(N2001012) LL(459.1) DFO(6300280-01)

#### 25-JAN-2002

LNM/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked TC6 with  
red light, starboard hand spar buoy FIR, marked  
TC6

48°30'41.0"N 053°04'16.4"W

(N2000273) LL(458.81) DFO(6829133-01)

### 4849 - Fish Plant / Conserverie de poisson - New Chart - 30-DEC-1988 - NAD 1983

#### 09-SEP-2022

LNM/D. 24-DEC-2021

Add depth of 1 metre

47°41'21.9"N 053°13'16.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-01)

#### 09-SEP-2022

LNM/D. 24-DEC-2021

Add depth of 1.6 metres

47°41'27.1"N 053°13'03.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-02)

#### 09-SEP-2022

LNM/D. 24-DEC-2021

Add depth of 0.6 metres

47°41'27.1"N 053°13'01.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-03)

#### 09-SEP-2022

LNM/D. 24-DEC-2021

Delete depth of 1.4 metres

47°41'26.8"N 053°13'00.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-04)

#### 09-SEP-2022

LNM/D. 24-DEC-2021

Add depth of 1 metre

47°41'26.9"N 053°13'00.4"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-05)



### Chart no. 4849

**09-SEP-2022**

LNМ/D. 24-DEC-2021

Add depth of 5.5 metres

47°41'21.8"N 053°13'16.1"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

*DFO(6310229-06)*

**09-SEP-2022**

LNМ/D. 24-DEC-2021

Delete depth of 5.8 metres

47°41'21.7"N 053°13'16.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

*DFO(6310229-07)*

**09-SEP-2022**

LNМ/D. 24-DEC-2021

Add depth of 5.9 metres

47°41'22.3"N 053°13'12.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

*DFO(6310229-08)*

**09-SEP-2022**

LNМ/D. 24-DEC-2021

Add depth of 3.6 metres

47°41'26.0"N 053°13'04.2"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

*DFO(6310229-09)*

**09-SEP-2022**

LNМ/D. 24-DEC-2021

Delete depth of 4.2 metres

47°41'25.8"N 053°13'03.9"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

*DFO(6310229-10)*

**09-SEP-2022**

LNМ/D. 24-DEC-2021

Add depth of 1.2 metres

47°41'27.6"N 053°13'01.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

*DFO(6310229-11)*

**09-SEP-2022**

LNМ/D. 24-DEC-2021

Delete depth of 1.2 metres

47°41'27.3"N 053°13'01.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

*DFO(6310229-12)*

**13-JUN-2003**

LNМ/D. 23-MAY-2003





**Chart no. 4849**

Affix patch 47°42'30.0"N 053°18'30.0"W

*DFO(6500109-01)*

[PDF](#)

**30-MAR-2001**

LNМ/D. 01-OCT-1999

(T)Delete light

47°41'24.6"N 053°12'52.8"W

The original light has been temporarily dismantled to facilitate new construction. (N2001-009(T)) LL(481.000) DFO(6829425-01)  
A temporary light has been installed.  
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.  
Cancelled on 22-AUG-03

**30-MAR-2001**

LNМ/D. 01-OCT-1999

(T)Add light, Fl R

47°41'24.4"N 053°12'52.8"W

The original light has been temporarily dismantled to facilitate new construction. A temporary light has been installed. (N2001-009(T)) DFO(6829425-02)  
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.  
Cancelled on 18-JUL-03

**4849 - Harbour Grace and / et Carbonear - New Chart - 30-DEC-1988 - NAD 1983**

**12-MAY-2017**

LNМ/D. 24-MAR-2017

Add breakwater with legend Bkw

joining 47°44'17.7"N 053°13'22.1"W

(See Chart No. 1, F4.1)

47°44'14.5"N 053°13'22.2"W

This notice affects Electronic Navigational Chart:

and 47°44'13.0"N 053°13'23.6"W

CA376120, CA476405

*DFO(6307708-01)*

**12-MAY-2017**

LNМ/D. 24-MAR-2017

Add light FlR

47°44'13.0"N 053°13'23.6"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (N2016054) LL(477.5) DFO(6307708-02)

CA376120, CA476405



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4849

**28-OCT-2016**

Amend Fl R to read Fl Y against light  
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:  
CA376120, CA476405, CA576416

LNМ/D. 24-JUL-2015

47°44'14.5"N 053°13'26.4"W

(N2016053) LL(478) DFO(6307707-01)

**26-MAY-2006**

Delete depth of 7 metres 47°40'40.5"N 053°14'40.0"W

LNМ/D. 03-JUN-2005

*DFO(6302811-01)*

**26-MAY-2006**

Add depth of 0 metres, 2 decimetres, with a bottom quality of Bo 47°40'41.4"N 053°14'40.1"W

LNМ/D. 03-JUN-2005

*DFO(6302811-02)*

**13-JUN-2003**

Affix patch 47°41'18.0"N 063°13'00.0"W

LNМ/D. 23-MAY-2003

*DFO(6500109-02)*

[PDF](#)

**23-MAY-2003**

Delete red and white fairway pillar light buoy Mo(A), WHIS,  
marked CC

LNМ/D. 26-JUL-2002

47°45'00.0"N 053°09'25.5"W

(N2002048) LL(476) DFO(6300407-01)

**26-JUL-2002**

Delete light FR

LNМ/D. 07-JUN-2002

47°40'52.3"N 053°14'22.2"W

(N2002004) LL(482.000) DFO(6300091-01)

**30-MAR-2001**

LNМ/D. 01-OCT-1999



### Chart no. 4849

(T)Delete light

47°41'24.6"N 053°12'52.8"W

The original light has been temporarily dismantled to facilitate new construction. (N2001-009(T)) LL(481.000) DFO(6829425-01)

A temporary light has been installed.

Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.

Cancelled on 22-AUG-03

**30-MAR-2001**

LNМ/D. 01-OCT-1999

(T)Add light, Fl R

47°41'24.4"N 053°12'52.8"W

The original light has been temporarily dismantled to facilitate new construction. A temporary light has been installed. (N2001-009(T)) DFO(6829425-02)

Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.

Cancelled on 18-JUL-03

### 4849 - Port Union - New Chart - 30-DEC-1988 - NAD 1983

**28-JAN-2005**

LNМ/D. 19-DEC-2003

Delete yellow cautionary can buoy, marked Priv 48°30'10.0"N 053°04'36.8"W

*DFO(6302206-01)*

**28-JAN-2005**

LNМ/D. 19-DEC-2003

Delete yellow cautionary can buoy, marked Priv 48°30'11.3"N 053°04'44.0"W

*DFO(6302206-02)*

### 4849 - Public Wharf / Quai - New Chart - 30-DEC-1988 - NAD 1983

**26-MAY-2023**

LNМ/D. 09-SEP-2022

Delete depth of 1.2 metres

47°44'17.2"N 053°13'26.2"W

(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA576416

*DFO(6310662-01)*



### Chart no. 4849

**26-MAY-2023**

LNМ/D. 09-SEP-2022

Add depth of 0.5 metres  
(See Chart 1, I10)

47°44'17.3"N 053°13'26.0"W

This notice affects Electronic Navigational Chart: CA576416

*DFO(6310662-02)*

**26-MAY-2023**

LNМ/D. 09-SEP-2022

Add depth of 1.7 metres  
(See Chart 1, I10)

47°44'17.0"N 053°13'26.4"W

This notice affects Electronic Navigational Chart: CA576416

*DFO(6310662-03)*

**12-MAY-2017**

LNМ/D. 24-MAR-2017

Affix patch

47°44'16.0"N 053°13'25.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576416

*DFO(6307708-03)*

**28-OCT-2016**

LNМ/D. 24-JUL-2015

Amend Fl R to read Fl Y against light  
(See Chart No. 1, P16)

47°44'14.5"N 053°13'26.4"W

This notice affects Electronic Navigational Chart: (N2016053) LL(478) DFO(6307707-01)  
CA376120, CA476405, CA576416

### 4849 - The Admiral's Marina - New Chart - 30-DEC-1988 - NAD 1983

**29-JUN-2018**

LNМ/D. 12-MAY-2017

Affix patch

47°40'24.0"N 053°14'24.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576731

*DFO(6308316-02)*

**08-MAY-2009**

LNМ/D. 03-OCT-2008

Delete light FlR  
(See Chart No 1 P1)

47°40'23.2"N 053°14'22.8"W

*(N2009004) LL(482.71) DFO(6304340-01)*

**08-MAY-2009**

LNМ/D. 03-OCT-2008

Add light FlR  
(See Chart No 1 P1)

47°40'23.3"N 053°14'23.0"W

*(N2009004) LL(482.71) DFO(6304340-02)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4849

**08-MAY-2009**

LNМ/D. 03-OCT-2008

Delete coastline between 47°40'22.3"N 053°14'25.2"W  
(See Chart No. 1, C1) and 47°40'23.3"N 053°14'22.5"W

*DFO(6304340-03)*

**08-MAY-2009**

LNМ/D. 03-OCT-2008

Add wharf extension joining 47°40'22.3"N 053°14'25.2"W  
(See Chart No 1 F13) 47°40'23.3"N 053°14'22.9"W  
and 47°40'23.2"N 053°14'22.8"W

*DFO(6304340-04)*

**08-MAY-2009**

LNМ/D. 03-OCT-2008

Add coastline between 47°40'23.2"N 053°14'22.8"W  
(See Chart No. 1 C1) and 47°40'23.3"N 053°14'22.5"W

*DFO(6304340-05)*

**08-MAY-2009**

LNМ/D. 03-OCT-2008

Delete depth of 0 metres, 8 decimetres 47°40'22.5"N 053°14'23.9"W  
(See Chart No 1 I10)

*DFO(6304340-06)*

**28-DEC-2007**

LNМ/D. 19-OCT-2007

Affix patch 47°40'24.0"N 053°14'27.0"W

*(N2006117) LL(482.789) DFO(6303760-01)*

[PDF](#)