



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4850

### 4850 - Cape St Francis to / à Baccalieu Island and / et Heart's Content - New Chart - 11-MAY-1990 - NAD 1983

**14-JUL-2017**

Delete legend Fog Sig 30s against light  
(See Chart No. 1, R20)

LNLM/D. 16-DEC-2016

47°48'32.0"N 052°47'12.0"W

(N2017008) LL(499) DFO(6307942-01)

This notice affects Electronic Navigational Chart:  
CA176030, CA276101, CA376015

**16-DEC-2016**

Add green port hand lighted spar buoy Fl G marked CV3  
(See Chart No. 1, Qg)

LNLM/D. 07-OCT-2016

48°05'03.3"N 052°54'06.6"W

(N2016039) LL(474.1) DFO(6307695-03)

This notice affects Electronic Navigational Chart:  
CA376146

**07-OCT-2016**

Reposition red starboard hand lighted pillar buoy Fl R,  
marked CV2.

LNLM/D. 21-NOV-2014

from 48°04'56.8"N 052°54'09.1"W  
to 48°05'01.5"N 052°54'04.9"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational  
Chart: CA376146

(N2016055) LL(474.0) DFO(6307687-01)

**07-OCT-2016**

Replace red starboard hand pillar light buoy Fl R, marked  
CV2, with red starboard hand spar light buoy Fl  
R, marked CV2

LNLM/D. 21-NOV-2014

48°05'01.5"N 052°54'04.9"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:  
CA376146

(N2016055) LL(474.0) DFO(6307687-02)

**21-NOV-2014**

Amend BULL ARM to read ST. JOHN'S against the note 'ST. JOHN'S  
VESSEL TRAFFIC SERVICES / SERVICES DE TRAFIC  
MARITIME DE BULL ARM'

LNLM/D. 12-SEP-2014

48°07'43.8"N 052°55'54.8"W

DFO(6306966-01)

**12-SEP-2014**

Add radio reporting line  
(See Chart No. 1, M40.2)

LNLM/D. 06-DEC-2013

between 48°05'40.8"N 053°32'43.2"W  
and 47°59'24.4"N 053°19'03.7"W

This notice affects Electronic Navigational Chart:  
CA276092, CA376146

DFO(6306732-03)



## Chart no. 4850

**12-SEP-2014**

LNM/D. 06-DEC-2013

Add mandatory calling-in point "2" with arrowhead pointing 028° and 208°

(See Chart No. 1, M40.1)

*DFO(6306732-04)*

This notice affects Electronic Navigational Chart: CA276092

**12-SEP-2014**

LNM/D. 06-DEC-2013

Add radio reporting line

(See Chart No. 1, M40.2)

between 48°12'04.0"N 053°06'12.6"W

and 48°05'27.2"N 053°01'37.4"W

This notice affects Electronic Navigational Chart:  
CA276092, CA376146, CA376243, CA576147

*DFO(6306732-05)*

**12-SEP-2014**

LNM/D. 06-DEC-2013

Add mandatory calling-in point "1" with arrowhead pointing 057° and 237°

(See Chart No. 1, M40.1)

*DFO(6306732-07)*

This notice affects Electronic Navigational Chart: CA376146,  
CA576147

**12-SEP-2014**

LNM/D. 06-DEC-2013

Affix patch 47°50'00.0"N 053°10'12.0"W

[PDF](#)

*DFO(6306732-14)*

**12-SEP-2014**

LNM/D. 06-DEC-2013

Affix patch

48°07'00.0"N 052°55'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA376146

*DFO(6306732-15)*

**12-SEP-2014**

LNM/D. 06-DEC-2013

Add See / Voir note

48°03'44.3"N 053°27'33.1"W

VTS ZONES / ZONES STM

*DFO(6306732-16)*

**04-FEB-2011**

LNM/D. 18-JUN-2010

Delete depth of 1 metre, 5 decimetres 47°54'46.2"N 053°03'54.7"W

(See Chart No. 1, I10)

*DFO(6304690-01)*



**Chart no. 4850**

**04-FEB-2011**

LNМ/D. 18-JUN-2010

Delete light FLG

47°54'46.4"N 053°03'56.8"W

(See Chart No. 1, P1)

(N2009056) LL(475.1) DFO(6304690-02)

**04-FEB-2011**

LNМ/D. 18-JUN-2010

Add breakwater

joining 47°54'44.1"N 053°03'52.5"W

(See Chart No 1 F4.1)

47°54'46.1"N 053°03'56.6"W

and 47°54'46.3"N 053°04'00.1"W

DFO(6304690-03)

**04-FEB-2011**

LNМ/D. 18-JUN-2010

Add light FLG

47°54'46.3"N 053°04'00.1"W

(See Chart No 1 P1)

(N2009056) LL(475.1) DFO(6304690-04)

**18-JUN-2010**

LNМ/D. 12-FEB-2010

Add extension to breakwater between 48°01'11.0"N 053°15'36.0"W

(See Chart No 1 F4.2)

and 48°01'09.4"N 053°15'34.4"W

DFO(6304763-01)

**18-JUN-2010**

LNМ/D. 12-FEB-2010

Reposition light FIR

from 48°01'11.0"N 053°15'36.0"W

(See Chart 1 P1)

to 48°01'09.4"N 053°15'34.4"W

(N2010011) LL(470.1) DFO(6304763-02)

**12-FEB-2010**

LNМ/D. 01-JAN-2010

Amend FIR 3s 38m 5M to read Fl 3s 38m 5M against light

48°05'41.1"N 053°32'43.1"W

(See Chart No 1 P16)

(N2009053) LL(465) DFO(6304674-01)

**01-JAN-2010**

LNМ/D. 09-OCT-2009

Add red starboard hand lighted spar buoy FIR, marked

48°02'40.8"N 053°06'13.5"W

TSC2

(See Chart No 1 Qf)

(N2009028) LL(470.2) DFO(6304569-01)



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4850

### 09-OCT-2009

Add green port hand lighted spar buoy FlG, marked TSC1  
(See Chart No 1 Qg)

LNМ/D. 21-AUG-2009

48°02'42.2"N 053°06'11.4"W

*(N2009025) LL(470.3) DFO(6304567-01)*

### 21-AUG-2009

Add note:  
DIAGRAM / DIAGRAMME  
See Sailing Directions  
Voir Instructions nautiques

LNМ/D. 19-SEP-2008

48°05'42.0"N 052°54'18.1"W

*DFO(6304524-01)*

### 19-SEP-2008

Delete green port hand lighted spar buoy FlG, marked  
TSC1  
(See Chart No 1 Qg)

LNМ/D. 24-AUG-2007

48°02'42.3"N 053°06'11.3"W

*(N2008021) LL(470.3) DFO(6304006-01)*

### 19-SEP-2008

Delete red starboard hand lighted spar buoy FlR, marked  
TSC2  
(See Chart No 1 Qf)

LNМ/D. 24-AUG-2007

48°02'40.8"N 053°06'13.5"W

*(N2008022) LL(470.2) DFO(6304010-01)*

### 15-SEP-2006

Add red starboard hand lighted spar buoy FlR, marked  
TSC2

LNМ/D. 26-MAY-2006

48°02'40.8"N 053°06'13.5"W

*(N2006098) LL(470.2) DFO(6303007-01)*

### 15-SEP-2006

Add green port hand lighted spar buoy FlG, marked TSC1

LNМ/D. 26-MAY-2006

48°02'42.3"N 053°06'11.3"W

*(N2006099) LL(470.3) DFO(6303008-01)*

### 10-MAR-2006

Add breakwater extension with legend 'Bkw' between 48°04'58.5"N 052°54'01.0"W  
and 48°05'00.7"N 052°54'02.8"W

LNМ/D. 30-DEC-2005

*DFO(6302759-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4850

**10-MAR-2006** LNM/D. 30-DEC-2005

Add light Fl R 48°05'00.7"N 052°54'02.8"W

*LL(474.4) DFO(6302759-02)*

**05-NOV-2004**

Add black and yellow, North cardinal pillar light buoy Q,  
marked TG

LNM/D. 24-SEP-2004

48°11'41.3"N 052°54'56.6"W

*(N2002044) LL(471.8) DFO(6300293-01)*

**24-SEP-2004**

Add green port hand spar light buoy QG, marked TH1

LNM/D. 20-AUG-2004

48°03'06.0"N 053°14'25.0"W

*(N2004168) LL(469.89) DFO(6301893-01)*

**20-AUG-2004**

Add green port hand spar light buoy FlG, marked TW1

LNM/D. 26-DEC-2003

47°57'45.0"N 053°20'06.0"W

*(N2004107) LL(469.21) DFO(6301603-01)*

**20-AUG-2004**

Add red starboard hand spar light buoy FlR, marked  
TW2

LNM/D. 26-DEC-2003

47°57'23.0"N 053°19'59.0"W

*(N2004108) LL(469.22) DFO(6301604-01)*

**05-DEC-2003**

Delete depth of 2 metres 7 decimetres 48°05'03.0"N 052°53'59.0"W

LNM/D. 14-NOV-2003

*(N2003038) DFO(6301006-01)*

**05-DEC-2003**

Add breakwater between 48°05'06.0"N 052°54'00.2"W  
and 48°05'03.3"N 052°54'00.1"W

LNM/D. 14-NOV-2003

*(N2003038) DFO(6301006-02)*

**05-DEC-2003**

LNM/D. 14-NOV-2003



**Chart no. 4850**

Add light FI G 48°05'03.3"N 052°54'00.1"W

*(N2003038) LL(474.3) DFO(6301006-03)*

**14-NOV-2003** LNM/D. 13-JUN-2003

Amend Fl G to read Q G 47°52'46.2"N 053°22'16.3"W

*(N2002117) LL(468.8) DFO(6300540-01)*

**14-NOV-2003** LNM/D. 13-JUN-2003

Reposition light FlG from 47°54'44.0"N 053°03'55.4"W  
to 47°54'46.4"N 053°03'56.8"W

*(N2002143) LL(475.1) DFO(6300581-01)*

**13-JUN-2003** LNM/D. 16-MAY-2003

Delete red and white fairway pillar light buoy Mo (A),  
BELL, marked TP 48°06'02.8"N 053°01'45.6"W

*(N2002047) LL(471.5) DFO(6300406-01)*

**13-JUN-2003** LNM/D. 16-MAY-2003

Replace red starboard hand pillar light and bell buoy Fl R,  
BELL, marked CV2 with red starboard hand pillar  
light buoy Fl R, marked CV2 48°04'57.0"N 052°54'09.0"W

*(N2002050) LL(474) DFO(6300409-01)*

**13-JUN-2003** LNM/D. 16-MAY-2003

Add green port hand spar light buoy FlG, marked TP1 48°05'56.5"N 053°01'19.7"W

*(N2002052) LL(471.51) DFO(6300410-01)*

**16-MAY-2003** LNM/D. 21-FEB-2003

Delete red and white fairway pillar light buoy Mo (A),  
BELL, marked TH 48°03'00.5"N 053°14'56.6"W

*(N2002042) LL(470.2) DFO(6300288-01)*

**21-FEB-2003** LNM/D. 23-AUG-2002



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4850

Add submerged wreck 47°54'25.8"N 052°49'24.7"W

*(N2002032) DFO(6300432-01)*

**23-AUG-2002**

LNМ/D. 08-MAR-2002

Add light FIR 47°58'11.2"N 053°00'59.4"W

*(N2000389) LL(475.3) DFO(6829292-01)*

**08-MAR-2002**

LNМ/D. 25-JAN-2002

Amend FIR to read FlG 47°54'44.0"N 053°03'55.4"W

*(N2000064) LL(475.1) DFO(6828824-01)*

**25-JAN-2002**

LNМ/D. 18-JAN-2002

Add wreck 48°12'00.0"N 052°53'30.0"W

*(N2000-345) DFO(6829836-01)*

**11-JAN-2002**

LNМ/D. 01-SEP-2000

Amend Fl 3s 38m 5M to read FlR 3s 38m 5M 48°05'41.1"N 053°32'43.1"W

*(N2000063) LL(465) DFO(6828823-01)*

**01-SEP-2000**

LNМ/D. 11-DEC-1998

Delete green light, port hand pillar buoy Fl G, marked  
MSF3

47°48'44.5"N 052°46'01.5"W

*(N2000-100) LL(499.1) DFO(6828899-01)*

**01-SEP-2000**

LNМ/D. 11-DEC-1998

Add black and yellow, north cardinal pillar light buoy Q,  
marked MSF

47°48'44.5"N 052°46'01.0"W

*(N2000-100) LL(499.1) DFO(6828899-02)*

### 4850 - Heart's Content - New Chart - 11-MAY-1990 - NAD 1983

**15-FEB-2013**

LNМ/D. 04-FEB-2011



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4850

Affix patch 47°52'45.0"N 053°22'00.0"W  
[PDF](#)

*DFO(6306296-01)*

**14-NOV-2003**

LNM/D. 13-JUN-2003

Amend Fl G to read Q G

47°52'46.2"N 053°22'16.3"W

*(N2002117) LL(468.8) DFO(6300540-01)*

### 4850 - Old Perlican - New Chart - 11-MAY-1990 - NAD 1983

**03-SEP-2021**

LNM/D. 11-DEC-2020

Reposition red starboard hand lighted spar buoy Fl R,  
marked TP2

from 48°05'22.1"N 053°00'51.0"W  
to 48°05'33.5"N 053°01'05.2"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational  
Chart: CA576147

*(N2021076) LL(470.76) DFO(6309552-01)*

**03-SEP-2021**

LNM/D. 11-DEC-2020

Reposition green port hand lighted spar buoy Fl G,  
marked TP3

from 48°05'21.0"N 053°00'47.9"W  
to 48°05'30.3"N 053°00'57.2"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational  
Chart: CA576147

*(N2021077) LL(470.75) DFO(6309553-01)*

**11-DEC-2020**

LNM/D. 14-JUL-2017

Affix patch

48°05'00.0"N 053°00'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576147

*DFO(6309306-01)*

**12-SEP-2014**

LNM/D. 06-DEC-2013

Add radio reporting line

between 48°05'54.0"N 053°01'56.2"W  
and 48°05'27.1"N 053°01'37.5"W

(See Chart No. 1, M40.2)

This notice affects Electronic Navigational Chart:  
CA276092, CA376146, CA376243, CA576147

*DFO(6306732-05)*

**12-SEP-2014**

LNM/D. 06-DEC-2013





Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4850

Add mandatory calling-in point "1" with arrowhead pointing 057° and 48°05'41.6"N 053°01'47.8"W  
237°

(See Chart No. 1, M40.1)

*DFO(6306732-07)*

This notice affects Electronic Navigational Chart: CA376146,  
CA576147

**06-DEC-2013** LNM/D. 15-FEB-2013

Affix patch 48°05'12.5"N 053°00'36.1"W

[PDF](#)

*DFO(6306573-01)*

**24-AUG-2007**

LNM/D. 15-SEP-2006

Reposition green port hand lighted spar buoy FlG,  
marked TP3

from 48°05'23.5"N 053°00'49.5"W  
to 48°05'21.0"N 053°00'48.0"W

*(N2007023) LL(470.74) DFO(6303558-01)*

**26-MAY-2006**

LNM/D. 10-MAR-2006

Add green port hand lighted spar buoy Fl G, marked TP7

48°05'15.7"N 053°00'30.8"W

*(N2006010) LL(470.51) DFO(6302833-01)*

**26-MAY-2006**

LNM/D. 10-MAR-2006

Add green port hand lighted spar buoy Fl G, marked TP9

48°05'16.7"N 053°00'27.5"W

*(N2006011) LL(470.53) DFO(6302845-01)*

**26-MAY-2006**

LNM/D. 10-MAR-2006

Add red starboard hand lighted spar buoy FIR, marked  
TP8

48°05'10.3"N 053°00'36.2"W

*(N2006015) LL(470.55) DFO(6302864-01)*

**30-DEC-2005**

LNM/D. 05-NOV-2004

Delete green port hand lighted spar buoy FlG, marked  
TP3

48°05'30.0"N 053°01'00.0"W

*(N2005087) LL(470.74) DFO(6302629-01)*

**30-DEC-2005**

LNM/D. 05-NOV-2004



**Chart no. 4850**

- Add green port hand lighted spar buoy FlG, marked TP3 48°05'23.5"N 053°00'49.5"W  
(N2005087) LL(470.74) DFO(6302629-02)
- 30-DEC-2005** LNM/D. 05-NOV-2004  
Delete red starboard hand lighted spar buoy FlR, 48°05'22.0"N 053°00'54.0"W  
marked TP4 (N2005088) LL(470.71) DFO(6302630-01)
- 30-DEC-2005** LNM/D. 05-NOV-2004  
Add red starboard hand lighted spar buoy FlR, marked 48°05'18.4"N 053°00'48.3"W  
TP4 (N2005088) LL(470.71) DFO(6302630-02)
- 30-DEC-2005** LNM/D. 05-NOV-2004  
Delete green port hand lighted spar buoy FlG, marked 48°05'18.0"N 053°00'45.0"W  
TP5 (N2005089) LL(470.72) DFO(6302631-01)
- 30-DEC-2005** LNM/D. 05-NOV-2004  
Add green port hand lighted spar buoy FlG, marked TP5 48°05'20.2"N 053°00'47.8"W  
(N2005089) LL(470.72) DFO(6302631-02)
- 30-DEC-2005** LNM/D. 05-NOV-2004  
Delete red starboard hand lighted spar buoy FlR, 48°05'33.0"N 053°01'12.0"W  
marked TP2 (N2005096) LL(470.73) DFO(6302643-01)
- 30-DEC-2005** LNM/D. 05-NOV-2004  
Add red starboard hand lighted spar buoy FlR, marked 48°05'22.1"N 053°00'51.1"W  
TP2 (N2005096) LL(470.73) DFO(6302643-02)
- 26-DEC-2003** LNM/D. 05-DEC-2003  
Amend "TP6" to read "TP4" against red starboard hand 48°05'22.0"N 053°00'54.0"W  
spar light buoy (N2003028) LL(470.71) DFO(6301000-01)



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4850

### 26-DEC-2003

Amend "TP4" to read "TP2" against red starboard hand spar light buoy

LNМ/D. 05-DEC-2003

48°05'33.0"N 053°01'12.0"W

(N2003029) LL(470.73) DFO(6301001-01)

### 16-MAY-2003

Replace green port hand spar light buoy FIG, marked TP1 with green port hand spar light buoy FIG, marked TP3

LNМ/D. 21-FEB-2003

48°05'30.0"N 053°01'00.0"W

(N2002055) LL(470.74) DFO(6300413-01)

### 16-MAY-2003

Replace green port hand spar light buoy FIG, marked TP3 with green port hand spar light buoy FIG, marked TP5

LNМ/D. 21-FEB-2003

48°05'18.0"N 053°00'45.0"W

(N2002056) LL(470.72) DFO(6300414-01)

### 16-MAY-2003

Replace red starboard hand spar light buoy FLR, marked TP2 with red starboard hand spar light buoy FLR, marked TP4

LNМ/D. 21-FEB-2003

48°05'33.0"N 053°01'12.0"W

(N2002057) LL(470.73) DFO(6300415-01)

### 16-MAY-2003

Replace red starboard hand spar light buoy FLR, marked TP4 with red starboard hand spar light buoy FLR, marked TP6

LNМ/D. 21-FEB-2003

48°05'22.0"N 053°00'54.0"W

(N2002058) LL(470.71) DFO(6300416-01)

### 18-JAN-2002

Replace red, starboard hand spar buoy, marked TP2, with red light, starboard hand spar buoy FLR, marked TP2

LNМ/D. 11-JAN-2002

48°05'33.0"N 053°01'12.0"W

(N2000094) LL(470.73) DFO(6828881-01)

### 18-JAN-2002

Replace green port hand spar buoy, marked TP3 with green port hand spar light buoy FIG, marked TP3

LNМ/D. 11-JAN-2002

48°05'18.0"N 053°00'45.0"W

(N2000095) LL(470.72) DFO(6828882-01)



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4850

**18-JAN-2002**

LN/D. 11-JAN-2002

Delete red, starboard hand spar buoy, marked TP4 48°05'22.0"N 053°00'56.0"W

*(N2000096) DFO(6828883-01)*

**18-JAN-2002**

LN/D. 11-JAN-2002

Add red light, starboard hand spar buoy FLR, marked  
TP4

48°05'22.0"N 053°00'54.0"W

*(N2000-096) LL(470.71) DFO(6828883-02)*

**18-JAN-2002**

LN/D. 11-JAN-2002

Replace green port hand spar buoy, marked TP1 with  
green port hand spar light buoy FIG, marked  
TP1

48°05'30.0"N 053°01'00.0"W

*(N2000097) LL(470.74) DFO(6828884-01)*