



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

4862 - Carmanville to / à Bacalhoa Island and / et Fogo - New Chart - 26-DEC-2003 - NAD 1983

10-NOV-2023

LNМ/D. 28-APR-2023

Add marine farm

49°34'46.8"N 054°15'39.0"W

(See Chart 1, K48.2)

This notice affects Electronic Navigational Chart: CA476813

DFO(6310942-01)

28-APR-2023

LNМ/D. 14-APR-2023

Delete green port hand lighted pillar buoy Fl G, marked DV5

49°42'28.3"N 054°17'29.7"W

(See Chart 1, Qc)

(N2023042) LL(367.5) DFO(6310641-01)

This notice affects Electronic Navigational Chart:

CA476719, CA576720

14-APR-2023

LNМ/D. 23-DEC-2022

Amend Fl(2)5s to read Fl(2)10s against black, red and black isolated danger lighted spar buoy, marked DC

49°23'34.9"N 054°16'55.0"W

(See Chart 1, Q130.4)

(N2023029) LL(390.131) DFO(6310613-01)

This notice affects Electronic Navigational Chart: CA476813, CA576280

23-DEC-2022

LNМ/D. 23-SEP-2022

Delete green port hand lighted spar buoy Fl G, marked DWG5

49°40'32.5"N 054°23'34.3"W

(See Chart 1, Qc)

(N2022277) LL(344.41) DFO(6310498-01)

This notice affects Electronic Navigational Chart: CA476814

23-DEC-2022

LNМ/D. 23-SEP-2022

Add green port hand lighted spar buoy Q G, marked DWG5

49°40'32.5"N 054°23'38.0"W

(See Chart 1, Qc)

(N2022277) LL(344.41) DFO(6310498-02)

This notice affects Electronic Navigational Chart: CA476814

23-SEP-2022

LNМ/D. 09-SEP-2022



Chart no. 4862

Reposition red starboard hand lighted spar buoy Fl R,
marked DWG2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476814

from 49°40'37.6"N 054°23'21.2"W
to 49°40'36.6"N 054°23'28.2"W

(N2022144) LL(345.41) DFO(6310237-01)

23-SEP-2022

Amend FlG to read Q G against green port hand lighted
spar buoy, marked DF3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA476719, CA576720

LNLM/D. 09-SEP-2022
49°43'36.8"N 054°16'18.1"W
(N2022150) LL(365.3) DFO(6310243-01)

09-SEP-2022

Add green port hand lighted spar buoy Fl G, marked
DWG1
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA476814

LNLM/D. 08-JUL-2022
49°40'41.3"N 054°22'58.1"W
(N2022160) LL(344.39) DFO(6310253-01)

08-JUL-2022

Delete light Fl G
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA476719, CA576720

LNLM/D. 11-FEB-2022
49°42'54.7"N 054°17'08.2"W
(N2022067) LL(366) DFO(6310099-01)

08-JUL-2022

Delete green port hand lighted spar buoy FlG, marked
DK3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA476813

LNLM/D. 11-FEB-2022
49°25'59.0"N 054°21'20.0"W
(N2022071) LL(387.92) DFO(6310103-01)

08-JUL-2022

Amend note Chart/Carte 4529 to read Chart/Carte 4861
(See Chart No. 1, A18)

LNLM/D. 11-FEB-2022
49°43'52.0"N 054°17'52.0"W
DFO(6310103-02)

11-FEB-2022

LNLM/D. 31-DEC-2021



Chart no. 4862

Add light Fl 4s2M 49°34'33.8"N 054°22'10.1"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (N2021176) LL(371.1) DFO(6309898-01)
CA376655, CA476813

31-DEC-2021 LNM/D. 08-OCT-2021
Delete green port hand lighted spar buoy Fl G, marked 49°23'34.9"N 054°16'55.9"W
DC13
(See Chart No. 1, Qg) (N2021171) LL(390.131) DFO(6309893-01)
This notice affects Electronic Navigational
Chart: CA476813, CA576280

31-DEC-2021 LNM/D. 08-OCT-2021
Add black, red and black isolated danger lighted spar 49°23'34.9"N 054°16'54.6"W
buoy Fl(2)5s, marked DC
(See Chart No. 1, Q130.4) (N2021171) LL(390.131) DFO(6309893-02)
This notice affects Electronic Navigational Chart:
CA476813, CA576280

08-OCT-2021 LNM/D. 25-SEP-2020
Reposition red starboard hand lighted pillar buoy Fl R, from 49°33'33.8"N 054°17'03.6"W
marked DX8 to 49°33'34.1"N 054°17'12.3"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational (N2021058) LL(373) DFO(6309538-01)
Chart: CA476813

08-OCT-2021 LNM/D. 25-SEP-2020
Add black, yellow and black East cardinal lighted spar 49°34'07.7"N 054°15'55.5"W
buoy Q(3)10s, marked DX
(See Chart No. 1, Q130.3) (N2021096) LL(372.6) DFO(6309570-01)
This notice affects Electronic Navigational Chart:
CA476813

25-SEP-2020 LNM/D. 24-JUL-2020
Amend Fl 6s10m6M to read Fl 4s10m5M against light 49°26'55.9"N 054°13'41.5"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (N2020073) LL(389) DFO(6309151-01)
CA376655, CA476813

24-JUL-2020 LNM/D. 03-JUL-2020



Chart no. 4862

Amend Fl 6s11m6M to read Fl 4s11m6M against light 49°36'41.8"N 054°27'09.6"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (N2020043) LL(377) DFO(6309010-01)
CA376655, CA476814

24-JUL-2020 LNM/D. 03-JUL-2020
Add yellow and black South cardinal lighted pillar buoy 49°33'21.9"N 054°19'58.8"W
Q(6)+LFl 15s, marked DHL
(See Chart No. 1, Q130.3) (N2020052) LL(372.9) DFO(6309019-01)
This notice affects Electronic Navigational Chart:
CA476813

24-JUL-2020 LNM/D. 03-JUL-2020
Add yellow cautionary lighted pillar buoy Fl Y, marked 49°33'20.8"N 054°24'50.2"W
DHJ
(See Chart No. 1, Qm) (N2020053) LL(372.4) DFO(6309020-01)
This notice affects Electronic Navigational Chart:
CA476813

03-JUL-2020 LNM/D. 05-JUL-2019
Amend FlG 6s to read Fl G 5s against light 49°40'07.7"N 054°24'49.5"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (N2020041) LL(372) DFO(6309008-01)
CA376655, CA476814

05-JUL-2019 LNM/D. 20-JUL-2018
Delete private light, FlG(Priv) 49°42'48.8"N 054°17'16.7"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (N2019017) LL(367) DFO(6308663-01)
CA476814

20-JUL-2018 LNM/D. 17-NOV-2017
Amend DX9 to read DH1 against buoy 49°34'13.5"N 054°19'13.3"W
(See Chart No. 1, Q11)
This notice affects Electronic Navigational Chart: (N2018032) LL(373.1) DFO(6308320-01)
CA476813

17-NOV-2017 LNM/D. 25-AUG-2017



Chart no. 4862

Replace wharf with wharf in ruins with legend Ru
(See Chart No. 1 F13, F33)
This notice affects Electronic Navigational Chart:
CA476814

between 49°38'33.4"N 054°34'59.7"W
and 49°38'33.4"N 054°34'56.9"W

DFO(6308127-01)

25-AUG-2017

Delete ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA476813

LNLM/D. 06-NOV-2015
joining 49°34'52.2"N 054°21'58.7"W
49°34'53.0"N 054°22'04.5"W
and 49°34'02.1"N 054°23'18.1"W

DFO(6308011-01)

25-AUG-2017

Add ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA476813

LNLM/D. 06-NOV-2015
between 49°34'02.6"N 054°23'19.0"W
and 49°34'52.2"N 054°21'58.7"W

DFO(6308011-02)

25-AUG-2017

Delete ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA376655, CA476813

LNLM/D. 06-NOV-2015
joining 49°33'24.1"N 054°28'31.7"W
49°34'07.8"N 054°24'09.1"W
and 49°34'14.1"N 054°24'09.1"W

DFO(6308011-03)

25-AUG-2017

Add ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA376655, CA476813

LNLM/D. 06-NOV-2015
between 49°33'30.1"N 054°26'04.2"W
and 49°34'08.2"N 054°23'40.4"W

DFO(6308011-04)

25-AUG-2017

Delete ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA376655, CA476813

LNLM/D. 06-NOV-2015
joining 49°33'24.1"N 054°28'31.7"W
49°33'31.5"N 054°19'15.4"W
and 49°34'10.4"N 054°18'15.1"W

DFO(6308011-05)

25-AUG-2017

LNLM/D. 06-NOV-2015



Chart no. 4862

Add ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA376655, CA476813

joining 49°33'24.1"N 054°28'31.7"W
49°33'30.1"N 054°26'04.2"W
49°33'17.2"N 054°20'00.0"W
49°33'24.1"N 054°19'14.2"W
49°33'54.2"N 054°18'41.4"W
and 49°34'10.4"N 054°18'15.1"W

DFO(6308011-06)

06-NOV-2015

LNLM/D. 16-JAN-2015

Add ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart:
CA376655, CA476813

joining 49°34'14.1"N 054°24'03.5"W
49°34'02.3"N 054°23'18.8"W
49°34'53.1"N 054°22'04.6"W
and 49°34'10.4"N 054°18'15.5"W

DFO(6307250-03)

16-JAN-2015

LNLM/D. 28-MAR-2014

Reposition green port hand lighted spar buoy FlG,
marked DWG3
(See Chart No. 1, Qg)
This notice affects Electronic Navigational
Chart: CA476814

from 49°40'33.8"N 054°23'24.6"W
to 49°40'35.7"N 054°23'23.0"W

(N2014083) LL(344.4) DFO(6307027-01)

28-MAR-2014

LNLM/D. 21-FEB-2014

Amend sector light FRWG to read FRWG (Occas) against light
(See Chart No 1 P50)
This notice affects Electronic Navigational Chart: CA376655,
CA476814

49°41'14.5"N 054°33'17.1"W

LL(362.5) DFO(6306703-01)

21-FEB-2014

LNLM/D. 17-MAY-2013

Add sounding of 6 meters 7 decimetres, with legend, "PA, Rep (2013)"
(See Chart No. 1, I3.2)
This notice affects Electronic Navigational Chart: CA476813

49°33'50.4"N 054°26'05.4"W

DFO(6306599-01)

17-MAY-2013

LNLM/D. 20-JUL-2012

Reposition red starboard hand lighted spar buoy FlR,
marked DCB2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational
Chart: CA476814

from 49°37'12.8"N 054°33'47.6"W
to 49°37'11.2"N 054°33'54.7"W

(N2012019) LL(376.2) DFO(6306358-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

20-JUL-2012

Reposition green port hand lighted spar buoy FlG,
marked DWG5
(See Chart No. 1, Qg)

LNM/D. 16-MAR-2012

from 49°40'29.9"N 054°23'35.5"W
to 49°40'32.4"N 054°23'34.4"W

(N2012014) LL(344.41) DFO(6306078-01)

This notice affects Electronic Navigational
Chart: CA476814

16-MAR-2012

Reposition red starboard hand lighted spar buoy FlR, marked
DX6
(See Chart No. 1, Qf)

LNM/D. 10-DEC-2010

from 49°33'39.5"N 054°16'49.5"W
to 49°33'39.8"N 054°16'38.6"W

LL(372.62) DFO(6305947-01)

10-DEC-2010

Delete depth of 7 metres, 6 decimetres
(See Chart No 1 I10)

LNM/D. 24-SEP-2010

49°33'21.1"N 054°25'37.9"W

DFO(6305132-01)

This notice affects Electronic Navigational Chart: CA476813

10-DEC-2010

Add depth of 4 metres, 8 decimetres
(See Chart No 1 I10)

LNM/D. 24-SEP-2010

49°33'23.1"N 054°25'38.0"W

DFO(6305132-02)

This notice affects Electronic Navigational Chart: CA376655,
CA476813

10-DEC-2010

Add depth of 4 metres, 5 decimetres
(See Chart No 1 I10)

LNM/D. 24-SEP-2010

49°33'17.2"N 054°25'30.0"W

DFO(6305132-03)

This notice affects Electronic Navigational Chart: CA476813

10-DEC-2010

LNM/D. 24-SEP-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

Delete depth of 6 metres, 7 decimetres
(See Chart No 1 I10)

49°23'53.3"N 054°16'55.7"W

DFO(6305132-04)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

Add depth of 5 metres, 5 decimetres
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°23'53.9"N 054°16'55.0"W

DFO(6305132-05)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

Delete depth of 8 metres, 8 decimetres
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°24'41.0"N 054°16'13.4"W

DFO(6305132-07)

This notice affects Electronic Navigational Chart: CA476813

10-DEC-2010

Add depth of 7 metres, 3 decimetres
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°24'40.9"N 054°16'13.7"W

DFO(6305132-08)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

Add depth of 8 metres, 3 decimetres
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°25'20.2"N 054°15'39.9"W

DFO(6305132-10)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

LNМ/D. 24-SEP-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

Delete depth of 3 metres, 7 decimetres
(See Chart No 1 I10)

49°24'16.9"N 054°16'17.9"W

DFO(6305132-11)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010

Add depth of 2 metres, 1 decimetre
(See Chart No 1 I10)

LNМ/D. 24-SEP-2010

49°24'16.0"N 054°16'17.7"W

DFO(6305132-12)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

24-SEP-2010

Reposition yellow, black and yellow West cardinal lighted
pillar buoy Q (9) 15s, marked DHC
(See Chart No. 1 Q130.3)

LNМ/D. 27-AUG-2010

from 49°38'02.8"N 054°28'47.6"W
to 49°38'02.4"N 054°28'55.8"W

(N2004119) LL(376) DFO(6305021-01)

This notice affects Electronic Navigational
Chart: CA476814

27-AUG-2010

Delete depth of 3 metres, 8 decimetres
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°45'15.2"N 054°18'44.0"W

DFO(6304983-01)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

Add depth of 3 metres, 3 decimetres
(See Chart No. 1, I10)

LNМ/D. 04-JUN-2010

49°45'15.0"N 054°18'40.8"W

DFO(6304983-02)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

Delete depth of 18 metres, 3 decimetres
(See Chart No. 1, I10)

49°43'11.9"N 054°19'55.0"W

DFO(6304983-03)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

Add depth of 16 metres, 8 decimetres
(See Chart No. 1, I10)

LN/D. 04-JUN-2010

49°43'13.8"N 054°19'57.0"W

DFO(6304983-04)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

Delete depth of 5 metres, 3 decimetres
(See Chart No. 1, I10)

LN/D. 04-JUN-2010

49°37'59.0"N 054°21'00.0"W

DFO(6304983-05)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

Add depth of 4 metres, 9 decimetres
(See Chart No. 1, I10)

LN/D. 04-JUN-2010

49°37'58.8"N 054°21'00.0"W

DFO(6304983-06)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

Delete depth of 4 metres, 2 decimetres
(See Chart No. 1, I10)

LN/D. 04-JUN-2010

49°39'10.4"N 054°21'36.5"W

DFO(6304983-07)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

Add depth of 3 metres, 8 decimetres
(See Chart No. 1, I10)

LN/D. 04-JUN-2010

49°39'10.2"N 054°21'37.2"W

DFO(6304983-08)

This notice affects Electronic Navigational Chart: CA476814



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

27-AUG-2010

LNМ/D. 04-JUN-2010

Delete depth of 14 metres, 3 decimetres
(See Chart No. 1, I10)

49°39'16.8"N 054°20'02.7"W

DFO(6304983-09)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010

Add depth of 13 metres, 8 decimetres
(See Chart No. 1, I10)

49°39'16.2"N 054°20'01.8"W

DFO(6304983-10)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010

Add depth of 11 metres, 8 decimetres
(See Chart No. 1, I10)

49°36'22.8"N 054°20'57.6"W

DFO(6304983-11)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010

Delete depth of 15 metres, 6 decimetres
(See Chart No. 1, I10)

49°42'01.1"N 054°20'15.5"W

DFO(6304983-12)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010

Add depth of 5 metres, 7 decimetres
(See Chart No. 1, I10)

49°42'00.6"N 054°20'10.2"W

DFO(6304983-13)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010

Delete depth of 15 metres, 5 decimetres
(See Chart No. 1, I10)

49°44'17.3"N 054°18'07.3"W

DFO(6304983-14)

This notice affects Electronic Navigational Chart: CA476814



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

27-AUG-2010

LNМ/D. 04-JUN-2010

Add depth of 14 metres
(See Chart No. 1, I10)

49°44'16.8"N 054°18'09.0"W

DFO(6304983-15)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010

Add depth of 10 metres, 3 decimetres
(See Chart No. 1, I10)

49°41'36.0"N 054°23'25.2"W

DFO(6304983-16)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010

Add depth of 13 metres, 4 decimetres
(See Chart No 1 I10)

49°42'07.2"N 054°18'00.0"W

DFO(6304987-14)

This notice affects Electronic Navigational Chart: CA476814

27-AUG-2010

LNМ/D. 04-JUN-2010

Delete depth of 15 metres, 7 decimetres
(See Chart No 1 I10)

49°42'07.9"N 054°18'02.8"W

DFO(6304987-30)

This notice affects Electronic Navigational Chart: CA476814

04-JUN-2010

LNМ/D. 21-NOV-2008

Reposition green port hand lighted spar buoy FlG,
marked DX5
(See Chart No 1 Qg)

from 49°33'44.5"N 054°16'11.0"W
to 49°33'43.4"N 054°16'16.5"W

(N2010016) LL(372.63) DFO(6304818-01)

21-NOV-2008

LNМ/D. 17-OCT-2008



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

Reposition green port hand lighted spar buoy FlG,
marked DWG5
(See Chart No 1 Qg)

from 49°40'32.0"N 054°23'36.0"W
to 49°40'29.9"N 054°23'35.5"W

(N2008042) LL(344.41) DFO(6304137-01)

This notice affects Electronic Navigational
Chart: CA476814

17-OCT-2008

LNm/D. 10-OCT-2008

Add green port hand lighted spar buoy FlG, marked
DWG5
(See Chart No 1 Qg)

49°40'32.0"N 054°23'36.0"W

(N2008024) LL(344.41) DFO(6304012-01)

This notice affects Electronic Navigational Chart:
CA476814

17-OCT-2008

LNm/D. 10-OCT-2008

Add green port hand lighted spar buoy FlG, marked
DWG7
(See Chart No 1 Qg)

49°40'23.1"N 054°24'05.9"W

(N2008023) LL(344.42) DFO(6304035-01)

This notice affects Electronic Navigational Chart:
CA476814

10-OCT-2008

LNm/D. 02-NOV-2007

Amend sectors against sector light FRWG
(See Chart No 1P40)

49°41'14.5"N 054°33'17.1"W

Visible through an arc of 5°, red from 301° to
300½°, oscillating red and white from 300½° to
299½°, white from 299½° to 297½°, oscillating
green and white from 297½° to 296½° and green
from 296½° to 296°. Charted sectors extend 3.3
NM from light.

(N2008040) LL(362.5) DFO(6304063-01)

This notice affects Electronic Navigational Chart:
CA476814

02-NOV-2007

LNm/D. 26-OCT-2007



Chart no. 4862

Replace depth of 17 metres, 4 decimetres with depth of 15 metres, 9 decimetres
(See Chart No 1 Section I 10.)

49°44'39.6"N 054°15'44.1"W

DFO(6303683-01)

This notice affects Electronic Navigational Chart: CA476814

02-NOV-2007

Add depth of 5 metres, 8 decimetres
(See Chart No 1 Section I 10.)

LNМ/D. 26-OCT-2007
49°40'05.5"N 054°16'31.6"W

DFO(6303683-03)

This notice affects Electronic Navigational Chart: CA476814

02-NOV-2007

Add depth of 9 metres, 8 decimetres
(See Chart No 1 Section I 10.)

LNМ/D. 26-OCT-2007
49°41'14.8"N 054°17'45.9"W

DFO(6303683-04)

This notice affects Electronic Navigational Chart: CA476814

26-OCT-2007

Amend note Adjoining Chart/Carte adjacente 4520 to read Adjoining Chart/Carte adjacente 4820

LNМ/D. 26-JAN-2007
centre of north border

DFO(6303536-14)

26-OCT-2007

Amend note Adjoining Chart/Carte adjacente 4520 to read Adjoining Chart/Carte adjacente 4820

LNМ/D. 26-JAN-2007
centre of south border

DFO(6303536-15)

26-OCT-2007

Add note Adjoining Chart/Carte adjacente 4863 western border of chart at 49° 32' 30" N

LNМ/D. 26-JAN-2007

DFO(6303536-16)

26-JAN-2007

LNМ/D. 19-JAN-2007



Chart no. 4862

Add sector light FRWG

49°41'14.5"N 054°33'17.1"W

Visible through an arc of 5°, red from 301° to 300°, oscillating red and white from 300° to 299°, white from 299° to 298°, oscillating green and white from 298° to 297° and green from 297° to 296°. Charted secteurs extend 3.3 NM from light.

(N2006116) LL(362.5) DFO(6303255-01)

This notice affects Electronic Navigational Chart:
CA476814

19-JAN-2007

LNM/D. 13-JAN-2006

Delete front leading light "FR 53m"

49°41'20.1"N 054°33'15.4"W

(N2006112) LL(362.2) DFO(6303231-01)

This notice affects Electronic Navigational Chart:
CA476814

19-JAN-2007

LNM/D. 13-JAN-2006

Delete rear leading light "FR 63m" with leading line and bearing legend "121½° 301½°"

49°41'25.0"N 054°33'27.7"W

(N2006113) LL(362.3) DFO(6303231-02)

This notice affects Electronic Navigational Chart:
CA476814

13-JAN-2006

LNM/D. 10-JUN-2005

Add depth of 2 metres, 4 decimetres 49°34'17.5"N 054°28'12.0"W

DFO(6302699-01)

10-JUN-2005

LNM/D. 04-MAR-2005

Amend "FR 12m" to "Oc R 12m" against front range light

49°34'33.1"N 054°24'32.2"W

(N2005010) LL(368.4) DFO(6302266-01)

10-JUN-2005

LNM/D. 04-MAR-2005

Amend "FR 18m" to read "Oc R 18m" against rear range light

49°34'31.2"N 054°24'28.8"W

(N2005011) LL(368.5) DFO(6302267-01)



Chart no. 4862

04-MAR-2005

LNM/D. 27-AUG-2004

Delete front range light "FR 18m"

49°42'30.7"N 054°16'48.4"W

(N2004204) LL(367.2) DFO(6302162-01)

04-MAR-2005

LNM/D. 27-AUG-2004

Delete rear range light "FR 21m"

49°42'31.2"N 054°16'44.2"W

(N2004205) LL(367.3) DFO(6302162-02)

04-MAR-2005

LNM/D. 27-AUG-2004

Delete leading line and legends "076½° 256½°" between 49°42'31.2"N 054°16'44.2"W
and 49°42'11.0"N 054°18'54.0"W

LL(367.2) DFO(6302162-03)

04-MAR-2005

LNM/D. 27-AUG-2004

Amend "FIR" to read "FIG" against light

49°42'54.8"N 054°17'08.2"W

(N2004206) LL(366) DFO(6302164-01)

04-MAR-2005

LNM/D. 27-AUG-2004

Amend "FIR" to read "FIG (Priv)" against light

49°42'48.8"N 054°17'16.7"W

(N2004207) LL(367) DFO(6302165-01)

27-AUG-2004

LNM/D. 30-JUL-2004

Add red starboard hand spar light buoy QR, marked DPA2

49°38'56.0"N 054°34'00.0"W

(N2004136) LL(375.1) DFO(6301799-01)

27-AUG-2004

LNM/D. 30-JUL-2004

Add green port hand spar light buoy QG, marked DPA7

49°38'34.0"N 054°34'53.0"W

(N2004140) LL(375.8) DFO(6301813-01)

27-AUG-2004

LNM/D. 30-JUL-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4862

Add legend "Channel Buoyed/Chenal balisé" 49°39'00.0"N 054°34'42.0"W

DFO(6301862-01)

30-JUL-2004

Replace green port spar light buoy Fl G, marked DH13,
with yellow, black, yellow West cardinal pillar light
buoy Q(9)15s, marked DHC

49°38'02.4"N 054°28'47.6"W

(N2004095) LL(376) DFO(6301588-01)

30-JUL-2004

Replace green port spar light buoy Fl G, marked DH7
with black, yellow, black East cardinal spar light
buoy Q(3)10s, marked DHE

49°35'32.8"N 054°26'59.6"W

(N2004096) LL(377.85) DFO(6301589-01)

30-JUL-2004

Replace red starboard hand spar light buoy FlR, marked
DH10 with yellow and black, South cardinal
spar light buoy (Q(6)+LFl)15s, marked DHF

49°36'21.8"N 054°27'11.6"W

(N2004097) LL(377.87) DFO(6301590-01)