



Chart no. 4864

4864 - Black Island to / à Little Denier Island - New Chart - 25-AUG-2006 - NAD 1983

15-SEP-2023

LNLM/D. 18-AUG-2023

Delete legend Fog Sig 30s against light
(See Chart No 1 R1, R20)

49°31'06.6"N 055°07'01.0"W

This notice affects Electronic Navigational Chart: (N2023097) LL(347) DFO(6310764-01)
CA476639

18-AUG-2023

LNLM/D. 21-APR-2023

Add rock which covers and uncovers with drying height unknown with legend Rep (2023)
49°31'05.5"N 055°04'05.6"W

(See Chart 1, K11, I3)

DFO(6310716-01)

This notice affects Electronic Navigational Chart: CA476639

21-APR-2023

LNLM/D. 07-APR-2023

Delete green port hand lighted spar buoy Fl G, marked
DBT3

49°31'01.6"N 054°58'25.1"W

(See Chart 1, Qc)

(N2023041) LL(361.07) DFO(6310640-01)

This notice affects Electronic Navigational Chart:
CA476639

07-APR-2023

LNLM/D. 13-JAN-2023

Amend Fl 6s35m6M to read Fl 5s35m5M against light
(See Chart 1, P16)

49°19'44.7"N 055°12'13.8"W

This notice affects Electronic Navigational Chart: (N2023008) LL(349) DFO(6310592-01)
CA476639

07-APR-2023

LNLM/D. 13-JAN-2023

Delete light Fl
(See Chart 1, P1)

49°32'06.7"N 055°14'14.9"W

This notice affects Electronic Navigational Chart: (N2023014) LL(346) DFO(6310598-01)
CA476639

13-JAN-2023

LNLM/D. 07-OCT-2022

Amend DDL1 to read DBT7 against green port hand
lighted spar buoy Fl G

49°31'55.3"N 054°58'36.5"W

(See Chart 1, Qc)

(N2022302) LL(361.08) DFO(6310544-01)

This notice affects Electronic Navigational Chart:
CA476639, CA576601



Chart no. 4864

13-JAN-2023

LNLM/D. 07-OCT-2022

Amend DDL2 to read DBT6 against red starboard hand
lighted spar buoy Fl R.

49°31'55.8"N 054°58'37.1"W

(See Chart 1, Qb)

(N2022303) LL(361.09) DFO(6310545-01)

This notice affects Electronic Navigational Chart:
CA476639, CA576601

07-OCT-2022

LNLM/D. 12-AUG-2022

Add green port hand spar buoy, marked DBT5
(See Chart 1, Qc)

49°32'01.5"N 054°58'25.8"W

(N2022161) LL(361.065) DFO(6310254-01)

This notice affects Electronic Navigational Chart:
CA476639, CA576601

12-AUG-2022

LNLM/D. 17-NOV-2017

Add black and yellow North cardinal lighted spar buoy
Q, marked DDN

49°31'10.3"N 054°58'24.1"W

(See Chart No. 1, Q130.3)

(N2022081) LL(361.095) DFO(6310130-01)

This notice affects Electronic Navigational Chart:
CA476639

17-NOV-2017

LNLM/D. 20-OCT-2017

Affix patch

49°31'00.0"N 055°15'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA476639

DFO(6308132-01)

20-OCT-2017

LNLM/D. 12-MAY-2017

Add wreck, least depth unknown with legend Rep (2017)

49°31'57.0"N 055°14'04.9"W

(See Chart No. 1, K29, I3.2)

This notice affects Electronic Navigational Chart: CA476639

DFO(6308066-01)

12-MAY-2017

LNLM/D. 03-MAR-2017

Replace depth of 2 metres, 1 decimetre with dangerous underwater
rock of unknown depth, with legend Rep (2017)

49°30'10.9"N 055°13'07.8"W

(See Chart No. 1, I10, K13, I3.2)

DFO(6307922-01)

This notice affects Electronic Navigational Chart: CA376656,
CA476639

03-MAR-2017

LNLM/D. 28-OCT-2016



Chart no. 4864

Add underwater rock of unknown depth, dangerous to surface navigation with legend Rep(2016) 49°31'00.0"N 055°14'51.0"W
(See Chart No. 1, K13) *DFO(6307873-01)*

This notice affects Electronic Navigational Chart: CA476639

28-OCT-2016

Delete light Fl G LNM/D. 07-OCT-2016
(See Chart No. 1, P1) 49°19'18.0"N 055°02'00.7"W
This notice affects Electronic Navigational Chart: *(N2016056P) LL(352.9) DFO(6307712-01)*
CA476168

07-OCT-2016

Add red starboard hand lighted spar buoy QR, marked LNM/D. 24-JUN-2016
DSP2 49°21'14.2"N 055°01'44.8"W
(See Chart No. 1, Qf) *(N2013024) LL(352.97) DFO(6307700-01)*
This notice affects Electronic Navigational Chart:
CA476168

24-JUN-2016

Add marine farm LNM/D. 27-DEC-2013
(See Chart No. 1, K48.2) 49°20'54.0"N 055°20'09.0"W
This notice affects Electronic Navigational Chart: CA476639 *DFO(6307550-01)*

27-DEC-2013

Amend QR to read FIR against red starboard hand spar LNM/D. 09-NOV-2012
light buoy, marked DDL2 49°31'55.8"N 054°58'37.1"W
(See Chart No. 1, Qf) *(N2013021) LL(361.09) DFO(6306547-01)*
This notice affects Electronic Navigational
Chart: CA476639

27-DEC-2013

Amend QG to read FlG against green port hand lighted LNM/D. 09-NOV-2012
spar buoy marked DDL1 49°31'55.1"N 054°58'36.4"W
(See Chart No. 1, Qg) *(N2013022) LL(361.08) DFO(6306547-02)*
This notice affects Electronic Navigational Chart:
CA476639

09-NOV-2012

LNM/D. 09-DEC-2011



Chart no. 4864

Add marine farm
(See Chart No. 1, K48.2)

49°27'38.2"N 055°20'50.5"W

DFO(6306236-01)

This notice affects Electronic Navigational Chart: CA476639

09-DEC-2011

LNM/D. 31-DEC-2010

Add marine farm
(See Chart No. 1, K48.2)

49°24'07.0"N 055°17'50.0"W

DFO(6305837-01)

31-DEC-2010

LNM/D. 24-DEC-2010

Add black, yellow and black East cardinal lighted spar
buoy Q(3) 10s, marked DSC
(See Chart No 1 Q130.3)

49°20'40.2"N 055°01'27.6"W

(N2010057) LL(352.94) DFO(6305125-01)

This notice affects Electronic Navigational Chart:
CA476168

24-DEC-2010

LNM/D. 10-DEC-2010

Add green port hand lighted spar buoy FlG, marked
DSP1
(See Chart No. 1, Qg)

49°21'08.0"N 055°01'35.6"W

(N2010058) LL(352.96) DFO(6305126-01)

This notice affects Electronic Navigational Chart:
CA476168

10-DEC-2010

LNM/D. 18-JUN-2010

Add yellow, black and yellow West cardinal lighted spar
buoy VQ(9) 10s, marked DSR
(See Chart No 1 Q130.3)

49°32'32.4"N 054°57'19.2"W

(N2010056) LL(359.9) DFO(6305123-01)

This notice affects Electronic Navigational Chart:
CA376655

18-JUN-2010

LNM/D. 21-MAY-2010



Chart no. 4864

Add red starboard hand lighted spar buoy FIR, marked
DW4.2
(See Chart 1 Qf) 49°29'09.8"N 055°17'23.4"W
(N2010024) LL(344.5) DFO(6304885-01)

18-JUN-2010 LNM/D. 21-MAY-2010
Add green port hand lighted spar buoy FIG, marked DW5 49°22'51.6"N 055°15'45.1"W
(See Chart No 1 Qg) (N2010025) LL(344.9) DFO(6304886-01)

18-JUN-2010 LNM/D. 21-MAY-2010
Add green port hand lighted spar buoy FIG, marked DW1 49°29'26.8"N 055°17'32.2"W
(See Chart No 1 Qg) (N2010026) LL(344.6) DFO(6304887-01)

18-JUN-2010 LNM/D. 21-MAY-2010
Add green port hand lighted spar buoy FIG, marked DLR1 49°34'33.7"N 055°30'03.2"W
(See Chart 1 Qg) (N2010027) LL(340.1) DFO(6304898-01)

18-JUN-2010 LNM/D. 21-MAY-2010
Add green port hand lighted spar buoy FIG, marked DLR3 49°34'18.6"N 055°31'00.9"W
(See Chart 1 Qg) (N2010028) LL(340.3) DFO(6304899-01)

21-MAY-2010 LNM/D. 23-APR-2010
Replace black, yellow and black East cardinal lighted spar buoy VQ(3) 49°31'17.8"N 055°21'08.4"W
5s, marked DWD with black, yellow and black East cardinal
lighted pillar buoy VQ(3) 5s marked DWD LL(345.3) DFO(6304812-01)
(See Chart No 1 Q130.3)

23-APR-2010 LNM/D. 13-NOV-2009
Amend Q(3) 10s to read VQ(3) 5s against black, yellow and black East 49°31'17.8"N 055°21'08.4"W
cardinal lighted spar buoy marked DWD
(See Chart No 1 Q130.3) LL(345.3) DFO(6304769-01)

13-NOV-2009 LNM/D. 02-OCT-2009



Chart no. 4864

Add green port hand lighted spar buoy FlG, marked 49°31'01.6"N 054°58'25.1"W
DBT3
(See Chart No 1 Qg) (N2009048) LL(361.07) DFO(6304634-01)

This notice affects Electronic Navigational Chart:
CA476803

02-OCT-2009 LNM/D. 19-SEP-2008
Add red starboard hand lighted spar buoy QR, marked 49°31'55.8"N 054°58'37.1"W
DDL2
(See Chart No 1 Qf) (N2009027) LL(361.09) DFO(6304568-01)

02-OCT-2009 LNM/D. 19-SEP-2008
Add red starboard hand lighted spar buoy QR, marked 49°32'16.9"N 054°58'08.4"W
DBT2
(See Chart No 1 Qf) (N2009029) LL(361.06) DFO(6304570-01)

This notice affects Electronic Navigational Chart:
CA476803

02-OCT-2009 LNM/D. 19-SEP-2008
Add green port hand lighted spar buoy QG, marked 49°31'55.3"N 054°58'36.5"W
DDL1
(See Chart No 1 Qg) (N2009030) LL(361.08) DFO(6304571-01)

19-SEP-2008 LNM/D. 04-APR-2008
Delete red starboard hand lighted spar buoy FlR, marked 49°29'09.8"N 055°17'23.4"W
DW4.2
(See Chart No 1 Qf) (N2008018) LL(344.5) DFO(6304007-01)

19-SEP-2008 LNM/D. 04-APR-2008
Delete green port hand lighted spar buoy FlG, marked 49°22'51.6"N 055°15'45.1"W
DW5
(See Chart No 1 Qg) (N2008019) LL(344.9) DFO(6304008-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4864

19-SEP-2008

Delete green port hand lighted spar buoy FlG, marked
DW1
(See Chart No 1 Qg)

LNLM/D. 04-APR-2008

49°29'26.8"N 055°17'32.2"W

(N2008020) LL(344.6) DFO(6304009-01)

04-APR-2008

Delete depth of 3 metres
(See Chart No 1 I10)

LNLM/D. 28-DEC-2007

49°21'01.5"N 054°59'05.7"W

DFO(6303832-01)

This notice affects Electronic Navigational Chart: CA476168

04-APR-2008

Add dangerous underwater rock with depth of 1 metre, 3 decimetres
(See Chart No 1 K14)

LNLM/D. 28-DEC-2007

49°21'01.8"N 054°59'05.7"W

DFO(6303832-02)

This notice affects Electronic Navigational Chart: CA476168

28-DEC-2007

Amend FR to read FIR against light
(See Chart No 1 P16)

49°20'23.8"N 055°23'51.4"W

(N2007057) LL(345) DFO(6303744-01)