



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4885

4885 - Port Harmon - New Edition - 08-MAR-2002 - NAD 1983

26-AUG-2022

LNLM/D. 08-APR-2022

Amend Fl G to read Q G against green port hand lighted
spar buoy, marked XS5

48°30'49.0"N 058°32'13.0"W

(See Chart No. 1, Qg)

(N2022125) LL(180.52) DFO(6310195-01)

This notice affects Electronic Navigational Chart:
CA576826

08-APR-2022

LNLM/D. 24-SEP-2021

Amend Fl G to read Q G against green port lighted spar
buoy, marked XS9

48°31'30.5"N 058°31'45.4"W

(See Chart No. 1, Qg)

(N2022038) LL(180.6) DFO(6310041-01)

This notice affects Electronic Navigational Chart:
CA576826

24-SEP-2021

LNLM/D. 31-JUL-2020

Amend 10,1m to read 10,1m (2020)
(See Chart No. 1, I22)

48°31'40.6"N 058°31'39.1"W

DFO(6309614-01)

This notice affects Electronic Navigational Chart: CA576088

24-SEP-2021

LNLM/D. 31-JUL-2020

Amend 10,4m to read 8,6m (2020)
(See Chart No. 1, I22)

48°30'28.5"N 058°32'25.4"W

DFO(6309614-03)

This notice affects Electronic Navigational Chart: CA576088

24-SEP-2021

LNLM/D. 31-JUL-2020

Amend 10,4m to read 8,6m (2020)
(See Chart No. 1, I22)

48°31'19.9"N 058°31'50.7"W

DFO(6309614-04)

This notice affects Electronic Navigational Chart: CA576088

31-JUL-2020

LNLM/D. 01-MAY-2020

Reposition red starboard hand lighted spar buoy Fl R,
marked XS10

from 48°31'34.0"N 058°31'32.9"W
to 48°31'34.3"N 058°31'34.7"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational
Chart: CA576088

(N2020060) LL(180.61) DFO(6309027-01)



Chart no. 4885

20-DEC-2019

LNМ/D. 09-MAR-2018

Delete light Fl R

48°30'29.3"N 058°32'16.7"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (N2019112) LL(180.12) DFO(6308873-01)
CA476085, CA576088

20-DEC-2019

LNМ/D. 09-MAR-2018

Delete light Fl G

48°30'38.5"N 058°32'21.9"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (N2019113) LL(180.3) DFO(6308876-01)
CA576088

09-MAR-2018

LNМ/D. 14-JUL-2017

Reposition green port hand lighted spar buoy Fl G,
marked XS11

from 48°31'44.0"N 058°31'48.4"W
to 48°31'45.6"N 058°31'48.6"W

(See Chart No. 1, Qg)

(N2018002) LL(180.62) DFO(6308213-01)

This notice affects Electronic Navigational
Chart: CA576088

09-MAR-2018

LNМ/D. 14-JUL-2017

Delete red starboard hand lighted spar buoy Fl R,
marked XS8

48°31'16.0"N 058°31'50.4"W

(See Chart No. 1, Qf)

(N2018003) LL(180.55) DFO(6308214-01)

This notice affects Electronic Navigational Chart:
CA576088

09-MAR-2018

LNМ/D. 14-JUL-2017

Add red starboard hand lighted spar buoy Fl R, marked
XS8

48°31'09.6"N 058°31'54.6"W

(See Chart No. 1, Qf)

(N2018003) LL(180.55) DFO(6308214-02)

This notice affects Electronic Navigational Chart:
CA576088

09-MAR-2018

LNМ/D. 14-JUL-2017

Delete green port hand lighted spar buoy Fl G, marked
XS7

48°31'15.0"N 058°31'55.4"W

(See Chart No. 1, Qg)

(N2018004) LL(180.54) DFO(6308215-01)

This notice affects Electronic Navigational Chart:
CA576088



Chart no. 4885

09-MAR-2018

LNМ/D. 14-JUL-2017

Add green port hand lighted spar buoy Fl G, marked XS7
(See Chart No. 1, Qg)

48°31'09.0"N 058°31'59.4"W

This notice affects Electronic Navigational Chart: (N2018004) LL(180.54) DFO(6308215-02)
CA576088

09-MAR-2018

LNМ/D. 14-JUL-2017

Delete green port hand lighted spar buoy Fl G, marked
XS5

48°30'44.8"N 058°32'15.9"W

(See Chart No. 1, Qg)

(N2018005) LL(180.52) DFO(6308216-01)

This notice affects Electronic Navigational Chart:
CA576088

09-MAR-2018

LNМ/D. 14-JUL-2017

Add green port hand lighted spar buoy Fl G, marked XS5
(See Chart No. 1, Qg)

48°30'49.0"N 058°32'13.0"W

This notice affects Electronic Navigational Chart: (N2018005) LL(180.52) DFO(6308216-02)
CA576088

09-MAR-2018

LNМ/D. 14-JUL-2017

Reposition red starboard hand lighted spar buoy Fl R,
marked XS6

from 48°30'46.0"N 058°32'10.8"W
to 48°30'49.6"N 058°32'08.5"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart: (N2018006) LL(180.53) DFO(6308217-01)
CA576088

07-JUL-2017

LNМ/D. 28-DEC-2007

Affix patch

48°30'54.0"N 058°32'15.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576088 DFO(6307983-01)

28-DEC-2007

LNМ/D. 22-JUN-2007

Affix patch 48°31'40.0"N 058°31'39.0"W

DFO(6303759-01)

[PDF](#)

22-JUN-2007

LNМ/D. 30-JUL-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4885

Amend dredged channel depth of 10 metres to read 10 metres, 4
decimetres

48°31'20.3"N 058°31'50.3"W

DFO(6303490-01)

22-JUN-2007

LNM/D. 30-JUL-2004

Amend dredged channel depth of 10 metres to read 10 metres, 4
decimetres

48°30'28.4"N 058°32'25.3"W

DFO(6303490-02)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres, 4 decimetres 48°30'21.4"N 058°32'29.4"W

DFO(6303490-03)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 8 metres, 8 decimetres 48°30'23.3"N 058°32'28.2"W

DFO(6303490-04)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 8 metres, 5 decimetres 48°30'24.4"N 058°32'28.9"W

DFO(6303490-05)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 8 metres, 6 decimetres 48°30'25.4"N 058°32'28.0"W

DFO(6303490-06)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres, 3 decimetres 48°30'25.5"N 058°32'26.7"W

DFO(6303490-07)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres 48°30'23.6"N 058°32'26.4"W

DFO(6303490-08)



Chart no. 4885

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres, 8 decimetres 48°30'27.4"N 058°32'27.3"W

DFO(6303490-09)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres, 8 decimetres 48°30'32.3"N 058°32'21.4"W

DFO(6303490-10)

22-JUN-2007

LNM/D. 30-JUL-2004

Replace depth of 7 metres, 8 decimetres with depth of 9 metres, 5
decimetres

48°30'38.4"N 058°32'20.1"W

DFO(6303490-11)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres, 1 decimetre 48°30'50.8"N 058°32'08.0"W

DFO(6303490-12)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres, 5 decimetres 48°30'54.3"N 058°32'05.4"W

DFO(6303490-13)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres, 2 decimetres 48°30'58.3"N 058°32'03.0"W

DFO(6303490-14)

22-JUN-2007

LNM/D. 30-JUL-2004

Delete depth of 9 metres, 8 decimetres 48°31'02.7"N 058°31'59.7"W

DFO(6303490-15)

22-JUN-2007

LNM/D. 30-JUL-2004



Chart no. 4885

Delete depth of 9 metres, 9 decimetres 48°31'14.4"N 058°31'51.8"W

DFO(6303490-16)

22-JUN-2007

LNМ/D. 30-JUL-2004

Delete depth of 9 metres, 9 decimetres 48°31'20.6"N 058°31'51.3"W

DFO(6303490-17)

22-JUN-2007

LNМ/D. 30-JUL-2004

Delete depth of 8 metres, 6 decimetres 48°31'23.7"N 058°31'45.4"W

DFO(6303490-18)

22-JUN-2007

LNМ/D. 30-JUL-2004

(P>Delete dredged channel with a maintained depth of 9 metres 2 decimetres (The Turning Basin in Port Harmon has been dredged to 10 metres 1 decimetre. A chart amendment patch will be available in the future.)

joining 48°31'29.2"N 058°31'41.7"W
48°31'40.4"N 058°31'29.4"W
48°31'48.5"N 058°31'37.0"W
48°31'48.6"N 058°31'36.8"W
48°31'50.2"N 058°31'38.4"W
48°31'46.8"N 058°31'46.5"W
and 48°31'30.4"N 058°31'45.5"W

The patch for the turning basin in Port Harmon has been released in the December 2007 edition. See Notice 28-Dec-2007 (DFO 6303759). Notice 22-Jun-2007(P), DFO(6303511) is now cancelled. Cancelled on 08-FEB-08

DFO(6303511-01)

22-JUN-2007

LNМ/D. 30-JUL-2004

(P)Add dredged channel with a maintained depth of 10 metres, 1 decimetre (The Turning Basin in Port Harmon has been dredged to 10 metres 1 decimetre. A chart amendment patch will be available in the future.)

joining 48°31'34.3"N 058°31'38.2"W
48°31'39.1"N 058°31'27.8"W
48°31'40.4"N 058°31'29.4"W
48°31'48.5"N 058°31'37.0"W
48°31'48.9"N 058°31'35.9"W
48°31'50.6"N 058°31'38.5"W
48°31'48.5"N 058°31'41.3"W
48°31'45.4"N 058°31'48.7"W
48°31'32.7"N 058°31'45.2"W
48°31'30.4"N 058°31'45.5"W
and 48°31'29.2"N 058°31'41.7"W

The patch for the turning basin in Port Harmon has been released in the December 2007 edition. See Notice 28-Dec-2007 (DFO 6303759). Notice 22-Jun-2007(P), DFO(6303511) is now cancelled. Cancelled on 08-FEB-08

DFO(6303511-02)



Chart no. 4885

22-JUN-2007

(P)Add depth of 9 metres, 8 decimetres
(The Turning Basin in Port Harmon has been dredged to 10 metres 1 decimetre. A chart amendment patch will be available in the future.)

The patch for the turning basin in Port Harmon has been released in the December 2007 edition. See Notice 28-Dec-2007 (DFO 6303759). Notice 22-Jun-2007(P), DFO(6303511) is now cancelled.
Cancelled on 08-FEB-08

LNМ/D. 30-JUL-2004
48°31'41.9"N 058°31'30.9"W
DFO(6303511-03)

22-JUN-2007

(P)Add depth of 9 metres
(The Turning Basin in Port Harmon has been dredged to 10 metres 1 decimetre. A chart amendment patch will be available in the future.)

The patch for the turning basin in Port Harmon has been released in the December 2007 edition. See Notice 28-Dec-2007 (DFO 6303759). Notice 22-Jun-2007(P), DFO(6303511) is now cancelled.
Cancelled on 08-FEB-08

LNМ/D. 30-JUL-2004
48°31'43.6"N 058°31'47.9"W
DFO(6303511-04)

22-JUN-2007

(P)Add depth of 9 metres 8 decimetres
(The Turning Basin in Port Harmon has been dredged to 10 metres 1 decimetre. A chart amendment patch will be available in the future.)

The patch for the turning basin in Port Harmon has been released in the December 2007 edition. See Notice 28-Dec-2007 (DFO 6303759). Notice 22-Jun-2007(P), DFO(6303511) is now cancelled.
Cancelled on 08-FEB-08

LNМ/D. 30-JUL-2004
48°31'42.2"N 058°31'46.6"W
DFO(6303511-05)

22-JUN-2007

LNМ/D. 30-JUL-2004



Chart no. 4885

(P)Add depth of 9 metres 7 decimetres
(The Turning Basin in Port Harmon has been dredged to 10 metres 1 decimetre. A chart amendment patch will be available in the future.)

48°31'40.1"N 058°31'46.2"W

DFO(6303511-06)

The patch for the turning basin in Port Harmon has been released in the December 2007 edition. See Notice 28-Dec-2007 (DFO 6303759). Notice 22-Jun-2007(P), DFO(6303511) is now cancelled.
Cancelled on 08-FEB-08

22-JUN-2007

LNМ/D. 30-JUL-2004

(P)Add depth of 9 metres 1 decimetre
(The Turning Basin in Port Harmon has been dredged to 10 metres 1 decimetre. A chart amendment patch will be available in the future.)

48°31'33.2"N 058°31'39.2"W

DFO(6303511-07)

The patch for the turning basin in Port Harmon has been released in the December 2007 edition. See Notice 28-Dec-2007 (DFO 6303759). Notice 22-Jun-2007(P), DFO(6303511) is now cancelled.
Cancelled on 08-FEB-08

22-JUN-2007

LNМ/D. 30-JUL-2004

(P)Add depth of 9 metres 1 decimetre
(The Turning Basin in Port Harmon has been dredged to 10 metres 1 decimetre. A chart amendment patch will be available in the future.)

48°31'30.9"N 058°31'40.7"W

DFO(6303511-08)

The patch for the turning basin in Port Harmon has been released in the December 2007 edition. See Notice 28-Dec-2007 (DFO 6303759). Notice 22-Jun-2007(P), DFO(6303511) is now cancelled.
Cancelled on 08-FEB-08

30-JUL-2004

LNМ/D. 16-JUL-2004

Reposition red starboard hand spar light buoy FlR,
marked XS2

from 48°30'32.1"N 058°32'20.4"W
to 48°30'30.4"N 058°32'21.4"W

(N2004067) LL(180.2) DFO(6301557-01)

24-OCT-2003

LNМ/D. 07-FEB-2003



Chart no. 4885

Delete legend BELL against red and white fairway pillar
light buoy Mo (A), BELL, marked XS

48°29'44.0"N 058°32'52.4"W

(N2003018) LL(179.5) DFO(6300960-01)

4885 - Port Harmon and Approaches / et les approches - New Edition - 08-MAR-2002 - NAD 1983

01-MAY-2020

LNМ/D. 20-DEC-2019

Add breakwater with legend Bkw
(See Chart No. 1, F4.1)

between 48°25'52.6"N 058°29'09.6"W
and 48°25'53.9"N 058°29'08.1"W

This notice affects Electronic Navigational Chart:
CA476085, CA576086

DFO(6308927-01)

01-MAY-2020

LNМ/D. 20-DEC-2019

Delete light Fl G

48°25'52.0"N 058°29'09.2"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA476085, CA576086

(N2020006) LL(183) DFO(6308927-02)

01-MAY-2020

LNМ/D. 20-DEC-2019

Add light Fl Y

48°25'53.9"N 058°29'08.1"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA476085, CA576086

(N2020006) LL(183) DFO(6308927-03)

20-DEC-2019

LNМ/D. 09-MAR-2018

Delete light Fl R

48°30'29.3"N 058°32'16.7"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA476085, CA576088

(N2019112) LL(180.12) DFO(6308873-01)

14-JUL-2017

LNМ/D. 07-JUL-2017

Add depth of 9 metres, 8 decimetres
(See Chart No. 1, I10)

48°32'18.9"N 058°37'17.4"W

This notice affects Electronic Navigational Chart: CA476085

DFO(6307902-01)

14-JUL-2017

LNМ/D. 07-JUL-2017



Chart no. 4885

Add depth of 9 metres, 4 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476085	48°32'11.7"N 058°34'51.3"W <i>DFO(6307902-02)</i>
14-JUL-2017 Add depth of 27 metres, 9 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276138, CA476085	LNLM/D. 07-JUL-2017 48°30'21.1"N 058°39'41.0"W <i>DFO(6307902-03)</i>
14-JUL-2017 Add depth of 16 metres, 6 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276138, CA476085	LNLM/D. 07-JUL-2017 48°26'07.5"N 058°45'26.6"W <i>DFO(6307902-04)</i>
14-JUL-2017 Delete depth of 22 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476085	LNLM/D. 07-JUL-2017 48°26'13.5"N 058°42'30.0"W <i>DFO(6307902-05)</i>
14-JUL-2017 Add depth of 17 metres, 9 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476085	LNLM/D. 07-JUL-2017 48°26'08.6"N 058°42'26.1"W <i>DFO(6307902-06)</i>
14-JUL-2017 Add depth of 13 metres, 8 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476085	LNLM/D. 07-JUL-2017 48°24'12.3"N 058°39'57.5"W <i>DFO(6307902-07)</i>
14-JUL-2017 Add depth of 9 metres, 9 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476085	LNLM/D. 07-JUL-2017 48°26'39.3"N 058°34'02.3"W <i>DFO(6307902-08)</i>
14-JUL-2017	LNLM/D. 07-JUL-2017



Chart no. 4885

Replace depth of 13 metres, 1 decimetre with depth of 9 metres, 5 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476085

48°27'33.5"N 058°29'11.3"W
DFO(6307902-09)

14-JUL-2017

Replace depth of 19 metres, 2 decimetres with depth of 10 metres, 9 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138, CA476085

LNLM/D. 07-JUL-2017
48°27'28.6"N 058°29'03.4"W
DFO(6307902-10)

14-JUL-2017

Add depth of 14 metres, 9 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476085

LNLM/D. 07-JUL-2017
48°28'12.4"N 058°27'27.0"W
DFO(6307902-11)

16-JUL-2004

Delete rear range light, F R 24m

LNLM/D. 24-OCT-2003
48°25'34.7"N 058°29'18.0"W
(N2002027) LL(182) DFO(6301729-01)

16-JUL-2004

Delete front range light, F R 6m

LNLM/D. 24-OCT-2003
48°25'45.0"N 058°29'18.0"W
(N2002026) LL(181) DFO(6301729-02)

24-OCT-2003

Delete legend BELL against red and white fairway pillar light buoy Mo (A), BELL, marked XS

LNLM/D. 07-FEB-2003
48°29'44.0"N 058°32'52.4"W
(N2003018) LL(179.5) DFO(6300960-01)

07-FEB-2003

Amend depth of 2.4 metres to 24 metres

48°31'23.2"N 058°33'48.5"W
DFO(6300650-01)

07-FEB-2003



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4885

Amend depth of 3.7 metres to 37 metres 48°29'36.3"N 058°31'45.7"W

DFO(6300650-02)

4885 - St. George's Public Wharf / Quai public - New Edition - 08-MAR-2002 - NAD 1983

01-MAY-2020

LNМ/D. 20-DEC-2019

Add breakwater with legend Bkw
(See Chart No. 1, F4.1)
This notice affects Electronic Navigational Chart:
CA476085, CA576086

joining 48°25'52.2"N 058°29'09.7"W
48°25'52.6"N 058°29'10.1"W
and 48°25'53.9"N 058°29'08.1"W

DFO(6308927-01)

01-MAY-2020

LNМ/D. 20-DEC-2019

Delete light Fl G
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA476085, CA576086

48°25'52.4"N 058°29'09.4"W

(N2020006) LL(183) DFO(6308927-02)

01-MAY-2020

LNМ/D. 20-DEC-2019

Add light Fl Y
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA476085, CA576086

48°25'53.9"N 058°29'08.1"W

(N2020006) LL(183) DFO(6308927-03)