



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4886

### 4886 - Fish Plant Wharf / Quai de l'usine de transformation de poisson - New Chart - 26-DEC-1997 - NAD 1983

**14-APR-2023**

LNLM/D. 23-DEC-2022

Add green port hand lighted spar buoy Fl G, marked  
DT9

49°39'06.0"N 054°46'06.0"W

(See Chart 1, Qc)

(N2023001) LL(358.39) DFO(6310585-01)

This notice affects Electronic Navigational Chart:  
CA576425

**30-SEP-2022**

LNLM/D. 08-JUL-2022

Delete red starboard hand lighted spar buoy Fl R, marked  
DT12

49°38'58.8"N 054°45'58.8"W

(See Chart No. 1, Qf)

(N2022142) LL(358.6) DFO(6310255-01)

This notice affects Electronic Navigational Chart:  
CA576425

**30-SEP-2022**

LNLM/D. 08-JUL-2022

Add yellow cautionary lighted spar buoy Fl Y, marked DT  
(See Chart No. 1, Qm)

49°38'58.8"N 054°45'58.8"W

This notice affects Electronic Navigational Chart:  
CA576425

(N2022142) LL(358.6) DFO(6310255-02)

**08-JUL-2022**

LNLM/D. 07-AUG-2020

Delete green port hand lighted spar buoy Fl G, marked  
DT9

49°39'06.0"N 054°46'06.0"W

(See Chart No. 1, Qg)

(N2022077) LL(358.39) DFO(6310110-01)

This notice affects Electronic Navigational Chart:  
CA576425

**22-MAR-2019**

LNLM/D. 08-JAN-2016

Affix patch

49°39'00.0"N 054°46'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576425

DFO(6308592-01)

**08-JAN-2016**

LNLM/D. 20-NOV-2015

Delete green port hand lighted spar buoy FlG, marked  
DT5

49°39'01.2"N 054°46'05.4"W

(See Chart No. 1, Qg)

(N2015083) LL(358.193) DFO(6307405-01)

This notice affects Electronic Navigational  
Chart: CA576426



**Chart no. 4886**

**20-NOV-2015**

Reposition red starboard hand lighted spar buoy Fl R,  
marked DT12  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational  
Chart: CA576426

LNМ/D. 08-JUL-2011  
from 49°38'59.5"N 054°45'58.8"W  
to 49°38'58.8"N 054°45'58.8"W  
(N2015053) LL(358.6) DFO(6307280-01)

**20-NOV-2015**

Reposition red starboard hand lighted spar buoy Fl R,  
marked DT8  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational  
Chart: CA576425

LNМ/D. 08-JUL-2011  
from 49°39'06.6"N 054°46'06.5"W  
to 49°39'05.4"N 054°46'06.6"W  
(N2015056) LL(358.3) DFO(6307280-02)

**20-NOV-2015**

Reposition red starboard hand lighted spar buoy Fl R,  
marked DT10  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational  
Chart: CA576426

LNМ/D. 08-JUL-2011  
from 49°39'00.0"N 054°46'01.3"W  
to 49°39'01.2"N 054°46'03.0"W  
(N2015054) LL(358.4) DFO(6307280-03)

**20-NOV-2015**

Reposition green port hand lighted spar buoy Fl G,  
marked DT9  
(See Chart No. 1, Qg)

LNМ/D. 08-JUL-2011  
from 49°39'05.0"N 054°46'03.4"W  
to 49°39'06.0"N 054°46'06.0"W  
(N2015055) LL(358.39) DFO(6307280-04)

**20-NOV-2015**

Add green port hand lighted spar buoy Fl G, marked  
DT5  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart:  
CA576426

LNМ/D. 08-JUL-2011  
49°39'01.2"N 054°46'05.4"W  
(N2015058) LL(358.193) DFO(6307280-09)

**12-SEP-2008**

Delete green port hand lighted spar buoy Fl G, marked  
DT11  
(See Chart No 1 Qg)

LNМ/D. 27-MAY-2005  
49°39'03.5"N 054°46'01.9"W  
(N2008006) LL(358.5) DFO(6303959-01)



**Chart no. 4886**

**27-MAY-2005**

LNM/D. 07-MAY-2004

Add breakwater with loose boulders joining 49°39'06.5"N 054°46'01.6"W  
49°39'05.5"N 054°46'04.4"W  
49°39'05.7"N 054°46'04.9"W  
49°39'06.1"N 054°46'04.7"W  
49°39'07.1"N 054°46'02.0"W  
and 49°39'07.0"N 054°46'01.7"W

*(N2004025) LL(359.5) DFO(6301347-01)*

**27-MAY-2005**

LNM/D. 07-MAY-2004

Delete light FIG 49°39'03.8"N 054°46'00.5"W

*(N2004025) LL(359.5) DFO(6301347-02)*

**27-MAY-2005**

LNM/D. 07-MAY-2004

Add light FIG 49°39'05.8"N 054°46'04.6"W

*(N2004025) LL(359.5) DFO(6301347-03)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Delete red, starboard hand spar buoy, marked DT12 49°38'59.3"N 054°45'58.8"W

*(N2000-264) DFO(6829124-01)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Add red light, starboard hand spar buoy FIR, marked DT12 49°38'59.5"N 054°45'58.8"W

*(N2000-264) LL(358.600) DFO(6829124-02)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Add green light, port hand spar buoy FIG, marked DT9 49°39'05.0"N 054°46'03.4"W

*(N1999-055) LL(358.39) DFO(6829379-01)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Delete black, red, black, isolated danger spar buoy, marked DT 49°39'04.1"N 054°46'01.8"W

*(N1999-056) DFO(6829469-01)*



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4886

**20-APR-2001**

LNМ/D. 03-NOV-2000

Delete green, port hand spar buoy, marked DT11

49°39'04.2"N 054°46'04.2"W

*(N2000-169) LL(358.5) DFO(6828974-01)*

**20-APR-2001**

LNМ/D. 03-NOV-2000

Add green light, port hand spar buoy FIG, marked DT11

49°39'03.5"N 054°46'01.9"W

*(N2000-169) LL(358.5) DFO(6828974-02)*

**27-OCT-2000**

LNМ/D. 12-FEB-1999

Replace starboard hand spar buoy, marked DT8, with red  
light, starboard hand spar buoy Fl R, marked  
DT8

49°39'06.6"N 054°46'06.7"W

*(N2000-160) LL(358.3) DFO(6828965-01)*

**27-OCT-2000**

LNМ/D. 12-FEB-1999

Replace starboard hand spar buoy, marked DT10, with  
red light, starboard hand spar buoy Fl R, marked  
DT10

49°39'00.0"N 054°46'01.3"W

*(N2000-162) LL(358.4) DFO(6828967-01)*

### **4886 - Twillingate CCG Wharf / Quai GCC - New Chart - 26-DEC-1997 - NAD 1983**

**22-MAR-2019**

LNМ/D. 08-JAN-2016

Delete Coast guard station with rescue station  
(See Chart No 1. T11)

49°39'33.7"N 054°46'24.7"W

This notice affects Electronic Navigational Chart: CA576425

*DFO(6308592-03)*

**05-OCT-2001**

LNМ/D. 08-JUN-2001

Amend FR to read Fl R

49°39'32.0"N 054°46'18.7"W

*(N2001064) LL(359) DFO(6829565-01)*

### **4886 - Twillingate Harbours - New Chart - 26-DEC-1997 - NAD 1983**

**23-DEC-2022**

LNМ/D. 30-SEP-2022



### Chart no. 4886

Reposition red starboard hand lighted spar buoy Fl R,  
marked DUR6 from 49°40'00.8"N 054°44'39.0"W  
(See Chart 1, Qb) to 49°40'00.1"N 054°44'39.1"W  
This notice affects Electronic Navigational (N2022272) LL(361.33) DFO(6310476-01)  
Chart: CA576425

#### 23-DEC-2022

LNLM/D. 30-SEP-2022

Reposition green port hand lighted spar buoy Fl G,  
marked DUR1 from 49°40'08.5"N 054°44'13.2"W  
(See Chart 1, Qc) to 49°40'08.0"N 054°44'21.3"W  
This notice affects Electronic Navigational (N2022274) LL(361.1) DFO(6310479-01)  
Chart: CA576425

#### 23-DEC-2022

LNLM/D. 30-SEP-2022

Reposition green port hand lighted spar buoy Fl G,  
marked DUR3 from 49°40'04.0"N 054°44'31.0"W  
(See Chart 1, Qc) to 49°40'03.1"N 054°44'32.0"W  
This notice affects Electronic Navigational (N2022276) LL(361.2) DFO(6310496-01)  
Chart: CA576425

#### 30-SEP-2022

LNLM/D. 08-JUL-2022

Add green port hand lighted spar buoy Fl G, marked  
DUL7 from 49°39'47.2"N 054°44'13.5"W  
(See Chart No. 1, Qg) (N2022153) LL(361.63) DFO(6310246-01)  
This notice affects Electronic Navigational Chart:  
CA576425

#### 30-SEP-2022

LNLM/D. 08-JUL-2022

Add green port hand lighted spar buoy Fl G, marked  
DUL5 from 49°39'54.1"N 054°44'12.5"W  
(See Chart No. 1, Qg) (N2022154) LL(361.62) DFO(6310247-01)  
This notice affects Electronic Navigational Chart:  
CA576425

#### 30-SEP-2022

LNLM/D. 08-JUL-2022

Add red starboard hand lighted spar buoy Fl R, marked  
DUL4 from 49°40'01.9"N 054°44'09.2"W  
(See Chart No. 1, Qf) (N2022155) LL(361.61) DFO(6310248-01)  
This notice affects Electronic Navigational Chart:  
CA576425



### Chart no. 4886

**30-SEP-2022**

LNМ/D. 08-JUL-2022

Add green port hand lighted spar buoy Fl G, marked  
DUR1/3

49°40'05.2"N 054°44'24.9"W

(See Chart No. 1, Qg)

(N2022157) LL(361.52) DFO(6310250-01)

This notice affects Electronic Navigational Chart:  
CA576425

**30-SEP-2022**

LNМ/D. 08-JUL-2022

Add red starboard hand lighted spar buoy Fl R, marked  
DUR2

49°40'12.2"N 054°44'14.3"W

(See Chart No. 1, Qf)

(N2022158) LL(361.5) DFO(6310251-01)

This notice affects Electronic Navigational Chart:  
CA576425

**30-SEP-2022**

LNМ/D. 08-JUL-2022

Add red starboard hand lighted spar buoy Fl R, marked  
DUL2

49°40'31.9"N 054°44'05.8"W

(See Chart No. 1, Qf)

(N2022159) LL(361.4) DFO(6310252-01)

This notice affects Electronic Navigational Chart:  
CA576425

**30-SEP-2022**

LNМ/D. 08-JUL-2022

Add green port hand lighted spar buoy Fl G, marked  
DUL3

49°40'10.4"N 054°43'59.7"W

(See Chart No. 1, Qg)

(N2022200) LL(361.6) DFO(6310317-01)

This notice affects Electronic Navigational Chart:  
CA576425

**07-AUG-2020**

LNМ/D. 22-MAR-2019

Amend QG to read Fl G against light

49°38'40.0"N 054°46'18.0"W

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:  
CA376655, CA476804

(N2020044) LL(361) DFO(6309011-01)

**22-MAR-2019**

LNМ/D. 08-JAN-2016

Affix patch

49°39'00.0"N 054°46'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576425

DFO(6308592-01)

**08-JAN-2016**

LNМ/D. 20-NOV-2015



**Chart no. 4886**

Add green port hand lighted spar buoy FlG, marked DT5  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: CA576425

49°39'12.0"N 054°46'05.4"W  
(N2015083) LL(358.193) DFO(6307405-02)

**20-NOV-2015** LNM/D. 08-JUL-2011  
Reposition red starboard hand lighted spar buoy Fl R, marked DT8  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA576425

from 49°39'06.6"N 054°46'06.5"W  
to 49°39'05.4"N 054°46'06.6"W  
(N2015056) LL(358.3) DFO(6307280-02)

**20-NOV-2015** LNM/D. 08-JUL-2011  
Reposition red starboard hand lighted spar buoy Fl R, marked DT6  
(See Chart No. 1, Qf)  
This notice affects Electronic Navigational Chart: CA576425

from 49°39'11.3"N 054°46'09.0"W  
to 49°39'10.2"N 054°46'07.2"W  
(N2015057) LL(358.2) DFO(6307280-05)

**20-NOV-2015** LNM/D. 08-JUL-2011  
Delete green port hand lighted spar buoy Fl G, marked DT5  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: CA576425

49°39'12.0"N 054°46'04.0"W  
(N2015058) LL(358.193) DFO(6307280-06)

**20-NOV-2015** LNM/D. 08-JUL-2011  
Reposition green port hand lighted spar buoy Fl G, marked DT3  
(See Chart No. 1, Qg)  
This notice affects Electronic Navigational Chart: CA576425

from 49°39'17.5"N 054°46'04.4"W  
to 49°39'16.8"N 054°46'04.2"W  
(N2015059) LL(358.191) DFO(6307280-07)

**20-NOV-2015** LNM/D. 08-JUL-2011  
Reposition red starboard hand lighted spar buoy FR, marked DT2 and amend FR to read Fl R against light.  
(See Chart No. 1, Qf, P16)  
This notice affects Electronic Navigational Chart: CA576425

from 49°39'16.7"N 054°46'07.3"W  
to 49°39'17.4"N 054°46'07.8"W  
(N2015060) LL(358.1) DFO(6307280-08)



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

## Chart no. 4886

**08-JUL-2011**

Reposition red starboard hand lighted spar buoy FLR,  
marked DT4  
(See Chart No. 1, Qf)

LNМ/D. 12-SEP-2008

from 49°39'14.9"N 054°46'08.3"W  
to 49°39'13.6"N 054°46'06.7"W

*(N2011039) LL(358.192) DFO(6305545-01)*

**12-SEP-2008**

Delete green port hand lighted spar buoy FLG, marked  
DT11  
(See Chart No 1 Qg)

LNМ/D. 27-MAY-2005

49°39'03.5"N 054°46'01.9"W

*(N2008006) LL(358.5) DFO(6303959-01)*

**27-MAY-2005**

Add breakwater between 49°39'06.9"N 054°46'02.0"W  
and 49°39'05.7"N 054°46'04.6"W

LNМ/D. 07-MAY-2004

*(N2004025) LL(359.5) DFO(6301347-01)*

**27-MAY-2005**

Delete light FLG 49°39'03.8"N 054°46'00.5"W

LNМ/D. 07-MAY-2004

*(N2004025) LL(359.5) DFO(6301347-02)*

**27-MAY-2005**

Add light FLG 49°39'05.8"N 054°46'04.6"W

LNМ/D. 07-MAY-2004

*(N2004025) LL(359.5) DFO(6301347-03)*

**07-MAY-2004**

Reposition green port hand spar light buoy FLG,  
marked DT5

LNМ/D. 13-FEB-2004

from 49°39'14.6"N 054°46'04.8"W  
to 49°39'12.0"N 054°46'04.0"W

*(N2004021) LL(358.193) DFO(6301341-01)*

**13-FEB-2004**

Amend FLG to read QG against light

LNМ/D. 05-OCT-2001

49°38'40.0"N 054°46'18.1"W

*(N2002165) LL(361) DFO(6300751-01)*





Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

**Chart no. 4886**

**05-OCT-2001**

LNM/D. 08-JUN-2001

Amend FR to read Fl R

49°39'32.0"N 054°46'18.7"W

*(N2001064) LL(359) DFO(6829565-01)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Delete green, port hand can buoy, marked DT3

49°39'16.9"N 054°46'04.2"W

*(N2000-157) DFO(6828962-01)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Add green light, port hand spar buoy FIG, marked DT3

49°39'17.5"N 054°46'04.4"W

*(N2000-157) LL(358.191) DFO(6828962-02)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Delete green, port hand spar buoy, marked DUR5

49°39'57.4"N 054°44'39.7"W

*(N2000-165) DFO(6828970-01)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Add green light, port hand spar buoy FIG, marked  
DUR5

49°39'59.7"N 054°44'38.5"W

*(N2000-165) LL(361.320) DFO(6828970-02)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Delete red, starboard hand spar buoy, marked DT4

49°39'15.0"N 054°46'07.9"W

*(N2000-262) DFO(6829122-01)*

**08-JUN-2001**

LNM/D. 20-APR-2001

Add red light, starboard hand spar buoy FlR, marked  
DT4

49°39'14.9"N 054°46'08.3"W

*(N2000-262) LL(358.192) DFO(6829122-02)*

**08-JUN-2001**

LNM/D. 20-APR-2001



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4886

Delete green, port hand spar buoy, marked D9 49°40'28.8"N 054°45'59.4"W

*(N2000-263) DFO(6829123-01)*

#### 08-JUN-2001

LNM/D. 20-APR-2001

Add green light, port hand spar buoy FIG, marked D9

49°40'27.5"N 054°45'59.5"W

*(N2000-263) LL(358.110) DFO(6829123-02)*

#### 08-JUN-2001

LNM/D. 20-APR-2001

Add light Fl G

49°40'03.7"N 054°45'22.6"W

*(N2000285) LL(358.132) DFO(6829145-01)*

#### 20-APR-2001

LNM/D. 03-NOV-2000

Replace red starboard hand spar buoy, marked DUR4,  
with red light, starboard hand spar buoy Fl R,  
marked DUR4

49°40'03.6"N 054°44'33.0"W

*(N2000-164) LL(361.3) DFO(6828969-01)*

#### 20-APR-2001

LNM/D. 03-NOV-2000

Delete green, port hand spar buoy, marked DT11

49°39'04.2"N 054°46'04.2"W

*(N2000-169) LL(358.5) DFO(6828974-01)*

#### 20-APR-2001

LNM/D. 03-NOV-2000

Add green light, port hand spar buoy Fl G, marked DT11

49°39'03.5"N 054°46'01.9"W

*(N2000-169) LL(358.5) DFO(6828974-02)*

#### 03-NOV-2000

LNM/D. 27-OCT-2000

Replace starboard hand spar buoy, marked D4, with red  
light, starboard hand spar buoy, Fl R, marked  
D4

49°40'52.2"N 054°44'54.0"W

*(N2000-153) LL(358.15) DFO(6828958-01)*

#### 03-NOV-2000

LNM/D. 27-OCT-2000



**Chart no. 4886**

Replace starboard hand spar buoy, marked D8, with red light, starboard hand spar buoy, Fl R, marked D8  
49°40'45.0"N 054°45'43.2"W  
(N2000-154) LL(358.13) DFO(6828959-01)

**03-NOV-2000** LNM/D. 27-OCT-2000  
Delete green, port hand, spar buoy, marked D7  
49°40'40.1"N 054°45'36.0"W  
(N2000-155) LL(358.12) DFO(6828960-01)

**03-NOV-2000** LNM/D. 27-OCT-2000  
Add green light, port hand spar buoy Fl G, marked D7  
49°40'40.5"N 054°45'36.0"W  
(N2000-155) LL(358.12) DFO(6828960-02)

**03-NOV-2000** LNM/D. 27-OCT-2000  
Replace port hand spar buoy, marked D3, with green light, port hand spar buoy Fl G, marked D3  
49°40'49.2"N 054°44'40.2"W  
(N2000-156) LL(358.161) DFO(6828961-01)

**03-NOV-2000** LNM/D. 27-OCT-2000  
Replace port hand spar buoy, marked D1, with green light, port hand spar buoy Fl G, marked D1  
49°40'54.0"N 054°44'06.0"W  
(N2000-167) LL(358.17) DFO(6828972-01)

**03-NOV-2000** LNM/D. 27-OCT-2000  
Replace starboard hand spar buoy, marked D2, with red light, starboard hand spar buoy Fl R, marked D2  
49°41'01.2"N 054°44'08.0"W  
(N2000-168) LL(358.16) DFO(6828973-01)

**03-NOV-2000** LNM/D. 27-OCT-2000  
Replace port hand spar buoy, marked D5, with green light, port hand spar buoy, Fl G, marked D5  
49°40'45.8"N 054°45'04.2"W  
(N2000-170) LL(358.159) DFO(6828975-01)

**03-NOV-2000** LNM/D. 27-OCT-2000



**Chart no. 4886**

Replace starboard hand spar buoy, marked D6, with red light, starboard hand spar buoy, Fl R, marked D6  
49°40'47.0"N 054°45'15.0"W  
(N2000-171) LL(358.14) DFO(6828976-01)

**27-OCT-2000** LNM/D. 12-FEB-1999  
Replace port hand spar buoy, marked DT5, with green light, port hand spar buoy Fl G, marked DT5  
49°39'14.3"N 054°46'04.8"W  
(N2000-158) LL(358.193) DFO(6828963-01)

**27-OCT-2000** LNM/D. 12-FEB-1999  
Replace starboard hand spar buoy, marked DT6, with red light, starboardhand spar buoy Fl R, marked DT6  
49°39'11.4"N 054°46'09.0"W  
(N2000-159) LL(358.2) DFO(6828964-01)

**27-OCT-2000** LNM/D. 12-FEB-1999  
Replace starboard hand spar buoy, marked DT8, with red light, starboard hand spar buoy Fl R, marked DT8  
49°39'06.6"N 054°46'06.7"W  
(N2000-160) LL(358.3) DFO(6828965-01)

**27-OCT-2000** LNM/D. 12-FEB-1999  
Replace port hand spar buoy, marked DUR3, with green light, port hand spar buoy Fl G, marked DUR3  
49°40'03.8"N 054°44'31.0"W  
(N2000-163) LL(361.2) DFO(6828968-01)

**27-OCT-2000** LNM/D. 12-FEB-1999  
Replace starboard hand spar buoy, marked DUR6, with red light, starboard hand spar buoy Fl R, marked DUR6  
49°40'01.0"N 054°44'39.0"W  
(N2000-166) LL(361.33) DFO(6828971-01)