



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

4905 - Borden - New Edition - 29-DEC-2000 - NAD 1983

28-APR-2017

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA376076, CA576077, CA576078

LNM/D. 30-DEC-2016
joining 46°14'24.2"N 063°41'45.0"W
46°14'27.4"N 063°41'43.9"W
and 46°14'51.5"N 063°41'28.2"W

DFO(6307888-01)

28-APR-2017

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA576077, CA576078

LNM/D. 30-DEC-2016
between 46°14'24.2"N 063°41'35.4"W
and 46°14'50.2"N 063°41'27.7"W

DFO(6307888-02)

17-AUG-2012

Delete depth of 4 metres, 8 decimetres
(See Chart No. 1, I10)

LNM/D. 10-AUG-2012
46°14'42.0"N 063°41'57.5"W

DFO(6306117-01)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

Delete depth of 6 metres, 4 decimetres
(See Chart No. 1, I10)

LNM/D. 10-AUG-2012
46°14'40.7"N 063°41'36.3"W

DFO(6306117-02)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

Delete depth of 7 metres
(See Chart No. 1, I10)

LNM/D. 10-AUG-2012
46°14'38.2"N 063°41'39.9"W

DFO(6306117-03)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

Delete depth of 7 metres, 9 decimetres
(See Chart No. 1, I10)

LNM/D. 10-AUG-2012
46°14'32.8"N 063°41'28.5"W

DFO(6306117-04)

This notice affects Electronic Navigational Chart: CA576077



Chart no. 4905

17-AUG-2012

LNM/D. 10-AUG-2012

Delete depth of 9 metres, 1 decimetre
(See Chart No. 1, I10)

46°14'33.1"N 063°41'45.8"W

DFO(6306117-05)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

LNM/D. 10-AUG-2012

Add depth of 4 metres
(See Chart No. 1, I10)

46°14'42.0"N 063°41'57.5"W

DFO(6306117-06)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

LNM/D. 10-AUG-2012

Add depth of 5 metres, 4 decimetres
(See Chart No. 1, I10)

46°14'40.8"N 063°41'36.3"W

DFO(6306117-07)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

LNM/D. 10-AUG-2012

Add depth of 3 metres, 7 decimetres
(See Chart No. 1, I10)

46°14'41.5"N 063°41'38.6"W

DFO(6306117-08)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

LNM/D. 10-AUG-2012

Add depth of 5 metres, 7 decimetres
(See Chart No. 1, I10)

46°14'38.2"N 063°41'39.8"W

DFO(6306117-09)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

LNM/D. 10-AUG-2012

Add depth of 4 metres, 6 decimetres
(See Chart No. 1, I10)

46°14'35.9"N 063°41'43.2"W

DFO(6306117-10)

This notice affects Electronic Navigational Chart: CA576077



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

17-AUG-2012

Add depth of 7 metres, 5 decimetres
(See Chart No. 1, I10)

LNМ/D. 10-AUG-2012

46°14'33.1"N 063°41'45.8"W

DFO(6306117-11)

This notice affects Electronic Navigational Chart: CA576077

17-AUG-2012

Add depth of 6 metres, 9 decimetres
(See Chart No. 1, I10)

LNМ/D. 10-AUG-2012

46°14'32.8"N 063°41'28.5"W

DFO(6306117-12)

This notice affects Electronic Navigational Chart: CA576077

4905 - Cape Tormentine - New Edition - 29-DEC-2000 - NAD 1983

25-NOV-2022

Amend Fl G to read Fl G 4s6m against light
(See Chart 1, P16)

LNМ/D. 05-NOV-2021

46°08'02.9"N 063°46'11.7"W

This notice affects Electronic Navigational Chart: *(G2022115) LL(1091.5) DFO(6310373-01)*
CA376076, CA576078

28-JUN-2019

Reposition green port hand spar buoy, marked XD11
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA576078

LNМ/D. 21-JUN-2019

from 46°07'58.0"N 063°46'32.0"W
to 46°08'00.8"N 063°46'33.0"W

(G2019032) DFO(6308658-01)

28-APR-2017

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA376076, CA576077, CA576078

LNМ/D. 30-DEC-2016

between 46°07'32.7"N 063°47'01.7"W
and 46°07'50.2"N 063°45'57.7"W

DFO(6307888-01)

28-APR-2017

Add submarine cable
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart:
CA576077, CA576078

LNМ/D. 30-DEC-2016

between 46°07'32.5"N 063°47'01.6"W
and 46°07'46.3"N 063°45'57.7"W

DFO(6307888-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

30-DEC-2016

Delete radar reflector

(See Chart No. 1, S4)

This notice affects Electronic Navigational Chart: CA576078 LL(1091.5) DFO(6307805-02)

LNM/D. 16-DEC-2016

46°08'02.9"N 063°46'11.7"W

28-SEP-2007

Reposition green port hand spar buoy, marked XD11

from 46°07'53.8"N 063°46'30.2"W

to 46°07'58.0"N 063°46'32.0"W

(G2007103) LL(6094.9) DFO(6303567-01)

LNM/D. 27-JUL-2007

23-DEC-2005

Amend "FLY" to read "FIG" against light

LNM/D. 26-NOV-2004

46°08'02.7"N 063°46'11.8"W

(G2004167) LL(1091.5) DFO(6302594-01)

18-JUL-2003

Add red starboard hand spar light buoy FIR, marked XD4

LNM/D. 06-JUN-2003

46°08'09.0"N 063°46'11.6"W

(G2003032) LL(1095.1) DFO(6300916-01)

18-JUL-2003

Add green port hand spar light buoy QG, marked XD5

LNM/D. 06-JUN-2003

46°07'58.0"N 063°46'25.5"W

(G2003033) LL(1096) DFO(6300917-01)

4905 - Cape Tormentine à / to West Point - New Edition - 29-DEC-2000 - NAD 1983

23-JUN-2023

Add wreck showing a portion of superstructure with legend ED Rep
(2021)

(See Chart 1, K24, I1, I3)

This notice affects Electronic Navigational Chart: CA276286,
CA376076, CA476128

LNM/D. 25-NOV-2022

46°21'25.8"N 064°31'44.4"W

DFO(6310706-01)

25-NOV-2022

LNM/D. 05-NOV-2021



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

Amend Fl G 3s6m to read Fl G 4s6m against light
(See Chart 1, P16) 46°08'02.8"N 063°46'11.8"W

This notice affects Electronic Navigational Chart: (G2022115) LL(1091.5) DFO(6310373-01)
CA376076, CA576078

25-NOV-2022

LNМ/D. 05-NOV-2021

Add depth of 0.3 metres
(See Chart 1, I10)

46°17'08.6"N 064°32'35.9"W

This notice affects Electronic Navigational Chart: CA376076,
CA476128

DFO(6310444-01)

25-NOV-2022

LNМ/D. 05-NOV-2021

Add depth of 0.2 metres
(See Chart 1, I10)

46°16'34.5"N 064°34'03.4"W

This notice affects Electronic Navigational Chart: CA376076,
CA476128

DFO(6310444-08)

05-NOV-2021

LNМ/D. 16-JUL-2021

Delete light Fl Y(2) 12s 14m 10M
(See Chart No. 1, P1)

46°19'12.0"N 064°30'45.0"W

This notice affects Electronic Navigational Chart: (G2021136) LL(1113) DFO(6309643-01)
CA276286, CA376076, CA476128

05-NOV-2021

LNМ/D. 16-JUL-2021

Add abandoned lighthouse with legend LtHo (disused) /
LtHo (désaffecté)

46°19'12.0"N 064°30'45.0"W

(See Chart No. 1, P1)

(G2021136) LL(1113) DFO(6309643-02)

This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

05-NOV-2021

LNМ/D. 16-JUL-2021

Reposition green port hand lighted spar buoy Fl G,
marked XW1

from 46°32'21.5"N 064°41'34.3"W
to 46°32'26.9"N 064°41'44.6"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational
Chart: CA376076

(G2021172) LL(1126.1) DFO(6309690-01)

05-NOV-2021

LNМ/D. 16-JUL-2021



Chart no. 4905

Reposition red starboard hand lighted spar buoy Fl R,
marked XW2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA376076

from 46°32'25.6"N 064°41'40.6"W
to 46°32'27.8"N 064°41'45.2"W

(G2021173) LL(1126.2) DFO(6309691-01)

16-JUL-2021

Add green port hand lighted spar buoy Fl G, marked
XW1
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart:
CA376076

LNМ/D. 26-FEB-2021
46°32'21.5"N 064°41'34.3"W
(G2021043) LL(1126.1) DFO(6309473-01)

16-JUL-2021

Add red starboard hand lighted spar buoy Fl R, marked
XW2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA376076

LNМ/D. 26-FEB-2021
46°32'25.6"N 064°41'40.6"W
(G2021044) LL(1126.2) DFO(6309474-01)

26-FEB-2021

Delete front range/leading light F Y 6m
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart:
CA376076

LNМ/D. 09-OCT-2020
46°26'54.0"N 064°06'19.5"W
(G2020228) LL(1026) DFO(6309269-01)

26-FEB-2021

Delete rear range/leading light F Y 10m with leading line
and bearing 286° and 106°
(See Chart No. 1, P20.2, Pe)
This notice affects Electronic Navigational Chart:
CA376076

LNМ/D. 09-OCT-2020
46°26'52.5"N 064°06'11.5"W
(G2020229) LL(1027) DFO(6309270-01)

26-FEB-2021

Add light Fl R
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA276286, CA376076

LNМ/D. 09-OCT-2020
46°13'28.6"N 064°22'58.4"W
(G2020268) LL(1103.5) DFO(6309345-01)

09-OCT-2020

LNМ/D. 07-AUG-2020



Chart no. 4905

Add red and white fairway lighted spar buoy Mo(A),
marked DH
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart:
CA376076

46°27'18.7"N 064°08'25.9"W
(G2020166) LL(1023) DFO(6309192-01)

09-OCT-2020 LNM/D. 07-AUG-2020
Delete red starboard hand lighted spar buoy Fl R, marked DH2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA376076 LL(1023.1) DFO(6309192-02)

46°27'09.7"N 064°07'42.9"W

07-AUG-2020 LNM/D. 06-MAR-2020
Delete red starboard hand lighted pillar buoy Fl R, marked
XT2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

46°23'31.0"N 064°33'08.0"W
(G2020048) LL(1115) DFO(6309014-01)

07-AUG-2020 LNM/D. 06-MAR-2020
Add red and white fairway lighted conical buoy Mo(A),
marked XT
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

46°23'19.7"N 064°32'38.5"W
(G2020049) LL(1115.1) DFO(6309015-01)

07-AUG-2020 LNM/D. 06-MAR-2020
Delete front range/leading light 2 Lts F R
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart:
CA376076, CA476128

46°14'28.3"N 064°30'40.6"W
(G2020070) LL(1107) DFO(6309044-01)

07-AUG-2020 LNM/D. 06-MAR-2020
Delete rear range/leading light with leading line
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart:
CA376076, CA476128

46°14'22.5"N 064°30'42.0"W
(G2020071) LL(1108) DFO(6309045-01)

07-AUG-2020 LNM/D. 06-MAR-2020



Chart no. 4905

Reposition red starboard hand lighted pillar buoy Q R, marked DG2 from 46°24'06.3"N 064°08'29.8"W
marked DG2 to 46°24'09.8"N 064°08'46.5"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA376076 (G2020079) LL(1024.5) DFO(6309047-01)

07-AUG-2020

Delete red starboard hand lighted pillar buoy Fl R, marked XT4 LNM/D. 06-MAR-2020
marked XT4 46°22'24.0"N 064°34'08.0"W
(See Chart No. 1, Qf) (G2020038) LL(1114.2) DFO(6309129-01)
This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128

07-AUG-2020

Add red starboard hand lighted conical buoy Fl R, marked XT4 LNM/D. 06-MAR-2020
marked XT4 46°22'28.4"N 064°34'01.0"W
(See Chart No. 1, Qf) (G2020038) LL(1113.04) DFO(6309129-02)
This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128

06-MAR-2020

Add depth of 0.6 metres LNM/D. 07-FEB-2020
(See Chart No. 1, I10) 46°18'20.4"N 063°46'36.7"W
This notice affects Electronic Navigational Chart: CA376076 DFO(6308890-04)

06-MAR-2020

Delete depth of 3.4 metres LNM/D. 07-FEB-2020
(See Chart No. 1, I10) 46°18'15.9"N 063°46'42.3"W
This notice affects Electronic Navigational Chart: CA376076 DFO(6308890-06)

06-MAR-2020

Add depth of 0.3 metres LNM/D. 07-FEB-2020
(See Chart No. 1, I10) 46°18'50.3"N 063°48'02.1"W
This notice affects Electronic Navigational Chart: CA376076 DFO(6308890-07)

06-MAR-2020

Add drying height of 0.5 metres LNM/D. 07-FEB-2020
(See Chart No. 1, I15) 46°16'49.2"N 063°43'47.3"W
This notice affects Electronic Navigational Chart: CA376076 DFO(6308890-11)



Chart no. 4905

06-MAR-2020

LNМ/D. 07-FEB-2020

Delete depth of 1.4 metres
(See Chart No. 1, I10)

46°16'51.4"N 063°44'00.5"W

This notice affects Electronic Navigational Chart: CA376076

DFO(6308890-13)

06-MAR-2020

LNМ/D. 07-FEB-2020

Add depth of 1.2 metres
(See Chart No. 1, I10)

46°16'45.8"N 063°44'06.2"W

This notice affects Electronic Navigational Chart: CA376076

DFO(6308890-14)

06-MAR-2020

LNМ/D. 07-FEB-2020

Add drying height of 0.3 metres
(See Chart No. 1, I15)

46°12'57.8"N 063°37'41.6"W

This notice affects Electronic Navigational Chart: CA376076

DFO(6308890-18)

07-FEB-2020

LNМ/D. 08-NOV-2019

Amend QG to read Fl G against light
(See Chart No. 1, P16)

46°24'24.7"N 064°08'04.8"W

This notice affects Electronic Navigational Chart: (G2019146) LL(1025.5) DFO(6308912-01)
CA276286, CA376076

08-NOV-2019

LNМ/D. 28-JUN-2019

Add depth of 3.5 metres
(See Chart No. 1, I10)

46°10'46.5"N 063°49'31.3"W

This notice affects Electronic Navigational Chart: CA376076

DFO(6308734-01)

08-NOV-2019

LNМ/D. 28-JUN-2019

Delete depth of 3.7 metres
(See Chart No. 1, I10)

46°10'19.0"N 063°54'22.0"W

This notice affects Electronic Navigational Chart: CA376076

DFO(6308734-05)

08-NOV-2019

LNМ/D. 28-JUN-2019

Add depth of 2.9 metres
(See Chart No. 1, I10)

46°10'22.8"N 063°54'18.7"W

This notice affects Electronic Navigational Chart: CA376076

DFO(6308734-06)

08-NOV-2019

LNМ/D. 28-JUN-2019



Chart no. 4905

Add depth of 3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376076	46°11'13.6"N 063°58'37.4"W <i>DFO(6308734-10)</i>
08-NOV-2019 Delete depth of 3.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376076	LNM/D. 28-JUN-2019 46°11'10.2"N 063°58'32.8"W <i>DFO(6308734-11)</i>
08-NOV-2019 Replace depth of 6.1 metres with depth of 5.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376076	LNM/D. 28-JUN-2019 46°11'43.6"N 063°59'48.1"W <i>DFO(6308734-14)</i>
08-NOV-2019 Add depth of 8.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376076	LNM/D. 28-JUN-2019 46°12'13.9"N 063°59'56.2"W <i>DFO(6308734-15)</i>
08-NOV-2019 Delete depth of 2.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286, CA376076	LNM/D. 28-JUN-2019 46°06'06.1"N 063°43'50.7"W <i>DFO(6308734-17)</i>
08-NOV-2019 Add depth of 1.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286, CA376076	LNM/D. 28-JUN-2019 46°06'05.9"N 063°43'55.0"W <i>DFO(6308734-18)</i>
08-NOV-2019 Add depth of 2.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286, CA376076	LNM/D. 28-JUN-2019 46°03'38.5"N 063°51'23.5"W <i>DFO(6308734-20)</i>
08-NOV-2019	LNM/D. 28-JUN-2019



Chart no. 4905

Delete depth of 3.4 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376076

46°03'33.4"N 063°51'23.6"W
DFO(6308734-21)

08-NOV-2019

Replace depth of 2.1 metres with depth of 1.4 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376076

LNМ/D. 28-JUN-2019
46°05'08.7"N 063°46'34.7"W
DFO(6308734-26)

28-JUN-2019

Reposition red starboard hand lighted spar buoy Fl R,
marked XK2
(See Chart No. 1, Qf)
This notice affects Electronic Navigational
Chart: CA376076

LNМ/D. 21-JUN-2019
from 46°13'45.0"N 064°22'32.5"W
to 46°14'00.7"N 064°22'42.7"W
(G2019033) LL(1102.3) DFO(6308659-01)

28-JUN-2019

Delete red starboard hand lighted pillar buoy QR,
marked XK6
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA376076

LNМ/D. 21-JUN-2019
46°13'45.0"N 064°22'43.6"W
(G2019034) LL(1102.5) DFO(6308660-01)

28-JUN-2019

Add Channel Buoyed/Chenal balisé
This notice affects Electronic Navigational Chart: CA376076

LNМ/D. 21-JUN-2019
46°14'11.1"N 064°23'07.9"W
DFO(6308660-02)

28-JUN-2019

Reposition red and white fairway lighted pillar buoy
Mo(A), marked DJ
(See Chart No. 1, Qh)
This notice affects Electronic Navigational
Chart: CA276286, CA376076

LNМ/D. 21-JUN-2019
from 46°33'21.0"N 064°07'28.0"W
to 46°33'23.1"N 064°06'38.5"W
(G2019039) LL(1027.45) DFO(6308666-01)

21-JUN-2019

LNМ/D. 08-FEB-2019



Chart no. 4905

Add wreck, least depth unknown, dangerous to surface navigation with legend Rep (2011) 46°24'50.4"N 064°16'31.2"W
(See Chart No. 1, K28, I3.1) *DFO(6308664-01)*
This notice affects Electronic Navigational Chart: CA376076

08-FEB-2019 LNM/D. 17-AUG-2018
Amend Iso R to read Fl R against light 46°10'06.0"N 063°55'58.0"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2019001) LL(1097) *DFO(6308551-01)*
CA276286, CA376076

17-AUG-2018 LNM/D. 20-JUL-2018
Delete red and white fairway lighted pillar bell buoy 46°16'53.7"N 064°30'03.6"W
Mo(A), marked XN
(See Chart No. 1, Qh) *(G2018067) LL(1105) DFO(6308310-01)*
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

17-AUG-2018 LNM/D. 20-JUL-2018
Add red and white fairway lighted pillar bell buoy Mo(A), 46°16'38.0"N 064°29'05.0"W
marked XN
(See Chart No. 1, Qh) *(G2018067) LL(1105) DFO(6308310-02)*
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128

17-AUG-2018 LNM/D. 20-JUL-2018
Add light Fl G against green port hand 46°20'48.0"N 063°51'23.0"W
can buoy, marked DE1
(See Chart No. 1, Q7) *(G2018075 & G2018085) LL(1018.18) DFO(6308334-01)*
This notice affects Electronic
Navigational Chart: CA376076,
CA476181

17-AUG-2018 LNM/D. 20-JUL-2018
Delete legend BELL against red and white fairway lighted 46°19'51.0"N 063°51'18.8"W
pillar bell buoy Mo(A), marked DE
(See Chart No. 1, R21) *(G2018104) LL(1023) DFO(6308382-01)*
This notice affects Electronic Navigational Chart:
CA376076, CA476181

20-JUL-2018 LNM/D. 11-MAY-2018



Chart no. 4905

Delete white and orange information lighted pillar buoy
Fl Y, marked DC
(See Chart No. 1, Qp)
This notice affects Electronic Navigational Chart:
CA376076

46°18'22.0"N 063°49'57.0"W
(G2018070) LL(1017.8) DFO(6308317-01)

20-JUL-2018

Delete white and orange information lighted pillar buoy
Fl Y, marked DD
(See Chart No. 1, Qp)
This notice affects Electronic Navigational Chart:
CA376076, CA476181

LNLM/D. 11-MAY-2018
46°18'46.0"N 063°49'25.0"W
(G2018071) LL(1017.9) DFO(6308318-01)

11-MAY-2018

Delete pilot boarding station
(See Chart No. 1, T1.1)
This notice affects Electronic Navigational Chart: CA276286,
CA376076

LNLM/D. 16-FEB-2018
46°31'26.2"N 064°31'56.9"W
DFO(6308253-01)

11-MAY-2018

Delete pilot boarding station
(See Chart No. 1, T1.1)
This notice affects Electronic Navigational Chart: CA276286,
CA376076

LNLM/D. 16-FEB-2018
46°17'00.0"N 064°24'57.0"W
DFO(6308253-02)

16-FEB-2018

Delete front range/leading light FY 5m
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart: CA276286, CA376076

LNLM/D. 02-FEB-2018
46°34'59.1"N 064°43'20.9"W
(G2018001) LL(1127.5) DFO(6308199-01)

16-FEB-2018

Delete rear range/leading light FY 7m, with leading line
and bearing 091° and 271°
(See Chart No. 1, P20.2, Pe)
This notice affects Electronic Navigational Chart:
CA276286, CA376076

LNLM/D. 02-FEB-2018
46°34'58.8"N 064°43'26.6"W
(G2018002) LL(1127.6) DFO(6308199-02)

02-FEB-2018

LNLM/D. 14-JUL-2017



Chart no. 4905

Delete rear range/leading light with leading line 46°20'01.0"N 064°37'00.0"W
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart: (G2017124) LL(1117) DFO(6308197-01)
CA376076, CA476128

02-FEB-2018 LNM/D. 14-JUL-2017
Delete front range/leading light 2Lts FY 46°20'07.0"N 064°36'52.7"W
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart: (G2017125) LL(1116) DFO(6308198-01)
CA376076, CA476128

14-JUL-2017 LNM/D. 28-APR-2017
Replace red starboard hand lighted pillar buoy Q R, marked XN12 46°15'28.5"N 064°30'28.7"W
with red starboard hand lighted spar buoy Q R, marked XN12
(See Chart No. 1, Qf) DFO(6307944-06)
This notice affects Electronic Navigational Chart: CA376076,
CA476128

14-JUL-2017 LNM/D. 28-APR-2017
Reposition red starboard hand lighted spar buoy Q R, from 46°15'28.5"N 064°30'28.7"W
marked XN12 to 46°15'26.8"N 064°30'34.6"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA376076, CA476128 (G2017037) LL(1106) DFO(6307944-07)

28-APR-2017 LNM/D. 30-DEC-2016
Add submarine cable joining 46°07'32.5"N 063°47'02.0"W
(See Chart No. 1, L30.1) 46°07'56.0"N 063°45'26.5"W
This notice affects Electronic Navigational Chart: 46°08'21.0"N 063°44'47.0"W
CA376076, CA576077, CA576078 46°08'42.4"N 063°44'41.0"W
46°09'29.3"N 063°45'05.0"W
46°12'03.5"N 063°43'52.4"W
46°12'51.0"N 063°42'14.0"W
and 46°14'52.5"N 063°41'27.4"W
DFO(6307888-01)

30-DEC-2016 LNM/D. 16-DEC-2016
Amend FLG to read FLG 3s6m against light 46°08'02.9"N 063°46'11.7"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376076 LL(1091.5) DFO(6307805-01)



Chart no. 4905

16-DEC-2016

LNМ/D. 10-JUN-2016

Amend LFlG to read Fl G against light
(See Chart No. 1, P16)

46°37'04.1"N 064°22'17.7"W

This notice affects Electronic Navigational Chart: (G2016134) LL(1028.2) DFO(6307735-01)
CA376076

10-JUN-2016

LNМ/D. 27-NOV-2015

Add light FlG

46°34'56.7"N 064°43'10.2"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (G2016028) LL(1127.2) DFO(6307503-01)
CA276286, CA376076

27-NOV-2015

LNМ/D. 19-JUN-2015

Add breakwater

between 46°28'30.5"N 064°42'40.6"W
and 46°28'30.5"N 064°42'52.3"W

(See Chart No. 1, F4.1)

This notice affects Electronic Navigational Chart:
CA376076, CA476127

DFO(6307341-01)

19-JUN-2015

LNМ/D. 24-APR-2015

Amend FlG to read QG against light
(See Chart No. 1, P16)

46°24'24.0"N 064°08'05.3"W

This notice affects Electronic Navigational Chart: (G2015038) LL(1025.5) DFO(6307141-01)
CA276286, CA376076

24-APR-2015

LNМ/D. 07-NOV-2014

Delete light Fl

46°27'23.5"N 064°39'02.6"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (G2015012) LL(1120) DFO(6307091-01)
CA376076, CA476127

07-NOV-2014

LNМ/D. 31-OCT-2014

Add black, yellow and black East cardinal lighted spar
buoy VQ(3) 5s, marked XVA

46°27'23.2"N 064°35'41.5"W

(See Chart No. 1, Q130.3)

This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476127

(G2014151) LL(1119.2) DFO(6306917-02)

31-OCT-2014

LNМ/D. 17-OCT-2014



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

Delete red starboard hand lighted pillar buoy FIR,
marked XV2

46°27'03.0"N 064°35'45.0"W

(See Chart No. 1, Qf)

(G2014076) LL(1119.55) DFO(6306899-01)

This notice affects Electronic Navigational
Chart: CA276286, CA376076, CA476127

17-OCT-2014

LNМ/D. 06-SEP-2013

Delete green port hand lighted pillar bell buoy BELL,
FlG marked X17

46°31'36.0"N 064°32'54.0"W

(See Chart No. 1, Qg)

(G2014075) LL(1125.5) DFO(6306898-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376076

06-SEP-2013

LNМ/D. 29-MAR-2013

Add marine farm

46°30'06.0"N 064°40'22.0"W

(See Chart No. 1, K48.2)

This notice affects Electronic Navigational Chart: CA376076,
CA476127

DFO(6306421-01)

29-MAR-2013

LNМ/D. 17-AUG-2012

Add legend "Channel Buoyed/Chenal balisé" 46°26'52.2"N 064°07'53.5"W

DFO(6306340-01)

29-MAR-2013

LNМ/D. 17-AUG-2012

Delete red starboard hand lighted spar buoy FIR, marked DH6 46°27'05.1"N 064°07'18.0"W
(See Chart No. 1, Qf)

LL(1023.2) DFO(6306340-02)

29-MAR-2013

LNМ/D. 17-AUG-2012

Delete red starboard hand lighted spar buoy FIR, marked DH8 46°26'48.6"N 064°06'56.4"W
(See Chart No. 1, Qf)

LL(1023.6) DFO(6306340-03)

10-AUG-2012

LNМ/D. 20-JUL-2012

Delete depth of 2 metres, 1 decimetre
(See Chart No. 1, I10)

46°21'25.3"N 064°35'19.0"W

DFO(6306113-05)

This notice affects Electronic Navigational Chart: CA376076



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

10-AUG-2012

Add depth of 1 metre, 5 decimetres
(See Chart No. 1, I10)

LNМ/D. 20-JUL-2012
46°21'27.3"N 064°35'18.8"W

DFO(6306113-11)

This notice affects Electronic Navigational Chart: CA376076

20-JUL-2012

Amend F RWG to read FlG against light
(See Chart No. 1, P1)

LNМ/D. 23-MAR-2012
46°26'25.9"N 064°06'48.4"W

(G2012108) LL(1027.3) DFO(6306066-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376076

23-MAR-2012

Delete red and white fairway lighted pillar buoy Mo(A),
marked XE
(See Chart No. 1, Qh)

LNМ/D. 02-MAR-2012
46°11'18.2"N 064°03'26.7"W

(G2012015) LL(1097.8) DFO(6305950-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376076

23-MAR-2012

Delete wharf
(See Chart No. 1, F14)

LNМ/D. 02-MAR-2012
joining 46°09'56.1"N 064°03'57.2"W
46°09'58.0"N 064°03'59.5"W
46°09'58.0"N 064°04'05.1"W
and 46°09'54.0"N 064°04'05.1"W

This notice affects Electronic Navigational Chart:
CA376076

DFO(6305951-01)

02-MAR-2012

Amend FLY 5s 13m 13M to read Fl 5s 13m 11M against
light
(See Chart No. 1, P1)

LNМ/D. 10-FEB-2012
46°14'04.3"N 064°15'49.6"W

(G2012011) LL(1101) DFO(6305930-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376076



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

10-FEB-2012

LNМ/D. 20-JAN-2012

Delete front range/leading light F R 4m
(See Chart No. 1, P20.2)

46°26'27.9"N 064°06'35.2"W

(G2012003) LL(1027.1) DFO(6305910-01)

10-FEB-2012

LNМ/D. 20-JAN-2012

Delete rear range/leading light F R 8m with leading line
and bearing 144°
324°
(See Chart No. 1, P20.2)

46°26'23.0"N 064°06'30.0"W

(G2012004) LL(1027.2) DFO(6305911-01)

20-JAN-2012

LNМ/D. 28-OCT-2011

Delete red starboard hand lighted pillar buoy QR,
marked XE2
(See Chart No. 1, Qf)

46°10'36.2"N 064°03'35.7"W

(G2011332) LL(1097.4) DFO(6305885-01)

20-JAN-2012

LNМ/D. 28-OCT-2011

Delete legend Balisé/Buoyed 46°10'21.0"N 064°04'27.0"W

DFO(6305885-02)

28-OCT-2011

LNМ/D. 01-JUL-2011

Delete red starboard hand lighted spar buoy F1R,
marked DH2/4
(See Chart No. 1, Qf)

46°27'05.3"N 064°07'18.7"W

(G2011288) LL(1023.2) DFO(6305783-01)

28-OCT-2011

LNМ/D. 01-JUL-2011

Add red starboard hand lighted spar buoy F1R, marked
DH6
(See Chart No. 1, Qf)

46°27'05.1"N 064°07'18.0"W

(G2011288) LL(1023.2) DFO(6305783-02)

01-JUL-2011

LNМ/D. 17-JUN-2011

Reposition red starboard hand lighted pillar buoy F1R,
marked XT4
(See Chart No. 1, Qf)

from 46°22'24.5"N 064°34'10.0"W
to 46°22'22.9"N 064°34'08.6"W

(G2011163) LL(1114.2) DFO(6305538-01)



Chart no. 4905

17-JUN-2011 LNM/D. 10-JUN-2011
Delete light LFlG 46°37'06.0"N 064°22'17.0"W
(See Chart No. 1, P1)
LL(1028.2) DFO(6305506-01)

17-JUN-2011 LNM/D. 10-JUN-2011
Add extension to wharf between 46°37'04.1"N 064°22'19.4"W
(See Chart 1 F14) and 46°37'04.1"N 064°22'17.7"W
DFO(6305506-02)

17-JUN-2011 LNM/D. 10-JUN-2011
Add light LFlG 46°37'04.1"N 064°22'17.7"W
(See Chart No. 1, P1)
LL(1028.2) DFO(6305506-03)

10-JUN-2011 LNM/D. 10-DEC-2010
Delete green port hand lighted pillar buoy Q G, marked Q3 46°42'31.1"N 064°44'40.5"W
(See Chart No. 1, Qg)
(G2011126) LL(1132) DFO(6305483-01)

This notice affects Electronic Navigational Chart:
CA476131

10-DEC-2010 LNM/D. 03-DEC-2010
Delete green port hand lighted pillar buoy FlG marked 46°33'28.0"N 064°05'42.0"W
DJ7.
(See Chart No 1 Qg) *(G2010177) LL(1027.41) DFO(6305117-01)*

10-DEC-2010 LNM/D. 03-DEC-2010
Delete red starboard hand lighted pillar buoy QR, marked DJ12. 46°33'28.0"N 064°05'18.0"W
(See Chart No 1 Qg) *LL(1027.42) DFO(6305117-03)*

10-DEC-2010 LNM/D. 03-DEC-2010
Delete red starboard hand lighted pillar buoy FlR, marked DJ20. 46°33'16.8"N 064°05'10.2"W
(See Chart No 1 Qg) *LL(1027.43) DFO(6305117-04)*



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

10-DEC-2010

LNM/D. 03-DEC-2010

Add legend Channel Buoyed / Chenal balisé 46°33'29.0"N 064°06'06.8"W

DFO(6305117-05)

03-DEC-2010

LNM/D. 26-NOV-2010

Delete light Fl
(See Chart No 1 P1)

46°09'56.3"N 064°04'06.6"W

(G2010180) LL(1097.2) DFO(6305118-02)

26-NOV-2010

LNM/D. 29-OCT-2010

Add red starboard hand lighted spar buoy Fl R, marked
DH2/4
(See Chart No. 1 Qf)

46°27'05.3"N 064°07'18.7"W

(G2010168) LL(1023.2) DFO(6305100-01)

29-OCT-2010

LNM/D. 21-MAY-2010

Add marine farm
(See Chart No. 1 K48.2)

46°33'34.5"N 064°04'49.2"W

DFO(6305061-01)

21-MAY-2010

LNM/D. 04-DEC-2009

Amend Iso 10s 14m 11M to read Iso 10s 14m 8M against
light
(See Chart No 1 P16)

46°22'47.0"N 063°49'01.1"W

(G2009134) LL(1020) DFO(6304727-01)

04-DEC-2009

LNM/D. 02-OCT-2009

Delete red, starboard hand conical buoy, marked DM4
(See Chart No 1 Qf)

46°37'01.9"N 064°22'15.4"W

(G2009141) DFO(6304613-01)

04-DEC-2009

LNM/D. 02-OCT-2009

Delete red starboard hand conical buoy, marked DM6
(See Chart No 1 Qf)

46°37'04.3"N 064°22'15.2"W

(G2009142) DFO(6304614-01)

04-DEC-2009

LNM/D. 02-OCT-2009



Chart no. 4905

Add legend Channel Buoyed/Chenal balisé 46°36'54.0"N 064°22'15.0"W

(G2009143) DFO(6304615-01)

02-OCT-2009

LNM/D. 20-FEB-2009

Add legend Channel Buoyed/Chenal balisé 46°14'18.0"N 064°18'30.0"W

LL(1102.1) DFO(6304625-01)

20-FEB-2009

LNM/D. 05-SEP-2008

Delete private yellow cautionary spar buoy, marked SCBL 46°11'40.8"N 063°46'38.0"W
(See Chart No 1 Qm)

DFO(6304250-01)

20-FEB-2009

LNM/D. 05-SEP-2008

Add depth of 16 metres, 4 decimetres over artificial feature 46°11'40.8"N 063°46'38.0"W

DFO(6304250-02)

05-SEP-2008

LNM/D. 22-AUG-2008

(T)Add subsurface mooring at a depth of 10 metres (33 feet) attached 46°39'57.6"N 064°31'37.2"W
to a private yellow cautionary lighted spar buoy Fl(5) 20s

The surface buoy has a 550 metre (1800 feet) scope. Proposed
date of removal is November 2008. (contact Murray Scotney,
Bedford Institute of Oceanography, 902-426-3495)

DFO(6304005-01)

The mooring has been removed. Notice 05-September-2008(T),
DFO (6304005) is now cancelled.

Cancelled on 19-DEC-08

05-SEP-2008

LNM/D. 22-AUG-2008

(T)Add subsurface mooring at a depth of 10 metres (33 feet) attached 46°39'25.2"N 064°37'12.0"W
to a private yellow cautionary lighted spar buoy Fl(5) 20s

The surface buoy has a 550 metre (1800 feet) scope. Proposed
date of removal is November 2008. (contact Murray Scotney,
Bedford Institute of Oceanography, 902-426-3495)

DFO(6304005-02)

The mooring has been removed. Notice 05-September-2008(T),
DFO (6304005) is now cancelled.

Cancelled on 19-DEC-08

22-AUG-2008

LNM/D. 04-APR-2008



Chart no. 4905

(T)Delete private yellow cautionary spar buoy, marked SCBL. 46°11'40.8"N 063°46'38.0"W
(See Chart No 1 Qm)
The removal is temporary and will be deployed November 2008. *DFO(6303912-01)*
This buoy is permanently discontinued. Notice 22-Aug-2008(T) DFO (6303912), is cancelled. See reference DFO(6304250) appearing in this edition.
Cancelled on 20-FEB-09

04-APR-2008 LNM/D. 14-DEC-2007
Add private yellow cautionary spar buoy, marked SCBL. 46°11'40.8"N 063°46'38.0"W
DFO(6303793-01)

04-APR-2008 LNM/D. 14-DEC-2007
Add wreck WK with known depth of 11 metres 8 decimetres 46°11'53.2"N 063°41'55.9"W
(See Chart No 1 K26)
DFO(6303818-01)

14-DEC-2007 LNM/D. 28-SEP-2007
Add red starboard hand lighted pillar buoy FIR, marked DJ20 46°33'16.8"N 064°05'10.2"W
(G2007132) LL(1027.43) DFO(6303648-01)

27-JUL-2007 LNM/D. 23-DEC-2005
(T)Add private yellow cautionary buoy marked SCBL 46°11'40.8"N 063°46'25.2"W
Proposed date of removal is September 2007.
Buoy permanently established. Notice 27-July-2007(T), DFO *DFO(6303559-01)*
(6303559-01) is cancelled.
Cancelled on 16-JAN-09

23-DEC-2005 LNM/D. 26-NOV-2004
Amend "FIY" to read "FIG" against light 46°08'02.7"N 063°46'11.8"W
(G2004167) LL(1091.5) DFO(6302594-01)

23-DEC-2005 LNM/D. 26-NOV-2004
Add red starboard hand lighted spar buoy FIR, marked DH8 46°26'48.6"N 064°06'56.4"W
(G2005146) LL(1023.6) DFO(6302595-01)



Chart no. 4905

26-NOV-2004

LNM/D. 27-AUG-2004

Delete front range light "FY 5m"

46°34'50.5"N 064°43'22.5"W

(G2004170) LL(1127.5) DFO(6302012-01)

26-NOV-2004

LNM/D. 27-AUG-2004

Delete rear range light "FY 6m"

46°34'50.5"N 064°43'26.5"W

(G2004171) LL(1127.6) DFO(6302012-02)

26-NOV-2004

LNM/D. 27-AUG-2004

Delete leading line and legend "91° 271°" 46°34'50.0"N 064°40'10.0"W

DFO(6302012-03)

26-NOV-2004

LNM/D. 27-AUG-2004

Add front range light "FY 5m"

46°34'58.7"N 064°43'21.5"W

(G2004170) LL(1127.5) DFO(6302012-04)

26-NOV-2004

LNM/D. 27-AUG-2004

Add rear range light "FY 7m"

46°34'58.8"N 064°43'26.6"W

(G2004171) LL(1127.6) DFO(6302012-05)

26-NOV-2004

LNM/D. 27-AUG-2004

Add leading line with bearing 091° from front range

46°34'58.7"N 064°43'21.5"W

Useable portion of leading line is east of longitude 64-42-45W.

DFO(6302012-06)

26-NOV-2004

LNM/D. 27-AUG-2004

Add legend "091° - 271°" against leading line 46°35'03.0"N 064°40'10.0"W

DFO(6302012-07)

27-AUG-2004

LNM/D. 09-JUL-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

Add light LFIG 46°37'05.6"N 064°22'17.7"W

(G2004136) LL(1028.2) DFO(6301768-01)

09-JUL-2004

LNM/D. 11-JUN-2004

Add yellow ODAS/SADO light buoy, Fl (5) Y, marked 44161 46°19'54.0"N 064°22'36.0"W

DFO(6301727-01)

11-JUN-2004

LNM/D. 19-MAR-2004

Delete light Fl G 46°24'30.3"N 064°36'56.4"W

(G2004075) LL(1118.5) DFO(6301450-01)

11-JUN-2004

LNM/D. 19-MAR-2004

Add light Fl R 46°24'28.3"N 064°36'55.3"W

(G2004075) LL(1118.5) DFO(6301450-02)

19-MAR-2004

LNM/D. 20-FEB-2004

Delete leading line and legend "187°" and "007°" 46°37'05.4"N 064°22'19.7"W

(G2003161) LL(1028) DFO(6301195-01)

19-MAR-2004

LNM/D. 20-FEB-2004

Delete front range light FY 6m 46°37'05.4"N 064°22'19.7"W

(G2003162) LL(1028) DFO(6301195-02)

19-MAR-2004

LNM/D. 20-FEB-2004

Delete rear range light FY 14m 46°37'14.0"N 064°22'17.0"W

(G2003161) LL(1028.1) DFO(6301195-03)

20-FEB-2004

LNM/D. 18-JUL-2003

Delete red starboard hand spar light buoy FlR, marked
XD2 46°08'36.0"N 063°44'53.5"W

(G2003138) LL(1094.5) DFO(6301149-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4905

06-JUN-2003

LN/D. 20-JUL-2001

Add red, starboard hand conical buoy, marked DM4 46°37'01.9"N 064°22'15.4"W

(G2002169) DFO(6300642-01)

06-JUN-2003

LN/D. 20-JUL-2001

Add red, starboard hand conical buoy, marked DM6 46°37'04.3"N 064°22'15.2"W

(G2002170) DFO(6300643-01)

20-JUL-2001

Add red light, starboard hand spar buoy FLR, marked
DH2

46°27'08.8"N 064°07'44.0"W

(G2000060) LL(1023.100) DFO(6829523-01)