



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4906

4906 - West Point à / to Baie de Tracadie - New Chart - 18-MAR-1988 - NAD 1983

28-JUL-2023

LNLM/D. 14-APR-2023

Delete red and white fairway lighted spar buoy Mo(A),
marked DP

46°54'03.1"N 064°14'19.9"W

(See Chart 1, Qd)

(G2023029) LL(1032.05) DFO(6310696-01)

This notice affects Electronic Navigational
Chart: CA276286, CA376062

28-JUL-2023

LNLM/D. 14-APR-2023

Add red and white fairway lighted can buoy Mo(A),
marked DP

46°54'02.2"N 064°14'17.8"W

(See Chart 1, Qd)

(G2023029) LL(1032.05) DFO(6310696-02)

This notice affects Electronic Navigational Chart:
CA276286, CA376062

14-APR-2023

LNLM/D. 10-MAR-2023

Delete green port hand lighted pillar bell buoy, Fl G,
marked X31

47°07'09.0"N 064°47'06.0"W

(See Chart 1, Qc)

(G2023001) LL(1162) DFO(6310587-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376062, CA476133

14-APR-2023

LNLM/D. 10-MAR-2023

Add green port hand lighted spar buoy, Fl G, marked X31
(See Chart 1, Qc)

47°07'09.0"N 064°47'06.0"W

This notice affects Electronic Navigational Chart:
CA276286, CA376062, CA476133

(G2023001) LL(1162) DFO(6310587-02)

10-MAR-2023

LNLM/D. 20-MAY-2022

Affix patch

46°51'39.0"N 064°52'48.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA376062

DFO(6310529-01)

10-MAR-2023

LNLM/D. 20-MAY-2022

Delete Note

47°27'47.6"N 064°50'43.6"W

DIAGRAMME/DIAGRAM

Voir Instructions nautiques

See Sailing Directions

(See Chart No. 1, A18)

This notice affects Electronic Navigational Chart: CA376062

DFO(6310529-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4906

10-MAR-2023

LN/D. 20-MAY-2022

Delete Note

46°59'28.7"N 064°49'56.0"W

DIAGRAMME/DIAGRAM

Voir Instructions nautiques

DFO(6310529-03)

See Sailing Directions

(See Chart No. 1, A18)

This notice affects Electronic Navigational Chart: CA376062

10-MAR-2023

LN/D. 20-MAY-2022

Delete Note

46°53'14.1"N 064°11'22.4"W

DIAGRAMME/DIAGRAM

Voir Instructions nautiques

DFO(6310529-04)

See Sailing Directions

(See Chart No. 1, A18)

This notice affects Electronic Navigational Chart: CA376062

10-MAR-2023

LN/D. 20-MAY-2022

Delete Note

46°57'32.8"N 064°05'04.4"W

DIAGRAMME/DIAGRAM

Voir Instructions nautiques

DFO(6310529-05)

See Sailing Directions

(See Chart No. 1, A18)

This notice affects Electronic Navigational Chart: CA376062

20-MAY-2022

LN/D. 27-AUG-2021

Reposition light FIG

from 47°31'29.5"N 064°54'29.2"W

(See Chart No. 1, P1)

to 47°31'21.7"N 064°54'30.4"W

This notice affects Electronic Navigational

Chart: CA376062

(G2022015) LL(1244.9) DFO(6410659-01)

20-MAY-2022

LN/D. 27-AUG-2021

Add pier

joining 47°31'22.3"N 064°54'33.3"W

(See Chart No. 1, F14)

47°31'22.9"N 064°54'31.6"W

This notice affects Electronic Navigational Chart:

and 47°31'21.7"N 064°54'30.4"W

CA376062

DFO(6410659-02)

27-AUG-2021

LN/D. 06-AUG-2021



Chart no. 4906

Reposition red starboard hand lighted spar buoy Q R, from 47°18'56.3"N 064°55'21.1"W
marked TA2/2 to 47°18'32.5"N 064°55'37.8"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA376062 (G2021051) LL(1238.05) DFO(6309481-01)

06-AUG-2021

Add wreck with known depth of 17 metres, PA LNM/D. 02-OCT-2020
(See Chart No. 1, K26) 46°52'41.2"N 064°47'26.8"W
This notice affects Electronic Navigational Chart: CA276286, DFO(6309508-01)
CA376062

02-OCT-2020

Delete green port hand lighted pillar buoy QG, marked Q3 LNM/D. 27-OCT-2017
(See Chart No. 1, Qg) 46°42'55.1"N 064°44'46.5"W
This notice affects Electronic Navigational Chart: CA376076, CA476131 (G2020157) LL(1132) DFO(6309177-01)

02-OCT-2020

Add green port hand lighted can buoy Q G, marked Q3 LNM/D. 27-OCT-2017
(See Chart No. 1, Qg) 46°42'52.9"N 064°44'40.9"W
This notice affects Electronic Navigational Chart: CA376076, CA476131 (G2020157) LL(1132) DFO(6309177-02)

27-OCT-2017

Delete black, yellow and black East cardinal lighted LNM/D. 25-AUG-2017
spar buoy Q(3) W 10s, marked DPB 46°53'07.0"N 064°14'21.0"W
(See Chart No. 1, Q130.3) (G2017081) LL(1032.35) DFO(6308045-01)
This notice affects Electronic Navigational Chart: CA376062

27-OCT-2017

Delete yellow and black South cardinal lighted spar LNM/D. 25-AUG-2017
buoy Q(6)+LFl 15s, marked DPA 46°52'53.2"N 064°14'22.3"W
(See Chart No. 1, Q130.3) (G2017080) LL(1032.45) DFO(6308045-02)
This notice affects Electronic Navigational Chart: CA376062

27-OCT-2017

LNM/D. 25-AUG-2017



Chart no. 4906

Add Balisé / Buoyed

46°52'43.7"N 064°14'28.8"W

This notice affects Electronic Navigational Chart: CA376062

DFO(6308045-03)

25-AUG-2017

LNLM/D. 28-JUL-2017

Amend 2 Lts Fl & Fl G to read 2 Lts LFl Y & Fl G against
light

47°04'57.3"N 064°53'14.6"W

(See Chart No. 1, P16)

(G2017064) LL(1165.8) DFO(6307994-01)

This notice affects Electronic Navigational Chart:
CA376062, CA476133, CA576723

28-JUL-2017

LNLM/D. 07-JUL-2017

Add black, yellow and black
East cardinal lighted spar
buoy Q(3)10s, marked
DPB

46°53'06.7"N 064°14'21.1"W

(G2017043, G2017051 & G2017079) LL(1032.35) DFO(6307956-01)

(See Chart No. 1, Q130.3)

This notice affects
Electronic Navigational
Chart: CA376062

28-JUL-2017

LNLM/D. 07-JUL-2017

Add yellow and black South cardinal lighted spar buoy
Q(6)+LFl 15s, marked DPA

46°52'53.2"N 064°14'22.3"W

(See Chart No. 1, Q130.3)

(G2017044) LL(1032.45) DFO(6307956-02)

This notice affects Electronic Navigational Chart:
CA376062

28-JUL-2017

LNLM/D. 07-JUL-2017

Delete red starboard hand lighted conical buoy, Fl R, marked DP6
(See Chart No. 1, Qf)

46°53'16.7"N 064°14'17.4"W

This notice affects Electronic Navigational Chart: CA376062 *LL(1032.2) DFO(6307956-03)*

28-JUL-2017

LNLM/D. 07-JUL-2017

Delete green port hand lighted can buoy Fl G, marked DP3
(See Chart No. 1, Qg)

46°53'30.5"N 064°14'06.4"W

This notice affects Electronic Navigational Chart: CA376062 *LL(1032.1) DFO(6307956-04)*

28-JUL-2017

LNLM/D. 07-JUL-2017



Chart no. 4906

Add Channel Buoy / Chenal balisé

46°53'39.0"N 064°14'34.0"W

This notice affects Electronic Navigational Chart: CA376062

DFO(6307956-05)

07-JUL-2017

LN/D. 30-JUN-2017

Replace wharf with wharf in ruins with legend Ru

joining 47°03'15.0"N 064°57'20.3"W

(See Chart No. 1 F33.1)

47°03'21.5"N 064°57'25.5"W

This notice affects Electronic Navigational Chart:

and 47°03'20.4"N 064°57'28.1"W

CA476133

DFO(6307966-01)

30-JUN-2017

LN/D. 16-JUN-2017

Delete red starboard hand lighted spar buoy Fl R, marked
TE2

47°30'10.7"N 064°50'54.0"W

(See Chart No. 1, Qf)

(G2017026) LL(1240) DFO(6307934-01)

This notice affects Electronic Navigational Chart:
CA376062

16-JUN-2017

LN/D. 28-APR-2017

Add green port hand lighted can buoy Fl G, marked DP3

46°53'30.5"N 064°14'06.6"W

(See Chart No. 1, Qg)

This notice affects Electronic Navigational Chart:

(G2017027) LL(1032.1) DFO(6307935-01)

CA376062

16-JUN-2017

LN/D. 28-APR-2017

Add red starboard hand lighted conical buoy Fl R,
marked DP6

46°53'16.7"N 064°14'17.4"W

(See Chart No. 1, Qf)

(G2017028) LL(1032.2) DFO(6307935-02)

This notice affects Electronic Navigational Chart:

CA376062

16-JUN-2017

LN/D. 28-APR-2017

Add light Fl G

46°52'48.0"N 064°14'07.8"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:

(G2017014) LL(1033.5) DFO(6307935-03)

CA276286, CA376062

28-APR-2017

LN/D. 17-JUN-2016



Chart no. 4906

Delete front range/leading light F R 46°52'47.8"N 064°14'05.5"W
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart: *(G2017010) LL(1033) DFO(6307899-01)*
CA276286, CA376062

28-APR-2017 LNM/D. 17-JUN-2016
Delete rear range/leading light F R with leading line and 46°52'34.7"N 064°14'03.1"W
bearing 173°
(See Chart No. 1, P20.2) *(G2017011) LL(1034) DFO(6307899-02)*
This notice affects Electronic Navigational Chart:
CA276286, CA376062

17-JUN-2016 LNM/D. 29-APR-2016
Reposition green port hand lighted pillar buoy QG, marked from 46°43'00.6"N 064°44'34.1"W
Q3 to 46°42'54.1"N 064°44'46.6"W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational *(G2016048) LL(1132) DFO(6307537-01)*
Chart: CA476131

29-APR-2016 LNM/D. 24-JUL-2015
Add light FLY 47°27'54.9"N 064°53'04.3"W
(See Chart No. 1, P1) *(G2016024) LL(1239.85) DFO(6307494-01)*
This notice affects Electronic Navigational Chart:
CA376062

24-JUL-2015 LNM/D. 15-MAY-2015
Reposition red starboard hand lighted spar buoy QR, from 47°19'00.5"N 064°55'18.6"W
marked TA2/2 to 47°18'56.3"N 064°55'21.1"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational *(G2015059) LL(1238.05) DFO(6307182-01)*
Chart: CA376062

15-MAY-2015 LNM/D. 03-APR-2015
Delete Note DIAGRAMME / DIAGRAM 47°04'18.4"N 064°52'33.0"W
Voir Instructions nautiques
See Sailing Directions *DFO(6307108-04)*
This notice affects Electronic Navigational Chart: CA376062,
CA476133



Chart no. 4906

03-APR-2015

LNМ/D. 12-DEC-2014

Add depth of 21 metres 9 decimetres
(See Chart No. 1, I10)

47°13'30.0"N 064°01'20.0"W

This notice affects Electronic Navigational Chart: CA376062

DFO(6307085-01)

12-DEC-2014

LNМ/D. 18-APR-2014

Affix patch

47°20'00.0"N 064°55'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA376062

DFO(6307026-01)

18-APR-2014

LNМ/D. 03-JAN-2014

Amend sector light Fl(2)RWG to read FRWG against
light

46°57'47.3"N 064°49'49.9"W

(See Chart No 1 P40.1)

(G2014023) LL(1159.6) DFO(6306706-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376062

03-JAN-2014

LNМ/D. 27-DEC-2013

Delete front range/leading light FY
(See Chart No. 1, P20.2)

46°57'46.3"N 064°49'48.0"W

This notice affects Electronic Navigational Chart:
CA376062

(G2013162) LL(1160) DFO(6306556-01)

03-JAN-2014

LNМ/D. 27-DEC-2013

Delete rear range/leading light FY with leading line and
bearing 003½°

46°57'48.9"N 064°49'47.5"W

(See Chart No. 1, P20.2)

(G2013163) LL(1161) DFO(6306556-02)

This notice affects Electronic Navigational Chart:
CA276286, CA376062

03-JAN-2014

LNМ/D. 27-DEC-2013

Add sector light Fl(2)RWG
(See Chart No. 1, P30.3)

46°57'47.2"N 064°49'49.9"W

This notice affects Electronic Navigational Chart:
CA276286, CA376062

(G2013164) LL(1159.6) DFO(6306556-03)

27-DEC-2013

LNМ/D. 25-OCT-2013



Chart no. 4906

Amend Fl to read 2 Lts Fl & FlG against light 47°04'57.3"N 064°53'14.6"W
(See Chart No. 1, P1)
This notice affects Electronic (G2013174) LL(1165.8 and 1165.9) DFO(6306586-03)
Navigational Chart: CA376062

25-OCT-2013 LNM/D. 30-AUG-2013
Add light FlG 46°57'39.5"N 064°49'51.6"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2013122) LL(1162.3) DFO(6306492-01)
CA276286, CA376062

25-OCT-2013 LNM/D. 30-AUG-2013
Amend FlR to read Fl against light 46°57'37.9"N 064°49'47.3"W
(See Chart No 1 P16)
This notice affects Electronic Navigational Chart: (G2013141) LL(1159.5) DFO(6306498-01)
CA276286, CA376062

30-AUG-2013 LNM/D. 29-MAR-2013
Amend Fl(3)20s21m18M to read Fl 22m13M against 47°04'22.2"N 064°47'50.6"W
light
(See Chart No. 1, P1) (G2013098) LL(1163.0) DFO(6306470-01)
This notice affects Electronic Navigational Chart:
CA179171, CA276286, CA376062, CA476133

29-MAR-2013 LNM/D. 29-JUN-2012
Amend WHIS to read BELL against the North cardinal 47°05'00.0"N 064°00'03.0"W
light and whistle buoy Q, marked DS.
(See Chart No 1 Qc) (G2012201) LL(1037) DFO(6306248-01)
This notice affects Electronic Navigational Chart:
CA276286, CA376062

29-JUN-2012 LNM/D. 02-MAR-2012
Reposition green port hand lighted pillar buoy QG, marked from 46°43'07.2"N 064°44'46.8"W
Q3 to 46°43'00.6"N 064°44'34.2"W
(See Chart No. 1, Qg) (G2012100) LL(1132) DFO(6306056-03)

This notice affects Electronic Navigational
Chart: CA376062, CA476131

02-MAR-2012 LNM/D. 10-JUN-2011



Chart no. 4906

Amend Fl R to read FlG against light
(See Chart No. 1, P1)

47°27'55.6"N 064°52'57.1"W

(G2012013) LL(1239.8) DFO(6305932-01)

10-JUN-2011

LNМ/D. 06-MAR-2009

Reposition green port hand lighted pillar buoy Q G,
marked Q3
(See Chart No. 1, Qg)

from 46°42'39.2"N 064°44'38.9"W
to 46°43'07.2"N 064°44'46.8"W

(G2011126) LL(1132) DFO(6305483-02)

This notice affects Electronic Navigational
Chart: CA376062

06-MAR-2009

LNМ/D. 05-SEP-2008

Add light QG
(See Chart No 1 P1)

46°44'25.5"N 064°22'46.0"W

(G2008102) LL(1031.5) DFO(6304259-01)

06-MAR-2009

LNМ/D. 05-SEP-2008

Amend Fl 6s 14m to read LFl 6s 14m 12M against light
(See Chart No 1 P16)

LL(1032) DFO(6304278-01)

05-SEP-2008

LNМ/D. 28-MAR-2008

(T)Add subsurface mooring at a depth of 10 metres (33 feet) attached
to a private yellow cautionary lighted spar buoy Fl(5) 20s
The surface buoy has a 550 metre (1800 feet) scope. Proposed
date of removal is November 2008. (contact Murray Scotney,
Bedford Institute of Oceanography, 902-426-3495)
The mooring has been removed. Notice 05-September-2008(T),
DFO (6304005) is now cancelled.
Cancelled on 19-DEC-08

46°39'57.6"N 064°31'37.2"W

DFO(6304005-01)

05-SEP-2008

LNМ/D. 28-MAR-2008

(T)Add subsurface mooring at a depth of 10 metres (33 feet) attached
to a private yellow cautionary lighted spar buoy Fl(5) 20s
The surface buoy has a 550 metre (1800 feet) scope. Proposed
date of removal is November 2008. (contact Murray Scotney,
Bedford Institute of Oceanography, 902-426-3495)
The mooring has been removed. Notice 05-September-2008(T),
DFO (6304005) is now cancelled.
Cancelled on 19-DEC-08

46°39'25.2"N 064°37'12.0"W

DFO(6304005-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4906

28-MAR-2008

LNM/D. 27-OCT-2006

Replace red starboard hand lighted pillar bell buoy FIR,
marked DP2 with red and white fairway lighted
spar buoy Mo(A), marked DP
(See Chart No 1 Qf and Qh)

46°54'03.0"N 064°14'20.0"W

(G2007057) LL(1032.05) DFO(6303466-01)

This notice affects Electronic Navigational
Chart: CA376062

27-OCT-2006

LNM/D. 01-SEP-2006

Delete light FRWG

46°50'42.0"N 064°54'52.0"W

(G2006099) LL(1158) DFO(6302994-01)

01-SEP-2006

LNM/D. 05-AUG-2005

Delete red starboard hand lighted pillar buoy FIR,
marked TE4

47°30'45.0"N 064°52'00.0"W

(G2006064) LL(1240.5) DFO(6303027-01)

05-AUG-2005

LNM/D. 25-MAR-2005

Delete light FIG

47°28'18.7"N 064°54'37.9"W

(G2005060) LL(1239.9) DFO(6302401-01)

This notice affects Electronic Navigational Chart:
CA279075

25-MAR-2005

LNM/D. 05-NOV-2004

Affix patch 47°29'00.0"N 064°54'00.0"W

DFO(6302265-01)

[PDF](#)

05-NOV-2004

LNM/D. 03-SEP-2004

Replace red starboard hand pillar light buoy QR, marked
M2, with red starboard hand spar light buoy QR,
marked M2

47°05'51.9"N 064°56'30.0"W

(G2004151) LL(1170) DFO(6301930-02)

03-SEP-2004

LNM/D. 08-AUG-2003



Chart no. 4906

Amend FR to read FIR against light 46°57'58.0"N 064°07'33.5"W

(G2004080) LL(1035) DFO(6301639-01)

08-AUG-2003

LNM/D. 07-MAR-2003

Add yellow ODAS/SADO light buoy, Fl Y 5s, marked 44150 46°51'00.0"N 064°38'48.0"W

DFO(6300963-01)

07-MAR-2003

LNM/D. 17-JAN-2003

Delete legend "Fog Sig" against light 46°57'40.6"N 064°49'50.1"W

(G2002142) LL(1161.2) DFO(6300572-01)

17-JAN-2003

LNM/D. 21-JUN-2002

Add Note:

47°29'00.0"N 064°49'00.0"W

Voir ATTENTION No.2 / See CAUTION No.2

(G2002088) LL(1239) DFO(6300211-01)

17-JAN-2003

LNM/D. 21-JUN-2002

Add legend PA against light 47°28'41.5"N 064°52'20.6"W

(G2002088) LL(1239) DFO(6300211-02)

21-JUN-2002

LNM/D. 24-DEC-1999

Replace red starboard hand pillar light and bell buoy

47°05'51.9"N 064°56'30.0"W

FIR, marked M2, with red starboard hand

pillar light buoy QR, marked M2

(G2001012) LL(1170.000) DFO(6300252-01)